# CLEAN WATER INFRASTRUCTURE REPLACEMENT PLAN UPDATE for the KENT COUNTY WATER AUTHORITY

**DECEMBER 13, 2019**

# Table of Contents

Section 1
Inventory

Section 2
Infrastructure Adequacy

Section 3
Infrastructure Adequacy (Water Main Details)

Section 4
Cost Summary

Section 5
Financial Adequacy

| System Information | |
|---|---|
| System Name | Kent County Water Authority |
| PWSID | RI1559511 |
| System Type | CWS |
| Contact Name | David L. Simmons |
| Contact Phone | 401-821-9300 |
| Contact E-mail | [redacted] |
| Fiscal Year Used | July 1- June 30 |
| **Current System Information** | |
| Retail Population | 88,779 |
| Consecutive Population | Wholesale to Warwck |
| Consecutive Population | Retail Sale to Center of New England |
| Consecutive Population | Retail Sale to Coventry School |
| Total Population | |
| # of Service Connections | 27,230 |
| Type of Source Water | Blended: Purchased SW and Produced GW |
| Purchaser or Wholesaler | Both |
| Annual Usage (Million Gallons) | 2,303 million gallons |

| Infrastructure Type | Infrastructure Subtype | Brief Infrastructure Description | Number of Infrastructure Subtype | Age (in years) | Condition (poor, fair, good, excellent; or rating scale) | Remaining Useful Life (in years) | Need for Rehabilitation or Replacement (20-year timeframe) (Yes/No) | Evaluation/Prioritization for Rehabilitation or Replacement (5-year intervals) (Yes/No) | Infrastructure Supports SDWA Compliance (Yes/No) | Financial Forecast (in dollars) | O&M Notes | Other Notes |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Source | Well | Mishnock Well #3, Gravel Packed Well 67.5', Developed March 2000, Cleaned in 2013, 18" Steel Cased 10' SS Screen | 1 | 20 | Excellent | 40-50 | Yes | Yes | Yes | $10,000 | Clean and Redevelopment | (Water Treatment Plant Online Dec 2013) Recuring |
| Source | Well | Mishnock Well #4, Gravel Packed Well 72', Developed 2001, Cleaned in 2013, 18" Steel Cased 10' SS Screen | 1 | 19 | Excellent | 40-50 | Yes | Yes | Yes | $10,000 | Clean and Redevelopment | (Water Treatment Plant Online Dec 2013) Recuring |
| Source | Well | Mishnock Well #5, Gravel Packed Well 85', Developed 2001, Cleaned in 2013, 18" Steel Cased 10' SS Screen | 1 | 19 | Excellent | 40-50 | Yes | Yes | Yes | $10,000 | Clean and Redevelopment | (Water Treatment Plant Online Dec 2013) Recuring |
| Treatment | Treatment Building | Mishnock Treatment Facility | 1 | 6 | Excellent | 40-50 | Yes | Yes | Yes | $30,000 | Inspect tank coating and recost as needed, Overhaul aeration blowers and chemical pumps | Water Treatment Plant Online Dec 2013 |
| Treatment | Treatment Building | Mishnock Treatment Facility | 5 | 6 | Excellent | 4 | Yes | Yes | Yes | $1,000,000 | Remove<br>Replace membranes | Water Treatment Plant Online Dec 2013 |
| Treatment | Generator | Mishnock Treatment Facility<br>600 kW GenSet with ATS | 1 | 6 | Excellent | 30-35 | No | No | Yes | $0 | 0 | Water Treatment Plant Online Dec 2013 |

| Infrastructure Type | Infrastructure Subtype | Brief Infrastructure Description | Number of Infrastructure Subtype | Age (in years) | Condition (poor, fair, good, excellent; or rating scale) | Remaining Useful Life (in years) | Need for Rehabilitation or Replacement (20-year timeframe) (Yes/No) | Evaluation/Prioritization for Rehabilitation or Replacement (5-year intervals) (Yes/No) | Infrastructure Supports SDWA Compliance (Yes/No) | Financial Forecast (in dollars) | O&M Notes | Other Notes |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treatment | Finished Water Pumps | Low Lift Pumps. 50 HP Multistate Turbines. | 2 | 6 | Good | 15-20 | Yes | Yes | Yes | $7,000 | Remove<br>Inspect<br>Rebuild 1 Pump and Motor | (Water Treatment Plant Online Dec 2013. Replace motor & pump.)<br>Recuring |
| Treatment | Finished Water Pumps | High Lift Pumps. 100 HP Multistate Turbines. | 3 | 6 | Good | 15-20 | Yes | Yes | Yes | $7,000 | Remove<br>Inspect<br>Rebuild 1 Pump and Motor | (Water Treatment Plant Online Dec 2013. Replace Motor & Pump.)<br>Recuring |
| Source | Well | Ground Water, Gravel-Packed, Well Spring Lake, Offline | 1 | 59 | Poor (offline) | >10 with repairs | Yes | Yes | No | $2,000,000 | Budgetd $50,000 for Cleaning and Inspection. Requires replacement of well building wit treatment and/or transmission main to mishnock plant | Facility Replacement within 5yr and Complete well Redevelopment in. |
| Source | Well Pump | Mishnock Well Pump # 3, 25 HP Submersible Vertical Turbine Pump | 1 | 6 | Good | 10-15 | Yes | Yes | Yes | $15,000 | Remove pump<br>Inspect and overhaul<br>Clean and redevelop well | (Water Treatment Plant Online Dec 2013.)<br>As Part of Well Redevelopment<br>Recuring |
| Source | Well Pump | Mishnock Well Pump # 4, 30 HP Submersible Vertical Turbine Pump | 1 | 6 | Good | 10-15 | Yes | Yes | Yes | $15,000 | Remove pump<br>Inspect and overhaul<br>Clean and redevelop well | (Water Treatment Plant Online Dec 2013.)<br>As Part of Well Redevelopment<br>Recuring |
| Source | Well Pump | Mishnock Well Pump #5, 20 HP Submersible Vertical Turbine Pump | 1 | 6 | Good | 10-15 | Yes | Yes | Yes | $15,000 | Remove pump<br>Inspect and overhaul<br>Clean and redevelop well | (Water Treatment Plant Online Dec 2013)<br>Recuring |

| Infrastructure Type | Infrastructure Subtype | Brief Infrastructure Description | Number of Infrastructure Subtype | Age (in years) | Condition (poor, fair, good, excellent; or rating scale) | Remaining Useful Life (in years) | Need for Rehabilitation or Replacement (20-year timeframe) (Yes/No) | Evaluation/Prioritization for Rehabilitation or Replacement (5-year intervals) (Yes/No) | Infrastructure Supports SDWA Compliance (Yes/No) | Financial Forecast (in dollars) | O&M Notes | Other Notes |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Source | Well | Ground Water, Gravel-Packed Well, East Greenwich | 1 | 55 | Excellent | 10-15 | no | No | Yes | $0 | $0 | Redeveloped 2017 |
| Treatment | Treatment Building | East Greenwich Well Treatment Facility | 1 | 2 | Excellent | 40-50 | No | Yes | No | $6,000,000 | CIP or IFR Construction Contract for Pressure Filter & Finished Water Tank 4 Log Removal | Construction new wellfield facility 2017. May fit IFR requirements for compliance with SDWA or becomes CIP Addition to Include Pressure Filter & Finished Water |
| Treatment | Generator | East Greenwich Well Treatment Facility 250 kW LG | 1 | 1 | Excellent | 30-35 | No | No | Yes | $0 | 0 | Construction new wellfield facility 2017. |
| Transmission_Distribution | Transmission Pump Station | Clinton Ave. Pump Station | 1 | 14 | Excellent | 35-40 | No | No | Yes | $0 | 0 | Rehabilitated in 2006 |
| Transmission_Distribution | Booster Pumps | 3,800 gpm Vertical Turbine Pumps at Clinton Ave. Pump Station | 5 | 14 | Good | 10-15 | Yes | Yes | Yes | $10,000 | Overhaul 1 Pump & Motor per year over 5 yr period | New 2006 |
| Transmission_Distribution | Booster Pumps | 2,100 gpm Vertical Turbine Pumps at Clinton Ave. Pump Station | 2 | 14 | Good | 10-15 | Yes | Yes | Yes | $10,000 | Overhaul 1 pump per year over 5 yr period | New in 2006 |

| Infrastructure Type | Infrastructure Subtype | Brief Infrastructure Description | Number of Infrastructure Subtype | Age (in years) | Condition (poor, fair, good, excellent; or rating scale) | Remaining Useful Life (in years) | Need for Rehabilitation or Replacement (20-year timeframe) (Yes/No) | Evaluation/Prioritization for Rehabilitation or Replacement (5-year intervals) (Yes/No) | Infrastructure Supports SDWA Compliance (Yes/No) | Financial Forecast (in dollars) | O&M Notes | Other Notes |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission_Distribution | Water Meters | 12 inch Master Meter at Oaklawn Ave for Interconnection with Providence Water Supply Board, Underground Station. | 1 | 15 | Functional | 30 | Yes | No | Yes | $0 | 0 | Rehabilitated in 2004 |
| Transmission_Distribution | Transmission Pump Station | Bald Hill Road Pump Station | 1 | 5 | Excellent | 35-40 | No | yes | Yes | $2,000,000 | Complete installation of high service 500 foot gradient pumps and transmission main | Rehabilitated 2014 low service pumping |
| Storage | Reservoir | 3,000,000 Gallon Setian Lane Steel Tank, No Cathodic Protection | 1 | 50 | Good | 20 | Yes | Yes | Yes | $400,000 | Blast and Coat Exterior | Rehabilitate Coating System Fails. |
| Storage | Reservoir | Frenchtown Tank. 1,500,000 Gallon Concrete Tank, No Cathodic Protection | 1 | 42 | Good | 20-50 | Yes | No | Yes | $25,000 | 0 | Costs for Cleaning and Inspecting (20yr). Blast The Outer Surfaces When Coating System Fails |
| Storage | Reservoir | Wakefield Street Tank. 2,000,000 Gallon Concrete Reservoir. No Cathodic Protection. OUT OF SERVICE. | 1 | 29 | N/A | 0 | Yes | Yes | No | $25,000 | Hydraulic Model Study Evaluate Tank unable to cycle due to pump head influence | Out Of Service. $100,000 to Demolish |
| Storage | Standpipe | West Street Tank. 1,000,000 Gallon Steel Standpipe. No Cathodic Protection. OUT OF SERVICE. | Enter Number of Components Included in The Infrastructure if More Than 1 | 63 | N/A | 0 | Yes | Yes | No | $100,000 | Demolition Contract unable to cycle due to pump head influence | Out Of Service. $100,000 to Demolish |

| Infrastructure Type | Infrastructure Subtype | Brief Infrastructure Description | Number of Infrastructure Subtype | Age (in years) | Condition (poor, fair, good, excellent; or rating scale) | Remaining Useful Life (in years) | Need for Rehabilitation or Replacement (20-year timeframe) (Yes/No) | Evaluation/Prioritization for Rehabilitation or Replacement (5-year intervals) (Yes/No) | Infrastructure Supports SDWA Compliance (Yes/No) | Financial Forecast (in dollars) | O&M Notes | Other Notes |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Storage | Standpipe | Read School House Road Tank. 1,500,000 Gallon Concrete Tank. No Cathodic Protection | 1 | 10 | Good | 50+ | No | Yes | Yes | $0 | $5,000 for Cleaning and Inspection | Constructed at 500ft elevation in 2009. Recoat Exterior As Coating System Fails. |
| Storage | Elevated Water Storage | Technology Park Elevated Tank. 1,500,000 Spheroid Steel Tank With Cathodic Protection | 1 | 31 | Very good | 50+ | Yes | No | Yes | $1,000,000 | $5,000 for Cleaning and Inspection | Costs for Complete Recoating, Cleaning, and Inspection. $1 million Expense for Complete Rehabilitation At The End of Coating System Life Cycle. |
| Storage | Reservoir | Carr Pond Road Tank. 3,000,000 Gallon Concrete Reservoir. No Cathodic Protection | 1 | 18 | Very good | 50+ | Yes | No | Yes | $0 | Unable to cycle per RIDOH requirements due to reduced demand and hydraulic influences | Recoat Exterior When Coating System Fails. Offline |
| Transmission_Distribution | Booster Pump Station Building | Knotty Oak Rd. | 1 | 19 | Poor Offline | 10 | No | No | No | $100,000 | No longe serviceable. Infrastructur shifted to 500 foot gradient making this pum station obsolete | Demolish Building |
| Transmission_Distribution | Booster Pumps | 1,200 gpm pump at Johnson Blvd. pumping station | 1 | 28 | Good | 10 | Yes | No | Yes | $50,000 | Obsolete | Removed From Service since Mishnock Treatment Plant High Service Capacity is Online |
| Transmission_Distribution | Booster Pump Station | West Warwick Industrial Park | 1 | 15 | Excellent | 20+ | Yes | Yes | Yes | $10,000 | Overhaul 1 Pump & Motor | Structure Consists Of A Prefabricated Buried Steel Vault With Ladder Access. |

| Infrastructure Type | Infrastructure Subtype | Brief Infrastructure Description | Number of Infrastructure Subtype | Age (in years) | Condition (poor, fair, good, excellent; or rating scale) | Remaining Useful Life (in years) | Need for Rehabilitation or Replacement (20-year timeframe) (Yes/No) | Evaluation/Prioritization for Rehabilitation or Replacement (5-year intervals) (Yes/No) | Infrastructure Supports SDWA Compliance (Yes/No) | Financial Forecast (in dollars) | O&M Notes | Other Notes |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission_Distribution | Booster Pump Station | Seitan Lane Booster Pump Station | 1 | 15 | Excellent | 10 | Yes | Yes | Yes | $5,000 | Overhaul 1 Pump & Motor | Structure Consists Of A Prefabricated Buried Steel Vault With Ladder Access. |
| Transmission_Distribution | Pressure reducing station | Middle Road | 1 | 21 | Good | 10 | Yes | No | Yes | $75,000 | 0 | Installed in 1999. 20+ Years With Proper Maintenance. A Mechanical/Electric Upgrade is Recommended at 16-20 Years at A Cost Of $75,000. |
| Transmission_Distribution | Pressure reducing station | Cowesett Road | 1 | 21 | Good | 10 | Yes | No | Yes | $75,000 | 0 | Installed in 1999. 20+ Years With Proper Maintenance. A Mechanical/Electric Upgrade is Recommended at 20-25 Years at A Cost Of $75,000. |
| Transmission_Distribution | Pressure reducing station | Love Lane | 1 | 21 | Good | 10 | Yes | No | Yes | $75,000 | 0 | Installed in 1999. 20+ Years With Proper Maintenance. A Mechanical/Electric Upgrade is Recommended at 20-25 Years at A Cost Of $75,000. |
| Transmission_Distribution | Pressure reducing station | Post Road | 1 | 21 | Good | 10 | Yes | No | Yes | $75,000 | 0 | Installed in 1999. 20+ Years With Proper Maintenance. A Mechanical/Electric Upgrade is Recommended at 20-25 Years at A Cost Of $75,000. |
| Transmission_Distribution | Pressure reducing station | Centerville Road | 1 | 21 | Good | 10 | Yes | No | Yes | $75,000 | 0 | Installed in 1999. 20+ Years With Proper Maintenance. A Mechanical/Electric Upgrade is Recommended at 20-25 Years at A Cost Of $75,000. |

| Infrastructure Type | Infrastructure Subtype | Brief Infrastructure Description | Number of Infrastructure Subtype | Age (in years) | Condition (poor, fair, good, excellent; or rating scale) | Remaining Useful Life (in years) | Need for Rehabilitation or Replacement (20-year timeframe) (Yes/No) | Evaluation/Prioritization for Rehabilitation or Replacement (5-year intervals) (Yes/No) | Infrastructure Supports SDWA Compliance (Yes/No) | Financial Forecast (in dollars) | O&M Notes | Other Notes |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission_Distribution | Pressure reducing station | Division Road | 1 | 21 | Excellent | 20 | Yes | No | Yes | $75,000 | 0 | Installed in 1999. 20+ Years With Proper Maintenance. A Mechanical/Electric Upgrade is Recommended at 16-20 Years at A Cost Of $75,000. |
| Transmission_Distribution | Pressure reducing station | Helen Street | 1 | 28 | Poor | 5 | Yes | Yes | Yes | $300,000 | This Facility Should Be Replaced With A Modern, Buried Capsule-Type Valve Vault With Confined Space Entry Provisions At The Estimated Cost Of $300,000. | Requires relocation of station and infrastructure. Relocate to Johnsons BLV site or may require aquision of property if this location is not usable |
| Transmission_Distribution | Pressure reducing station | Mishnock Road | 1 | 28 | Poor | 5 | Yes | Yes | Yes | $300,000 | This Facility Should Be Replaced With A Modern, Buried Capsule-Type Valve Vault With Confined Space Entry Provisions At The Estimated Cost Of $300,000. | Can be replaced on current property under control of KCWA |
| Transmission_Distribution | Pressure reducing station | Tiogue Avenue | 1 | 10 | Excellent | 15 | Yes | Yes | Yes | $0 | This Facility Should Be Replaced With A Modern, Buried Capsule-Type Valve Vault With Confined Space Entry Provisions At The Estimated Cost Of $300,000. | Installed in 2009. 20+ Years With Proper Maintenance. A Mechanical/Electric Upgrade is Recommended at 20-25 Years at A Cost Of $75,000. |
| Transmission_Distribution | Generator | Quaker Lane 600 kW GenSet with ATS | 1 | 5 | Excellent | 30-35 | No | No | Yes | $0 | 0 | 40+ Years With Proper Maintenance. No upgrades needed. |
| Transmission_Distribution | Generator | Setien Lane Booster Pump Station 725 kW Generator | 1 | 15 | Excellent | 30-35 | No | No | Yes | $0 | 0 | 40+ Years With Proper Maintenance. No upgrades needed. |

| Infrastructure Type | Infrastructure Subtype | Brief Infrastructure Description | Number of Infrastructure Subtype | Age (in years) | Condition (poor, fair, good, excellent; or rating scale) | Remaining Useful Life (in years) | Need for Rehabilitation or Replacement (20-year timeframe) (Yes/No) | Evaluation/Prioritization for Rehabilitation or Replacement (5-year intervals) (Yes/No) | Infrastructure Supports SDWA Compliance (Yes/No) | Financial Forecast (in dollars) | O&M Notes | Other Notes |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission_Distribution | Generator | Clinton Ave. Pump Station 725 kW Generator | 1 | 13 | Excellent | 30-35 | No | No | Yes | $0 | 0 | 40+ Years With Proper Maintenance. No upgrades needed. |
| Other | Office Building | Main Street Administrative and Maintenance Building | 1 | 100 years | Poor-Fair | Reached end of useful life | Yes | Yes | Yes | $8.000,000 | Purchase property and construct new facilities | Complete Replacement Using IFR and CIP Funds At A Cost Of $8,000,000. |
| Other | Other (describe) | Hydraulic Model Update | 1 | 10 | Fair | 1 | Yes | No | Yes | $125,000 | 2019 Update | Ongoing; Provides Guidance On Implementing System Improvements |
| Other | Other (describe) | GIS For The System | 1 | 10 | Ongoing | 20 | Yes | Yes | Meets SDWA Requirements (Yes/No) | $12,000 | continuous reoccuring cost | Update, Licenses & Software |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 5941 | P-7253 | COV | Abbotts Crossing Rd | 6 | Asbestos Cement | 476 | 69 | 2 out of 5 | $442 | 210,191 |
| Distribution Main | 5942 | P-7253 | COV | Abbotts Crossing Rd | 6 | Asbestos Cement | 204 | 69 | 2 out of 5 | $442 | 90,243 |
| Distribution Main | 5943 | P-7253 | COV | Abbotts Crossing Rd | 6 | Asbestos Cement | 598 | 69 | 2 out of 5 | $442 | 264,097 |
| Distribution Main | 7848 | P-7252 | COV | Abbotts Crossing Rd | 6 | Asbestos Cement | 51 | 69 | 2 out of 5 | $442 | 22,718 |
| Distribution Main | 7849 | P-7252 | COV | Abbotts Crossing Rd | 6 | Asbestos Cement | 6 | 69 | 2 out of 5 | $442 | 2,648 |
| Distribution Main | 11973 | P-7253 | COV | Abbotts Crossing Rd | 6 | Asbestos Cement | 396 | 69 | 2 out of 5 | $442 | 174,934 |
| Distribution Main | 6314 | P-7145 | COV | Acacia Ct | 8 | Asbestos Cement | 59 | 39 | 1 out of 5 | $442 | 26,081 |
| Distribution Main | 7278 | P-7145 | COV | Acacia Ct | 8 | Asbestos Cement | 522 | 39 | 1 out of 5 | $442 | 230,794 |
| Distribution Main | 1086 | | COV | Acorn St | 6 | Asbestos Cement | 17 | 53 | 1.85 out of 5 | $442 | 7,694 |
| Distribution Main | 2471 | P-8302 | COV | Acorn St | 6 | Asbestos Cement | 109 | 53 | 1.85 out of 5 | $442 | 48,256 |
| Distribution Main | 2472 | P-8302 | COV | Acorn St | 6 | Asbestos Cement | 196 | 53 | 1.85 out of 5 | $442 | 86,528 |
| Distribution Main | 2642 | P-8982 | COV | Acorn St | 6 | Asbestos Cement | 25 | 53 | 1.85 out of 5 | $442 | 10,872 |
| Distribution Main | 2643 | P-8982 | COV | Acorn St | 6 | Asbestos Cement | 418 | 53 | 1.85 out of 5 | $442 | 184,791 |
| Distribution Main | 11174 | P-8302 | COV | Acorn St | 6 | Asbestos Cement | 16 | 53 | 1.85 out of 5 | $442 | 7,269 |
| Distribution Main | 1854 | P-7604 | COV | Ada Ct | 6 | Asbestos Cement | 185 | 60 | 1.85 out of 5 | $442 | 81,739 |
| Distribution Main | 3285 | P-7445 | COV | Adams Dr | 8 | Asbestos Cement | 363 | 42 | 1.14 out of 5 | $442 | 160,491 |
| Distribution Main | 6615 | P-7445 | COV | Adams Dr | 8 | Asbestos Cement | 4 | 42 | 1.14 out of 5 | $442 | 1,919 |
| Distribution Main | 6616 | P-7445 | COV | Adams Dr | 8 | Asbestos Cement | 152 | 42 | 1.14 out of 5 | $442 | 67,361 |
| Distribution Main | 7434 | P-7176 | COV | Adams Dr | 8 | Asbestos Cement | 501 | 41 | 1.14 out of 5 | $442 | 221,243 |
| Transmission Main | 7514 | P-8387 | COV | Adams Dr | 12 | Ductile Iron | 31 | 30 | 0.14 out of 5 | $442 | 13,610 |
| Transmission Main | 7519 | P-8387 | COV | Adams Dr | 12 | Ductile Iron | 294 | 30 | 0.14 out of 5 | $442 | 129,841 |
| Distribution Main | 7806 | P-7175 | COV | Adams Dr | 8 | Asbestos Cement | 316 | 41 | 1.14 out of 5 | $442 | 139,646 |
| Distribution Main | 9949 | | COV | Adams Dr | 8 | Ductile Iron | 18 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 10870 | P-8386 | COV | Adams Dr | 12 | Ductile Iron | 147 | 30 | 0.14 out of 5 | $442 | 64,760 |
| Transmission Main | 10871 | P-7445 | COV | Adams Dr | 12 | Ductile Iron | 5 | 30 | 0.14 out of 5 | $442 | 2,015 |
| Distribution Main | 11345 | P-7176 | COV | Adams Dr | 8 | Asbestos Cement | 5 | 41 | 1.14 out of 5 | $442 | 2,015 |
| Distribution Main | 1757 | P-7578 | COV | Alaska St | 2 | Galvanized Iron | 20 | 86 | 3.43 out of 5 | $442 | 8,883 |
| Distribution Main | 2297 | P-8297 | COV | Alaska St | 8 | Ductile Iron | 134 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2782 | P-7578 | COV | Alaska St | 2 | Galvanized Iron | 378 | 86 | 3.43 out of 5 | $442 | 167,185 |
| Distribution Main | 3029 | P-9030 | COV | Albro Lane | 1 | Unknown | 195 | UNK | 1.42 out of 5 | $442 | 86,339 |
| Distribution Main | 1176 | P-8117 | COV | Alexis St | 8 | Ductile Iron | 286 | 27 | 0.14 out of 5 | $442 | 126,266 |
| Distribution Main | 1186 | P-8116 | COV | Alexis St | 8 | Ductile Iron | 599 | 27 | 0.14 out of 5 | $442 | 264,914 |
| Distribution Main | 1333 | P-7354 | COV | Almond Way | 8 | Ductile Iron | 220 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5304 | P-7248 | COV | Alvero Rd | 8 | Ductile Iron | 5 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5305 | P-7248 | COV | Alvero Rd | 8 | Ductile Iron | 712 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7923 | P-7248 | COV | Alvero Rd | 8 | Ductile Iron | 12 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7934 | P-7230 | COV | Alvero Rd | 8 | Asbestos Cement | 20 | 56 | 1.14 out of 5 | $442 | 8,961 |
| Distribution Main | 7935 | P-7230 | COV | Alvero Rd | 8 | Asbestos Cement | 430 | 56 | 1.14 out of 5 | $442 | 190,227 |
| Distribution Main | 7938 | P-7237 | COV | Alvero Rd | 8 | Asbestos Cement | 57 | 56 | 1.14 out of 5 | $442 | 25,136 |
| Distribution Main | 7939 | P-7237 | COV | Alvero Rd | 8 | Asbestos Cement | 314 | 56 | 1.14 out of 5 | $442 | 138,912 |
| Distribution Main | 11416 | P-7237 | COV | Alvero Rd | 8 | Asbestos Cement | 5 | 56 | 1.14 out of 5 | $442 | 2,175 |
| Transmission Main | 3709 | P-8841 | COV | Ames St | 16 | Asbestos Cement | 439 | 62 | 1.29 out of 5 | $442 | 194,133 |
| Transmission Main | 3710 | P-8841 | COV | Ames St | 16 | Asbestos Cement | 77 | 62 | 1.29 out of 5 | $442 | 33,849 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 8522 | P-8371 | COV | Ames St | 16 | Ductile Iron | 425 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8523 | P-8371 | COV | Ames St | 16 | Ductile Iron | 64 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8526 | P-8370 | COV | Ames St | 16 | Ductile Iron | 560 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8550 | P-8371 | COV | Ames St | 16 | Ductile Iron | 16 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11041 | P-1929 | COV | Ames St | 16 | Asbestos Cement | 27 | 62 | 1.29 out of 5 | $442 | 12,128 |
| Transmission Main | 208 | P-8838 | COV | Ames St. | 16 | Asbestos Cement | 543 | 62 | 1.29 out of 5 | $442 | 239,888 |
| Transmission Main | 209 | P-8838 | COV | Ames St. | 16 | Asbestos Cement | 384 | 62 | 1.29 out of 5 | $442 | 169,843 |
| Distribution Main | 1496 | P-7816 | COV | Amherst Ave | 6 | Asbestos Cement | 527 | 52 | 1.85 out of 5 | $442 | 232,907 |
| Distribution Main | 2716 | P-7996 | COV | Anderson Ave | 6 | Asbestos Cement | 221 | 58 | 1.85 out of 5 | $442 | 97,687 |
| Distribution Main | 2717 | P-7996 | COV | Anderson Ave | 6 | Asbestos Cement | 485 | 58 | 1.85 out of 5 | $442 | 214,246 |
| Distribution Main | 2553 | P-7623 | COV | Angelwood Rd. | 6 | Asbestos Cement | 29 | 60 | 1.85 out of 5 | $442 | 12,676 |
| Distribution Main | 2562 | P-7622 | COV | Angelwood Rd. | 6 | Asbestos Cement | 279 | 60 | 1.85 out of 5 | $442 | 123,320 |
| Distribution Main | 2621 | P-7623 | COV | Angelwood Rd. | 6 | Asbestos Cement | 456 | 60 | 1.85 out of 5 | $442 | 201,457 |
| Transmission Main | 8058 | P-8142 | COV | Angus St. | 12 | Ductile Iron | 565 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8059 | P-8142 | COV | Angus St. | 12 | Ductile Iron | 928 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 573 | P-8024 | COV | Ann Ct. | 2 | Copper | 313 | 79 | 2.43 out of 5 | $442 | 138,292 |
| Distribution Main | 1951 | P-7866 | COV | Anthony St. | 6 | Cast Iron | 7 | 86 | 2.43 out of 5 | $442 | 2,992 |
| Distribution Main | 2827 | P-7866 | COV | Anthony St. | 6 | Cast Iron | 181 | 86 | 2.43 out of 5 | $442 | 79,953 |
| Distribution Main | 2828 | P-7866 | COV | Anthony St. | 6 | Cast Iron | 286 | 86 | 2.43 out of 5 | $442 | 126,595 |
| Distribution Main | 3075 | P-9031 | COV | Anthony St. | 6 | Cast Iron | 324 | 86 | 2.43 out of 5 | $442 | 143,237 |
| Distribution Main | 3076 | P-9031 | COV | Anthony St. | 6 | Cast Iron | 107 | 86 | 2.43 out of 5 | $442 | 47,099 |
| Distribution Main | 10071 | P-9031 | COV | Anthony St. | 6 | Cast Iron | 21 | 86 | 2.43 out of 5 | $442 | 9,280 |
| Distribution Main | 7211 | P-8955 | COV | Apple Blossom Ln. | 6 | Asbestos Cement | 147 | 57 | 1.85 out of 5 | $442 | 64,819 |
| Distribution Main | 7212 | P-8955 | COV | Apple Blossom Ln. | 6 | Asbestos Cement | 86 | 57 | 1.85 out of 5 | $442 | 38,117 |
| Distribution Main | 7807 | P-7034 | COV | Apple Blossom Ln. | 6 | Asbestos Cement | 710 | 57 | 1.85 out of 5 | $442 | 313,623 |
| Distribution Main | 7831 | P-7035 | COV | Apple Blossom Ln. | 6 | Asbestos Cement | 606 | 57 | 1.85 out of 5 | $442 | 267,814 |
| Distribution Main | 11363 | P-8955 | COV | Apple Blossom Ln. | 6 | Asbestos Cement | 4 | 57 | 1.85 out of 5 | $442 | 1,764 |
| Distribution Main | 8093 | P-8391 | COV | Arbor Dr | 8 | Ductile Iron | 286 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8094 | P-8391 | COV | Arbor Dr | 8 | Ductile Iron | 230 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8099 | P-8394 | COV | Arbor Dr | 8 | Ductile Iron | 41 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8100 | P-8393 | COV | Arbor Dr | 8 | Ductile Iron | 42 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8372 | P-8390 | COV | Arbor Dr | 8 | Ductile Iron | 505 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8373 | P-8390 | COV | Arbor Dr | 8 | Ductile Iron | 511 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8374 | P-8404 | COV | Arbor Dr | 8 | Ductile Iron | 136 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8375 | P-8404 | COV | Arbor Dr | 8 | Ductile Iron | 206 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10846 | P-8387 | COV | Arbor Dr | 8 | Ductile Iron | 276 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11430 | P-8391 | COV | Arbor Dr | 8 | Ductile Iron | 48 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11431 | P-8391 | COV | Arbor Dr | 8 | Ductile Iron | 151 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11871 | P-8390 | COV | Arbor Dr | 8 | Ductile Iron | 270 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7958 | P-7124 | COV | Arbutus Tr. | 8 | Ductile Iron | 70 | 27 | 0.14 out of 5 | $442 | 31,070 |
| Distribution Main | 7959 | P-7124 | COV | Arbutus Tr. | 8 | Ductile Iron | 301 | 27 | 0.14 out of 5 | $442 | 133,042 |
| Distribution Main | 7966 | P-7123 | COV | Arbutus Tr. | 8 | Ductile Iron | 332 | 27 | 0.14 out of 5 | $442 | 146,783 |
| Distribution Main | 7967 | P-7120 | COV | Arbutus Tr. | 8 | Ductile Iron | 538 | 27 | 0.14 out of 5 | $442 | 237,998 |
| Distribution Main | 479 | P-7582 | COV | Arizona St. | 2 | Cast Iron | 20 | 86 | 3.14 out of 5 | $442 | 8,656 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 529 | P-8295 | COV | Arizona St. | 8 | Ductile Iron | 69 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1057 | P-7579 | COV | Arizona St. | 2 | Galvanized Iron | 25 | 86 | 3.43 out of 5 | $442 | 10,984 |
| Distribution Main | 1058 | P-7579 | COV | Arizona St. | 2 | Galvanized Iron | 524 | 86 | 3.43 out of 5 | $442 | 231,638 |
| Distribution Main | 1124 | P-7582 | COV | Arizona St. | 2 | Cast Iron | 284 | 86 | 3.85 out of 5 | $442 | 125,350 |
| Distribution Main | 1306 | P-8295 | COV | Arizona St. | 2 | Galvanized Iron | 8 | 86 | 3.43 out of 5 | $442 | 3,530 |
| Distribution Main | 2633 | P-7579 | COV | Arizona St. | 2 | Galvanized Iron | 31 | 86 | 3.43 out of 5 | $442 | 13,686 |
| Transmission Main | 186 | P-7697 | COV | Arnold Rd. | 16 | Cast Iron | 640 | 129 | 1.86 out of 5 | $442 | 283,063 |
| Transmission Main | 188 | P-8984 | COV | Arnold Rd. | 16 | Cast Iron | 26 | 129 | 1.86 out of 5 | $442 | 11,380 |
| Transmission Main | 257 | P-1779 | COV | Arnold Rd. | 16 | Ductile Iron | 10 | 28 | 0.14 out of 5 | $442 | 4,278 |
| Transmission Main | 258 | P-1779 | COV | Arnold Rd. | 16 | Ductile Iron | 193 | 28 | 0.14 out of 5 | $442 | 85,093 |
| Transmission Main | 259 | P-1766 | COV | Arnold Rd. | 16 | Ductile Iron | 104 | 28 | 0.14 out of 5 | $442 | 45,971 |
| Transmission Main | 260 | P-8185 | COV | Arnold Rd. | 16 | Ductile Iron | 108 | 28 | 0.14 out of 5 | $442 | 47,605 |
| Transmission Main | 261 | P-8185 | COV | Arnold Rd. | 16 | Ductile Iron | 830 | 28 | 0.14 out of 5 | $442 | 367,052 |
| Transmission Main | 273 | P-8183 | COV | Arnold Rd. | 16 | Ductile Iron | 167 | 28 | 0.14 out of 5 | $442 | 73,598 |
| Transmission Main | 274 | P-8183 | COV | Arnold Rd. | 16 | Ductile Iron | 37 | 28 | 0.14 out of 5 | $442 | 16,313 |
| Transmission Main | 349 | | COV | Arnold Rd. | 12 | Ductile Iron | 41 | 28 | 0.14 out of 5 | $442 | 18,095 |
| Transmission Main | 350 | | COV | Arnold Rd. | 12 | Ductile Iron | 8 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 352 | | COV | Arnold Rd. | 8 | Ductile Iron | 12 | 28 | 0.14 out of 5 | $442 | 5,447 |
| Distribution Main | 353 | | COV | Arnold Rd. | 8 | Ductile Iron | 4 | 28 | 0.14 out of 5 | $442 | 1,573 |
| Distribution Main | 354 | P-8314 | COV | Arnold Rd. | 8 | Ductile Iron | 21 | 28 | 0.14 out of 5 | $442 | 9,069 |
| Transmission Main | 690 | P-8183 | COV | Arnold Rd. | 16 | Ductile Iron | 148 | 28 | 0.14 out of 5 | $442 | 65,400 |
| Transmission Main | 693 | P-8183 | COV | Arnold Rd. | 16 | Ductile Iron | 36 | 28 | 0.14 out of 5 | $442 | 15,805 |
| Distribution Main | 715 | | COV | Arnold Rd. | 8 | Asbestos Cement | 23 | 50 | 1.14 out of 5 | $442 | 10,142 |
| Distribution Main | 716 | P-8187 | COV | Arnold Rd. | 8 | Asbestos Cement | 272 | 50 | 1.14 out of 5 | $442 | 120,268 |
| Distribution Main | 717 | P-8187 | COV | Arnold Rd. | 8 | Asbestos Cement | 148 | 50 | 1.14 out of 5 | $442 | 65,559 |
| Transmission Main | 764 | P-8185 | COV | Arnold Rd. | 16 | Ductile Iron | 894 | 28 | 0.14 out of 5 | $442 | 395,098 |
| Transmission Main | 765 | P-7697 | COV | Arnold Rd. | 16 | Cast Iron | 137 | 129 | 1.86 out of 5 | $442 | 60,740 |
| Transmission Main | 768 | P-8188 | COV | Arnold Rd. | 16 | Ductile Iron | 140 | 28 | 0.14 out of 5 | $442 | 61,687 |
| Transmission Main | 769 | P-8188 | COV | Arnold Rd. | 16 | Ductile Iron | 395 | 28 | 0.14 out of 5 | $442 | 174,519 |
| Distribution Main | 1035 | P-8176 | COV | Arnold Rd. | 8 | Asbestos Cement | 4 | 50 | 1.14 out of 5 | $442 | 1,856 |
| Transmission Main | 1041 | P-7692 | COV | Arnold Rd. | 16 | Cast Iron | 57 | 129 | 1.86 out of 5 | $442 | 25,089 |
| Transmission Main | 1422 | P-8188 | COV | Arnold Rd. | 16 | Ductile Iron | 236 | 28 | 0.14 out of 5 | $442 | 104,458 |
| Transmission Main | 1423 | P-8984 | COV | Arnold Rd. | 16 | Cast Iron | 237 | 129 | 1.86 out of 5 | $442 | 104,613 |
| Distribution Main | 1424 | P-7711 | COV | Arnold Rd. | 8 | Asbestos Cement | 157 | 50 | 1.14 out of 5 | $442 | 69,558 |
| Distribution Main | 1425 | P-7711 | COV | Arnold Rd. | 8 | Asbestos Cement | 154 | 50 | 1.14 out of 5 | $442 | 67,962 |
| Distribution Main | 1428 | P-8176 | COV | Arnold Rd. | 8 | Asbestos Cement | 300 | 50 | 1.14 out of 5 | $442 | 132,536 |
| Distribution Main | 1453 | | COV | Arnold Rd. | 6 | Unknown | 4 | UNK | 0.71 out of 5 | $442 | 1,595 |
| Transmission Main | 1618 | P-8188 | COV | Arnold Rd. | 16 | Ductile Iron | 1,401 | 28 | 0.14 out of 5 | $442 | 619,426 |
| Transmission Main | 1619 | P-8188 | COV | Arnold Rd. | 16 | Ductile Iron | 85 | 28 | 0.14 out of 5 | $442 | 37,534 |
| Distribution Main | 1620 | P-8185 | COV | Arnold Rd. | 8 | Asbestos Cement | 88 | 50 | 1.14 out of 5 | $442 | 39,033 |
| Distribution Main | 1621 | P-8185 | COV | Arnold Rd. | 8 | Asbestos Cement | 561 | 50 | 1.14 out of 5 | $442 | 247,976 |
| Transmission Main | 1622 | P-8185 | COV | Arnold Rd. | 16 | Ductile Iron | 456 | 28 | 0.14 out of 5 | $442 | 201,669 |
| Transmission Main | 1623 | P-8188 | COV | Arnold Rd. | 16 | Ductile Iron | 133 | 28 | 0.14 out of 5 | $442 | 58,831 |
| Transmission Main | 1624 | P-8188 | COV | Arnold Rd. | 16 | Ductile Iron | 646 | 28 | 0.14 out of 5 | $442 | 285,703 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 1650 | P-7711 | COV | Arnold Rd. | 8 | Asbestos Cement | 132 | 50 | 1.14 out of 5 | $442 | 58,363 |
| Transmission Main | 1653 | P-7697 | COV | Arnold Rd. | 16 | Cast Iron | 38 | 129 | 1.86 out of 5 | $442 | 16,772 |
| Transmission Main | 1654 | P-7690 | COV | Arnold Rd. | 16 | Cast Iron | 171 | 129 | 1.86 out of 5 | $442 | 75,577 |
| Transmission Main | 1655 | P-7694 | COV | Arnold Rd. | 16 | Cast Iron | 233 | 129 | 1.86 out of 5 | $442 | 103,083 |
| Transmission Main | 1656 | P-8306 | COV | Arnold Rd. | 16 | Cast Iron | 162 | 129 | 1.86 out of 5 | $442 | 71,709 |
| Transmission Main | 1657 | P-8306 | COV | Arnold Rd. | 16 | Cast Iron | 67 | 129 | 1.86 out of 5 | $442 | 29,643 |
| Transmission Main | 1753 | P-7596 | COV | Arnold Rd. | 16 | Cast Iron | 162 | 129 | 1.86 out of 5 | $442 | 71,544 |
| Transmission Main | 1760 | P-7597 | COV | Arnold Rd. | 16 | Cast Iron | 149 | 129 | 1.86 out of 5 | $442 | 65,977 |
| Transmission Main | 1761 | P-7651 | COV | Arnold Rd. | 16 | Cast Iron | 16 | 129 | 1.86 out of 5 | $442 | 6,947 |
| Transmission Main | 1762 | P-7651 | COV | Arnold Rd. | 16 | Cast Iron | 286 | 129 | 1.86 out of 5 | $442 | 126,287 |
| Distribution Main | 2186 | P-8176 | COV | Arnold Rd. | 8 | Asbestos Cement | 17 | 50 | 1.14 out of 5 | $442 | 7,708 |
| Distribution Main | 2192 | P-8313 | COV | Arnold Rd. | 8 | Asbestos Cement | 213 | 50 | 1.14 out of 5 | $442 | 94,362 |
| Transmission Main | 2289 | P-7650 | COV | Arnold Rd. | 16 | Cast Iron | 992 | 129 | 1.86 out of 5 | $442 | 438,283 |
| Distribution Main | 2448 | P-8313 | COV | Arnold Rd. | 8 | Asbestos Cement | 4 | 50 | 1.14 out of 5 | $442 | 1,621 |
| Distribution Main | 2564 | | COV | Arnold Rd. | 6 | Unknown | 4 | UNK | 0.71 out of 5 | $442 | 1,737 |
| Distribution Main | 2582 | P-8187 | COV | Arnold Rd. | 8 | Asbestos Cement | 388 | 50 | 1.14 out of 5 | $442 | 171,528 |
| Distribution Main | 2583 | | COV | Arnold Rd. | 8 | Asbestos Cement | 6 | 50 | 1.14 out of 5 | $442 | 2,790 |
| Transmission Main | 2590 | | COV | Arnold Rd. | 16 | Cast Iron | 33 | UNK | 1.14 out of 5 | $442 | 14,772 |
| Transmission Main | 2591 | | COV | Arnold Rd. | 16 | Cast Iron | 33 | UNK | 1.14 out of 5 | $442 | 14,566 |
| Transmission Main | 2592 | P-7688 | COV | Arnold Rd. | 16 | Ductile Iron | 173 | 129 | 0.72 out of 5 | $442 | 76,279 |
| Transmission Main | 2596 | P-8310 | COV | Arnold Rd. | 16 | Cast Iron | 285 | 129 | 1.86 out of 5 | $442 | 126,142 |
| Transmission Main | 2597 | P-8308 | COV | Arnold Rd. | 16 | Cast Iron | 205 | 129 | 1.86 out of 5 | $442 | 90,760 |
| Transmission Main | 2598 | P-8308 | COV | Arnold Rd. | 16 | Cast Iron | 33 | 129 | 1.86 out of 5 | $442 | 14,744 |
| Transmission Main | 2599 | P-7663 | COV | Arnold Rd. | 16 | Cast Iron | 241 | 129 | 1.86 out of 5 | $442 | 106,621 |
| Transmission Main | 2600 | P-7659 | COV | Arnold Rd. | 16 | Cast Iron | 175 | 129 | 1.86 out of 5 | $442 | 77,412 |
| Transmission Main | 2601 | P-8984 | COV | Arnold Rd. | 16 | Ductile Iron | 15 | 129 | 0.72 out of 5 | $442 | 6,775 |
| Transmission Main | 2602 | P-8984 | COV | Arnold Rd. | 16 | Ductile Iron | 19 | 28 | 0.14 out of 5 | $442 | 8,388 |
| Transmission Main | 2630 | P-8267 | COV | Arnold Rd. | 16 | Cast Iron | 35 | 129 | 1.86 out of 5 | $442 | 15,648 |
| Transmission Main | 2631 | P-8267 | COV | Arnold Rd. | 16 | Cast Iron | 224 | 129 | 1.86 out of 5 | $442 | 99,116 |
| Transmission Main | 2792 | P-8793 | COV | Arnold Rd. | 16 | Cast Iron | 168 | 129 | 1.86 out of 5 | $442 | 74,104 |
| Transmission Main | 2793 | P-8793 | COV | Arnold Rd. | 16 | Cast Iron | 198 | 129 | 1.86 out of 5 | $442 | 87,473 |
| Transmission Main | 2794 | P-7589 | COV | Arnold Rd. | 16 | Cast Iron | 6 | 129 | 1.86 out of 5 | $442 | 2,663 |
| Transmission Main | 2795 | P-7589 | COV | Arnold Rd. | 16 | Cast Iron | 66 | 129 | 1.86 out of 5 | $442 | 29,391 |
| Transmission Main | 2796 | P-7588 | COV | Arnold Rd. | 16 | Cast Iron | 398 | 129 | 1.86 out of 5 | $442 | 175,853 |
| Distribution Main | 3139 | P-8314 | COV | Arnold Rd. | 8 | Asbestos Cement | 138 | 50 | 1.14 out of 5 | $442 | 60,790 |
| Distribution Main | 3141 | P-8313 | COV | Arnold Rd. | 8 | Asbestos Cement | 180 | 50 | 1.14 out of 5 | $442 | 79,481 |
| Distribution Main | 3142 | P-8314 | COV | Arnold Rd. | 8 | Asbestos Cement | 383 | 50 | 1.14 out of 5 | $442 | 169,325 |
| Transmission Main | 9583 | P-8184 | COV | Arnold Rd. | 16 | Ductile Iron | 157 | 28 | 0.14 out of 5 | $442 | 69,294 |
| Distribution Main | 9584 | P-8313 | COV | Arnold Rd. | 8 | Asbestos Cement | 28 | 50 | 1.14 out of 5 | $442 | 12,568 |
| Distribution Main | 10351 | | COV | Arnold Rd. | 8 | Ductile Iron | 62 | 28 | 0.14 out of 5 | $442 | 27,519 |
| Distribution Main | 10352 | | COV | Arnold Rd. | 8 | Ductile Iron | 136 | 28 | 0.14 out of 5 | $442 | 59,984 |
| Transmission Main | 11025 | P-7697 | COV | Arnold Rd. | 16 | Cast Iron | 10 | 129 | 1.86 out of 5 | $442 | 4,299 |
| Transmission Main | 11138 | P-8306 | COV | Arnold Rd. | 16 | Cast Iron | 7 | 129 | 1.86 out of 5 | $442 | 3,106 |
| Transmission Main | 11177 | P-7694 | COV | Arnold Rd. | 16 | Cast Iron | 4 | 129 | 1.86 out of 5 | $442 | 1,820 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 11188 | P-8793 | COV | Arnold Rd. | 16 | Cast Iron | 38 | 133 | 1.86 out of 5 | $442 | 16,743 |
| Distribution Main | 11201 | P-8314 | COV | Arnold Rd. | 8 | Asbestos Cement | 24 | 50 | 1.14 out of 5 | $442 | 10,591 |
| Distribution Main | 3146 | P-9038 | COV | Arnold St. | 1 | Copper | 113 | 86 | 2.57 out of 5 | $442 | 49,916 |
| Distribution Main | 7963 | P-7134 | COV | Ash Ln. | 8 | Ductile Iron | 250 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7964 | P-7134 | COV | Ash Ln. | 8 | Ductile Iron | 9 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1855 | P-7606 | COV | Audrey Ct. | 6 | Asbestos Cement | 182 | 60 | 1.85 out of 5 | $442 | 80,227 |
| Distribution Main | 8727 | P-7108 | COV | Azalea Way | 8 | Asbestos Cement | 16 | 40 | 1 out of 5 | $442 | 6,997 |
| Distribution Main | 8728 | P-7107 | COV | Azalea Way | 8 | Asbestos Cement | 790 | 40 | 1 out of 5 | $442 | 349,362 |
| Distribution Main | 2922 | P-8848 | COV | Bakerville | 6 | Unknown | 156 | UNK | 0.71 out of 5 | $442 | 69,097 |
| Distribution Main | 9918 | P-8848 | COV | Bakerville | 6 | Unknown | 52 | UNK | 0.71 out of 5 | $442 | 23,062 |
| Distribution Main | 420 | P-7699 | COV | Balsam Rd. | 6 | Asbestos Cement | 288 | 60 | 1.85 out of 5 | $442 | 127,424 |
| Distribution Main | 2563 | P-7699 | COV | Balsam Rd. | 6 | Asbestos Cement | 9 | 60 | 1.85 out of 5 | $442 | 4,124 |
| Distribution Main | 2593 | P-7700 | COV | Balsam Rd. | 6 | Asbestos Cement | 136 | 60 | 1.85 out of 5 | $442 | 59,914 |
| Distribution Main | 9619 | P-7538 | COV | Bank St | 8 | PVC | 290 | 35 | 0.43 out of 5 | $442 | 128,085 |
| Distribution Main | 9620 | P-7538 | COV | Bank St | 8 | PVC | 8 | 35 | 0.43 out of 5 | $442 | 3,576 |
| Distribution Main | 5326 | P-7518 | COV | Barber St. | 2 | Galvanized Iron | 498 | 121 | 3.57 out of 5 | $442 | 220,016 |
| Distribution Main | 5327 | P-7518 | COV | Barber St. | 2 | Galvanized Iron | 67 | 121 | 3.57 out of 5 | $442 | 29,700 |
| Distribution Main | 10073 | P-7518 | COV | Barber St. | 4 | Cast Iron | 16 | 121 | 3.29 out of 5 | $442 | 6,864 |
| Distribution Main | 10074 | P-7518 | COV | Barber St. | 4 | Ductile Iron | 20 | 27 | 1.57 out of 5 | $442 | 8,840 |
| Distribution Main | 11298 | P-7518 | COV | Barber St. | 2 | Galvanized Iron | 6 | 121 | 3.57 out of 5 | $442 | 2,731 |
| Distribution Main | 226 | P-7897 | COV | Barberry Ct. | 6 | Asbestos Cement | 278 | 39 | 1.71 out of 5 | $442 | 122,706 |
| Distribution Main | 941 | P-8030 | COV | Bassett St. | 2 | Galvanized Iron | 276 | 109 | 3.57 out of 5 | $442 | 121,994 |
| Distribution Main | 312 | P-8278 | COV | Bates Ave. | 8 | Cast Iron | 365 | 132 | 1.86 out of 5 | $442 | 161,153 |
| Distribution Main | 574 | | COV | Bates Ave. | 6 | Cast Iron | 14 | 32 | 1.99 out of 5 | $442 | 6,188 |
| Distribution Main | 2699 | P-8278 | COV | Bates Ave. | 8 | Cast Iron | 175 | 79 | 1.57 out of 5 | $442 | 77,421 |
| Distribution Main | 6180 | P-8280 | COV | Bates Ave. | 6 | Cast Iron | 433 | 79 | 2.28 out of 5 | $442 | 191,170 |
| Distribution Main | 6181 | P-8280 | COV | Bates Ave. | 6 | Cast Iron | 115 | 79 | 2.28 out of 5 | $442 | 50,812 |
| Distribution Main | 6182 | P-8279 | COV | Bates Ave. | 2 | Cast Iron | 385 | 79 | 3 out of 5 | $442 | 170,199 |
| Distribution Main | 6183 | P-9057 | COV | Bates Ave. | 2 | Cast Iron | 209 | 132 | 3.29 out of 5 | $442 | 92,460 |
| Distribution Main | 6184 | P-8034 | COV | Bates Ave. | 6 | Cast Iron | 5 | 132 | 2.57 out of 5 | $442 | 2,245 |
| Distribution Main | 6185 | P-8034 | COV | Bates Ave. | 6 | Cast Iron | 494 | 132 | 2.57 out of 5 | $442 | 218,141 |
| Distribution Main | 2819 | P-7847 | COV | Battey Ave. | 6 | Ductile Iron | 164 | 29 | 0.85 out of 5 | $442 | 72,417 |
| Distribution Main | 2820 | P-7847 | COV | Battey Ave. | 6 | Ductile Iron | 376 | 29 | 0.85 out of 5 | $442 | 166,387 |
| Distribution Main | 9650 | P-7847 | COV | Battey Ave. | 6 | Ductile Iron | 316 | 29 | 0.85 out of 5 | $442 | 139,567 |
| Distribution Main | 842 | P-7787 | COV | Baylor Dr. | 6 | Asbestos Cement | 246 | 53 | 1.85 out of 5 | $442 | 108,829 |
| Distribution Main | 1483 | P-7783 | COV | Baylor Dr. | 6 | Asbestos Cement | 26 | 53 | 1.85 out of 5 | $442 | 11,438 |
| Distribution Main | 1484 | P-7783 | COV | Baylor Dr. | 6 | Asbestos Cement | 452 | 53 | 1.85 out of 5 | $442 | 199,900 |
| Distribution Main | 9807 | P-8989 | COV | Beach St | 8 | Ductile Iron | 161 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9808 | P-8988 | COV | Beach St | 8 | Ductile Iron | 6 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11610 | P-8988 | COV | Beach St | 8 | Ductile Iron | 8 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 767 | P-8988 | COV | Beach St. | 1 | Copper | 50 | 1 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 1457 | P-8992 | COV | Beach St. | 2 | Copper | 262 | 65 | 2.43 out of 5 | $442 | 115,872 |
| Distribution Main | 1645 | P-7660 | COV | Beach St. | 6 | Cast Iron | 43 | 65 | 2.28 out of 5 | $442 | 19,020 |
| Distribution Main | 11137 | P-7660 | COV | Beach St. | 6 | Cast Iron | 7 | 65 | 2.28 out of 5 | $442 | 3,020 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 5049 | P-7531 | COV | Beaton St. | 6 | Asbestos Cement | 401 | 71 | 2 out of 5 | $442 | 177,063 |
| Distribution Main | 5056 | P-7531 | COV | Beaton St. | 6 | Asbestos Cement | 76 | 71 | 2 out of 5 | $442 | 33,399 |
| Distribution Main | 9082 | P-9040 | COV | Beaulieu Ave | 1 | Copper | 447 | UNK | 1.99 out of 5 | $442 | 197,629 |
| Distribution Main | 9218 | P-8836 | COV | Bee St | 8 | Ductile Iron | 291 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1064 | P-8977 | COV | Beechwood St. | 6 | Asbestos Cement | 67 | 65 | 2 out of 5 | $442 | 29,788 |
| Distribution Main | 1065 | P-8977 | COV | Beechwood St. | 6 | Asbestos Cement | 207 | 65 | 2 out of 5 | $442 | 91,694 |
| Distribution Main | 1451 | | COV | Beechwood St. | 6 | Asbestos Cement | 28 | 65 | 2 out of 5 | $442 | 12,173 |
| Distribution Main | 2641 | P-8303 | COV | Beechwood St. | 6 | Asbestos Cement | 246 | 65 | 2 out of 5 | $442 | 108,777 |
| Distribution Main | 10869 | P-8304 | COV | Beechwood St. | 6 | Asbestos Cement | 244 | 65 | 2 out of 5 | $442 | 107,634 |
| Distribution Main | 11099 | P-8304 | COV | Beechwood St. | 6 | Asbestos Cement | 19 | 65 | 2 out of 5 | $442 | 8,543 |
| Distribution Main | 9089 | P-8886 | COV | Bellmare Rd | 8 | Ductile Iron | 72 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9090 | P-8886 | COV | Bellmare Rd | 8 | Ductile Iron | 286 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 828 | P-7401 | COV | Benoit St. | 6 | Ductile Iron | 839 | 27 | 0.85 out of 5 | $442 | 371,051 |
| Distribution Main | 829 | P-7401 | COV | Benoit St. | 6 | Ductile Iron | 475 | 27 | 0.85 out of 5 | $442 | 209,979 |
| Distribution Main | 2831 | P-7401 | COV | Benoit St. | 6 | Ductile Iron | 30 | 27 | 0.85 out of 5 | $442 | 13,157 |
| Distribution Main | 3078 | P-9033 | COV | Benoit St. | 6 | Ductile Iron | 245 | 27 | 0.85 out of 5 | $442 | 108,116 |
| Distribution Main | 3079 | P-9033 | COV | Benoit St. | 6 | Ductile Iron | 188 | 27 | 0.85 out of 5 | $442 | 83,143 |
| Distribution Main | 10070 | P-9033 | COV | Benoit St. | 6 | Ductile Iron | 3 | 27 | 0.85 out of 5 | $442 | 1,316 |
| Distribution Main | 8371 | P-9010 | COV | Berkshire Rd. | 1 | Copper | 96 | 13 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 844 | P-7813 | COV | Bernard Dr. | 6 | Asbestos Cement | 68 | 65 | 2 out of 5 | $442 | 29,865 |
| Distribution Main | 845 | P-7813 | COV | Bernard Dr. | 6 | Asbestos Cement | 150 | 65 | 2 out of 5 | $442 | 66,495 |
| Distribution Main | 9562 | P-7813 | COV | Bernard Dr. | 6 | Asbestos Cement | 176 | 65 | 2 out of 5 | $442 | 77,766 |
| Transmission Main | 7540 | | COV | Bestwick Trail | 12 | Ductile Iron | 73 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 7541 | | COV | Bestwick Trail | 12 | Ductile Iron | 6 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 143 | P-7924 | COV | Birchwood Ln. | 8 | PVC | 560 | 39 | 0.43 out of 5 | $442 | 247,389 |
| Distribution Main | 3014 | P-8338 | COV | Birdie Ct. | 6 | Ductile Iron | 245 | 30 | 0.85 out of 5 | $442 | 108,117 |
| Distribution Main | 1025 | P-7923 | COV | Black Walnut Dr. | 8 | PVC | 504 | 36 | 0.43 out of 5 | $442 | 222,917 |
| Distribution Main | 1026 | P-7921 | COV | Black Walnut Dr. | 8 | PVC | 137 | 36 | 0.43 out of 5 | $442 | 60,381 |
| Distribution Main | 1027 | P-7919 | COV | Black Walnut Dr. | 8 | PVC | 79 | 36 | 0.43 out of 5 | $442 | 34,770 |
| Distribution Main | 1050 | P-7927 | COV | Black Walnut Dr. | 8 | PVC | 216 | 36 | 0.43 out of 5 | $442 | 95,404 |
| Distribution Main | 1051 | P-7921 | COV | Black Walnut Dr. | 8 | PVC | 210 | 36 | 0.43 out of 5 | $442 | 92,762 |
| Distribution Main | 1913 | P-7929 | COV | Black Walnut Dr. | 8 | PVC | 21 | 36 | 0.43 out of 5 | $442 | 9,426 |
| Distribution Main | 1914 | P-7929 | COV | Black Walnut Dr. | 8 | PVC | 430 | 36 | 0.43 out of 5 | $442 | 190,114 |
| Distribution Main | 2463 | P-7917 | COV | Black Walnut Dr. | 8 | PVC | 296 | 36 | 0.43 out of 5 | $442 | 130,942 |
| Distribution Main | 2576 | P-7925 | COV | Black Walnut Dr. | 8 | PVC | 380 | 36 | 0.43 out of 5 | $442 | 167,836 |
| Distribution Main | 2577 | P-7925 | COV | Black Walnut Dr. | 8 | PVC | 99 | 36 | 0.43 out of 5 | $442 | 43,901 |
| Distribution Main | 11865 | P-7929 | COV | Black Walnut Dr. | 8 | PVC | 238 | 36 | 0.43 out of 5 | $442 | 105,234 |
| Distribution Main | 1138 | P-8874 | COV | Black Walnut St. | 8 | Ductile Iron | 7 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1139 | P-8874 | COV | Black Walnut St. | 8 | Ductile Iron | 28 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 601 | P-7970 | COV | Blackrock Rd | 24 | Ductile Iron | 306 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 602 | P-7397 | COV | Blackrock Rd | 8 | Asbestos Cement | 489 | 70 | 1.29 out of 5 | $442 | 215,931 |
| Distribution Main | 603 | P-7397 | COV | Blackrock Rd | 8 | Asbestos Cement | 223 | 70 | 1.29 out of 5 | $442 | 98,631 |
| Transmission Main | 8179 | P-8500 | COV | Blackrock Rd | 24 | Ductile Iron | 71 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8180 | P-8500 | COV | Blackrock Rd | 24 | Ductile Iron | 1,081 | 15 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 8183 | P-7396 | COV | Blackrock Rd | 12 | Ductile Iron | 49 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8186 | P-8499 | COV | Blackrock Rd | 24 | Ductile Iron | 263 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8188 | P-7397 | COV | Blackrock Rd | 8 | Asbestos Cement | 93 | 70 | 1.29 out of 5 | $442 | 40,946 |
| Transmission Main | 8189 | P-8499 | COV | Blackrock Rd | 24 | Ductile Iron | 25 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8190 | P-8499 | COV | Blackrock Rd | 24 | Ductile Iron | 581 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8192 | P-7944 | COV | Blackrock Rd | 24 | Ductile Iron | 98 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8193 | P-7944 | COV | Blackrock Rd | 24 | Ductile Iron | 325 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8194 | P-7936 | COV | Blackrock Rd | 24 | Ductile Iron | 594 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8222 | P-7970 | COV | Blackrock Rd | 24 | Ductile Iron | 45 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8223 | P-7970 | COV | Blackrock Rd | 24 | Ductile Iron | 517 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8225 | P-7397 | COV | Blackrock Rd | 8 | Asbestos Cement | 569 | 70 | 1.29 out of 5 | $442 | 251,524 |
| Distribution Main | 8226 | P-7397 | COV | Blackrock Rd | 8 | Asbestos Cement | 35 | 70 | 1.29 out of 5 | $442 | 15,313 |
| Transmission Main | 8227 | P-8499 | COV | Blackrock Rd | 24 | Ductile Iron | 543 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8229 | P-8501 | COV | Blackrock Rd | 24 | Ductile Iron | 144 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8230 | P-8501 | COV | Blackrock Rd | 24 | Ductile Iron | 374 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8234 | P-8501 | COV | Blackrock Rd | 24 | Ductile Iron | 615 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8236 | P-8501 | COV | Blackrock Rd | 24 | Ductile Iron | 722 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8237 | P-8501 | COV | Blackrock Rd | 24 | Ductile Iron | 322 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10063 | P-8497 | COV | Blackrock Rd | 24 | Ductile Iron | 32 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10080 | P-7397 | COV | Blackrock Rd | 8 | Ductile Iron | 9 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10389 | P-7397 | COV | Blackrock Rd | 8 | Ductile Iron | 13 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10390 | P-7397 | COV | Blackrock Rd | 8 | Ductile Iron | 183 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11033 | P-7397 | COV | Blackrock Rd | 8 | Asbestos Cement | 155 | 70 | 1.29 out of 5 | $442 | 68,431 |
| Transmission Main | 11036 | P-7970 | COV | Blackrock Rd | 24 | Ductile Iron | 257 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11072 | P-7944 | COV | Blackrock Rd | 24 | Ductile Iron | 479 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11073 | P-7944 | COV | Blackrock Rd | 24 | Ductile Iron | 9 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11442 | P-7396 | COV | Blackrock Rd | 12 | Ductile Iron | 5 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11444 | P-7944 | COV | Blackrock Rd | 24 | Ductile Iron | 36 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11445 | P-7944 | COV | Blackrock Rd | 24 | Ductile Iron | 258 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11447 | P-7936 | COV | Blackrock Rd | 24 | Ductile Iron | 2 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11452 | P-8501 | COV | Blackrock Rd | 24 | Ductile Iron | 175 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11639 | P-8497 | COV | Blackrock Rd | 24 | Ductile Iron | 6 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7746 | P-7060 | COV | Blue Spruce Dr | 8 | Asbestos Cement | 803 | 43 | 1.14 out of 5 | $442 | 354,783 |
| Distribution Main | 7747 | P-7060 | COV | Blue Spruce Dr | 8 | Asbestos Cement | 206 | 44 | 1.14 out of 5 | $442 | 91,183 |
| Distribution Main | 7819 | P-7060 | COV | Blue Spruce Dr | 8 | Asbestos Cement | 30 | 43 | 1.14 out of 5 | $442 | 13,257 |
| Distribution Main | 7735 | P-7050 | COV | Blueberry Ln | 6 | Asbestos Cement | 369 | 57 | 1.85 out of 5 | $442 | 163,133 |
| Distribution Main | 9629 | P-9015 | COV | Bonney St | 6 | Ductile Iron | 2 | 12 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9632 | P-9015 | COV | Bonney St | 8 | Ductile Iron | 50 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2259 | P-7766 | COV | Bonney St. | 8 | Ductile Iron | 32 | 59 | 0.29 out of 5 | $442 | 14,100 |
| Distribution Main | 3682 | P-7766 | COV | Bonney St. | 6 | Asbestos Cement | 12 | 59 | 1.85 out of 5 | $442 | 5,269 |
| Distribution Main | 3683 | P-7766 | COV | Bonney St. | 6 | Asbestos Cement | 445 | 59 | 1.85 out of 5 | $442 | 196,807 |
| Distribution Main | 10081 | | COV | Boston St | 4 | Ductile Iron | 30 | 12 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 200 | P-7867 | COV | Boston St. | 6 | Cast Iron | 344 | 91 | 2.43 out of 5 | $442 | 152,209 |
| Distribution Main | 253 | P-8377 | COV | Boston St. | 6 | Asbestos Cement | 776 | 70 | 2 out of 5 | $442 | 343,026 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 597 | P-8376 | COV | Boston St. | 6 | Ductile Iron | 887 | 27 | 0.85 out of 5 | $442 | 391,858 |
| Distribution Main | 598 | P-8376 | COV | Boston St. | 6 | Ductile Iron | 37 | 27 | 0.85 out of 5 | $442 | 16,299 |
| Distribution Main | 2375 | P-9037 | COV | Boston St. | 6 | Cast Iron | 402 | 91 | 2.43 out of 5 | $442 | 177,677 |
| Distribution Main | 2376 | P-9037 | COV | Boston St. | 6 | Cast Iron | 105 | 91 | 2.43 out of 5 | $442 | 46,207 |
| Distribution Main | 2377 | P-7403 | COV | Boston St. | 6 | Cast Iron | 8 | 91 | 2.43 out of 5 | $442 | 3,518 |
| Distribution Main | 2378 | P-7403 | COV | Boston St. | 6 | Cast Iron | 755 | 91 | 2.43 out of 5 | $442 | 333,842 |
| Distribution Main | 3082 | P-7402 | COV | Boston St. | 6 | Cast Iron | 112 | 91 | 2.43 out of 5 | $442 | 49,458 |
| Distribution Main | 8182 | P-8377 | COV | Boston St. | 8 | Ductile Iron | 18 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8187 | P-7396 | COV | Boston St. | 12 | Ductile Iron | 398 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8228 | P-8377 | COV | Boston St. | 6 | Asbestos Cement | 47 | 70 | 2 out of 5 | $442 | 20,918 |
| Distribution Main | 10069 | P-7399 | COV | Boston St. | 6 | Cast Iron | 38 | 91 | 2.43 out of 5 | $442 | 16,774 |
| Distribution Main | 10072 | P-9037 | COV | Boston St. | 6 | Cast Iron | 13 | 91 | 2.43 out of 5 | $442 | 5,916 |
| Transmission Main | 10078 | P-7396 | COV | Boston St. | 12 | Ductile Iron | 171 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11032 | P-8377 | COV | Boston St. | 6 | Asbestos Cement | 64 | 70 | 2 out of 5 | $442 | 28,502 |
| Distribution Main | 11779 | P-7403 | COV | Boston St. | 6 | Cast Iron | 461 | 91 | 2.43 out of 5 | $442 | 203,674 |
| Distribution Main | 7885 | P-7214 | COV | Boulder Dr. | 8 | Ductile Iron | 28 | 29 | 0.14 out of 5 | $442 | 12,325 |
| Distribution Main | 7886 | P-7214 | COV | Boulder Dr. | 8 | Ductile Iron | 307 | 29 | 0.14 out of 5 | $442 | 135,628 |
| Distribution Main | 7888 | P-7213 | COV | Boulder Dr. | 8 | Ductile Iron | 232 | 29 | 0.14 out of 5 | $442 | 102,737 |
| Distribution Main | 7889 | P-7213 | COV | Boulder Dr. | 8 | Ductile Iron | 486 | 29 | 0.14 out of 5 | $442 | 214,866 |
| Distribution Main | 3015 | P-8335 | COV | Brassie Ct. | 6 | Ductile Iron | 325 | 30 | 0.85 out of 5 | $442 | 143,656 |
| Distribution Main | 1617 | P-7364 | COV | Breezy Lake Dr. | 6 | Asbestos Cement | 201 | 54 | 1.85 out of 5 | $442 | 88,898 |
| Distribution Main | 2120 | P-8884 | COV | Breezy Lake Dr. | 1 | Unknown | 59 | UNK | 1.42 out of 5 | $442 | 26,147 |
| Distribution Main | 2121 | P-8882 | COV | Breezy Lake Dr. | 6 | Asbestos Cement | 30 | 54 | 1.85 out of 5 | $442 | 13,320 |
| Distribution Main | 2122 | P-8882 | COV | Breezy Lake Dr. | 6 | Asbestos Cement | 369 | 54 | 1.85 out of 5 | $442 | 163,070 |
| Distribution Main | 2123 | P-8883 | COV | Breezy Lake Dr. | 6 | Asbestos Cement | 213 | 54 | 1.85 out of 5 | $442 | 94,314 |
| Distribution Main | 2124 | P-7365 | COV | Breezy Lake Dr. | 6 | Asbestos Cement | 499 | 54 | 1.85 out of 5 | $442 | 220,767 |
| Distribution Main | 2125 | P-7367 | COV | Breezy Lake Dr. | 6 | Asbestos Cement | 185 | 54 | 1.85 out of 5 | $442 | 81,862 |
| Distribution Main | 2126 | P-7366 | COV | Breezy Lake Dr. | 6 | Asbestos Cement | 167 | 54 | 1.85 out of 5 | $442 | 73,905 |
| Distribution Main | 1613 | P-7364 | COV | Breezy Lake Rd | 8 | Ductile Iron | 56 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8786 | | COV | Brenda Dr | 8 | Ductile Iron | 34 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7854 | P-7184 | COV | Brenda Dr. | 6 | Asbestos Cement | 541 | 48 | 1.85 out of 5 | $442 | 239,195 |
| Distribution Main | 8788 | P-8895 | COV | Brenda Dr. | 6 | Ductile Iron | 2 | 8 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 2629 | P-7556 | COV | Brentwood Dr. | 6 | Asbestos Cement | 379 | 66 | 2 out of 5 | $442 | 167,331 |
| Distribution Main | 9940 | P-8995 | COV | Briar Point Ave | 8 | Ductile Iron | 41 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9941 | P-8995 | COV | Briar Point Ave | 8 | Ductile Iron | 136 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1461 | P-7695 | COV | Briar Point Ave. | 6 | Asbestos Cement | 460 | 72 | 2 out of 5 | $442 | 203,111 |
| Distribution Main | 1049 | P-7926 | COV | Briarwood Ct. | 8 | PVC | 242 | 39 | 0.43 out of 5 | $442 | 106,896 |
| Transmission Main | 8389 | P-8219 | COV | Broad St | 12 | Ductile Iron | 239 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8457 | P-1910 | COV | Broad St | 12 | Ductile Iron | 192 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8460 | P-1248 | COV | Broad St | 12 | Ductile Iron | 177 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9676 | P-1910 | COV | Broad St | 12 | Ductile Iron | 27 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9677 | P-1910 | COV | Broad St | 12 | Ductile Iron | 16 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 815 | P-7387 | COV | Brookfield Rd. | 8 | Ductile Iron | 512 | 28 | 0.14 out of 5 | $442 | 226,515 |
| Distribution Main | 9470 | P-8905 | COV | Brookside Lane | 2 | Copper | 5 | 69 | 2.43 out of 5 | $442 | 2,342 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9471 | P-8905 | COV | Brookside Lane | 2 | Copper | 292 | 69 | 2.43 out of 5 | $442 | 129,222 |
| Distribution Main | 9215 | P-8074 | COV | Brown St | 8 | Ductile Iron | 10 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2748 | P-8074 | COV | Brown St. | 8 | Cast Iron | 457 | 91 | 1.72 out of 5 | $442 | 201,935 |
| Distribution Main | 2749 | P-8074 | COV | Brown St. | 8 | Cast Iron | 604 | 91 | 1.72 out of 5 | $442 | 266,907 |
| Distribution Main | 11860 | P-8074 | COV | Brown St. | 8 | Cast Iron | 15 | 91 | 1.72 out of 5 | $442 | 6,422 |
| Distribution Main | 4811 | P-7076 | COV | Butternut Dr. | 8 | Ductile Iron | 184 | 28 | 0.14 out of 5 | $442 | 81,320 |
| Distribution Main | 4812 | P-7076 | COV | Butternut Dr. | 8 | Ductile Iron | 19 | 28 | 0.14 out of 5 | $442 | 8,398 |
| Distribution Main | 7592 | P-7076 | COV | Butternut Dr. | 8 | Asbestos Cement | 42 | 41 | 1.14 out of 5 | $442 | 18,482 |
| Distribution Main | 7779 | P-7157 | COV | Butternut Dr. | 8 | Asbestos Cement | 339 | 41 | 1.14 out of 5 | $442 | 149,867 |
| Distribution Main | 7780 | P-7157 | COV | Butternut Dr. | 8 | Asbestos Cement | 371 | 41 | 1.14 out of 5 | $442 | 163,842 |
| Distribution Main | 3002 | P-8934 | COV | Cady Street | 8 | Ductile Iron | 227 | 30 | 0.14 out of 5 | $442 | 100,263 |
| Distribution Main | 679 | P-8113 | COV | Canyon Dr. | 6 | Asbestos Cement | 25 | 59 | 1.85 out of 5 | $442 | 11,219 |
| Distribution Main | 2109 | P-8113 | COV | Canyon Dr. | 6 | Asbestos Cement | 341 | 59 | 1.85 out of 5 | $442 | 150,614 |
| Distribution Main | 2617 | P-7667 | COV | Cape Way | 6 | Asbestos Cement | 151 | 44 | 1.85 out of 5 | $442 | 66,782 |
| Distribution Main | 399 | P-8289 | COV | Capwell Ave. | 8 | Cast Iron | 472 | 132 | 1.86 out of 5 | $442 | 208,701 |
| Distribution Main | 400 | P-8289 | COV | Capwell Ave. | 8 | Cast Iron | 44 | 132 | 1.86 out of 5 | $442 | 19,354 |
| Distribution Main | 9518 | P-8292 | COV | Capwell Ave. | 6 | Cast Iron | 532 | 132 | 2.57 out of 5 | $442 | 235,184 |
| Distribution Main | 1504 | P-7573 | COV | Card St. | 6 | Cast Iron | 411 | 132 | 2.57 out of 5 | $442 | 181,448 |
| Distribution Main | 1505 | P-7573 | COV | Card St. | 6 | Cast Iron | 23 | 132 | 2.57 out of 5 | $442 | 10,170 |
| Distribution Main | 1765 | P-7814 | COV | Card St. | 2 | PVC | 4 | 30 | 1.85 out of 5 | $442 | 1,876 |
| Distribution Main | 9587 | P-7814 | COV | Card St. | 2 | PVC | 89 | 30 | 1.85 out of 5 | $442 | 39,186 |
| Distribution Main | 3039 | | COV | Cardinal Ave. | 6 | Asbestos Cement | 4 | 71 | 2 out of 5 | $442 | 1,659 |
| Distribution Main | 3042 | P-7987 | COV | Cardinal Ave. | 6 | Asbestos Cement | 234 | 71 | 2 out of 5 | $442 | 103,305 |
| Transmission Main | 8673 | P-8347 | COV | Carol Ct | 12 | PVC | 483 | 32 | 0.43 out of 5 | $442 | 213,346 |
| Distribution Main | 741 | P-7634 | COV | Carolyn St. | 6 | Asbestos Cement | 37 | 58 | 1.85 out of 5 | $442 | 16,236 |
| Distribution Main | 742 | P-7634 | COV | Carolyn St. | 6 | Asbestos Cement | 3 | 58 | 1.85 out of 5 | $442 | 1,512 |
| Distribution Main | 743 | P-7634 | COV | Carolyn St. | 6 | Asbestos Cement | 157 | 58 | 1.85 out of 5 | $442 | 69,287 |
| Distribution Main | 4786 | P-7519 | COV | Carr Street | 2 | Galvanized Iron | 194 | 92 | 3.43 out of 5 | $442 | 85,963 |
| Distribution Main | 6317 | P-7130 | COV | Catalpa Way | 8 | Ductile Iron | 66 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6318 | P-7130 | COV | Catalpa Way | 8 | Ductile Iron | 305 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7961 | P-7135 | COV | Catalpa Way | 8 | Ductile Iron | 224 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7962 | P-7135 | COV | Catalpa Way | 8 | Ductile Iron | 243 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7965 | P-7122 | COV | Catalpa Way | 8 | Ductile Iron | 787 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7973 | P-7136 | COV | Catalpa Way | 8 | Ductile Iron | 489 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 8731 | P-7130 | COV | Catalpa Way | 8 | Ductile Iron | 4 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 8732 | P-7122 | COV | Catalpa Way | 8 | Ductile Iron | 4 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 570 | P-7994 | COV | Cecile Ave. | 6 | Asbestos Cement | 374 | 67 | 2 out of 5 | $442 | 165,136 |
| Distribution Main | 571 | P-7994 | COV | Cecile Ave. | 6 | Asbestos Cement | 305 | 67 | 2 out of 5 | $442 | 134,854 |
| Distribution Main | 2711 | P-7990 | COV | Cecile Ave. | 6 | Asbestos Cement | 214 | 67 | 2 out of 5 | $442 | 94,503 |
| Distribution Main | 2712 | P-7990 | COV | Cecile Ave. | 6 | Asbestos Cement | 24 | 67 | 2 out of 5 | $442 | 10,825 |
| Distribution Main | 2730 | P-7992 | COV | Cecile Ave. | 6 | Asbestos Cement | 236 | 67 | 2 out of 5 | $442 | 104,177 |
| Distribution Main | 673 | P-8109 | COV | Cedar St. | 6 | Asbestos Cement | 467 | 60 | 1.85 out of 5 | $442 | 206,238 |
| Distribution Main | 674 | P-8109 | COV | Cedar St. | 6 | Asbestos Cement | 48 | 60 | 1.85 out of 5 | $442 | 21,060 |
| Distribution Main | 2110 | P-8121 | COV | Cedar St. | 6 | Ductile Iron | 608 | 25 | 0.85 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2638 | P-8985 | COV | Cedar Tree Lane | 2 | Copper | 145 | 84 | 2.57 out of 5 | $442 | 64,169 |
| Distribution Main | 2639 | P-8986 | COV | Cedar Tree Lane | 2 | Copper | 100 | 84 | 2.57 out of 5 | $442 | 44,420 |
| Distribution Main | 2586 | P-8985 | COV | Cedar Tree Ln | 6 | Asbestos Cement | 97 | 72 | 2 out of 5 | $442 | 42,669 |
| Distribution Main | 9727 | P-8849 | COV | Centennial St | 8 | Ductile Iron | 2 | 26 | 0.14 out of 5 | $442 | 884 |
| Distribution Main | 9728 | P-8849 | COV | Centennial St | 6 | Ductile Iron | 110 | 26 | 0.85 out of 5 | $442 | 48,695 |
| Distribution Main | 680 | P-7384 | COV | Centennial St. | 8 | Asbestos Cement | 113 | 48 | 1.14 out of 5 | $442 | 49,732 |
| Distribution Main | 681 | P-7384 | COV | Centennial St. | 8 | Asbestos Cement | 679 | 48 | 1.14 out of 5 | $442 | 300,121 |
| Distribution Main | 1468 | P-7375 | COV | Centennial St. | 8 | Asbestos Cement | 275 | 48 | 1.14 out of 5 | $442 | 121,542 |
| Distribution Main | 1469 | P-7376 | COV | Centennial St. | 8 | Asbestos Cement | 159 | 48 | 1.14 out of 5 | $442 | 70,291 |
| Distribution Main | 9726 | P-7385 | COV | Centennial St. | 8 | Asbestos Cement | 145 | 48 | 1.14 out of 5 | $442 | 64,077 |
| Transmission Main | 25 | P-8465 | COV | Center Of N.E. Blvd | 16 | Unknown | 7 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 9317 | P-8411 | COV | Centre New England Blvd | 12 | Ductile Iron | 6 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1587 | P-7835 | COV | Centre St. | 6 | Ductile Iron | 529 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 3147 | P-7822 | COV | Centre St. | 8 | Asbestos Cement | 779 | 56 | 1.14 out of 5 | $442 | 344,112 |
| Distribution Main | 10113 | P-7822 | COV | Centre St. | 8 | Asbestos Cement | 14 | 56 | 1.14 out of 5 | $442 | 6,036 |
| Distribution Main | 10114 | P-7822 | COV | Centre St. | 8 | Asbestos Cement | 24 | 56 | 1.14 out of 5 | $442 | 10,756 |
| Distribution Main | 11640 | P-7822 | COV | Centre St. | 8 | Asbestos Cement | 9 | 56 | 1.14 out of 5 | $442 | 3,861 |
| Distribution Main | 7947 | P-7211 | COV | Chandler Dr. | 8 | Asbestos Cement | 40 | 45 | 1.14 out of 5 | $442 | 17,827 |
| Distribution Main | 7948 | P-7211 | COV | Chandler Dr. | 8 | Asbestos Cement | 349 | 45 | 1.14 out of 5 | $442 | 154,185 |
| Distribution Main | 7955 | P-7208 | COV | Chandler Dr. | 8 | Asbestos Cement | 573 | 45 | 1.14 out of 5 | $442 | 253,128 |
| Distribution Main | 7956 | P-7208 | COV | Chandler Dr. | 8 | Asbestos Cement | 1,067 | 45 | 1.14 out of 5 | $442 | 471,576 |
| Distribution Main | 7957 | P-7198 | COV | Chandler Dr. | 8 | Asbestos Cement | 485 | 45 | 1.14 out of 5 | $442 | 214,312 |
| Distribution Main | 1668 | P-7612 | COV | Charlotte St. | 6 | Asbestos Cement | 606 | 60 | 1.85 out of 5 | $442 | 267,644 |
| Distribution Main | 1252 | P-7329 | COV | Charwood Dr. | 8 | Asbestos Cement | 481 | 41 | 1.14 out of 5 | $442 | 212,788 |
| Distribution Main | 1254 | P-7334 | COV | Charwood Dr. | 8 | Asbestos Cement | 232 | 41 | 1.14 out of 5 | $442 | 102,588 |
| Distribution Main | 1339 | P-7334 | COV | Charwood Dr. | 8 | Asbestos Cement | 133 | 41 | 1.14 out of 5 | $442 | 58,636 |
| Distribution Main | 7741 | P-7038 | COV | Cherry Blossom Ln. | 6 | Asbestos Cement | 608 | 57 | 1.85 out of 5 | $442 | 268,847 |
| Distribution Main | 7742 | P-7038 | COV | Cherry Blossom Ln. | 6 | Asbestos Cement | 531 | 57 | 1.85 out of 5 | $442 | 234,858 |
| Distribution Main | 249 | P-8119 | COV | Chestnut Street | 1 | Copper | 20 | 63 | 2.43 out of 5 | $442 | 8,911 |
| Distribution Main | 1418 | P-8119 | COV | Chestnut Street | 1 | Copper | 141 | 63 | 2.43 out of 5 | $442 | 62,198 |
| Distribution Main | 9468 | P-8858 | COV | Chestnut Street | 0.75 | Copper | 323 | UNK | 1.99 out of 5 | $442 | 142,987 |
| Distribution Main | 5331 | P-8522 | COV | Chloe Court | 8 | Ductile Iron | 434 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1688 | P-9042 | COV | Chopin Street | 2 | Galvanized Iron | 147 | 124 | 3.57 out of 5 | $442 | 65,114 |
| Distribution Main | 9641 | P-9042 | COV | Chopin Street | 6 | Asbestos Cement | 106 | 71 | 2 out of 5 | $442 | 46,695 |
| Distribution Main | 1956 | P-7290 | COV | Cindy Ln. | 6 | Asbestos Cement | 466 | 53 | 1.85 out of 5 | $442 | 205,860 |
| Distribution Main | 3054 | P-7340 | COV | Cinnamon Dr. | 8 | Ductile Iron | 465 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4455 | P-7022 | COV | Circlewood Dr. | 8 | Asbestos Cement | 465 | 41 | 1.14 out of 5 | $442 | 205,713 |
| Distribution Main | 4456 | P-7022 | COV | Circlewood Dr. | 8 | Asbestos Cement | 786 | 41 | 1.14 out of 5 | $442 | 347,341 |
| Distribution Main | 7748 | P-7024 | COV | Circlewood Dr. | 8 | Asbestos Cement | 424 | 41 | 1.14 out of 5 | $442 | 187,350 |
| Distribution Main | 7749 | P-7024 | COV | Circlewood Dr. | 8 | Asbestos Cement | 144 | 41 | 1.14 out of 5 | $442 | 63,566 |
| Distribution Main | 11799 | P-7022 | COV | Circlewood Dr. | 8 | Asbestos Cement | 628 | 41 | 1.14 out of 5 | $442 | 277,400 |
| Transmission Main | 2552 | P-8968 | COV | Clark Mill St. | 12 | Ductile Iron | 39 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2622 | P-8968 | COV | Clark Mill St. | 12 | Ductile Iron | 54 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6173 | P-8200 | COV | Clark Mill St. | 8 | Ductile Iron | 21 | 22 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6174 | P-8200 | COV | Clark Mill St. | 8 | Ductile Iron | 58 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6175 | P-8200 | COV | Clark Mill St. | 8 | Ductile Iron | 359 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6176 | P-8525 | COV | Clark Mill St. | 8 | Ductile Iron | 335 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6177 | P-8525 | COV | Clark Mill St. | 8 | Ductile Iron | 487 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 8095 | P-8966 | COV | Clark Mill St. | 8 | Ductile Iron | 394 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 8376 | P-8399 | COV | Clark Mill St. | 8 | Ductile Iron | 274 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 8377 | P-8399 | COV | Clark Mill St. | 8 | Ductile Iron | 215 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 8378 | P-8525 | COV | Clark Mill St. | 8 | Ductile Iron | 227 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 8379 | P-8525 | COV | Clark Mill St. | 8 | Ductile Iron | 163 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10842 | P-8966 | COV | Clark Mill St. | 8 | Ductile Iron | 9 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10843 | P-8966 | COV | Clark Mill St. | 8 | Ductile Iron | 273 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11872 | P-8525 | COV | Clark Mill St. | 8 | Ductile Iron | 224 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 225 | P-7908 | COV | Clarke Rd. | 20 | Asbestos Cement | 375 | 51 | 1.14 out of 5 | $442 | 165,647 |
| Transmission Main | 1014 | P-7892 | COV | Clarke Rd. | 20 | Asbestos Cement | 790 | 51 | 1.14 out of 5 | $442 | 349,337 |
| Transmission Main | 1015 | P-7892 | COV | Clarke Rd. | 20 | Asbestos Cement | 96 | 51 | 1.14 out of 5 | $442 | 42,230 |
| Transmission Main | 1179 | P-7911 | COV | Clarke Rd. | 20 | Asbestos Cement | 385 | 51 | 1.85 out of 5 | $442 | 170,012 |
| Transmission Main | 1927 | P-7907 | COV | Clarke Rd. | 20 | Asbestos Cement | 291 | 51 | 1 out of 5 | $442 | 128,406 |
| Transmission Main | 1928 | P-7907 | COV | Clarke Rd. | 20 | Asbestos Cement | 53 | 51 | 1.14 out of 5 | $442 | 23,564 |
| Transmission Main | 2460 | P-7916 | COV | Clarke Rd. | 20 | Asbestos Cement | 1,010 | 51 | 1.14 out of 5 | $442 | 446,316 |
| Transmission Main | 2461 | P-7916 | COV | Clarke Rd. | 20 | Asbestos Cement | 776 | 51 | 1 out of 5 | $442 | 343,178 |
| Transmission Main | 8104 | P-8488 | COV | Clarke Rd. | 12 | Ductile Iron | 26 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 8106 | P-8488 | COV | Clarke Rd. | 8 | Ductile Iron | 10 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 9966 | P-7909 | COV | Clarke Rd. | 20 | Asbestos Cement | 4 | 51 | 1.14 out of 5 | $442 | 1,642 |
| Transmission Main | 9967 | P-7909 | COV | Clarke Rd. | 20 | Asbestos Cement | 254 | 51 | 1.14 out of 5 | $442 | 112,275 |
| Distribution Main | 700 | P-7566 | COV | Clearview Dr. | 6 | Asbestos Cement | 236 | 67 | 2 out of 5 | $442 | 104,135 |
| Distribution Main | 1061 | P-7571 | COV | Clearview Dr. | 6 | Asbestos Cement | 26 | 67 | 2 out of 5 | $442 | 11,655 |
| Distribution Main | 1062 | P-7571 | COV | Clearview Dr. | 6 | Asbestos Cement | 268 | 67 | 2 out of 5 | $442 | 118,576 |
| Distribution Main | 1639 | P-8514 | COV | Clifton Ave. | 6 | Asbestos Cement | 12 | 63 | 2 out of 5 | $442 | 5,119 |
| Distribution Main | 1660 | P-7491 | COV | Clifton Ave. | 6 | Asbestos Cement | 194 | 63 | 2 out of 5 | $442 | 85,849 |
| Distribution Main | 1665 | P-8969 | COV | Clifton Ave. | 6 | Asbestos Cement | 214 | 63 | 2 out of 5 | $442 | 94,795 |
| Distribution Main | 2763 | P-7493 | COV | Clifton Ave. | 6 | Asbestos Cement | 211 | 63 | 2 out of 5 | $442 | 93,066 |
| Distribution Main | 2764 | P-7493 | COV | Clifton Ave. | 6 | Asbestos Cement | 96 | 63 | 2 out of 5 | $442 | 42,278 |
| Distribution Main | 4809 | P-7150 | COV | Clubhouse Rd. | 8 | PVC | 235 | 31 | 0.43 out of 5 | $442 | 103,879 |
| Distribution Main | 4810 | P-7150 | COV | Clubhouse Rd. | 8 | PVC | 384 | 31 | 0.43 out of 5 | $442 | 169,549 |
| Distribution Main | 7452 | P-7091 | COV | Clubhouse Rd. | 8 | Asbestos Cement | 7 | 45 | 1.14 out of 5 | $442 | 2,980 |
| Distribution Main | 7453 | P-7091 | COV | Clubhouse Rd. | 8 | Asbestos Cement | 169 | 45 | 1.14 out of 5 | $442 | 74,520 |
| Distribution Main | 7462 | P-7147 | COV | Clubhouse Rd. | 8 | Asbestos Cement | 1,007 | 45 | 1.14 out of 5 | $442 | 445,279 |
| Distribution Main | 7463 | P-7092 | COV | Clubhouse Rd. | 8 | Asbestos Cement | 718 | 45 | 1.14 out of 5 | $442 | 317,310 |
| Distribution Main | 7596 | P-8364 | COV | Clubhouse Rd. | 8 | PVC | 392 | 31 | 0.43 out of 5 | $442 | 173,475 |
| Distribution Main | 7600 | P-7148 | COV | Clubhouse Rd. | 8 | Asbestos Cement | 509 | 45 | 1.14 out of 5 | $442 | 225,171 |
| Distribution Main | 7774 | P-8361 | COV | Clubhouse Rd. | 8 | Asbestos Cement | 79 | 45 | 1.14 out of 5 | $442 | 34,754 |
| Distribution Main | 7775 | P-8362 | COV | Clubhouse Rd. | 8 | Asbestos Cement | 58 | 45 | 1.14 out of 5 | $442 | 25,774 |
| Distribution Main | 7788 | P-8362 | COV | Clubhouse Rd. | 8 | Asbestos Cement | 327 | 45 | 1.14 out of 5 | $442 | 144,388 |
| Distribution Main | 7789 | P-8362 | COV | Clubhouse Rd. | 8 | Asbestos Cement | 204 | 45 | 1.14 out of 5 | $442 | 89,981 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 11397 | P-7148 | COV | Clubhouse Rd. | 8 | Asbestos Cement | 37 | 45 | 1.14 out of 5 | $442 | 16,254 |
| Distribution Main | 7777 | P-8360 | COV | Clubhouse Rd. (Coventry H | 8 | Ductile Iron | 1,019 | 29 | 0.14 out of 5 | $442 | 450,243 |
| Distribution Main | 7778 | P-8360 | COV | Clubhouse Rd. (Coventry H | 8 | Ductile Iron | 1 | 29 | 0.14 out of 5 | $442 | 575 |
| Distribution Main | 10504 | P-7152 | COV | Clubhouse Rd. (Coventry H | 8 | Ductile Iron | 26 | 29 | 0.14 out of 5 | $442 | 11,460 |
| Distribution Main | 10505 | P-7152 | COV | Clubhouse Rd. (Coventry H | 8 | Ductile Iron | 594 | 29 | 0.14 out of 5 | $442 | 262,654 |
| Transmission Main | 847 | P-7190 | COV | Cobblestone Ter. | 12 | Ductile Iron | 31 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 848 | P-7190 | COV | Cobblestone Ter. | 12 | Ductile Iron | 725 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 849 | P-7189 | COV | Cobblestone Ter. | 8 | Ductile Iron | 229 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 850 | P-7191 | COV | Cobblestone Ter. | 12 | Ductile Iron | 963 | 26 | 0.14 out of 5 | $442 | 425,471 |
| Transmission Main | 851 | P-7191 | COV | Cobblestone Ter. | 12 | Ductile Iron | 59 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5849 | P-8808 | COV | Cobblestone Ter. | 8 | Ductile Iron | 81 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5853 | P-7188 | COV | Cobblestone Ter. | 8 | Ductile Iron | 468 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5855 | P-8808 | COV | Cobblestone Ter. | 8 | Ductile Iron | 394 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5856 | P-8808 | COV | Cobblestone Ter. | 8 | Ductile Iron | 346 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5857 | P-7189 | COV | Cobblestone Ter. | 8 | Ductile Iron | 438 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7960 | P-7191 | COV | Cobblestone Ter. | 8 | Ductile Iron | 19 | 26 | 0.14 out of 5 | $442 | 8,463 |
| Distribution Main | 10976 | P-7188 | COV | Cobblestone Ter. | 8 | Ductile Iron | 18 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11031 | P-7190 | COV | Cobblestone Ter. | 12 | Ductile Iron | 2 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11979 | P-7191 | COV | Cobblestone Ter. | 12 | Ductile Iron | 806 | 26 | 0.14 out of 5 | $442 | 356,275 |
| Distribution Main | 5854 | P-8892 | COV | Cobblestone Terr | 8 | Ductile Iron | 39 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3176 | P-7784 | COV | Colby Dr. | 6 | Asbestos Cement | 501 | 56 | 1.85 out of 5 | $442 | 221,401 |
| Distribution Main | 7914 | P-8908 | COV | Collier Way | 6 | Asbestos Cement | 5 | 65 | 2 out of 5 | $442 | 2,316 |
| Distribution Main | 7915 | P-8908 | COV | Collier Way | 6 | Asbestos Cement | 202 | 65 | 2 out of 5 | $442 | 89,091 |
| Distribution Main | 7916 | | COV | Collier Way | 6 | Unknown | 12 | 65 | 1.14 out of 5 | $442 | 5,438 |
| Distribution Main | 11275 | P-8908 | COV | Collier Way | 6 | Asbestos Cement | 5 | 65 | 2 out of 5 | $442 | 2,115 |
| Distribution Main | 1593 | P-7644 | COV | Colonial Rd. | 6 | Asbestos Cement | 382 | 53 | 1.85 out of 5 | $442 | 169,005 |
| Distribution Main | 2609 | | COV | Colonial Rd. | 6 | Asbestos Cement | 26 | 53 | 1.85 out of 5 | $442 | 11,336 |
| Distribution Main | 2612 | P-7645 | COV | Colonial Rd. | 6 | Asbestos Cement | 379 | 53 | 1.85 out of 5 | $442 | 167,455 |
| Distribution Main | 2613 | P-7645 | COV | Colonial Rd. | 6 | Asbestos Cement | 254 | 53 | 1.85 out of 5 | $442 | 112,140 |
| Distribution Main | 2614 | P-7644 | COV | Colonial Rd. | 6 | Asbestos Cement | 6 | 53 | 1.85 out of 5 | $442 | 2,633 |
| Distribution Main | 1123 | P-7581 | COV | Colorado St. | 2 | Galvanized Iron | 539 | 86 | 4.14 out of 5 | $442 | 238,279 |
| Distribution Main | 1172 | P-7581 | COV | Colorado St. | 2 | Galvanized Iron | 31 | 86 | 3.43 out of 5 | $442 | 13,624 |
| Distribution Main | 1173 | P-7581 | COV | Colorado St. | 2 | Galvanized Iron | 2 | 86 | 3.43 out of 5 | $442 | 780 |
| Distribution Main | 1711 | P-7796 | COV | Columbia Ave. | 6 | Asbestos Cement | 1,016 | 60 | 1.85 out of 5 | $442 | 449,030 |
| Distribution Main | 1712 | P-7796 | COV | Columbia Ave. | 6 | Asbestos Cement | 781 | 60 | 1.85 out of 5 | $442 | 345,117 |
| Distribution Main | 1713 | P-7773 | COV | Columbia Ave. | 6 | Asbestos Cement | 24 | 60 | 1.85 out of 5 | $442 | 10,746 |
| Distribution Main | 1714 | P-7773 | COV | Columbia Ave. | 6 | Asbestos Cement | 618 | 60 | 1.85 out of 5 | $442 | 273,254 |
| Distribution Main | 2202 | P-7796 | COV | Columbia Ave. | 6 | Asbestos Cement | 20 | 60 | 1.85 out of 5 | $442 | 8,911 |
| Distribution Main | 10972 | P-7773 | COV | Columbia Ave. | 6 | Asbestos Cement | 7 | 60 | 1.85 out of 5 | $442 | 2,895 |
| Distribution Main | 11115 | P-7796 | COV | Columbia Ave. | 6 | Asbestos Cement | 10 | 60 | 1.85 out of 5 | $442 | 4,247 |
| Transmission Main | 10391 | P-8872 | COV | Colvin St. | 24 | Ductile Iron | 121 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10392 | P-8872 | COV | Colvin St. | 24 | Ductile Iron | 403 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12235 | | COV | Colvin St. | 24 | Ductile Iron | 95 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1911 | P-8474 | COV | Colvintown Rd. | 8 | Ductile Iron | 650 | 16 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 1912 | P-8474 | COV | Colvintown Rd. | 8 | Ductile Iron | 448 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2411 | P-8890 | COV | Colvintown Rd. | 8 | Ductile Iron | 155 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2412 | P-8890 | COV | Colvintown Rd. | 8 | Ductile Iron | 639 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2413 | P-8269 | COV | Colvintown Rd. | 8 | Ductile Iron | 229 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2414 | P-8269 | COV | Colvintown Rd. | 8 | Ductile Iron | 715 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2415 | P-8269 | COV | Colvintown Rd. | 8 | Ductile Iron | 292 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2416 | P-8269 | COV | Colvintown Rd. | 8 | Ductile Iron | 893 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2417 | P-8269 | COV | Colvintown Rd. | 8 | Ductile Iron | 152 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2418 | P-8269 | COV | Colvintown Rd. | 8 | Ductile Iron | 964 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2971 | P-8474 | COV | Colvintown Rd. | 8 | Ductile Iron | 261 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2972 | P-8474 | COV | Colvintown Rd. | 8 | Ductile Iron | 41 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4101 | P-8474 | COV | Colvintown Rd. | 8 | Ductile Iron | 472 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4102 | P-8474 | COV | Colvintown Rd. | 8 | Ductile Iron | 439 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5301 | P-8273 | COV | Colvintown Rd. | 8 | Asbestos Cement | 513 | 48 | 1.14 out of 5 | $442 | 226,649 |
| Distribution Main | 5302 | P-8273 | COV | Colvintown Rd. | 8 | Asbestos Cement | 611 | 48 | 1.14 out of 5 | $442 | 270,199 |
| Distribution Main | 5303 | P-7421 | COV | Colvintown Rd. | 8 | Asbestos Cement | 4 | 48 | 1.14 out of 5 | $442 | 1,630 |
| Distribution Main | 7162 | P-7220 | COV | Colvintown Rd. | 8 | Asbestos Cement | 4 | 48 | 1.14 out of 5 | $442 | 1,606 |
| Distribution Main | 7166 | P-7316 | COV | Colvintown Rd. | 8 | Asbestos Cement | 36 | 48 | 1.14 out of 5 | $442 | 15,993 |
| Distribution Main | 7167 | P-7316 | COV | Colvintown Rd. | 8 | Asbestos Cement | 482 | 48 | 1.14 out of 5 | $442 | 213,160 |
| Distribution Main | 7168 | P-7314 | COV | Colvintown Rd. | 8 | Asbestos Cement | 656 | 48 | 1.14 out of 5 | $442 | 290,030 |
| Distribution Main | 7169 | P-7343 | COV | Colvintown Rd. | 8 | Asbestos Cement | 7 | 48 | 1.14 out of 5 | $442 | 3,025 |
| Distribution Main | 7521 | P-8774 | COV | Colvintown Rd. | 8 | Asbestos Cement | 11 | 48 | 1.14 out of 5 | $442 | 5,015 |
| Distribution Main | 7522 | P-8774 | COV | Colvintown Rd. | 8 | Asbestos Cement | 218 | 48 | 1.14 out of 5 | $442 | 96,357 |
| Distribution Main | 7852 | P-8270 | COV | Colvintown Rd. | 8 | Asbestos Cement | 300 | 48 | 1.14 out of 5 | $442 | 132,533 |
| Distribution Main | 7853 | P-8270 | COV | Colvintown Rd. | 8 | Asbestos Cement | 604 | 48 | 1.14 out of 5 | $442 | 266,831 |
| Distribution Main | 7907 | P-7315 | COV | Colvintown Rd. | 8 | Asbestos Cement | 299 | 48 | 1.14 out of 5 | $442 | 132,225 |
| Distribution Main | 7908 | P-7315 | COV | Colvintown Rd. | 8 | Asbestos Cement | 54 | 48 | 1.14 out of 5 | $442 | 23,724 |
| Distribution Main | 7910 | P-7294 | COV | Colvintown Rd. | 8 | Asbestos Cement | 251 | 48 | 1.14 out of 5 | $442 | 111,083 |
| Distribution Main | 7911 | P-7294 | COV | Colvintown Rd. | 8 | Asbestos Cement | 182 | 48 | 1.14 out of 5 | $442 | 80,390 |
| Distribution Main | 7912 | P-7314 | COV | Colvintown Rd. | 8 | Asbestos Cement | 4 | 48 | 1.14 out of 5 | $442 | 1,557 |
| Distribution Main | 7917 | P-7218 | COV | Colvintown Rd. | 8 | Asbestos Cement | 440 | 48 | 1.14 out of 5 | $442 | 194,345 |
| Distribution Main | 7918 | P-7218 | COV | Colvintown Rd. | 8 | Asbestos Cement | 303 | 48 | 1.14 out of 5 | $442 | 133,885 |
| Distribution Main | 7919 | P-7240 | COV | Colvintown Rd. | 8 | Asbestos Cement | 428 | 48 | 1.14 out of 5 | $442 | 189,117 |
| Distribution Main | 7931 | P-7220 | COV | Colvintown Rd. | 8 | Asbestos Cement | 60 | 48 | 1.14 out of 5 | $442 | 26,528 |
| Distribution Main | 9301 | P-8891 | COV | Colvintown Rd. | 8 | Ductile Iron | 8 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9302 | P-8891 | COV | Colvintown Rd. | 8 | Ductile Iron | 23 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9434 | P-7314 | COV | Colvintown Rd. | 8 | Asbestos Cement | 43 | 48 | 1.14 out of 5 | $442 | 18,807 |
| Distribution Main | 10082 | P-8890 | COV | Colvintown Rd. | 8 | Ductile Iron | 274 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10974 | P-7315 | COV | Colvintown Rd. | 8 | Asbestos Cement | 33 | 48 | 1.14 out of 5 | $442 | 14,401 |
| Distribution Main | 11173 | P-8269 | COV | Colvintown Rd. | 8 | Ductile Iron | 109 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11243 | P-8474 | COV | Colvintown Rd. | 8 | Ductile Iron | 83 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11414 | P-7218 | COV | Colvintown Rd. | 8 | Asbestos Cement | 40 | 48 | 1.14 out of 5 | $442 | 17,810 |
| Distribution Main | 11415 | P-7218 | COV | Colvintown Rd. | 8 | Asbestos Cement | 15 | 48 | 1.14 out of 5 | $442 | 6,502 |
| Transmission Main | 268 | P-8174 | COV | Compton Rd. | 12 | Ductile Iron | 886 | 47 | 0.29 out of 5 | $442 | 391,762 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 355 | P-8176 | COV | Compton Rd. | 12 | Asbestos Cement | 2 | 47 | 1.14 out of 5 | $442 | 917 |
| Transmission Main | 691 | P-8176 | COV | Compton Rd. | 12 | Asbestos Cement | 12 | 47 | 1.14 out of 5 | $442 | 5,193 |
| Distribution Main | 8224 | P-9036 | COV | Congdon St. | 4 | Cast Iron | 495 | 70 | 3 out of 5 | $442 | 218,883 |
| Distribution Main | 9519 | P-7398 | COV | Congdon St. | 6 | Cast Iron | 471 | 70 | 2.28 out of 5 | $442 | 208,337 |
| Distribution Main | 9335 | P-8395 | COV | Conifer Ct | 8 | Ductile Iron | 177 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9336 | P-8396 | COV | Conifer Ct | 8 | Ductile Iron | 6 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9337 | P-8396 | COV | Conifer Ct | 8 | Ductile Iron | 344 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1447 | P-7858 | COV | Contentment Dr. | 8 | Asbestos Cement | 258 | 50 | 1.14 out of 5 | $442 | 114,118 |
| Distribution Main | 1448 | P-7858 | COV | Contentment Dr. | 8 | Asbestos Cement | 231 | 50 | 1.14 out of 5 | $442 | 102,319 |
| Distribution Main | 2379 | P-7858 | COV | Contentment Dr. | 8 | Asbestos Cement | 11 | 50 | 1.14 out of 5 | $442 | 4,770 |
| Distribution Main | 10461 | | COV | Contentment Dr. | 8 | Asbestos Cement | 3 | 50 | 1.14 out of 5 | $442 | 1,516 |
| Distribution Main | 11130 | P-7858 | COV | Contentment Dr. | 8 | Asbestos Cement | 182 | 50 | 1.14 out of 5 | $442 | 80,600 |
| Distribution Main | 710 | P-8312 | COV | Cook St. | 6 | Ductile Iron | 538 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 3229 | P-7800 | COV | Cornell Ct. | 6 | Asbestos Cement | 401 | 52 | 1.85 out of 5 | $442 | 177,096 |
| Distribution Main | 698 | P-7842 | COV | Cote Ct. | 6 | Ductile Iron | 201 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 699 | P-7841 | COV | Cote Ct. | 6 | Ductile Iron | 448 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 3172 | P-7838 | COV | Cote Ct. | 6 | Ductile Iron | 608 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 3173 | P-7838 | COV | Cote Ct. | 6 | Ductile Iron | 19 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 816 | P-7388 | COV | Country View Dr. | 8 | Ductile Iron | 49 | 30 | 0.14 out of 5 | $442 | 21,448 |
| Distribution Main | 817 | P-7388 | COV | Country View Dr. | 8 | Ductile Iron | 500 | 30 | 0.14 out of 5 | $442 | 221,136 |
| Distribution Main | 11090 | P-7388 | COV | Country View Dr. | 8 | Ductile Iron | 289 | 30 | 0.14 out of 5 | $442 | 127,643 |
| Distribution Main | 11861 | P-7388 | COV | Country View Dr. | 8 | Ductile Iron | 342 | 30 | 0.14 out of 5 | $442 | 151,185 |
| Distribution Main | 1174 | P-7670 | COV | Cove Rd. | 6 | Asbestos Cement | 618 | 56 | 1.85 out of 5 | $442 | 273,029 |
| Distribution Main | 1175 | P-7670 | COV | Cove Rd. | 6 | Asbestos Cement | 43 | 56 | 1.85 out of 5 | $442 | 18,983 |
| Distribution Main | 1178 | P-7619 | COV | Coventry Dr. | 6 | Asbestos Cement | 555 | 60 | 1.85 out of 5 | $442 | 245,500 |
| Distribution Main | 1637 | P-7607 | COV | Coventry Dr. | 6 | Asbestos Cement | 518 | 60 | 1.85 out of 5 | $442 | 229,079 |
| Distribution Main | 1638 | P-7614 | COV | Coventry Dr. | 6 | Asbestos Cement | 101 | 60 | 1.85 out of 5 | $442 | 44,854 |
| Distribution Main | 1662 | P-7603 | COV | Coventry Dr. | 6 | Asbestos Cement | 203 | 60 | 1.85 out of 5 | $442 | 89,514 |
| Distribution Main | 1664 | P-7614 | COV | Coventry Dr. | 6 | Asbestos Cement | 35 | 60 | 1.85 out of 5 | $442 | 15,407 |
| Distribution Main | 1842 | P-7605 | COV | Coventry Dr. | 6 | Asbestos Cement | 39 | 60 | 1.85 out of 5 | $442 | 17,454 |
| Distribution Main | 1843 | P-7605 | COV | Coventry Dr. | 6 | Asbestos Cement | 248 | 60 | 1.85 out of 5 | $442 | 109,408 |
| Distribution Main | 9507 | P-8944 | COV | Coventry Dr. | 8 | Ductile Iron | 34 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9508 | P-8944 | COV | Coventry Dr. | 8 | Ductile Iron | 26 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9571 | P-8945 | COV | Coventry Dr. | 6 | Ductile Iron | 4 | 19 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 5330 | | COV | Coventry/Spring Lake Well | 12 | Ductile Iron | 378 | 30 | 0.14 out of 5 | $442 | 166,955 |
| Distribution Main | 5341 | | COV | Coventry/Spring Lake Well | 8 | Ductile Iron | 94 | 30 | 0.14 out of 5 | $442 | 41,692 |
| Distribution Main | 5342 | | COV | Coventry/Spring Lake Well | 8 | Ductile Iron | 334 | 30 | 0.14 out of 5 | $442 | 147,475 |
| Transmission Main | 11299 | | COV | Coventry/Spring Lake Well | 12 | Ductile Iron | 17 | 30 | 0.14 out of 5 | $442 | 7,712 |
| Distribution Main | 2466 | P-7905 | COV | Crabapple Ct. | 6 | Asbestos Cement | 252 | 39 | 1.71 out of 5 | $442 | 111,515 |
| Distribution Main | 9760 | P-619 | COV | Creighton Pl | 8 | Ductile Iron | 211 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9767 | P-619 | COV | Creighton Pl | 8 | Ductile Iron | 364 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9768 | P-619 | COV | Creighton Pl | 8 | Ductile Iron | 38 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2584 | P-7708 | COV | Crestwood Rd. | 8 | Asbestos Cement | 502 | 60 | 1.14 out of 5 | $442 | 222,034 |
| Transmission Main | 266 | P-8538 | COV | Crompton Rd. | 16 | Ductile Iron | 276 | 28 | 0.14 out of 5 | $442 | 122,188 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 267 | P-8711 | COV | Crompton Rd. | 16 | Ductile Iron | 32 | 28 | 0.14 out of 5 | $442 | 14,058 |
| Transmission Main | 692 | P-8172 | COV | Crompton Rd. | 16 | Ductile Iron | 4 | 28 | 0.14 out of 5 | $442 | 1,595 |
| Transmission Main | 12060 | P-8711 | COV | Crompton Rd. | 16 | Ductile Iron | 154 | 28 | 0.14 out of 5 | $442 | 68,167 |
| Distribution Main | 7157 | P-7236 | COV | Cynthia Dr. | 8 | Asbestos Cement | 442 | 54 | 1.14 out of 5 | $442 | 195,370 |
| Distribution Main | 7158 | P-7233 | COV | Cynthia Dr. | 8 | Asbestos Cement | 706 | 54 | 1.14 out of 5 | $442 | 312,061 |
| Distribution Main | 7159 | P-7233 | COV | Cynthia Dr. | 8 | Asbestos Cement | 297 | 54 | 1.14 out of 5 | $442 | 131,457 |
| Distribution Main | 7863 | P-7235 | COV | Cynthia Dr. | 8 | Asbestos Cement | 493 | 54 | 1.14 out of 5 | $442 | 217,972 |
| Distribution Main | 7926 | P-7232 | COV | Cynthia Dr. | 8 | Asbestos Cement | 211 | 54 | 1.14 out of 5 | $442 | 93,320 |
| Distribution Main | 2268 | P-7764 | COV | Cypruss Rd. | 6 | Asbestos Cement | 555 | 57 | 1.85 out of 5 | $442 | 245,523 |
| Distribution Main | 2272 | P-7764 | COV | Cypruss Rd. | 6 | Asbestos Cement | 32 | 57 | 1.85 out of 5 | $442 | 14,252 |
| Distribution Main | 7155 | P-7203 | COV | Daniel Dr. | 6 | Asbestos Cement | 48 | 44 | 1.85 out of 5 | $442 | 21,006 |
| Distribution Main | 7864 | P-7210 | COV | Daniel Dr. | 6 | Asbestos Cement | 544 | 44 | 1.85 out of 5 | $442 | 240,501 |
| Distribution Main | 7865 | P-7210 | COV | Daniel Dr. | 6 | Asbestos Cement | 38 | 44 | 1.85 out of 5 | $442 | 16,689 |
| Distribution Main | 7913 | P-7202 | COV | Daniel Dr. | 6 | Asbestos Cement | 998 | 44 | 1.85 out of 5 | $442 | 441,043 |
| Distribution Main | 7952 | P-7199 | COV | Daniel Dr. | 6 | Asbestos Cement | 379 | 44 | 1.85 out of 5 | $442 | 167,317 |
| Distribution Main | 8356 | P-7721 | COV | Darton St. | 8 | Ductile Iron | 162 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10273 | | COV | David Drive | 6 | Ductile Iron | 662 | 5 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9631 | P-9017 | COV | Dawley St | 6 | Ductile Iron | 2 | 12 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9633 | P-9017 | COV | Dawley St | 8 | Ductile Iron | 29 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1594 | P-7767 | COV | Dawley St. | 8 | Ductile Iron | 23 | 66 | 0.43 out of 5 | $442 | 10,292 |
| Distribution Main | 2258 | P-7767 | COV | Dawley St. | 6 | Asbestos Cement | 521 | 66 | 2 out of 5 | $442 | 230,132 |
| Distribution Main | 199 | P-7283 | COV | Dawn Ln. | 6 | Asbestos Cement | 403 | 57 | 1.85 out of 5 | $442 | 177,945 |
| Distribution Main | 11028 | P-7283 | COV | Dawn Ln. | 6 | Asbestos Cement | 31 | 57 | 1.85 out of 5 | $442 | 13,713 |
| Distribution Main | 40 | P-7472 | COV | Deborah Ave | 6 | Asbestos Cement | 47 | 57 | 1.85 out of 5 | $442 | 20,769 |
| Distribution Main | 2765 | P-7469 | COV | Deborah Ave. | 6 | Asbestos Cement | 310 | 57 | 1.85 out of 5 | $442 | 137,149 |
| Distribution Main | 2766 | P-7469 | COV | Deborah Ave. | 6 | Asbestos Cement | 268 | 57 | 1.85 out of 5 | $442 | 118,576 |
| Distribution Main | 7873 | P-7310 | COV | Deer Run Rd. | 6 | Asbestos Cement | 1,038 | 35 | 1.71 out of 5 | $442 | 458,637 |
| Distribution Main | 7874 | P-7310 | COV | Deer Run Rd. | 6 | Asbestos Cement | 22 | 35 | 1.71 out of 5 | $442 | 9,840 |
| Distribution Main | 7880 | P-7310 | COV | Deer Run Rd. | 6 | Asbestos Cement | 35 | 35 | 1.71 out of 5 | $442 | 15,509 |
| Distribution Main | 11977 | P-7310 | COV | Deer Run Rd. | 6 | Asbestos Cement | 36 | 35 | 1.71 out of 5 | $442 | 16,045 |
| Distribution Main | 2269 | P-7761 | COV | Deerfield Rd. | 6 | Asbestos Cement | 6 | 55 | 1.85 out of 5 | $442 | 2,570 |
| Distribution Main | 2273 | P-7761 | COV | Deerfield Rd. | 6 | Asbestos Cement | 12 | 55 | 1.85 out of 5 | $442 | 5,226 |
| Distribution Main | 3677 | P-7761 | COV | Deerfield Rd. | 6 | Asbestos Cement | 83 | 55 | 1.85 out of 5 | $442 | 36,802 |
| Distribution Main | 3678 | P-7761 | COV | Deerfield Rd. | 6 | Asbestos Cement | 568 | 55 | 1.85 out of 5 | $442 | 250,849 |
| Distribution Main | 3816 | P-7760 | COV | Deerfield Rd. | 8 | Asbestos Cement | 158 | UNK | 0.85 out of 5 | $442 | 69,627 |
| Distribution Main | 10364 | P-7760 | COV | Deerfield Rd. | 8 | Ductile Iron | 62 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10365 | P-7760 | COV | Deerfield Rd. | 8 | Ductile Iron | 7 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1859 | P-7546 | COV | Dell St. | 6 | Asbestos Cement | 325 | 69 | 2 out of 5 | $442 | 143,617 |
| Distribution Main | 1860 | P-7546 | COV | Dell St. | 6 | Asbestos Cement | 6 | 69 | 2 out of 5 | $442 | 2,814 |
| Distribution Main | 9219 | P-8835 | COV | Dennis St | 8 | Ductile Iron | 213 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2844 | P-7811 | COV | Dexter St. | 6 | Asbestos Cement | 499 | 69 | 2 out of 5 | $442 | 220,726 |
| Distribution Main | 7871 | P-7205 | COV | Diane Dr. | 8 | Asbestos Cement | 40 | 40 | 1 out of 5 | $442 | 17,862 |
| Distribution Main | 7950 | P-7206 | COV | Diane Dr. | 8 | Asbestos Cement | 595 | 40 | 1 out of 5 | $442 | 262,887 |
| Distribution Main | 7951 | P-7206 | COV | Diane Dr. | 8 | Asbestos Cement | 363 | 40 | 1 out of 5 | $442 | 160,629 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 314 | P-9052 | COV | Dion Ave | 1 | Copper | 130 | 70 | 2.43 out of 5 | $442 | 57,421 |
| Distribution Main | 953 | P-8007 | COV | Dion Ave. | 6 | Asbestos Cement | 241 | 70 | 2 out of 5 | $442 | 106,312 |
| Distribution Main | 9635 | P-9050 | COV | Dion Ave. | 6 | Asbestos Cement | 88 | 70 | 2 out of 5 | $442 | 39,023 |
| Distribution Main | 9636 | P-9049 | COV | Dion Ave. | 1 | Copper | 113 | 70 | 2.43 out of 5 | $442 | 50,034 |
| Distribution Main | 9805 | P-8990 | COV | Dixie Rd | 8 | Ductile Iron | 103 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9806 | P-8991 | COV | Dixie Rd | 6 | Ductile Iron | 13 | 12 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 1651 | P-7658 | COV | Dixie Rd. | 6 | Ductile Iron | 10 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 1652 | P-7658 | COV | Dixie Rd. | 6 | Ductile Iron | 561 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 9630 | P-9016 | COV | Dodd St | 8 | Ductile Iron | 327 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7723 | P-7019 | COV | Dogwood Dr. | 6 | PVC | 56 | 33 | 1.14 out of 5 | $442 | 24,781 |
| Distribution Main | 7724 | P-7019 | COV | Dogwood Dr. | 6 | PVC | 570 | 33 | 1.14 out of 5 | $442 | 251,809 |
| Distribution Main | 7170 | P-8271 | COV | Donna'S Way | 8 | Ductile Iron | 323 | 30 | 0.14 out of 5 | $442 | 142,808 |
| Distribution Main | 7171 | P-8271 | COV | Donna'S Way | 8 | Ductile Iron | 111 | 30 | 0.14 out of 5 | $442 | 49,271 |
| Distribution Main | 2729 | P-7989 | COV | Doolittle St. | 6 | Asbestos Cement | 532 | 61 | 2 out of 5 | $442 | 235,059 |
| Distribution Main | 2731 | P-7981 | COV | Doolittle St. | 6 | Asbestos Cement | 466 | 61 | 2 out of 5 | $442 | 205,918 |
| Distribution Main | 2732 | P-8001 | COV | Doolittle St. | 6 | Asbestos Cement | 435 | 61 | 2.71 out of 5 | $442 | 192,279 |
| Distribution Main | 6313 | P-7143 | COV | Doric Ct. | 6 | Asbestos Cement | 20 | 39 | 1.71 out of 5 | $442 | 8,680 |
| Distribution Main | 7277 | P-7143 | COV | Doric Ct. | 6 | Asbestos Cement | 259 | 39 | 1.71 out of 5 | $442 | 114,610 |
| Distribution Main | 1567 | P-8052 | COV | Doris St. | 6 | Asbestos Cement | 311 | 56 | 1.85 out of 5 | $442 | 137,542 |
| Distribution Main | 8581 | P-9048 | COV | Douglas Ct | 8 | Ductile Iron | 36 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8582 | P-9048 | COV | Douglas Ct | 8 | Ductile Iron | 233 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9338 | P-8393 | COV | Douglas Fir Way | 8 | Ductile Iron | 147 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9339 | P-8393 | COV | Douglas Fir Way | 8 | Ductile Iron | 144 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1337 | P-7330 | COV | Driftwood Dr. | 8 | Asbestos Cement | 1,042 | 48 | 1.14 out of 5 | $442 | 460,711 |
| Distribution Main | 1338 | P-7330 | COV | Driftwood Dr. | 8 | Asbestos Cement | 34 | 48 | 1.14 out of 5 | $442 | 15,027 |
| Distribution Main | 11789 | P-7330 | COV | Driftwood Dr. | 8 | Asbestos Cement | 227 | 48 | 1.14 out of 5 | $442 | 100,521 |
| Distribution Main | 4808 | P-8276 | COV | Dumont Farm Rd. | 6 | Ductile Iron | 250 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 514 | P-8380 | COV | Easement | 6 | Asbestos Cement | 171 | 53 | 1.85 out of 5 | $442 | 75,794 |
| Distribution Main | 1187 | P-8375 | COV | Easement | 6 | Cast Iron | 310 | 119 | 2.57 out of 5 | $442 | 137,224 |
| Distribution Main | 1999 | P-8346 | COV | Easement | 8 | Ductile Iron | 133 | 30 | 0.14 out of 5 | $442 | 58,705 |
| Transmission Main | 2000 | P-8330 | COV | Easement | 12 | Ductile Iron | 276 | 30 | 0.14 out of 5 | $442 | 122,165 |
| Transmission Main | 4806 | P-8329 | COV | Easement | 12 | Ductile Iron | 1,730 | 30 | 0.14 out of 5 | $442 | 764,571 |
| Distribution Main | 10170 | P-8789 | COV | Easement | 8 | Ductile Iron | 187 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10235 | P-8812 | COV | Easement | 8 | Ductile Iron | 528 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 696 | P-7741 | COV | East Shore Dr | 8 | Ductile Iron | 419 | 27 | 0.14 out of 5 | $442 | 185,213 |
| Distribution Main | 697 | P-7741 | COV | East Shore Dr | 8 | Ductile Iron | 199 | 27 | 0.14 out of 5 | $442 | 87,970 |
| Distribution Main | 2293 | P-7739 | COV | East Shore Dr | 8 | Ductile Iron | 382 | 27 | 0.14 out of 5 | $442 | 168,859 |
| Distribution Main | 9943 | P-7739 | COV | East Shore Dr | 6 | Ductile Iron | 8 | 27 | 0.85 out of 5 | $442 | 3,721 |
| Distribution Main | 11912 | P-7741 | COV | East Shore Dr | 8 | Ductile Iron | 24 | 27 | 0.14 out of 5 | $442 | 10,645 |
| Distribution Main | 694 | P-7738 | COV | East Shore Dr. | 8 | Asbestos Cement | 272 | 49 | 1.14 out of 5 | $442 | 120,030 |
| Distribution Main | 695 | P-7738 | COV | East Shore Dr. | 8 | Asbestos Cement | 5 | 49 | 1.14 out of 5 | $442 | 2,014 |
| Distribution Main | 1293 | P-7719 | COV | East Shore Dr. | 8 | Ductile Iron | 435 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2292 | P-7737 | COV | East Shore Dr. | 8 | Asbestos Cement | 373 | 49 | 1.14 out of 5 | $442 | 164,675 |
| Distribution Main | 8362 | P-9013 | COV | East Shore Dr. | 8 | Ductile Iron | 92 | 13 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 8363 | P-9011 | COV | East Shore Dr. | 8 | Ductile Iron | 18 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8364 | P-7721 | COV | East Shore Dr. | 8 | Ductile Iron | 88 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8365 | P-7721 | COV | East Shore Dr. | 8 | Ductile Iron | 110 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8370 | P-7722 | COV | East Shore Dr. | 8 | Ductile Iron | 278 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10854 | P-7720 | COV | East Shore Dr. | 8 | Ductile Iron | 203 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10855 | P-7720 | COV | East Shore Dr. | 8 | Ductile Iron | 14 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10856 | P-7733 | COV | East Shore Dr. | 8 | Ductile Iron | 298 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10857 | P-8763 | COV | East Shore Dr. | 8 | Ductile Iron | 115 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10858 | P-8763 | COV | East Shore Dr. | 8 | Ductile Iron | 139 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11466 | P-7720 | COV | East Shore Dr. | 8 | Ductile Iron | 6 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11467 | P-7719 | COV | East Shore Dr. | 8 | Ductile Iron | 246 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7273 | P-7144 | COV | Eastgate Dr. | 8 | Asbestos Cement | 389 | 40 | 1 out of 5 | $442 | 172,127 |
| Distribution Main | 7274 | P-7144 | COV | Eastgate Dr. | 8 | Asbestos Cement | 60 | 40 | 1 out of 5 | $442 | 26,720 |
| Distribution Main | 7275 | P-7142 | COV | Eastgate Dr. | 8 | Asbestos Cement | 7 | 40 | 1 out of 5 | $442 | 3,235 |
| Distribution Main | 7276 | P-7142 | COV | Eastgate Dr. | 8 | Asbestos Cement | 375 | 40 | 1 out of 5 | $442 | 165,900 |
| Distribution Main | 7279 | P-7146 | COV | Eastgate Dr. | 8 | Asbestos Cement | 429 | 40 | 1 out of 5 | $442 | 189,516 |
| Distribution Main | 7974 | P-7144 | COV | Eastgate Dr. | 8 | Asbestos Cement | 47 | 40 | 1 out of 5 | $442 | 20,934 |
| Distribution Main | 9670 | P-8794 | COV | Edith St | 8 | Ductile Iron | 68 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2768 | P-7635 | COV | Edna St. | 6 | Asbestos Cement | 324 | 58 | 1.85 out of 5 | $442 | 143,125 |
| Distribution Main | 8580 | P-9046 | COV | Edward St | 8 | Ductile Iron | 402 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10874 | P-9047 | COV | Edward St | 8 | Ductile Iron | 50 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1170 | P-7972 | COV | Edward St. | 6 | Asbestos Cement | 115 | 72 | 2 out of 5 | $442 | 50,689 |
| Distribution Main | 1214 | P-9043 | COV | Edward St. | 2 | Galvanized Iron | 299 | UNK | 2.85 out of 5 | $442 | 131,967 |
| Distribution Main | 1215 | P-9043 | COV | Edward St. | 2 | Galvanized Iron | 171 | 21 | 2.99 out of 5 | N/A | $0 |
| Distribution Main | 2363 | P-7971 | COV | Edward St. | 2 | Galvanized Iron | 219 | 89 | 3.43 out of 5 | $442 | 96,800 |
| Distribution Main | 2734 | P-7991 | COV | Edward St. | 6 | Asbestos Cement | 11 | 67 | 2 out of 5 | $442 | 4,761 |
| Distribution Main | 2735 | P-7991 | COV | Edward St. | 6 | Asbestos Cement | 302 | 67 | 2 out of 5 | $442 | 133,602 |
| Distribution Main | 2737 | P-7968 | COV | Edward St. | 6 | Ductile Iron | 166 | 21 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 9638 | P-9044 | COV | Edward St. | 6 | Asbestos Cement | 77 | UNK | 1.56 out of 5 | $442 | 34,203 |
| Distribution Main | 9639 | P-9044 | COV | Edward St. | 6 | Asbestos Cement | 94 | UNK | 1.56 out of 5 | $442 | 41,486 |
| Distribution Main | 9735 | P-607 | COV | Eileen Dr | 8 | Ductile Iron | 228 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11594 | P-606 | COV | Eileen Dr | 8 | Ductile Iron | 107 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 576 | P-7984 | COV | Eisenhower St. | 6 | Asbestos Cement | 387 | 48 | 1.85 out of 5 | $442 | 171,229 |
| Distribution Main | 577 | P-7984 | COV | Eisenhower St. | 6 | Asbestos Cement | 39 | 48 | 1.85 out of 5 | $442 | 17,331 |
| Distribution Main | 2709 | P-7983 | COV | Eisenhower St. | 6 | Asbestos Cement | 513 | 48 | 1.85 out of 5 | $442 | 226,787 |
| Distribution Main | 668 | P-8110 | COV | Eleanor Dr. | 6 | Asbestos Cement | 201 | 59 | 1.85 out of 5 | $442 | 88,757 |
| Distribution Main | 669 | P-8110 | COV | Eleanor Dr. | 6 | Asbestos Cement | 535 | 59 | 1.85 out of 5 | $442 | 236,637 |
| Distribution Main | 11857 | P-8110 | COV | Eleanor Dr. | 6 | Asbestos Cement | 48 | 59 | 1.85 out of 5 | $442 | 21,401 |
| Distribution Main | 236 | P-8125 | COV | Elm St. | 6 | Cast Iron | 70 | 119 | 2.57 out of 5 | $442 | 30,970 |
| Distribution Main | 237 | P-8125 | COV | Elm St. | 6 | Cast Iron | 309 | 119 | 2.57 out of 5 | $442 | 136,758 |
| Distribution Main | 675 | P-8112 | COV | Elmonte Dr. | 6 | Asbestos Cement | 322 | 59 | 1.85 out of 5 | $442 | 142,536 |
| Distribution Main | 676 | P-8112 | COV | Elmonte Dr. | 6 | Asbestos Cement | 28 | 59 | 1.85 out of 5 | $442 | 12,368 |
| Distribution Main | 677 | P-8856 | COV | Elmonte Dr. | 6 | Asbestos Cement | 113 | 59 | 1.85 out of 5 | $442 | 49,776 |
| Distribution Main | 2108 | P-8111 | COV | Elmonte Dr. | 6 | Asbestos Cement | 247 | 59 | 1.85 out of 5 | $442 | 109,150 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 142 | P-7928 | COV | Elmwood Ct. | 8 | PVC | 147 | 39 | 0.43 out of 5 | $442 | 64,964 |
| Distribution Main | 2465 | P-7928 | COV | Elmwood Ct. | 8 | PVC | 16 | 39 | 0.43 out of 5 | $442 | 7,173 |
| Transmission Main | 8343 | P-7731 | COV | Elton St | 12 | Asbestos Cement | 165 | 66 | 1.29 out of 5 | $442 | 72,780 |
| Distribution Main | 8333 | P-7728 | COV | Elton St. | 8 | Ductile Iron | 46 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8334 | P-7728 | COV | Elton St. | 8 | Ductile Iron | 170 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8355 | P-7723 | COV | Elton St. | 8 | Ductile Iron | 240 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8366 | P-7723 | COV | Elton St. | 8 | Ductile Iron | 260 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8367 | P-7728 | COV | Elton St. | 8 | Ductile Iron | 19 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9558 | P-9009 | COV | Elton St. | 8 | Ductile Iron | 24 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11465 | P-7728 | COV | Elton St. | 8 | Ductile Iron | 8 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2270 | P-7762 | COV | Englewood Rd. | 6 | Asbestos Cement | 325 | 55 | 1.85 out of 5 | $442 | 143,869 |
| Distribution Main | 3817 | | COV | Englewood Rd. | 6 | Asbestos Cement | 83 | 55 | 1.85 out of 5 | $442 | 36,630 |
| Distribution Main | 9701 | P-9019 | COV | Englewood Rd. | 8 | Ductile Iron | 135 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9702 | P-9020 | COV | Englewood Rd. | 6 | Ductile Iron | 5 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 12108 | P-9019 | COV | Englewood Rd. | 8 | Ductile Iron | 21 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 814 | P-7933 | COV | Evergreen Ct. | 8 | Ductile Iron | 609 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 175 | P-7974 | COV | Fairview Ave. | 6 | Cast Iron | 23 | 132 | 2.57 out of 5 | $442 | 10,318 |
| Distribution Main | 176 | P-7974 | COV | Fairview Ave. | 6 | Cast Iron | 122 | 132 | 2.57 out of 5 | $442 | 53,813 |
| Transmission Main | 210 | P-8701 | COV | Fairview Ave. | 16 | Asbestos Cement | 970 | 75 | 1.29 out of 5 | $442 | 428,816 |
| Transmission Main | 211 | P-8701 | COV | Fairview Ave. | 16 | Asbestos Cement | 286 | 75 | 1.29 out of 5 | $442 | 126,632 |
| Transmission Main | 212 | P-1258 | COV | Fairview Ave. | 12 | Cast Iron | 136 | 124 | 1.86 out of 5 | $442 | 60,116 |
| Transmission Main | 409 | P-7977 | COV | Fairview Ave. | 16 | Asbestos Cement | 119 | 75 | 1.29 out of 5 | $442 | 52,630 |
| Transmission Main | 410 | P-7977 | COV | Fairview Ave. | 16 | Asbestos Cement | 588 | 75 | 1.29 out of 5 | $442 | 259,955 |
| Distribution Main | 411 | P-7975 | COV | Fairview Ave. | 6 | Cast Iron | 350 | 132 | 2.57 out of 5 | $442 | 154,873 |
| Distribution Main | 452 | P-7959 | COV | Fairview Ave. | 6 | Cast Iron | 579 | 132 | 2.57 out of 5 | $442 | 255,737 |
| Distribution Main | 453 | P-7959 | COV | Fairview Ave. | 6 | Cast Iron | 212 | 132 | 2.57 out of 5 | $442 | 93,625 |
| Transmission Main | 1285 | P-7977 | COV | Fairview Ave. | 16 | Asbestos Cement | 150 | 75 | 1.29 out of 5 | $442 | 66,448 |
| Distribution Main | 1289 | P-7959 | COV | Fairview Ave. | 6 | Cast Iron | 32 | 132 | 2.57 out of 5 | $442 | 13,958 |
| Distribution Main | 1507 | | COV | Fairview Ave. | 6 | Cast Iron | 663 | 132 | 2.57 out of 5 | $442 | 292,836 |
| Distribution Main | 1509 | P-7442 | COV | Fairview Ave. | 6 | Cast Iron | 306 | 132 | 2.57 out of 5 | $442 | 135,388 |
| Distribution Main | 1510 | P-7442 | COV | Fairview Ave. | 6 | Cast Iron | 581 | 132 | 2.57 out of 5 | $442 | 256,723 |
| Distribution Main | 1797 | | COV | Fairview Ave. | 6 | Cast Iron | 605 | 134 | 2.57 out of 5 | $442 | 267,526 |
| Transmission Main | 2132 | P-7977 | COV | Fairview Ave. | 16 | Asbestos Cement | 126 | 75 | 1.29 out of 5 | $442 | 55,776 |
| Distribution Main | 2401 | P-8845 | COV | Fairview Ave. | 6 | Cast Iron | 275 | 132 | 2.57 out of 5 | $442 | 121,593 |
| Transmission Main | 2403 | P-8057 | COV | Fairview Ave. | 16 | Asbestos Cement | 378 | 75 | 1.29 out of 5 | $442 | 167,233 |
| Transmission Main | 2677 | P-8070 | COV | Fairview Ave. | 16 | Asbestos Cement | 99 | 75 | 1.29 out of 5 | $442 | 43,663 |
| Transmission Main | 2916 | P-8061 | COV | Fairview Ave. | 16 | Asbestos Cement | 31 | 75 | 1.29 out of 5 | $442 | 13,801 |
| Transmission Main | 2917 | P-8061 | COV | Fairview Ave. | 16 | Asbestos Cement | 223 | 75 | 1.29 out of 5 | $442 | 98,484 |
| Transmission Main | 2925 | P-8059 | COV | Fairview Ave. | 16 | Asbestos Cement | 357 | 75 | 1.29 out of 5 | $442 | 157,892 |
| Transmission Main | 2928 | P-7072 | COV | Fairview Ave. | 16 | Asbestos Cement | 582 | 75 | 1.29 out of 5 | $442 | 257,442 |
| Transmission Main | 2932 | P-8057 | COV | Fairview Ave. | 16 | Asbestos Cement | 31 | 75 | 1.29 out of 5 | $442 | 13,679 |
| Transmission Main | 3020 | P-8065 | COV | Fairview Ave. | 16 | Asbestos Cement | 622 | 75 | 1.29 out of 5 | $442 | 274,889 |
| Transmission Main | 3034 | P-9039 | COV | Fairview Ave. | 16 | Asbestos Cement | 34 | 75 | 1.29 out of 5 | $442 | 14,880 |
| Transmission Main | 3035 | P-9039 | COV | Fairview Ave. | 16 | Asbestos Cement | 702 | 75 | 1.29 out of 5 | $442 | 310,296 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 3036 | P-7978 | COV | Fairview Ave. | 16 | Asbestos Cement | 28 | 75 | 1.29 out of 5 | $442 | 12,365 |
| Transmission Main | 3037 | | COV | Fairview Ave. | 16 | Unknown | 5 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 3038 | P-8066 | COV | Fairview Ave. | 16 | Asbestos Cement | 342 | 75 | 1.29 out of 5 | $442 | 151,117 |
| Transmission Main | 3478 | P-7914 | COV | Fairview Ave. | 16 | Asbestos Cement | 509 | 75 | 1.29 out of 5 | $442 | 224,939 |
| Distribution Main | 3705 | | COV | Fairview Ave. | 6 | Cast Iron | 261 | 132 | 2.57 out of 5 | $442 | 115,533 |
| Distribution Main | 3711 | P-1210 | COV | Fairview Ave. | 6 | Cast Iron | 299 | 132 | 2.57 out of 5 | $442 | 132,338 |
| Distribution Main | 3712 | P-1210 | COV | Fairview Ave. | 6 | Cast Iron | 684 | 132 | 2.57 out of 5 | $442 | 302,412 |
| Distribution Main | 3713 | P-1209 | COV | Fairview Ave. | 6 | Cast Iron | 514 | 124 | 2.57 out of 5 | $442 | 227,276 |
| Transmission Main | 3714 | P-1213 | COV | Fairview Ave. | 16 | Asbestos Cement | 26 | 75 | 1.29 out of 5 | $442 | 11,446 |
| Transmission Main | 3715 | P-1213 | COV | Fairview Ave. | 16 | Asbestos Cement | 246 | 75 | 1.29 out of 5 | $442 | 108,714 |
| Transmission Main | 8272 | P-7963 | COV | Fairview Ave. | 24 | Ductile Iron | 16 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8273 | P-7963 | COV | Fairview Ave. | 16 | Asbestos Cement | 16 | 75 | 1.29 out of 5 | $442 | 6,980 |
| Distribution Main | 8601 | P-7975 | COV | Fairview Ave. | 6 | Ductile Iron | 343 | 20 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8602 | P-7975 | COV | Fairview Ave. | 6 | Ductile Iron | 178 | 20 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 9083 | P-7977 | COV | Fairview Ave. | 16 | Asbestos Cement | 14 | 75 | 1.29 out of 5 | $442 | 6,107 |
| Distribution Main | 9085 | | COV | Fairview Ave. | 6 | Cast Iron | 4 | 124 | 2.57 out of 5 | $442 | 1,948 |
| Transmission Main | 10965 | P-7977 | COV | Fairview Ave. | 24 | Ductile Iron | 8 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11023 | P-7974 | COV | Fairview Ave. | 6 | Cast Iron | 9 | 132 | 2.57 out of 5 | $442 | 3,810 |
| Distribution Main | 11024 | P-7974 | COV | Fairview Ave. | 6 | Cast Iron | 2 | 132 | 2.57 out of 5 | $442 | 766 |
| Transmission Main | 11035 | P-8070 | COV | Fairview Ave. | 16 | Asbestos Cement | 14 | 75 | 1.29 out of 5 | $442 | 6,199 |
| Transmission Main | 11200 | P-9039 | COV | Fairview Ave. | 16 | Asbestos Cement | 135 | 75 | 1.29 out of 5 | $442 | 59,457 |
| Distribution Main | 11225 | P-1209 | COV | Fairview Ave. | 6 | Cast Iron | 6 | 124 | 2.57 out of 5 | $442 | 2,719 |
| Distribution Main | 11226 | | COV | Fairview Ave. | 6 | Cast Iron | 14 | 134 | 2.57 out of 5 | $442 | 6,305 |
| Distribution Main | 11781 | P-7959 | COV | Fairview Ave. | 6 | Cast Iron | 468 | 132 | 2.57 out of 5 | $442 | 206,739 |
| Distribution Main | 589 | P-8333 | COV | Fairway Dr. | 8 | Ductile Iron | 257 | 30 | 0.14 out of 5 | $442 | 113,565 |
| Distribution Main | 590 | P-8333 | COV | Fairway Dr. | 8 | Ductile Iron | 374 | 30 | 0.14 out of 5 | $442 | 165,337 |
| Transmission Main | 591 | P-8324 | COV | Fairway Dr. | 12 | Ductile Iron | 264 | 30 | 0.14 out of 5 | $442 | 116,825 |
| Distribution Main | 592 | P-8343 | COV | Fairway Dr. | 8 | Ductile Iron | 42 | 30 | 0.14 out of 5 | $442 | 18,745 |
| Distribution Main | 593 | P-8343 | COV | Fairway Dr. | 8 | Ductile Iron | 423 | 30 | 0.14 out of 5 | $442 | 186,757 |
| Transmission Main | 599 | | COV | Fairway Dr. | 12 | Ductile Iron | 133 | 30 | 0.14 out of 5 | $442 | 58,862 |
| Distribution Main | 1329 | P-8332 | COV | Fairway Dr. | 8 | Ductile Iron | 738 | 30 | 0.14 out of 5 | $442 | 326,328 |
| Distribution Main | 1330 | P-8332 | COV | Fairway Dr. | 8 | Ductile Iron | 67 | 30 | 0.14 out of 5 | $442 | 29,816 |
| Distribution Main | 1331 | P-8332 | COV | Fairway Dr. | 8 | Ductile Iron | 250 | 30 | 0.14 out of 5 | $442 | 110,485 |
| Distribution Main | 1332 | P-8332 | COV | Fairway Dr. | 8 | Ductile Iron | 15 | 30 | 0.14 out of 5 | $442 | 6,524 |
| Transmission Main | 3016 | P-8328 | COV | Fairway Dr. | 12 | Ductile Iron | 466 | 30 | 0.14 out of 5 | $442 | 206,130 |
| Distribution Main | 3017 | P-8331 | COV | Fairway Dr. | 8 | Ductile Iron | 351 | 30 | 0.14 out of 5 | $442 | 155,202 |
| Distribution Main | 4807 | P-8333 | COV | Fairway Dr. | 8 | Ductile Iron | 54 | 30 | 0.14 out of 5 | $442 | 23,663 |
| Distribution Main | 5058 | P-8334 | COV | Fairway Dr. | 8 | Ductile Iron | 95 | 30 | 0.14 out of 5 | $442 | 42,145 |
| Distribution Main | 5059 | P-8334 | COV | Fairway Dr. | 8 | Ductile Iron | 26 | 30 | 0.14 out of 5 | $442 | 11,491 |
| Distribution Main | 5060 | P-8340 | COV | Fairway Dr. | 8 | Ductile Iron | 3 | 30 | 0.14 out of 5 | $442 | 1,131 |
| Distribution Main | 5061 | P-8340 | COV | Fairway Dr. | 8 | Ductile Iron | 81 | 30 | 0.14 out of 5 | $442 | 35,611 |
| Distribution Main | 5932 | P-8340 | COV | Fairway Dr. | 8 | Ductile Iron | 121 | 30 | 0.14 out of 5 | $442 | 53,575 |
| Distribution Main | 5933 | P-8337 | COV | Fairway Dr. | 8 | Ductile Iron | 241 | 30 | 0.14 out of 5 | $442 | 106,653 |
| Distribution Main | 5934 | P-8339 | COV | Fairway Dr. | 8 | Ductile Iron | 200 | 30 | 0.14 out of 5 | $442 | 88,413 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 10293 | | COV | Fairway Dr. | 12 | Ductile Iron | 3 | 30 | 0.14 out of 5 | $442 | 1,218 |
| Distribution Main | 11890 | P-8343 | COV | Fairway Dr. | 8 | Ductile Iron | 349 | 30 | 0.14 out of 5 | $442 | 154,474 |
| Transmission Main | 182 | P-7963 | COV | Fariview Ave. | 16 | Asbestos Cement | 1,276 | 75 | 1.29 out of 5 | $442 | 563,861 |
| Transmission Main | 2131 | P-7963 | COV | Fariview Ave. | 16 | Asbestos Cement | 10 | 75 | 1.29 out of 5 | $442 | 4,508 |
| Distribution Main | 3011 | P-8342 | COV | Fariway Dr. | 8 | Ductile Iron | 206 | 30 | 0.14 out of 5 | $442 | 91,205 |
| Distribution Main | 8091 | P-8967 | COV | Fawns Ct | 8 | Ductile Iron | 28 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 8092 | P-8967 | COV | Fawns Ct | 8 | Ductile Iron | 6 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9769 | P-616 | COV | Fenland Dr | 8 | Ductile Iron | 141 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9770 | P-616 | COV | Fenland Dr | 8 | Ductile Iron | 163 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 791 | P-7540 | COV | Ferncrest Avenue | 6 | Asbestos Cement | 425 | 50 | 1.85 out of 5 | $442 | 187,889 |
| Distribution Main | 792 | P-7540 | COV | Ferncrest Avenue | 6 | Asbestos Cement | 51 | 50 | 1.85 out of 5 | $442 | 22,605 |
| Distribution Main | 1478 | P-8322 | COV | Ferncrest St. | 8 | Ductile Iron | 332 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2817 | P-8322 | COV | Ferncrest St. | 8 | Ductile Iron | 127 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9510 | P-7540 | COV | Ferncrest St. | 6 | Ductile Iron | 5 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11189 | P-8322 | COV | Ferncrest St. | 8 | Ductile Iron | 22 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2294 | P-7740 | COV | Ferris Dr. | 8 | Ductile Iron | 313 | 27 | 0.14 out of 5 | $442 | 138,521 |
| Distribution Main | 1597 | P-1173 | COV | Field Ave. | 8 | Ductile Iron | 54 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4970 | P-1173 | COV | Field Ave. | 6 | Asbestos Cement | 451 | 72 | 2 out of 5 | $442 | 199,517 |
| Distribution Main | 4971 | P-1173 | COV | Field Ave. | 6 | Asbestos Cement | 200 | 72 | 2 out of 5 | $442 | 88,260 |
| Distribution Main | 7759 | P-7227 | COV | First St. | 6 | Asbestos Cement | 13 | 65 | 2 out of 5 | $442 | 5,812 |
| Distribution Main | 7760 | P-7227 | COV | First St. | 6 | Asbestos Cement | 26 | 65 | 2 out of 5 | $442 | 11,581 |
| Distribution Main | 7763 | P-7226 | COV | First St. | 6 | Asbestos Cement | 242 | 65 | 2 out of 5 | $442 | 107,096 |
| Transmission Main | 8753 | P-7222 | COV | Flat River Rd | 16 | Ductile Iron | 51 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8754 | P-7222 | COV | Flat River Rd | 16 | Ductile Iron | 483 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8755 | P-7193 | COV | Flat River Rd | 16 | Ductile Iron | 103 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8756 | P-7193 | COV | Flat River Rd | 16 | Ductile Iron | 806 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8765 | P-7185 | COV | Flat River Rd | 20 | Ductile Iron | 680 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8777 | P-7193 | COV | Flat River Rd | 20 | Ductile Iron | 290 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8778 | P-7193 | COV | Flat River Rd | 20 | Ductile Iron | 142 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8802 | | COV | Flat River Rd | 6 | Ductile Iron | 3 | 8 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 10431 | P-7193 | COV | Flat River Rd | 20 | Ductile Iron | 115 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10860 | P-7193 | COV | Flat River Rd | 16 | Ductile Iron | 622 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10861 | P-7183 | COV | Flat River Rd | 20 | Ductile Iron | 38 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10862 | P-7183 | COV | Flat River Rd | 20 | Ductile Iron | 317 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11499 | P-7222 | COV | Flat River Rd | 16 | Ductile Iron | 287 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11500 | P-7222 | COV | Flat River Rd | 16 | Ductile Iron | 109 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11501 | P-7193 | COV | Flat River Rd | 16 | Ductile Iron | 47 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11506 | P-7183 | COV | Flat River Rd | 20 | Ductile Iron | 44 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11507 | P-7193 | COV | Flat River Rd | 20 | Ductile Iron | 42 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11510 | P-7193 | COV | Flat River Rd | 20 | Ductile Iron | 15 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11511 | P-7193 | COV | Flat River Rd | 20 | Ductile Iron | 12 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11974 | P-7193 | COV | Flat River Rd | 16 | Ductile Iron | 77 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12097 | P-7222 | COV | Flat River Rd | 16 | Ductile Iron | 25 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12098 | P-7222 | COV | Flat River Rd | 16 | Ductile Iron | 24 | 8 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4916 | P-8344 | COV | Flat River Rd. | 8 | Ductile Iron | 109 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4917 | P-8344 | COV | Flat River Rd. | 8 | Ductile Iron | 544 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5055 | P-7255 | COV | Flat River Rd. | 8 | Ductile Iron | 20 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5944 | P-8345 | COV | Flat River Rd. | 8 | Ductile Iron | 16 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7160 | P-7229 | COV | Flat River Rd. | 8 | Asbestos Cement | 9 | 69 | 1.29 out of 5 | $442 | 3,864 |
| Distribution Main | 7161 | P-7229 | COV | Flat River Rd. | 8 | Ductile Iron | 759 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7756 | | COV | Flat River Rd. | 8 | Asbestos Cement | 518 | UNK | 0.85 out of 5 | $442 | 229,155 |
| Distribution Main | 7757 | | COV | Flat River Rd. | 8 | Asbestos Cement | 52 | UNK | 0.85 out of 5 | $442 | 22,773 |
| Distribution Main | 7920 | P-8345 | COV | Flat River Rd. | 8 | Ductile Iron | 16 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7921 | P-7249 | COV | Flat River Rd. | 8 | Ductile Iron | 9 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7922 | P-7249 | COV | Flat River Rd. | 8 | Ductile Iron | 482 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11274 | P-8344 | COV | Flat River Rd. | 8 | Ductile Iron | 62 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1087 | P-7693 | COV | Florida Ave. | 6 | Asbestos Cement | 30 | 65 | 2 out of 5 | $442 | 13,132 |
| Distribution Main | 1088 | P-7693 | COV | Florida Ave. | 6 | Asbestos Cement | 507 | 65 | 2 out of 5 | $442 | 224,124 |
| Distribution Main | 2585 | P-8998 | COV | Florida Ave. | 1 | Copper | 254 | 65 | 2.43 out of 5 | $442 | 112,328 |
| Distribution Main | 9220 | P-8078 | COV | Fones St | 8 | Ductile Iron | 84 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9221 | P-8078 | COV | Fones St | 8 | Ductile Iron | 208 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11555 | P-8834 | COV | Fones St | 8 | Ductile Iron | 85 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1459 | P-8308 | COV | Forest St. | 6 | Asbestos Cement | 460 | 65 | 2 out of 5 | $442 | 203,121 |
| Distribution Main | 1758 | P-9007 | COV | Forestdale Dr | 6 | Asbestos Cement | 251 | 51 | 1.85 out of 5 | $442 | 111,025 |
| Distribution Main | 2623 | P-7569 | COV | Forestdale St. | 6 | Asbestos Cement | 473 | 51 | 1.85 out of 5 | $442 | 209,214 |
| Distribution Main | 2624 | P-7569 | COV | Forestdale St. | 6 | Asbestos Cement | 19 | 51 | 1.85 out of 5 | $442 | 8,200 |
| Distribution Main | 9076 | P-8974 | COV | Forge Rd | 8 | Ductile Iron | 321 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2462 | P-7900 | COV | Forsythia Ct. | 6 | Asbestos Cement | 279 | 39 | 1.71 out of 5 | $442 | 123,450 |
| Distribution Main | 2997 | | COV | Foster Dr. | 6 | Asbestos Cement | 220 | 72 | 2 out of 5 | $442 | 97,403 |
| Distribution Main | 2998 | | COV | Foster Dr. | 6 | Asbestos Cement | 7 | 72 | 2 out of 5 | $442 | 3,248 |
| Distribution Main | 3003 | P-7278 | COV | Foster Dr. | 6 | Asbestos Cement | 389 | 72 | 2 out of 5 | $442 | 171,761 |
| Distribution Main | 7944 | P-7244 | COV | Frances Ct. | 6 | Asbestos Cement | 196 | 56 | 1.85 out of 5 | $442 | 86,782 |
| Distribution Main | 10799 | P-7267 | COV | Francis St. | 8 | Ductile Iron | 201 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10803 | P-7266 | COV | Francis St. | 8 | Ductile Iron | 396 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2704 | | COV | Gadoury St. | 6 | Asbestos Cement | 9 | 70 | 2 out of 5 | $442 | 3,923 |
| Distribution Main | 2710 | P-7980 | COV | Gadoury St. | 6 | Asbestos Cement | 403 | 70 | 2 out of 5 | $442 | 178,097 |
| Distribution Main | 11034 | P-7980 | COV | Gadoury St. | 6 | Asbestos Cement | 19 | 70 | 2 out of 5 | $442 | 8,362 |
| Distribution Main | 7924 | P-7250 | COV | Gail Ct. | 8 | Asbestos Cement | 242 | 50 | 1.14 out of 5 | $442 | 107,114 |
| Distribution Main | 7925 | P-7250 | COV | Gail Ct. | 8 | Asbestos Cement | 402 | 50 | 1.14 out of 5 | $442 | 177,821 |
| Distribution Main | 8458 | | COV | Garden St. | 8 | Ductile Iron | 20 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6449 | P-7174 | COV | Garfield Dr. | 8 | Asbestos Cement | 19 | 40 | 1 out of 5 | $442 | 8,231 |
| Distribution Main | 6454 | P-7174 | COV | Garfield Dr. | 8 | Asbestos Cement | 358 | 40 | 1 out of 5 | $442 | 158,309 |
| Distribution Main | 6455 | P-7174 | COV | Garfield Dr. | 8 | Asbestos Cement | 545 | 40 | 1 out of 5 | $442 | 240,938 |
| Distribution Main | 1036 | P-8177 | COV | Gay St. | 8 | PVC | 20 | 33 | 0.43 out of 5 | $442 | 8,965 |
| Distribution Main | 1037 | P-8177 | COV | Gay St. | 8 | PVC | 299 | 33 | 0.43 out of 5 | $442 | 132,098 |
| Distribution Main | 1429 | P-8177 | COV | Gay St. | 8 | PVC | 3 | 33 | 0.43 out of 5 | $442 | 1,514 |
| Distribution Main | 2718 | P-8005 | COV | Gerald Ave. | 6 | Asbestos Cement | 498 | 70 | 2 out of 5 | $442 | 220,253 |
| Distribution Main | 10201 | | COV | Gervais St | 6 | Ductile Iron | 8 | 15 | 0.71 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 8184 | P-7363 | COV | Gervais St. | 12 | Ductile Iron | 384 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8185 | P-7363 | COV | Gervais St. | 12 | Ductile Iron | 320 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8191 | P-8378 | COV | Gervais St. | 8 | Asbestos Cement | 721 | 57 | 1.14 out of 5 | $442 | 318,875 |
| Transmission Main | 8214 | P-8497 | COV | Gervais St. | 20 | Ductile Iron | 619 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8215 | P-8497 | COV | Gervais St. | 20 | Ductile Iron | 366 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8231 | P-8379 | COV | Gervais St. | 8 | Asbestos Cement | 23 | 57 | 1.14 out of 5 | $442 | 10,250 |
| Distribution Main | 8232 | P-8379 | COV | Gervais St. | 8 | Asbestos Cement | 417 | 57 | 1.14 out of 5 | $442 | 184,531 |
| Distribution Main | 8233 | P-8379 | COV | Gervais St. | 8 | Asbestos Cement | 143 | 57 | 1.14 out of 5 | $442 | 63,169 |
| Distribution Main | 8235 | P-8379 | COV | Gervais St. | 8 | Asbestos Cement | 619 | 57 | 1.14 out of 5 | $442 | 273,714 |
| Transmission Main | 8257 | P-8497 | COV | Gervais St. | 20 | Ductile Iron | 397 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8258 | P-8497 | COV | Gervais St. | 20 | Ductile Iron | 724 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8259 | P-7363 | COV | Gervais St. | 12 | Ductile Iron | 397 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8260 | P-7363 | COV | Gervais St. | 12 | Ductile Iron | 768 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8261 | P-8497 | COV | Gervais St. | 20 | Ductile Iron | 275 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8262 | P-7395 | COV | Gervais St. | 12 | Ductile Iron | 102 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8263 | P-7395 | COV | Gervais St. | 12 | Ductile Iron | 155 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10061 | P-8379 | COV | Gervais St. | 24 | Ductile Iron | 82 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10062 | P-8497 | COV | Gervais St. | 20 | Ductile Iron | 407 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10077 | P-7390 | COV | Gervais St. | 12 | Ductile Iron | 152 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10079 | P-7391 | COV | Gervais St. | 12 | Ductile Iron | 328 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10111 | P-8497 | COV | Gervais St. | 20 | Ductile Iron | 36 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10894 | P-8378 | COV | Gervais St. | 8 | Asbestos Cement | 95 | 57 | 1.14 out of 5 | $442 | 41,901 |
| Transmission Main | 11443 | P-7363 | COV | Gervais St. | 12 | Ductile Iron | 16 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11455 | P-7395 | COV | Gervais St. | 12 | Ductile Iron | 19 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12092 | P-7363 | COV | Gervais St. | 12 | Ductile Iron | 218 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12093 | P-7363 | COV | Gervais St. | 12 | Ductile Iron | 47 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5912 | P-7110 | COV | Giblin Ln. | 8 | Ductile Iron | 328 | 29 | 0.14 out of 5 | $442 | 145,078 |
| Distribution Main | 5914 | P-7111 | COV | Giblin Ln. | 8 | Ductile Iron | 514 | 29 | 0.14 out of 5 | $442 | 227,223 |
| Distribution Main | 5915 | P-7111 | COV | Giblin Ln. | 8 | Ductile Iron | 407 | 29 | 0.14 out of 5 | $442 | 179,997 |
| Distribution Main | 2267 | P-7752 | COV | Gilles St. | 8 | Ductile Iron | 452 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10168 | P-8787 | COV | Ginger Tr | 8 | Ductile Iron | 279 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10169 | P-8787 | COV | Ginger Tr | 8 | Ductile Iron | 456 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10171 | P-8788 | COV | Ginger Tr | 8 | Ductile Iron | 300 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10172 | P-8790 | COV | Ginger Tr | 8 | Ductile Iron | 212 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11030 | P-8790 | COV | Ginger Tr | 8 | Ductile Iron | 40 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11792 | P-8788 | COV | Ginger Tr | 8 | Ductile Iron | 36 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1251 | P-7353 | COV | Ginger Tr. | 8 | Ductile Iron | 178 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1253 | P-7335 | COV | Ginger Tr. | 8 | Ductile Iron | 5 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1255 | P-7355 | COV | Ginger Tr. | 8 | Ductile Iron | 360 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1257 | P-7335 | COV | Ginger Tr. | 8 | Ductile Iron | 3 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1258 | P-7353 | COV | Ginger Tr. | 8 | Ductile Iron | 5 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1334 | P-7335 | COV | Ginger Tr. | 8 | Ductile Iron | 439 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1335 | P-7335 | COV | Ginger Tr. | 8 | Ductile Iron | 75 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1336 | P-7335 | COV | Ginger Tr. | 8 | Ductile Iron | 250 | 21 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3049 | P-7337 | COV | Ginger Tr. | 8 | Ductile Iron | 407 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3050 | P-7337 | COV | Ginger Tr. | 8 | Ductile Iron | 43 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3051 | P-7337 | COV | Ginger Tr. | 8 | Ductile Iron | 245 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3052 | P-7337 | COV | Ginger Tr. | 8 | Ductile Iron | 106 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3053 | P-7337 | COV | Ginger Tr. | 8 | Ductile Iron | 484 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4415 | P-7339 | COV | Ginger Tr. | 8 | Ductile Iron | 411 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4417 | P-7339 | COV | Ginger Tr. | 8 | Ductile Iron | 4 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4418 | P-7337 | COV | Ginger Tr. | 8 | Ductile Iron | 4 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4420 | P-8888 | COV | Ginger Tr. | 8 | Ductile Iron | 510 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4421 | P-8888 | COV | Ginger Tr. | 8 | Ductile Iron | 3 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4422 | P-7339 | COV | Ginger Tr. | 8 | Ductile Iron | 103 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7859 | P-7341 | COV | Ginger Tr. | 8 | Ductile Iron | 4 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7860 | P-7341 | COV | Ginger Tr. | 8 | Ductile Iron | 373 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10110 | P-7337 | COV | Ginger Tr. | 8 | Ductile Iron | 17 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 12179 | | COV | Glacier Way | 8 | Ductile Iron | 414 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12180 | | COV | Glacier Way | 8 | Ductile Iron | 178 | 29 | 0.14 out of 5 | $442 | 78,619 |
| Distribution Main | 2781 | P-7657 | COV | Glen Ave. | 8 | Ductile Iron | 196 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1925 | P-7912 | COV | Glenview Ct. | 8 | Asbestos Cement | 526 | 43 | 1.14 out of 5 | $442 | 232,506 |
| Distribution Main | 1926 | P-7912 | COV | Glenview Ct. | 8 | Asbestos Cement | 46 | 43 | 1.14 out of 5 | $442 | 20,326 |
| Distribution Main | 587 | P-7326 | COV | Glenwood Dr. | 8 | Asbestos Cement | 455 | 43 | 1.14 out of 5 | $442 | 201,037 |
| Distribution Main | 1250 | P-7328 | COV | Glenwood Dr. | 8 | Asbestos Cement | 134 | 43 | 1.14 out of 5 | $442 | 59,027 |
| Distribution Main | 1259 | P-8787 | COV | Glenwood Dr. | 8 | Asbestos Cement | 138 | 43 | 1.14 out of 5 | $442 | 60,998 |
| Distribution Main | 1340 | P-7328 | COV | Glenwood Dr. | 8 | Asbestos Cement | 93 | 43 | 1.14 out of 5 | $442 | 41,286 |
| Distribution Main | 1341 | P-7328 | COV | Glenwood Dr. | 8 | Asbestos Cement | 450 | 43 | 1.14 out of 5 | $442 | 199,083 |
| Distribution Main | 2118 | P-7326 | COV | Glenwood Dr. | 8 | Asbestos Cement | 11 | 43 | 1.14 out of 5 | $442 | 4,915 |
| Distribution Main | 3143 | P-8179 | COV | Grafton St. | 8 | PVC | 390 | 28 | 0.43 out of 5 | $442 | 172,592 |
| Distribution Main | 1033 | P-8181 | COV | Grand View St. | 8 | Ductile Iron | 329 | 28 | 0.14 out of 5 | $442 | 145,569 |
| Distribution Main | 1426 | P-8999 | COV | Grand View St. | 8 | Ductile Iron | 15 | 28 | 0.14 out of 5 | $442 | 6,733 |
| Distribution Main | 1427 | P-8999 | COV | Grand View St. | 8 | Ductile Iron | 94 | 28 | 0.14 out of 5 | $442 | 41,694 |
| Distribution Main | 3138 | P-8315 | COV | Grand View St. | 8 | Ductile Iron | 237 | 28 | 0.14 out of 5 | $442 | 104,598 |
| Distribution Main | 3140 | P-8181 | COV | Grand View St. | 8 | Ductile Iron | 3 | 28 | 0.14 out of 5 | $442 | 1,379 |
| Distribution Main | 1089 | | COV | Grant Dr. | 6 | Asbestos Cement | 16 | 57 | 1.85 out of 5 | $442 | 7,086 |
| Distribution Main | 1460 | P-7691 | COV | Grant Dr. | 6 | Asbestos Cement | 716 | 57 | 1.85 out of 5 | $442 | 316,409 |
| Distribution Main | 2610 | P-7674 | COV | Grant Dr. | 6 | Asbestos Cement | 294 | 57 | 1.85 out of 5 | $442 | 130,106 |
| Distribution Main | 2611 | P-7675 | COV | Grant Dr. | 6 | Asbestos Cement | 459 | 57 | 1.85 out of 5 | $442 | 202,901 |
| Distribution Main | 834 | P-7833 | COV | Greene St. | 2 | Galvanized Iron | 25 | 73 | 3.28 out of 5 | $442 | 10,888 |
| Distribution Main | 3151 | P-7833 | COV | Greene St. | 2 | Galvanized Iron | 455 | 73 | 3.28 out of 5 | $442 | 201,272 |
| Distribution Main | 6452 | P-7178 | COV | Hancock Dr. | 8 | Asbestos Cement | 116 | 42 | 1.14 out of 5 | $442 | 51,278 |
| Distribution Main | 6453 | P-7178 | COV | Hancock Dr. | 8 | Asbestos Cement | 735 | 42 | 1.14 out of 5 | $442 | 324,956 |
| Distribution Main | 11338 | P-7178 | COV | Hancock Dr. | 8 | Asbestos Cement | 7 | 42 | 1.14 out of 5 | $442 | 3,148 |
| Distribution Main | 11866 | P-7178 | COV | Hancock Dr. | 8 | Asbestos Cement | 401 | 42 | 1.14 out of 5 | $442 | 177,252 |
| Distribution Main | 790 | P-8935 | COV | Harding Street | 1 | Copper | 367 | UNK | 1.99 out of 5 | $442 | 162,022 |
| Transmission Main | 5292 | P-7001 | COV | Harkney Hill Rd. | 12 | Ductile Iron | 10 | 30 | 0.14 out of 5 | $442 | 4,293 |
| Transmission Main | 7261 | P-7001 | COV | Harkney Hill Rd. | 12 | Ductile Iron | 504 | 30 | 0.14 out of 5 | $442 | 222,744 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 7262 | P-7001 | COV | Harkney Hill Rd. | 12 | Ductile Iron | 400 | 30 | 0.14 out of 5 | $442 | 176,935 |
| Transmission Main | 7263 | P-7002 | COV | Harkney Hill Rd. | 12 | Ductile Iron | 29 | 30 | 0.14 out of 5 | $442 | 12,768 |
| Transmission Main | 7787 | P-7002 | COV | Harkney Hill Rd. | 12 | Ductile Iron | 7 | 30 | 0.14 out of 5 | $442 | 2,930 |
| Transmission Main | 7801 | P-7001 | COV | Harkney Hill Rd. | 12 | Ductile Iron | 7 | 30 | 0.14 out of 5 | $442 | 3,101 |
| Transmission Main | 11802 | P-7001 | COV | Harkney Hill Rd. | 12 | Ductile Iron | 436 | 30 | 0.14 out of 5 | $442 | 192,566 |
| Distribution Main | 9787 | P-629 | COV | Harley St | 8 | Ductile Iron | 123 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 714 | P-7706 | COV | Harrington Rd. | 6 | Asbestos Cement | 13 | 54 | 1.85 out of 5 | $442 | 5,722 |
| Distribution Main | 2587 | P-7701 | COV | Harrington Rd. | 6 | Asbestos Cement | 304 | 54 | 1.85 out of 5 | $442 | 134,200 |
| Distribution Main | 2588 | P-7701 | COV | Harrington Rd. | 6 | Asbestos Cement | 14 | 54 | 1.85 out of 5 | $442 | 6,364 |
| Distribution Main | 2589 | P-7706 | COV | Harrington Rd. | 6 | Asbestos Cement | 352 | 54 | 1.85 out of 5 | $442 | 155,648 |
| Distribution Main | 9658 | P-7706 | COV | Harrington Rd. | 6 | Asbestos Cement | 346 | 54 | 1.85 out of 5 | $442 | 152,986 |
| Transmission Main | 8383 | P-8752 | COV | Harris St | 12 | Ductile Iron | 156 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8444 | | COV | Harris St | 12 | Ductile Iron | 16 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 232 | | COV | Harris St. | 6 | Unknown | 2 | UNK | 0.71 out of 5 | $442 | 802 |
| Distribution Main | 9738 | P-608 | COV | Harvest Dr | 8 | Ductile Iron | 565 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2690 | P-7947 | COV | Hawthorne Rd. | 8 | Asbestos Cement | 522 | 55 | 1.14 out of 5 | $442 | 230,726 |
| Distribution Main | 2691 | P-7946 | COV | Hawthorne Rd. | 8 | Asbestos Cement | 420 | 55 | 1.14 out of 5 | $442 | 185,497 |
| Distribution Main | 1861 | P-7602 | COV | Haywood Rd. | 8 | Asbestos Cement | 255 | 60 | 1.14 out of 5 | $442 | 112,490 |
| Distribution Main | 2468 | P-8227 | COV | Haywood Rd. | 8 | Ductile Iron | 195 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2469 | P-8227 | COV | Haywood Rd. | 8 | Ductile Iron | 366 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9951 | P-8227 | COV | Haywood Rd. | 8 | Asbestos Cement | 11 | 60 | 1.14 out of 5 | $442 | 4,938 |
| Distribution Main | 566 | P-7966 | COV | Hazard St. | 6 | Cast Iron | 434 | 79 | 2.28 out of 5 | $442 | 191,754 |
| Distribution Main | 567 | P-7966 | COV | Hazard St. | 6 | Cast Iron | 14 | 79 | 2.28 out of 5 | $442 | 6,227 |
| Distribution Main | 1689 | P-9041 | COV | Hazard St. | 6 | Cast Iron | 168 | 79 | 2.28 out of 5 | $442 | 74,307 |
| Distribution Main | 1690 | P-9041 | COV | Hazard St. | 6 | Cast Iron | 5 | 79 | 2.28 out of 5 | $442 | 2,135 |
| Distribution Main | 2694 | P-9041 | COV | Hazard St. | 6 | Cast Iron | 145 | 79 | 2.28 out of 5 | $442 | 64,085 |
| Distribution Main | 2740 | P-8282 | COV | Hazard St. | 6 | Cast Iron | 168 | 79 | 2.28 out of 5 | $442 | 74,118 |
| Distribution Main | 2741 | P-8283 | COV | Hazard St. | 6 | Cast Iron | 449 | 79 | 2.28 out of 5 | $442 | 198,662 |
| Distribution Main | 2742 | P-7976 | COV | Hazard St. | 6 | Cast Iron | 14 | 79 | 2.28 out of 5 | $442 | 6,009 |
| Distribution Main | 2743 | P-7976 | COV | Hazard St. | 6 | Cast Iron | 226 | 79 | 2.28 out of 5 | $442 | 99,805 |
| Distribution Main | 9084 | P-7976 | COV | Hazard St. | 6 | Cast Iron | 15 | 79 | 2.28 out of 5 | $442 | 6,728 |
| Distribution Main | 1763 | P-8300 | COV | Hazel St. | 2 | Copper | 275 | 78 | 2.43 out of 5 | $442 | 121,609 |
| Distribution Main | 1764 | P-8300 | COV | Hazel St. | 6 | Asbestos Cement | 4 | 78 | 2 out of 5 | $442 | 1,944 |
| Distribution Main | 2778 | P-8300 | COV | Hazel St. | 6 | Asbestos Cement | 22 | 78 | 2 out of 5 | $442 | 9,937 |
| Distribution Main | 7877 | P-7305 | COV | Heather Ct. | 8 | Asbestos Cement | 242 | 34 | 1 out of 5 | $442 | 107,000 |
| Transmission Main | 1626 | P-8266 | COV | Helen Ave. | 12 | Ductile Iron | 45 | 30 | 0.14 out of 5 | $442 | 19,764 |
| Distribution Main | 2360 | P-8518 | COV | Helen Ave. | 6 | Asbestos Cement | 999 | 65 | 2 out of 5 | $442 | 441,556 |
| Distribution Main | 2361 | P-7484 | COV | Helen Ave. | 6 | Asbestos Cement | 16 | 65 | 2 out of 5 | $442 | 7,292 |
| Transmission Main | 4414 | P-7165 | COV | Helen Ave. | 12 | Ductile Iron | 933 | 30 | 0.14 out of 5 | $442 | 412,301 |
| Distribution Main | 6613 | P-7483 | COV | Helen Ave. | 6 | Asbestos Cement | 138 | 65 | 2 out of 5 | $442 | 61,215 |
| Distribution Main | 6614 | P-7483 | COV | Helen Ave. | 6 | Asbestos Cement | 137 | 65 | 2 out of 5 | $442 | 60,762 |
| Distribution Main | 6619 | P-7468 | COV | Helen Ave. | 6 | Asbestos Cement | 94 | 65 | 2 out of 5 | $442 | 41,656 |
| Distribution Main | 6620 | P-7482 | COV | Helen Ave. | 6 | Asbestos Cement | 274 | 65 | 2 out of 5 | $442 | 121,004 |
| Distribution Main | 6623 | P-7461 | COV | Helen Ave. | 6 | Asbestos Cement | 108 | 65 | 2 out of 5 | $442 | 47,603 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 7188 | P-7164 | COV | Helen Ave. | 12 | Ductile Iron | 645 | 30 | 0.14 out of 5 | $442 | 285,109 |
| Transmission Main | 7189 | P-7164 | COV | Helen Ave. | 12 | Ductile Iron | 3 | 30 | 0.14 out of 5 | $442 | 1,326 |
| Transmission Main | 7192 | P-7164 | COV | Helen Ave. | 12 | Ductile Iron | 125 | 30 | 0.14 out of 5 | $442 | 55,128 |
| Distribution Main | 7438 | P-7457 | COV | Helen Ave. | 6 | Asbestos Cement | 383 | 65 | 2 out of 5 | $442 | 169,217 |
| Distribution Main | 7439 | P-7457 | COV | Helen Ave. | 6 | Asbestos Cement | 469 | 65 | 2 out of 5 | $442 | 207,179 |
| Transmission Main | 7513 | P-7164 | COV | Helen Ave. | 12 | Ductile Iron | 135 | 30 | 0.14 out of 5 | $442 | 59,664 |
| Transmission Main | 8134 | P-8266 | COV | Helen Ave. | 12 | Ductile Iron | 21 | 30 | 0.14 out of 5 | $442 | 9,112 |
| Transmission Main | 8135 | | COV | Helen Ave. | 12 | Ductile Iron | 15 | 30 | 0.14 out of 5 | $442 | 6,718 |
| Transmission Main | 8136 | P-7165 | COV | Helen Ave. | 12 | Ductile Iron | 14 | 30 | 0.14 out of 5 | $442 | 6,281 |
| Transmission Main | 9503 | | COV | Helen Ave. | 12 | Ductile Iron | 12 | 30 | 0.14 out of 5 | $442 | 5,218 |
| Transmission Main | 11440 | P-8266 | COV | Helen Ave. | 12 | Ductile Iron | 7 | 30 | 0.14 out of 5 | $442 | 3,040 |
| Transmission Main | 11441 | P-7165 | COV | Helen Ave. | 12 | Ductile Iron | 8 | 30 | 0.14 out of 5 | $442 | 3,393 |
| Distribution Main | 12173 | | COV | Helen Ave. | 6 | Asbestos Cement | 157 | 65 | 2 out of 5 | $442 | 69,412 |
| Distribution Main | 2784 | P-7655 | COV | Henry Ave. | 8 | Ductile Iron | 226 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1011 | P-8871 | COV | Henry Court | 4 | Cast Iron | 207 | 32 | 2.71 out of 5 | $442 | 91,554 |
| Distribution Main | 8081 | P-9019 | COV | Hibiscus Ln | 8 | Ductile Iron | 154 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8082 | P-9019 | COV | Hibiscus Ln | 8 | Ductile Iron | 652 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 516 | P-7943 | COV | Hickory Rd. | 6 | Asbestos Cement | 521 | 34 | 1.71 out of 5 | $442 | 230,378 |
| Distribution Main | 517 | P-7943 | COV | Hickory Rd. | 6 | Asbestos Cement | 428 | 34 | 1.71 out of 5 | $442 | 189,057 |
| Transmission Main | 8382 | P-8752 | COV | Highland Ave | 12 | Ductile Iron | 375 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8384 | P-8752 | COV | Highland Ave | 12 | Ductile Iron | 10 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8441 | P-8127 | COV | Highland Ave | 12 | Ductile Iron | 123 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8442 | P-8127 | COV | Highland Ave | 12 | Ductile Iron | 88 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8443 | P-8830 | COV | Highland Ave | 8 | Ductile Iron | 23 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 228 | P-8125 | COV | Highland Ave. | 6 | Cast Iron | 7 | 25 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 242 | P-8126 | COV | Highland Ave. | 6 | Cast Iron | 319 | 25 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 243 | P-8126 | COV | Highland Ave. | 6 | Cast Iron | 212 | 25 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 11864 | P-8126 | COV | Highland Ave. | 6 | Cast Iron | 265 | 25 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 594 | P-7324 | COV | Highwood Dr. | 8 | Asbestos Cement | 24 | 55 | 1.14 out of 5 | $442 | 10,573 |
| Distribution Main | 1342 | P-7332 | COV | Highwood Dr. | 8 | Asbestos Cement | 853 | 41 | 1.14 out of 5 | $442 | 377,012 |
| Distribution Main | 1343 | P-7332 | COV | Highwood Dr. | 8 | Asbestos Cement | 625 | 41 | 1.14 out of 5 | $442 | 276,434 |
| Distribution Main | 2116 | P-7327 | COV | Highwood Dr. | 8 | Asbestos Cement | 159 | 55 | 1.14 out of 5 | $442 | 70,276 |
| Distribution Main | 2117 | P-7327 | COV | Highwood Dr. | 8 | Asbestos Cement | 529 | 55 | 1.14 out of 5 | $442 | 233,673 |
| Distribution Main | 2119 | P-7324 | COV | Highwood Dr. | 8 | Asbestos Cement | 186 | 55 | 1.14 out of 5 | $442 | 82,369 |
| Distribution Main | 10134 | P-7331 | COV | Highwood Dr. | 8 | Asbestos Cement | 495 | 48 | 1.14 out of 5 | $442 | 218,838 |
| Distribution Main | 11790 | P-7332 | COV | Highwood Dr. | 8 | Asbestos Cement | 566 | 41 | 1.14 out of 5 | $442 | 250,107 |
| Transmission Main | 8857 | P-8770 | COV | Hill Farm Rd | 12 | Ductile Iron | 190 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8858 | P-8770 | COV | Hill Farm Rd | 12 | Ductile Iron | 4 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4790 | P-7008 | COV | Hill Farm Rd. | 12 | Asbestos Cement | 109 | 37 | 1 out of 5 | $442 | 48,209 |
| Transmission Main | 4791 | P-7008 | COV | Hill Farm Rd. | 12 | Asbestos Cement | 843 | 37 | 1 out of 5 | $442 | 372,801 |
| Transmission Main | 7586 | P-7010 | COV | Hill Farm Rd. | 12 | PVC | 1,279 | 31 | 0.43 out of 5 | $442 | 565,429 |
| Transmission Main | 7587 | P-7010 | COV | Hill Farm Rd. | 12 | PVC | 648 | 31 | 0.43 out of 5 | $442 | 286,430 |
| Transmission Main | 7588 | P-8769 | COV | Hill Farm Rd. | 12 | Asbestos Cement | 724 | 37 | 1 out of 5 | $442 | 320,007 |
| Transmission Main | 7589 | P-8769 | COV | Hill Farm Rd. | 12 | Asbestos Cement | 520 | 37 | 1 out of 5 | $442 | 229,865 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 7766 | P-7003 | COV | Hill Farm Rd. | 12 | Ductile Iron | 5 | 30 | 0.14 out of 5 | $442 | 2,142 |
| Transmission Main | 7770 | P-7003 | COV | Hill Farm Rd. | 12 | Ductile Iron | 390 | 30 | 0.14 out of 5 | $442 | 172,350 |
| Transmission Main | 7771 | P-7003 | COV | Hill Farm Rd. | 12 | Ductile Iron | 157 | 30 | 0.14 out of 5 | $442 | 69,507 |
| Transmission Main | 8329 | P-8523 | COV | Hill Farm Rd. | 12 | Asbestos Cement | 61 | 37 | 1 out of 5 | $442 | 27,123 |
| Transmission Main | 8330 | P-8523 | COV | Hill Farm Rd. | 12 | Asbestos Cement | 25 | 37 | 1 out of 5 | $442 | 11,122 |
| Transmission Main | 8856 | P-7004 | COV | Hill Farm Rd. | 12 | Asbestos Cement | 305 | 37 | 1 out of 5 | $442 | 134,798 |
| Transmission Main | 9432 | P-8962 | COV | Hill Farm Rd. | 12 | Asbestos Cement | 15 | 37 | 1 out of 5 | $442 | 6,582 |
| Transmission Main | 11264 | P-7008 | COV | Hill Farm Rd. | 12 | Asbestos Cement | 9 | 37 | 1 out of 5 | $442 | 4,104 |
| Transmission Main | 11392 | P-8769 | COV | Hill Farm Rd. | 12 | Asbestos Cement | 31 | 37 | 1 out of 5 | $442 | 13,632 |
| Transmission Main | 11519 | P-7004 | COV | Hill Farm Rd. | 12 | Asbestos Cement | 23 | 37 | 1 out of 5 | $442 | 9,996 |
| Transmission Main | 11800 | P-7008 | COV | Hill Farm Rd. | 12 | Asbestos Cement | 664 | 37 | 1 out of 5 | $442 | 293,631 |
| Transmission Main | 11801 | P-7010 | COV | Hill Farm Rd. | 12 | PVC | 381 | 31 | 0.43 out of 5 | $442 | 168,538 |
| Transmission Main | 8204 | P-8099 | COV | Hill St | 16 | Asbestos Cement | 483 | 63 | 1.29 out of 5 | $442 | 213,638 |
| Transmission Main | 8205 | P-8099 | COV | Hill St | 16 | Asbestos Cement | 475 | 63 | 1.29 out of 5 | $442 | 209,917 |
| Transmission Main | 8206 | P-8099 | COV | Hill St | 16 | Asbestos Cement | 20 | 63 | 1.29 out of 5 | $442 | 9,005 |
| Transmission Main | 8207 | P-6045 | COV | Hill St | 16 | Asbestos Cement | 466 | 63 | 1.29 out of 5 | $442 | 206,157 |
| Transmission Main | 8208 | P-6045 | COV | Hill St | 16 | Asbestos Cement | 670 | 63 | 1.29 out of 5 | $442 | 296,017 |
| Transmission Main | 8246 | P-8101 | COV | Hill St | 16 | Asbestos Cement | 31 | 63 | 1.29 out of 5 | $442 | 13,646 |
| Transmission Main | 8249 | P-8101 | COV | Hill St | 16 | Asbestos Cement | 927 | 63 | 1.29 out of 5 | $442 | 409,725 |
| Transmission Main | 8250 | P-8101 | COV | Hill St | 16 | Asbestos Cement | 130 | 63 | 1.29 out of 5 | $442 | 57,323 |
| Transmission Main | 8253 | P-6045 | COV | Hill St | 16 | Asbestos Cement | 324 | 63 | 1.29 out of 5 | $442 | 143,297 |
| Transmission Main | 8525 | P-8839 | COV | Hill St | 16 | Ductile Iron | 39 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11450 | P-8099 | COV | Hill St | 16 | Asbestos Cement | 4 | 63 | 1.29 out of 5 | $442 | 1,952 |
| Distribution Main | 152 | P-8097 | COV | Hill St. | 8 | Asbestos Cement | 12 | 72 | 1.29 out of 5 | $442 | 5,217 |
| Distribution Main | 224 | | COV | Hill St. | 1 | Unknown | 5 | UNK | 1.42 out of 5 | $442 | 2,074 |
| Distribution Main | 425 | P-8081 | COV | Hill St. | 6 | Cast Iron | 192 | 91 | 2.43 out of 5 | $442 | 84,866 |
| Distribution Main | 625 | P-8105 | COV | Hill St. | 4 | Cast Iron | 61 | 132 | 3.29 out of 5 | $442 | 27,126 |
| Distribution Main | 626 | P-8105 | COV | Hill St. | 4 | Cast Iron | 19 | 132 | 3.29 out of 5 | $442 | 8,611 |
| Distribution Main | 822 | P-8103 | COV | Hill St. | 6 | Cast Iron | 85 | 132 | 2.57 out of 5 | $442 | 37,734 |
| Distribution Main | 1010 | P-8103 | COV | Hill St. | 6 | Cast Iron | 105 | 132 | 2.57 out of 5 | $442 | 46,250 |
| Distribution Main | 1099 | P-8097 | COV | Hill St. | 8 | Asbestos Cement | 139 | 72 | 1.29 out of 5 | $442 | 61,630 |
| Distribution Main | 1100 | P-8868 | COV | Hill St. | 6 | Cast Iron | 45 | 132 | 2.57 out of 5 | $442 | 19,735 |
| Distribution Main | 1101 | P-8868 | COV | Hill St. | 6 | Cast Iron | 101 | 132 | 2.57 out of 5 | $442 | 44,702 |
| Distribution Main | 1110 | P-8105 | COV | Hill St. | 4 | Cast Iron | 351 | 132 | 3.29 out of 5 | $442 | 155,345 |
| Transmission Main | 1137 | P-8091 | COV | Hill St. | 24 | Ductile Iron | 99 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1171 | P-8096 | COV | Hill St. | 8 | Asbestos Cement | 18 | 72 | 1.29 out of 5 | $442 | 7,947 |
| Distribution Main | 1180 | | COV | Hill St. | 1 | Unknown | 4 | UNK | 1.42 out of 5 | $442 | 1,756 |
| Distribution Main | 1318 | P-8868 | COV | Hill St. | 6 | Cast Iron | 21 | 132 | 2.57 out of 5 | $442 | 9,062 |
| Distribution Main | 1319 | P-8861 | COV | Hill St. | 4 | Cast Iron | 220 | 132 | 3.29 out of 5 | $442 | 97,070 |
| Distribution Main | 1440 | P-8372 | COV | Hill St. | 8 | Ductile Iron | 477 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1791 | P-8083 | COV | Hill St. | 6 | Cast Iron | 180 | 91 | 2.43 out of 5 | $442 | 79,672 |
| Distribution Main | 2106 | P-7939 | COV | Hill St. | 8 | Asbestos Cement | 571 | 72 | 1.29 out of 5 | $442 | 252,222 |
| Distribution Main | 2107 | P-7939 | COV | Hill St. | 8 | Asbestos Cement | 13 | 72 | 1.29 out of 5 | $442 | 5,939 |
| Distribution Main | 2113 | P-8098 | COV | Hill St. | 6 | Cast Iron | 285 | 132 | 2.57 out of 5 | $442 | 125,974 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2114 | P-8096 | COV | Hill St. | 8 | Asbestos Cement | 623 | 72 | 1.29 out of 5 | $442 | 275,562 |
| Distribution Main | 2745 | P-8073 | COV | Hill St. | 8 | Asbestos Cement | 302 | 72 | 1.29 out of 5 | $442 | 133,542 |
| Distribution Main | 2746 | P-8073 | COV | Hill St. | 8 | Asbestos Cement | 368 | 72 | 1.29 out of 5 | $442 | 162,745 |
| Distribution Main | 2747 | P-7953 | COV | Hill St. | 8 | Asbestos Cement | 307 | 72 | 1.29 out of 5 | $442 | 135,508 |
| Distribution Main | 3722 | P-8083 | COV | Hill St. | 8 | Ductile Iron | 30 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8195 | P-7939 | COV | Hill St. | 8 | Ductile Iron | 45 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8196 | P-7939 | COV | Hill St. | 8 | Ductile Iron | 20 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8197 | P-7935 | COV | Hill St. | 24 | Ductile Iron | 157 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8198 | P-7935 | COV | Hill St. | 24 | Ductile Iron | 464 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8199 | P-8852 | COV | Hill St. | 24 | Ductile Iron | 40 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8200 | P-7930 | COV | Hill St. | 24 | Ductile Iron | 114 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8201 | P-7930 | COV | Hill St. | 24 | Ductile Iron | 358 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8238 | P-7935 | COV | Hill St. | 24 | Ductile Iron | 294 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8239 | P-7935 | COV | Hill St. | 24 | Ductile Iron | 282 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8240 | P-7930 | COV | Hill St. | 24 | Ductile Iron | 226 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8241 | P-8090 | COV | Hill St. | 24 | Ductile Iron | 54 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8242 | P-8090 | COV | Hill St. | 24 | Ductile Iron | 410 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8243 | P-8092 | COV | Hill St. | 24 | Ductile Iron | 476 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8244 | P-8506 | COV | Hill St. | 24 | Ductile Iron | 484 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8245 | P-8506 | COV | Hill St. | 24 | Ductile Iron | 507 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9688 | P-8505 | COV | Hill St. | 24 | Ductile Iron | 69 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11016 | P-8506 | COV | Hill St. | 24 | Ductile Iron | 16 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11125 | P-8868 | COV | Hill St. | 6 | Cast Iron | 10 | 132 | 2.57 out of 5 | $442 | 4,333 |
| Transmission Main | 11446 | P-7935 | COV | Hill St. | 24 | Ductile Iron | 17 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11448 | P-7930 | COV | Hill St. | 24 | Ductile Iron | 132 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11453 | P-8092 | COV | Hill St. | 24 | Ductile Iron | 18 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 83 | | COV | Hilldan Street | 8 | Asbestos Cement | 141 | UNK | 0.85 out of 5 | $442 | 62,121 |
| Distribution Main | 9214 | P-1212 | COV | Hillside Ave | 8 | Ductile Iron | 744 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9216 | P-8077 | COV | Hillside Ave | 8 | Ductile Iron | 225 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9217 | P-8077 | COV | Hillside Ave | 8 | Ductile Iron | 224 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9662 | P-8075 | COV | Hillside Ave | 8 | Ductile Iron | 191 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10403 | P-8079 | COV | Hillside Ave | 8 | Ductile Iron | 12 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2578 | P-9001 | COV | Hilltop Avenue | 6 | Asbestos Cement | 236 | 60 | 1.85 out of 5 | $442 | 104,512 |
| Distribution Main | 10801 | P-7265 | COV | Holden St | 8 | Ductile Iron | 74 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10802 | P-7264 | COV | Holden St | 8 | Ductile Iron | 216 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11735 | P-7265 | COV | Holden St | 8 | Ductile Iron | 20 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 528 | | COV | Holloway Ave. | 6 | Asbestos Cement | 12 | 19 | 1.56 out of 5 | N/A | $0 |
| Distribution Main | 1710 | P-7777 | COV | Holloway Ave. | 6 | Asbestos Cement | 232 | 61 | 2 out of 5 | $442 | 102,347 |
| Distribution Main | 2203 | | COV | Holloway Ave. | 2 | Unknown | 56 | UNK | 1.42 out of 5 | $442 | 24,878 |
| Distribution Main | 3180 | P-7781 | COV | Holloway Ave. | 6 | Asbestos Cement | 243 | 61 | 2 out of 5 | $442 | 107,536 |
| Distribution Main | 3185 | P-7774 | COV | Holloway Ave. | 6 | Asbestos Cement | 239 | 61 | 2 out of 5 | $442 | 105,591 |
| Distribution Main | 9556 | P-7774 | COV | Holloway Ave. | 8 | Ductile Iron | 19 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9557 | P-7774 | COV | Holloway Ave. | 6 | Ductile Iron | 13 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 1918 | P-8876 | COV | Holly Court | 8 | Unknown | 139 | UNK | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9690 | P-8876 | COV | Holly Court | 8 | Unknown | 4 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 554 | P-7687 | COV | Holmes Rd. | 6 | Asbestos Cement | 13 | 65 | 2 out of 5 | $442 | 5,924 |
| Distribution Main | 722 | P-7685 | COV | Holmes Rd. | 6 | Asbestos Cement | 440 | 65 | 2 out of 5 | $442 | 194,523 |
| Distribution Main | 723 | P-7685 | COV | Holmes Rd. | 6 | Asbestos Cement | 442 | 65 | 2 out of 5 | $442 | 195,239 |
| Distribution Main | 1092 | P-8187 | COV | Holmes Rd. | 6 | Asbestos Cement | 372 | 65 | 2 out of 5 | $442 | 164,536 |
| Distribution Main | 5333 | P-7528 | COV | Homestead Dr. | 6 | Asbestos Cement | 78 | 58 | 1.85 out of 5 | $442 | 34,327 |
| Distribution Main | 5334 | P-7528 | COV | Homestead Dr. | 6 | Asbestos Cement | 96 | 58 | 1.85 out of 5 | $442 | 42,609 |
| Distribution Main | 1921 | P-7899 | COV | Honey Locust Ct. | 6 | Asbestos Cement | 332 | 40 | 1.85 out of 5 | $442 | 146,952 |
| Distribution Main | 6450 | P-7173 | COV | Hoover Dr. | 8 | Asbestos Cement | 316 | 41 | 1.14 out of 5 | $442 | 139,787 |
| Distribution Main | 7435 | P-7172 | COV | Hoover Dr. | 8 | Asbestos Cement | 382 | 41 | 1.14 out of 5 | $442 | 168,698 |
| Distribution Main | 575 | P-8026 | COV | Hope Ct | 2 | Galvanized Iron | 243 | 73 | 3.28 out of 5 | $442 | 107,443 |
| Distribution Main | 2715 | P-8026 | COV | Hope Ct | 2 | Galvanized Iron | 21 | 73 | 3.28 out of 5 | $442 | 9,384 |
| Distribution Main | 2405 | P-8060 | COV | Hopeview Avenue | 2 | Copper | 287 | 71 | 2.43 out of 5 | $442 | 126,965 |
| Distribution Main | 7936 | P-7231 | COV | Hopkins Ct. | 6 | Asbestos Cement | 121 | 56 | 1.85 out of 5 | $442 | 53,484 |
| Distribution Main | 7937 | P-7231 | COV | Hopkins Ct. | 6 | Asbestos Cement | 192 | 56 | 1.85 out of 5 | $442 | 84,804 |
| Transmission Main | 61 | P-7485 | COV | Hopkins Hill Rd | 12 | Ductile Iron | 14 | 30 | 0.14 out of 5 | $442 | 6,106 |
| Distribution Main | 9425 | P-8388 | COV | Hopkins Hill Rd |  | Ductile Iron | 8 | 30 | 0.14 out of 5 | $442 | 3,536 |
| Transmission Main | 422 | P-7489 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 185 | 30 | 0.14 out of 5 | $442 | 81,656 |
| Transmission Main | 535 | P-7495 | COV | Hopkins Hill Rd. | 20 | Ductile Iron | 24 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 707 |  | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 25 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 727 | P-8199 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 18 | 30 | 0.14 out of 5 | $442 | 7,767 |
| Transmission Main | 731 | P-7485 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 250 | 30 | 0.14 out of 5 | $442 | 110,286 |
| Transmission Main | 736 | P-7477 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 458 | 30 | 0.14 out of 5 | $442 | 202,599 |
| Transmission Main | 737 | P-7477 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 192 | 30 | 0.14 out of 5 | $442 | 84,755 |
| Transmission Main | 738 | P-7479 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 205 | 30 | 0.14 out of 5 | $442 | 90,420 |
| Transmission Main | 739 | P-7480 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 49 | 30 | 0.14 out of 5 | $442 | 21,497 |
| Transmission Main | 1271 | P-8464 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 124 | 30 | 0.14 out of 5 | $442 | 54,682 |
| Transmission Main | 1272 | P-8464 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 592 | 30 | 0.14 out of 5 | $442 | 261,577 |
| Transmission Main | 1640 | P-7495 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 565 | 30 | 0.14 out of 5 | $442 | 249,675 |
| Transmission Main | 1641 | P-7495 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 234 | 30 | 0.14 out of 5 | $442 | 103,552 |
| Transmission Main | 1684 | P-7495 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 443 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1836 | P-7495 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 9 | 30 | 0.14 out of 5 | $442 | 3,787 |
| Transmission Main | 1837 | P-7490 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 138 | 30 | 0.14 out of 5 | $442 | 61,031 |
| Transmission Main | 1838 | P-7490 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 129 | 30 | 0.14 out of 5 | $442 | 56,807 |
| Transmission Main | 1867 | P-8512 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 7 | 30 | 0.14 out of 5 | $442 | 3,161 |
| Transmission Main | 2359 | P-8512 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 124 | 30 | 0.14 out of 5 | $442 | 54,740 |
| Distribution Main | 2607 | P-7489 | COV | Hopkins Hill Rd. | 6 | Ductile Iron | 20 | 30 | 0.85 out of 5 | $442 | 8,822 |
| Transmission Main | 2754 | P-7488 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 200 | 30 | 0.14 out of 5 | $442 | 88,600 |
| Transmission Main | 2767 | P-7488 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 28 | 30 | 0.14 out of 5 | $442 | 12,230 |
| Transmission Main | 2769 | P-8199 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 157 | 30 | 0.14 out of 5 | $442 | 69,265 |
| Transmission Main | 2770 | P-8199 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 57 | 30 | 0.14 out of 5 | $442 | 25,016 |
| Transmission Main | 4922 | P-7495 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 77 | 30 | 0.14 out of 5 | $442 | 34,230 |
| Transmission Main | 5325 | P-7542 | COV | Hopkins Hill Rd. | 12 | PVC | 12 | 33 | 0.43 out of 5 | $442 | 5,146 |
| Transmission Main | 5345 | P-7542 | COV | Hopkins Hill Rd. | 12 | PVC | 40 | 33 | 0.43 out of 5 | $442 | 17,631 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 5346 | P-7542 | COV | Hopkins Hill Rd. | 12 | PVC | 452 | 33 | 0.43 out of 5 | $442 | 200,001 |
| Transmission Main | 7542 | P-8388 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 612 | 30 | 0.14 out of 5 | $442 | 270,659 |
| Transmission Main | 7574 | P-8408 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 359 | 30 | 0.14 out of 5 | $442 | 158,853 |
| Transmission Main | 7575 | P-8408 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 1,100 | 30 | 0.14 out of 5 | $442 | 486,390 |
| Transmission Main | 8096 | P-8388 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 152 | 30 | 0.14 out of 5 | $442 | 67,342 |
| Transmission Main | 8097 | P-8388 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 146 | 30 | 0.14 out of 5 | $442 | 64,362 |
| Transmission Main | 8098 | P-8388 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 96 | 30 | 0.14 out of 5 | $442 | 42,349 |
| Transmission Main | 9426 | P-8512 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 2 | 30 | 0.14 out of 5 | $442 | 710 |
| Transmission Main | 11276 | P-7495 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 24 | 30 | 0.14 out of 5 | $442 | 10,451 |
| Transmission Main | 11389 | P-8408 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 59 | 30 | 0.14 out of 5 | $442 | 25,945 |
| Transmission Main | 11432 | P-8388 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 13 | 30 | 0.14 out of 5 | $442 | 5,731 |
| Transmission Main | 11868 | P-8408 | COV | Hopkins Hill Rd. | 12 | Ductile Iron | 844 | 30 | 0.14 out of 5 | $442 | 373,001 |
| Transmission Main | 12082 | P-7542 | COV | Hopkins Hill Rd. | 12 | PVC | 36 | 33 | 0.43 out of 5 | $442 | 15,873 |
| Distribution Main | 1143 | P-7945 | COV | Hornbeam Rd | 8 | Ductile Iron | 47 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9340 | P-8417 | COV | Hornbeam Rd | 8 | Ductile Iron | 393 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9341 | P-8417 | COV | Hornbeam Rd | 8 | Ductile Iron | 508 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 521 | P-7948 | COV | Hornbeam Rd. | 8 | Asbestos Cement | 415 | 55 | 1.14 out of 5 | $442 | 183,318 |
| Distribution Main | 522 | P-7948 | COV | Hornbeam Rd. | 8 | Asbestos Cement | 518 | 55 | 1.85 out of 5 | $442 | 229,021 |
| Distribution Main | 523 | P-7945 | COV | Hornbeam Rd. | 8 | Asbestos Cement | 251 | 55 | 1.14 out of 5 | $442 | 110,744 |
| Distribution Main | 8302 | P-8412 | COV | Hornbeam Rd. | 8 | Ductile Iron | 791 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8305 | P-8416 | COV | Hornbeam Rd. | 8 | Ductile Iron | 26 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8306 | P-8416 | COV | Hornbeam Rd. | 8 | Ductile Iron | 505 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10895 | P-8412 | COV | Hornbeam Rd. | 8 | Ductile Iron | 76 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 69 | P-8114 | COV | Howard Ave | 8 | Ductile Iron | 27 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 70 | P-8114 | COV | Howard Ave | 8 | Ductile Iron | 10 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 95 | P-8859 | COV | Howard Ave. | 16 | Ductile Iron | 25 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 233 | P-8857 | COV | Howard Ave. | 6 | Cast Iron | 22 | 132 | 2.57 out of 5 | $442 | 9,857 |
| Distribution Main | 245 | P-8857 | COV | Howard Ave. | 6 | Cast Iron | 92 | 132 | 2.57 out of 5 | $442 | 40,729 |
| Distribution Main | 246 | P-8115 | COV | Howard Ave. | 6 | Cast Iron | 995 | 132 | 2.57 out of 5 | $442 | 439,729 |
| Distribution Main | 247 | P-8115 | COV | Howard Ave. | 6 | Cast Iron | 291 | 132 | 2.57 out of 5 | $442 | 128,689 |
| Distribution Main | 248 | P-8857 | COV | Howard Ave. | 6 | Cast Iron | 33 | 132 | 2.57 out of 5 | $442 | 14,734 |
| Transmission Main | 306 | P-8369 | COV | Howard Ave. | 16 | Asbestos Cement | 214 | 62 | 1.29 out of 5 | $442 | 94,443 |
| Transmission Main | 307 | P-8369 | COV | Howard Ave. | 16 | Asbestos Cement | 156 | 62 | 1.29 out of 5 | $442 | 68,933 |
| Distribution Main | 1177 | P-8366 | COV | Howard Ave. | 6 | Cast Iron | 19 | 132 | 2.57 out of 5 | $442 | 8,475 |
| Transmission Main | 1213 | P-8509 | COV | Howard Ave. | 16 | Asbestos Cement | 225 | 63 | 1.29 out of 5 | $442 | 99,442 |
| Distribution Main | 1416 | P-8857 | COV | Howard Ave. | 6 | Cast Iron | 31 | 132 | 2.57 out of 5 | $442 | 13,910 |
| Distribution Main | 1417 | P-8857 | COV | Howard Ave. | 6 | Cast Iron | 55 | 132 | 2.57 out of 5 | $442 | 24,225 |
| Transmission Main | 1632 | P-8118 | COV | Howard Ave. | 16 | Asbestos Cement | 2,102 | 63 | 1.29 out of 5 | $442 | 928,877 |
| Distribution Main | 1633 | P-8114 | COV | Howard Ave. | 8 | Asbestos Cement | 419 | 63 | 1.29 out of 5 | $442 | 185,247 |
| Distribution Main | 1634 | P-8114 | COV | Howard Ave. | 8 | Asbestos Cement | 573 | 63 | 1.29 out of 5 | $442 | 253,075 |
| Distribution Main | 2575 | P-8089 | COV | Howard Ave. | 6 | Ductile Iron | 95 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9691 | | COV | Howard Ave. | | Unknown | 9 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 9692 | | COV | Howard Ave. | | Unknown | 12 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 10376 | P-8089 | COV | Howard Ave. | 6 | Ductile Iron | 14 | 18 | 0.71 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10377 | | COV | Howard Ave. | 6 | Cast Iron | 3 | 132 | 2.57 out of 5 | $442 | 1,542 |
| Transmission Main | 11015 | P-8859 | COV | Howard Ave. | 16 | Ductile Iron | 12 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11046 | P-8857 | COV | Howard Ave. | 6 | Cast Iron | 4 | 132 | 2.57 out of 5 | $442 | 1,919 |
| Distribution Main | 11047 | P-8115 | COV | Howard Ave. | 6 | Cast Iron | 218 | 132 | 2.57 out of 5 | $442 | 96,324 |
| Transmission Main | 11109 | P-8509 | COV | Howard Ave. | 16 | Asbestos Cement | 5 | 62 | 1.29 out of 5 | $442 | 2,314 |
| Transmission Main | 11134 | P-8118 | COV | Howard Ave. | 16 | Asbestos Cement | 743 | 63 | 1.29 out of 5 | $442 | 328,396 |
| Transmission Main | 11135 | P-8118 | COV | Howard Ave. | 16 | Asbestos Cement | 12 | 63 | 1.29 out of 5 | $442 | 5,484 |
| Distribution Main | 11858 | P-8114 | COV | Howard Ave. | 8 | Asbestos Cement | 349 | 63 | 1.29 out of 5 | $442 | 154,085 |
| Distribution Main | 9040 | P-1208 | COV | Hoxie Ct. | 8 | Ductile Iron | 101 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9041 | P-1208 | COV | Hoxie Ct. | 8 | Ductile Iron | 188 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7738 | P-8957 | COV | Huckleberry Road | 6 | Asbestos Cement | 10 | 57 | 1.85 out of 5 | $442 | 4,322 |
| Distribution Main | 7830 | P-8957 | COV | Huckleberry Road | 6 | Asbestos Cement | 351 | 57 | 1.85 out of 5 | $442 | 155,316 |
| Transmission Main | 3046 | P-7360 | COV | Hunters Crossing Dr. | 16 | Ductile Iron | 388 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 3047 | P-8885 | COV | Hunters Crossing Dr. | 16 | Ductile Iron | 383 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 3055 | P-7350 | COV | Hunters Crossing Dr. | 16 | Ductile Iron | 297 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 3056 | P-7350 | COV | Hunters Crossing Dr. | 16 | Ductile Iron | 450 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 3057 | P-7350 | COV | Hunters Crossing Dr. | 16 | Ductile Iron | 19 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 3059 | P-7358 | COV | Hunters Crossing Dr. | 16 | Ductile Iron | 171 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 3063 | P-7357 | COV | Hunters Crossing Dr. | 16 | Ductile Iron | 654 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 3064 | P-7349 | COV | Hunters Crossing Dr. | 16 | Ductile Iron | 1,325 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5850 | P-7344 | COV | Hunters Crossing Dr. | 16 | Ductile Iron | 454 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5851 | P-7344 | COV | Hunters Crossing Dr. | 16 | Ductile Iron | 344 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5852 | P-8887 | COV | Hunters Crossing Dr. | 16 | Ductile Iron | 9 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9965 | P-8887 | COV | Hunters Crossing Dr. | 8 | Ductile Iron | 6 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1120 | P-7580 | COV | Idaho St. | 2 | Galvanized Iron | 24 | 86 | 3.43 out of 5 | $442 | 10,518 |
| Distribution Main | 1121 | P-7583 | COV | Idaho St. | 2 | Galvanized Iron | 252 | 86 | 3.43 out of 5 | $442 | 111,436 |
| Distribution Main | 1122 | P-7580 | COV | Idaho St. | 2 | Galvanized Iron | 509 | 86 | 4.14 out of 5 | $442 | 225,012 |
| Distribution Main | 2634 | P-7580 | COV | Idaho St. | 2 | Galvanized Iron | 13 | 86 | 3.43 out of 5 | $442 | 5,585 |
| Distribution Main | 5939 | P-8898 | COV | Industrial Drive | 8 | Asbestos Cement | 193 | 54 | 1.14 out of 5 | $442 | 85,294 |
| Distribution Main | 5940 | P-8898 | COV | Industrial Drive | 8 | Asbestos Cement | 380 | 54 | 1.14 out of 5 | $442 | 168,140 |
| Distribution Main | 5945 | P-8898 | COV | Industrial Drive | 8 | Asbestos Cement | 224 | 54 | 1.14 out of 5 | $442 | 99,168 |
| Distribution Main | 7505 | P-8898 | COV | Industrial Drive | 8 | Asbestos Cement | 306 | 54 | 1.14 out of 5 | $442 | 135,264 |
| Distribution Main | 8779 | P-8898 | COV | Industrial Drive | 8 | Ductile Iron | 33 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10497 | | COV | Industrial Drive | 6 | Asbestos Cement | 1 | 54 | 1.85 out of 5 | $442 | 646 |
| Distribution Main | 11320 | P-8898 | COV | Industrial Drive | 8 | Asbestos Cement | 50 | 54 | 1.14 out of 5 | $442 | 22,220 |
| Distribution Main | 823 | P-9034 | COV | Irene Ln | 6 | Asbestos Cement | 121 | 50 | 1.85 out of 5 | $442 | 53,535 |
| Distribution Main | 824 | P-9034 | COV | Irene Ln | 6 | Asbestos Cement | 21 | 50 | 1.85 out of 5 | $442 | 9,393 |
| Distribution Main | 827 | P-7404 | COV | Irene Ln | 6 | Asbestos Cement | 460 | 50 | 1.85 out of 5 | $442 | 203,174 |
| Distribution Main | 2830 | P-9034 | COV | Irene Ln | 6 | Asbestos Cement | 147 | 50 | 1.85 out of 5 | $442 | 64,841 |
| Distribution Main | 7882 | P-7306 | COV | Ironwood Dr. | 8 | Asbestos Cement | 371 | 34 | 1 out of 5 | $442 | 164,155 |
| Distribution Main | 7894 | P-7304 | COV | Ironwood Dr. | 8 | Asbestos Cement | 190 | 34 | 1 out of 5 | $442 | 83,959 |
| Distribution Main | 7895 | P-7304 | COV | Ironwood Dr. | 8 | Asbestos Cement | 193 | 34 | 1 out of 5 | $442 | 85,320 |
| Distribution Main | 7897 | P-7302 | COV | Ironwood Dr. | 8 | Asbestos Cement | 373 | 34 | 1 out of 5 | $442 | 164,658 |
| Distribution Main | 7634 | P-7100 | COV | Island Dr. | 6 | Ductile Iron | 147 | 26 | 0.85 out of 5 | $442 | 64,923 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 7635 | P-7099 | COV | Island Dr. | 6 | Ductile Iron | 150 | 26 | 0.85 out of 5 | $442 | 66,360 |
| Distribution Main | 7636 | P-7099 | COV | Island Dr. | 6 | Ductile Iron | 53 | 26 | 0.85 out of 5 | $442 | 23,303 |
| Distribution Main | 7637 | P-7098 | COV | Island Dr. | 6 | Ductile Iron | 74 | 26 | 0.85 out of 5 | $442 | 32,844 |
| Distribution Main | 7638 | P-7098 | COV | Island Dr. | 6 | Ductile Iron | 723 | 26 | 0.85 out of 5 | $442 | 319,481 |
| Distribution Main | 7781 | P-7096 | COV | Island Dr. | 8 | Asbestos Cement | 44 | 43 | 1.14 out of 5 | $442 | 19,581 |
| Distribution Main | 7794 | P-7096 | COV | Island Dr. | 8 | Asbestos Cement | 106 | 43 | 1.14 out of 5 | $442 | 46,680 |
| Distribution Main | 7795 | P-7096 | COV | Island Dr. | 8 | Asbestos Cement | 606 | 43 | 1.14 out of 5 | $442 | 267,780 |
| Distribution Main | 7796 | P-7093 | COV | Island Dr. | 8 | Asbestos Cement | 40 | 43 | 1.14 out of 5 | $442 | 17,564 |
| Distribution Main | 7797 | P-7093 | COV | Island Dr. | 8 | Asbestos Cement | 366 | 43 | 1.14 out of 5 | $442 | 161,917 |
| Distribution Main | 10065 | P-7096 | COV | Island Dr. | 8 | PVC | 85 | 26 | 0.43 out of 5 | $442 | 37,758 |
| Distribution Main | 7768 | P-7007 | COV | Isle Of Capri Rd. | 6 | Ductile Iron | 523 | 28 | 0.85 out of 5 | $442 | 231,325 |
| Distribution Main | 7769 | P-7007 | COV | Isle Of Capri Rd. | 6 | Ductile Iron | 71 | 28 | 0.85 out of 5 | $442 | 31,274 |
| Distribution Main | 9998 | P-7007 | COV | Isle Of Capri Rd. | 6 | Ductile Iron | 6 | 28 | 0.85 out of 5 | $442 | 2,788 |
| Distribution Main | 7896 | P-7299 | COV | Ivy Dr. | 8 | Asbestos Cement | 511 | 40 | 1 out of 5 | $442 | 225,874 |
| Distribution Main | 7820 | P-7042 | COV | Jack Pine Rd. | 6 | Asbestos Cement | 194 | 57 | 1.85 out of 5 | $442 | 85,735 |
| Distribution Main | 7821 | P-7042 | COV | Jack Pine Rd. | 6 | Asbestos Cement | 219 | 57 | 1.85 out of 5 | $442 | 96,988 |
| Distribution Main | 7822 | P-7048 | COV | Jack Pine Rd. | 6 | Asbestos Cement | 346 | 57 | 1.85 out of 5 | $442 | 153,140 |
| Distribution Main | 7832 | P-7031 | COV | Jack Pine Rd. | 6 | Asbestos Cement | 254 | 57 | 2.57 out of 5 | $442 | 112,164 |
| Distribution Main | 8296 | P-7031 | COV | Jack Pine Rd. | 6 | Asbestos Cement | 15 | 57 | 1.85 out of 5 | $442 | 6,713 |
| Distribution Main | 11411 | P-7042 | COV | Jack Pine Rd. | 6 | Asbestos Cement | 47 | 57 | 1.85 out of 5 | $442 | 20,769 |
| Distribution Main | 11412 | P-7048 | COV | Jack Pine Rd. | 6 | Asbestos Cement | 6 | 57 | 1.85 out of 5 | $442 | 2,493 |
| Distribution Main | 545 | P-7681 | COV | Jade Rd. | 8 | Asbestos Cement | 44 | 50 | 1.14 out of 5 | $442 | 19,252 |
| Distribution Main | 546 | P-7681 | COV | Jade Rd. | 8 | Asbestos Cement | 208 | 50 | 1.14 out of 5 | $442 | 92,061 |
| Distribution Main | 720 | P-7682 | COV | Jade Rd. | 8 | Asbestos Cement | 487 | 50 | 1.14 out of 5 | $442 | 215,132 |
| Distribution Main | 721 | P-7682 | COV | Jade Rd. | 8 | Asbestos Cement | 388 | 50 | 1.14 out of 5 | $442 | 171,471 |
| Distribution Main | 1256 | P-7336 | COV | Jasmine Ct. | 8 | Ductile Iron | 191 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10181 | P-7161 | COV | Jefferson Dr | | Unknown | 15 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 2984 | P-7161 | COV | Jefferson Dr. | 12 | Ductile Iron | 45 | 30 | 0.14 out of 5 | $442 | 19,981 |
| Transmission Main | 2985 | P-7161 | COV | Jefferson Dr. | 12 | Ductile Iron | 551 | 30 | 0.14 out of 5 | $442 | 243,389 |
| Transmission Main | 4839 | P-7162 | COV | Jefferson Dr. | 12 | Ductile Iron | 53 | 30 | 0.14 out of 5 | $442 | 23,250 |
| Transmission Main | 4840 | P-7162 | COV | Jefferson Dr. | 12 | Ductile Iron | 805 | 30 | 0.14 out of 5 | $442 | 355,880 |
| Transmission Main | 4923 | P-8244 | COV | Jefferson Dr. | 12 | Ductile Iron | 12 | 30 | 0.14 out of 5 | $442 | 5,493 |
| Distribution Main | 5323 | P-7443 | COV | Jefferson Dr. | 8 | Asbestos Cement | 717 | 42 | 1.14 out of 5 | $442 | 316,907 |
| Distribution Main | 5324 | P-7443 | COV | Jefferson Dr. | 8 | Asbestos Cement | 49 | 42 | 1.14 out of 5 | $442 | 21,739 |
| Distribution Main | 6617 | P-7444 | COV | Jefferson Dr. | 8 | Asbestos Cement | 801 | 42 | 1.14 out of 5 | $442 | 354,221 |
| Distribution Main | 6618 | P-7444 | COV | Jefferson Dr. | 8 | Asbestos Cement | 57 | 42 | 1.14 out of 5 | $442 | 25,110 |
| Distribution Main | 6621 | P-7444 | COV | Jefferson Dr. | 8 | Asbestos Cement | 7 | 42 | 1.14 out of 5 | $442 | 3,049 |
| Distribution Main | 6622 | P-7444 | COV | Jefferson Dr. | 8 | Asbestos Cement | 18 | 42 | 1.14 out of 5 | $442 | 7,747 |
| Distribution Main | 9260 | P-7443 | COV | Jefferson Dr. | 8 | Asbestos Cement | 4 | 42 | 1.14 out of 5 | $442 | 1,563 |
| Distribution Main | 9948 | | COV | Jefferson Dr. | 8 | Ductile Iron | 18 | 30 | 0.14 out of 5 | $442 | 8,062 |
| Distribution Main | 11297 | P-7443 | COV | Jefferson Dr. | 8 | Asbestos Cement | 336 | 42 | 1.14 out of 5 | $442 | 148,400 |
| Distribution Main | 11336 | P-7444 | COV | Jefferson Dr. | 8 | Asbestos Cement | 3 | 42 | 1.14 out of 5 | $442 | 1,481 |
| Transmission Main | 11337 | P-7161 | COV | Jefferson Dr. | 12 | Ductile Iron | 4 | 30 | 0.14 out of 5 | $442 | 1,793 |
| Distribution Main | 11344 | P-7444 | COV | Jefferson Dr. | 8 | Asbestos Cement | 2 | 42 | 1.14 out of 5 | $442 | 1,021 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 11975 | P-7161 | COV | Jefferson Dr. | 12 | Ductile Iron | 304 | 30 | 0.14 out of 5 | $442 | 134,365 |
| Transmission Main | 11978 | P-7161 | COV | Jefferson Dr. | 12 | Ductile Iron | 194 | 30 | 0.14 out of 5 | $442 | 85,789 |
| Distribution Main | 2198 | P-7746 | COV | Jennifer Ln. | 8 | Ductile Iron | 7 | 27 | 0.14 out of 5 | $442 | 3,242 |
| Distribution Main | 2199 | P-7748 | COV | Jennifer Ln. | 8 | Ductile Iron | 90 | 27 | 0.14 out of 5 | $442 | 39,787 |
| Distribution Main | 2200 | P-7748 | COV | Jennifer Ln. | 8 | Ductile Iron | 141 | 27 | 0.14 out of 5 | $442 | 62,510 |
| Distribution Main | 2201 | P-7750 | COV | Jennifer Ln. | 8 | Ductile Iron | 80 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2901 | P-7750 | COV | Jennifer Ln. | 8 | Ductile Iron | 323 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2902 | P-7750 | COV | Jennifer Ln. | 8 | Ductile Iron | 147 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9572 | | COV | Jennifer Ln. | 8 | Ductile Iron | 3 | 27 | 0.14 out of 5 | $442 | 1,497 |
| Distribution Main | 9927 | P-7746 | COV | Jennifer Ln. | 8 | Ductile Iron | 171 | 27 | 0.14 out of 5 | $442 | 75,399 |
| Transmission Main | 337 | P-7627 | COV | Johnson Blvd. | 12 | Asbestos Cement | 22 | 58 | 1.14 out of 5 | $442 | 9,769 |
| Transmission Main | 338 | P-7627 | COV | Johnson Blvd. | 12 | Asbestos Cement | 187 | 58 | 1.14 out of 5 | $442 | 82,506 |
| Transmission Main | 339 | P-7627 | COV | Johnson Blvd. | 12 | Asbestos Cement | 71 | 58 | 1.14 out of 5 | $442 | 31,273 |
| Transmission Main | 342 | P-7627 | COV | Johnson Blvd. | 12 | Asbestos Cement | 36 | 58 | 1.14 out of 5 | $442 | 15,918 |
| Transmission Main | 343 | P-8191 | COV | Johnson Blvd. | 16 | Ductile Iron | 658 | 28 | 0.14 out of 5 | $442 | 291,042 |
| Transmission Main | 351 | P-7648 | COV | Johnson Blvd. | 16 | Ductile Iron | 3 | 28 | 0.14 out of 5 | $442 | 1,256 |
| Transmission Main | 682 | P-7642 | COV | Johnson Blvd. | 12 | Asbestos Cement | 241 | 58 | 1.14 out of 5 | $442 | 106,719 |
| Transmission Main | 683 | P-8194 | COV | Johnson Blvd. | 16 | Ductile Iron | 306 | 28 | 0.14 out of 5 | $442 | 135,270 |
| Transmission Main | 684 | P-7637 | COV | Johnson Blvd. | 16 | Ductile Iron | 10 | 28 | 0.14 out of 5 | $442 | 4,483 |
| Transmission Main | 689 | P-8193 | COV | Johnson Blvd. | 16 | Ductile Iron | 923 | 28 | 0.14 out of 5 | $442 | 408,075 |
| Distribution Main | 728 | P-7637 | COV | Johnson Blvd. | 10 | Asbestos Cement | 602 | 63 | 1.29 out of 5 | $442 | 265,993 |
| Distribution Main | 729 | P-7637 | COV | Johnson Blvd. | 10 | Asbestos Cement | 116 | 63 | 1.29 out of 5 | $442 | 51,331 |
| Distribution Main | 730 | P-7629 | COV | Johnson Blvd. | 10 | Asbestos Cement | 84 | 58 | 1.14 out of 5 | $442 | 37,082 |
| Distribution Main | 744 | P-7631 | COV | Johnson Blvd. | 10 | Asbestos Cement | 246 | 63 | 1.29 out of 5 | $442 | 108,825 |
| Distribution Main | 748 | P-7629 | COV | Johnson Blvd. | 10 | Asbestos Cement | 255 | 58 | 1.14 out of 5 | $442 | 112,801 |
| Transmission Main | 766 | P-8194 | COV | Johnson Blvd. | 16 | Ductile Iron | 27 | 28 | 0.14 out of 5 | $442 | 12,095 |
| Transmission Main | 770 | | COV | Johnson Blvd. | 12 | PVC | 206 | 28 | 0.43 out of 5 | $442 | 91,208 |
| Transmission Main | 772 | P-7639 | COV | Johnson Blvd. | 12 | Asbestos Cement | 219 | 58 | 1.14 out of 5 | $442 | 96,740 |
| Transmission Main | 774 | P-8191 | COV | Johnson Blvd. | 16 | Ductile Iron | 389 | 28 | 0.14 out of 5 | $442 | 171,727 |
| Transmission Main | 775 | P-8191 | COV | Johnson Blvd. | 16 | Ductile Iron | 744 | 28 | 0.14 out of 5 | $442 | 328,715 |
| Transmission Main | 1421 | P-8193 | COV | Johnson Blvd. | 16 | Ductile Iron | 4 | 28 | 0.14 out of 5 | $442 | 1,645 |
| Transmission Main | 1625 | P-7637 | COV | Johnson Blvd. | 16 | Ductile Iron | 23 | 28 | 0.14 out of 5 | $442 | 10,205 |
| Transmission Main | 1658 | P-7643 | COV | Johnson Blvd. | 12 | Asbestos Cement | 36 | 58 | 1.14 out of 5 | $442 | 16,028 |
| Transmission Main | 1659 | P-7639 | COV | Johnson Blvd. | 12 | Asbestos Cement | 70 | 58 | 1.14 out of 5 | $442 | 31,012 |
| Transmission Main | 1866 | P-7627 | COV | Johnson Blvd. | 12 | Asbestos Cement | 6 | 58 | 1.14 out of 5 | $442 | 2,569 |
| Transmission Main | 1872 | P-7640 | COV | Johnson Blvd. | 12 | PVC | 395 | 28 | 0.43 out of 5 | $442 | 174,676 |
| Distribution Main | 2606 | P-7627 | COV | Johnson Blvd. | 10 | Asbestos Cement | 259 | 58 | 1.14 out of 5 | $442 | 114,600 |
| Distribution Main | 2762 | P-7486 | COV | Johnson Blvd. | 10 | Asbestos Cement | 208 | 63 | 1.29 out of 5 | $442 | 92,054 |
| Distribution Main | 2773 | P-7486 | COV | Johnson Blvd. | 10 | Asbestos Cement | 38 | 58 | 1.14 out of 5 | $442 | 16,889 |
| Transmission Main | 9925 | P-7627 | COV | Johnson Blvd. | 12 | Asbestos Cement | 14 | 58 | 1.14 out of 5 | $442 | 6,365 |
| Transmission Main | 9926 | P-7627 | COV | Johnson Blvd. | 12 | Asbestos Cement | 45 | 58 | 1.14 out of 5 | $442 | 19,704 |
| Transmission Main | 11087 | | COV | Johnson Blvd. | 12 | PVC | 8 | 28 | 0.43 out of 5 | $442 | 3,702 |
| Transmission Main | 72 | | COV | Johnson Blvd. Ps | 16 | Ductile Iron | 6 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 73 | | COV | Johnson Blvd. Ps | 16 | Ductile Iron | 5 | UNK | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 74 | | COV | Johnson Blvd. Ps | 16 | Ductile Iron | 41 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 75 | | COV | Johnson Blvd. Ps | 16 | Ductile Iron | 31 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 76 | P-7627 | COV | Johnson Blvd. Ps | 10 | Ductile Iron | 3 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 77 | | COV | Johnson Blvd. Ps | 10 | Ductile Iron | 14 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 78 | | COV | Johnson Blvd. Ps | 16 | Ductile Iron | 20 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 79 | | COV | Johnson Blvd. Ps | 16 | Ductile Iron | 7 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 80 | | COV | Johnson Blvd. Ps | 16 | Ductile Iron | 205 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 81 | | COV | Johnson Blvd. Ps | 16 | Ductile Iron | 8 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 340 | | COV | Johnson Blvd. Ps | 16 | Ductile Iron | 193 | 28 | 0.14 out of 5 | $442 | 85,281 |
| Transmission Main | 341 | | COV | Johnson Blvd. Ps | 16 | Ductile Iron | 467 | 28 | 0.14 out of 5 | $442 | 206,272 |
| Transmission Main | 771 | P-7648 | COV | Johnson Blvd. Ps | 16 | Ductile Iron | 21 | 28 | 0.14 out of 5 | $442 | 9,125 |
| Transmission Main | 773 | P-7643 | COV | Johnson Blvd. Ps | 16 | Ductile Iron | 1,147 | 28 | 0.14 out of 5 | $442 | 506,846 |
| Transmission Main | 1616 | | COV | Johnson Blvd. Ps | 16 | Ductile Iron | 183 | 28 | 0.14 out of 5 | $442 | 80,665 |
| Distribution Main | 1922 | P-7894 | COV | Juniper Ct. | 6 | Asbestos Cement | 167 | 40 | 1.71 out of 5 | $442 | 73,709 |
| Distribution Main | 6113 | P-7114 | COV | Juniper Hill Dr. | 8 | Ductile Iron | 306 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6114 | P-7114 | COV | Juniper Hill Dr. | 8 | Ductile Iron | 69 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7272 | P-7109 | COV | Juniper Hill Dr. | 8 | Asbestos Cement | 393 | 40 | 1 out of 5 | $442 | 173,920 |
| Distribution Main | 7465 | P-7106 | COV | Juniper Hill Dr. | 8 | Asbestos Cement | 659 | 40 | 1 out of 5 | $442 | 291,435 |
| Distribution Main | 7978 | P-7114 | COV | Juniper Hill Dr. | 8 | Ductile Iron | 157 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7979 | P-7114 | COV | Juniper Hill Dr. | 8 | Ductile Iron | 435 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 578 | P-7999 | COV | Justa Ave. | 6 | Asbestos Cement | 239 | 72 | 2 out of 5 | $442 | 105,657 |
| Distribution Main | 2733 | P-8000 | COV | Justa Ave. | 6 | Asbestos Cement | 235 | 72 | 2 out of 5 | $442 | 103,899 |
| Distribution Main | 9751 | P-8211 | COV | Kathy Ave | 8 | Ductile Iron | 349 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9752 | P-8211 | COV | Kathy Ave | 8 | Ductile Iron | 22 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 812 | P-7765 | COV | Kennedy Dr. | 8 | Asbestos Cement | 310 | 58 | 1.14 out of 5 | $442 | 136,951 |
| Distribution Main | 2271 | P-7765 | COV | Kennedy Dr. | 8 | Ductile Iron | 6 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3684 | P-7763 | COV | Kennedy Dr. | 8 | Asbestos Cement | 562 | 58 | 1.14 out of 5 | $442 | 248,262 |
| Distribution Main | 9703 | P-7763 | COV | Kennedy Dr. | 8 | Ductile Iron | 26 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10362 | P-7767 | COV | Kennedy Dr. | 8 | Ductile Iron | 8 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10363 | P-7767 | COV | Kennedy Dr. | 8 | Ductile Iron | 36 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9741 | P-8205 | COV | Kennington Ave | 8 | Ductile Iron | 538 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6116 | P-8948 | COV | Kiley Way | 8 | Ductile Iron | 550 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6117 | P-8948 | COV | Kiley Way | 8 | Ductile Iron | 459 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6311 | P-7141 | COV | Kiley Way | 8 | Ductile Iron | 91 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6312 | P-7139 | COV | Kiley Way | 8 | Ductile Iron | 428 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8173 | P-8949 | COV | Kiley Way | 8 | Ductile Iron | 1,039 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8174 | P-7140 | COV | Kiley Way | 8 | Ductile Iron | 28 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8175 | P-7140 | COV | Kiley Way | 8 | Ductile Iron | 797 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11331 | P-7141 | COV | Kiley Way | 8 | Ductile Iron | 378 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2369 | P-7541 | COV | Kilton St. | 8 | Ductile Iron | 459 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9749 | P-8208 | COV | Kimberly Ave | 8 | Ductile Iron | 483 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 734 | P-8216 | COV | King St. | 12 | Ductile Iron | 15 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 735 | P-8216 | COV | King St. | 6 | Ductile Iron | 11 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 2755 | P-8216 | COV | King St. | 6 | Ductile Iron | 253 | 25 | 0.85 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2756 | P-8216 | COV | King St. | 6 | Ductile Iron | 27 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 2757 | P-8216 | COV | King St. | 6 | Ductile Iron | 336 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 2758 | P-8216 | COV | King St. | 6 | Ductile Iron | 377 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 2759 | P-8216 | COV | King St. | 6 | Ductile Iron | 12 | 25 | 0.85 out of 5 | N/A | $0 |
| Transmission Main | 2772 | P-8196 | COV | King St. | 12 | Ductile Iron | 350 | 30 | 0.14 out of 5 | $442 | 154,909 |
| Transmission Main | 11086 | P-8216 | COV | King St. | 12 | Ductile Iron | 6 | 30 | 0.14 out of 5 | $442 | 2,490 |
| Distribution Main | 7798 | P-7094 | COV | Kingfisher Dr. | 8 | PVC | 322 | 38 | 0.43 out of 5 | $442 | 142,542 |
| Distribution Main | 7799 | P-7094 | COV | Kingfisher Dr. | 8 | PVC | 888 | 38 | 0.43 out of 5 | $442 | 392,311 |
| Distribution Main | 9257 | P-7095 | COV | Kingfisher Dr. | 6 | PVC | 245 | 34 | 1.14 out of 5 | $442 | 108,156 |
| Distribution Main | 9258 | P-8950 | COV | Kingfisher Dr. | 8 | PVC | 5 | 34 | 0.43 out of 5 | $442 | 2,295 |
| Distribution Main | 9259 | P-8951 | COV | Kingfisher Dr. | 8 | PVC | 23 | 34 | 0.43 out of 5 | $442 | 10,253 |
| Distribution Main | 10008 | P-7095 | COV | Kingfisher Dr. | 8 | PVC | 3 | 34 | 0.43 out of 5 | $442 | 1,295 |
| Distribution Main | 10009 | P-7095 | COV | Kingfisher Dr. | 8 | PVC | 8 | 34 | 0.43 out of 5 | $442 | 3,608 |
| Distribution Main | 10010 | P-8950 | COV | Kingfisher Dr. | 8 | PVC | 216 | 38 | 0.43 out of 5 | $442 | 95,338 |
| Distribution Main | 7707 | P-7028 | COV | Kingswood Dr. | 6 | Asbestos Cement | 300 | 51 | 1.85 out of 5 | $442 | 132,535 |
| Distribution Main | 7714 | P-7029 | COV | Kingswood Dr. | 6 | Asbestos Cement | 11 | 51 | 1.85 out of 5 | $442 | 4,744 |
| Distribution Main | 7732 | P-7027 | COV | Kingswood Dr. | 6 | Asbestos Cement | 4 | 51 | 1.85 out of 5 | $442 | 1,584 |
| Distribution Main | 7733 | P-7027 | COV | Kingswood Dr. | 6 | Asbestos Cement | 530 | 51 | 1.85 out of 5 | $442 | 234,348 |
| Distribution Main | 11403 | P-7028 | COV | Kingswood Dr. | 6 | Asbestos Cement | 4 | 51 | 1.85 out of 5 | $442 | 1,674 |
| Distribution Main | 9637 | | COV | Knight St | 2 | Unknown | 6 | UNK | 1.42 out of 5 | $442 | 2,595 |
| Distribution Main | 568 | P-7967 | COV | Knight St. | 6 | Cast Iron | 19 | 79 | 2.28 out of 5 | $442 | 8,245 |
| Distribution Main | 2738 | P-7967 | COV | Knight St. | 6 | Cast Iron | 514 | 79 | 2.28 out of 5 | $442 | 227,191 |
| Distribution Main | 2739 | P-7967 | COV | Knight St. | 6 | Cast Iron | 24 | 79 | 2.28 out of 5 | $442 | 10,416 |
| Distribution Main | 9968 | | COV | Knight St. | 6 | Cast Iron | 11 | 79 | 2.28 out of 5 | $442 | 4,922 |
| Distribution Main | 8107 | P-8880 | COV | Knotty Oak Ln | 8 | Ductile Iron | 53 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 113 | P-8253 | COV | Knotty Oak Rd | 16 | Asbestos Cement | 20 | 51 | 1.14 out of 5 | $442 | 8,871 |
| Distribution Main | 115 | P-7275 | COV | Knotty Oak Rd | 8 | Asbestos Cement | 461 | 72 | 1.29 out of 5 | $442 | 203,563 |
| Transmission Main | 216 | P-7888 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 414 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 217 | P-7888 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 348 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 218 | | COV | Knotty Oak Rd. | 16 | Ductile Iron | 24 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 219 | P-7361 | COV | Knotty Oak Rd. | 16 | Ductile Iron | 3 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 220 | P-7363 | COV | Knotty Oak Rd. | 12 | Ductile Iron | 36 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 221 | P-7881 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 329 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 222 | P-8497 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 59 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 223 | P-8496 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 33 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 251 | P-8242 | COV | Knotty Oak Rd. | 8 | Asbestos Cement | 18 | 72 | 1.29 out of 5 | $442 | 7,840 |
| Distribution Main | 252 | P-8242 | COV | Knotty Oak Rd. | 8 | Asbestos Cement | 28 | 72 | 1.29 out of 5 | $442 | 12,180 |
| Transmission Main | 1030 | P-8877 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 36 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1031 | P-8877 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 837 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1042 | P-8489 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 113 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1047 | P-8490 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 103 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1048 | P-8490 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 951 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1109 | P-8491 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 135 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1112 | P-7887 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 54 | 15 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 1115 | P-8879 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 16 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1116 | P-8879 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 62 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1117 | P-8879 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 514 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1118 | P-7890 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 607 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1184 | P-7362 | COV | Knotty Oak Rd. | 12 | Asbestos Cement | 19 | 57 | 1.14 out of 5 | $442 | 8,235 |
| Transmission Main | 1185 | P-7362 | COV | Knotty Oak Rd. | 12 | Asbestos Cement | 792 | 57 | 1.14 out of 5 | $442 | 349,850 |
| Transmission Main | 1216 | P-7361 | COV | Knotty Oak Rd. | 20 | Asbestos Cement | 336 | 24 | 1 out of 5 | N/A | $0 |
| Transmission Main | 1217 | P-8496 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 11 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1218 | P-8496 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 9 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1219 | P-8496 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 68 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1220 | P-8495 | COV | Knotty Oak Rd. | 20 | Asbestos Cement | 410 | 51 | 1.14 out of 5 | $442 | 181,336 |
| Transmission Main | 1221 | P-7887 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 24 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1222 | P-8879 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 631 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1223 | P-8879 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 728 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1260 | P-7317 | COV | Knotty Oak Rd. | 8 | Asbestos Cement | 305 | 72 | 1.29 out of 5 | $442 | 135,009 |
| Transmission Main | 1269 | P-8495 | COV | Knotty Oak Rd. | 20 | Asbestos Cement | 652 | 51 | 1.14 out of 5 | $442 | 288,196 |
| Transmission Main | 1446 | P-7873 | COV | Knotty Oak Rd. | 20 | Asbestos Cement | 1,234 | 72 | 1.29 out of 5 | $442 | 545,580 |
| Transmission Main | 1450 | P-8253 | COV | Knotty Oak Rd. | 16 | Asbestos Cement | 10 | 51 | 1.14 out of 5 | $442 | 4,338 |
| Transmission Main | 1635 | P-7362 | COV | Knotty Oak Rd. | 12 | Ductile Iron | 37 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2291 | P-8253 | COV | Knotty Oak Rd. | 20 | Asbestos Cement | 587 | 51 | 1.14 out of 5 | $442 | 259,429 |
| Transmission Main | 2456 | P-8491 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 13 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2457 | P-7880 | COV | Knotty Oak Rd. | 20 | Asbestos Cement | 32 | 51 | 1.14 out of 5 | $442 | 14,115 |
| Transmission Main | 2574 | P-8879 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 216 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2666 | | COV | Knotty Oak Rd. | 12 | Ductile Iron | 18 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 2674 | P-8495 | COV | Knotty Oak Rd. | 20 | Asbestos Cement | 535 | 51 | 1.14 out of 5 | $442 | 236,337 |
| Transmission Main | 2675 | P-7279 | COV | Knotty Oak Rd. | 12 | Asbestos Cement | 19 | 72 | 1.29 out of 5 | $442 | 8,250 |
| Transmission Main | 2678 | P-8916 | COV | Knotty Oak Rd. | 12 | Asbestos Cement | 790 | 57 | 1.14 out of 5 | $442 | 348,988 |
| Transmission Main | 2679 | P-8916 | COV | Knotty Oak Rd. | 12 | Asbestos Cement | 674 | 57 | 1.14 out of 5 | $442 | 298,028 |
| Transmission Main | 2680 | P-7875 | COV | Knotty Oak Rd. | 20 | Asbestos Cement | 2,331 | 51 | 1.14 out of 5 | $442 | 1,030,462 |
| Distribution Main | 2813 | P-8245 | COV | Knotty Oak Rd. | 8 | Asbestos Cement | 575 | 72 | 1.29 out of 5 | $442 | 254,274 |
| Distribution Main | 2822 | P-8245 | COV | Knotty Oak Rd. | 8 | Asbestos Cement | 11 | 72 | 1.29 out of 5 | $442 | 5,049 |
| Distribution Main | 2991 | P-7274 | COV | Knotty Oak Rd. | 8 | Asbestos Cement | 5 | 72 | 1.29 out of 5 | $442 | 2,097 |
| Distribution Main | 2992 | P-7274 | COV | Knotty Oak Rd. | 8 | Asbestos Cement | 11 | 72 | 1.29 out of 5 | $442 | 4,669 |
| Distribution Main | 2993 | P-7317 | COV | Knotty Oak Rd. | 8 | Asbestos Cement | 4 | 72 | 1.29 out of 5 | $442 | 1,857 |
| Distribution Main | 2995 | P-7279 | COV | Knotty Oak Rd. | 8 | Asbestos Cement | 565 | 72 | 1.29 out of 5 | $442 | 249,728 |
| Distribution Main | 2996 | P-7279 | COV | Knotty Oak Rd. | 8 | Asbestos Cement | 272 | 72 | 1.29 out of 5 | $442 | 120,043 |
| Transmission Main | 3008 | P-7878 | COV | Knotty Oak Rd. | 12 | Asbestos Cement | 763 | 57 | 1.14 out of 5 | $442 | 337,160 |
| Transmission Main | 3009 | P-7323 | COV | Knotty Oak Rd. | 12 | Asbestos Cement | 118 | 57 | 1.14 out of 5 | $442 | 51,958 |
| Transmission Main | 3010 | P-7323 | COV | Knotty Oak Rd. | 12 | Asbestos Cement | 59 | 57 | 1.14 out of 5 | $442 | 25,893 |
| Transmission Main | 8101 | P-8488 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 6 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 8102 | P-8489 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 25 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 8103 | P-8489 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 24 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 8105 | P-7891 | COV | Knotty Oak Rd. | 8 | Ductile Iron | 32 | 30 | 0.14 out of 5 | $442 | 14,088 |
| Transmission Main | 8108 | P-7890 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 242 | 15 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 8109 | P-7891 | COV | Knotty Oak Rd. | 8 | Asbestos Cement | 549 | 30 | 1 out of 5 | $442 | 242,798 |
| Distribution Main | 8110 | P-7891 | COV | Knotty Oak Rd. | 8 | Ductile Iron | 27 | 30 | 0.14 out of 5 | $442 | 12,028 |
| Transmission Main | 8113 | P-7890 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 342 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8114 | P-7890 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 49 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8115 | P-8879 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 397 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8116 | P-8495 | COV | Knotty Oak Rd. | 20 | Asbestos Cement | 243 | 51 | 1.14 out of 5 | $442 | 107,574 |
| Transmission Main | 8117 | P-8495 | COV | Knotty Oak Rd. | 20 | Asbestos Cement | 47 | 51 | 1.14 out of 5 | $442 | 20,813 |
| Transmission Main | 8118 | P-7362 | COV | Knotty Oak Rd. | 12 | Asbestos Cement | 115 | 57 | 1.14 out of 5 | $442 | 50,719 |
| Transmission Main | 8119 | P-7362 | COV | Knotty Oak Rd. | 12 | Asbestos Cement | 244 | 57 | 1.14 out of 5 | $442 | 107,720 |
| Transmission Main | 8120 | P-8495 | COV | Knotty Oak Rd. | 20 | Asbestos Cement | 140 | 51 | 1.14 out of 5 | $442 | 61,922 |
| Transmission Main | 8121 | P-8495 | COV | Knotty Oak Rd. | 20 | Asbestos Cement | 20 | 51 | 1.14 out of 5 | $442 | 8,688 |
| Transmission Main | 8122 | P-7362 | COV | Knotty Oak Rd. | 12 | Asbestos Cement | 411 | 57 | 1.14 out of 5 | $442 | 181,674 |
| Transmission Main | 8216 | P-6015 | COV | Knotty Oak Rd. | 12 | Ductile Iron | 241 | 30 | 0.14 out of 5 | $442 | 106,499 |
| Transmission Main | 10085 | P-8489 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 50 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11045 | P-7361 | COV | Knotty Oak Rd. | 16 | Ductile Iron | 2 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11136 | P-7362 | COV | Knotty Oak Rd. | 12 | Ductile Iron | 4 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11433 | P-7892 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 5 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 11434 | P-8488 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 4 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 11435 | P-8489 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 16 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 11436 | P-8489 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 3 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 11437 | P-7891 | COV | Knotty Oak Rd. | 8 | Ductile Iron | 5 | 30 | 0.14 out of 5 | $442 | 2,232 |
| Distribution Main | 11438 | P-7891 | COV | Knotty Oak Rd. | 8 | Asbestos Cement | 257 | 30 | 1 out of 5 | $442 | 113,520 |
| Distribution Main | 11777 | P-7279 | COV | Knotty Oak Rd. | 8 | Asbestos Cement | 5 | 72 | 1.29 out of 5 | $442 | 2,329 |
| Transmission Main | 11778 | P-8916 | COV | Knotty Oak Rd. | 12 | Asbestos Cement | 58 | 57 | 1.14 out of 5 | $442 | 25,747 |
| Transmission Main | 12059 | P-7782 | COV | Knotty Oak Rd. | 20 | Ductile Iron | 63 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 250 | P-8920 | COV | Knotty Oak Rd. Ps | 10 | Ductile Iron | 28 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 497 | P-8920 | COV | Knotty Oak Rd. Ps | 10 | Ductile Iron | 34 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 498 | P-8924 | COV | Knotty Oak Rd. Ps | 12 | Ductile Iron | 7 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 499 | P-8922 | COV | Knotty Oak Rd. Ps | 10 | Ductile Iron | 23 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1265 | P-8927 | COV | Knotty Oak Rd. Ps | 12 | Ductile Iron | 24 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1266 | P-8923 | COV | Knotty Oak Rd. Ps | 12 | Ductile Iron | 24 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1615 | P-8924 | COV | Knotty Oak Rd. Ps | 12 | Ductile Iron | 32 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 8264 | P-6135 | COV | Knotty Oak Road | 24 | Ductile Iron | 233 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8265 | P-6135 | COV | Knotty Oak Road | 24 | Ductile Iron | 290 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10399 | P-6089 | COV | Knotty Oak Road | 24 | Ductile Iron | 535 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11456 | P-6135 | COV | Knotty Oak Road | 24 | Ductile Iron | 51 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1224 | P-8878 | COV | Knotty Oak Shores | 8 | Ductile Iron | 334 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1225 | P-8878 | COV | Knotty Oak Shores | 8 | Ductile Iron | 43 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10426 | P-8878 | COV | Knotty Oak Shores | 8 | Ductile Iron | 33 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1444 | P-7378 | COV | La Casa Dr. | 6 | Asbestos Cement | 362 | 49 | 1.85 out of 5 | $442 | 160,160 |
| Distribution Main | 1445 | P-7378 | COV | La Casa Dr. | 6 | Asbestos Cement | 46 | 49 | 1.85 out of 5 | $442 | 20,403 |
| Distribution Main | 2290 | P-7380 | COV | La Casa Dr. | 6 | Asbestos Cement | 358 | 49 | 1.85 out of 5 | $442 | 158,086 |
| Distribution Main | 11129 | P-7378 | COV | La Casa Dr. | 6 | Asbestos Cement | 25 | 49 | 1.85 out of 5 | $442 | 10,875 |
| Distribution Main | 185 | P-7369 | COV | La Forge Dr. | 8 | Ductile Iron | 11 | 15 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 447 | P-7377 | COV | La Forge Dr. | 8 | Asbestos Cement | 56 | 51 | 1.14 out of 5 | $442 | 24,763 |
| Distribution Main | 1465 | P-8850 | COV | La Forge Dr. | 8 | Asbestos Cement | 132 | 51 | 1.14 out of 5 | $442 | 58,147 |
| Distribution Main | 10270 | P-8850 | COV | La Forge Dr. | 8 | Asbestos Cement | 15 | 51 | 1.14 out of 5 | $442 | 6,783 |
| Distribution Main | 1923 | P-7913 | COV | Labrea Way | 8 | Ductile Iron | 470 | 29 | 0.14 out of 5 | $442 | 207,585 |
| Distribution Main | 1924 | P-7913 | COV | Labrea Way | 8 | Ductile Iron | 222 | 29 | 0.14 out of 5 | $442 | 97,979 |
| Distribution Main | 1464 | P-7379 | COV | Laforge Drive | 8 | Asbestos Cement | 298 | 51 | 1.14 out of 5 | $442 | 131,681 |
| Distribution Main | 1466 | P-7369 | COV | Laforge Drive | 8 | Asbestos Cement | 72 | 51 | 1.14 out of 5 | $442 | 31,758 |
| Distribution Main | 1467 | P-7369 | COV | Laforge Drive | 8 | Asbestos Cement | 272 | 51 | 1.14 out of 5 | $442 | 120,077 |
| Distribution Main | 1470 | P-7377 | COV | Laforge Drive | 8 | Asbestos Cement | 313 | 51 | 1.14 out of 5 | $442 | 138,310 |
| Distribution Main | 1746 | P-7005 | COV | Lakehurst Dr. | 6 | Ductile Iron | 601 | 28 | 0.85 out of 5 | $442 | 265,576 |
| Distribution Main | 7767 | P-7005 | COV | Lakehurst Dr. | 6 | Ductile Iron | 55 | 28 | 0.85 out of 5 | $442 | 24,115 |
| Distribution Main | 11409 | P-7005 | COV | Lakehurst Dr. | 6 | Ductile Iron | 29 | 28 | 0.85 out of 5 | $442 | 12,760 |
| Distribution Main | 36 | P-7584 | COV | Lakeside Dr | 3 | Galvanized Iron | 575 | 86 | 3.43 out of 5 | $442 | 254,217 |
| Distribution Main | 37 | P-7585 | COV | Lakeside Dr | 2 | Galvanized Iron | 283 | 86 | 3.43 out of 5 | $442 | 125,055 |
| Distribution Main | 9680 | | COV | Lakeside Dr | 0.75 | Copper | 7 | 8 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 9681 | | COV | Lakeside Dr | 0.75 | Copper | 8 | 8 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 9682 | | COV | Lakeside Dr | 0.75 | Copper | 8 | 8 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 1685 | P-9002 | COV | Lakeside Dr. | 1.5 | Copper | 1,284 | 86 | 2.57 out of 5 | $442 | 567,698 |
| Distribution Main | 1759 | P-9002 | COV | Lakeside Dr. | 1.5 | Copper | 17 | 86 | 2.57 out of 5 | $442 | 7,594 |
| Distribution Main | 11139 | P-9002 | COV | Lakeside Dr. | 1.5 | Copper | 72 | 86 | 2.57 out of 5 | $442 | 31,869 |
| Distribution Main | 11140 | P-9002 | COV | Lakeside Dr. | 1.5 | Copper | 2 | 86 | 2.57 out of 5 | $442 | 951 |
| Distribution Main | 11141 | P-9002 | COV | Lakeside Dr. | 1.5 | Copper | 2 | 86 | 2.57 out of 5 | $442 | 878 |
| Distribution Main | 1851 | P-8320 | COV | Lambert St. | 1 | Unknown | 218 | 22 | 1.57 out of 5 | N/A | $0 |
| Distribution Main | 8390 | P-1224 | COV | Lamphear St | 8 | Ductile Iron | 23 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8461 | P-1224 | COV | Lamphear St | 6 | Ductile Iron | 5 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10177 | | COV | Lamphear St | 1.5 | PVC | 10 | 10 | 1.71 out of 5 | N/A | $0 |
| Distribution Main | 1595 | P-7771 | COV | Lantern Ln. | 8 | Ductile Iron | 42 | 59 | 0.29 out of 5 | $442 | 18,778 |
| Distribution Main | 2256 | P-7771 | COV | Lantern Ln. | 6 | Asbestos Cement | 23 | 59 | 1.85 out of 5 | $442 | 10,374 |
| Distribution Main | 2257 | P-7771 | COV | Lantern Ln. | 6 | Asbestos Cement | 399 | 59 | 1.85 out of 5 | $442 | 176,171 |
| Distribution Main | 418 | P-7703 | COV | Larch Dr. | 6 | Asbestos Cement | 16 | 60 | 1.85 out of 5 | $442 | 6,921 |
| Distribution Main | 419 | P-7703 | COV | Larch Dr. | 6 | Asbestos Cement | 564 | 60 | 1.85 out of 5 | $442 | 249,340 |
| Distribution Main | 1452 | P-7704 | COV | Larch Dr. | 6 | Asbestos Cement | 162 | 60 | 1.85 out of 5 | $442 | 71,656 |
| Distribution Main | 1454 | | COV | Larch Dr. | 6 | Asbestos Cement | 7 | 60 | 1.85 out of 5 | $442 | 3,278 |
| Distribution Main | 1646 | P-7698 | COV | Larch Dr. | 8 | Asbestos Cement | 13 | 60 | 1.14 out of 5 | $442 | 5,749 |
| Distribution Main | 1647 | P-7698 | COV | Larch Dr. | 8 | Asbestos Cement | 207 | 60 | 1.14 out of 5 | $442 | 91,554 |
| Distribution Main | 2594 | P-7702 | COV | Larch Dr. | 6 | Asbestos Cement | 638 | 60 | 1.85 out of 5 | $442 | 282,024 |
| Distribution Main | 2595 | P-7698 | COV | Larch Dr. | 8 | Asbestos Cement | 50 | 60 | 1.14 out of 5 | $442 | 21,959 |
| Distribution Main | 11026 | P-7698 | COV | Larch Dr. | 8 | Asbestos Cement | 28 | 60 | 1.14 out of 5 | $442 | 12,172 |
| Distribution Main | 1856 | P-7600 | COV | Larchmont Dr. | 8 | Asbestos Cement | 959 | 53 | 1.14 out of 5 | $442 | 424,039 |
| Distribution Main | 1857 | P-7600 | COV | Larchmont Dr. | 8 | Asbestos Cement | 163 | 53 | 1.14 out of 5 | $442 | 71,967 |
| Distribution Main | 2637 | P-7599 | COV | Larchmont Dr. | 8 | Asbestos Cement | 203 | 53 | 1.14 out of 5 | $442 | 89,796 |
| Distribution Main | 7878 | P-7303 | COV | Laura Ct. | 8 | Asbestos Cement | 27 | 34 | 1 out of 5 | $442 | 12,021 |
| Distribution Main | 7879 | P-7303 | COV | Laura Ct. | 8 | Asbestos Cement | 345 | 34 | 1 out of 5 | $442 | 152,393 |
| Distribution Main | 832 | P-7828 | COV | Laurel Ave. | 6 | Cast Iron | 181 | 132 | 2.57 out of 5 | $442 | 79,927 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 833 | P-7829 | COV | Laurel Ave. | 6 | Cast Iron | 234 | 132 | 2.57 out of 5 | $442 | 103,235 |
| Distribution Main | 839 | P-7830 | COV | Laurel Ave. | 6 | Cast Iron | 109 | 132 | 2.57 out of 5 | $442 | 48,368 |
| Distribution Main | 840 | P-7830 | COV | Laurel Ave. | 6 | Cast Iron | 27 | 132 | 2.57 out of 5 | $442 | 12,014 |
| Distribution Main | 841 | P-7826 | COV | Laurel Ave. | 6 | Asbestos Cement | 304 | 52 | 1.85 out of 5 | $442 | 134,264 |
| Distribution Main | 1482 | P-7820 | COV | Laurel Ave. | 6 | Asbestos Cement | 268 | 52 | 1.85 out of 5 | $442 | 118,550 |
| Distribution Main | 1494 | P-7839 | COV | Laurel Ave. | 6 | Asbestos Cement | 69 | 50 | 1.85 out of 5 | $442 | 30,471 |
| Distribution Main | 3150 | P-7826 | COV | Laurel Ave. | 6 | Asbestos Cement | 25 | 52 | 1.85 out of 5 | $442 | 11,133 |
| Distribution Main | 3152 | P-7862 | COV | Laurel Ave. | 6 | Cast Iron | 48 | 132 | 2.57 out of 5 | $442 | 21,103 |
| Distribution Main | 3158 | P-7821 | COV | Laurel Ave. | 6 | Asbestos Cement | 257 | 52 | 1.85 out of 5 | $442 | 113,674 |
| Distribution Main | 3159 | P-7821 | COV | Laurel Ave. | 6 | Asbestos Cement | 3 | 52 | 1.85 out of 5 | $442 | 1,395 |
| Distribution Main | 3161 | P-7839 | COV | Laurel Ave. | 6 | Asbestos Cement | 144 | 50 | 1.85 out of 5 | $442 | 63,550 |
| Distribution Main | 3162 | P-7840 | COV | Laurel Ave. | 6 | Asbestos Cement | 217 | 50 | 1.85 out of 5 | $442 | 95,774 |
| Distribution Main | 3163 | P-7840 | COV | Laurel Ave. | 6 | Asbestos Cement | 317 | 52 | 1.85 out of 5 | $442 | 139,954 |
| Distribution Main | 10112 | P-7839 | COV | Laurel Ave. | 6 | Asbestos Cement | 4 | 50 | 1.85 out of 5 | $442 | 1,709 |
| Distribution Main | 11091 | P-7826 | COV | Laurel Ave. | 6 | Asbestos Cement | 13 | 52 | 1.85 out of 5 | $442 | 5,720 |
| Distribution Main | 6460 | P-7463 | COV | Laurie Ave. | 6 | Asbestos Cement | 596 | 49 | 1.85 out of 5 | $442 | 263,572 |
| Distribution Main | 423 | P-7624 | COV | Lawnwood Rd. | 6 | Asbestos Cement | 173 | 50 | 1.85 out of 5 | $442 | 76,249 |
| Distribution Main | 424 | P-7624 | COV | Lawnwood Rd. | 6 | Asbestos Cement | 17 | 50 | 1.85 out of 5 | $442 | 7,551 |
| Distribution Main | 2557 | P-7624 | COV | Lawnwood Rd. | 6 | Asbestos Cement | 319 | 50 | 1.85 out of 5 | $442 | 141,066 |
| Distribution Main | 2558 | P-7625 | COV | Lawnwood Rd. | 6 | Asbestos Cement | 64 | 50 | 1.85 out of 5 | $442 | 28,405 |
| Distribution Main | 2620 | P-7625 | COV | Lawnwood Rd. | 6 | Asbestos Cement | 292 | 50 | 1.85 out of 5 | $442 | 128,892 |
| Distribution Main | 7758 | P-7224 | COV | Leader St. | 6 | Asbestos Cement | 234 | 69 | 2 out of 5 | $442 | 103,312 |
| Distribution Main | 7761 | P-7225 | COV | Leader St. | 6 | Asbestos Cement | 209 | 69 | 2 out of 5 | $442 | 92,261 |
| Distribution Main | 9803 | P-7224 | COV | Leader St. | 6 | Asbestos Cement | 37 | 69 | 2 out of 5 | $442 | 16,407 |
| Distribution Main | 1868 | P-7630 | COV | Ledo St. | 6 | Asbestos Cement | 496 | 57 | 1.85 out of 5 | $442 | 219,129 |
| Distribution Main | 10446 | P-7952 | COV | Leisure Way | 8 | Ductile Iron | 64 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 4073 | P-8135 | COV | Lemis St. | 6 | Asbestos Cement | 672 | 59 | 1.85 out of 5 | $442 | 297,063 |
| Distribution Main | 4074 | P-8135 | COV | Lemis St. | 6 | Asbestos Cement | 359 | 59 | 1.85 out of 5 | $442 | 158,654 |
| Distribution Main | 8776 | P-8899 | COV | Leuba Rd | 8 | Ductile Iron | 43 | 26 | 0.14 out of 5 | $442 | 19,027 |
| Distribution Main | 10423 | P-8899 | COV | Leuba Rd | 8 | Ductile Iron | 39 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 852 | P-7194 | COV | Leuba Rd. | 8 | Asbestos Cement | 110 | 45 | 1.14 out of 5 | $442 | 48,802 |
| Distribution Main | 7503 | P-7192 | COV | Leuba Rd. | 8 | Ductile Iron | 149 | 26 | 0.14 out of 5 | $442 | 66,032 |
| Distribution Main | 7504 | P-7192 | COV | Leuba Rd. | 8 | Ductile Iron | 642 | 26 | 0.14 out of 5 | $442 | 283,845 |
| Distribution Main | 7870 | P-7197 | COV | Leuba Rd. | 8 | Asbestos Cement | 616 | 45 | 1.14 out of 5 | $442 | 272,097 |
| Distribution Main | 7945 | P-7196 | COV | Leuba Rd. | 8 | Asbestos Cement | 309 | 45 | 1.14 out of 5 | $442 | 136,541 |
| Distribution Main | 7946 | P-7196 | COV | Leuba Rd. | 8 | Asbestos Cement | 218 | 45 | 1.14 out of 5 | $442 | 96,432 |
| Distribution Main | 8775 | P-7192 | COV | Leuba Rd. | 8 | Ductile Iron | 68 | 26 | 0.14 out of 5 | $442 | 30,132 |
| Distribution Main | 10109 | P-7192 | COV | Leuba Rd. | 8 | Ductile Iron | 25 | 26 | 0.14 out of 5 | $442 | 11,157 |
| Distribution Main | 10424 | P-7192 | COV | Leuba Rd. | 8 | Ductile Iron | 265 | 26 | 0.14 out of 5 | $442 | 117,009 |
| Distribution Main | 10425 | P-7192 | COV | Leuba Rd. | 8 | Ductile Iron | 576 | 26 | 0.14 out of 5 | $442 | 254,479 |
| Distribution Main | 11980 | P-7192 | COV | Leuba Rd. | 8 | Ductile Iron | 474 | 26 | 0.14 out of 5 | $442 | 209,428 |
| Distribution Main | 94 | P-8873 | COV | Leveilee St | 8 | Ductile Iron | 19 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2454 | P-8102 | COV | Levielle Street | 6 | Cast Iron | 622 | 132 | 2.57 out of 5 | $442 | 275,110 |
| Distribution Main | 2455 | P-8102 | COV | Levielle Street | 6 | Cast Iron | 13 | 132 | 2.57 out of 5 | $442 | 5,541 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 8524 | P-8842 | COV | Lincoln Ave | 16 | Ductile Iron | 88 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8859 | P-8219 | COV | Lincoln Ave | 12 | Ductile Iron | 42 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8860 | | COV | Lincoln Ave | 6 | Ductile Iron | 24 | 12 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 8861 | P-8754 | COV | Lincoln Ave | 12 | Ductile Iron | 72 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8862 | P-8842 | COV | Lincoln Ave | 16 | Ductile Iron | 84 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8863 | P-8754 | COV | Lincoln Ave | 16 | Ductile Iron | 258 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8864 | P-8843 | COV | Lincoln Ave | 8 | Ductile Iron | 9 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8865 | P-8843 | COV | Lincoln Ave | 8 | Ductile Iron | 29 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9685 | | COV | Lincoln Ave | 8 | Ductile Iron | 7 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 229 | P-8367 | COV | Lincoln Ave. | 8 | Ductile Iron | 259 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 238 | P-8368 | COV | Lincoln Ave. | 16 | Asbestos Cement | 107 | 62 | 1.29 out of 5 | $442 | 47,267 |
| Distribution Main | 1419 | P-8367 | COV | Lincoln Ave. | 8 | Ductile Iron | 47 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1420 | P-8367 | COV | Lincoln Ave. | 8 | Ductile Iron | 2 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10439 | P-8840 | COV | Lincoln Ave. | 16 | Ductile Iron | 13 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10963 | P-8368 | COV | Lincoln Ave. | 16 | Asbestos Cement | 17 | 62 | 1.29 out of 5 | $442 | 7,547 |
| Transmission Main | 11037 | P-8368 | COV | Lincoln Ave. | 16 | Asbestos Cement | 24 | 62 | 1.29 out of 5 | $442 | 10,418 |
| Transmission Main | 11038 | P-8840 | COV | Lincoln Ave. | 16 | Ductile Iron | 13 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11657 | P-8840 | COV | Lincoln Ave. | 16 | Ductile Iron | 5 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7940 | P-7234 | COV | Linda Ct. | 6 | Asbestos Cement | 39 | 51 | 1.85 out of 5 | $442 | 17,079 |
| Distribution Main | 7941 | P-7234 | COV | Linda Ct. | 6 | Asbestos Cement | 206 | 51 | 1.85 out of 5 | $442 | 91,059 |
| Distribution Main | 7827 | P-7059 | COV | Linden Ln. | 6 | Asbestos Cement | 377 | 46 | 1.85 out of 5 | $442 | 166,576 |
| Distribution Main | 4060 | P-8148 | COV | Linray St. | 6 | Asbestos Cement | 23 | 54 | 1.85 out of 5 | $442 | 10,092 |
| Distribution Main | 4061 | P-8148 | COV | Linray St. | 6 | Asbestos Cement | 196 | 54 | 1.85 out of 5 | $442 | 86,639 |
| Distribution Main | 4955 | | COV | Linray St. | 6 | Asbestos Cement | 16 | 54 | 1.85 out of 5 | $442 | 7,157 |
| Distribution Main | 2751 | P-7470 | COV | Linwood Dr. | 6 | Asbestos Cement | 285 | 56 | 1.85 out of 5 | $442 | 126,113 |
| Distribution Main | 2753 | P-8515 | COV | Linwood Dr. | 6 | Asbestos Cement | 11 | 56 | 1.85 out of 5 | $442 | 4,739 |
| Distribution Main | 2771 | P-7478 | COV | Linwood Dr. | 6 | Asbestos Cement | 199 | 56 | 1.85 out of 5 | $442 | 88,141 |
| Distribution Main | 6458 | P-7459 | COV | Linwood Dr. | 6 | Asbestos Cement | 189 | 57 | 1.85 out of 5 | $442 | 83,339 |
| Distribution Main | 6459 | P-7459 | COV | Linwood Dr. | 6 | Asbestos Cement | 340 | 57 | 1.85 out of 5 | $442 | 150,296 |
| Distribution Main | 7440 | P-7470 | COV | Linwood Dr. | 6 | Asbestos Cement | 40 | 57 | 1.85 out of 5 | $442 | 17,701 |
| Distribution Main | 7442 | P-7464 | COV | Linwood Dr. | 6 | Asbestos Cement | 317 | 57 | 1.85 out of 5 | $442 | 140,059 |
| Distribution Main | 11187 | P-7470 | COV | Linwood Dr. | 6 | Asbestos Cement | 99 | 56 | 1.85 out of 5 | $442 | 43,616 |
| Distribution Main | 1663 | P-7618 | COV | Lionel Ave. | 8 | Asbestos Cement | 273 | 60 | 1.14 out of 5 | $442 | 120,687 |
| Distribution Main | 1839 | P-7610 | COV | Lionel Ave. | 8 | Asbestos Cement | 516 | 60 | 1.14 out of 5 | $442 | 227,917 |
| Distribution Main | 1840 | P-7615 | COV | Lionel Ave. | 8 | Asbestos Cement | 434 | 60 | 1.14 out of 5 | $442 | 191,761 |
| Distribution Main | 1841 | P-7615 | COV | Lionel Ave. | 8 | Asbestos Cement | 41 | 60 | 1.14 out of 5 | $442 | 18,129 |
| Distribution Main | 9506 | P-8942 | COV | Lionel Ave. | 8 | Ductile Iron | 62 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2536 | P-8154 | COV | Lions Dr. | 8 | Asbestos Cement | 23 | 46 | 1.14 out of 5 | $442 | 10,227 |
| Distribution Main | 4567 | P-8154 | COV | Lions Dr. | 8 | Asbestos Cement | 398 | 46 | 1.14 out of 5 | $442 | 175,785 |
| Distribution Main | 7868 | P-7245 | COV | Lloyd Dr. | 8 | Asbestos Cement | 327 | 56 | 1.14 out of 5 | $442 | 144,683 |
| Distribution Main | 7869 | P-7245 | COV | Lloyd Dr. | 8 | Asbestos Cement | 49 | 56 | 1.14 out of 5 | $442 | 21,780 |
| Distribution Main | 7927 | P-7238 | COV | Lloyd Dr. | 8 | Asbestos Cement | 332 | 56 | 1.14 out of 5 | $442 | 146,598 |
| Distribution Main | 7928 | P-7238 | COV | Lloyd Dr. | 8 | Asbestos Cement | 5 | 56 | 1.14 out of 5 | $442 | 2,077 |
| Distribution Main | 7942 | P-7243 | COV | Lloyd Dr. | 8 | Asbestos Cement | 580 | 56 | 1.14 out of 5 | $442 | 256,453 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 7943 | P-7247 | COV | Lloyd Dr. | 8 | Asbestos Cement | 254 | 56 | 1.14 out of 5 | $442 | 112,346 |
| Distribution Main | 2372 | P-8323 | COV | Locust St. | 8 | Ductile Iron | 270 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 197 | P-7281 | COV | Long Pond Rd. | 8 | Asbestos Cement | 337 | 60 | 1.14 out of 5 | $442 | 148,823 |
| Distribution Main | 198 | P-7280 | COV | Long Pond Rd. | 8 | Asbestos Cement | 225 | 60 | 1.14 out of 5 | $442 | 99,280 |
| Distribution Main | 1953 | P-7285 | COV | Long Pond Rd. | 8 | Asbestos Cement | 507 | 60 | 1.14 out of 5 | $442 | 224,140 |
| Distribution Main | 11029 | P-7285 | COV | Long Pond Rd. | 8 | Asbestos Cement | 28 | 60 | 1.14 out of 5 | $442 | 12,467 |
| Distribution Main | 2531 | P-8155 | COV | Longfellow Dr. | 8 | Asbestos Cement | 351 | 46 | 1.14 out of 5 | $442 | 155,303 |
| Distribution Main | 2532 | P-8155 | COV | Longfellow Dr. | 8 | Asbestos Cement | 40 | 46 | 1.14 out of 5 | $442 | 17,733 |
| Distribution Main | 2533 | P-8153 | COV | Longfellow Dr. | 8 | Asbestos Cement | 242 | 46 | 1.14 out of 5 | $442 | 107,047 |
| Distribution Main | 2539 | P-8156 | COV | Longfellow Dr. | 8 | Asbestos Cement | 11 | 46 | 1.14 out of 5 | $442 | 4,992 |
| Distribution Main | 4564 | P-8159 | COV | Longfellow Dr. | 8 | Asbestos Cement | 23 | 46 | 1.14 out of 5 | $442 | 10,125 |
| Distribution Main | 4565 | P-8156 | COV | Longfellow Dr. | 8 | Asbestos Cement | 105 | 46 | 1.14 out of 5 | $442 | 46,598 |
| Distribution Main | 4566 | P-8156 | COV | Longfellow Dr. | 8 | Asbestos Cement | 185 | 46 | 1.14 out of 5 | $442 | 81,769 |
| Distribution Main | 4568 | P-8159 | COV | Longfellow Dr. | 8 | Asbestos Cement | 265 | 46 | 1.14 out of 5 | $442 | 117,111 |
| Distribution Main | 4569 | P-8159 | COV | Longfellow Dr. | 8 | Asbestos Cement | 482 | 46 | 1.14 out of 5 | $442 | 213,233 |
| Distribution Main | 11176 | P-8156 | COV | Longfellow Dr. | 8 | Asbestos Cement | 2 | 46 | 1.14 out of 5 | $442 | 1,027 |
| Distribution Main | 2788 | P-7653 | COV | Loretta Ave. | 8 | Ductile Iron | 228 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 38 | P-7467 | COV | Lorraine Ave | 6 | Asbestos Cement | 797 | 60 | 1.85 out of 5 | $442 | 352,334 |
| Distribution Main | 39 | P-7467 | COV | Lorraine Ave | 6 | Asbestos Cement | 421 | 60 | 1.85 out of 5 | $442 | 186,023 |
| Distribution Main | 2752 | P-7476 | COV | Lorraine Ave. | 6 | Asbestos Cement | 20 | 60 | 1.85 out of 5 | $442 | 8,876 |
| Distribution Main | 2980 | P-7512 | COV | Lowell St. | 6 | Asbestos Cement | 456 | 70 | 2 out of 5 | $442 | 201,460 |
| Distribution Main | 4787 | P-7512 | COV | Lowell St. | 6 | Asbestos Cement | 7 | 70 | 2 out of 5 | $442 | 3,170 |
| Distribution Main | 5343 | P-7516 | COV | Lowell St. | 6 | Asbestos Cement | 192 | 70 | 2 out of 5 | $442 | 85,056 |
| Distribution Main | 5344 | P-7516 | COV | Lowell St. | 6 | Asbestos Cement | 38 | 70 | 2 out of 5 | $442 | 16,776 |
| Distribution Main | 549 | P-7680 | COV | Lydia Rd. | 8 | Asbestos Cement | 40 | 56 | 1.14 out of 5 | $442 | 17,619 |
| Distribution Main | 550 | P-7680 | COV | Lydia Rd. | 8 | Asbestos Cement | 708 | 56 | 1.14 out of 5 | $442 | 312,820 |
| Distribution Main | 553 | P-7681 | COV | Lydia Rd. | 8 | Asbestos Cement | 27 | 56 | 1.14 out of 5 | $442 | 12,072 |
| Distribution Main | 2554 | P-7677 | COV | Lydia Rd. | 8 | Asbestos Cement | 241 | 56 | 1.14 out of 5 | $442 | 106,564 |
| Distribution Main | 2559 | P-7669 | COV | Lydia Rd. | 8 | Asbestos Cement | 255 | 56 | 1.14 out of 5 | $442 | 112,791 |
| Distribution Main | 2561 | P-7676 | COV | Lydia Rd. | 8 | Asbestos Cement | 261 | 56 | 1.14 out of 5 | $442 | 115,277 |
| Distribution Main | 2603 | P-8973 | COV | Lydia Rd. | 8 | Asbestos Cement | 605 | 56 | 1.14 out of 5 | $442 | 267,596 |
| Distribution Main | 2608 | P-7669 | COV | Lydia Rd. | 8 | Asbestos Cement | 7 | 56 | 1.14 out of 5 | $442 | 2,891 |
| Distribution Main | 11178 | P-8973 | COV | Lydia Rd. | 8 | Asbestos Cement | 136 | 56 | 1.14 out of 5 | $442 | 60,092 |
| Transmission Main | 5253 | P-7065 | COV | Lynn Dr. | 12 | PVC | 553 | 32 | 0.43 out of 5 | $442 | 244,408 |
| Transmission Main | 5254 | P-7065 | COV | Lynn Dr. | 12 | PVC | 260 | 32 | 0.43 out of 5 | $442 | 115,139 |
| Transmission Main | 5255 | P-7061 | COV | Lynn Dr. | 12 | PVC | 8 | 32 | 0.43 out of 5 | $442 | 3,659 |
| Transmission Main | 5256 | P-7061 | COV | Lynn Dr. | 12 | PVC | 268 | 32 | 0.43 out of 5 | $442 | 118,626 |
| Transmission Main | 7813 | P-7077 | COV | Lynn Dr. | 12 | PVC | 297 | 32 | 0.43 out of 5 | $442 | 131,401 |
| Transmission Main | 8674 | P-7062 | COV | Lynn Dr. | 12 | PVC | 198 | 32 | 0.43 out of 5 | $442 | 87,657 |
| Transmission Main | 11293 | P-7065 | COV | Lynn Dr. | 12 | PVC | 14 | 32 | 0.43 out of 5 | $442 | 6,311 |
| Transmission Main | 11491 | P-7062 | COV | Lynn Dr. | 12 | PVC | 12 | 32 | 0.43 out of 5 | $442 | 5,328 |
| Distribution Main | 402 | P-8008 | COV | Macarthur Blvd. | 8 | Asbestos Cement | 371 | 71 | 1.29 out of 5 | $442 | 163,893 |
| Distribution Main | 403 | P-8008 | COV | Macarthur Blvd. | 8 | Asbestos Cement | 822 | 71 | 1.29 out of 5 | $442 | 363,318 |
| Distribution Main | 406 | P-7985 | COV | Macarthur Blvd. | 8 | Asbestos Cement | 857 | 71 | 1.29 out of 5 | $442 | 378,954 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 414 | P-7997 | COV | Macarthur Blvd. | 8 | Asbestos Cement | 265 | 71 | 1.29 out of 5 | $442 | 117,249 |
| Distribution Main | 415 | P-8004 | COV | Macarthur Blvd. | 8 | Asbestos Cement | 137 | 71 | 1.29 out of 5 | $442 | 60,709 |
| Distribution Main | 416 | P-7998 | COV | Macarthur Blvd. | 8 | Asbestos Cement | 30 | 71 | 1.29 out of 5 | $442 | 13,477 |
| Distribution Main | 417 | P-7998 | COV | Macarthur Blvd. | 8 | Asbestos Cement | 123 | 71 | 1.29 out of 5 | $442 | 54,489 |
| Distribution Main | 2130 | | COV | Macarthur Blvd. | 8 | Asbestos Cement | 15 | 71 | 1.29 out of 5 | $442 | 6,738 |
| Distribution Main | 2133 | P-7993 | COV | Macarthur Blvd. | 8 | Asbestos Cement | 261 | 71 | 1.29 out of 5 | $442 | 115,421 |
| Distribution Main | 2134 | P-9053 | COV | Macarthur Blvd. | 8 | Asbestos Cement | 273 | 71 | 1.29 out of 5 | $442 | 120,610 |
| Distribution Main | 3018 | P-7986 | COV | Macarthur Blvd. | 8 | Asbestos Cement | 24 | 71 | 1.29 out of 5 | $442 | 10,697 |
| Distribution Main | 3019 | P-7986 | COV | Macarthur Blvd. | 8 | Asbestos Cement | 480 | 71 | 1.29 out of 5 | $442 | 212,006 |
| Distribution Main | 3043 | P-8008 | COV | Macarthur Blvd. | 8 | Asbestos Cement | 4 | 71 | 1.29 out of 5 | $442 | 1,725 |
| Distribution Main | 10064 | P-7997 | COV | Macarthur Blvd. | 8 | Asbestos Cement | 4 | 71 | 1.29 out of 5 | $442 | 1,600 |
| Distribution Main | 1910 | P-8958 | COV | Magnolia Ln. | 8 | Asbestos Cement | 5 | 51 | 1.14 out of 5 | $442 | 2,314 |
| Distribution Main | 2970 | P-8958 | COV | Magnolia Ln. | 8 | Asbestos Cement | 52 | 51 | 1.14 out of 5 | $442 | 23,026 |
| Distribution Main | 7706 | P-7018 | COV | Magnolia Ln. | 8 | Asbestos Cement | 612 | 51 | 1.14 out of 5 | $442 | 270,437 |
| Distribution Main | 7708 | P-7014 | COV | Magnolia Ln. | 8 | Asbestos Cement | 6 | 51 | 1.14 out of 5 | $442 | 2,796 |
| Distribution Main | 7711 | P-7016 | COV | Magnolia Ln. | 8 | Asbestos Cement | 1,011 | 51 | 1.14 out of 5 | $442 | 446,821 |
| Distribution Main | 7712 | P-7016 | COV | Magnolia Ln. | 8 | Asbestos Cement | 63 | 51 | 1.14 out of 5 | $442 | 27,683 |
| Distribution Main | 7713 | P-7021 | COV | Magnolia Ln. | 8 | Asbestos Cement | 408 | 51 | 1.14 out of 5 | $442 | 180,245 |
| Distribution Main | 7720 | P-7016 | COV | Magnolia Ln. | 8 | Asbestos Cement | 14 | 51 | 1.14 out of 5 | $442 | 6,338 |
| Distribution Main | 7721 | P-7014 | COV | Magnolia Ln. | 8 | Asbestos Cement | 193 | 51 | 1.14 out of 5 | $442 | 85,310 |
| Distribution Main | 7722 | P-7014 | COV | Magnolia Ln. | 8 | Asbestos Cement | 8 | 51 | 1.14 out of 5 | $442 | 3,501 |
| Distribution Main | 7728 | P-7020 | COV | Magnolia Ln. | 8 | Asbestos Cement | 165 | 51 | 1.14 out of 5 | $442 | 73,076 |
| Distribution Main | 7729 | P-7020 | COV | Magnolia Ln. | 8 | Asbestos Cement | 54 | 51 | 1.14 out of 5 | $442 | 23,725 |
| Distribution Main | 11402 | P-7018 | COV | Magnolia Ln. | 8 | Asbestos Cement | 3 | 51 | 1.14 out of 5 | $442 | 1,253 |
| Distribution Main | 11406 | P-7014 | COV | Magnolia Ln. | 8 | Asbestos Cement | 7 | 51 | 1.14 out of 5 | $442 | 3,135 |
| Distribution Main | 11408 | P-7020 | COV | Magnolia Ln. | 8 | Asbestos Cement | 28 | 51 | 1 out of 5 | $442 | 12,466 |
| Distribution Main | 8761 | P-8904 | COV | Main St | 8 | Ductile Iron | 43 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8762 | P-8904 | COV | Main St | 16 | Ductile Iron | 584 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8763 | P-8904 | COV | Main St | 16 | Ductile Iron | 109 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8764 | P-8904 | COV | Main St | 16 | Ductile Iron | 100 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9347 | | COV | Main St | 8 | Ductile Iron | 6 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10200 | | COV | Main St | 6 | Ductile Iron | 2 | 5 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11504 | P-8904 | COV | Main St | 8 | Ductile Iron | 14 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11505 | P-8904 | COV | Main St | 8 | Ductile Iron | 18 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 227 | P-8374 | COV | Main St. | 12 | Cast Iron | 11 | 133 | 1.86 out of 5 | $442 | 5,033 |
| Transmission Main | 234 | P-8373 | COV | Main St. | 12 | Cast Iron | 381 | 133 | 1.86 out of 5 | $442 | 168,402 |
| Transmission Main | 235 | P-8373 | COV | Main St. | 12 | Cast Iron | 411 | 133 | 1.86 out of 5 | $442 | 181,870 |
| Transmission Main | 239 | P-8375 | COV | Main St. | 12 | Cast Iron | 305 | 133 | 1.86 out of 5 | $442 | 134,964 |
| Transmission Main | 244 | P-8828 | COV | Main St. | 12 | Cast Iron | 132 | 133 | 1.86 out of 5 | $442 | 58,469 |
| Distribution Main | 579 | P-8912 | COV | Main St. | 8 | Cast Iron | 375 | 129 | 1.86 out of 5 | $442 | 165,713 |
| Distribution Main | 580 | | COV | Main St. | 8 | Cast Iron | 14 | 129 | 1.86 out of 5 | $442 | 5,976 |
| Transmission Main | 667 | P-8544 | COV | Main St. | 12 | Cast Iron | 91 | 133 | 1.86 out of 5 | $442 | 40,201 |
| Transmission Main | 789 | P-7848 | COV | Main St. | 16 | Cast Iron | 222 | 129 | 1.86 out of 5 | $442 | 98,315 |
| Transmission Main | 796 | P-7587 | COV | Main St. | 16 | Ductile Iron | 617 | 0 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 797 | P-7846 | COV | Main St. | 12 | Ductile Iron | 290 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 798 | P-7846 | COV | Main St. | 12 | Ductile Iron | 585 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1013 | | COV | Main St. | 6 | Unknown | 23 | UNK | 0.71 out of 5 | $442 | 10,132 |
| Transmission Main | 1053 | P-8544 | COV | Main St. | 12 | Cast Iron | 106 | 133 | 1.86 out of 5 | $442 | 46,934 |
| Transmission Main | 1054 | P-8544 | COV | Main St. | 12 | Cast Iron | 831 | 133 | 1.86 out of 5 | $442 | 367,232 |
| Distribution Main | 1055 | | COV | Main St. | 6 | Unknown | 38 | UNK | 0.71 out of 5 | $442 | 16,833 |
| Distribution Main | 1056 | | COV | Main St. | 6 | Unknown | 28 | UNK | 0.71 out of 5 | $442 | 12,580 |
| Transmission Main | 1188 | P-8132 | COV | Main St. | 12 | Cast Iron | 205 | 119 | 1.86 out of 5 | $442 | 90,703 |
| Transmission Main | 1189 | P-8132 | COV | Main St. | 12 | Cast Iron | 166 | 133 | 1.86 out of 5 | $442 | 73,446 |
| Transmission Main | 1312 | P-8544 | COV | Main St. | 12 | Cast Iron | 48 | 133 | 1.86 out of 5 | $442 | 21,085 |
| Transmission Main | 1313 | P-8544 | COV | Main St. | 12 | Cast Iron | 430 | 133 | 1.86 out of 5 | $442 | 190,123 |
| Transmission Main | 1314 | P-8544 | COV | Main St. | 12 | Cast Iron | 334 | 133 | 1.86 out of 5 | $442 | 147,602 |
| Transmission Main | 2288 | P-7258 | COV | Main St. | 12 | Ductile Iron | 651 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2810 | P-7260 | COV | Main St. | 12 | Ductile Iron | 144 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2811 | P-7260 | COV | Main St. | 12 | Ductile Iron | 536 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2821 | P-7256 | COV | Main St. | 8 | Cast Iron | 228 | 129 | 1.86 out of 5 | $442 | 100,908 |
| Transmission Main | 2823 | P-7260 | COV | Main St. | 16 | Ductile Iron | 16 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2990 | P-8912 | COV | Main St. | 8 | Cast Iron | 85 | 129 | 2.57 out of 5 | $442 | 37,724 |
| Transmission Main | 2999 | P-7844 | COV | Main St. | 12 | Ductile Iron | 72 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3000 | P-7844 | COV | Main St. | 12 | Ductile Iron | 281 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5054 | P-7258 | COV | Main St. | 16 | Cast Iron | 3 | 129 | 1.86 out of 5 | $442 | 1,246 |
| Transmission Main | 9686 | P-1251 | COV | Main St. | 12 | Ductile Iron | 15 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9687 | P-1251 | COV | Main St. | 12 | Ductile Iron | 6 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10127 | P-7255 | COV | Main St. | 8 | Cast Iron | 10 | 129 | 1.86 out of 5 | $442 | 4,321 |
| Transmission Main | 10596 | P-7848 | COV | Main St. | 16 | Ductile Iron | 13 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10684 | | COV | Main St. | 10 | Ductile Iron | 58 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10685 | | COV | Main St. | 3 | Cast Iron | 59 | UNK | 2.56 out of 5 | $442 | 26,245 |
| Distribution Main | 10689 | | COV | Main St. | 2 | Copper | 10 | UNK | 1.99 out of 5 | $442 | 4,531 |
| Distribution Main | 10690 | | COV | Main St. | 10 | Cast Iron | 27 | UNK | 1.14 out of 5 | $442 | 12,045 |
| Transmission Main | 10985 | P-8373 | COV | Main St. | 12 | Cast Iron | 7 | 133 | 1.86 out of 5 | $442 | 3,188 |
| Transmission Main | 11009 | P-7844 | COV | Main St. | 16 | Ductile Iron | 4 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11082 | P-8544 | COV | Main St. | 12 | Cast Iron | 80 | 133 | 1.86 out of 5 | $442 | 35,330 |
| Transmission Main | 11083 | P-8544 | COV | Main St. | 12 | Cast Iron | 15 | 133 | 1.86 out of 5 | $442 | 6,541 |
| Transmission Main | 11084 | P-8544 | COV | Main St. | 12 | Cast Iron | 30 | 133 | 1.86 out of 5 | $442 | 13,048 |
| Transmission Main | 11089 | P-7587 | COV | Main St. | 16 | Cast Iron | 20 | 129 | 1.86 out of 5 | $442 | 8,966 |
| Transmission Main | 11124 | P-8544 | COV | Main St. | 12 | Cast Iron | 7 | 133 | 1.86 out of 5 | $442 | 3,099 |
| Transmission Main | 11862 | P-8373 | COV | Main St. | 12 | Cast Iron | 186 | 133 | 1.86 out of 5 | $442 | 82,111 |
| Transmission Main | 11863 | P-8373 | COV | Main St. | 12 | Cast Iron | 32 | 133 | 1.86 out of 5 | $442 | 14,131 |
| Transmission Main | 12163 | P-8375 | COV | Main St. | 12 | Cast Iron | 100 | 133 | 1.86 out of 5 | $442 | 44,010 |
| Transmission Main | 12164 | P-8375 | COV | Main St. | 12 | Cast Iron | 16 | 133 | 1.86 out of 5 | $442 | 6,957 |
| Transmission Main | 8111 | P-6087 | COV | Main St. (Sci) | 24 | Ductile Iron | 1,191 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8112 | P-6087 | COV | Main St. (Sci) | 24 | Ductile Iron | 1,001 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8268 | P-6135 | COV | Main St. (Sci) | 24 | Ductile Iron | 88 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7844 | P-8910 | COV | Main Street | 8 | Ductile Iron | 154 | 0 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 7845 | P-8910 | COV | Main Street | 8 | Ductile Iron | 17 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7846 | P-8910 | COV | Main Street | 6 | Asbestos Cement | 5 | UNK | 1.56 out of 5 | $442 | 2,384 |
| Distribution Main | 7847 | P-8910 | COV | Main Street | 6 | Asbestos Cement | 537 | UNK | 1.56 out of 5 | $442 | 237,224 |
| Distribution Main | 7850 | P-8911 | COV | Main Street | 8 | Ductile Iron | 199 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7851 | P-8911 | COV | Main Street | 8 | Ductile Iron | 761 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9435 | P-8910 | COV | Main Street | 12 | Ductile Iron | 590 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9436 | P-7255 | COV | Main Street | 8 | Ductile Iron | 312 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 732 | P-7632 | COV | Majorie St. | 6 | Asbestos Cement | 242 | 57 | 1.85 out of 5 | $442 | 106,947 |
| Distribution Main | 745 | P-7633 | COV | Majorie St. | 6 | Asbestos Cement | 391 | 57 | 1.85 out of 5 | $442 | 172,946 |
| Distribution Main | 520 | P-7937 | COV | Manning Ct. | 6 | Asbestos Cement | 323 | 60 | 1.85 out of 5 | $442 | 142,845 |
| Distribution Main | 1140 | P-7937 | COV | Manning Ct. | 8 | Ductile Iron | 56 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1141 | P-7937 | COV | Manning Ct. | 8 | Ductile Iron | 5 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10449 | | COV | Manning Ct. | 0.75 | Copper | 62 | UNK | 1.99 out of 5 | $442 | 27,258 |
| Distribution Main | 10450 | | COV | Manning Ct. | 0.75 | Copper | 102 | UNK | 1.99 out of 5 | $442 | 44,938 |
| Distribution Main | 11071 | P-7937 | COV | Manning Ct. | 6 | Asbestos Cement | 6 | 60 | 1.85 out of 5 | $442 | 2,702 |
| Distribution Main | 1661 | P-7527 | COV | Manor Dr. | 6 | Asbestos Cement | 500 | 58 | 1.85 out of 5 | $442 | 220,823 |
| Distribution Main | 5332 | P-7527 | COV | Manor Dr. | 6 | Asbestos Cement | 80 | 58 | 1.85 out of 5 | $442 | 35,186 |
| Distribution Main | 5335 | P-8940 | COV | Manor Dr. | 6 | Asbestos Cement | 16 | 58 | 1.85 out of 5 | $442 | 6,882 |
| Distribution Main | 5336 | P-8940 | COV | Manor Dr. | 6 | Asbestos Cement | 274 | 58 | 1.85 out of 5 | $442 | 121,100 |
| Distribution Main | 7783 | P-7422 | COV | Maple Root Rd. | 6 | Asbestos Cement | 930 | 54 | 1.85 out of 5 | $442 | 411,005 |
| Distribution Main | 788 | P-7270 | COV | Maple St. | 8 | Asbestos Cement | 354 | 63 | 1.29 out of 5 | $442 | 156,284 |
| Distribution Main | 800 | P-7270 | COV | Maple St. | 8 | Asbestos Cement | 640 | 63 | 1.29 out of 5 | $442 | 282,897 |
| Distribution Main | 801 | P-7268 | COV | Maple St. | 8 | Asbestos Cement | 135 | 63 | 1.29 out of 5 | $442 | 59,659 |
| Distribution Main | 1261 | | COV | Maple St. | 8 | Asbestos Cement | 3 | 63 | 1.29 out of 5 | $442 | 1,325 |
| Distribution Main | 2816 | P-7268 | COV | Maple St. | 8 | Asbestos Cement | 935 | 63 | 1.29 out of 5 | $442 | 413,474 |
| Distribution Main | 2994 | | COV | Maple St. | 6 | Asbestos Cement | 346 | 63 | 2 out of 5 | $442 | 152,738 |
| Distribution Main | 3001 | | COV | Maple St. | 6 | Unknown | 8 | UNK | 0.71 out of 5 | $442 | 3,551 |
| Distribution Main | 396 | P-7854 | COV | Mapledale St. | 4 | Cast Iron | 310 | 129 | 3.29 out of 5 | $442 | 136,848 |
| Distribution Main | 397 | P-7855 | COV | Mapledale St. | 4 | Cast Iron | 13 | 129 | 3.29 out of 5 | $442 | 5,925 |
| Distribution Main | 398 | P-7855 | COV | Mapledale St. | 4 | Cast Iron | 406 | 129 | 3.29 out of 5 | $442 | 179,352 |
| Distribution Main | 1286 | P-7853 | COV | Mapledale St. | 6 | Cast Iron | 416 | 81 | 2.43 out of 5 | $442 | 183,840 |
| Distribution Main | 1287 | P-7853 | COV | Mapledale St. | 6 | Cast Iron | 20 | 81 | 2.43 out of 5 | $442 | 8,647 |
| Distribution Main | 9626 | P-7856 | COV | Mapledale St. | 4 | Cast Iron | 74 | 129 | 3.29 out of 5 | $442 | 32,525 |
| Distribution Main | 585 | P-7325 | COV | Maplewood Dr. | 8 | Asbestos Cement | 699 | 55 | 1.14 out of 5 | $442 | 309,048 |
| Distribution Main | 586 | P-7325 | COV | Maplewood Dr. | 8 | Asbestos Cement | 437 | 55 | 1.14 out of 5 | $442 | 193,182 |
| Distribution Main | 3067 | P-7885 | COV | Marie Dr. | 8 | Asbestos Cement | 64 | 50 | 1.14 out of 5 | $442 | 28,130 |
| Distribution Main | 3068 | P-7885 | COV | Marie Dr. | 8 | Asbestos Cement | 936 | 50 | 1.14 out of 5 | $442 | 413,535 |
| Distribution Main | 3069 | P-7884 | COV | Marie Dr. | 8 | Asbestos Cement | 532 | 50 | 1.14 out of 5 | $442 | 235,068 |
| Distribution Main | 10428 | P-7886 | COV | Marie Dr. | 8 | Ductile Iron | 45 | 50 | 0.29 out of 5 | $442 | 19,761 |
| Distribution Main | 1686 | P-7492 | COV | Marion Ave. | 6 | Asbestos Cement | 334 | 57 | 1.85 out of 5 | $442 | 147,783 |
| Distribution Main | 2619 | P-7492 | COV | Marion Ave. | 6 | Asbestos Cement | 11 | 57 | 1.85 out of 5 | $442 | 4,806 |
| Distribution Main | 7450 | P-7101 | COV | Marion Dr. | 8 | Asbestos Cement | 695 | 44 | 1.14 out of 5 | $442 | 307,199 |
| Distribution Main | 7451 | P-7101 | COV | Marion Dr. | 8 | Asbestos Cement | 53 | 44 | 1.14 out of 5 | $442 | 23,538 |
| Distribution Main | 7458 | P-7103 | COV | Marion Dr. | 8 | Asbestos Cement | 405 | 44 | 1.14 out of 5 | $442 | 178,951 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2402 | P-8058 | COV | Marshall Cir. | 6 | Asbestos Cement | 24 | 71 | 2 out of 5 | $442 | 10,640 |
| Distribution Main | 2404 | P-8058 | COV | Marshall Cir. | 6 | Asbestos Cement | 9 | 71 | 2 out of 5 | $442 | 4,072 |
| Distribution Main | 2406 | P-8064 | COV | Marshall Cir. | 6 | Ductile Iron | 473 | 27 | 0.85 out of 5 | $442 | 209,214 |
| Distribution Main | 2918 | P-8063 | COV | Marshall Cir. | 6 | Ductile Iron | 154 | 27 | 0.85 out of 5 | $442 | 67,893 |
| Distribution Main | 2926 | P-8058 | COV | Marshall Cir. | 6 | Asbestos Cement | 203 | 71 | 2 out of 5 | $442 | 89,522 |
| Distribution Main | 2927 | P-8058 | COV | Marshall Cir. | 6 | Asbestos Cement | 226 | 71 | 2 out of 5 | $442 | 99,872 |
| Distribution Main | 10066 | P-8063 | COV | Marshall Cir. | 6 | Ductile Iron | 79 | 27 | 0.85 out of 5 | $442 | 34,968 |
| Distribution Main | 10067 | P-8064 | COV | Marshall Cir. | 6 | Ductile Iron | 23 | 27 | 0.85 out of 5 | $442 | 10,161 |
| Distribution Main | 10068 | P-8064 | COV | Marshall Cir. | 6 | Ductile Iron | 58 | 27 | 0.85 out of 5 | $442 | 25,787 |
| Distribution Main | 4062 | P-8150 | COV | Martin St. | 6 | Asbestos Cement | 130 | 59 | 1.85 out of 5 | $442 | 57,569 |
| Distribution Main | 4954 | P-8182 | COV | Martin St. | 6 | Asbestos Cement | 602 | 59 | 1.85 out of 5 | $442 | 266,141 |
| Distribution Main | 5935 | P-8336 | COV | Mashie Cir. | 6 | Ductile Iron | 11 | 30 | 0.85 out of 5 | $442 | 4,663 |
| Distribution Main | 5936 | P-8336 | COV | Mashie Cir. | 6 | Ductile Iron | 221 | 30 | 0.85 out of 5 | $442 | 97,519 |
| Distribution Main | 3148 | P-7825 | COV | Matteson St. | 6 | Asbestos Cement | 407 | 52 | 1.85 out of 5 | $442 | 179,984 |
| Distribution Main | 3149 | P-7825 | COV | Matteson St. | 6 | Asbestos Cement | 29 | 52 | 1.85 out of 5 | $442 | 12,799 |
| Distribution Main | 11786 | P-7825 | COV | Matteson St. | 6 | Asbestos Cement | 271 | 52 | 1.85 out of 5 | $442 | 119,641 |
| Distribution Main | 2760 | P-7481 | COV | Maude Ave. | 6 | Asbestos Cement | 630 | 61 | 2 out of 5 | $442 | 278,300 |
| Distribution Main | 2761 | P-7481 | COV | Maude Ave. | 6 | Asbestos Cement | 490 | 61 | 2 out of 5 | $442 | 216,421 |
| Distribution Main | 2774 | P-8517 | COV | Maude Ave. | 6 | Asbestos Cement | 8 | 61 | 2 out of 5 | $442 | 3,512 |
| Distribution Main | 6456 | P-7481 | COV | Maude Ave. | 6 | Asbestos Cement | 16 | 61 | 2 out of 5 | $442 | 7,175 |
| Distribution Main | 6457 | P-7481 | COV | Maude Ave. | 6 | Asbestos Cement | 10 | 61 | 2 out of 5 | $442 | 4,413 |
| Distribution Main | 8339 | | COV | Mead St | 6 | Ductile Iron | 3 | 14 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8340 | | COV | Mead St | 8 | Ductile Iron | 61 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8341 | P-8717 | COV | Mead St | 8 | Ductile Iron | 16 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8342 | P-8717 | COV | Mead St | 8 | Ductile Iron | 21 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10454 | | COV | Mead St | 6 | Steel | 3 | 14 | 1.28 out of 5 | N/A | $0 |
| Distribution Main | 10387 | P-7724 | COV | Mead St. | 8 | Ductile Iron | 259 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10388 | P-7724 | COV | Mead St. | 8 | Ductile Iron | 46 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11655 | P-7726 | COV | Mead St. | 8 | Ductile Iron | 209 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3070 | P-7287 | COV | Meadow Ln. | 6 | Asbestos Cement | 380 | 43 | 1.85 out of 5 | $442 | 167,994 |
| Distribution Main | 565 | | COV | Meadowbrook Farm Road | 8 | Ductile Iron | 20 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 1500 | P-7869 | COV | Meeting St. | 6 | Cast Iron | 8 | 81 | 2.43 out of 5 | $442 | 3,700 |
| Distribution Main | 1501 | P-7869 | COV | Meeting St. | 6 | Cast Iron | 396 | 81 | 2.43 out of 5 | $442 | 175,232 |
| Distribution Main | 1502 | P-7872 | COV | Meeting St. | 2 | Galvanized Iron | 142 | 81 | 3.43 out of 5 | $442 | 62,728 |
| Distribution Main | 1949 | P-7868 | COV | Meeting St. | 6 | Cast Iron | 235 | 81 | 2.43 out of 5 | $442 | 103,694 |
| Distribution Main | 11132 | P-7869 | COV | Meeting St. | 6 | Cast Iron | 19 | 81 | 2.43 out of 5 | $442 | 8,435 |
| Distribution Main | 11780 | P-7869 | COV | Meeting St. | 6 | Cast Iron | 117 | 81 | 2.43 out of 5 | $442 | 51,724 |
| Distribution Main | 194 | P-7291 | COV | Meredith Dr. | 6 | Asbestos Cement | 395 | 60 | 1.85 out of 5 | $442 | 174,616 |
| Distribution Main | 195 | P-7292 | COV | Meredith Dr. | 6 | Asbestos Cement | 14 | 60 | 1.85 out of 5 | $442 | 6,226 |
| Distribution Main | 196 | P-7292 | COV | Meredith Dr. | 6 | Asbestos Cement | 204 | 60 | 1.85 out of 5 | $442 | 90,097 |
| Distribution Main | 1954 | P-7286 | COV | Meredith Dr. | 6 | Asbestos Cement | 282 | 60 | 1.85 out of 5 | $442 | 124,707 |
| Distribution Main | 1955 | P-7286 | COV | Meredith Dr. | 6 | Asbestos Cement | 13 | 60 | 1.85 out of 5 | $442 | 5,939 |
| Distribution Main | 3085 | P-7282 | COV | Meredith Dr. | 6 | Asbestos Cement | 359 | 60 | 1.85 out of 5 | $442 | 158,797 |
| Distribution Main | 3086 | | COV | Meredith Dr. | 6 | Asbestos Cement | 85 | 60 | 1.85 out of 5 | $442 | 37,436 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 11027 | P-7292 | COV | Meredith Dr. | 6 | Asbestos Cement | 4 | 60 | 1.85 out of 5 | $442 | 1,621 |
| Distribution Main | 7866 | P-7200 | COV | Metro Dr. | 8 | Asbestos Cement | 79 | 44 | 1.14 out of 5 | $442 | 34,783 |
| Distribution Main | 7867 | P-7200 | COV | Metro Dr. | 8 | Asbestos Cement | 569 | 44 | 1.14 out of 5 | $442 | 251,629 |
| Distribution Main | 7949 | P-7204 | COV | Metro Dr. | 8 | Asbestos Cement | 386 | 44 | 1.14 out of 5 | $442 | 170,695 |
| Distribution Main | 7953 | P-7207 | COV | Metro Dr. | 8 | Asbestos Cement | 268 | 44 | 1.14 out of 5 | $442 | 118,387 |
| Distribution Main | 7954 | P-7207 | COV | Metro Dr. | 8 | Asbestos Cement | 316 | 44 | 1.14 out of 5 | $442 | 139,826 |
| Distribution Main | 9969 | O-7201 | COV | Metro Dr. | 8 | Asbestos Cement | 381 | 44 | 1.14 out of 5 | $442 | 168,260 |
| Distribution Main | 936 | P-9061 | COV | Michael Court | 1 | Copper | 241 | UNK | 1.99 out of 5 | $442 | 106,318 |
| Distribution Main | 8391 | P-8832 | COV | Mill St | 8 | Ductile Iron | 25 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8459 | P-8833 | COV | Mill St | 6 | Ductile Iron | 13 | 10 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 1 | P-8263 | COV | Mishnock Rd | 12 | Ductile Iron | 11 | 30 | 0.14 out of 5 | $442 | 5,072 |
| Distribution Main | 2 | | COV | Mishnock Rd | 8 | Ductile Iron | 22 | 30 | 0.14 out of 5 | $442 | 9,549 |
| Distribution Main | 3 | | COV | Mishnock Rd | 8 | Ductile Iron | 43 | 30 | 0.14 out of 5 | $442 | 18,857 |
| Transmission Main | 4 | P-8263 | COV | Mishnock Rd | 12 | Ductile Iron | 11 | 30 | 0.14 out of 5 | $442 | 4,875 |
| Transmission Main | 1743 | P-7456 | COV | Mishnock Rd. | 12 | Ductile Iron | 131 | 30 | 0.14 out of 5 | $442 | 57,713 |
| Transmission Main | 1744 | P-7456 | COV | Mishnock Rd. | 12 | Ductile Iron | 581 | 30 | 0.14 out of 5 | $442 | 256,825 |
| Transmission Main | 1745 | P-8263 | COV | Mishnock Rd. | 12 | Ductile Iron | 310 | 30 | 0.14 out of 5 | $442 | 137,155 |
| Transmission Main | 4813 | P-3005 | COV | Mishnock Rd. | 12 | Ductile Iron | 343 | 30 | 0.14 out of 5 | $442 | 151,450 |
| Transmission Main | 4814 | P-3005 | COV | Mishnock Rd. | 12 | Ductile Iron | 585 | 30 | 0.14 out of 5 | $442 | 258,521 |
| Transmission Main | 4918 | P-3005 | COV | Mishnock Rd. | 12 | Ductile Iron | 300 | 30 | 0.14 out of 5 | $442 | 132,806 |
| Transmission Main | 5351 | | COV | Mishnock Rd. | 12 | Ductile Iron | 51 | 30 | 0.14 out of 5 | $442 | 22,517 |
| Transmission Main | 5352 | | COV | Mishnock Rd. | 12 | Ductile Iron | 86 | 30 | 0.14 out of 5 | $442 | 37,837 |
| Transmission Main | 10105 | | COV | Mishnock Rd. | 12 | Ductile Iron | 78 | 30 | 0.14 out of 5 | $442 | 34,635 |
| Transmission Main | 11869 | P-7456 | COV | Mishnock Rd. | 12 | Ductile Iron | 57 | 30 | 0.14 out of 5 | $442 | 25,179 |
| Transmission Main | 496 | | COV | Mishnock Wells | 12 | Ductile Iron | 699 | 30 | 0.14 out of 5 | $442 | 308,739 |
| Transmission Main | 11065 | | COV | Mishnock Wells | 12 | Ductile Iron | 51 | 30 | 0.14 out of 5 | $442 | 22,553 |
| Distribution Main | 8357 | P-7735 | COV | Mohawk St | 8 | Ductile Iron | 453 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8358 | P-7735 | COV | Mohawk St | 8 | Ductile Iron | 443 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8360 | P-8765 | COV | Mohawk St | 8 | Ductile Iron | 52 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8361 | P-8765 | COV | Mohawk St | 8 | Ductile Iron | 145 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8368 | P-8767 | COV | Mohawk St | 8 | Ductile Iron | 188 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8369 | P-8767 | COV | Mohawk St | 8 | Ductile Iron | 276 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9511 | P-9014 | COV | Mohawk St | 8 | Ductile Iron | 92 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9942 | P-7737 | COV | Mohawk St | 8 | Ductile Iron | 35 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9944 | P-8766 | COV | Mohawk St | 8 | Ductile Iron | 25 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9945 | P-8766 | COV | Mohawk St | 8 | Ductile Iron | 191 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8352 | P-7727 | COV | Mohawk St. | 8 | Ductile Iron | 705 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9950 | | COV | Monroe Dr | 8 | Ductile Iron | 15 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6451 | P-7166 | COV | Monroe Dr. | 8 | Asbestos Cement | 500 | 42 | 1.14 out of 5 | $442 | 220,891 |
| Distribution Main | 6461 | P-7170 | COV | Monroe Dr. | 8 | Ductile Iron | 20 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6462 | P-7170 | COV | Monroe Dr. | 8 | Ductile Iron | 569 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7436 | P-7167 | COV | Monroe Dr. | 8 | Asbestos Cement | 416 | 42 | 1.14 out of 5 | $442 | 184,010 |
| Distribution Main | 7437 | P-7167 | COV | Monroe Dr. | 8 | Asbestos Cement | 77 | 42 | 1.14 out of 5 | $442 | 33,861 |
| Distribution Main | 7802 | P-7168 | COV | Monroe Dr. | 8 | Asbestos Cement | 41 | 34 | 1 out of 5 | $442 | 18,142 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 7803 | P-7168 | COV | Monroe Dr. | 8 | Asbestos Cement | 785 | 34 | 1 out of 5 | $442 | 346,940 |
| Distribution Main | 7804 | P-7169 | COV | Monroe Dr. | 8 | Ductile Iron | 338 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9504 | P-7171 | COV | Monroe Dr. | 8 | Ductile Iron | 78 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9505 | P-7171 | COV | Monroe Dr. | 8 | Ductile Iron | 344 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11335 | P-7166 | COV | Monroe Dr. | 8 | Asbestos Cement | 11 | 42 | 1.14 out of 5 | $442 | 4,855 |
| Distribution Main | 11867 | P-7168 | COV | Monroe Dr. | 8 | Asbestos Cement | 46 | 42 | 1.14 out of 5 | $442 | 20,202 |
| Distribution Main | 478 | P-7575 | COV | Montana Ave. | 3 | Galvanized Iron | 233 | 86 | 3.43 out of 5 | $442 | 102,986 |
| Distribution Main | 1119 | P-7574 | COV | Montana Ave. | 3 | Galvanized Iron | 377 | 86 | 3.43 out of 5 | $442 | 166,852 |
| Distribution Main | 1755 | | COV | Montana Ave. | 3 | Galvanized Iron | 13 | 86 | 3.43 out of 5 | $442 | 5,586 |
| Distribution Main | 1756 | P-7577 | COV | Montana Ave. | 3 | Galvanized Iron | 226 | 86 | 3.43 out of 5 | $442 | 100,046 |
| Distribution Main | 2635 | P-7576 | COV | Montana Ave. | 3 | Galvanized Iron | 236 | 86 | 3.43 out of 5 | $442 | 104,348 |
| Distribution Main | 2786 | | COV | Montana Ave. | 3 | Galvanized Iron | 6 | 86 | 3.43 out of 5 | $442 | 2,555 |
| Distribution Main | 2681 | P-7979 | COV | Morin Ave. | 1 | Copper | 417 | 54 | 2.28 out of 5 | $442 | 184,230 |
| Distribution Main | 6170 | P-8384 | COV | Morningside Dr. | 8 | Asbestos Cement | 19 | 47 | 1.14 out of 5 | $442 | 8,396 |
| Distribution Main | 1853 | P-7616 | COV | Morris St. | 6 | Asbestos Cement | 195 | 60 | 1.85 out of 5 | $442 | 86,370 |
| Distribution Main | 2625 | P-7613 | COV | Morris St. | 6 | Asbestos Cement | 90 | 60 | 1.85 out of 5 | $442 | 39,739 |
| Distribution Main | 2626 | P-7613 | COV | Morris St. | 6 | Asbestos Cement | 283 | 60 | 1.85 out of 5 | $442 | 125,211 |
| Distribution Main | 819 | P-7346 | COV | Moss Ln. | 8 | Ductile Iron | 932 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 8303 | P-8260 | COV | Mountain Laurel Dr | 8 | Ductile Iron | 633 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8307 | P-8413 | COV | Mountain Laurel Dr | 8 | Ductile Iron | 237 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8308 | P-8413 | COV | Mountain Laurel Dr | 8 | Ductile Iron | 216 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8309 | P-8413 | COV | Mountain Laurel Dr | 8 | Ductile Iron | 129 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9615 | P-8415 | COV | Mountain Laurel Dr | 8 | Ductile Iron | 75 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1111 | P-7920 | COV | Mulberry Ct. | 8 | PVC | 253 | 39 | 0.43 out of 5 | $442 | 111,949 |
| Distribution Main | 230 | P-8089 | COV | Mumford St. | 8 | Ductile Iron | 245 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 231 | P-8089 | COV | Mumford St. | 8 | Ductile Iron | 16 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 543 | P-8086 | COV | Mumford St. | 8 | Ductile Iron | 195 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 544 | P-8086 | COV | Mumford St. | 8 | Ductile Iron | 258 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1766 | P-8086 | COV | Mumford St. | 8 | Ductile Iron | 185 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3490 | P-8084 | COV | Mumford St. | 8 | Ductile Iron | 359 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3491 | P-8084 | COV | Mumford St. | 8 | Ductile Iron | 33 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3725 | P-8837 | COV | Mumford St. | 8 | Ductile Iron | 37 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10962 | P-8085 | COV | Mumford St. | 8 | Ductile Iron | 362 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11859 | P-8089 | COV | Mumford St. | 8 | Ductile Iron | 228 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3077 | P-9035 | COV | Murray St | 6 | Asbestos Cement | 484 | 50 | 1.85 out of 5 | $442 | 213,982 |
| Distribution Main | 547 | P-7684 | COV | Myra Rd. | 6 | Asbestos Cement | 158 | 56 | 1.85 out of 5 | $442 | 69,712 |
| Distribution Main | 548 | P-7679 | COV | Myra Rd. | 6 | Asbestos Cement | 241 | 56 | 1.85 out of 5 | $442 | 106,668 |
| Distribution Main | 555 | P-7683 | COV | Myra Rd. | 6 | Asbestos Cement | 608 | 56 | 1.85 out of 5 | $442 | 268,810 |
| Distribution Main | 183 | P-7954 | COV | Nancy Ct. | 6 | Asbestos Cement | 393 | 56 | 1.85 out of 5 | $442 | 173,560 |
| Distribution Main | 746 | P-7636 | COV | Nancy St. | 6 | Asbestos Cement | 309 | 59 | 1.85 out of 5 | $442 | 136,576 |
| Distribution Main | 8274 | P-7954 | COV | Nancy St. | 8 | Ductile Iron | 23 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8275 | P-7954 | COV | Nancy St. | 8 | Ductile Iron | 29 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 31 | P-8317 | COV | New London Tpk | 12 | Ductile Iron | 407 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 32 | P-8316 | COV | New London Tpk | 12 | PVC | 143 | 31 | 0.43 out of 5 | $442 | 62,996 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 62 | | COV | New London Tpk | 12 | Unknown | 14 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 63 | | COV | New London Tpk | 12 | Unknown | 2 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 269 | P-8170 | COV | New London Tpk. | 16 | Ductile Iron | 24 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 270 | P-8170 | COV | New London Tpk. | 16 | Ductile Iron | 4 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 271 | P-8170 | COV | New London Tpk. | 16 | Ductile Iron | 3 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 272 | P-8170 | COV | New London Tpk. | 16 | Ductile Iron | 7 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1162 | P-8317 | COV | New London Tpk. | 8 | Ductile Iron | 31 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1163 | P-8317 | COV | New London Tpk. | 12 | Ductile Iron | 13 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1627 | P-8170 | COV | New London Tpk. | 8 | Asbestos Cement | 8 | 50 | 1.14 out of 5 | $442 | 3,546 |
| Transmission Main | 1630 | P-8175 | COV | New London Tpk. | 16 | Ductile Iron | 482 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2184 | P-8170 | COV | New London Tpk. | 8 | Asbestos Cement | 4 | 50 | 1.14 out of 5 | $442 | 1,662 |
| Distribution Main | 2185 | P-8169 | COV | New London Tpk. | 8 | Asbestos Cement | 414 | 50 | 1.14 out of 5 | $442 | 182,989 |
| Transmission Main | 2187 | P-8316 | COV | New London Tpk. | 12 | Asbestos Cement | 188 | 59 | 1.14 out of 5 | $442 | 82,884 |
| Transmission Main | 2188 | P-8316 | COV | New London Tpk. | 12 | Asbestos Cement | 48 | 59 | 1.14 out of 5 | $442 | 21,267 |
| Transmission Main | 2878 | P-8136 | COV | New London Tpk. | 12 | Asbestos Cement | 43 | 59 | 1.14 out of 5 | $442 | 18,881 |
| Transmission Main | 2879 | P-8136 | COV | New London Tpk. | 12 | Asbestos Cement | 266 | 59 | 1.14 out of 5 | $442 | 117,394 |
| Transmission Main | 2882 | P-8162 | COV | New London Tpk. | 12 | Asbestos Cement | 375 | 59 | 1.14 out of 5 | $442 | 165,846 |
| Distribution Main | 3145 | P-8169 | COV | New London Tpk. | 8 | Asbestos Cement | 4 | 50 | 1.14 out of 5 | $442 | 1,662 |
| Transmission Main | 4063 | P-8137 | COV | New London Tpk. | 12 | Asbestos Cement | 257 | 59 | 1.14 out of 5 | $442 | 113,726 |
| Transmission Main | 4064 | P-8145 | COV | New London Tpk. | 12 | Asbestos Cement | 274 | 59 | 1.14 out of 5 | $442 | 121,324 |
| Transmission Main | 4065 | P-8151 | COV | New London Tpk. | 12 | Asbestos Cement | 126 | 59 | 1.85 out of 5 | $442 | 55,619 |
| Transmission Main | 4066 | P-8168 | COV | New London Tpk. | 12 | Asbestos Cement | 137 | 59 | 1.14 out of 5 | $442 | 60,607 |
| Transmission Main | 4067 | P-8168 | COV | New London Tpk. | 12 | Asbestos Cement | 15 | 59 | 1.14 out of 5 | $442 | 6,665 |
| Transmission Main | 4068 | P-8166 | COV | New London Tpk. | 12 | Asbestos Cement | 423 | 59 | 1.14 out of 5 | $442 | 186,919 |
| Transmission Main | 4069 | P-8166 | COV | New London Tpk. | 12 | Asbestos Cement | 353 | 59 | 1.14 out of 5 | $442 | 156,194 |
| Transmission Main | 9580 | P-8316 | COV | New London Tpk. | 12 | PVC | 6 | 31 | 0.43 out of 5 | $442 | 2,638 |
| Distribution Main | 9581 | P-8317 | COV | New London Tpk. | 8 | Asbestos Cement | 117 | 50 | 1.14 out of 5 | $442 | 51,530 |
| Transmission Main | 9582 | P-8318 | COV | New London Tpk. | 12 | Ductile Iron | 401 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9613 | | COV | New London Tpke | 8 | Ductile Iron | 3 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1669 | P-3134 | COV | New London Turnpike | 16 | Ductile Iron | 5 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1670 | P-3134 | COV | New London Turnpike | 16 | Ductile Iron | 123 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2824 | P-8913 | COV | Newell Court | 2 | Copper | 392 | 85 | 2.57 out of 5 | $442 | 173,264 |
| Distribution Main | 3012 | P-8341 | COV | Niblick Cir. | 6 | Ductile Iron | 206 | 30 | 0.85 out of 5 | $442 | 91,012 |
| Distribution Main | 3013 | P-8341 | COV | Niblick Cir. | 6 | Ductile Iron | 525 | 30 | 0.85 out of 5 | $442 | 232,119 |
| Distribution Main | 5922 | P-3001 | COV | Nichole Ln. | 8 | Asbestos Cement | 397 | 38 | 1 out of 5 | $442 | 175,534 |
| Distribution Main | 7269 | P-3002 | COV | Nichole Ln. | 8 | Asbestos Cement | 363 | 38 | 1 out of 5 | $442 | 160,653 |
| Distribution Main | 7653 | P-3001 | COV | Nichole Ln. | 8 | Asbestos Cement | 50 | 38 | 1 out of 5 | $442 | 22,131 |
| Distribution Main | 7654 | P-3001 | COV | Nichole Ln. | 8 | Asbestos Cement | 348 | 38 | 1 out of 5 | $442 | 153,610 |
| Distribution Main | 11369 | P-3002 | COV | Nichole Ln. | 8 | Asbestos Cement | 164 | 38 | 1 out of 5 | $442 | 72,541 |
| Distribution Main | 41 | P-7472 | COV | Noella Ave | 6 | Asbestos Cement | 746 | 57 | 1.85 out of 5 | $442 | 329,544 |
| Distribution Main | 6448 | P-7460 | COV | Noella Ave. | 6 | Asbestos Cement | 225 | 59 | 1.85 out of 5 | $442 | 99,568 |
| Distribution Main | 7441 | P-7465 | COV | Noella Ave. | 6 | Asbestos Cement | 331 | 57 | 1.85 out of 5 | $442 | 146,500 |
| Distribution Main | 7805 | P-7462 | COV | Noella Ave. | 6 | Asbestos Cement | 143 | 59 | 1.85 out of 5 | $442 | 63,132 |
| Distribution Main | 9313 | | COV | Nooseneck Hill Rd | 2 | Unknown | 71 | 11 | 1.42 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 10458 | | COV | Nooseneck Hill Rd | 12 | Ductile Iron | 18 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 10528 | | COV | Nooseneck Hill Rd | 12 | HDPE | 59 | UNK | 0.28 out of 5 | $442 | 26,165 |
| Transmission Main | 10529 | | COV | Nooseneck Hill Rd | 12 | HDPE | 86 | UNK | 0.28 out of 5 | $442 | 37,820 |
| Transmission Main | 10705 | | COV | Nooseneck Hill Rd | 12 | Ductile Iron | 24 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 558 | P-8760 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 624 | 54 | 1.14 out of 5 | $442 | 275,596 |
| Transmission Main | 559 | P-8215 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 523 | 54 | 1.14 out of 5 | $442 | 231,199 |
| Transmission Main | 560 | P-8215 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 223 | 54 | 1.14 out of 5 | $442 | 98,707 |
| Transmission Main | 1248 | P-8759 | COV | Nooseneck Hill Rd. | 12 | Ductile Iron | 632 | 30 | 0.14 out of 5 | $442 | 279,404 |
| Transmission Main | 1249 | P-8759 | COV | Nooseneck Hill Rd. | 12 | Ductile Iron | 30 | 30 | 0.14 out of 5 | $442 | 13,249 |
| Transmission Main | 1909 | P-7952 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 14 | 54 | 1.14 out of 5 | $442 | 6,173 |
| Transmission Main | 2986 | P-7952 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 10 | 54 | 1.14 out of 5 | $442 | 4,209 |
| Transmission Main | 4397 | P-7419 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 17 | 54 | 1.14 out of 5 | $442 | 7,556 |
| Transmission Main | 4398 | P-7419 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 620 | 54 | 1.14 out of 5 | $442 | 274,203 |
| Transmission Main | 4792 | P-7159 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 7 | 54 | 1.14 out of 5 | $442 | 2,903 |
| Transmission Main | 4793 | P-8215 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 139 | 54 | 1.14 out of 5 | $442 | 61,395 |
| Transmission Main | 4794 | P-7952 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 194 | 54 | 1.14 out of 5 | $442 | 85,883 |
| Transmission Main | 4795 | P-7952 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 287 | 54 | 1.14 out of 5 | $442 | 126,646 |
| Transmission Main | 5306 | P-7952 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 245 | 54 | 1.14 out of 5 | $442 | 108,206 |
| Distribution Main | 5920 | | COV | Nooseneck Hill Rd. | 8 | Unknown | 20 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 5921 | P-7417 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 49 | 54 | 1.14 out of 5 | $442 | 21,690 |
| Transmission Main | 6626 | | COV | Nooseneck Hill Rd. | 12 | Ductile Iron | 10 | 30 | 0.14 out of 5 | $442 | 4,346 |
| Transmission Main | 6627 | P-8755 | COV | Nooseneck Hill Rd. | 12 | Ductile Iron | 1,144 | 30 | 0.14 out of 5 | $442 | 505,813 |
| Transmission Main | 6629 | P-8755 | COV | Nooseneck Hill Rd. | 12 | Ductile Iron | 1,524 | 30 | 0.14 out of 5 | $442 | 673,710 |
| Transmission Main | 7147 | P-8215 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 873 | 54 | 1.14 out of 5 | $442 | 385,683 |
| Transmission Main | 7148 | P-8215 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 46 | 54 | 1.14 out of 5 | $442 | 20,450 |
| Transmission Main | 7149 | P-8526 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 225 | 54 | 1.14 out of 5 | $442 | 99,577 |
| Transmission Main | 7150 | P-8226 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 527 | 54 | 1.14 out of 5 | $442 | 232,955 |
| Transmission Main | 7151 | P-8226 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 78 | 54 | 1.14 out of 5 | $442 | 34,274 |
| Transmission Main | 7152 | P-8751 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 1,477 | 54 | 1.14 out of 5 | $442 | 652,922 |
| Transmission Main | 7153 | P-8358 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 381 | 54 | 1.14 out of 5 | $442 | 168,599 |
| Distribution Main | 7154 | P-8520 | COV | Nooseneck Hill Rd. | 8 | Unknown | 61 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 7194 | P-7426 | COV | Nooseneck Hill Rd. | 10 | Asbestos Cement | 373 | 54 | 1.14 out of 5 | $442 | 164,788 |
| Transmission Main | 7206 | P-8750 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 187 | 54 | 1.14 out of 5 | $442 | 82,575 |
| Transmission Main | 7258 | P-8755 | COV | Nooseneck Hill Rd. | 12 | Ductile Iron | 408 | 30 | 0.14 out of 5 | $442 | 180,267 |
| Transmission Main | 7259 | | COV | Nooseneck Hill Rd. | 12 | Ductile Iron | 9 | 30 | 0.14 out of 5 | $442 | 4,123 |
| Transmission Main | 7260 | | COV | Nooseneck Hill Rd. | 12 | Ductile Iron | 40 | 30 | 0.14 out of 5 | $442 | 17,524 |
| Transmission Main | 7510 | P-8750 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 1,020 | 54 | 1.14 out of 5 | $442 | 451,044 |
| Transmission Main | 7511 | P-8750 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 534 | 54 | 1.14 out of 5 | $442 | 236,193 |
| Distribution Main | 7544 | P-8954 | COV | Nooseneck Hill Rd. | 8 | Unknown | 19 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 7545 | P-8953 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 3 | 54 | 1.14 out of 5 | $442 | 1,529 |
| Transmission Main | 7546 | P-8953 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 27 | 54 | 1.14 out of 5 | $442 | 11,976 |
| Distribution Main | 7548 | | COV | Nooseneck Hill Rd. | 8 | Unknown | 18 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 7549 | P-8226 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 140 | 54 | 1.14 out of 5 | $442 | 62,030 |
| Transmission Main | 7550 | P-3062 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 27 | 54 | 1.14 out of 5 | $442 | 11,809 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 7551 | P-3062 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 744 | 54 | 1.14 out of 5 | $442 | 328,705 |
| Distribution Main | 7685 | | COV | Nooseneck Hill Rd. | 8 | Unknown | 4 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 7686 | | COV | Nooseneck Hill Rd. | 8 | Unknown | 4 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 7687 | P-8954 | COV | Nooseneck Hill Rd. | 8 | Unknown | 7 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 7688 | P-8226 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 86 | 54 | 1.14 out of 5 | $442 | 38,044 |
| Transmission Main | 7800 | P-7419 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 33 | 54 | 1.14 out of 5 | $442 | 14,473 |
| Distribution Main | 9123 | | COV | Nooseneck Hill Rd. | 8 | Ductile Iron | 12 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 9124 | | COV | Nooseneck Hill Rd. | 8 | Ductile Iron | 3 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 10230 | P-3038 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 21 | 54 | 1.14 out of 5 | $442 | 9,483 |
| Transmission Main | 11066 | P-7417 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 7 | 54 | 1.14 out of 5 | $442 | 3,265 |
| Transmission Main | 11069 | P-8755 | COV | Nooseneck Hill Rd. | 12 | Ductile Iron | 48 | 30 | 0.14 out of 5 | $442 | 21,307 |
| Transmission Main | 11346 | P-8755 | COV | Nooseneck Hill Rd. | 12 | Ductile Iron | 71 | 30 | 0.14 out of 5 | $442 | 31,527 |
| Transmission Main | 11387 | P-3062 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 143 | 54 | 1.14 out of 5 | $442 | 63,300 |
| Transmission Main | 11793 | P-8215 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 33 | 54 | 1.14 out of 5 | $442 | 14,385 |
| Transmission Main | 11794 | P-8226 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 125 | 54 | 1.14 out of 5 | $442 | 55,104 |
| Transmission Main | 11971 | P-8750 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 154 | 54 | 1.14 out of 5 | $442 | 68,088 |
| Transmission Main | 12193 | P-3062 | COV | Nooseneck Hill Rd. | 12 | Asbestos Cement | 637 | 54 | 1.14 out of 5 | $442 | 281,383 |
| Transmission Main | 562 | | COV | Nooseneck Hill Road | 12 | Unknown | 78 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 563 | | COV | Nooseneck Hill Road | 12 | Unknown | 3 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 3440 | | COV | Nooseneck Hill Road | 16 | Ductile Iron | 5 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 3441 | | COV | Nooseneck Hill Road | 16 | Ductile Iron | 8 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 3442 | | COV | Nooseneck Hill Road | 16 | Ductile Iron | 5 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 3443 | P-8959 | COV | Nooseneck Hill Road | 16 | Ductile Iron | 4 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 3444 | P-8959 | COV | Nooseneck Hill Road | 16 | Ductile Iron | 9 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 3445 | P-8959 | COV | Nooseneck Hill Road | 16 | Ductile Iron | 5 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 3446 | P-8959 | COV | Nooseneck Hill Road | 16 | Ductile Iron | 13 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 3447 | P-8959 | COV | Nooseneck Hill Road | 16 | Ductile Iron | 455 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 5313 | P-8959 | COV | Nooseneck Hill Road | 16 | Ductile Iron | 18 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 718 | P-7709 | COV | North Glen Dr. | 6 | Asbestos Cement | 633 | 60 | 1.85 out of 5 | $442 | 279,958 |
| Distribution Main | 719 | P-7709 | COV | North Glen Dr. | 6 | Asbestos Cement | 12 | 60 | 1.85 out of 5 | $442 | 5,318 |
| Distribution Main | 1585 | P-8013 | COV | North St. | 6 | Cast Iron | 433 | 91 | 2.43 out of 5 | $442 | 191,578 |
| Distribution Main | 1586 | P-8013 | COV | North St. | 2 | Copper | 17 | 14 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 8331 | P-8524 | COV | Northup Plat Rd | 8 | Ductile Iron | 491 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2750 | P-8082 | COV | Notre Dame St. | 2 | Copper | 551 | 82 | 2.57 out of 5 | $442 | 243,433 |
| Transmission Main | 466 | P-1442 | COV | Nottingham Dr. | 16 | Ductile Iron | 986 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 467 | P-1277 | COV | Nottingham Dr. | 16 | Ductile Iron | 6 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 468 | | COV | Nottingham Dr. | 16 | Ductile Iron | 5 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 984 | P-1277 | COV | Nottingham Dr. | 16 | Ductile Iron | 726 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 986 | | COV | Nottingham Dr. | 16 | Ductile Iron | 5 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 987 | | COV | Nottingham Dr. | 16 | Ductile Iron | 31 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 988 | P-1449 | COV | Nottingham Dr. | 16 | Ductile Iron | 25 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2351 | | COV | Nottingham Dr. | 16 | Ductile Iron | 21 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4419 | P-8889 | COV | Nutmeg Circle | 8 | Ductile Iron | 195 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2644 | P-7598 | COV | Oak Rd. | 6 | Asbestos Cement | 56 | UNK | 1.56 out of 5 | $442 | 24,557 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2645 | P-7598 | COV | Oak Rd. | 6 | Asbestos Cement | 40 | UNK | 1.56 out of 5 | $442 | 17,824 |
| Distribution Main | 2777 | P-7593 | COV | Oak Rd. | 6 | Ductile Iron | 15 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 2780 | P-7598 | COV | Oak Rd. | 8 | Ductile Iron | 229 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2801 | P-7593 | COV | Oak Rd. | 8 | Ductile Iron | 238 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9469 | P-8860 | COV | Oak St. | 0.75 | Copper | 282 | UNK | 1.99 out of 5 | $442 | 124,728 |
| Distribution Main | 3048 | P-8494 | COV | Oak Wy | 8 | Ductile Iron | 46 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1028 | P-7889 | COV | Old Hope Rd. | 8 | Ductile Iron | 9 | 29 | 0.14 out of 5 | $442 | 3,950 |
| Distribution Main | 1113 | P-7889 | COV | Old Hope Rd. | 8 | Ductile Iron | 216 | 29 | 0.14 out of 5 | $442 | 95,575 |
| Distribution Main | 1114 | P-7889 | COV | Old Hope Rd. | 8 | Ductile Iron | 347 | 29 | 0.14 out of 5 | $442 | 153,156 |
| Distribution Main | 10427 | P-7889 | COV | Old Hope Rd. | 8 | Ductile Iron | 59 | 29 | 0.14 out of 5 | $442 | 25,938 |
| Distribution Main | 8770 | P-8903 | COV | Old Main St | 8 | Ductile Iron | 21 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8771 | P-8903 | COV | Old Main St | 8 | Ductile Iron | 18 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8772 | P-8902 | COV | Old Main St | 8 | Ductile Iron | 39 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3283 | P-8274 | COV | Old Main St. | 8 | Asbestos Cement | 7 | 48 | 1.14 out of 5 | $442 | 3,283 |
| Distribution Main | 4910 | P-8275 | COV | Old Main St. | 8 | Asbestos Cement | 191 | 48 | 1.14 out of 5 | $442 | 84,409 |
| Distribution Main | 4911 | P-7221 | COV | Old Main St. | 8 | Asbestos Cement | 233 | 69 | 1.29 out of 5 | $442 | 102,852 |
| Distribution Main | 4912 | P-7221 | COV | Old Main St. | 8 | Asbestos Cement | 309 | 69 | 1.29 out of 5 | $442 | 136,718 |
| Distribution Main | 7932 | P-8274 | COV | Old Main St. | 8 | Asbestos Cement | 397 | 48 | 1.14 out of 5 | $442 | 175,496 |
| Distribution Main | 7933 | P-7223 | COV | Old Main St. | 8 | Asbestos Cement | 472 | 69 | 1.29 out of 5 | $442 | 208,703 |
| Distribution Main | 8784 | P-7221 | COV | Old Main St. | 8 | Asbestos Cement | 36 | 69 | 1.29 out of 5 | $442 | 15,991 |
| Distribution Main | 8785 | P-8275 | COV | Old Main St. | 8 | Asbestos Cement | 50 | 48 | 1.14 out of 5 | $442 | 21,914 |
| Distribution Main | 9804 | P-7229 | COV | Old Main St. | 8 | Asbestos Cement | 66 | 69 | 1.29 out of 5 | $442 | 29,366 |
| Distribution Main | 11609 | P-7223 | COV | Old Main St. | 8 | Asbestos Cement | 32 | 69 | 1.29 out of 5 | $442 | 14,279 |
| Distribution Main | 5918 | P-7447 | COV | Old Mishnock Highway | 8 | Ductile Iron | 36 | 26 | 0.14 out of 5 | $442 | 15,846 |
| Distribution Main | 5919 | P-7447 | COV | Old Mishnock Highway | 8 | Ductile Iron | 258 | 26 | 0.14 out of 5 | $442 | 113,883 |
| Distribution Main | 7571 | P-7446 | COV | Old Mishnock Highway | 8 | Ductile Iron | 36 | 26 | 0.14 out of 5 | $442 | 15,751 |
| Distribution Main | 7572 | P-7446 | COV | Old Mishnock Highway | 8 | Ductile Iron | 590 | 26 | 0.14 out of 5 | $442 | 260,596 |
| Distribution Main | 7645 | P-7447 | COV | Old Mishnock Highway | 8 | Ductile Iron | 198 | 26 | 0.14 out of 5 | $442 | 87,527 |
| Distribution Main | 7651 | P-8964 | COV | Old Mishnock Highway | 8 | Ductile Iron | 23 | 26 | 0.14 out of 5 | $442 | 10,081 |
| Distribution Main | 11370 | P-7446 | COV | Old Mishnock Highway | 8 | Ductile Iron | 28 | 26 | 0.14 out of 5 | $442 | 12,453 |
| Distribution Main | 11870 | P-7446 | COV | Old Mishnock Highway | 8 | Ductile Iron | 393 | 26 | 0.14 out of 5 | $442 | 173,836 |
| Transmission Main | 8060 | P-8143 | COV | Old North Rd | 12 | Ductile Iron | 693 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8061 | P-8143 | COV | Old North Rd | 12 | Ductile Iron | 623 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8062 | P-8173 | COV | Old North Rd | 12 | Ductile Iron | 1,165 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8063 | P-8173 | COV | Old North Rd | 12 | Ductile Iron | 180 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8070 | P-9024 | COV | Old North Rd | 12 | Ductile Iron | 573 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8071 | P-9024 | COV | Old North Rd | 12 | Ductile Iron | 83 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8072 | P-7753 | COV | Old North Rd | 12 | Ductile Iron | 104 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11418 | P-9024 | COV | Old North Rd | 12 | Ductile Iron | 42 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11424 | P-9024 | COV | Old North Rd | 12 | Ductile Iron | 393 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11909 | P-9024 | COV | Old North Rd | 12 | Ductile Iron | 75 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11910 | P-9024 | COV | Old North Rd | 12 | Ductile Iron | 35 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2274 | P-7756 | COV | Old North Rd. | 12 | PVC | 505 | 43 | 0.57 out of 5 | $442 | 223,399 |
| Transmission Main | 2275 | P-7756 | COV | Old North Rd. | 12 | PVC | 164 | 43 | 0.57 out of 5 | $442 | 72,286 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 3810 | P-9021 | COV | Old North Rd. | 12 | Ductile Iron | 243 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8078 | P-9022 | COV | Old North Rd. | 12 | Ductile Iron | 282 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9892 | | COV | Old North Rd. | 12 | Ductile Iron | 141 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9893 | P-7756 | COV | Old North Rd. | 12 | Ductile Iron | 12 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11234 | P-9021 | COV | Old North Rd. | 12 | Ductile Iron | 12 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11421 | P-7756 | COV | Old North Rd. | 12 | PVC | 140 | 43 | 0.57 out of 5 | $442 | 61,921 |
| Transmission Main | 11425 | | COV | Old North Rd. | 12 | Ductile Iron | 9 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5916 | P-7115 | COV | Orchid Tr. | 8 | Ductile Iron | 381 | 27 | 0.14 out of 5 | $442 | 168,599 |
| Distribution Main | 6115 | P-7116 | COV | Orchid Tr. | 8 | Ductile Iron | 421 | 27 | 0.14 out of 5 | $442 | 186,209 |
| Distribution Main | 7855 | P-8947 | COV | Orchid Tr. | 8 | Ductile Iron | 8 | 27 | 0.14 out of 5 | $442 | 3,354 |
| Distribution Main | 7976 | P-7116 | COV | Orchid Tr. | 8 | Ductile Iron | 63 | 27 | 0.14 out of 5 | $442 | 27,815 |
| Distribution Main | 7977 | P-7116 | COV | Orchid Tr. | 8 | Ductile Iron | 20 | 27 | 0.14 out of 5 | $442 | 8,697 |
| Distribution Main | 629 | P-1175 | COV | Oriole Ave. | 6 | Asbestos Cement | 331 | 69 | 2 out of 5 | $442 | 146,434 |
| Distribution Main | 630 | P-1175 | COV | Oriole Ave. | 6 | Asbestos Cement | 256 | 69 | 2 out of 5 | $442 | 113,137 |
| Distribution Main | 1596 | P-1175 | COV | Oriole Ave. | 8 | Ductile Iron | 55 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9073 | P-8981 | COV | Osceola Ave | 2 | PVC | 324 | 30 | 1.85 out of 5 | $442 | 143,154 |
| Distribution Main | 9086 | P-8983 | COV | Osceola Ave | 6 | Asbestos Cement | 205 | UNK | 1.56 out of 5 | $442 | 90,587 |
| Distribution Main | 9087 | P-8978 | COV | Osceola Ave | 6 | Unknown | 232 | UNK | 0.71 out of 5 | $442 | 102,520 |
| Distribution Main | 7792 | P-7097 | COV | Osprey Dr. | 8 | PVC | 211 | 34 | 0.43 out of 5 | $442 | 93,079 |
| Distribution Main | 7793 | P-7097 | COV | Osprey Dr. | 8 | PVC | 26 | 34 | 0.43 out of 5 | $442 | 11,679 |
| Distribution Main | 1270 | P-9000 | COV | Overview Dr. | 2 | Copper | 94 | 79 | 2.43 out of 5 | $442 | 41,430 |
| Distribution Main | 2285 | P-7592 | COV | Overview Dr. | 6 | Asbestos Cement | 94 | 70 | 2 out of 5 | $442 | 41,453 |
| Distribution Main | 2775 | P-9000 | COV | Overview Dr. | 6 | Asbestos Cement | 30 | 30 | 1.71 out of 5 | $442 | 13,106 |
| Distribution Main | 2776 | P-9000 | COV | Overview Dr. | 6 | Asbestos Cement | 24 | 30 | 1.71 out of 5 | $442 | 10,722 |
| Distribution Main | 2789 | P-9000 | COV | Overview Dr. | 1.5 | Copper | 323 | 79 | 2.43 out of 5 | $442 | 142,810 |
| Distribution Main | 2791 | P-7591 | COV | Overview Dr. | 6 | Asbestos Cement | 228 | 70 | 2 out of 5 | $442 | 100,706 |
| Distribution Main | 2800 | P-9000 | COV | Overview Dr. | 6 | Asbestos Cement | 6 | 30 | 1.71 out of 5 | $442 | 2,499 |
| Distribution Main | 7594 | P-7086 | COV | Pamela Ct. | 8 | Ductile Iron | 106 | 28 | 0.14 out of 5 | $442 | 46,821 |
| Distribution Main | 1564 | P-8051 | COV | Park Ave. | 6 | Asbestos Cement | 15 | 57 | 1.85 out of 5 | $442 | 6,442 |
| Distribution Main | 1566 | P-8054 | COV | Park Ave. | 6 | Asbestos Cement | 261 | 57 | 1.85 out of 5 | $442 | 115,280 |
| Distribution Main | 2939 | P-8051 | COV | Park Ave. | 6 | Asbestos Cement | 233 | 57 | 1.85 out of 5 | $442 | 102,879 |
| Distribution Main | 3755 | P-8054 | COV | Park Ave. | 8 | Asbestos Cement | 10 | 57 | 1.14 out of 5 | $442 | 4,220 |
| Distribution Main | 8752 | P-8053 | COV | Park Ave. | 6 | Asbestos Cement | 31 | 57 | 1.85 out of 5 | $442 | 13,736 |
| Distribution Main | 10800 | P-7263 | COV | Park St | 8 | Ductile Iron | 267 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2826 | P-7539 | COV | Parker St. | 8 | Ductile Iron | 591 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1442 | P-7956 | COV | Partridge Dr. | 8 | Ductile Iron | 453 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1443 | P-7956 | COV | Partridge Dr. | 8 | Ductile Iron | 47 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2689 | P-7958 | COV | Partridge Dr. | 8 | Ductile Iron | 382 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2197 | P-7747 | COV | Patience Ln. | 8 | Ductile Iron | 335 | 27 | 0.14 out of 5 | $442 | 148,202 |
| Distribution Main | 2129 | | COV | Patton St. | 6 | Asbestos Cement | 10 | 70 | 2 out of 5 | $442 | 4,239 |
| Distribution Main | 3040 | P-7988 | COV | Patton St. | 6 | Asbestos Cement | 424 | 70 | 2 out of 5 | $442 | 187,435 |
| Distribution Main | 3041 | P-7988 | COV | Patton St. | 6 | Asbestos Cement | 338 | 70 | 2 out of 5 | $442 | 149,290 |
| Distribution Main | 7929 | P-7246 | COV | Patty St. | 8 | Asbestos Cement | 90 | 56 | 1.14 out of 5 | $442 | 39,613 |
| Distribution Main | 7930 | P-7246 | COV | Patty St. | 8 | Asbestos Cement | 342 | 56 | 1.85 out of 5 | $442 | 151,269 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 678 | P-8106 | COV | Paulette Dr. | 6 | Asbestos Cement | 518 | 59 | 1.85 out of 5 | $442 | 228,970 |
| Distribution Main | 7737 | P-8956 | COV | Peach Tree Lane | 6 | Asbestos Cement | 25 | 44 | 1.85 out of 5 | $442 | 11,028 |
| Distribution Main | 7815 | P-7032 | COV | Peach Tree Lane | 6 | Asbestos Cement | 21 | 44 | 1.85 out of 5 | $442 | 9,124 |
| Distribution Main | 7816 | P-7032 | COV | Peach Tree Lane | 6 | Asbestos Cement | 930 | 44 | 1.85 out of 5 | $442 | 410,966 |
| Distribution Main | 7829 | P-8956 | COV | Peach Tree Lane | 6 | Asbestos Cement | 447 | 44 | 1.85 out of 5 | $442 | 197,449 |
| Distribution Main | 1441 | P-8002 | COV | Peacock Dr. | 8 | Ductile Iron | 615 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2814 | P-8915 | COV | Pearl St | 2 | Galvanized Iron | 298 | 87 | 3.43 out of 5 | $442 | 131,674 |
| Distribution Main | 846 | P-7788 | COV | Pembroke Ln. | 6 | Asbestos Cement | 591 | 53 | 1.85 out of 5 | $442 | 261,373 |
| Distribution Main | 1480 | P-7790 | COV | Pembroke Ln. | 6 | Asbestos Cement | 436 | 53 | 1.85 out of 5 | $442 | 192,537 |
| Distribution Main | 1485 | P-7786 | COV | Pembroke Ln. | 6 | Asbestos Cement | 341 | 53 | 1.85 out of 5 | $442 | 150,897 |
| Distribution Main | 1486 | P-7786 | COV | Pembroke Ln. | 6 | Asbestos Cement | 525 | 53 | 1.85 out of 5 | $442 | 231,925 |
| Distribution Main | 1707 | P-7782 | COV | Pembroke Ln. | 6 | Asbestos Cement | 300 | 53 | 1.85 out of 5 | $442 | 132,608 |
| Distribution Main | 1708 | P-7778 | COV | Pembroke Ln. | 6 | Asbestos Cement | 23 | 53 | 1.85 out of 5 | $442 | 10,139 |
| Distribution Main | 1709 | P-7778 | COV | Pembroke Ln. | 6 | Asbestos Cement | 651 | 53 | 1.85 out of 5 | $442 | 287,817 |
| Distribution Main | 1718 | P-7775 | COV | Pembroke Ln. | 6 | Asbestos Cement | 234 | 53 | 1.85 out of 5 | $442 | 103,522 |
| Distribution Main | 3183 | P-7772 | COV | Pembroke Ln. | 6 | Asbestos Cement | 227 | 53 | 1.85 out of 5 | $442 | 100,212 |
| Distribution Main | 9550 | P-7772 | COV | Pembroke Ln. | 6 | Ductile Iron | 28 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9551 | P-7772 | COV | Pembroke Ln. | 8 | Ductile Iron | 14 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8852 | P-7053 | COV | Peninsula Ct | 8 | Ductile Iron | 533 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4416 | P-7338 | COV | Peppermint Lane | 8 | Ductile Iron | 177 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1487 | P-7789 | COV | Pettine St. | 6 | Asbestos Cement | 370 | 60 | 1.85 out of 5 | $442 | 163,481 |
| Distribution Main | 1488 | P-7789 | COV | Pettine St. | 6 | Asbestos Cement | 13 | 60 | 1.85 out of 5 | $442 | 5,626 |
| Distribution Main | 1706 | P-7785 | COV | Pettine St. | 6 | Asbestos Cement | 671 | 60 | 1.85 out of 5 | $442 | 296,452 |
| Distribution Main | 3184 | P-7779 | COV | Pettine St. | 6 | Asbestos Cement | 223 | 60 | 1.85 out of 5 | $442 | 98,617 |
| Distribution Main | 8830 | P-9065 | COV | Phillip St. | 8 | Ductile Iron | 42 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8831 | P-8041 | COV | Phillip St. | 8 | Ductile Iron | 572 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8832 | P-8041 | COV | Phillip St. | 8 | Ductile Iron | 508 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11516 | P-8042 | COV | Phillip St. | 8 | Ductile Iron | 207 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 624 | P-8062 | COV | Pierce St. | 4 | Cast Iron | 81 | 132 | 3.29 out of 5 | $442 | 35,864 |
| Distribution Main | 1320 | P-8862 | COV | Pierce St. | 4 | Cast Iron | 195 | 132 | 3.29 out of 5 | $442 | 86,291 |
| Distribution Main | 1321 | P-8104 | COV | Pierce St. | 4 | Cast Iron | 134 | 132 | 3.29 out of 5 | $442 | 59,144 |
| Distribution Main | 2458 | P-8867 | COV | Pierce St. | 4 | Cast Iron | 181 | 132 | 3.29 out of 5 | $442 | 80,009 |
| Distribution Main | 2459 | P-8866 | COV | Pierce St. | 4 | Cast Iron | 189 | 132 | 3.29 out of 5 | $442 | 83,666 |
| Distribution Main | 2669 | P-8867 | COV | Pierce St. | 4 | Cast Iron | 4 | 132 | 3.29 out of 5 | $442 | 1,987 |
| Distribution Main | 11126 | P-8862 | COV | Pierce St. | 4 | Cast Iron | 12 | 132 | 3.29 out of 5 | $442 | 5,293 |
| Distribution Main | 706 | | COV | Pilgrim Ave. | 6 | Asbestos Cement | 6 | 70 | 2 out of 5 | $442 | 2,633 |
| Distribution Main | 835 | P-7823 | COV | Pilgrim Ave. | 8 | Asbestos Cement | 79 | 61 | 1.29 out of 5 | $442 | 35,092 |
| Distribution Main | 836 | P-7824 | COV | Pilgrim Ave. | 8 | Asbestos Cement | 372 | 61 | 1.29 out of 5 | $442 | 164,283 |
| Distribution Main | 837 | P-7861 | COV | Pilgrim Ave. | 6 | Asbestos Cement | 891 | 61 | 2 out of 5 | $442 | 393,639 |
| Distribution Main | 838 | P-7861 | COV | Pilgrim Ave. | 6 | Asbestos Cement | 3 | 70 | 2 out of 5 | $442 | 1,487 |
| Distribution Main | 1479 | P-7823 | COV | Pilgrim Ave. | 8 | Asbestos Cement | 194 | 61 | 1.29 out of 5 | $442 | 85,812 |
| Distribution Main | 1959 | | COV | Pilgrim Ave. | | Unknown | 40 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 3153 | P-7862 | COV | Pilgrim Ave. | 6 | Asbestos Cement | 20 | 70 | 2 out of 5 | $442 | 8,820 |
| Distribution Main | 3164 | P-7808 | COV | Pilgrim Ave. | 8 | Asbestos Cement | 294 | 61 | 1.29 out of 5 | $442 | 130,071 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3165 | P-7808 | COV | Pilgrim Ave. | 8 | Asbestos Cement | 301 | 61 | 1.29 out of 5 | $442 | 133,150 |
| Distribution Main | 3166 | P-7808 | COV | Pilgrim Ave. | 8 | Asbestos Cement | 87 | 61 | 1.29 out of 5 | $442 | 38,472 |
| Distribution Main | 3167 | P-7810 | COV | Pilgrim Ave. | 8 | Asbestos Cement | 329 | 61 | 1.29 out of 5 | $442 | 145,325 |
| Distribution Main | 3177 | P-7812 | COV | Pilgrim Ave. | 6 | Asbestos Cement | 890 | 70 | 2 out of 5 | $442 | 393,190 |
| Distribution Main | 3178 | P-7812 | COV | Pilgrim Ave. | 6 | Asbestos Cement | 42 | 70 | 2 out of 5 | $442 | 18,365 |
| Distribution Main | 3179 | P-7808 | COV | Pilgrim Ave. | 8 | Asbestos Cement | 205 | 61 | 1.14 out of 5 | $442 | 90,453 |
| Distribution Main | 3224 | P-7818 | COV | Pilgrim Ave. | 8 | Asbestos Cement | 121 | 61 | 1.14 out of 5 | $442 | 53,650 |
| Distribution Main | 3225 | P-7818 | COV | Pilgrim Ave. | 8 | Asbestos Cement | 156 | 61 | 1.29 out of 5 | $442 | 68,967 |
| Distribution Main | 9563 | P-7812 | COV | Pilgrim Ave. | 8 | Ductile Iron | 24 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9564 | P-7812 | COV | Pilgrim Ave. | 8 | Ductile Iron | 2 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9565 | P-7812 | COV | Pilgrim Ave. | 6 | Ductile Iron | 7 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 2464 | P-7922 | COV | Pin Oak Ct. | 8 | PVC | 252 | 39 | 0.43 out of 5 | $442 | 111,440 |
| Distribution Main | 1052 | | COV | Pine Acres Boulivard | 8 | Ductile Iron | 35 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1085 | P-7595 | COV | Pine Ave. | 8 | Ductile Iron | 730 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2779 | P-7595 | COV | Pine Ave. | 8 | Ductile Iron | 4 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2790 | P-7594 | COV | Pine Ave. | 8 | Ductile Iron | 171 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 477 | P-7570 | COV | Pinehurst Rd. | 6 | Asbestos Cement | 364 | 65 | 2 out of 5 | $442 | 160,788 |
| Distribution Main | 10451 | | COV | Pioneer Rd. | 1 | Copper | 18 | UNK | 1.99 out of 5 | $442 | 7,996 |
| Distribution Main | 7808 | P-7046 | COV | Plum Tree Ln. | 8 | Asbestos Cement | 21 | 46 | 1.14 out of 5 | $442 | 9,482 |
| Distribution Main | 7835 | P-7046 | COV | Plum Tree Ln. | 8 | Asbestos Cement | 235 | 46 | 1.14 out of 5 | $442 | 103,669 |
| Distribution Main | 7836 | P-7046 | COV | Plum Tree Ln. | 8 | Asbestos Cement | 634 | 46 | 1.14 out of 5 | $442 | 280,249 |
| Distribution Main | 184 | P-7392 | COV | Pond View Dr. | 6 | Asbestos Cement | 150 | 53 | 1.85 out of 5 | $442 | 66,395 |
| Distribution Main | 604 | P-7392 | COV | Pond View Dr. | 8 | Ductile Iron | 117 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2127 | P-7393 | COV | Pond View Dr. | 6 | Asbestos Cement | 592 | 53 | 1.85 out of 5 | $442 | 261,602 |
| Distribution Main | 2128 | P-7393 | COV | Pond View Dr. | 6 | Asbestos Cement | 547 | 53 | 1.85 out of 5 | $442 | 241,630 |
| Distribution Main | 144 | P-7918 | COV | Poplar Ct. | 8 | PVC | 267 | 39 | 0.43 out of 5 | $442 | 117,958 |
| Transmission Main | 8381 | P-8128 | COV | Potter Ct | 12 | Ductile Iron | 1,011 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8381 | P-8128 | COV | Potter Ct | 12 | Ductile Iron | 26 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1844 | P-8941 | COV | Potters St. | 6 | Asbestos Cement | 138 | 69 | 2 out of 5 | $442 | 61,108 |
| Distribution Main | 1845 | P-7543 | COV | Potters St. | 6 | Asbestos Cement | 233 | 69 | 2 out of 5 | $442 | 103,072 |
| Distribution Main | 1852 | P-7544 | COV | Potters St. | 6 | Asbestos Cement | 193 | 69 | 2 out of 5 | $442 | 85,472 |
| Distribution Main | 2627 | P-8305 | COV | Powhatan Ave. | 6 | Asbestos Cement | 395 | 53 | 1.85 out of 5 | $442 | 174,588 |
| Distribution Main | 9617 | P-8939 | COV | Prince Street | 6 | Asbestos Cement | 80 | 62 | 2 out of 5 | $442 | 35,328 |
| Distribution Main | 9618 | | COV | Prince Street | 1 | Copper | 5 | 62 | 2.43 out of 5 | $442 | 2,198 |
| Distribution Main | 11284 | P-8939 | COV | Prince Street | 6 | Asbestos Cement | 1 | 62 | 2 out of 5 | $442 | 530 |
| Distribution Main | 4788 | P-8937 | COV | Princess Street | 2 | Galvanized Iron | 318 | 61 | 3.28 out of 5 | $442 | 140,585 |
| Distribution Main | 5048 | P-8938 | COV | Princess Street | 2 | Galvanized Iron | 252 | 129 | 3.57 out of 5 | $442 | 111,245 |
| Distribution Main | 11283 | P-8938 | COV | Princess Street | 2 | Galvanized Iron | 4 | 129 | 3.57 out of 5 | $442 | 1,940 |
| Distribution Main | 1449 | P-7807 | COV | Princeton Ave. | 8 | Asbestos Cement | 239 | 59 | 1.14 out of 5 | $442 | 105,516 |
| Distribution Main | 1489 | P-7794 | COV | Princeton Ave. | 8 | Asbestos Cement | 472 | 59 | 1.14 out of 5 | $442 | 208,814 |
| Distribution Main | 1490 | P-7794 | COV | Princeton Ave. | 8 | Asbestos Cement | 29 | 59 | 1.14 out of 5 | $442 | 13,035 |
| Distribution Main | 1493 | P-9028 | COV | Princeton Ave. | 8 | Asbestos Cement | 255 | 59 | 1.14 out of 5 | $442 | 112,863 |
| Distribution Main | 1495 | P-7803 | COV | Princeton Ave. | 8 | Asbestos Cement | 244 | 59 | 1.14 out of 5 | $442 | 107,837 |
| Distribution Main | 1717 | P-7793 | COV | Princeton Ave. | 8 | Asbestos Cement | 844 | 59 | 1.14 out of 5 | $442 | 372,947 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3160 | P-7797 | COV | Princeton Ave. | 8 | Asbestos Cement | 259 | 59 | 1.14 out of 5 | $442 | 114,608 |
| Distribution Main | 3186 | P-7776 | COV | Princeton Ave. | 8 | Asbestos Cement | 28 | 59 | 1.14 out of 5 | $442 | 12,384 |
| Distribution Main | 3187 | P-7776 | COV | Princeton Ave. | 8 | Asbestos Cement | 569 | 59 | 1.14 out of 5 | $442 | 251,307 |
| Distribution Main | 3226 | P-7805 | COV | Princeton Ave. | 8 | Asbestos Cement | 25 | 59 | 1.14 out of 5 | $442 | 10,971 |
| Distribution Main | 3227 | P-7802 | COV | Princeton Ave. | 8 | Asbestos Cement | 238 | 59 | 1.14 out of 5 | $442 | 105,120 |
| Distribution Main | 3230 | P-7801 | COV | Princeton Ave. | 8 | Asbestos Cement | 444 | 59 | 1.14 out of 5 | $442 | 196,277 |
| Distribution Main | 3231 | P-7801 | COV | Princeton Ave. | 8 | Asbestos Cement | 48 | 59 | 1.14 out of 5 | $442 | 21,251 |
| Distribution Main | 3234 | P-7805 | COV | Princeton Ave. | 8 | Asbestos Cement | 51 | 59 | 1.14 out of 5 | $442 | 22,512 |
| Distribution Main | 3235 | P-7805 | COV | Princeton Ave. | 8 | Asbestos Cement | 317 | 59 | 1.14 out of 5 | $442 | 140,021 |
| Distribution Main | 1636 | P-8319 | COV | Prospect Ave. | 6 | Asbestos Cement | 104 | 67 | 2 out of 5 | $442 | 45,767 |
| Distribution Main | 1849 | P-8319 | COV | Prospect Ave. | 6 | Asbestos Cement | 9 | 67 | 2 out of 5 | $442 | 4,104 |
| Distribution Main | 2648 | P-7545 | COV | Prospect Ave. | 6 | Asbestos Cement | 23 | 67 | 2 out of 5 | $442 | 10,173 |
| Distribution Main | 2649 | P-7545 | COV | Prospect Ave. | 6 | Asbestos Cement | 294 | 67 | 2 out of 5 | $442 | 129,885 |
| Transmission Main | 631 | P-591 | COV | Pulaski St. | 12 | Ductile Iron | 655 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 632 | P-591 | COV | Pulaski St. | 12 | Ductile Iron | 102 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7427 | P-8017 | COV | Pulaski St. | 12 | Ductile Iron | 252 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7428 | P-8017 | COV | Pulaski St. | 12 | Ductile Iron | 302 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7429 | P-8014 | COV | Pulaski St. | 12 | Ductile Iron | 133 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7430 | P-8014 | COV | Pulaski St. | 12 | Ductile Iron | 44 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7431 | P-8012 | COV | Pulaski St. | 12 | Ductile Iron | 347 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8149 | P-8019 | COV | Pulaski St. | 12 | Ductile Iron | 32 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8168 | P-591 | COV | Pulaski St. | 12 | Ductile Iron | 84 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11787 | P-591 | COV | Pulaski St. | 12 | Ductile Iron | 246 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3083 | P-7400 | COV | Puritan Ave. | 6 | Asbestos Cement | 634 | 57 | 1.85 out of 5 | $442 | 280,307 |
| Distribution Main | 3084 | P-7400 | COV | Puritan Ave. | 6 | Asbestos Cement | 32 | 57 | 1.85 out of 5 | $442 | 14,183 |
| Distribution Main | 11788 | P-7400 | COV | Puritan Ave. | 6 | Asbestos Cement | 370 | 57 | 1.85 out of 5 | $442 | 163,440 |
| Distribution Main | 2671 | | COV | Quidnick Street | 8 | Unknown | 22 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 2672 | | COV | Quidnick Street | 6 | Unknown | 12 | UNK | 0.71 out of 5 | $442 | 5,276 |
| Distribution Main | 10347 | | COV | Quidnick Street | 8 | Unknown | 58 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 10348 | | COV | Quidnick Street | 6 | Unknown | 40 | UNK | 0.71 out of 5 | $442 | 17,896 |
| Distribution Main | 10349 | | COV | Quidnick Street | 6 | Unknown | 42 | UNK | 0.71 out of 5 | $442 | 18,450 |
| Distribution Main | 9077 | P-7666 | COV | Quiet / Forge | 8 | Ductile Iron | 242 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11179 | P-7666 | COV | Quiet / Forge | 8 | Ductile Iron | 31 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 421 | P-8303 | COV | Quiet Ave. | 6 | Asbestos Cement | 104 | 53 | 1.85 out of 5 | $442 | 46,101 |
| Distribution Main | 2618 | | COV | Quiet Ave. | 6 | Asbestos Cement | 53 | 53 | 1.85 out of 5 | $442 | 23,464 |
| Distribution Main | 9074 | P-8976 | COV | Quiet Ave. | 6 | Ductile Iron | 3 | 31 | 0.85 out of 5 | $442 | 1,434 |
| Distribution Main | 9075 | P-8976 | COV | Quiet Ave. | 6 | Ductile Iron | 119 | 31 | 0.85 out of 5 | $442 | 52,538 |
| Distribution Main | 11057 | P-8303 | COV | Quiet Ave. | 6 | Asbestos Cement | 7 | 53 | 1.85 out of 5 | $442 | 2,964 |
| Distribution Main | 947 | P-9069 | COV | Rainville Avenue | 1 | Unknown | 299 | UNK | 1.42 out of 5 | $442 | 132,330 |
| Distribution Main | 1644 | P-7552 | COV | Rathbun St. | 2 | Copper | 751 | 78 | 2.43 out of 5 | $442 | 332,048 |
| Distribution Main | 1683 | P-7552 | COV | Rathbun St. | 2 | Copper | 12 | 78 | 2.43 out of 5 | $442 | 5,420 |
| Distribution Main | 1850 | P-7552 | COV | Rathbun St. | 2 | Copper | 80 | 78 | 2.43 out of 5 | $442 | 35,566 |
| Distribution Main | 8359 | P-7736 | COV | Rawlinson Dr | 8 | Ductile Iron | 314 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 531 | | COV | Rawlinson Dr. | 6 | Asbestos Cement | 47 | UNK | 1.56 out of 5 | $442 | 20,987 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2301 | P-7742 | COV | Rawlinson Dr. | 8 | Ductile Iron | 43 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3181 | P-7742 | COV | Rawlinson Dr. | 6 | Asbestos Cement | 335 | 60 | 1.85 out of 5 | $442 | 147,892 |
| Distribution Main | 3182 | P-7742 | COV | Rawlinson Dr. | 6 | Asbestos Cement | 817 | 60 | 1.85 out of 5 | $442 | 361,206 |
| Distribution Main | 9548 | P-7742 | COV | Rawlinson Dr. | 6 | Ductile Iron | 7 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9552 | P-7742 | COV | Rawlinson Dr. | 6 | Ductile Iron | 7 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11203 | P-7742 | COV | Rawlinson Dr. | 6 | Asbestos Cement | 4 | 60 | 1.85 out of 5 | $442 | 1,672 |
| Distribution Main | 11785 | P-7742 | COV | Rawlinson Dr. | 6 | Asbestos Cement | 152 | 60 | 1.85 out of 5 | $442 | 67,030 |
| Distribution Main | 1097 | P-8846 | COV | Ray St. | 6 | PVC | 20 | 38 | 1.14 out of 5 | $442 | 8,989 |
| Distribution Main | 1559 | P-8055 | COV | Ray St. | 6 | PVC | 165 | 38 | 1.14 out of 5 | $442 | 72,876 |
| Distribution Main | 1560 | P-8055 | COV | Ray St. | 6 | PVC | 196 | 38 | 1.14 out of 5 | $442 | 86,680 |
| Distribution Main | 2923 | P-7071 | COV | Ray St. | 6 | PVC | 106 | 38 | 1.14 out of 5 | $442 | 46,958 |
| Distribution Main | 2924 | P-7071 | COV | Ray St. | 6 | PVC | 523 | 38 | 1.14 out of 5 | $442 | 231,359 |
| Distribution Main | 11783 | P-7071 | COV | Ray St. | 6 | PVC | 26 | 38 | 1.14 out of 5 | $442 | 11,274 |
| Distribution Main | 954 | P-8006 | COV | Raymond St | 6 | Asbestos Cement | 256 | 70 | 2 out of 5 | $442 | 113,168 |
| Distribution Main | 313 | P-9051 | COV | Raymond St. | 6 | Asbestos Cement | 78 | 70 | 2 out of 5 | $442 | 34,428 |
| Distribution Main | 569 | P-7995 | COV | Raymond St. | 6 | Asbestos Cement | 274 | 70 | 2 out of 5 | $442 | 121,020 |
| Distribution Main | 2727 | P-8003 | COV | Raymond St. | 6 | Asbestos Cement | 31 | 70 | 2 out of 5 | $442 | 13,642 |
| Distribution Main | 2728 | P-8003 | COV | Raymond St. | 6 | Asbestos Cement | 222 | 70 | 2 out of 5 | $442 | 98,046 |
| Distribution Main | 8993 | P-8038 | COV | Read Ave | 8 | Ductile Iron | 7 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11517 | P-8039 | COV | Read Ave | 8 | Ductile Iron | 6 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 315 | P-9060 | COV | Read Ave. | 6 | Cast Iron | 68 | 132 | 2.57 out of 5 | $442 | 30,086 |
| Distribution Main | 937 | P-9062 | COV | Read Ave. | 6 | Cast Iron | 68 | 132 | 2.57 out of 5 | $442 | 30,126 |
| Distribution Main | 938 | P-8031 | COV | Read Ave. | 6 | Cast Iron | 157 | 132 | 2.57 out of 5 | $442 | 69,562 |
| Distribution Main | 939 | P-8031 | COV | Read Ave. | 6 | Cast Iron | 3 | 132 | 2.57 out of 5 | $442 | 1,506 |
| Distribution Main | 940 | P-8029 | COV | Read Ave. | 8 | Cast Iron | 7 | 132 | 1.86 out of 5 | $442 | 3,113 |
| Distribution Main | 943 | P-9066 | COV | Read Ave. | 6 | Cast Iron | 209 | 132 | 2.57 out of 5 | $442 | 92,502 |
| Distribution Main | 944 | P-9066 | COV | Read Ave. | 6 | Cast Iron | 14 | 132 | 2.57 out of 5 | $442 | 6,157 |
| Distribution Main | 946 | P-9068 | COV | Read Ave. | 6 | Cast Iron | 108 | 132 | 2.57 out of 5 | $442 | 47,540 |
| Distribution Main | 948 | P-8032 | COV | Read Ave. | 6 | Cast Iron | 72 | 132 | 2.57 out of 5 | $442 | 31,639 |
| Distribution Main | 949 | P-8039 | COV | Read Ave. | 6 | Cast Iron | 214 | 132 | 2.57 out of 5 | $442 | 94,754 |
| Distribution Main | 950 | P-8039 | COV | Read Ave. | 6 | Cast Iron | 751 | 132 | 2.57 out of 5 | $442 | 331,977 |
| Distribution Main | 951 | P-8043 | COV | Read Ave. | 6 | Cast Iron | 264 | 132 | 2.57 out of 5 | $442 | 116,664 |
| Distribution Main | 952 | P-8043 | COV | Read Ave. | 6 | Cast Iron | 329 | 132 | 2.57 out of 5 | $442 | 145,577 |
| Distribution Main | 2697 | P-8028 | COV | Read Ave. | 8 | Cast Iron | 13 | 132 | 1.86 out of 5 | $442 | 5,672 |
| Distribution Main | 2698 | P-8023 | COV | Read Ave. | 6 | Cast Iron | 31 | 132 | 2.57 out of 5 | $442 | 13,708 |
| Distribution Main | 2703 | P-8029 | COV | Read Ave. | 6 | Cast Iron | 215 | 132 | 2.57 out of 5 | $442 | 95,058 |
| Distribution Main | 2705 | P-8038 | COV | Read Ave. | 6 | Cast Iron | 365 | 132 | 2.57 out of 5 | $442 | 161,235 |
| Distribution Main | 2708 | P-9055 | COV | Read Ave. | 6 | Cast Iron | 357 | 132 | 2.57 out of 5 | $442 | 157,819 |
| Distribution Main | 2713 | P-9054 | COV | Read Ave. | 6 | Cast Iron | 230 | 132 | 2.57 out of 5 | $442 | 101,636 |
| Distribution Main | 2714 | P-9054 | COV | Read Ave. | 6 | Cast Iron | 14 | 132 | 2.57 out of 5 | $442 | 6,381 |
| Distribution Main | 2719 | P-8027 | COV | Read Ave. | 6 | Cast Iron | 177 | 132 | 2.57 out of 5 | $442 | 78,373 |
| Distribution Main | 2720 | P-8027 | COV | Read Ave. | 6 | Cast Iron | 24 | 132 | 2.57 out of 5 | $442 | 10,680 |
| Distribution Main | 2722 | P-9036 | COV | Read Ave. | 6 | Cast Iron | 10 | 132 | 2.57 out of 5 | $442 | 4,498 |
| Distribution Main | 2723 | P-9036 | COV | Read Ave. | 6 | Cast Iron | 144 | 132 | 2.57 out of 5 | $442 | 63,514 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2725 | P-8023 | COV | Read Ave. | 6 | Cast Iron | 343 | 132 | 2.57 out of 5 | $442 | 151,603 |
| Distribution Main | 2920 | P-8043 | COV | Read Ave. | 6 | Cast Iron | 24 | 132 | 2.57 out of 5 | $442 | 10,783 |
| Distribution Main | 2921 | P-8043 | COV | Read Ave. | 6 | Cast Iron | 534 | 132 | 2.57 out of 5 | $442 | 235,831 |
| Distribution Main | 2930 | P-8043 | COV | Read Ave. | 6 | Cast Iron | 581 | 132 | 2.57 out of 5 | $442 | 256,669 |
| Transmission Main | 2931 | P-8045 | COV | Read Ave. | 16 | Asbestos Cement | 1,089 | 75 | 1.29 out of 5 | $442 | 481,285 |
| Transmission Main | 2933 | P-8056 | COV | Read Ave. | 16 | Asbestos Cement | 74 | 75 | 1.29 out of 5 | $442 | 32,870 |
| Transmission Main | 8991 | P-8056 | COV | Read Ave. | 16 | Asbestos Cement | 4 | 75 | 1.29 out of 5 | $442 | 1,794 |
| Distribution Main | 11186 | P-9054 | COV | Read Ave. | 6 | Cast Iron | 229 | 132 | 2.57 out of 5 | $442 | 101,235 |
| Distribution Main | 11782 | P-9054 | COV | Read Ave. | 6 | Cast Iron | 83 | 132 | 2.57 out of 5 | $442 | 36,717 |
| Transmission Main | 8798 | P-8785 | COV | Read School House Rd | 20 | Ductile Iron | 114 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8799 | | COV | Read School House Rd | 20 | Ductile Iron | 46 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8804 | P-8786 | COV | Read School House Rd | 20 | Ductile Iron | 47 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8805 | P-8786 | COV | Read School House Rd | 20 | Ductile Iron | 32 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11512 | P-8786 | COV | Read School House Rd | 20 | Ductile Iron | 21 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7172 | | COV | Read School House Rd. | 6 | Unknown | 5 | UNK | 0.71 out of 5 | $442 | 2,410 |
| Transmission Main | 7173 | | COV | Read School House Rd. | 12 | Unknown | 72 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 7902 | | COV | Read School House Rd. | 12 | Unknown | 6 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 8757 | P-8785 | COV | Read Schoolhouse Rd | 20 | Ductile Iron | 1,731 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8758 | P-8785 | COV | Read Schoolhouse Rd | 20 | Ductile Iron | 49 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8766 | P-7181 | COV | Read Schoolhouse Rd | 20 | Ductile Iron | 582 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8767 | P-7181 | COV | Read Schoolhouse Rd | 20 | Ductile Iron | 978 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8768 | P-8785 | COV | Read Schoolhouse Rd | 20 | Ductile Iron | 646 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8769 | P-8785 | COV | Read Schoolhouse Rd | 20 | Ductile Iron | 710 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8783 | | COV | Read Schoolhouse Rd | 12 | Ductile Iron | 17 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8789 | P-7181 | COV | Read Schoolhouse Rd | 20 | Ductile Iron | 40 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8790 | P-7181 | COV | Read Schoolhouse Rd | 20 | Ductile Iron | 41 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8795 | | COV | Read Schoolhouse Rd | 20 | Ductile Iron | 13 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8796 | | COV | Read Schoolhouse Rd | 12 | Ductile Iron | 3 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11502 | P-8785 | COV | Read Schoolhouse Rd | 20 | Ductile Iron | 142 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11503 | P-8785 | COV | Read Schoolhouse Rd | 20 | Ductile Iron | 10 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11508 | P-7181 | COV | Read Schoolhouse Rd | 20 | Ductile Iron | 26 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11509 | P-7181 | COV | Read Schoolhouse Rd | 20 | Ductile Iron | 17 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11796 | P-7181 | COV | Read Schoolhouse Rd | 20 | Ductile Iron | 534 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8781 | | COV | Read Schoolhouse Rd. | 12 | Ductile Iron | 12 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8782 | | COV | Read Schoolhouse Rd. | 12 | Ductile Iron | 14 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 491 | P-8854 | COV | Rebecca St | 8 | Ductile Iron | 34 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9689 | P-8855 | COV | Rebecca St | 6 | Ductile Iron | 4 | 15 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 670 | P-8107 | COV | Rebecca St. | 6 | Asbestos Cement | 368 | 58 | 1.85 out of 5 | $442 | 162,457 |
| Distribution Main | 671 | P-8107 | COV | Rebecca St. | 6 | Asbestos Cement | 486 | 58 | 1.85 out of 5 | $442 | 215,003 |
| Distribution Main | 672 | | COV | Rebecca St. | 6 | Asbestos Cement | 11 | 58 | 1.85 out of 5 | $442 | 4,781 |
| Distribution Main | 2111 | | COV | Rebecca St. | 6 | Asbestos Cement | 10 | 58 | 1.85 out of 5 | $442 | 4,542 |
| Distribution Main | 11085 | P-8107 | COV | Rebecca St. | 6 | Asbestos Cement | 235 | 58 | 1.85 out of 5 | $442 | 103,839 |
| Distribution Main | 7776 | P-8363 | COV | Red Cedar Dr. | 8 | Ductile Iron | 8 | 29 | 0.14 out of 5 | $442 | 3,721 |
| Distribution Main | 7786 | P-8952 | COV | Red Cedar Dr. | 8 | Ductile Iron | 80 | 29 | 0.14 out of 5 | $442 | 35,424 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 7790 | P-8363 | COV | Red Cedar Dr. | 8 | Ductile Iron | 43 | 29 | 0.14 out of 5 | $442 | 18,906 |
| Distribution Main | 7791 | P-8363 | COV | Red Cedar Dr. | 8 | Ductile Iron | 334 | 29 | 0.14 out of 5 | $442 | 147,812 |
| Distribution Main | 8332 | P-7089 | COV | Red Cedar Dr. | 6 | Asbestos Cement | 277 | 43 | 1.85 out of 5 | $442 | 122,486 |
| Distribution Main | 7736 | P-7045 | COV | Red Maple Rd. | 8 | Asbestos Cement | 20 | 57 | 1.14 out of 5 | $442 | 8,868 |
| Distribution Main | 7740 | P-7044 | COV | Red Maple Rd. | 8 | Asbestos Cement | 541 | 57 | 1.14 out of 5 | $442 | 239,151 |
| Distribution Main | 7828 | P-4045 | COV | Red Maple Rd. | 8 | Asbestos Cement | 276 | 57 | 1.14 out of 5 | $442 | 122,035 |
| Distribution Main | 1017 | P-7895 | COV | Red Oak Dr. | 8 | Asbestos Cement | 355 | 39 | 1 out of 5 | $442 | 156,847 |
| Distribution Main | 1018 | P-7898 | COV | Red Oak Dr. | 8 | Asbestos Cement | 308 | 39 | 1 out of 5 | $442 | 135,919 |
| Distribution Main | 1019 | P-7898 | COV | Red Oak Dr. | 8 | Asbestos Cement | 49 | 39 | 1 out of 5 | $442 | 21,495 |
| Distribution Main | 1020 | P-7901 | COV | Red Oak Dr. | 8 | Asbestos Cement | 207 | 39 | 1 out of 5 | $442 | 91,579 |
| Distribution Main | 1021 | P-7902 | COV | Red Oak Dr. | 8 | Asbestos Cement | 107 | 39 | 1 out of 5 | $442 | 47,509 |
| Distribution Main | 1022 | P-7902 | COV | Red Oak Dr. | 8 | Asbestos Cement | 104 | 39 | 1 out of 5 | $442 | 46,130 |
| Distribution Main | 1023 | P-7903 | COV | Red Oak Dr. | 8 | Asbestos Cement | 371 | 39 | 1 out of 5 | $442 | 164,182 |
| Distribution Main | 1024 | P-7903 | COV | Red Oak Dr. | 8 | Asbestos Cement | 401 | 39 | 1 out of 5 | $442 | 177,228 |
| Distribution Main | 1093 | P-7893 | COV | Red Oak Dr. | 8 | Asbestos Cement | 148 | 39 | 1 out of 5 | $442 | 65,505 |
| Distribution Main | 1094 | P-7893 | COV | Red Oak Dr. | 8 | Asbestos Cement | 253 | 39 | 1 out of 5 | $442 | 111,606 |
| Distribution Main | 1919 | P-8875 | COV | Red Oak Dr. | 8 | Asbestos Cement | 279 | 39 | 1 out of 5 | $442 | 123,216 |
| Distribution Main | 1920 | P-8875 | COV | Red Oak Dr. | 8 | Asbestos Cement | 382 | 39 | 1 out of 5 | $442 | 168,899 |
| Distribution Main | 3169 | P-7819 | COV | Reddington St. | 6 | Asbestos Cement | 935 | 44 | 1.85 out of 5 | $442 | 413,084 |
| Distribution Main | 5913 | P-8365 | COV | Regal Wood Dr. | 8 | Ductile Iron | 188 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7856 | P-7126 | COV | Regal Wood Dr. | 8 | Ductile Iron | 10 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7857 | P-7126 | COV | Regal Wood Dr. | 8 | Ductile Iron | 139 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7858 | P-7117 | COV | Regal Wood Dr. | 8 | Ductile Iron | 392 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7861 | P-7126 | COV | Regal Wood Dr. | 8 | Ductile Iron | 466 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7862 | P-7126 | COV | Regal Wood Dr. | 8 | Ductile Iron | 188 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 588 | P-8917 | COV | Regent Street | 6 | Ductile Iron | 663 | 29 | 0.85 out of 5 | $442 | 293,216 |
| Distribution Main | 1666 | P-8970 | COV | Regis Street | 6 | Asbestos Cement | 139 | 68 | 2 out of 5 | $442 | 61,628 |
| Transmission Main | 8075 | P-9025 | COV | Rejane St | 12 | Ductile Iron | 45 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4769 | P-8146 | COV | Rejane St. | 6 | Asbestos Cement | 58 | 68 | 2 out of 5 | $442 | 25,472 |
| Distribution Main | 4770 | P-8146 | COV | Rejane St. | 6 | Asbestos Cement | 445 | 68 | 2 out of 5 | $442 | 196,631 |
| Distribution Main | 4953 | P-8147 | COV | Rejane St. | 6 | Asbestos Cement | 249 | 68 | 2 out of 5 | $442 | 110,154 |
| Distribution Main | 818 | P-7347 | COV | Remington Farm Dr. | 8 | Ductile Iron | 872 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 820 | P-7348 | COV | Remington Farm Dr. | 8 | Ductile Iron | 53 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 821 | P-7348 | COV | Remington Farm Dr. | 8 | Ductile Iron | 84 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2104 | P-7345 | COV | Remington Farm Dr. | 8 | Ductile Iron | 826 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2105 | P-7345 | COV | Remington Farm Dr. | 8 | Ductile Iron | 42 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9961 | P-7347 | COV | Remington Farm Dr. | 8 | Ductile Iron | 374 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9962 | P-7345 | COV | Remington Farm Dr. | 8 | Ductile Iron | 696 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9963 | P-7345 | COV | Remington Farm Dr. | 8 | Ductile Iron | 50 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11981 | P-7345 | COV | Remington Farm Dr. | 8 | Ductile Iron | 34 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 724 | P-7686 | COV | Reno Ct. | 6 | Asbestos Cement | 138 | 50 | 1.85 out of 5 | $442 | 61,065 |
| Distribution Main | 725 | P-7686 | COV | Reno Ct. | 6 | Asbestos Cement | 97 | 50 | 1.85 out of 5 | $442 | 42,706 |
| Distribution Main | 10103 | | COV | Reservoir Rd | | Ductile Iron | 2 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5937 | P-7128 | COV | Reservoir Rd. | 8 | Ductile Iron | 74 | 23 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 5938 | P-7128 | COV | Reservoir Rd. | 8 | Ductile Iron | 964 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6322 | P-7137 | COV | Reservoir Rd. | 12 | Ductile Iron | 896 | 26 | 0.14 out of 5 | $442 | 396,147 |
| Transmission Main | 6323 | P-7137 | COV | Reservoir Rd. | 12 | Ductile Iron | 100 | 26 | 0.14 out of 5 | $442 | 44,151 |
| Distribution Main | 6624 | P-7158 | COV | Reservoir Rd. | 8 | Asbestos Cement | 308 | 54 | 1.14 out of 5 | $442 | 136,132 |
| Distribution Main | 6625 | P-7158 | COV | Reservoir Rd. | 8 | Asbestos Cement | 298 | 54 | 1.14 out of 5 | $442 | 131,611 |
| Transmission Main | 7193 | P-8359 | COV | Reservoir Rd. | 12 | Asbestos Cement | 60 | 54 | 1.14 out of 5 | $442 | 26,631 |
| Transmission Main | 7199 | | COV | Reservoir Rd. | 12 | Ductile Iron | 14 | 30 | 0.14 out of 5 | $442 | 6,088 |
| Transmission Main | 7200 | P-8355 | COV | Reservoir Rd. | 12 | PVC | 25 | 32 | 0.43 out of 5 | $442 | 11,080 |
| Transmission Main | 7204 | P-8355 | COV | Reservoir Rd. | 12 | Asbestos Cement | 12 | 54 | 1.14 out of 5 | $442 | 5,165 |
| Transmission Main | 7506 | P-8354 | COV | Reservoir Rd. | 12 | Asbestos Cement | 202 | 54 | 1.14 out of 5 | $442 | 89,194 |
| Transmission Main | 7507 | P-8354 | COV | Reservoir Rd. | 12 | Asbestos Cement | 404 | 54 | 1.14 out of 5 | $442 | 178,488 |
| Distribution Main | 7508 | P-8353 | COV | Reservoir Rd. | 8 | PVC | 512 | 32 | 0.43 out of 5 | $442 | 226,320 |
| Distribution Main | 7509 | P-8353 | COV | Reservoir Rd. | 8 | PVC | 171 | 32 | 0.43 out of 5 | $442 | 75,632 |
| Transmission Main | 7512 | P-8755 | COV | Reservoir Rd. | 12 | Ductile Iron | 99 | 30 | 0.14 out of 5 | $442 | 43,670 |
| Transmission Main | 7517 | P-8354 | COV | Reservoir Rd. | 12 | Ductile Iron | 15 | 30 | 0.14 out of 5 | $442 | 6,435 |
| Transmission Main | 7518 | P-8755 | COV | Reservoir Rd. | 12 | Ductile Iron | 3 | 30 | 0.14 out of 5 | $442 | 1,486 |
| Transmission Main | 7525 | P-7138 | COV | Reservoir Rd. | 12 | PVC | 316 | 31 | 0.43 out of 5 | $442 | 139,582 |
| Transmission Main | 7526 | P-7155 | COV | Reservoir Rd. | 12 | PVC | 137 | 31 | 0.43 out of 5 | $442 | 60,428 |
| Transmission Main | 7527 | P-7155 | COV | Reservoir Rd. | 12 | PVC | 290 | 31 | 0.43 out of 5 | $442 | 128,310 |
| Distribution Main | 7597 | P-7156 | COV | Reservoir Rd. | 8 | Asbestos Cement | 250 | 54 | 1.14 out of 5 | $442 | 110,586 |
| Transmission Main | 7598 | P-7153 | COV | Reservoir Rd. | 12 | PVC | 9 | 32 | 0.43 out of 5 | $442 | 3,800 |
| Transmission Main | 7599 | P-7153 | COV | Reservoir Rd. | 12 | PVC | 590 | 32 | 0.43 out of 5 | $442 | 260,978 |
| Transmission Main | 7968 | P-7129 | COV | Reservoir Rd. | 12 | Ductile Iron | 885 | 26 | 0.14 out of 5 | $442 | 391,106 |
| Transmission Main | 7969 | P-7129 | COV | Reservoir Rd. | 12 | Ductile Iron | 945 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 7980 | P-7137 | COV | Reservoir Rd. | 12 | Ductile Iron | 59 | 26 | 0.14 out of 5 | $442 | 25,919 |
| Transmission Main | 8171 | P-7137 | COV | Reservoir Rd. | 12 | Ductile Iron | 50 | 26 | 0.14 out of 5 | $442 | 22,262 |
| Transmission Main | 8172 | P-7137 | COV | Reservoir Rd. | 12 | Ductile Iron | 4 | 26 | 0.14 out of 5 | $442 | 1,866 |
| Distribution Main | 10175 | P-7153 | COV | Reservoir Rd. | 4 | Ductile Iron | 11 | 20 | 1.42 out of 5 | N/A | $0 |
| Transmission Main | 10422 | | COV | Reservoir Rd. | 12 | Ductile Iron | 7 | 30 | 0.14 out of 5 | $442 | 2,991 |
| Transmission Main | 11381 | P-8354 | COV | Reservoir Rd. | 12 | Asbestos Cement | 110 | 54 | 1.14 out of 5 | $442 | 48,755 |
| Transmission Main | 11382 | P-8755 | COV | Reservoir Rd. | 12 | Ductile Iron | 10 | 30 | 0.14 out of 5 | $442 | 4,362 |
| Transmission Main | 11383 | P-7155 | COV | Reservoir Rd. | 12 | PVC | 26 | 31 | 0.43 out of 5 | $442 | 11,560 |
| Transmission Main | 11384 | P-7155 | COV | Reservoir Rd. | 12 | PVC | 5 | 31 | 0.43 out of 5 | $442 | 2,359 |
| Distribution Main | 11395 | P-7156 | COV | Reservoir Rd. | 8 | Asbestos Cement | 4 | 54 | 1.14 out of 5 | $442 | 1,865 |
| Transmission Main | 11396 | P-7153 | COV | Reservoir Rd. | 12 | PVC | 299 | 32 | 0.43 out of 5 | $442 | 132,025 |
| Distribution Main | 1144 | | COV | Reynolds Ct. | 6 | Ductile Iron | 89 | 15 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 1012 | P-8864 | COV | Richard Ct | 1.5 | Galvanized Iron | 88 | UNK | 2.85 out of 5 | $442 | 38,841 |
| Distribution Main | 2667 | P-8865 | COV | Richard Ct | 1.5 | Galvanized Iron | 82 | UNK | 2.85 out of 5 | $442 | 36,367 |
| Distribution Main | 2668 | P-8863 | COV | Richard Ct | 1.5 | Galvanized Iron | 152 | UNK | 2.85 out of 5 | $442 | 67,392 |
| Distribution Main | 2783 | P-8301 | COV | Ridge Ave. | 8 | Ductile Iron | 197 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5329 | P-7514 | COV | Robbins Dr. | 6 | Asbestos Cement | 818 | 70 | 2 out of 5 | $442 | 361,716 |
| Distribution Main | 4951 | P-8140 | COV | Rosebud St. | 6 | Asbestos Cement | 191 | 58 | 1.85 out of 5 | $442 | 84,437 |
| Distribution Main | 4952 | P-8140 | COV | Rosebud St. | 6 | Asbestos Cement | 16 | 58 | 1.85 out of 5 | $442 | 6,984 |
| Distribution Main | 10404 | P-8140 | COV | Rosebud St. | 6 | Ductile Iron | 33 | 11 | 0.71 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2408 | P-8062 | COV | Rosella St. | 6 | Ductile Iron | 525 | 27 | 0.85 out of 5 | $442 | 231,866 |
| Distribution Main | 2919 | P-8062 | COV | Rosella St. | 6 | Ductile Iron | 4 | 27 | 0.85 out of 5 | $442 | 1,856 |
| Transmission Main | 733 | P-8195 | COV | Rosemary St. | 12 | Ductile Iron | 349 | 31 | 0.14 out of 5 | $442 | 154,271 |
| Distribution Main | 740 | P-7487 | COV | Rosemary St. | 6 | Asbestos Cement | 659 | 57 | 1.85 out of 5 | $442 | 291,148 |
| Transmission Main | 1267 | P-8195 | COV | Rosemary St. | 12 | Ductile Iron | 11 | 31 | 0.14 out of 5 | $442 | 4,776 |
| Transmission Main | 1268 | P-8195 | COV | Rosemary St. | 12 | Ductile Iron | 41 | 28 | 0.14 out of 5 | $442 | 18,214 |
| Distribution Main | 1095 | P-7910 | COV | Rosewood Ct. | 6 | Asbestos Cement | 348 | 38 | 1.71 out of 5 | $442 | 153,720 |
| Distribution Main | 8304 | P-8414 | COV | Ross Ct | 8 | Ductile Iron | 322 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9748 | P-8214 | COV | Roundway Dr | 8 | Ductile Iron | 253 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9757 | P-611 | COV | Roundway Dr | 8 | Ductile Iron | 306 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10405 | P-8214 | COV | Roundway Dr | 8 | Ductile Iron | 63 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10406 | P-8214 | COV | Roundway Dr | 8 | Ductile Iron | 35 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10865 | P-8212 | COV | Roundway Dr | 8 | Ductile Iron | 43 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10866 | P-8212 | COV | Roundway Dr | 8 | Ductile Iron | 176 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11599 | P-612 | COV | Roundway Dr | 8 | Ductile Iron | 100 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5257 | P-7023 | COV | Rustic Way | 8 | Asbestos Cement | 386 | 40 | 1 out of 5 | $442 | 170,735 |
| Distribution Main | 2190 | P-8315 | COV | Salvas Ave. | 8 | Ductile Iron | 386 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2191 | P-8315 | COV | Salvas Ave. | 8 | Ductile Iron | 93 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3144 | P-8315 | COV | Salvas Ave. | 8 | Ductile Iron | 74 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9052 | | COV | Salvas Ave. | 8 | Ductile Iron | 5 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11202 | P-8315 | COV | Salvas Ave. | 8 | Ductile Iron | 35 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2797 | P-7590 | COV | Sand St. | 6 | Asbestos Cement | 236 | 56 | 1.85 out of 5 | $442 | 104,093 |
| Distribution Main | 515 | P-7941 | COV | Sandalwood Ct. | 6 | Asbestos Cement | 9 | 53 | 1.85 out of 5 | $442 | 4,144 |
| Distribution Main | 2692 | P-7942 | COV | Sandalwood Ct. | 6 | Asbestos Cement | 43 | 53 | 1.85 out of 5 | $442 | 18,909 |
| Distribution Main | 2693 | P-8383 | COV | Sandalwood Ct. | 6 | Asbestos Cement | 483 | 53 | 1.85 out of 5 | $442 | 213,397 |
| Distribution Main | 2744 | P-8383 | COV | Sandalwood Ct. | 6 | Asbestos Cement | 12 | 53 | 1.85 out of 5 | $442 | 5,493 |
| Distribution Main | 1142 | | COV | Sandlewood Ct | 8 | Ductile Iron | 41 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 513 | P-8381 | COV | Sandlewood Ct. | 6 | Asbestos Cement | 152 | 53 | 1.85 out of 5 | $442 | 67,156 |
| Distribution Main | 518 | P-8381 | COV | Sandlewood Ct. | 6 | Asbestos Cement | 176 | 53 | 1.85 out of 5 | $442 | 77,728 |
| Distribution Main | 519 | P-8382 | COV | Sandlewood Ct. | 6 | Asbestos Cement | 107 | 53 | 1.85 out of 5 | $442 | 47,270 |
| Distribution Main | 10447 | | COV | Sandlewood Ct. | 6 | Asbestos Cement | 23 | 53 | 1.85 out of 5 | $442 | 9,978 |
| Distribution Main | 11070 | P-8381 | COV | Sandlewood Ct. | 6 | Asbestos Cement | 46 | 53 | 1.85 out of 5 | $442 | 20,194 |
| Transmission Main | 60 | P-8930 | COV | Sandy Bottom Rd | 16 | Ductile Iron | 523 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9577 | P-8928 | COV | Sandy Bottom Rd | 8 | Ductile Iron | 19 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10591 | P-8472 | COV | Sandy Bottom Rd | 12 | Ductile Iron | 795 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10592 | P-7843 | COV | Sandy Bottom Rd | 12 | Ductile Iron | 436 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10593 | P-8472 | COV | Sandy Bottom Rd | 8 | Ductile Iron | 15 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11684 | P-8473 | COV | Sandy Bottom Rd | 12 | Ductile Iron | 291 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11685 | P-7843 | COV | Sandy Bottom Rd | 16 | Ductile Iron | 22 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9573 | P-8472 | COV | Sandy Bottom Rd. | 8 | Ductile Iron | 29 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9574 | P-8472 | COV | Sandy Bottom Rd. | 8 | Ductile Iron | 24 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9575 | P-8472 | COV | Sandy Bottom Rd. | 8 | Ductile Iron | 143 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9576 | P-8472 | COV | Sandy Bottom Rd. | 8 | Cast Iron | 194 | 0 | 1.14 out of 5 | N/A | $0 |
| Distribution Main | 8773 | P-8901 | COV | Sawyer Dr | 8 | Ductile Iron | 52 | 8 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 8774 | P-8901 | COV | Sawyer Dr | 8 | Ductile Iron | 3 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4908 | P-8901 | COV | Sawyer Drive | 8 | Asbestos Cement | 216 | 44 | 1.14 out of 5 | $442 | 95,289 |
| Distribution Main | 4909 | P-8901 | COV | Sawyer Drive | 8 | Asbestos Cement | 344 | 44 | 1.14 out of 5 | $442 | 152,049 |
| Distribution Main | 7762 | P-7228 | COV | Second St. | 6 | Asbestos Cement | 168 | 65 | 2 out of 5 | $442 | 74,347 |
| Distribution Main | 8353 | P-7725 | COV | Seneca St. | 8 | Ductile Iron | 305 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8354 | P-8765 | COV | Seneca St. | 8 | Ductile Iron | 197 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7459 | P-7104 | COV | Sharon Dr. | 8 | Ductile Iron | 464 | 26 | 0.14 out of 5 | $442 | 205,200 |
| Distribution Main | 7460 | P-7104 | COV | Sharon Dr. | 8 | Ductile Iron | 798 | 26 | 0.14 out of 5 | $442 | 352,636 |
| Distribution Main | 11803 | P-7104 | COV | Sharon Dr. | 8 | Ductile Iron | 784 | 26 | 0.14 out of 5 | $442 | 346,326 |
| Distribution Main | 11804 | P-7104 | COV | Sharon Dr. | 8 | Ductile Iron | 790 | 26 | 0.14 out of 5 | $442 | 349,055 |
| Distribution Main | 2736 | P-8284 | COV | Sharp St. | 6 | Asbestos Cement | 290 | 56 | 1.85 out of 5 | $442 | 128,248 |
| Distribution Main | 9759 | P-620 | COV | Sheffield Ave | 8 | Ductile Iron | 213 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9784 | P-618 | COV | Sheffield Ave | 8 | Ductile Iron | 193 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10407 | P-615 | COV | Sheffield Ave | 8 | Ductile Iron | 31 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10408 | P-615 | COV | Sheffield Ave | 8 | Ductile Iron | 182 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11600 | P-618 | COV | Sheffield Ave | 8 | Ductile Iron | 128 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3044 | P-7836 | COV | Sheltra Ave | 8 | Asbestos Cement | 793 | 54 | 1.14 out of 5 | $442 | 350,684 |
| Distribution Main | 3045 | P-7836 | COV | Sheltra Ave | 8 | Asbestos Cement | 79 | 54 | 1.14 out of 5 | $442 | 34,752 |
| Distribution Main | 9513 | P-8285 | COV | Sheltra Ave. | 8 | PVC | 603 | 34 | 0.43 out of 5 | $442 | 266,552 |
| Distribution Main | 9514 | P-8285 | COV | Sheltra Ave. | 8 | PVC | 25 | 34 | 0.43 out of 5 | $442 | 10,999 |
| Distribution Main | 29 | P-7383 | COV | Sheri Dr | 8 | Ductile Iron | 5 | 30 | 0.14 out of 5 | $442 | 2,216 |
| Distribution Main | 30 | P-7383 | COV | Sheri Dr | 8 | Ductile Iron | 155 | 30 | 0.14 out of 5 | $442 | 68,322 |
| Distribution Main | 450 | P-7382 | COV | Sheri Dr. | 8 | Ductile Iron | 233 | 30 | 0.14 out of 5 | $442 | 102,968 |
| Distribution Main | 451 | P-7382 | COV | Sheri Dr. | 8 | Ductile Iron | 196 | 30 | 0.14 out of 5 | $442 | 86,812 |
| Distribution Main | 1463 | P-7381 | COV | Sheri Dr. | 8 | Ductile Iron | 119 | 30 | 0.14 out of 5 | $442 | 52,636 |
| Distribution Main | 448 | P-7374 | COV | Short Way Dr. | 6 | Asbestos Cement | 54 | 48 | 1.85 out of 5 | $442 | 23,757 |
| Distribution Main | 1473 | P-7374 | COV | Short Way Dr. | 6 | Asbestos Cement | 237 | 48 | 1.85 out of 5 | $442 | 104,792 |
| Distribution Main | 1474 | P-7374 | COV | Short Way Dr. | 6 | Asbestos Cement | 22 | 48 | 1.85 out of 5 | $442 | 9,789 |
| Distribution Main | 9780 | P-627 | COV | Sidney St | 8 | Ductile Iron | 152 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3065 | P-7359 | COV | Silo Lane | 8 | Ductile Iron | 230 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4907 | P-7105 | COV | Silver Maple Dr. | 8 | Asbestos Cement | 333 | 41 | 1.14 out of 5 | $442 | 147,111 |
| Distribution Main | 6112 | P-7121 | COV | Silver Maple Dr. | 8 | Ductile Iron | 292 | 28 | 0.14 out of 5 | $442 | 128,893 |
| Distribution Main | 6315 | P-7112 | COV | Silver Maple Dr. | 8 | Ductile Iron | 199 | 28 | 0.14 out of 5 | $442 | 87,930 |
| Distribution Main | 6316 | P-7113 | COV | Silver Maple Dr. | 8 | Asbestos Cement | 95 | 41 | 1.14 out of 5 | $442 | 42,068 |
| Distribution Main | 7455 | P-7108 | COV | Silver Maple Dr. | 8 | Asbestos Cement | 70 | 41 | 1.14 out of 5 | $442 | 30,827 |
| Distribution Main | 7461 | P-7108 | COV | Silver Maple Dr. | 8 | Asbestos Cement | 552 | 41 | 1.14 out of 5 | $442 | 244,052 |
| Distribution Main | 7975 | P-7118 | COV | Silver Maple Dr. | 8 | Ductile Iron | 380 | 28 | 0.14 out of 5 | $442 | 167,947 |
| Distribution Main | 8729 | P-7113 | COV | Silver Maple Dr. | 8 | Asbestos Cement | 86 | 41 | 1.14 out of 5 | $442 | 38,096 |
| Distribution Main | 8730 | P-7113 | COV | Silver Maple Dr. | 8 | Asbestos Cement | 14 | 41 | 1.14 out of 5 | $442 | 6,047 |
| Distribution Main | 10088 | P-7121 | COV | Silver Maple Dr. | 8 | Ductile Iron | 4 | 28 | 0.14 out of 5 | $442 | 1,654 |
| Distribution Main | 10089 | P-7121 | COV | Silver Maple Dr. | 8 | Ductile Iron | 56 | 28 | 0.14 out of 5 | $442 | 24,965 |
| Distribution Main | 10090 | P-7118 | COV | Silver Maple Dr. | 8 | Ductile Iron | 61 | 28 | 0.14 out of 5 | $442 | 27,004 |
| Distribution Main | 2196 | P-7749 | COV | Sooner Ln. | 8 | Ductile Iron | 334 | 27 | 0.14 out of 5 | $442 | 147,765 |
| Distribution Main | 1687 | P-604 | COV | Sophia'S Way | 6 | Ductile Iron | 213 | 29 | 0.85 out of 5 | $442 | 94,294 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9744 | P-1958 | COV | Sophia'S Way | 8 | Ductile Iron | 30 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9745 | P-1958 | COV | Sophia'S Way | 8 | Ductile Iron | 4 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9746 | P-1959 | COV | Sophia'S Way | 6 | Ductile Iron | 18 | 8 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 556 | P-7710 | COV | South Glen Dr. | 6 | Asbestos Cement | 259 | 60 | 1.85 out of 5 | $442 | 114,383 |
| Distribution Main | 557 | P-7710 | COV | South Glen Dr. | 6 | Asbestos Cement | 577 | 60 | 1.85 out of 5 | $442 | 254,884 |
| Transmission Main | 582 | P-7535 | COV | South Main St. | 16 | Cast Iron | 345 | 129 | 1.86 out of 5 | $442 | 152,636 |
| Transmission Main | 793 | P-7586 | COV | South Main St. | 16 | Cast Iron | 81 | 129 | 1.86 out of 5 | $442 | 35,905 |
| Transmission Main | 794 | P-7537 | COV | South Main St. | 16 | Cast Iron | 4 | 129 | 1.86 out of 5 | $442 | 1,939 |
| Transmission Main | 795 | P-7537 | COV | South Main St. | 16 | Cast Iron | 347 | 129 | 1.86 out of 5 | $442 | 153,409 |
| Transmission Main | 1264 | P-7535 | COV | South Main St. | 16 | Cast Iron | 8 | 129 | 1.86 out of 5 | $442 | 3,664 |
| Distribution Main | 1648 | P-7526 | COV | South Main St. | 8 | Asbestos Cement | 302 | 71 | 1.29 out of 5 | $442 | 133,485 |
| Distribution Main | 1649 | P-7526 | COV | South Main St. | 8 | Asbestos Cement | 182 | 71 | 1.29 out of 5 | $442 | 80,610 |
| Distribution Main | 1846 | P-7551 | COV | South Main St. | 8 | Asbestos Cement | 41 | 71 | 1.29 out of 5 | $442 | 17,942 |
| Distribution Main | 1847 | P-7551 | COV | South Main St. | 8 | Asbestos Cement | 164 | 71 | 1.29 out of 5 | $442 | 72,325 |
| Distribution Main | 1848 | P-7550 | COV | South Main St. | 8 | Asbestos Cement | 264 | 71 | 1.29 out of 5 | $442 | 116,791 |
| Distribution Main | 1869 | P-7534 | COV | South Main St. | 8 | Asbestos Cement | 405 | 71 | 1.29 out of 5 | $442 | 178,948 |
| Distribution Main | 1870 | P-7525 | COV | South Main St. | 8 | Asbestos Cement | 266 | 71 | 1.29 out of 5 | $442 | 117,598 |
| Transmission Main | 2366 | P-7535 | COV | South Main St. | 16 | Cast Iron | 127 | 129 | 1.86 out of 5 | $442 | 55,981 |
| Transmission Main | 2367 | P-8933 | COV | South Main St. | 16 | Cast Iron | 30 | 129 | 1.86 out of 5 | $442 | 13,042 |
| Transmission Main | 2368 | P-8933 | COV | South Main St. | 16 | Cast Iron | 8 | 129 | 1.86 out of 5 | $442 | 3,383 |
| Transmission Main | 2808 | P-7536 | COV | South Main St. | 16 | Cast Iron | 134 | 129 | 1.86 out of 5 | $442 | 59,056 |
| Transmission Main | 2809 | P-7586 | COV | South Main St. | 16 | Cast Iron | 174 | 129 | 1.86 out of 5 | $442 | 76,768 |
| Transmission Main | 2812 | P-7257 | COV | South Main St. | 16 | Cast Iron | 14 | 129 | 1.86 out of 5 | $442 | 6,019 |
| Distribution Main | 5320 | P-7511 | COV | South Main St. | 8 | Asbestos Cement | 124 | 71 | 1.29 out of 5 | $442 | 55,008 |
| Distribution Main | 5328 | P-7511 | COV | South Main St. | 8 | Asbestos Cement | 28 | 71 | 1.29 out of 5 | $442 | 12,274 |
| Distribution Main | 5337 | P-7517 | COV | South Main St. | 8 | Asbestos Cement | 366 | 71 | 1.29 out of 5 | $442 | 161,787 |
| Distribution Main | 5338 | P-7517 | COV | South Main St. | 8 | Asbestos Cement | 394 | 71 | 1.29 out of 5 | $442 | 174,158 |
| Distribution Main | 5347 | P-7511 | COV | South Main St. | 8 | Asbestos Cement | 194 | 71 | 1.29 out of 5 | $442 | 85,706 |
| Distribution Main | 5348 | P-7524 | COV | South Main St. | 8 | Asbestos Cement | 241 | 71 | 1.29 out of 5 | $442 | 106,617 |
| Distribution Main | 5349 | P-7524 | COV | South Main St. | 8 | Asbestos Cement | 123 | 71 | 1.29 out of 5 | $442 | 54,249 |
| Distribution Main | 5350 | P-7523 | COV | South Main St. | 8 | Asbestos Cement | 206 | 71 | 1.29 out of 5 | $442 | 91,014 |
| Distribution Main | 7689 | P-7517 | COV | South Main St. | 8 | Asbestos Cement | 491 | 71 | 1.29 out of 5 | $442 | 216,860 |
| Transmission Main | 11088 | P-7586 | COV | South Main St. | 16 | Cast Iron | 15 | 129 | 1.86 out of 5 | $442 | 6,605 |
| Distribution Main | 386 | P-7934 | COV | South Pond Dr. | 8 | Ductile Iron | 115 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 387 | P-7932 | COV | South Pond Dr. | 8 | Ductile Iron | 669 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 782 | P-7932 | COV | South Pond Dr. | 8 | Ductile Iron | 69 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 783 | P-7932 | COV | South Pond Dr. | 8 | Ductile Iron | 148 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 784 | P-7931 | COV | South Pond Dr. | 12 | Ductile Iron | 622 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 785 | P-7932 | COV | South Pond Dr. | 8 | Ductile Iron | 149 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1009 | P-7934 | COV | South Pond Dr. | 8 | Ductile Iron | 534 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9663 | P-7932 | COV | South Pond Dr. | 8 | Ductile Iron | 193 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9664 | P-7934 | COV | South Pond Dr. | 8 | Ductile Iron | 352 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9665 | P-7934 | COV | South Pond Dr. | 8 | Ductile Iron | 35 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1226 | P-8015 | COV | South St. | 6 | Ductile Iron | 1 | 14 | 0.71 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 1227 | P-8015 | COV | South St. | 6 | Asbestos Cement | 173 | 129 | 2.29 out of 5 | $442 | 76,388 |
| Distribution Main | 2702 | P-8015 | COV | South St. | 6 | Cast Iron | 512 | 129 | 2.57 out of 5 | $442 | 226,513 |
| Distribution Main | 2726 | P-8015 | COV | South St. | 8 | Ductile Iron | 26 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1506 | P-7561 | COV | Spencer St. | 6 | Cast Iron | 434 | 129 | 2.57 out of 5 | $442 | 191,677 |
| Distribution Main | 3494 | P-7572 | COV | Spencer St. | 6 | Cast Iron | 104 | 129 | 2.57 out of 5 | $442 | 46,002 |
| Distribution Main | 1952 | P-9032 | COV | St Vincent Depaul | 6 | Asbestos Cement | 6 | 80 | 2 out of 5 | $442 | 2,806 |
| Distribution Main | 3071 | P-9032 | COV | St Vincent Depaul | 6 | Asbestos Cement | 8 | 80 | 2 out of 5 | $442 | 3,356 |
| Distribution Main | 3073 | P-9032 | COV | St Vincent Depaul | 6 | Asbestos Cement | 301 | 80 | 2 out of 5 | $442 | 132,980 |
| Distribution Main | 3074 | P-9032 | COV | St Vincent Depaul | 6 | Asbestos Cement | 224 | 80 | 2 out of 5 | $442 | 99,181 |
| Distribution Main | 799 | P-7262 | COV | Station St. | 8 | Asbestos Cement | 126 | 56 | 1.14 out of 5 | $442 | 55,698 |
| Distribution Main | 1475 | P-8324 | COV | Station St. | 8 | Asbestos Cement | 1,044 | 56 | 1.14 out of 5 | $442 | 461,296 |
| Distribution Main | 1476 | P-8324 | COV | Station St. | 8 | Asbestos Cement | 614 | 56 | 1.14 out of 5 | $442 | 271,268 |
| Distribution Main | 1477 | P-8324 | COV | Station St. | 8 | Asbestos Cement | 705 | 56 | 1.14 out of 5 | $442 | 311,415 |
| Distribution Main | 2370 | P-7262 | COV | Station St. | 8 | Asbestos Cement | 588 | 56 | 1.85 out of 5 | $442 | 259,849 |
| Distribution Main | 2371 | P-7262 | COV | Station St. | 8 | Asbestos Cement | 20 | 56 | 1.14 out of 5 | $442 | 8,996 |
| Distribution Main | 2373 | P-8325 | COV | Station St. | 8 | Asbestos Cement | 691 | 56 | 1.14 out of 5 | $442 | 305,334 |
| Distribution Main | 2374 | P-8325 | COV | Station St. | 8 | Asbestos Cement | 2 | 56 | 1.14 out of 5 | $442 | 1,034 |
| Distribution Main | 2815 | P-8914 | COV | Station St. | 8 | Asbestos Cement | 305 | 56 | 1.14 out of 5 | $442 | 134,656 |
| Transmission Main | 2818 | P-7845 | COV | Station St. | 12 | Asbestos Cement | 9 | 78 | 1.29 out of 5 | $442 | 3,922 |
| Distribution Main | 3005 | P-7269 | COV | Station St. | 8 | Asbestos Cement | 228 | 56 | 1.14 out of 5 | $442 | 100,668 |
| Distribution Main | 3006 | P-7269 | COV | Station St. | 8 | Asbestos Cement | 186 | 56 | 1.14 out of 5 | $442 | 82,187 |
| Distribution Main | 5047 | P-7343 | COV | Station St. | 8 | Asbestos Cement | 16 | 56 | 1.14 out of 5 | $442 | 7,046 |
| Distribution Main | 5927 | P-7343 | COV | Station St. | 8 | Asbestos Cement | 409 | 56 | 1.14 out of 5 | $442 | 180,740 |
| Distribution Main | 5928 | P-7343 | COV | Station St. | 8 | Asbestos Cement | 39 | 56 | 1.14 out of 5 | $442 | 17,205 |
| Distribution Main | 5929 | P-7343 | COV | Station St. | 8 | Asbestos Cement | 909 | 56 | 1.14 out of 5 | $442 | 401,858 |
| Distribution Main | 5930 | P-7343 | COV | Station St. | 8 | Asbestos Cement | 463 | 56 | 1.14 out of 5 | $442 | 204,426 |
| Distribution Main | 5931 | P-8823 | COV | Station St. | 8 | Asbestos Cement | 838 | 56 | 1.14 out of 5 | $442 | 370,462 |
| Distribution Main | 7839 | P-8824 | COV | Station St. | 8 | Asbestos Cement | 15 | 56 | 1.14 out of 5 | $442 | 6,752 |
| Distribution Main | 7840 | P-8824 | COV | Station St. | 8 | Asbestos Cement | 311 | 56 | 1.14 out of 5 | $442 | 137,301 |
| Transmission Main | 10108 | P-7845 | COV | Station St. | 12 | Asbestos Cement | 7 | 78 | 1.29 out of 5 | $442 | 3,166 |
| Distribution Main | 11972 | P-8325 | COV | Station St. | 8 | Asbestos Cement | 339 | 56 | 1.14 out of 5 | $442 | 149,716 |
| Distribution Main | 7782 | P-7420 | COV | Steere Ln. | 6 | Asbestos Cement | 115 | 53 | 1.85 out of 5 | $442 | 50,918 |
| Distribution Main | 7784 | P-7421 | COV | Steere Ln. | 6 | Asbestos Cement | 333 | 53 | 1.85 out of 5 | $442 | 146,978 |
| Distribution Main | 7785 | P-7420 | COV | Steere Ln. | 6 | Asbestos Cement | 12 | 53 | 1.85 out of 5 | $442 | 5,523 |
| Distribution Main | 1029 | P-8879 | COV | Stewart Lane | 8 | Asbestos Cement | 3 | UNK | 0.85 out of 5 | $442 | 1,161 |
| Distribution Main | 2467 | P-8879 | COV | Stewart Lane | 8 | Ductile Iron | 53 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 1871 | P-7529 | COV | Stone St. | 6 | Cast Iron | 322 | 79 | 2.28 out of 5 | $442 | 142,254 |
| Distribution Main | 5050 | P-7530 | COV | Stone St. | 2 | Cast Iron | 304 | 79 | 3 out of 5 | $442 | 134,445 |
| Distribution Main | 5052 | P-8936 | COV | Stone St. | 6 | Cast Iron | 90 | 79 | 2.28 out of 5 | $442 | 39,624 |
| Distribution Main | 5053 | P-8936 | COV | Stone St. | 6 | Cast Iron | 56 | 79 | 2.28 out of 5 | $442 | 24,962 |
| Distribution Main | 5057 | P-8321 | COV | Stone St. | 6 | Cast Iron | 103 | 79 | 2.28 out of 5 | $442 | 45,389 |
| Distribution Main | 7883 | P-7215 | COV | Stoney Hill Cir. | 8 | Ductile Iron | 373 | 29 | 0.14 out of 5 | $442 | 164,750 |
| Distribution Main | 7884 | P-7215 | COV | Stoney Hill Cir. | 8 | Ductile Iron | 493 | 29 | 0.14 out of 5 | $442 | 218,018 |
| Distribution Main | 7890 | P-7217 | COV | Stoney Hill Cir. | 8 | Ductile Iron | 132 | 29 | 0.14 out of 5 | $442 | 58,431 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 7891 | P-7217 | COV | Stoney Hill Cir. | 8 | Ductile Iron | 267 | 29 | 0.14 out of 5 | $442 | 118,143 |
| Distribution Main | 5229 | P-7450 | COV | Stratford Dr. | 8 | Ductile Iron | 404 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5230 | P-7450 | COV | Stratford Dr. | 8 | Ductile Iron | 35 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 7593 | P-7087 | COV | Sugar Maple Dr. | 12 | Ductile Iron | 270 | 28 | 0.14 out of 5 | $442 | 119,471 |
| Transmission Main | 7595 | P-7084 | COV | Sugar Maple Dr. | 12 | Ductile Iron | 402 | 28 | 0.14 out of 5 | $442 | 177,591 |
| Transmission Main | 7772 | P-7085 | COV | Sugar Maple Dr. | 12 | Ductile Iron | 275 | 28 | 0.14 out of 5 | $442 | 121,585 |
| Transmission Main | 7773 | P-7087 | COV | Sugar Maple Dr. | 12 | Ductile Iron | 4 | 28 | 0.14 out of 5 | $442 | 1,976 |
| Transmission Main | 8297 | P-7075 | COV | Sugar Maple Dr. | 12 | Ductile Iron | 78 | 28 | 0.14 out of 5 | $442 | 34,663 |
| Transmission Main | 8298 | P-7085 | COV | Sugar Maple Dr. | 12 | Ductile Iron | 58 | 28 | 0.14 out of 5 | $442 | 25,766 |
| Transmission Main | 8299 | P-7075 | COV | Sugar Maple Dr. | 12 | Ductile Iron | 68 | 28 | 0.14 out of 5 | $442 | 30,235 |
| Transmission Main | 8301 | P-7075 | COV | Sugar Maple Dr. | 12 | Ductile Iron | 390 | 28 | 0.14 out of 5 | $442 | 172,347 |
| Transmission Main | 8326 | P-7073 | COV | Sugar Maple Dr. | 12 | Ductile Iron | 366 | 28 | 0.14 out of 5 | $442 | 161,674 |
| Transmission Main | 8327 | P-7083 | COV | Sugar Maple Dr. | 12 | Ductile Iron | 320 | 28 | 0.14 out of 5 | $442 | 141,351 |
| Transmission Main | 8328 | P-7083 | COV | Sugar Maple Dr. | 12 | Ductile Iron | 107 | 28 | 0.14 out of 5 | $442 | 47,440 |
| Transmission Main | 11393 | P-7087 | COV | Sugar Maple Dr. | 12 | Ductile Iron | 14 | 28 | 0.14 out of 5 | $442 | 6,203 |
| Transmission Main | 11394 | P-7084 | COV | Sugar Maple Dr. | 12 | Ductile Iron | 4 | 28 | 0.14 out of 5 | $442 | 1,736 |
| Distribution Main | 583 | P-7532 | COV | Sunapee Ct. | 6 | Asbestos Cement | 22 | 62 | 2 out of 5 | $442 | 9,715 |
| Distribution Main | 584 | P-7532 | COV | Sunapee Ct. | 6 | Asbestos Cement | 135 | 62 | 2 out of 5 | $442 | 59,619 |
| Distribution Main | 5051 | P-7533 | COV | Sunapee Ct. | 6 | Asbestos Cement | 604 | 62 | 2 out of 5 | $442 | 266,764 |
| Distribution Main | 9080 | P-8979 | COV | Sunset Ave | 6 | Asbestos Cement | 41 | UNK | 1.56 out of 5 | $442 | 17,927 |
| Distribution Main | 9081 | P-8979 | COV | Sunset Ave | 6 | Asbestos Cement | 152 | UNK | 1.56 out of 5 | $442 | 67,326 |
| Distribution Main | 1066 | P-8987 | COV | Sunset Street | 2 | Copper | 254 | 79 | 2.43 out of 5 | $442 | 112,069 |
| Distribution Main | 2470 | P-8987 | COV | Sunset Street | 2 | Copper | 12 | 79 | 2.43 out of 5 | $442 | 5,246 |
| Distribution Main | 2640 | P-8987 | COV | Sunset Street | 2 | Copper | 8 | 79 | 2.43 out of 5 | $442 | 3,395 |
| Distribution Main | 8079 | P-9023 | COV | Sweet Fern Ln | 8 | Ductile Iron | 32 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8080 | P-9023 | COV | Sweet Fern Ln | 8 | Ductile Iron | 836 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11791 | P-9023 | COV | Sweet Fern Ln | 8 | Ductile Iron | 424 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7163 | P-7296 | COV | Sweetwater Dr. | 8 | Asbestos Cement | 22 | 41 | 1.14 out of 5 | $442 | 9,627 |
| Distribution Main | 7165 | P-7295 | COV | Sweetwater Dr. | 8 | Asbestos Cement | 459 | 41 | 1.14 out of 5 | $442 | 202,699 |
| Distribution Main | 7905 | P-7296 | COV | Sweetwater Dr. | 8 | Asbestos Cement | 73 | 41 | 1.14 out of 5 | $442 | 32,257 |
| Distribution Main | 7906 | P-7296 | COV | Sweetwater Dr. | 8 | Asbestos Cement | 936 | 41 | 1.14 out of 5 | $442 | 413,640 |
| Distribution Main | 11976 | P-7296 | COV | Sweetwater Dr. | 8 | Asbestos Cement | 103 | 41 | 1.14 out of 5 | $442 | 45,558 |
| Distribution Main | 7570 | P-7451 | COV | Sycamore Dr. | 8 | Ductile Iron | 328 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7581 | P-7453 | COV | Sycamore Dr. | 8 | Ductile Iron | 406 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7582 | P-7453 | COV | Sycamore Dr. | 8 | Ductile Iron | 31 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7583 | P-7449 | COV | Sycamore Dr. | 8 | Ductile Iron | 426 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7584 | P-7448 | COV | Sycamore Dr. | 8 | Ductile Iron | 413 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7585 | P-7448 | COV | Sycamore Dr. | 8 | Ductile Iron | 7 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7652 | P-8965 | COV | Sycamore Dr. | 8 | Ductile Iron | 36 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1957 | P-7831 | COV | Taft St. | 6 | Cast Iron | 548 | 132 | 2.57 out of 5 | $442 | 242,066 |
| Distribution Main | 1958 | P-7831 | COV | Taft St. | 6 | Cast Iron | 136 | 132 | 2.57 out of 5 | $442 | 60,177 |
| Distribution Main | 3156 | P-7834 | COV | Taft St. | 6 | Asbestos Cement | 506 | 54 | 1.85 out of 5 | $442 | 223,831 |
| Distribution Main | 3157 | P-7834 | COV | Taft St. | 6 | Asbestos Cement | 46 | 54 | 1.85 out of 5 | $442 | 20,216 |
| Distribution Main | 9515 | P-7836 | COV | Taft St. | 8 | Asbestos Cement | 485 | 54 | 1.14 out of 5 | $442 | 214,554 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9516 | P-7836 | COV | Taft St. | 8 | Asbestos Cement | 40 | 54 | 1.14 out of 5 | $442 | 17,624 |
| Distribution Main | 853 | P-7125 | COV | Tallwood Dr. | 8 | Ductile Iron | 62 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 854 | P-7125 | COV | Tallwood Dr. | 8 | Ductile Iron | 342 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7887 | P-7127 | COV | Tallwood Dr. | 8 | Ductile Iron | 374 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11092 | P-7125 | COV | Tallwood Dr. | 8 | Ductile Iron | 15 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7970 | P-7119 | COV | Tamarack Tr. | 8 | Ductile Iron | 643 | 28 | 0.14 out of 5 | $442 | 284,166 |
| Distribution Main | 7971 | P-7119 | COV | Tamarack Tr. | 8 | Ductile Iron | 59 | 28 | 0.14 out of 5 | $442 | 26,106 |
| Distribution Main | 7972 | P-7119 | COV | Tamarack Tr. | 8 | Ductile Iron | 199 | 27 | 0.14 out of 5 | $442 | 88,030 |
| Distribution Main | 7164 | P-7313 | COV | Teakwood Dr. East | 8 | Asbestos Cement | 460 | 40 | 1 out of 5 | $442 | 203,244 |
| Distribution Main | 7875 | P-7298 | COV | Teakwood Dr. East | 8 | Asbestos Cement | 112 | 40 | 1 out of 5 | $442 | 49,504 |
| Distribution Main | 7876 | P-7298 | COV | Teakwood Dr. East | 8 | Asbestos Cement | 11 | 40 | 1 out of 5 | $442 | 4,867 |
| Distribution Main | 7909 | P-7297 | COV | Teakwood Dr. East | 8 | Asbestos Cement | 432 | 40 | 1 out of 5 | $442 | 190,943 |
| Distribution Main | 7881 | P-7309 | COV | Teakwood Dr. West | 8 | Asbestos Cement | 150 | 40 | 1 out of 5 | $442 | 66,171 |
| Distribution Main | 7892 | P-7308 | COV | Teakwood Dr. West | 8 | Asbestos Cement | 438 | 40 | 1 out of 5 | $442 | 193,410 |
| Distribution Main | 7893 | P-7307 | COV | Teakwood Dr. West | 8 | Asbestos Cement | 280 | 40 | 1 out of 5 | $442 | 123,944 |
| Distribution Main | 7898 | P-7309 | COV | Teakwood Dr. West | 8 | Asbestos Cement | 13 | 40 | 1 out of 5 | $442 | 5,540 |
| Distribution Main | 7899 | P-7309 | COV | Teakwood Dr. West | 8 | Asbestos Cement | 25 | 40 | 1 out of 5 | $442 | 10,848 |
| Distribution Main | 10236 | P-8812 | COV | Teakwood Drive | 8 | Ductile Iron | 203 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10237 | | COV | Teakwood Drive | 8 | Ductile Iron | 63 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10238 | P-8811 | COV | Teakwood Drive | 8 | Ductile Iron | 137 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10239 | P-8811 | COV | Teakwood Drive | 8 | Ductile Iron | 541 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10240 | P-8811 | COV | Teakwood Drive | 8 | Ductile Iron | 33 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10241 | P-8810 | COV | Teakwood Drive | 8 | Ductile Iron | 198 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10975 | P-8809 | COV | Teakwood Drive | 8 | Ductile Iron | 349 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11645 | P-8811 | COV | Teakwood Drive | 8 | Ductile Iron | 36 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10804 | P-7267 | COV | Tero Dr | 8 | Ductile Iron | 344 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10805 | P-7267 | COV | Tero Dr | 8 | Ductile Iron | 218 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3004 | | COV | Tero Dr. | 6 | Asbestos Cement | 7 | 44 | 1.85 out of 5 | $442 | 3,178 |
| Distribution Main | 3097 | P-8134 | COV | Terrace Ave. | 4 | Cast Iron | 517 | 129 | 3.29 out of 5 | $442 | 228,700 |
| Distribution Main | 9058 | | COV | The Crossroads | 4 | Ductile Iron | 21 | 18 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 7156 | P-7195 | COV | Thompson Dr. | 8 | Asbestos Cement | 554 | 45 | 1.14 out of 5 | $442 | 244,677 |
| Distribution Main | 2880 | P-8163 | COV | Tiffany Rd. | 8 | Asbestos Cement | 235 | 43 | 1.14 out of 5 | $442 | 104,002 |
| Distribution Main | 2881 | P-8163 | COV | Tiffany Rd. | 8 | Asbestos Cement | 52 | 43 | 1.14 out of 5 | $442 | 23,079 |
| Transmission Main | 4072 | P-8167 | COV | Tiffany Rd. | 12 | PVC | 317 | 32 | 0.43 out of 5 | $442 | 140,253 |
| Distribution Main | 4771 | P-8192 | COV | Tiffany Rd. | 8 | PVC | 709 | 32 | 0.43 out of 5 | $442 | 313,486 |
| Distribution Main | 4772 | P-8192 | COV | Tiffany Rd. | 8 | PVC | 267 | 32 | 0.43 out of 5 | $442 | 117,909 |
| Distribution Main | 11911 | P-8192 | COV | Tiffany Rd. | 8 | PVC | 686 | 32 | 0.43 out of 5 | $442 | 303,284 |
| Transmission Main | 8064 | P-8712 | COV | Tiffany Road | 12 | Ductile Iron | 766 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8073 | P-9027 | COV | Tiffany Road | 8 | Ductile Iron | 12 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8074 | P-9027 | COV | Tiffany Road | 8 | Ductile Iron | 2 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10140 | P-9026 | COV | Tiffany Road | 12 | Ductile Iron | 13 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9952 | P-8401 | COV | Timber Tr | 8 | Ductile Iron | 294 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9953 | P-8403 | COV | Timber Tr | 8 | Ductile Iron | 12 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9954 | P-8403 | COV | Timber Tr | 8 | Ductile Iron | 147 | 9 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9955 | P-8403 | COV | Timber Tr | 8 | Ductile Iron | 384 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9956 | P-8403 | COV | Timber Tr | 8 | Ductile Iron | 371 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9957 | P-8402 | COV | Timber Tr | 8 | Ductile Iron | 52 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9958 | P-8402 | COV | Timber Tr | 8 | Ductile Iron | 255 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10844 | P-8405 | COV | Timber Tr | 8 | Ductile Iron | 58 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10845 | P-8405 | COV | Timber Tr | 8 | Ductile Iron | 4 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10183 | | COV | Timber Trail | 8 | Ductile Iron | 459 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10184 | | COV | Timber Trail | 8 | Ductile Iron | 151 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10185 | | COV | Timber Trail | 8 | Ductile Iron | 416 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10186 | | COV | Timber Trail | 8 | Ductile Iron | 391 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12125 | | COV | Timber Trail | 8 | Ductile Iron | 114 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10683 | | COV | Tiogue Av | 12 | Ductile Iron | 11 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 8065 | | COV | Tiogue Ave | 12 | Ductile Iron | 1,133 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8066 | P-8526 | COV | Tiogue Ave | 12 | Ductile Iron | 169 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8067 | P-8526 | COV | Tiogue Ave | 12 | Ductile Iron | 5 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8068 | | COV | Tiogue Ave | 12 | Ductile Iron | 79 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8077 | P-7745 | COV | Tiogue Ave | 12 | Ductile Iron | 20 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8344 | | COV | Tiogue Ave | 12 | Ductile Iron | 10 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8345 | | COV | Tiogue Ave | 12 | Ductile Iron | 5 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8346 | | COV | Tiogue Ave | 12 | Ductile Iron | 22 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8347 | | COV | Tiogue Ave | 12 | Ductile Iron | 4 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8348 | P-7745 | COV | Tiogue Ave | 12 | Ductile Iron | 9 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8349 | P-7745 | COV | Tiogue Ave | 12 | Ductile Iron | 106 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8350 | | COV | Tiogue Ave | 12 | Ductile Iron | 11 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8351 | | COV | Tiogue Ave | 12 | Ductile Iron | 34 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9334 | | COV | Tiogue Ave | 2 | Copper | 22 | 9 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 9640 | | COV | Tiogue Ave | 6 | Ductile Iron | 22 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9897 | | COV | Tiogue Ave | 4 | PVC | 51 | UNK | 1.71 out of 5 | $442 | 22,704 |
| Distribution Main | 10286 | | COV | Tiogue Ave | 8 | Ductile Iron | 3 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10292 | | COV | Tiogue Ave | 8 | Ductile Iron | 7 | 26 | 0.14 out of 5 | $442 | 3,044 |
| Transmission Main | 11164 | | COV | Tiogue Ave | 12 | Ductile Iron | 28 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11419 | | COV | Tiogue Ave | 12 | Ductile Iron | 5 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11420 | P-8526 | COV | Tiogue Ave | 12 | Ductile Iron | 67 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11422 | | COV | Tiogue Ave | 12 | Ductile Iron | 9 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11423 | | COV | Tiogue Ave | 12 | Ductile Iron | 20 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 526 | P-7564 | COV | Tiogue Ave. | 12 | Ductile Iron | 65 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 527 | P-7564 | COV | Tiogue Ave. | 12 | Ductile Iron | 247 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 530 | P-7717 | COV | Tiogue Ave. | 12 | Ductile Iron | 38 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 532 | P-7715 | COV | Tiogue Ave. | 20 | Ductile Iron | 1,722 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 533 | P-8298 | COV | Tiogue Ave. | 8 | Cast Iron | 312 | 24 | 1.14 out of 5 | N/A | $0 |
| Distribution Main | 534 | P-8298 | COV | Tiogue Ave. | 8 | Cast Iron | 6 | 24 | 1.14 out of 5 | N/A | $0 |
| Transmission Main | 701 | P-9006 | COV | Tiogue Ave. | 16 | Ductile Iron | 197 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 702 | P-9006 | COV | Tiogue Ave. | 16 | Ductile Iron | 449 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 703 | P-7609 | COV | Tiogue Ave. | 20 | Ductile Iron | 204 | 19 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 704 | P-7508 | COV | Tiogue Ave. | 12 | Asbestos Cement | 7 | 57 | 1.14 out of 5 | $442 | 2,904 |
| Transmission Main | 705 | P-7508 | COV | Tiogue Ave. | 12 | Asbestos Cement | 280 | 57 | 1.14 out of 5 | $442 | 123,748 |
| Transmission Main | 708 | P-7609 | COV | Tiogue Ave. | 20 | Ductile Iron | 90 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1290 | P-7743 | COV | Tiogue Ave. | 12 | Ductile Iron | 402 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1291 | P-7743 | COV | Tiogue Ave. | 12 | Ductile Iron | 279 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1292 | P-8475 | COV | Tiogue Ave. | 12 | Ductile Iron | 947 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1294 | | COV | Tiogue Ave. | | Unknown | 16 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 1295 | P-8296 | COV | Tiogue Ave. | 16 | Ductile Iron | 404 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1296 | P-8296 | COV | Tiogue Ave. | 16 | Ductile Iron | 316 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1297 | P-7563 | COV | Tiogue Ave. | 12 | Ductile Iron | 400 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1298 | P-7563 | COV | Tiogue Ave. | 12 | Ductile Iron | 340 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1299 | | COV | Tiogue Ave. | 2 | Unknown | 9 | UNK | 1.42 out of 5 | $442 | 4,059 |
| Distribution Main | 1300 | | COV | Tiogue Ave. | 2 | Unknown | 26 | UNK | 1.42 out of 5 | $442 | 11,590 |
| Transmission Main | 1301 | P-8296 | COV | Tiogue Ave. | 16 | Ductile Iron | 420 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1302 | P-8296 | COV | Tiogue Ave. | 16 | Ductile Iron | 672 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1303 | | COV | Tiogue Ave. | 12 | Ductile Iron | 6 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1304 | P-9005 | COV | Tiogue Ave. | 12 | Ductile Iron | 218 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1305 | P-9005 | COV | Tiogue Ave. | 12 | Ductile Iron | 197 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1308 | P-7509 | COV | Tiogue Ave. | 12 | Asbestos Cement | 845 | 57 | 1.14 out of 5 | $442 | 373,582 |
| Transmission Main | 1309 | P-7509 | COV | Tiogue Ave. | 12 | Asbestos Cement | 882 | 57 | 1.14 out of 5 | $442 | 389,815 |
| Transmission Main | 1310 | P-8943 | COV | Tiogue Ave. | 12 | Asbestos Cement | 392 | 57 | 1.14 out of 5 | $442 | 173,127 |
| Transmission Main | 1311 | P-7608 | COV | Tiogue Ave. | 20 | Ductile Iron | 404 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1715 | P-7751 | COV | Tiogue Ave. | 12 | Ductile Iron | 157 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1716 | P-7751 | COV | Tiogue Ave. | 12 | Ductile Iron | 750 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2295 | P-7563 | COV | Tiogue Ave. | 12 | Ductile Iron | 357 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2296 | P-7563 | COV | Tiogue Ave. | 12 | Asbestos Cement | 420 | 0 | 0.85 out of 5 | N/A | $0 |
| Transmission Main | 2298 | | COV | Tiogue Ave. | 12 | Unknown | 10 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 2299 | P-8296 | COV | Tiogue Ave. | 16 | Ductile Iron | 226 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2300 | | COV | Tiogue Ave. | 12 | Unknown | 13 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 2303 | P-7717 | COV | Tiogue Ave. | 12 | Ductile Iron | 287 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2304 | P-7717 | COV | Tiogue Ave. | 12 | Ductile Iron | 409 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3272 | P-1172 | COV | Tiogue Ave. | 12 | Asbestos Cement | 10 | 54 | 1.14 out of 5 | $442 | 4,220 |
| Transmission Main | 3273 | P-1172 | COV | Tiogue Ave. | 12 | Asbestos Cement | 357 | 54 | 1.14 out of 5 | $442 | 157,786 |
| Transmission Main | 3274 | P-1172 | COV | Tiogue Ave. | 12 | Asbestos Cement | 106 | 54 | 1.14 out of 5 | $442 | 46,791 |
| Transmission Main | 3275 | P-1172 | COV | Tiogue Ave. | 12 | Asbestos Cement | 92 | 54 | 1.14 out of 5 | $442 | 40,557 |
| Transmission Main | 3679 | P-7754 | COV | Tiogue Ave. | 12 | Asbestos Cement | 199 | 54 | 1.14 out of 5 | $442 | 87,809 |
| Transmission Main | 3680 | P-7754 | COV | Tiogue Ave. | 12 | Asbestos Cement | 22 | 54 | 1.14 out of 5 | $442 | 9,791 |
| Transmission Main | 3681 | P-7755 | COV | Tiogue Ave. | 12 | Asbestos Cement | 264 | 54 | 1.14 out of 5 | $442 | 116,817 |
| Transmission Main | 3812 | P-7768 | COV | Tiogue Ave. | 12 | Asbestos Cement | 25 | 54 | 1.14 out of 5 | $442 | 11,068 |
| Transmission Main | 3813 | P-7768 | COV | Tiogue Ave. | 12 | Asbestos Cement | 296 | 54 | 1.14 out of 5 | $442 | 130,985 |
| Transmission Main | 3814 | P-7770 | COV | Tiogue Ave. | 12 | Asbestos Cement | 253 | 54 | 1.14 out of 5 | $442 | 111,984 |
| Transmission Main | 3815 | P-7770 | COV | Tiogue Ave. | 12 | Asbestos Cement | 421 | 54 | 1.14 out of 5 | $442 | 186,135 |
| Transmission Main | 3818 | P-7767 | COV | Tiogue Ave. | 12 | Asbestos Cement | 49 | 54 | 1.14 out of 5 | $442 | 21,572 |
| Transmission Main | 4571 | P-1174 | COV | Tiogue Ave. | 12 | Asbestos Cement | 48 | 54 | 1.14 out of 5 | $442 | 21,058 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 4572 | P-1174 | COV | Tiogue Ave. | 12 | Asbestos Cement | 187 | 54 | 1.14 out of 5 | $442 | 82,761 |
| Transmission Main | 4690 | P-1172 | COV | Tiogue Ave. | 12 | Asbestos Cement | 467 | 54 | 1.14 out of 5 | $442 | 206,527 |
| Transmission Main | 4723 | P-1172 | COV | Tiogue Ave. | 12 | Asbestos Cement | 75 | 54 | 1.14 out of 5 | $442 | 32,974 |
| Transmission Main | 4724 | P-1172 | COV | Tiogue Ave. | 12 | Asbestos Cement | 178 | 54 | 1.14 out of 5 | $442 | 78,672 |
| Transmission Main | 4779 | P-1577 | COV | Tiogue Ave. | 12 | Asbestos Cement | 48 | 54 | 1.14 out of 5 | $442 | 21,309 |
| Transmission Main | 4780 | P-1577 | COV | Tiogue Ave. | 12 | Asbestos Cement | 101 | 54 | 1.14 out of 5 | $442 | 44,531 |
| Distribution Main | 4838 | P-7505 | COV | Tiogue Ave. | 10 | Asbestos Cement | 81 | 57 | 1.14 out of 5 | $442 | 35,882 |
| Transmission Main | 4841 | P-7160 | COV | Tiogue Ave. | 12 | Ductile Iron | 339 | 30 | 0.14 out of 5 | $442 | 149,916 |
| Distribution Main | 4842 | P-8721 | COV | Tiogue Ave. | 10 | Asbestos Cement | 501 | 57 | 1.14 out of 5 | $442 | 221,550 |
| Distribution Main | 4843 | P-8721 | COV | Tiogue Ave. | 10 | Asbestos Cement | 244 | 57 | 1.14 out of 5 | $442 | 107,940 |
| Transmission Main | 4844 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 33 | 30 | 0.14 out of 5 | $442 | 14,468 |
| Transmission Main | 4845 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 633 | 30 | 0.14 out of 5 | $442 | 279,655 |
| Distribution Main | 4846 | P-7502 | COV | Tiogue Ave. | 8 | Asbestos Cement | 136 | 57 | 1.14 out of 5 | $442 | 59,963 |
| Transmission Main | 4847 | P-7506 | COV | Tiogue Ave. | 12 | Asbestos Cement | 45 | 19 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 4848 | P-7505 | COV | Tiogue Ave. | 10 | Asbestos Cement | 15 | 57 | 1.14 out of 5 | $442 | 6,537 |
| Distribution Main | 5319 | P-7503 | COV | Tiogue Ave. | 8 | Asbestos Cement | 70 | 57 | 1.14 out of 5 | $442 | 30,967 |
| Transmission Main | 5321 | P-7507 | COV | Tiogue Ave. | 12 | Asbestos Cement | 265 | 57 | 1.14 out of 5 | $442 | 117,257 |
| Transmission Main | 5322 | P-7507 | COV | Tiogue Ave. | 12 | Asbestos Cement | 526 | 57 | 1.14 out of 5 | $442 | 232,556 |
| Distribution Main | 5339 | P-8513 | COV | Tiogue Ave. | 8 | Asbestos Cement | 583 | 71 | 1.29 out of 5 | $442 | 257,699 |
| Distribution Main | 5340 | P-7496 | COV | Tiogue Ave. | 8 | Asbestos Cement | 843 | 71 | 1.29 out of 5 | $442 | 372,628 |
| Distribution Main | 6171 | P-7496 | COV | Tiogue Ave. | 8 | Asbestos Cement | 181 | 71 | 1.29 out of 5 | $442 | 79,998 |
| Distribution Main | 6172 | P-7496 | COV | Tiogue Ave. | 8 | Asbestos Cement | 51 | 71 | 1.29 out of 5 | $442 | 22,587 |
| Transmission Main | 7190 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 23 | 30 | 0.14 out of 5 | $442 | 10,194 |
| Transmission Main | 7191 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 752 | 30 | 0.14 out of 5 | $442 | 332,240 |
| Transmission Main | 7195 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 339 | 30 | 0.14 out of 5 | $442 | 150,017 |
| Transmission Main | 7196 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 6 | 30 | 0.14 out of 5 | $442 | 2,506 |
| Transmission Main | 7197 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 132 | 30 | 0.14 out of 5 | $442 | 58,285 |
| Transmission Main | 7198 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 8 | 30 | 0.14 out of 5 | $442 | 3,657 |
| Transmission Main | 7201 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 11 | 30 | 0.14 out of 5 | $442 | 5,070 |
| Transmission Main | 7202 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 463 | 30 | 0.14 out of 5 | $442 | 204,442 |
| Transmission Main | 7203 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 460 | 30 | 0.14 out of 5 | $442 | 203,358 |
| Distribution Main | 7205 | P-7503 | COV | Tiogue Ave. | 8 | Asbestos Cement | 8 | 71 | 1.29 out of 5 | $442 | 3,622 |
| Transmission Main | 7515 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 18 | 30 | 0.14 out of 5 | $442 | 7,932 |
| Transmission Main | 7516 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 19 | 30 | 0.14 out of 5 | $442 | 8,334 |
| Transmission Main | 8069 | P-8526 | COV | Tiogue Ave. | 12 | Ductile Iron | 31 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8076 | P-7755 | COV | Tiogue Ave. | 12 | Asbestos Cement | 37 | 54 | 1.14 out of 5 | $442 | 16,310 |
| Distribution Main | 9512 | | COV | Tiogue Ave. | 8 | Ductile Iron | 12 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9549 | P-8487 | COV | Tiogue Ave. | 12 | Ductile Iron | 216 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9553 | P-8425 | COV | Tiogue Ave. | 12 | Ductile Iron | 448 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9554 | P-8425 | COV | Tiogue Ave. | 12 | Ductile Iron | 483 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9555 | P-7718 | COV | Tiogue Ave. | 12 | Ductile Iron | 104 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9559 | P-7564 | COV | Tiogue Ave. | 12 | Ductile Iron | 76 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9560 | P-7564 | COV | Tiogue Ave. | 12 | Ductile Iron | 26 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9561 | | COV | Tiogue Ave. | 6 | Asbestos Cement | 48 | 61 | 2 out of 5 | $442 | 21,279 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 9566 | P-7563 | COV | Tiogue Ave. | 16 | Ductile Iron | 30 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9567 | P-8298 | COV | Tiogue Ave. | 8 | Cast Iron | 157 | 24 | 1.14 out of 5 | N/A | $0 |
| Distribution Main | 9568 | P-8298 | COV | Tiogue Ave. | 8 | Cast Iron | 274 | 24 | 1.14 out of 5 | N/A | $0 |
| Transmission Main | 9569 | P-7507 | COV | Tiogue Ave. | 12 | Asbestos Cement | 189 | 57 | 1.14 out of 5 | $442 | 83,432 |
| Distribution Main | 9570 | P-7496 | COV | Tiogue Ave. | 8 | Asbestos Cement | 197 | 71 | 1.29 out of 5 | $442 | 87,070 |
| Transmission Main | 9578 | P-8946 | COV | Tiogue Ave. | 12 | Asbestos Cement | 360 | 57 | 1.14 out of 5 | $442 | 159,114 |
| Transmission Main | 9579 | P-7714 | COV | Tiogue Ave. | 16 | Ductile Iron | 424 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9989 | P-8296 | COV | Tiogue Ave. | 16 | Ductile Iron | 471 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10806 | P-7563 | COV | Tiogue Ave. | 12 | Ductile Iron | 200 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10807 | P-7563 | COV | Tiogue Ave. | 12 | Ductile Iron | 183 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10808 | P-7563 | COV | Tiogue Ave. | 12 | Asbestos Cement | 216 | 70 | 1.29 out of 5 | $442 | 95,504 |
| Transmission Main | 11074 | P-7564 | COV | Tiogue Ave. | 12 | Ductile Iron | 16 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11075 | P-7564 | COV | Tiogue Ave. | 12 | Ductile Iron | 6 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11076 | P-7564 | COV | Tiogue Ave. | 12 | Asbestos Cement | 31 | 70 | 1.29 out of 5 | $442 | 13,682 |
| Transmission Main | 11077 | P-7717 | COV | Tiogue Ave. | 12 | Ductile Iron | 27 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11078 | P-7717 | COV | Tiogue Ave. | 12 | Ductile Iron | 17 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11114 | P-8475 | COV | Tiogue Ave. | 12 | Ductile Iron | 24 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11116 | P-7563 | COV | Tiogue Ave. | 12 | Ductile Iron | 88 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11117 | P-7563 | COV | Tiogue Ave. | 12 | Ductile Iron | 42 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11118 | P-9005 | COV | Tiogue Ave. | 12 | Ductile Iron | 185 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11119 | P-9005 | COV | Tiogue Ave. | 12 | Ductile Iron | 155 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11120 | P-9005 | COV | Tiogue Ave. | 12 | Ductile Iron | 97 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11123 | P-7509 | COV | Tiogue Ave. | 12 | Asbestos Cement | 202 | 57 | 1.14 out of 5 | $442 | 89,363 |
| Transmission Main | 11163 | P-7754 | COV | Tiogue Ave. | 12 | Asbestos Cement | 5 | 54 | 1.14 out of 5 | $442 | 2,215 |
| Transmission Main | 11165 | P-7563 | COV | Tiogue Ave. | 12 | Asbestos Cement | 108 | 70 | 1.29 out of 5 | $442 | 47,764 |
| Transmission Main | 11166 | P-8296 | COV | Tiogue Ave. | 16 | Ductile Iron | 108 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11235 | P-7770 | COV | Tiogue Ave. | 12 | Asbestos Cement | 42 | 54 | 1.14 out of 5 | $442 | 18,759 |
| Distribution Main | 11268 | P-7505 | COV | Tiogue Ave. | 10 | Asbestos Cement | 30 | 57 | 1.14 out of 5 | $442 | 13,360 |
| Transmission Main | 11269 | P-7160 | COV | Tiogue Ave. | 12 | Ductile Iron | 88 | 30 | 0.14 out of 5 | $442 | 38,903 |
| Distribution Main | 11270 | P-8721 | COV | Tiogue Ave. | 10 | Asbestos Cement | 188 | 57 | 1.14 out of 5 | $442 | 83,241 |
| Transmission Main | 11296 | P-7507 | COV | Tiogue Ave. | 12 | Asbestos Cement | 481 | 57 | 1.85 out of 5 | $442 | 212,466 |
| Transmission Main | 11339 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 78 | 30 | 0.14 out of 5 | $442 | 34,687 |
| Transmission Main | 11587 | P-8475 | COV | Tiogue Ave. | 12 | Asbestos Cement | 69 | 61 | 1.29 out of 5 | $442 | 30,626 |
| Transmission Main | 11736 | P-7563 | COV | Tiogue Ave. | 12 | Ductile Iron | 51 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11737 | P-7563 | COV | Tiogue Ave. | 12 | Ductile Iron | 3 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11738 | | COV | Tiogue Ave. | 2 | Unknown | 2 | UNK | 1.42 out of 5 | $442 | 817 |
| Transmission Main | 11784 | P-8425 | COV | Tiogue Ave. | 12 | Ductile Iron | 19 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12068 | P-7743 | COV | Tiogue Ave. | 12 | Ductile Iron | 96 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12075 | P-7717 | COV | Tiogue Ave. | 12 | Ductile Iron | 104 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12079 | P-7159 | COV | Tiogue Ave. | 12 | Ductile Iron | 34 | 30 | 0.14 out of 5 | $442 | 15,221 |
| Transmission Main | 12081 | P-7507 | COV | Tiogue Ave. | 12 | Asbestos Cement | 229 | 57 | 1.14 out of 5 | $442 | 101,418 |
| Transmission Main | 8335 | P-8485 | COV | Tiogue Tank Connection | 12 | Asbestos Cement | 15 | UNK | 0.85 out of 5 | $442 | 6,785 |
| Transmission Main | 8336 | P-8485 | COV | Tiogue Tank Connection | 12 | Asbestos Cement | 16 | UNK | 0.85 out of 5 | $442 | 7,161 |
| Transmission Main | 8337 | P-7730 | COV | Tiogue Tank Connection | 12 | Asbestos Cement | 97 | UNK | 0.85 out of 5 | $442 | 42,839 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 8338 | | COV | Tiogue Tank Connection | 8 | Ductile Iron | 26 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10455 | P-8485 | COV | Tiogue Tank Connection | 12 | Ductile Iron | 15 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10456 | | COV | Tiogue Tank Connection | 6 | Steel | 3 | UNK | 1.28 out of 5 | $442 | 1,414 |
| Distribution Main | 10457 | | COV | Tiogue Tank Connection | 6 | Ductile Iron | 6 | 14 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 11463 | P-8485 | COV | Tiogue Tank Connection | 12 | Ductile Iron | 4 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 11464 | P-8485 | COV | Tiogue Tank Connection | 12 | Ductile Iron | 5 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9634 | P-7572 | COV | Tobin St | 6 | Ductile Iron | 193 | 30 | 0.85 out of 5 | $442 | 85,463 |
| Distribution Main | 12107 | P-7572 | COV | Tobin St | 6 | Ductile Iron | 1 | 30 | 0.85 out of 5 | $442 | 479 |
| Distribution Main | 4070 | P-8165 | COV | Trafford Park Dr. | 8 | Asbestos Cement | 470 | 42 | 1.14 out of 5 | $442 | 207,613 |
| Distribution Main | 4071 | P-8165 | COV | Trafford Park Dr. | 8 | Asbestos Cement | 572 | 42 | 1.14 out of 5 | $442 | 252,648 |
| Distribution Main | 551 | P-7678 | COV | Tulip Rd. | 6 | Asbestos Cement | 35 | 56 | 1.85 out of 5 | $442 | 15,299 |
| Distribution Main | 552 | P-7678 | COV | Tulip Rd. | 6 | Asbestos Cement | 410 | 56 | 1.85 out of 5 | $442 | 181,211 |
| Distribution Main | 3174 | P-7837 | COV | Turcotte St. | 8 | PVC | 482 | 32 | 0.43 out of 5 | $442 | 213,230 |
| Distribution Main | 1754 | P-7656 | COV | Twin Lakes Ave. | 8 | Ductile Iron | 171 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2785 | P-7652 | COV | Twin Lakes Ave. | 8 | Ductile Iron | 6 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2787 | | COV | Twin Lakes Ave. | 8 | Ductile Iron | 31 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2798 | P-7652 | COV | Twin Lakes Ave. | 8 | Ductile Iron | 88 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2799 | P-7652 | COV | Twin Lakes Ave. | 8 | Ductile Iron | 555 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2802 | P-7654 | COV | Twin Lakes Ave. | 8 | Ductile Iron | 175 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 187 | P-7662 | COV | Vale St. | 2 | Copper | 399 | 83 | 2.57 out of 5 | $442 | 176,457 |
| Distribution Main | 709 | P-7662 | COV | Vale St. | 6 | Asbestos Cement | 62 | 83 | 2.14 out of 5 | $442 | 27,442 |
| Distribution Main | 10158 | | COV | Valley Crest Rd | 6 | Ductile Iron | 9 | 8 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10462 | | COV | Valley Crest Rd | 8 | Ductile Iron | 152 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 190 | P-723 | COV | Valley Crest Rd. | 6 | Asbestos Cement | 730 | 60 | 1.85 out of 5 | $442 | 322,490 |
| Distribution Main | 191 | P-7289 | COV | Valley Crest Rd. | 8 | Asbestos Cement | 124 | 59 | 1.14 out of 5 | $442 | 54,814 |
| Distribution Main | 192 | P-7289 | COV | Valley Crest Rd. | 8 | Asbestos Cement | 103 | 60 | 1.14 out of 5 | $442 | 45,720 |
| Distribution Main | 193 | P-7288 | COV | Valley Crest Rd. | 8 | Asbestos Cement | 9 | 59 | 1.14 out of 5 | $442 | 3,945 |
| Distribution Main | 3072 | P-7288 | COV | Valley Crest Rd. | 8 | Asbestos Cement | 204 | 59 | 1.14 out of 5 | $442 | 90,322 |
| Distribution Main | 4956 | P-8138 | COV | Valrene St. | 6 | Asbestos Cement | 437 | 52 | 1.85 out of 5 | $442 | 193,096 |
| Distribution Main | 4957 | P-8138 | COV | Valrene St. | 6 | Asbestos Cement | 23 | 52 | 1.85 out of 5 | $442 | 10,353 |
| Distribution Main | 11277 | P-8138 | COV | Valrene St. | 6 | Asbestos Cement | 67 | 52 | 1.85 out of 5 | $442 | 29,632 |
| Distribution Main | 3168 | P-7804 | COV | Vanderbilt Ter. | 6 | Asbestos Cement | 481 | 43 | 1.85 out of 5 | $442 | 212,418 |
| Distribution Main | 3228 | P-7799 | COV | Vanderbilt Ter. | 6 | Asbestos Cement | 470 | 43 | 1.85 out of 5 | $442 | 207,750 |
| Distribution Main | 2555 | P-7673 | COV | Vera Rd. | 6 | Asbestos Cement | 23 | 56 | 1.85 out of 5 | $442 | 10,236 |
| Distribution Main | 2556 | P-7673 | COV | Vera Rd. | 6 | Asbestos Cement | 552 | 56 | 1.85 out of 5 | $442 | 243,983 |
| Distribution Main | 2615 | P-8975 | COV | Vera Rd. | 6 | Asbestos Cement | 294 | 56 | 1.85 out of 5 | $442 | 129,843 |
| Distribution Main | 2616 | P-8975 | COV | Vera Rd. | 6 | Asbestos Cement | 44 | 56 | 1.85 out of 5 | $442 | 19,305 |
| Distribution Main | 7454 | P-7102 | COV | Veronica Ct. | 6 | Asbestos Cement | 11 | 44 | 1.85 out of 5 | $442 | 5,024 |
| Distribution Main | 7464 | P-7102 | COV | Veronica Ct. | 6 | Asbestos Cement | 351 | 44 | 1.85 out of 5 | $442 | 155,110 |
| Distribution Main | 1455 | P-7705 | COV | View Rd. | 2 | Copper | 312 | 60 | 2.28 out of 5 | $442 | 137,788 |
| Distribution Main | 1456 | P-7705 | COV | View Rd. | 2 | Copper | 47 | 60 | 2.28 out of 5 | $442 | 20,840 |
| Distribution Main | 449 | P-7370 | COV | Viola St. | 6 | Asbestos Cement | 395 | 51 | 1.85 out of 5 | $442 | 174,621 |
| Distribution Main | 1462 | P-7372 | COV | Viola St. | 6 | Asbestos Cement | 250 | 51 | 1.85 out of 5 | $442 | 110,373 |
| Distribution Main | 1471 | P-7371 | COV | Viola St. | 6 | Asbestos Cement | 312 | 51 | 1.85 out of 5 | $442 | 137,805 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 1472 | P-7373 | COV | Viola St. | 6 | Asbestos Cement | 284 | 51 | 1.85 out of 5 | $442 | 125,353 |
| Distribution Main | 8800 | | COV | Walker Lane | 6 | Asbestos Cement | 206 | UNK | 1.56 out of 5 | $442 | 91,082 |
| Distribution Main | 8801 | | COV | Walker Lane | 6 | Asbestos Cement | 412 | UNK | 1.56 out of 5 | $442 | 181,994 |
| Distribution Main | 10430 | | COV | Walker Lane | 6 | Ductile Iron | 35 | 8 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 9972 | | COV | Walker Ln | 12 | Ductile Iron | 39 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9973 | | COV | Walker Ln | 6 | Ductile Iron | 4 | 25 | 0.85 out of 5 | N/A | $0 |
| Transmission Main | 7174 | P-7186 | COV | Walker Ln. | 12 | Ductile Iron | 271 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 7520 | P-7187 | COV | Walker Ln. | 12 | Ductile Iron | 415 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 7523 | P-7186 | COV | Walker Ln. | 12 | Ductile Iron | 262 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 7524 | P-7186 | COV | Walker Ln. | 12 | Ductile Iron | 344 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 7872 | P-7186 | COV | Walker Ln. | 12 | Ductile Iron | 593 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 7900 | P-7186 | COV | Walker Ln. | 12 | Ductile Iron | 220 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 7901 | P-7186 | COV | Walker Ln. | 12 | Ductile Iron | 494 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 8787 | P-8896 | COV | Walker Ln. | 12 | Ductile Iron | 4 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9970 | P-7186 | COV | Walker Ln. | 12 | Ductile Iron | 1,035 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9971 | P-7186 | COV | Walker Ln. | 12 | Ductile Iron | 15 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11413 | P-7186 | COV | Walker Ln. | 12 | Ductile Iron | 18 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11889 | P-7186 | COV | Walker Ln. | 12 | Ductile Iron | 328 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 998 | P-7320 | COV | Walnut Hill Rd. | 8 | Asbestos Cement | 547 | 54 | 1.14 out of 5 | $442 | 241,831 |
| Distribution Main | 999 | P-7320 | COV | Walnut Hill Rd. | 8 | Asbestos Cement | 29 | 54 | 1.14 out of 5 | $442 | 12,739 |
| Transmission Main | 114 | P-7848 | COV | Washington St | 16 | Cast Iron | 16 | 129 | 1.86 out of 5 | $442 | 7,062 |
| Distribution Main | 9348 | | COV | Washington St | 8 | Ductile Iron | 32 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9947 | | COV | Washington St | 12 | Ductile Iron | 11 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 308 | P-8762 | COV | Washington St. | 12 | Cast Iron | 275 | 132 | 1.86 out of 5 | $442 | 121,624 |
| Transmission Main | 309 | P-8762 | COV | Washington St. | 12 | Cast Iron | 34 | 132 | 1.86 out of 5 | $442 | 14,928 |
| Transmission Main | 310 | P-8011 | COV | Washington St. | 12 | Cast Iron | 90 | 132 | 1.86 out of 5 | $442 | 39,785 |
| Transmission Main | 311 | P-8011 | COV | Washington St. | 12 | Cast Iron | 321 | 132 | 1.86 out of 5 | $442 | 141,933 |
| Transmission Main | 401 | P-8010 | COV | Washington St. | 12 | Cast Iron | 85 | 132 | 1.86 out of 5 | $442 | 37,510 |
| Transmission Main | 412 | P-8009 | COV | Washington St. | 12 | Cast Iron | 400 | 132 | 1.86 out of 5 | $442 | 176,993 |
| Transmission Main | 413 | P-8009 | COV | Washington St. | 12 | Cast Iron | 227 | 132 | 1.86 out of 5 | $442 | 100,507 |
| Transmission Main | 830 | P-7864 | COV | Washington St. | 12 | Asbestos Cement | 308 | 75 | 1.29 out of 5 | $442 | 136,058 |
| Transmission Main | 831 | P-7864 | COV | Washington St. | 12 | Asbestos Cement | 271 | 75 | 1.29 out of 5 | $442 | 119,784 |
| Transmission Main | 1038 | P-8010 | COV | Washington St. | 12 | Cast Iron | 13 | 132 | 1.86 out of 5 | $442 | 5,827 |
| Transmission Main | 1262 | P-8246 | COV | Washington St. | 16 | Cast Iron | 381 | 133 | 1.86 out of 5 | $442 | 168,588 |
| Transmission Main | 1263 | P-8246 | COV | Washington St. | 16 | Cast Iron | 407 | 133 | 1.86 out of 5 | $442 | 179,978 |
| Transmission Main | 1288 | P-7964 | COV | Washington St. | 12 | Cast Iron | 59 | 132 | 1.86 out of 5 | $442 | 26,277 |
| Transmission Main | 1405 | P-8010 | COV | Washington St. | 12 | Cast Iron | 14 | 132 | 1.86 out of 5 | $442 | 6,112 |
| Transmission Main | 1406 | P-8009 | COV | Washington St. | 12 | Cast Iron | 3 | 132 | 1.86 out of 5 | $442 | 1,295 |
| Transmission Main | 1497 | P-7865 | COV | Washington St. | 12 | Cast Iron | 29 | 132 | 1.86 out of 5 | $442 | 12,878 |
| Transmission Main | 1498 | P-7865 | COV | Washington St. | 12 | Cast Iron | 197 | 132 | 1.86 out of 5 | $442 | 87,271 |
| Transmission Main | 1499 | P-8288 | COV | Washington St. | 12 | Cast Iron | 33 | 132 | 1.86 out of 5 | $442 | 14,713 |
| Transmission Main | 1950 | P-7962 | COV | Washington St. | 12 | Cast Iron | 97 | 132 | 1.86 out of 5 | $442 | 43,093 |
| Transmission Main | 2194 | P-8244 | COV | Washington St. | 16 | Cast Iron | 13 | 133 | 1.86 out of 5 | $442 | 5,750 |
| Transmission Main | 2195 | P-8244 | COV | Washington St. | 16 | Cast Iron | 11 | 133 | 1.86 out of 5 | $442 | 4,968 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 2380 | P-7964 | COV | Washington St. | 12 | Asbestos Cement | 114 | 75 | 1.29 out of 5 | $442 | 50,295 |
| Transmission Main | 2381 | P-7865 | COV | Washington St. | 12 | Cast Iron | 24 | 132 | 1.86 out of 5 | $442 | 10,805 |
| Transmission Main | 2700 | P-8020 | COV | Washington St. | 12 | Cast Iron | 69 | 132 | 1.86 out of 5 | $442 | 30,407 |
| Transmission Main | 2701 | P-8020 | COV | Washington St. | 12 | Cast Iron | 168 | 132 | 1.86 out of 5 | $442 | 74,359 |
| Transmission Main | 2706 | P-8022 | COV | Washington St. | 12 | Cast Iron | 363 | 132 | 1.86 out of 5 | $442 | 160,548 |
| Transmission Main | 2707 | P-8022 | COV | Washington St. | 12 | Cast Iron | 82 | 132 | 1.86 out of 5 | $442 | 36,379 |
| Transmission Main | 2807 | P-7848 | COV | Washington St. | 16 | Cast Iron | 704 | 129 | 1.86 out of 5 | $442 | 311,099 |
| Transmission Main | 3007 | P-8243 | COV | Washington St. | 16 | Cast Iron | 14 | 129 | 1.86 out of 5 | $442 | 5,993 |
| Transmission Main | 3021 | P-8246 | COV | Washington St. | 16 | Cast Iron | 33 | 133 | 1.86 out of 5 | $442 | 14,631 |
| Transmission Main | 3022 | P-7962 | COV | Washington St. | 12 | Asbestos Cement | 591 | 75 | 1.29 out of 5 | $442 | 261,224 |
| Transmission Main | 3023 | P-7964 | COV | Washington St. | 12 | Cast Iron | 295 | 132 | 1.86 out of 5 | $442 | 130,280 |
| Transmission Main | 3024 | P-7964 | COV | Washington St. | 12 | Cast Iron | 212 | 132 | 1.86 out of 5 | $442 | 93,676 |
| Transmission Main | 3025 | P-8290 | COV | Washington St. | 16 | Cast Iron | 8 | 132 | 1.86 out of 5 | $442 | 3,490 |
| Transmission Main | 3026 | P-8288 | COV | Washington St. | 12 | Cast Iron | 238 | 132 | 1.86 out of 5 | $442 | 105,000 |
| Transmission Main | 3027 | P-8288 | COV | Washington St. | 12 | Cast Iron | 451 | 132 | 1.86 out of 5 | $442 | 199,458 |
| Transmission Main | 3028 | P-8291 | COV | Washington St. | 16 | Cast Iron | 245 | 132 | 1.86 out of 5 | $442 | 108,361 |
| Transmission Main | 3030 | P-8287 | COV | Washington St. | 12 | Cast Iron | 213 | 132 | 1.86 out of 5 | $442 | 94,146 |
| Transmission Main | 3031 | P-7965 | COV | Washington St. | 12 | Cast Iron | 20 | 132 | 1.86 out of 5 | $442 | 8,897 |
| Transmission Main | 3032 | P-7965 | COV | Washington St. | 12 | Cast Iron | 131 | 132 | 1.86 out of 5 | $442 | 57,733 |
| Transmission Main | 3033 | P-7963 | COV | Washington St. | 12 | Asbestos Cement | 9 | 75 | 1.29 out of 5 | $442 | 3,947 |
| Transmission Main | 3154 | P-7863 | COV | Washington St. | 12 | Cast Iron | 54 | 91 | 1.72 out of 5 | $442 | 23,681 |
| Transmission Main | 3155 | P-7863 | COV | Washington St. | 12 | Cast Iron | 405 | 91 | 1.72 out of 5 | $442 | 178,806 |
| Transmission Main | 3474 | P-8290 | COV | Washington St. | 16 | Cast Iron | 49 | 132 | 1.86 out of 5 | $442 | 21,785 |
| Transmission Main | 3475 | P-9029 | COV | Washington St. | 12 | Cast Iron | 16 | 132 | 1.86 out of 5 | $442 | 6,966 |
| Transmission Main | 3476 | P-9029 | COV | Washington St. | 12 | Cast Iron | 48 | 132 | 1.86 out of 5 | $442 | 21,119 |
| Transmission Main | 6178 | P-8777 | COV | Washington St. | 12 | Ductile Iron | 670 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6179 | P-8777 | COV | Washington St. | 12 | Ductile Iron | 433 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9625 | P-8291 | COV | Washington St. | 16 | Cast Iron | 242 | 132 | 1.86 out of 5 | $442 | 106,875 |
| Transmission Main | 9627 | P-7860 | COV | Washington St. | 12 | Ductile Iron | 179 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10859 | P-8291 | COV | Washington St. | 16 | Cast Iron | 47 | 132 | 1.86 out of 5 | $442 | 20,712 |
| Transmission Main | 10872 | P-9045 | COV | Washington St. | 12 | Cast Iron | 273 | 132 | 1.86 out of 5 | $442 | 120,564 |
| Transmission Main | 10873 | P-9045 | COV | Washington St. | 12 | Cast Iron | 325 | 132 | 1.86 out of 5 | $442 | 143,825 |
| Transmission Main | 11185 | P-8020 | COV | Washington St. | 12 | Cast Iron | 10 | 132 | 1.86 out of 5 | $442 | 4,272 |
| Transmission Main | 11199 | P-8288 | COV | Washington St. | 12 | Cast Iron | 139 | 132 | 1.86 out of 5 | $442 | 61,306 |
| Transmission Main | 11756 | P-7964 | COV | Washington St. | 12 | Cast Iron | 58 | 132 | 1.86 out of 5 | $442 | 25,631 |
| Transmission Main | 11757 | P-8288 | COV | Washington St. | 12 | Cast Iron | 373 | 132 | 1.86 out of 5 | $442 | 165,057 |
| Transmission Main | 11758 | P-8288 | COV | Washington St. | 12 | Cast Iron | 99 | 132 | 1.86 out of 5 | $442 | 43,781 |
| Transmission Main | 11774 | P-8009 | COV | Washington St. | 12 | Cast Iron | 64 | 132 | 1.86 out of 5 | $442 | 28,334 |
| Transmission Main | 11775 | P-8246 | COV | Washington St. | 16 | Cast Iron | 101 | 133 | 1.86 out of 5 | $442 | 44,545 |
| Transmission Main | 11776 | P-8246 | COV | Washington St. | 16 | Cast Iron | 276 | 133 | 1.86 out of 5 | $442 | 121,958 |
| Transmission Main | 12066 | P-8246 | COV | Washington St. | 16 | Cast Iron | 51 | 133 | 1.86 out of 5 | $442 | 22,705 |
| Distribution Main | 6169 | P-7301 | COV | Watercress Ct. | 8 | Asbestos Cement | 455 | 40 | 1 out of 5 | $442 | 201,116 |
| Distribution Main | 7691 | P-7312 | COV | Watercress Ct. | 8 | Asbestos Cement | 275 | 40 | 1 out of 5 | $442 | 121,373 |
| Distribution Main | 7692 | P-7312 | COV | Watercress Ct. | 8 | Asbestos Cement | 632 | 40 | 1 out of 5 | $442 | 279,355 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 7693 | P-7300 | COV | Watercress Ct. | 8 | Asbestos Cement | 493 | 40 | 1 out of 5 | $442 | 218,079 |
| Distribution Main | 7694 | P-7300 | COV | Watercress Ct. | 8 | Asbestos Cement | 138 | 40 | 1 out of 5 | $442 | 61,216 |
| Distribution Main | 7695 | P-7311 | COV | Watercress Ct. | 8 | Asbestos Cement | 159 | 40 | 1 out of 5 | $442 | 70,090 |
| Distribution Main | 10139 | | COV | Waterman Rd | 2 | Copper | 129 | 58 | 2.28 out of 5 | $442 | 56,838 |
| Distribution Main | 2193 | P-7568 | COV | Wendell St. | 6 | Asbestos Cement | 244 | 65 | 2 out of 5 | $442 | 107,686 |
| Distribution Main | 1598 | P-8152 | COV | Wendy Dr. | 8 | Asbestos Cement | 19 | 46 | 1.14 out of 5 | $442 | 8,314 |
| Distribution Main | 2534 | | COV | Wendy Dr. | 8 | Asbestos Cement | 95 | 46 | 1.14 out of 5 | $442 | 41,923 |
| Distribution Main | 2535 | P-8158 | COV | Wendy Dr. | 8 | Asbestos Cement | 18 | 46 | 1.14 out of 5 | $442 | 7,902 |
| Distribution Main | 2537 | P-8157 | COV | Wendy Dr. | 8 | Asbestos Cement | 8 | 46 | 1.14 out of 5 | $442 | 3,739 |
| Distribution Main | 2538 | P-8157 | COV | Wendy Dr. | 8 | Asbestos Cement | 156 | 46 | 1.14 out of 5 | $442 | 68,822 |
| Distribution Main | 2873 | P-8152 | COV | Wendy Dr. | 8 | Asbestos Cement | 186 | 46 | 1.14 out of 5 | $442 | 82,251 |
| Distribution Main | 4563 | P-8158 | COV | Wendy Dr. | 8 | Asbestos Cement | 400 | 46 | 1.14 out of 5 | $442 | 176,886 |
| Distribution Main | 1491 | P-7817 | COV | Wesleyan Ave. | 6 | Asbestos Cement | 18 | 52 | 1.85 out of 5 | $442 | 7,997 |
| Distribution Main | 1492 | P-7817 | COV | Wesleyan Ave. | 6 | Asbestos Cement | 596 | 52 | 1.85 out of 5 | $442 | 263,465 |
| Distribution Main | 2843 | P-7815 | COV | Wesleyan Ave. | 6 | Asbestos Cement | 263 | 52 | 1.85 out of 5 | $442 | 116,257 |
| Distribution Main | 3170 | P-7806 | COV | Wesleyan Ave. | 8 | Asbestos Cement | 606 | 52 | 1.14 out of 5 | $442 | 267,885 |
| Distribution Main | 3171 | P-7806 | COV | Wesleyan Ave. | 8 | Asbestos Cement | 720 | 52 | 1.14 out of 5 | $442 | 318,188 |
| Distribution Main | 3232 | P-7798 | COV | Wesleyan Ave. | 8 | Asbestos Cement | 29 | 52 | 1.14 out of 5 | $442 | 12,777 |
| Distribution Main | 3233 | P-7798 | COV | Wesleyan Ave. | 8 | Asbestos Cement | 225 | 52 | 1.14 out of 5 | $442 | 99,259 |
| Distribution Main | 11131 | P-7817 | COV | Wesleyan Ave. | 6 | Asbestos Cement | 2 | 52 | 1.85 out of 5 | $442 | 979 |
| Distribution Main | 747 | P-7628 | COV | West Lake Dr. | 6 | Asbestos Cement | 435 | 58 | 1.85 out of 5 | $442 | 192,281 |
| Distribution Main | 9939 | P-8996 | COV | West Shore Dr | 8 | Ductile Iron | 34 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10977 | P-8997 | COV | West Shore Dr | 8 | Ductile Iron | 22 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11627 | | COV | West Shore Dr | 6 | Ductile Iron | 17 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 1090 | P-7689 | COV | West Shore Dr. | 6 | Asbestos Cement | 90 | 53 | 1.85 out of 5 | $442 | 39,964 |
| Distribution Main | 1091 | P-7689 | COV | West Shore Dr. | 6 | Asbestos Cement | 414 | 53 | 1.85 out of 5 | $442 | 182,974 |
| Distribution Main | 711 | P-8309 | COV | West Shore Drive | 6 | Asbestos Cement | 208 | 65 | 2 out of 5 | $442 | 91,751 |
| Distribution Main | 712 | P-8993 | COV | West Shore Drive | 6 | Ductile Iron | 31 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 713 | P-8994 | COV | West Shore Drive | 1 | Copper | 202 | 65 | 2.43 out of 5 | $442 | 89,447 |
| Distribution Main | 1458 | P-7661 | COV | West Shore Drive | 1 | Copper | 231 | 83 | 2.57 out of 5 | $442 | 102,167 |
| Distribution Main | 9509 | | COV | West Shore Drive | 6 | Asbestos Cement | 30 | 65 | 2 out of 5 | $442 | 13,210 |
| Distribution Main | 12063 | P-8309 | COV | West Shore Drive | 6 | Ductile Iron | 5 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 5250 | P-7067 | COV | West View Dr. | 8 | Asbestos Cement | 56 | 46 | 1.14 out of 5 | $442 | 24,932 |
| Distribution Main | 5251 | P-7067 | COV | West View Dr. | 8 | Asbestos Cement | 468 | 46 | 1.14 out of 5 | $442 | 206,940 |
| Distribution Main | 5252 | P-7066 | COV | West View Dr. | 8 | Asbestos Cement | 30 | 32 | 1 out of 5 | $442 | 13,294 |
| Distribution Main | 7214 | P-7057 | COV | West View Dr. | 8 | Asbestos Cement | 190 | 46 | 1.14 out of 5 | $442 | 83,777 |
| Distribution Main | 7215 | P-7057 | COV | West View Dr. | 8 | Asbestos Cement | 134 | 46 | 1.14 out of 5 | $442 | 59,346 |
| Distribution Main | 7216 | P-7058 | COV | West View Dr. | 8 | Asbestos Cement | 267 | 46 | 1.14 out of 5 | $442 | 118,076 |
| Distribution Main | 7745 | P-7056 | COV | West View Dr. | 8 | Asbestos Cement | 12 | 46 | 1.14 out of 5 | $442 | 5,380 |
| Distribution Main | 7810 | P-7066 | COV | West View Dr. | 8 | Asbestos Cement | 232 | 46 | 1.14 out of 5 | $442 | 102,381 |
| Distribution Main | 7811 | P-7066 | COV | West View Dr. | 8 | Asbestos Cement | 373 | 32 | 1 out of 5 | $442 | 165,082 |
| Distribution Main | 7812 | P-7066 | COV | West View Dr. | 8 | Asbestos Cement | 216 | 32 | 1 out of 5 | $442 | 95,670 |
| Distribution Main | 7825 | P-7056 | COV | West View Dr. | 8 | Asbestos Cement | 304 | 46 | 1.14 out of 5 | $442 | 134,457 |
| Distribution Main | 11364 | P-7057 | COV | West View Dr. | 8 | Asbestos Cement | 4 | 46 | 1.14 out of 5 | $442 | 1,618 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 11410 | P-7066 | COV | West View Dr. | 8 | Asbestos Cement | 7 | 46 | 1.14 out of 5 | $442 | 3,201 |
| Distribution Main | 2364 | | COV | Whipple Court | 6 | Ductile Iron | 8 | 30 | 0.85 out of 5 | $442 | 3,610 |
| Distribution Main | 2365 | | COV | Whipple Court | 6 | Ductile Iron | 473 | 30 | 0.85 out of 5 | $442 | 209,075 |
| Distribution Main | 6319 | P-7133 | COV | White Oak Ct. | 8 | Ductile Iron | 200 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6320 | P-7132 | COV | White Oak Ct. | 8 | Ductile Iron | 813 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6321 | P-7132 | COV | White Oak Ct. | 8 | Ductile Iron | 69 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1915 | P-7906 | COV | White Pine Rd. | 8 | Asbestos Cement | 417 | 39 | 1 out of 5 | $442 | 184,479 |
| Distribution Main | 1916 | P-7904 | COV | White Pine Rd. | 8 | Asbestos Cement | 77 | 39 | 1 out of 5 | $442 | 34,149 |
| Distribution Main | 1917 | P-7904 | COV | White Pine Rd. | 8 | Asbestos Cement | 675 | 39 | 1 out of 5 | $442 | 298,528 |
| Distribution Main | 595 | P-7881 | COV | White Rock Dr. | 8 | Asbestos Cement | 663 | 54 | 1.14 out of 5 | $442 | 292,888 |
| Distribution Main | 596 | P-7881 | COV | White Rock Dr. | 8 | Asbestos Cement | 19 | 54 | 1.14 out of 5 | $442 | 8,531 |
| Distribution Main | 2115 | P-7322 | COV | White Rock Dr. | 8 | Asbestos Cement | 776 | 54 | 1.14 out of 5 | $442 | 342,861 |
| Distribution Main | 9964 | P-7321 | COV | White Rock Dr. | 8 | Asbestos Cement | 4 | 54 | 1.14 out of 5 | $442 | 1,794 |
| Distribution Main | 12171 | | COV | White Rock Dr. | 8 | Asbestos Cement | 175 | 54 | 1.14 out of 5 | $442 | 77,158 |
| Distribution Main | 12172 | | COV | White Rock Dr. | 8 | Asbestos Cement | 16 | 54 | 1.14 out of 5 | $442 | 7,130 |
| Distribution Main | 1584 | P-8764 | COV | Whitford St. | 8 | Ductile Iron | 827 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1059 | P-7565 | COV | Whitman St. | 6 | Asbestos Cement | 14 | 50 | 1.85 out of 5 | $442 | 6,276 |
| Distribution Main | 1060 | P-7565 | COV | Whitman St. | 6 | Asbestos Cement | 395 | 50 | 1.85 out of 5 | $442 | 174,712 |
| Distribution Main | 2262 | P-8161 | COV | Whittier Dr. | 8 | Asbestos Cement | 198 | 46 | 1.14 out of 5 | $442 | 87,497 |
| Distribution Main | 4562 | P-8160 | COV | Whittier Dr. | 8 | Asbestos Cement | 11 | 46 | 1.14 out of 5 | $442 | 4,836 |
| Distribution Main | 4963 | P-8160 | COV | Whittier Dr. | 8 | Asbestos Cement | 427 | 46 | 1.14 out of 5 | $442 | 188,590 |
| Distribution Main | 3058 | P-7356 | COV | Wildflower Dr. | 8 | Ductile Iron | 10 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3060 | P-7356 | COV | Wildflower Dr. | 8 | Ductile Iron | 706 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3061 | P-7356 | COV | Wildflower Dr. | 8 | Ductile Iron | 42 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2647 | P-7549 | COV | Wildwood St. | 6 | Asbestos Cement | 302 | 69 | 2 out of 5 | $442 | 133,587 |
| Distribution Main | 1063 | P-7559 | COV | Williams St. | 6 | Asbestos Cement | 298 | 69 | 2 out of 5 | $442 | 131,607 |
| Distribution Main | 2475 | P-7559 | COV | Williams St. | 2 | Galvanized Iron | 102 | 87 | 3.43 out of 5 | $442 | 45,203 |
| Distribution Main | 2636 | P-7559 | COV | Williams St. | 2 | Galvanized Iron | 18 | 87 | 3.43 out of 5 | $442 | 7,850 |
| Distribution Main | 2646 | P-7560 | COV | Williams St. | 6 | Asbestos Cement | 575 | 69 | 2 out of 5 | $442 | 254,248 |
| Distribution Main | 9766 | P-1384 | COV | Wilshire Way | 8 | Ductile Iron | 441 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9785 | P-628 | COV | Wilshire Way | 8 | Ductile Iron | 282 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9786 | P-628 | COV | Wilshire Way | 8 | Ductile Iron | 135 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11603 | P-628 | COV | Wilshire Way | 8 | Ductile Iron | 35 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9736 | P-8203 | COV | Windsor Park Dr | 8 | Ductile Iron | 540 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9737 | P-8204 | COV | Windsor Park Dr | 8 | Ductile Iron | 354 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9739 | P-8206 | COV | Windsor Park Dr | 8 | Ductile Iron | 121 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9740 | P-8206 | COV | Windsor Park Dr | 8 | Ductile Iron | 104 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9742 | P-1961 | COV | Windsor Park Dr | 8 | Ductile Iron | 234 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9743 | P-1961 | COV | Windsor Park Dr | 8 | Ductile Iron | 2 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9747 | P-9070 | COV | Windsor Park Dr | 8 | Ductile Iron | 70 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9750 | P-8213 | COV | Windsor Park Dr | 8 | Ductile Iron | 370 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9755 | P-8213 | COV | Windsor Park Dr | 8 | Ductile Iron | 97 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9756 | P-8213 | COV | Windsor Park Dr | 8 | Ductile Iron | 119 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10863 | P-8209 | COV | Windsor Park Dr | 8 | Ductile Iron | 150 | 8 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10864 | P-8207 | COV | Windsor Park Dr | 8 | Ductile Iron | 194 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10867 | P-8210 | COV | Windsor Park Dr | 8 | Ductile Iron | 86 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10868 | P-8210 | COV | Windsor Park Dr | 8 | Ductile Iron | 256 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11595 | P-8209 | COV | Windsor Park Dr | 8 | Ductile Iron | 24 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11596 | P-1960 | COV | Windsor Park Dr | 8 | Ductile Iron | 54 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11597 | P-603 | COV | Windsor Park Dr | 8 | Ductile Iron | 28 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11598 | P-8207 | COV | Windsor Park Dr | 8 | Ductile Iron | 62 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7213 | P-7068 | COV | Winterberry Dr. | 6 | Asbestos Cement | 19 | 46 | 1.85 out of 5 | $442 | 8,271 |
| Distribution Main | 7809 | P-7068 | COV | Winterberry Dr. | 6 | Asbestos Cement | 583 | 46 | 1.85 out of 5 | $442 | 257,523 |
| Distribution Main | 7814 | P-7070 | COV | Winterberry Dr. | 6 | Asbestos Cement | 48 | 46 | 1.85 out of 5 | $442 | 21,355 |
| Distribution Main | 7826 | P-7070 | COV | Winterberry Dr. | 6 | Asbestos Cement | 416 | 46 | 1.85 out of 5 | $442 | 183,725 |
| Distribution Main | 1016 | P-7896 | COV | Wintergreen Ct. | 6 | Asbestos Cement | 243 | 38 | 1.71 out of 5 | $442 | 107,387 |
| Distribution Main | 4457 | P-7055 | COV | Wisteria Dr. | 8 | Asbestos Cement | 16 | 57 | 1.14 out of 5 | $442 | 7,169 |
| Distribution Main | 7217 | P-7054 | COV | Wisteria Dr. | 8 | Asbestos Cement | 28 | 57 | 1.14 out of 5 | $442 | 12,591 |
| Distribution Main | 7218 | P-7054 | COV | Wisteria Dr. | 8 | Asbestos Cement | 426 | 57 | 1.14 out of 5 | $442 | 188,245 |
| Distribution Main | 7219 | P-7039 | COV | Wisteria Dr. | 8 | Asbestos Cement | 491 | 57 | 1.14 out of 5 | $442 | 217,064 |
| Distribution Main | 7220 | P-7040 | COV | Wisteria Dr. | 8 | Asbestos Cement | 48 | 57 | 1.14 out of 5 | $442 | 21,284 |
| Distribution Main | 7221 | P-7040 | COV | Wisteria Dr. | 8 | Asbestos Cement | 160 | 57 | 1.14 out of 5 | $442 | 70,931 |
| Distribution Main | 7222 | P-7041 | COV | Wisteria Dr. | 8 | Asbestos Cement | 216 | 57 | 1.14 out of 5 | $442 | 95,447 |
| Distribution Main | 7223 | P-7037 | COV | Wisteria Dr. | 8 | Asbestos Cement | 60 | 57 | 1.14 out of 5 | $442 | 26,654 |
| Distribution Main | 7224 | P-7037 | COV | Wisteria Dr. | 8 | Asbestos Cement | 559 | 57 | 1.14 out of 5 | $442 | 246,964 |
| Distribution Main | 7225 | P-7030 | COV | Wisteria Dr. | 8 | Asbestos Cement | 683 | 57 | 1.14 out of 5 | $442 | 301,918 |
| Distribution Main | 7547 | P-7055 | COV | Wisteria Dr. | 8 | Asbestos Cement | 8 | 57 | 1.14 out of 5 | $442 | 3,676 |
| Distribution Main | 7590 | P-7011 | COV | Wisteria Dr. | 8 | Asbestos Cement | 113 | 57 | 1.14 out of 5 | $442 | 50,114 |
| Distribution Main | 7591 | P-7011 | COV | Wisteria Dr. | 8 | Asbestos Cement | 895 | 57 | 1.14 out of 5 | $442 | 395,410 |
| Distribution Main | 7725 | P-7026 | COV | Wisteria Dr. | 8 | Asbestos Cement | 314 | 57 | 1.14 out of 5 | $442 | 138,567 |
| Distribution Main | 7726 | P-7017 | COV | Wisteria Dr. | 8 | Asbestos Cement | 9 | 57 | 1.14 out of 5 | $442 | 4,035 |
| Distribution Main | 7727 | P-7017 | COV | Wisteria Dr. | 8 | Asbestos Cement | 367 | 57 | 1.14 out of 5 | $442 | 162,219 |
| Distribution Main | 7734 | P-7030 | COV | Wisteria Dr. | 8 | Asbestos Cement | 16 | 57 | 1.14 out of 5 | $442 | 7,065 |
| Distribution Main | 7743 | P-7055 | COV | Wisteria Dr. | 8 | Asbestos Cement | 179 | 57 | 1.14 out of 5 | $442 | 78,923 |
| Distribution Main | 7744 | P-7055 | COV | Wisteria Dr. | 8 | Asbestos Cement | 251 | 57 | 1.14 out of 5 | $442 | 110,877 |
| Distribution Main | 8181 | P-7025 | COV | Wisteria Dr. | 8 | Asbestos Cement | 454 | 57 | 1.14 out of 5 | $442 | 200,848 |
| Distribution Main | 11365 | P-7054 | COV | Wisteria Dr. | 8 | Asbestos Cement | 3 | 57 | 1.14 out of 5 | $442 | 1,516 |
| Distribution Main | 11366 | P-7039 | COV | Wisteria Dr. | 8 | Asbestos Cement | 7 | 57 | 1.14 out of 5 | $442 | 2,987 |
| Distribution Main | 11367 | P-7040 | COV | Wisteria Dr. | 8 | Asbestos Cement | 20 | 57 | 1.14 out of 5 | $442 | 8,620 |
| Distribution Main | 11368 | P-7041 | COV | Wisteria Dr. | 8 | Asbestos Cement | 6 | 57 | 1.14 out of 5 | $442 | 2,791 |
| Distribution Main | 11407 | P-7026 | COV | Wisteria Dr. | 8 | Asbestos Cement | 13 | 57 | 1.14 out of 5 | $442 | 5,901 |
| Distribution Main | 11798 | P-7011 | COV | Wisteria Dr. | 8 | Asbestos Cement | 647 | 57 | 1.14 out of 5 | $442 | 286,086 |
| Distribution Main | 1667 | P-8932 | COV | Woburn Street | 6 | Asbestos Cement | 277 | 60 | 1.85 out of 5 | $442 | 122,413 |
| Distribution Main | 8324 | P-7082 | COV | Wolfe Ct. | 6 | Ductile Iron | 45 | 29 | 0.85 out of 5 | $442 | 20,016 |
| Distribution Main | 8325 | P-7082 | COV | Wolfe Ct. | 6 | Ductile Iron | 222 | 29 | 0.85 out of 5 | $442 | 98,311 |
| Distribution Main | 9261 | P-7013 | COV | Wood Cove Dr | | Unknown | 58 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 7209 | P-7052 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 43 | 51 | 1.14 out of 5 | $442 | 19,013 |
| Distribution Main | 7210 | P-7052 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 165 | 51 | 1.14 out of 5 | $442 | 72,799 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 7456 | P-7090 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 571 | 51 | 1.14 out of 5 | $442 | 252,539 |
| Distribution Main | 7457 | P-7090 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 54 | 51 | 1.14 out of 5 | $442 | 23,801 |
| Distribution Main | 7601 | P-7088 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 79 | 51 | 1.14 out of 5 | $442 | 34,863 |
| Distribution Main | 7602 | P-7088 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 540 | 51 | 1.14 out of 5 | $442 | 238,772 |
| Distribution Main | 7709 | P-7012 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 142 | 51 | 1.14 out of 5 | $442 | 62,549 |
| Distribution Main | 7710 | P-7012 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 492 | 51 | 1.14 out of 5 | $442 | 217,362 |
| Distribution Main | 7715 | P-7015 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 41 | 51 | 1.14 out of 5 | $442 | 18,262 |
| Distribution Main | 7716 | P-7015 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 5 | 51 | 1.14 out of 5 | $442 | 2,192 |
| Distribution Main | 7717 | P-7015 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 767 | 51 | 1.14 out of 5 | $442 | 339,082 |
| Distribution Main | 7718 | P-7029 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 383 | 51 | 1.14 out of 5 | $442 | 169,232 |
| Distribution Main | 7719 | P-7033 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 251 | 51 | 1.14 out of 5 | $442 | 110,780 |
| Distribution Main | 7730 | P-7013 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 690 | 51 | 1.14 out of 5 | $442 | 305,073 |
| Distribution Main | 7731 | P-7013 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 221 | 51 | 1.14 out of 5 | $442 | 97,861 |
| Distribution Main | 7739 | P-7079 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 15 | 51 | 1.14 out of 5 | $442 | 6,502 |
| Distribution Main | 7817 | P-7051 | COV | Wood Cove Dr. | 6 | Asbestos Cement | 418 | 51 | 1.85 out of 5 | $442 | 184,817 |
| Distribution Main | 7818 | P-7051 | COV | Wood Cove Dr. | 6 | Asbestos Cement | 257 | 51 | 1.85 out of 5 | $442 | 113,814 |
| Distribution Main | 7823 | P-7049 | COV | Wood Cove Dr. | 6 | Asbestos Cement | 453 | 51 | 1.85 out of 5 | $442 | 200,029 |
| Distribution Main | 7824 | P-7049 | COV | Wood Cove Dr. | 6 | Asbestos Cement | 395 | 51 | 1.85 out of 5 | $442 | 174,379 |
| Distribution Main | 7833 | P-7047 | COV | Wood Cove Dr. | 6 | Asbestos Cement | 54 | 51 | 1.85 out of 5 | $442 | 23,844 |
| Distribution Main | 7834 | P-7047 | COV | Wood Cove Dr. | 6 | Asbestos Cement | 221 | 51 | 1.85 out of 5 | $442 | 97,838 |
| Distribution Main | 7837 | P-7079 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 32 | 51 | 1.14 out of 5 | $442 | 14,311 |
| Distribution Main | 7838 | P-7079 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 405 | 51 | 1.14 out of 5 | $442 | 179,215 |
| Distribution Main | 8853 | P-8960 | COV | Wood Cove Dr. | 8 | Ductile Iron | 8 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8854 | P-8961 | COV | Wood Cove Dr. | 8 | Ductile Iron | 6 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8855 | P-8961 | COV | Wood Cove Dr. | 6 | Ductile Iron | 2 | 13 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11404 | P-7015 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 8 | 51 | 1.14 out of 5 | $442 | 3,327 |
| Distribution Main | 11405 | P-7015 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 11 | 51 | 1.14 out of 5 | $442 | 4,836 |
| Distribution Main | 11795 | P-7015 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 613 | 51 | 1.14 out of 5 | $442 | 271,109 |
| Distribution Main | 11797 | P-7088 | COV | Wood Cove Dr. | 8 | Asbestos Cement | 532 | 51 | 1.14 out of 5 | $442 | 235,032 |
| Distribution Main | 9332 | | COV | Wood St | 6 | Ductile Iron | 19 | 10 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 581 | P-8931 | COV | Wood St. | 16 | Cast Iron | 37 | 129 | 1.86 out of 5 | $442 | 16,388 |
| Transmission Main | 1039 | P-7557 | COV | Wood St. | 16 | Cast Iron | 126 | 129 | 1.86 out of 5 | $442 | 55,691 |
| Transmission Main | 1040 | P-7557 | COV | Wood St. | 16 | Cast Iron | 227 | 129 | 1.86 out of 5 | $442 | 100,534 |
| Transmission Main | 1307 | P-7558 | COV | Wood St. | 16 | Cast Iron | 186 | 129 | 1.86 out of 5 | $442 | 82,415 |
| Transmission Main | 2473 | P-7555 | COV | Wood St. | 16 | Cast Iron | 72 | 129 | 1.86 out of 5 | $442 | 31,614 |
| Transmission Main | 2474 | P-7555 | COV | Wood St. | 16 | Cast Iron | 52 | 129 | 1.86 out of 5 | $442 | 22,862 |
| Transmission Main | 2628 | P-7555 | COV | Wood St. | 16 | Cast Iron | 702 | 129 | 1.86 out of 5 | $442 | 310,488 |
| Transmission Main | 2632 | P-7558 | COV | Wood St. | 16 | Cast Iron | 215 | 129 | 1.86 out of 5 | $442 | 95,017 |
| Transmission Main | 2825 | | COV | Wood St. | 12 | Unknown | 14 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 2987 | P-8931 | COV | Wood St. | 16 | Cast Iron | 129 | 129 | 1.86 out of 5 | $442 | 56,829 |
| Transmission Main | 2988 | P-8931 | COV | Wood St. | 16 | Cast Iron | 506 | 129 | 1.86 out of 5 | $442 | 223,595 |
| Transmission Main | 2989 | | COV | Wood St. | 12 | Unknown | 67 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 11098 | P-7557 | COV | Wood St. | 16 | Cast Iron | 68 | 129 | 1.86 out of 5 | $442 | 30,239 |
| Transmission Main | 11121 | P-7558 | COV | Wood St. | 16 | Cast Iron | 23 | 129 | 1.86 out of 5 | $442 | 10,094 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 11122 | P-7558 | COV | Wood St. | 16 | Cast Iron | 11 | 129 | 1.86 out of 5 | $442 | 4,671 |
| Transmission Main | 11198 | P-8931 | COV | Wood St. | 16 | Cast Iron | 144 | 129 | 1.86 out of 5 | $442 | 63,725 |
| Transmission Main | 12182 | | COV | Wood St. | 16 | Cast Iron | 51 | 129 | 1.86 out of 5 | $442 | 22,427 |
| Transmission Main | 12183 | | COV | Wood St. | 16 | Cast Iron | 58 | 129 | 1.86 out of 5 | $442 | 25,768 |
| Distribution Main | 476 | | COV | Woodland Ave. | 6 | Asbestos Cement | 61 | 69 | 2 out of 5 | $442 | 27,045 |
| Distribution Main | 1642 | P-7547 | COV | Woodland Ave. | 6 | Asbestos Cement | 212 | 69 | 2 out of 5 | $442 | 93,502 |
| Distribution Main | 1643 | P-7547 | COV | Woodland Ave. | 6 | Asbestos Cement | 363 | 69 | 2 out of 5 | $442 | 160,624 |
| Distribution Main | 1858 | P-7548 | COV | Woodland Ave. | 6 | Asbestos Cement | 240 | 69 | 2 out of 5 | $442 | 106,130 |
| Distribution Main | 407 | P-8067 | COV | Woodmist Cir. | 8 | Ductile Iron | 1,054 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 408 | P-8067 | COV | Woodmist Cir. | 8 | Ductile Iron | 1,164 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11746 | P-8067 | COV | Woodmist Cir. | 8 | Ductile Iron | 795 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10342 | | COV | Wright Way | | Unknown | 19 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 1719 | P-7780 | COV | Yale Dr. | 6 | Asbestos Cement | 579 | 60 | 1.85 out of 5 | $442 | 255,699 |
| Distribution Main | 2204 | P-7791 | COV | Yale Dr. | 6 | Asbestos Cement | 441 | 60 | 1.85 out of 5 | $442 | 194,920 |
| Distribution Main | 2205 | P-7791 | COV | Yale Dr. | 6 | Asbestos Cement | 285 | 60 | 1.85 out of 5 | $442 | 126,054 |
| Distribution Main | 3175 | P-7792 | COV | Yale Dr. | 6 | Asbestos Cement | 197 | 60 | 1.85 out of 5 | $442 | 87,222 |
| Distribution Main | 9946 | P-7780 | COV | Yale Dr. | 6 | Asbestos Cement | 23 | 60 | 1.85 out of 5 | $442 | 10,044 |
| Distribution Main | 404 | P-7982 | COV | Yates Ave. | 6 | Asbestos Cement | 23 | 70 | 2 out of 5 | $442 | 10,157 |
| Distribution Main | 405 | P-7982 | COV | Yates Ave. | 6 | Asbestos Cement | 211 | 70 | 2 out of 5 | $442 | 93,309 |
| Distribution Main | 942 | P-9063 | COV | Yates Ave. | 1 | Copper | 339 | UNK | 1.99 out of 5 | $442 | 149,980 |
| Distribution Main | 9222 | P-8076 | COV | Yeaton St | 8 | Ductile Iron | 609 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1862 | P-7621 | COV | York Dr. | 8 | Asbestos Cement | 46 | 53 | 1.14 out of 5 | $442 | 20,150 |
| Distribution Main | 1863 | P-7621 | COV | York Dr. | 8 | Asbestos Cement | 740 | 53 | 1.14 out of 5 | $442 | 327,234 |
| Distribution Main | 1864 | P-7601 | COV | York Dr. | 8 | Asbestos Cement | 464 | 53 | 1.14 out of 5 | $442 | 205,118 |
| Distribution Main | 2560 | P-7627 | COV | York Dr. | 8 | Asbestos Cement | 34 | 53 | 1.14 out of 5 | $442 | 15,238 |
| Distribution Main | 2604 | P-7626 | COV | York Dr. | 8 | Asbestos Cement | 825 | 53 | 1.14 out of 5 | $442 | 364,735 |
| Distribution Main | 2605 | P-7626 | COV | York Dr. | 8 | Asbestos Cement | 660 | 53 | 1.14 out of 5 | $442 | 291,589 |
| Distribution Main | 2407 | P-8048 | COV | Youngs Ave. | 8 | Asbestos Cement | 196 | 63 | 1.29 out of 5 | $442 | 86,597 |
| Distribution Main | 2929 | P-8048 | COV | Youngs Ave. | 8 | Asbestos Cement | 15 | 63 | 1.29 out of 5 | $442 | 6,455 |
| Distribution Main | 8891 | P-5026 | CRA | Allard St | 8 | Ductile Iron | 53 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8892 | P-5026 | CRA | Allard St | 8 | Ductile Iron | 541 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8893 | P-5027 | CRA | Allard St | 8 | Ductile Iron | 468 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11806 | P-5026 | CRA | Allard St | 8 | Ductile Iron | 4 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8867 | P-5042 | CRA | Amanda Ct | 8 | Ductile Iron | 247 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8869 | P-5040 | CRA | Amanda St | 8 | Ductile Iron | 200 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8870 | P-5040 | CRA | Amanda St | 8 | Ductile Iron | 124 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8872 | P-5039 | CRA | Amanda St | 8 | Ductile Iron | 407 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8873 | P-5039 | CRA | Amanda St | 8 | Ductile Iron | 131 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8875 | P-5039 | CRA | Amanda St | 8 | Ductile Iron | 461 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8876 | P-5167 | CRA | Amanda St | 8 | Ductile Iron | 390 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11520 | P-5040 | CRA | Amanda St | 8 | Ductile Iron | 102 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7401 | P-5005 | CRA | Angell Ave. | 8 | Ductile Iron | 349 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7410 | P-5151 | CRA | Angell Ave. | 8 | Ductile Iron | 7 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7419 | P-5153 | CRA | Angell Ave. | 8 | Ductile Iron | 30 | 15 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 7424 | P-5153 | CRA | Angell Ave. | 8 | Ductile Iron | 159 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7466 | P-5005 | CRA | Angell Ave. | 8 | Ductile Iron | 116 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8701 | P-5153 | CRA | Angell Ave. | 8 | Ductile Iron | 140 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8702 | P-5006 | CRA | Angell Ave. | 8 | Ductile Iron | 27 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10988 | P-5006 | CRA | Angell Ave. | 8 | Ductile Iron | 91 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10989 | P-5015 | CRA | Angell Ave. | 8 | Ductile Iron | 256 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11376 | P-5003 | CRA | Angell Ave. | 8 | Ductile Iron | 481 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11377 | P-5151 | CRA | Angell Ave. | 8 | Ductile Iron | 4 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10321 | | CRA | Bald Hill Rd | 8 | Ductile Iron | 322 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10322 | | CRA | Bald Hill Rd | 8 | Ductile Iron | 29 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10323 | P-5101 | CRA | Bald Hill Rd | 10 | Ductile Iron | 12 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11805 | | CRA | Bald Hill Rd | 8 | Ductile Iron | 18 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12130 | | CRA | Bald Hill Rd | 8 | Ductile Iron | 4 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4591 | | CRA | Bald Hill Rd. | 6 | Asbestos Cement | 6 | 51 | 1.85 out of 5 | $442 | 2,798 |
| Distribution Main | 4592 | P-5099 | CRA | Bald Hill Rd. | 6 | Asbestos Cement | 9 | 51 | 1.85 out of 5 | $442 | 4,088 |
| Distribution Main | 4593 | P-5099 | CRA | Bald Hill Rd. | 6 | Asbestos Cement | 151 | 51 | 1.85 out of 5 | $442 | 66,527 |
| Distribution Main | 4594 | P-5095 | CRA | Bald Hill Rd. | 10 | Asbestos Cement | 543 | 51 | 1.14 out of 5 | $442 | 239,965 |
| Distribution Main | 5380 | P-5101 | CRA | Bald Hill Rd. | 10 | Asbestos Cement | 220 | 51 | 1.14 out of 5 | $442 | 97,115 |
| Distribution Main | 5382 | P-5100 | CRA | Bald Hill Rd. | 6 | Asbestos Cement | 114 | 51 | 1.85 out of 5 | $442 | 50,191 |
| Distribution Main | 5387 | P-5101 | CRA | Bald Hill Rd. | 10 | Asbestos Cement | 138 | 51 | 1.14 out of 5 | $442 | 61,043 |
| Distribution Main | 5388 | P-5100 | CRA | Bald Hill Rd. | 6 | Unknown | 11 | UNK | 0.71 out of 5 | $442 | 5,033 |
| Distribution Main | 5389 | P-5100 | CRA | Bald Hill Rd. | 6 | Asbestos Cement | 62 | UNK | 1.56 out of 5 | $442 | 27,620 |
| Distribution Main | 5646 | P-5095 | CRA | Bald Hill Rd. | 6 | Asbestos Cement | 345 | 51 | 1.85 out of 5 | $442 | 152,351 |
| Distribution Main | 5647 | P-5099 | CRA | Bald Hill Rd. | 6 | Asbestos Cement | 4 | 51 | 1.85 out of 5 | $442 | 1,793 |
| Distribution Main | 7411 | P-5101 | CRA | Bald Hill Rd. | 10 | Asbestos Cement | 150 | 51 | 1.14 out of 5 | $442 | 66,129 |
| Distribution Main | 7412 | P-5099 | CRA | Bald Hill Rd. | 6 | Asbestos Cement | 17 | 51 | 1.85 out of 5 | $442 | 7,456 |
| Distribution Main | 10532 | P-5095 | CRA | Bald Hill Rd. | 6 | Asbestos Cement | 49 | 51 | 1.85 out of 5 | $442 | 21,658 |
| Distribution Main | 10533 | | CRA | Bald Hill Rd. | 6 | Asbestos Cement | 53 | 51 | 1.85 out of 5 | $442 | 23,508 |
| Distribution Main | 10828 | P-5097 | CRA | Bald Hill Rd. | 10 | Asbestos Cement | 36 | 51 | 1.14 out of 5 | $442 | 15,703 |
| Distribution Main | 10829 | P-5097 | CRA | Bald Hill Rd. | 10 | Asbestos Cement | 239 | 51 | 1.14 out of 5 | $442 | 105,833 |
| Distribution Main | 11258 | P-5097 | CRA | Bald Hill Rd. | 10 | Asbestos Cement | 113 | 51 | 1.14 out of 5 | $442 | 50,115 |
| Distribution Main | 11300 | P-5100 | CRA | Bald Hill Rd. | 6 | Asbestos Cement | 6 | 51 | 1.85 out of 5 | $442 | 2,595 |
| Distribution Main | 11378 | P-5101 | CRA | Bald Hill Rd. | 10 | Asbestos Cement | 24 | 51 | 1.14 out of 5 | $442 | 10,477 |
| Distribution Main | 9034 | P-5033 | CRA | Benjamin Ave | 8 | Ductile Iron | 18 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8874 | P-5033 | CRA | Benjamin Ave. | 8 | Ductile Iron | 252 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8884 | P-5034 | CRA | Benjamin Ave. | 8 | Ductile Iron | 61 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10826 | P-5034 | CRA | Benjamin Ave. | 8 | Ductile Iron | 185 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10827 | P-5168 | CRA | Benjamin Ave. | 8 | Ductile Iron | 18 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4170 | | CRA | Briarwood Rd. | 6 | Asbestos Cement | 7 | 62 | 2 out of 5 | $442 | 2,976 |
| Distribution Main | 4171 | | CRA | Briarwood Rd. | 6 | Asbestos Cement | 5 | 62 | 2 out of 5 | $442 | 2,076 |
| Distribution Main | 4934 | P-5072 | CRA | Briarwood Rd. | 6 | Asbestos Cement | 20 | 62 | 2 out of 5 | $442 | 8,887 |
| Distribution Main | 6544 | P-5079 | CRA | Briarwood Rd. | 6 | Asbestos Cement | 190 | 62 | 2 out of 5 | $442 | 84,105 |
| Distribution Main | 7488 | P-5072 | CRA | Briarwood Rd. | 6 | Asbestos Cement | 6 | 62 | 2 out of 5 | $442 | 2,626 |
| Distribution Main | 4939 | P-5080 | CRA | Brookfield Dr. | 6 | Asbestos Cement | 435 | 64 | 2 out of 5 | $442 | 192,317 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6535 | P-5080 | CRA | Brookfield Dr. | 6 | Asbestos Cement | 415 | 64 | 2 out of 5 | $442 | 183,361 |
| Distribution Main | 6536 | P-5080 | CRA | Brookfield Dr. | 6 | Asbestos Cement | 77 | 64 | 2 out of 5 | $442 | 33,884 |
| Distribution Main | 6540 | P-5074 | CRA | Brookfield Dr. | 6 | Asbestos Cement | 7 | 64 | 2 out of 5 | $442 | 3,148 |
| Distribution Main | 6541 | P-5074 | CRA | Brookfield Dr. | 6 | Asbestos Cement | 350 | 64 | 2 out of 5 | $442 | 154,506 |
| Distribution Main | 6545 | P-5079 | CRA | Brookfield Dr. | 6 | Asbestos Cement | 5 | 64 | 2 out of 5 | $442 | 2,256 |
| Distribution Main | 10981 | P-5080 | CRA | Brookfield Dr. | 6 | Asbestos Cement | 3 | 64 | 2 out of 5 | $442 | 1,220 |
| Distribution Main | 8866 | P-5090 | CRA | Burdick Dr | 8 | Ductile Iron | 6 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10994 | P-5092 | CRA | Burdick Dr | 8 | Ductile Iron | 3 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3278 | P-5081 | CRA | Burdick Dr. | 8 | Asbestos Cement | 34 | 49 | 1.14 out of 5 | $442 | 15,076 |
| Distribution Main | 3279 | P-5081 | CRA | Burdick Dr. | 8 | Asbestos Cement | 180 | 49 | 1.14 out of 5 | $442 | 79,420 |
| Distribution Main | 5990 | P-5092 | CRA | Burdick Dr. | 8 | Asbestos Cement | 90 | 49 | 1.14 out of 5 | $442 | 39,928 |
| Distribution Main | 5991 | P-5089 | CRA | Burdick Dr. | 8 | Asbestos Cement | 126 | 49 | 1.14 out of 5 | $442 | 55,856 |
| Distribution Main | 5992 | P-5089 | CRA | Burdick Dr. | 8 | Asbestos Cement | 551 | 49 | 1.14 out of 5 | $442 | 243,723 |
| Distribution Main | 5993 | P-5092 | CRA | Burdick Dr. | 8 | Asbestos Cement | 958 | 49 | 1.14 out of 5 | $442 | 423,338 |
| Distribution Main | 5994 | P-5092 | CRA | Burdick Dr. | 8 | Asbestos Cement | 132 | 49 | 1.14 out of 5 | $442 | 58,347 |
| Distribution Main | 5997 | P-5090 | CRA | Burdick Dr. | 8 | Asbestos Cement | 269 | 49 | 1.14 out of 5 | $442 | 118,763 |
| Distribution Main | 5999 | P-5083 | CRA | Burdick Dr. | 8 | Asbestos Cement | 255 | 49 | 1.14 out of 5 | $442 | 112,799 |
| Distribution Main | 7372 | P-5092 | CRA | Burdick Dr. | 8 | Asbestos Cement | 25 | 49 | 1.14 out of 5 | $442 | 11,119 |
| Distribution Main | 7373 | P-5085 | CRA | Burdick Dr. | 8 | Asbestos Cement | 30 | 49 | 1.14 out of 5 | $442 | 13,439 |
| Distribution Main | 7374 | P-5085 | CRA | Burdick Dr. | 8 | Asbestos Cement | 247 | 49 | 1.14 out of 5 | $442 | 109,031 |
| Distribution Main | 4947 | P-5110 | CRA | Candle Dr. | 8 | Asbestos Cement | 297 | 42 | 1.14 out of 5 | $442 | 131,338 |
| Distribution Main | 4948 | P-5110 | CRA | Candle Dr. | 8 | Asbestos Cement | 102 | 42 | 1.14 out of 5 | $442 | 44,944 |
| Distribution Main | 7487 | P-5110 | CRA | Candle Dr. | 8 | Asbestos Cement | 18 | 42 | 1.14 out of 5 | $442 | 7,755 |
| Distribution Main | 762 | P-5049 | CRA | Capeway Rd. | 6 | Asbestos Cement | 127 | 70 | 2 out of 5 | $442 | 55,926 |
| Distribution Main | 763 | P-5049 | CRA | Capeway Rd. | 6 | Asbestos Cement | 92 | 70 | 2 out of 5 | $442 | 40,548 |
| Distribution Main | 3317 | P-5049 | CRA | Capeway Rd. | 6 | Asbestos Cement | 8 | 70 | 2 out of 5 | $442 | 3,575 |
| Distribution Main | 3281 | P-5117 | CRA | Carriage Rd. | 8 | Asbestos Cement | 10 | 42 | 1.14 out of 5 | $442 | 4,261 |
| Distribution Main | 3282 | P-5113 | CRA | Carriage Rd. | 8 | Asbestos Cement | 170 | 44 | 1.14 out of 5 | $442 | 74,992 |
| Distribution Main | 4520 | P-5111 | CRA | Carriage Rd. | 8 | Asbestos Cement | 39 | 44 | 1.14 out of 5 | $442 | 17,390 |
| Distribution Main | 4521 | | CRA | Carriage Rd. | 8 | Asbestos Cement | 57 | 44 | 1.14 out of 5 | $442 | 25,075 |
| Distribution Main | 4522 | P-5109 | CRA | Carriage Rd. | 8 | Asbestos Cement | 276 | 44 | 1.14 out of 5 | $442 | 121,919 |
| Distribution Main | 4936 | P-5117 | CRA | Carriage Rd. | 8 | Asbestos Cement | 145 | 42 | 1.14 out of 5 | $442 | 64,237 |
| Distribution Main | 5296 | P-5111 | CRA | Carriage Rd. | 8 | Asbestos Cement | 207 | 44 | 1.14 out of 5 | $442 | 91,685 |
| Distribution Main | 7483 | P-1 | CRA | Carriage Rd. | 8 | Asbestos Cement | 259 | 44 | 1.14 out of 5 | $442 | 114,683 |
| Distribution Main | 5905 | P-5115 | CRA | Chapel Dr. | 6 | PVC | 137 | 31 | 1.14 out of 5 | $442 | 60,614 |
| Distribution Main | 5906 | P-5115 | CRA | Chapel Dr. | 6 | PVC | 202 | 31 | 1.14 out of 5 | $442 | 89,403 |
| Distribution Main | 8871 | P-5038 | CRA | Ellison St | 8 | Ductile Iron | 11 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5907 | P-5038 | CRA | Ellison St. | 8 | Ductile Iron | 393 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5908 | P-5038 | CRA | Ellison St. | 8 | Ductile Iron | 452 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5909 | P-5038 | CRA | Ellison St. | 8 | Ductile Iron | 3 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5910 | P-5032 | CRA | Ellison St. | 8 | Ductile Iron | 228 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5911 | P-5032 | CRA | Ellison St. | 8 | Ductile Iron | 24 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9033 | P-5038 | CRA | Ellison St. | 8 | Ductile Iron | 389 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8885 | P-5036 | CRA | Esther St | 8 | Ductile Iron | 19 | 9 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 8886 | P-5036 | CRA | Esther St | 8 | Ductile Iron | 216 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8688 | P-5019 | CRA | Exchange St. | 8 | Ductile Iron | 157 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8689 | P-5019 | CRA | Exchange St. | 8 | Ductile Iron | 96 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10383 | P-5019 | CRA | Exchange St. | 8 | Ductile Iron | 3 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10384 | P-5019 | CRA | Exchange St. | 8 | Ductile Iron | 32 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4269 | P-5060 | CRA | Fairway Dr. | 8 | Ductile Iron | 274 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4270 | P-5060 | CRA | Fairway Dr. | 8 | Ductile Iron | 249 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4271 | | CRA | Fairway Dr. | 8 | Ductile Iron | 6 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4272 | P-5061 | CRA | Fairway Dr. | 8 | Ductile Iron | 145 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4273 | | CRA | Fairway Dr. | 4 | Unknown | 29 | UNK | 1.42 out of 5 | $442 | 12,876 |
| Distribution Main | 5366 | P-5057 | CRA | Fairway Dr. | 8 | Ductile Iron | 29 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5368 | p-5057 | CRA | Fairway Dr. | 8 | Ductile Iron | 127 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11003 | P-5061 | CRA | Fairway Dr. | 8 | Ductile Iron | 2 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11004 | p-5060 | CRA | Fairway Dr. | 8 | Ductile Iron | 2 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11249 | P-5061 | CRA | Fairway Dr. | 8 | Ductile Iron | 7 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8682 | P-5162 | CRA | Fruit St. | 8 | Ductile Iron | 29 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8898 | P-5022 | CRA | Fruit St. | 8 | Ductile Iron | 16 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8899 | P-5022 | CRA | Fruit St. | 8 | Ductile Iron | 214 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11524 | P-5163 | CRA | Fruit St. | 8 | Ductile Iron | 109 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5295 | P-5075 | CRA | Gaunt Dr. | 6 | Asbestos Cement | 236 | 65 | 2 out of 5 | $442 | 104,455 |
| Distribution Main | 6546 | P-5075 | CRA | Gaunt Dr. | 6 | Asbestos Cement | 7 | 65 | 2 out of 5 | $442 | 3,274 |
| Distribution Main | 9987 | P-5076 | CRA | Gaunt Dr. | 8 | Ductile Iron | 178 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9988 | P-5187 | CRA | Gaunt Dr. | 6 | Ductile Iron | 4 | 6 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 5370 | P-5059 | CRA | Green Ct. | 8 | Ductile Iron | 328 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5371 | P-5059 | CRA | Green Ct. | 8 | Ductile Iron | 19 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3092 | P-5118 | CRA | Greenview Rd. | 8 | Asbestos Cement | 336 | 44 | 1.14 out of 5 | $442 | 148,592 |
| Distribution Main | 3280 | P-5105 | CRA | Greenview Rd. | 8 | Asbestos Cement | 229 | 44 | 1.14 out of 5 | $442 | 101,308 |
| Distribution Main | 4945 | P-5118 | CRA | Greenview Rd. | 8 | Asbestos Cement | 82 | 44 | 1.14 out of 5 | $442 | 36,316 |
| Distribution Main | 4946 | P-5118 | CRA | Greenview Rd. | 8 | Asbestos Cement | 18 | 44 | 1.14 out of 5 | $442 | 8,089 |
| Distribution Main | 5369 | P-5058 | CRA | Hagen Ave. | 8 | Ductile Iron | 3 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5372 | P-5185 | CRA | Hagen Ave. | 8 | Ductile Iron | 86 | 46 | 0.29 out of 5 | $442 | 37,924 |
| Distribution Main | 5373 | P-5058 | CRA | Hagen Ave. | 8 | Ductile Iron | 281 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2283 | P-5142 | CRA | Hall Ave. | 6 | Asbestos Cement | 80 | 46 | 1.85 out of 5 | $442 | 35,554 |
| Distribution Main | 2284 | P-5142 | CRA | Hall Ave. | 6 | PVC | 555 | 34 | 1.14 out of 5 | $442 | 245,166 |
| Distribution Main | 9821 | P-5195 | CRA | Hall Ln | 8 | Ductile Iron | 27 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9822 | P-5123 | CRA | Hall Ln | 6 | Ductile Iron | 5 | 7 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10133 | | CRA | Hall Ln | 8 | Ductile Iron | 36 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7486 | P-5112 | CRA | Hard Point Rd. | 8 | Asbestos Cement | 436 | 43 | 1.14 out of 5 | $442 | 192,845 |
| Distribution Main | 7388 | P-5008 | CRA | Harrison Ave. | 8 | Ductile Iron | 243 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7396 | P-5007 | CRA | Harrison Ave. | 8 | Ductile Iron | 233 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8700 | P-5007 | CRA | Harrison Ave. | 8 | Ductile Iron | 3 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9818 | P-5121 | CRA | Hope Rd | 8 | Ductile Iron | 634 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9819 | P-5122 | CRA | Hope Rd | 8 | Ductile Iron | 737 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9820 | P-5121 | CRA | Hope Rd | 12 | Ductile Iron | 1 | 7 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9823 | P-5127 | CRA | Hope Rd | 8 | Ductile Iron | 367 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9824 | P-5127 | CRA | Hope Rd | 8 | Ductile Iron | 1,727 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11614 | P-5124 | CRA | Hope Rd | 8 | Ductile Iron | 25 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8915 | P-164 | CRA | Hopedale Dr | 8 | Ductile Iron | 457 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8916 | P-164 | CRA | Hopedale Dr | 8 | Ductile Iron | 18 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9405 | P-169 | CRA | Hopedale Dr | 8 | Ductile Iron | 78 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10131 | P-6114 | CRA | Jackson Flat Rd | 8 | Ductile Iron | 41 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7385 | P-5159 | CRA | Lincoln Park Ave. | 8 | Asbestos Cement | 232 | 15 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 7426 | P-5009 | CRA | Lincoln Park Ave. | 8 | Ductile Iron | 3 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8035 | P-5009 | CRA | Lincoln Park Ave. | 8 | Asbestos Cement | 23 | 48 | 1.14 out of 5 | $442 | 9,967 |
| Distribution Main | 8170 | P-5009 | CRA | Lincoln Park Ave. | 6 | Asbestos Cement | 153 | 48 | 1.85 out of 5 | $442 | 67,795 |
| Distribution Main | 8703 | P-5009 | CRA | Lincoln Park Ave. | 6 | Asbestos Cement | 989 | 48 | 2.57 out of 5 | $442 | 437,102 |
| Distribution Main | 8877 | P-5029 | CRA | Loring St. | 8 | Ductile Iron | 248 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8878 | P-5029 | CRA | Loring St. | 8 | Ductile Iron | 113 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8887 | P-5029 | CRA | Loring St. | 8 | Ductile Iron | 96 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11521 | P-5029 | CRA | Loring St. | 8 | Ductile Iron | 46 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10129 | P-5125 | CRA | Main St | 8 | Ductile Iron | 414 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10130 | P-5125 | CRA | Main St | 8 | Ductile Iron | 571 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11641 | P-5125 | CRA | Main St | 8 | Ductile Iron | 558 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11642 | P-5125 | CRA | Main St | 8 | Ductile Iron | 17 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11808 | P-5125 | CRA | Main St | 8 | Ductile Iron | 63 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11809 | P-5125 | CRA | Main St | 8 | Ductile Iron | 33 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11810 | P-5125 | CRA | Main St | 8 | Ductile Iron | 10 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12124 | P-5125 | CRA | Main St | 8 | Ductile Iron | 13 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1181 | P-5193 | CRA | Main St. | 12 | Cast Iron | 329 | 133 | 1.86 out of 5 | $442 | 145,615 |
| Transmission Main | 1182 | P-5193 | CRA | Main St. | 12 | Cast Iron | 475 | 133 | 1.86 out of 5 | $442 | 209,833 |
| Distribution Main | 1183 | P-5193 | CRA | Main St. | 6 | Unknown | 13 | UNK | 0.71 out of 5 | $442 | 5,782 |
| Transmission Main | 1315 | P-5193 | CRA | Main St. | 12 | Cast Iron | 393 | 133 | 1.86 out of 5 | $442 | 173,843 |
| Transmission Main | 1316 | P-5193 | CRA | Main St. | 12 | Cast Iron | 47 | 133 | 1.86 out of 5 | $442 | 20,966 |
| Transmission Main | 2112 | | CRA | Main St. | 12 | Cast Iron | 22 | 133 | 1.86 out of 5 | $442 | 9,862 |
| Transmission Main | 8599 | P-5121 | CRA | Main St. | 12 | Ductile Iron | 8 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9817 | | CRA | Main St. | 12 | Cast Iron | 14 | 133 | 1.86 out of 5 | $442 | 6,120 |
| Transmission Main | 10128 | | CRA | Main St. | 12 | Cast Iron | 6 | 133 | 1.86 out of 5 | $442 | 2,492 |
| Transmission Main | 11484 | P-5121 | CRA | Main St. | 12 | Ductile Iron | 6 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11613 | | CRA | Main St. | 12 | Cast Iron | 2 | 133 | 1.86 out of 5 | $442 | 758 |
| Transmission Main | 11807 | P-5193 | CRA | Main St. | 12 | Cast Iron | 56 | 133 | 1.86 out of 5 | $442 | 24,845 |
| Distribution Main | 6542 | P-5077 | CRA | Manor Rd. | 6 | Asbestos Cement | 299 | 65 | 2 out of 5 | $442 | 131,972 |
| Distribution Main | 6543 | P-5077 | CRA | Manor Rd. | 6 | Asbestos Cement | 489 | 65 | 2 out of 5 | $442 | 216,228 |
| Distribution Main | 8918 | P-157 | CRA | Maywood Dr | 8 | Ductile Iron | 472 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8919 | P-157 | CRA | Maywood Dr | 8 | Ductile Iron | 33 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8036 | P-5098 | CRA | Moon Ave. | 6 | Cast Iron | 20 | 91 | 2.43 out of 5 | $442 | 9,045 |
| Distribution Main | 8037 | P-5098 | CRA | Moon Ave. | 6 | Cast Iron | 116 | 91 | 2.43 out of 5 | $442 | 51,249 |
| Transmission Main | 873 | P-5188 | CRA | New London Ave. | 12 | Ductile Iron | 48 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 874 | P-5188 | CRA | New London Ave. | 12 | Ductile Iron | 294 | 15 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 2419 | P-5062 | CRA | New London Ave. | 12 | Ductile Iron | 264 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3589 | P-5062 | CRA | New London Ave. | 12 | Ductile Iron | 555 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4274 | P-5103 | CRA | New London Ave. | 12 | Ductile Iron | 475 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4275 | P-5103 | CRA | New London Ave. | 12 | Ductile Iron | 122 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5375 | P-5188 | CRA | New London Ave. | 12 | Ductile Iron | 154 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8160 | P-5062 | CRA | New London Ave. | 12 | Ductile Iron | 41 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3314 | P-5182 | CRA | Normandy Dr. | 6 | Asbestos Cement | 272 | 69 | 2 out of 5 | $442 | 120,313 |
| Distribution Main | 3315 | P-5138 | CRA | Normandy Dr. | 6 | Asbestos Cement | 324 | 69 | 2 out of 5 | $442 | 143,092 |
| Distribution Main | 3316 | P-5138 | CRA | Normandy Dr. | 6 | Asbestos Cement | 268 | 69 | 2 out of 5 | $442 | 118,450 |
| Distribution Main | 11213 | P-5138 | CRA | Normandy Dr. | 6 | Asbestos Cement | 33 | 69 | 2 out of 5 | $442 | 14,378 |
| Distribution Main | 3690 | P-5184 | CRA | Normandy Drive | 1 | Copper | 147 | UNK | 1.99 out of 5 | $442 | 65,087 |
| Distribution Main | 8907 | P-212 | CRA | Oakland Dr | 6 | Ductile Iron | 6 | 9 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 9412 | P-5174 | CRA | Oaklawn Ave | 12 | Ductile Iron | 27 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9413 | P-5175 | CRA | Oaklawn Ave | 8 | Ductile Iron | 29 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10211 | P-5093 | CRA | Oaklawn Ave | 6 | Ductile Iron | 9 | 13 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 1231 | P-5044 | CRA | Oaklawn Ave. | 12 | Cast Iron | 188 | 91 | 1.72 out of 5 | $442 | 83,059 |
| Transmission Main | 4590 | P-5173 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 272 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5360 | P-5050 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 410 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5362 | P-5052 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 171 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5365 | P-5056 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 4 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5367 | P-5056 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 221 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5457 | P-5055 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 1,348 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5458 | P-5173 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 24 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5459 | P-5173 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 85 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6667 | P-5156 | CRA | Oaklawn Ave. | 10 | Cast Iron | 103 | 91 | 1.72 out of 5 | $442 | 45,704 |
| Distribution Main | 7376 | P-5093 | CRA | Oaklawn Ave. | 10 | Asbestos Cement | 259 | 51 | 1.14 out of 5 | $442 | 114,260 |
| Transmission Main | 7413 | P-5155 | CRA | Oaklawn Ave. | 12 | Cast Iron | 265 | 91 | 1.72 out of 5 | $442 | 117,321 |
| Transmission Main | 7414 | P-5155 | CRA | Oaklawn Ave. | 12 | Cast Iron | 61 | 91 | 1.72 out of 5 | $442 | 26,982 |
| Distribution Main | 7415 | P-5166 | CRA | Oaklawn Ave. | 10 | Cast Iron | 102 | 91 | 1.72 out of 5 | $442 | 44,870 |
| Transmission Main | 7418 | P-5155 | CRA | Oaklawn Ave. | 12 | Cast Iron | 319 | 91 | 1.72 out of 5 | $442 | 141,210 |
| Transmission Main | 7468 | P-5045 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 289 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8161 | P-5139 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 293 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8162 | P-5139 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 322 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8163 | P-5054 | CRA | Oaklawn Ave. | 12 | Cast Iron | 106 | 91 | 1.72 out of 5 | $442 | 46,681 |
| Transmission Main | 8164 | P-5155 | CRA | Oaklawn Ave. | 12 | Cast Iron | 80 | 91 | 1.72 out of 5 | $442 | 35,417 |
| Transmission Main | 8165 | P-5155 | CRA | Oaklawn Ave. | 12 | Cast Iron | 67 | 91 | 1.72 out of 5 | $442 | 29,496 |
| Transmission Main | 8166 | P-5155 | CRA | Oaklawn Ave. | 12 | Cast Iron | 179 | 91 | 1.72 out of 5 | $442 | 79,000 |
| Transmission Main | 9035 | P-5050 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 297 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9036 | P-5137 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 3 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9037 | P-5137 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 14 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9389 | P-5052 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 47 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9390 | P-5052 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 4 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9391 | P-5056 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 21 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9392 | P-5052 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 35 | 17 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10121 | P-5095 | CRA | Oaklawn Ave. | 6 | Ductile Iron | 35 | 13 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11374 | P-5093 | CRA | Oaklawn Ave. | 10 | Asbestos Cement | 117 | 51 | 1.14 out of 5 | $442 | 51,697 |
| Transmission Main | 11578 | P-5050 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 15 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11579 | P-5052 | CRA | Oaklawn Ave. | 12 | Ductile Iron | 4 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5461 | P-5177 | CRA | Old Spring Rd. | 12 | Ductile Iron | 85 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5462 | P-5176 | CRA | Old Spring Rd. | 12 | Cast Iron | 49 | 91 | 1.72 out of 5 | $442 | 21,452 |
| Transmission Main | 7408 | P-5178 | CRA | Old Spring Rd. | 12 | Cast Iron | 184 | 91 | 1.72 out of 5 | $442 | 81,441 |
| Transmission Main | 7409 | P-5178 | CRA | Old Spring Rd. | 12 | Cast Iron | 30 | 91 | 1.72 out of 5 | $442 | 13,321 |
| Distribution Main | 7420 | P-5181 | CRA | Old Spring Rd. | 1.5 | Copper | 94 | UNK | 1.99 out of 5 | $442 | 41,424 |
| Distribution Main | 7421 | P-5180 | CRA | Old Spring Rd. | 1.5 | Copper | 132 | UNK | 1.99 out of 5 | $442 | 58,151 |
| Distribution Main | 7422 | P-5179 | CRA | Old Spring Rd. | 1.5 | Copper | 144 | UNK | 1.99 out of 5 | $442 | 63,632 |
| Transmission Main | 7423 | P-5046 | CRA | Old Spring Rd. | 12 | Cast Iron | 574 | 91 | 1.72 out of 5 | $442 | 253,670 |
| Transmission Main | 7425 | P-5048 | CRA | Old Spring Rd. | 12 | Cast Iron | 501 | 91 | 1.72 out of 5 | $442 | 221,447 |
| Distribution Main | 7391 | P-5010 | CRA | Olive St. | 8 | Ductile Iron | 6 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7392 | P-5150 | CRA | Olive St. | 8 | Ductile Iron | 6 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8032 | P-5150 | CRA | Olive St. | 8 | Ductile Iron | 232 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8695 | P-5010 | CRA | Olive St. | 8 | Ductile Iron | 55 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8696 | P-5010 | CRA | Olive St. | 8 | Ductile Iron | 174 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4940 | P-5067 | CRA | Ontario Ave. | 6 | Asbestos Cement | 234 | 60 | 1.85 out of 5 | $442 | 103,380 |
| Distribution Main | 7371 | P-5082 | CRA | Ontario Ave. | 6 | Asbestos Cement | 329 | 49 | 1.85 out of 5 | $442 | 145,563 |
| Distribution Main | 7397 | P-5159 | CRA | Oriole Ave. | 8 | Ductile Iron | 13 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7398 | P-5004 | CRA | Oriole Ave. | 8 | Ductile Iron | 13 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7399 | P-5004 | CRA | Oriole Ave. | 8 | Ductile Iron | 214 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7402 | P-5002 | CRA | Oriole Ave. | 8 | Ductile Iron | 236 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7403 | P-5004 | CRA | Oriole Ave. | 8 | Ductile Iron | 3 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7404 | P-5002 | CRA | Oriole Ave. | 8 | Ductile Iron | 3 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7469 | P-5001 | CRA | Oriole Ave. | 8 | Ductile Iron | 253 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8704 | P-5159 | CRA | Oriole Ave. | 6 | Ductile Iron | 3 | 15 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 490 | P-8853 | CRA | Paulette Dr. | 8 | Ductile Iron | 36 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7375 | P-5084 | CRA | Rainbow Rd. | 6 | Asbestos Cement | 193 | 49 | 1.85 out of 5 | $442 | 85,331 |
| Distribution Main | 3062 | P-7351 | CRA | Red Barn Ct. | 8 | Ductile Iron | 454 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3066 | P-7352 | CRA | Red Barn Ct. | 8 | Ductile Iron | 126 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4168 | P-5116 | CRA | Red Barn Ct. | 8 | Asbestos Cement | 170 | 42 | 1.14 out of 5 | $442 | 74,956 |
| Distribution Main | 5298 | P-5114 | CRA | Red Barn Ct. | 8 | Asbestos Cement | 309 | 42 | 1.14 out of 5 | $442 | 136,537 |
| Distribution Main | 8868 | P-5172 | CRA | Redfern Dr | 8 | Ductile Iron | 224 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10132 | | CRA | Roberts Ave | 8 | Ductile Iron | 38 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7407 | P-5016 | CRA | Searle Ave. | 8 | Ductile Iron | 34 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7416 | P-5160 | CRA | Searle Ave. | 8 | Ductile Iron | 83 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7417 | P-5160 | CRA | Searle Ave. | 8 | Ductile Iron | 193 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7467 | P-5016 | CRA | Searle Ave. | 8 | Ductile Iron | 235 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8034 | P-5151 | CRA | Searle Ave. | 8 | Ductile Iron | 266 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8691 | P-5018 | CRA | Searle Ave. | 8 | Ductile Iron | 26 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8692 | P-5018 | CRA | Searle Ave. | 8 | Ductile Iron | 285 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8693 | P-5151 | CRA | Searle Ave. | 8 | Ductile Iron | 33 | 15 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 8694 | P-5151 | CRA | Searle Ave. | 8 | Ductile Iron | 35 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11493 | P-5151 | CRA | Searle Ave. | 8 | Ductile Iron | 3 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8597 | P-5120 | CRA | Seven Mile Rd | 16 | Ductile Iron | 940 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8598 | P-5120 | CRA | Seven Mile Rd | 16 | Ductile Iron | 807 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8600 | P-5120 | CRA | Seven Mile Rd | 12 | Ductile Iron | 9 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8595 | P-5197 | CRA | Seven Mile Rd. | 16 | Ductile Iron | 372 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8596 | P-5197 | CRA | Seven Mile Rd. | 16 | Ductile Iron | 1,077 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9912 | P-5198 | CRA | Seven Mile Rd. | 16 | Ductile Iron | 9 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11901 | P-5197 | CRA | Seven Mile Rd. | 16 | Ductile Iron | 790 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8902 | P-5166 | CRA | Stoneham | 6 | Ductile Iron | 13 | 9 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8900 | P-5167 | CRA | Stoneham Ct. | 6 | Asbestos Cement | 67 | UNK | 1.56 out of 5 | $442 | 29,756 |
| Distribution Main | 8901 | P-5166 | CRA | Stoneham Ct. | 8 | Ductile Iron | 22 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8896 | P-5023 | CRA | Stoneham St | 8 | Ductile Iron | 290 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8897 | P-5023 | CRA | Stoneham St | 8 | Ductile Iron | 293 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5998 | P-5087 | CRA | Sunkist Cir. | 8 | Asbestos Cement | 124 | 47 | 1.14 out of 5 | $442 | 54,875 |
| Distribution Main | 5995 | P-5086 | CRA | Sunrise Road | 8 | Asbestos Cement | 276 | 47 | 1.14 out of 5 | $442 | 122,046 |
| Distribution Main | 5996 | P-5088 | CRA | Sunrise Road | 8 | Asbestos Cement | 335 | 47 | 1.14 out of 5 | $442 | 148,143 |
| Distribution Main | 7389 | P-5000 | CRA | Turner Ave. | 8 | Ductile Iron | 510 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7390 | P-5000 | CRA | Turner Ave. | 8 | Ductile Iron | 36 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7393 | P-5014 | CRA | Turner Ave. | 8 | Ductile Iron | 6 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7394 | P-5014 | CRA | Turner Ave. | 8 | Ductile Iron | 455 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7395 | P-5014 | CRA | Turner Ave. | 8 | Ductile Iron | 38 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7405 | P-5012 | CRA | Turner Ave. | 8 | Ductile Iron | 367 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7406 | P-5012 | CRA | Turner Ave. | 8 | Ductile Iron | 68 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7432 | P-5011 | CRA | Turner Ave. | 8 | Ductile Iron | 7 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7433 | P-5002 | CRA | Turner Ave. | 8 | Ductile Iron | 15 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8698 | P-5011 | CRA | Turner Ave. | 8 | Ductile Iron | 69 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8699 | P-5011 | CRA | Turner Ave. | 8 | Ductile Iron | 346 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11375 | P-5014 | CRA | Turner Ave. | 8 | Ductile Iron | 27 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3091 | P-5107 | CRA | Verdant Dr. | 8 | Asbestos Cement | 39 | 43 | 1.14 out of 5 | $442 | 17,108 |
| Distribution Main | 4937 | P-5108 | CRA | Verdant Dr. | 8 | Asbestos Cement | 336 | 43 | 1.14 out of 5 | $442 | 148,683 |
| Distribution Main | 4938 | P-5108 | CRA | Verdant Dr. | 8 | Asbestos Cement | 206 | 43 | 1.14 out of 5 | $442 | 91,222 |
| Distribution Main | 4950 | P-5107 | CRA | Verdant Dr. | 8 | Asbestos Cement | 202 | 43 | 1.14 out of 5 | $442 | 89,214 |
| Distribution Main | 5294 | P-5108 | CRA | Verdant Dr. | 8 | Asbestos Cement | 34 | 43 | 1.14 out of 5 | $442 | 15,055 |
| Distribution Main | 6550 | P-5108 | CRA | Verdant Dr. | 8 | Asbestos Cement | 13 | 43 | 1.14 out of 5 | $442 | 5,773 |
| Distribution Main | 7484 | P-5106 | CRA | Verdant Dr. | 8 | Asbestos Cement | 213 | 43 | 1.14 out of 5 | $442 | 94,187 |
| Distribution Main | 7485 | P-5106 | CRA | Verdant Dr. | 8 | Asbestos Cement | 148 | 43 | 1.14 out of 5 | $442 | 65,439 |
| Distribution Main | 10987 | P-5106 | CRA | Verdant Dr. | 8 | Asbestos Cement | 5 | 43 | 1.14 out of 5 | $442 | 2,241 |
| Distribution Main | 6539 | P-5069 | CRA | Versailles St. | 6 | Asbestos Cement | 522 | 50 | 1.85 out of 5 | $442 | 230,631 |
| Distribution Main | 6551 | P-5070 | CRA | Versailles St. | 6 | Asbestos Cement | 154 | 50 | 1.85 out of 5 | $442 | 68,012 |
| Distribution Main | 6552 | P-5070 | CRA | Versailles St. | 6 | Asbestos Cement | 320 | 50 | 1.85 out of 5 | $442 | 141,371 |
| Distribution Main | 7492 | P-5068 | CRA | Versailles St. | 6 | Asbestos Cement | 274 | 50 | 1.85 out of 5 | $442 | 120,903 |
| Distribution Main | 7493 | P-5071 | CRA | Versailles St. | 6 | Asbestos Cement | 22 | 50 | 1.85 out of 5 | $442 | 9,752 |
| Distribution Main | 5381 | P-5149 | CRA | Vinton Ave. | 8 | Ductile Iron | 3 | 15 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 7386 | P-5013 | CRA | Vinton Ave. | 8 | Ductile Iron | 590 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7387 | P-5013 | CRA | Vinton Ave. | 8 | Ductile Iron | 102 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7400 | P-5148 | CRA | Vinton Ave. | 8 | Ductile Iron | 352 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8003 | P-5149 | CRA | Vinton Ave. | 8 | Ductile Iron | 57 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8004 | P-5149 | CRA | Vinton Ave. | 8 | Ductile Iron | 393 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8033 | P-5148 | CRA | Vinton Ave. | 8 | Ductile Iron | 3 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8690 | P-5013 | CRA | Vinton Ave. | 8 | Ductile Iron | 8 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8697 | P-5148 | CRA | Vinton Ave. | 8 | Ductile Iron | 91 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4943 | P-5065 | CRA | Warfield Ave. | 6 | Asbestos Cement | 98 | 66 | 2 out of 5 | $442 | 43,478 |
| Distribution Main | 6553 | P-5063 | CRA | Warfield Ave. | 6 | Cast Iron | 155 | 83 | 2.43 out of 5 | $442 | 68,408 |
| Distribution Main | 6554 | P-5063 | CRA | Warfield Ave. | 6 | Cast Iron | 58 | 83 | 2.43 out of 5 | $442 | 25,683 |
| Distribution Main | 7489 | P-5064 | CRA | Warfield Ave. | 6 | Asbestos Cement | 197 | 66 | 2 out of 5 | $442 | 87,191 |
| Distribution Main | 8883 | P-5035 | CRA | Warren Ave | 8 | Ductile Iron | 226 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8890 | P-5028 | CRA | Warren Ave | 8 | Ductile Iron | 89 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8895 | P-5025 | CRA | Warren Ave | 8 | Ductile Iron | 337 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9386 | P-5037 | CRA | Warren Ave | 8 | Ductile Iron | 215 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9387 | P-5037 | CRA | Warren Ave | 8 | Ductile Iron | 557 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9388 | P-5170 | CRA | Warren Ave | 8 | Ductile Iron | 61 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10821 | P-5164 | CRA | Warren Ave | 8 | Ductile Iron | 247 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10822 | P-5028 | CRA | Warren Ave | 8 | Ductile Iron | 178 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10823 | P-5141 | CRA | Warren Ave | 8 | Ductile Iron | 78 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10824 | P-5170 | CRA | Warren Ave | 8 | Ductile Iron | 154 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10825 | P-5037 | CRA | Warren Ave | 8 | Ductile Iron | 50 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11523 | P-5165 | CRA | Warren Ave | 8 | Ductile Iron | 16 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8894 | P-5024 | CRA | Warren Ave. | 8 | Ductile Iron | 41 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5634 | P-5171 | CRA | Warren Ct. | 6 | Unknown | 136 | UNK | 0.71 out of 5 | $442 | 59,931 |
| Distribution Main | 8888 | P-5171 | CRA | Warren Ct. | 6 | Ductile Iron | 15 | 9 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8889 | P-5171 | CRA | Warren Ct. | 8 | Ductile Iron | 12 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5363 | P-5053 | CRA | Westbrook Rd. | 8 | Ductile Iron | 35 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5364 | P-5053 | CRA | Westbrook Rd. | 8 | Ductile Iron | 293 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9038 | P-5053 | CRA | Westbrook Rd. | 8 | Ductile Iron | 33 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2221 | P-5152 | CRA | Wheelock Ave. | 8 | Ductile Iron | 486 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8677 | P-5161 | CRA | Wilbur Ave. | 12 | Ductile Iron | 237 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8678 | P-5161 | CRA | Wilbur Ave. | 12 | Ductile Iron | 12 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8679 | P-5152 | CRA | Wilbur Ave. | 8 | Ductile Iron | 31 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8680 | P-5021 | CRA | Wilbur Ave. | 12 | Ductile Iron | 8 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8681 | P-5021 | CRA | Wilbur Ave. | 12 | Ductile Iron | 220 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8683 | P-5020 | CRA | Wilbur Ave. | 12 | Ductile Iron | 491 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8684 | P-5043 | CRA | Wilbur Ave. | 12 | Ductile Iron | 112 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8685 | P-5043 | CRA | Wilbur Ave. | 12 | Ductile Iron | 6 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8686 | P-5043 | CRA | Wilbur Ave. | 12 | Ductile Iron | 92 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8687 | P-5043 | CRA | Wilbur Ave. | 12 | Ductile Iron | 111 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11492 | P-5043 | CRA | Wilbur Ave. | 12 | Ductile Iron | 43 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5361 | P-5051 | CRA | Willow Rd. | 8 | Ductile Iron | 235 | 15 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9039 | P-5051 | CRA | Willow Rd. | 8 | Ductile Iron | 9 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4941 | P-5066 | CRA | Woodlawn Dr. | 6 | Asbestos Cement | 381 | 65 | 2 out of 5 | $442 | 168,490 |
| Distribution Main | 4942 | P-5066 | CRA | Woodlawn Dr. | 6 | Asbestos Cement | 433 | 65 | 2 out of 5 | $442 | 191,485 |
| Distribution Main | 7490 | P-5073 | CRA | Woodlawn Dr. | 6 | Asbestos Cement | 274 | 65 | 2 out of 5 | $442 | 121,100 |
| Distribution Main | 7491 | P-5073 | CRA | Woodlawn Dr. | 6 | Asbestos Cement | 233 | 65 | 2 out of 5 | $442 | 102,788 |
| Distribution Main | 5504 | P-4103 | EG | Adirondack Dr | 8 | Asbestos Cement | 50 | 43 | 1.14 out of 5 | $442 | 22,049 |
| Distribution Main | 5505 | P-4103 | EG | Adirondack Dr | 8 | Asbestos Cement | 488 | 43 | 1.14 out of 5 | $442 | 215,805 |
| Distribution Main | 5519 | P-4090 | EG | Adirondack Dr | 8 | Ductile Iron | 55 | 38 | 0.14 out of 5 | $442 | 24,377 |
| Distribution Main | 5520 | P-4090 | EG | Adirondack Dr | 8 | Ductile Iron | 227 | 38 | 0.14 out of 5 | $442 | 100,419 |
| Distribution Main | 5522 | P-4095 | EG | Adirondack Dr | 8 | Ductile Iron | 521 | 38 | 0.14 out of 5 | $442 | 230,151 |
| Distribution Main | 5523 | P-4095 | EG | Adirondack Dr | 8 | Ductile Iron | 45 | 38 | 0.14 out of 5 | $442 | 19,864 |
| Distribution Main | 5526 | P-4094 | EG | Adirondack Dr | 8 | Ductile Iron | 436 | 38 | 0.14 out of 5 | $442 | 192,496 |
| Distribution Main | 5533 | P-4101 | EG | Adirondack Dr | 8 | Asbestos Cement | 118 | 43 | 1.14 out of 5 | $442 | 51,997 |
| Distribution Main | 5534 | P-4101 | EG | Adirondack Dr | 8 | Asbestos Cement | 304 | 43 | 1.14 out of 5 | $442 | 134,360 |
| Distribution Main | 5654 | P-4097 | EG | Adirondack Dr | 8 | Ductile Iron | 691 | 38 | 0.14 out of 5 | $442 | 305,590 |
| Distribution Main | 5659 | P-4094 | EG | Adirondack Dr | 8 | Ductile Iron | 15 | 38 | 0.14 out of 5 | $442 | 6,412 |
| Distribution Main | 5876 | P-4102 | EG | Adirondack Dr | 8 | Asbestos Cement | 11 | 43 | 1.14 out of 5 | $442 | 4,855 |
| Distribution Main | 5877 | P-4102 | EG | Adirondack Dr | 8 | Asbestos Cement | 696 | 43 | 1.14 out of 5 | $442 | 307,582 |
| Distribution Main | 5878 | P-4101 | EG | Adirondack Dr | 8 | Asbestos Cement | 14 | 43 | 1.14 out of 5 | $442 | 6,223 |
| Distribution Main | 6696 | P-4103 | EG | Adirondack Dr | 8 | Asbestos Cement | 4 | 43 | 1.14 out of 5 | $442 | 1,588 |
| Distribution Main | 9320 | P-4102 | EG | Adirondack Dr | 8 | Asbestos Cement | 13 | 43 | 1.14 out of 5 | $442 | 5,892 |
| Distribution Main | 9321 | P-4101 | EG | Adirondack Dr | 8 | Asbestos Cement | 13 | 43 | 1.14 out of 5 | $442 | 5,619 |
| Distribution Main | 9322 | P-4097 | EG | Adirondack Dr | 8 | Ductile Iron | 6 | 38 | 0.14 out of 5 | $442 | 2,561 |
| Distribution Main | 9323 | P-4097 | EG | Adirondack Dr | 8 | Ductile Iron | 4 | 38 | 0.14 out of 5 | $442 | 1,574 |
| Distribution Main | 11309 | P-4094 | EG | Adirondack Dr | 8 | Ductile Iron | 4 | 38 | 0.14 out of 5 | $442 | 1,631 |
| Distribution Main | 11833 | P-4095 | EG | Adirondack Dr | 8 | Ductile Iron | 447 | 38 | 0.14 out of 5 | $442 | 197,355 |
| Distribution Main | 11839 | P-4095 | EG | Adirondack Dr | 8 | Ductile Iron | 447 | 38 | 0.14 out of 5 | $442 | 197,656 |
| Distribution Main | 5624 | P-4448 | EG | Alder Ct | 6 | Asbestos Cement | 215 | 48 | 1.85 out of 5 | $442 | 95,143 |
| Distribution Main | 4034 | P-4358 | EG | Allen Dr | 6 | Asbestos Cement | 409 | 51 | 1.85 out of 5 | $442 | 180,895 |
| Distribution Main | 4990 | P-4358 | EG | Allen Dr | 6 | Asbestos Cement | 28 | 51 | 1.85 out of 5 | $442 | 12,515 |
| Distribution Main | 5589 | P-4380 | EG | Allen Dr | 8 | Asbestos Cement | 392 | 51 | 1.14 out of 5 | $442 | 173,147 |
| Distribution Main | 6395 | P-4379 | EG | Allen Dr | 6 | Asbestos Cement | 465 | 51 | 1.85 out of 5 | $442 | 205,342 |
| Distribution Main | 6404 | P-4374 | EG | Allen Dr | 6 | Asbestos Cement | 198 | 51 | 1.85 out of 5 | $442 | 87,561 |
| Distribution Main | 6405 | P-4374 | EG | Allen Dr | 6 | Asbestos Cement | 33 | 51 | 1.85 out of 5 | $442 | 14,515 |
| Distribution Main | 10373 | P-4380 | EG | Allen Dr | 8 | Ductile Iron | 19 | 51 | 0.29 out of 5 | $442 | 8,608 |
| Distribution Main | 6056 | P-4480 | EG | Apple Tree Ct. | 6 | Asbestos Cement | 341 | 48 | 2.57 out of 5 | $442 | 150,794 |
| Distribution Main | 5392 | P-4051 | EG | Arbor Way | 8 | Asbestos Cement | 596 | 49 | 1.14 out of 5 | $442 | 263,583 |
| Distribution Main | 4373 | P-4715 | EG | Arrowhead Trail | 8 | Asbestos Cement | 69 | 46 | 1.14 out of 5 | $442 | 30,499 |
| Distribution Main | 4374 | | EG | Arrowhead Trail | 8 | Ductile Iron | 68 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4375 | P-4714 | EG | Arrowhead Trail | 8 | Asbestos Cement | 1,000 | 46 | 1.14 out of 5 | $442 | 441,968 |
| Distribution Main | 4376 | P-4714 | EG | Arrowhead Trail | 8 | Asbestos Cement | 78 | 46 | 1.14 out of 5 | $442 | 34,338 |
| Distribution Main | 11253 | P-4714 | EG | Arrowhead Trail | 8 | Asbestos Cement | 11 | 46 | 1.14 out of 5 | $442 | 4,694 |
| Distribution Main | 3662 | P-4704 | EG | Ashbrook Run | 8 | Ductile Iron | 434 | 30 | 0.14 out of 5 | $442 | 191,823 |
| Distribution Main | 3663 | P-4704 | EG | Ashbrook Run | 8 | Ductile Iron | 94 | 30 | 0.14 out of 5 | $442 | 41,337 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 5594 | P-4369 | EG | Atherton Rd. | 8 | Ductile Iron | 19 | 62 | 0.43 out of 5 | $442 | 8,478 |
| Distribution Main | 6391 | P-4369 | EG | Atherton Rd. | 6 | Asbestos Cement | 9 | 62 | 2 out of 5 | $442 | 3,773 |
| Distribution Main | 6392 | P-4369 | EG | Atherton Rd. | 6 | Asbestos Cement | 824 | 62 | 2 out of 5 | $442 | 364,322 |
| Distribution Main | 11814 | P-4369 | EG | Atherton Rd. | 6 | Asbestos Cement | 115 | 62 | 2.71 out of 5 | $442 | 50,944 |
| Distribution Main | 9229 | P-4196 | EG | Ayrault Rd | 8 | Ductile Iron | 364 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10966 | P-4193 | EG | Ayrault Rd | 8 | Ductile Iron | 317 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6197 | P-4445 | EG | Balsam Dr. | 6 | Asbestos Cement | 571 | 50 | 1.85 out of 5 | $442 | 252,586 |
| Distribution Main | 6198 | P-4445 | EG | Balsam Dr. | 6 | Asbestos Cement | 598 | 50 | 1.85 out of 5 | $442 | 264,249 |
| Distribution Main | 6570 | P-4446 | EG | Balsam Dr. | 6 | Asbestos Cement | 224 | 50 | 1.85 out of 5 | $442 | 98,988 |
| Distribution Main | 5622 | P-4979 | EG | Barrows Dr. | 6 | Unknown | 75 | 58 | 1 out of 5 | $442 | 33,256 |
| Distribution Main | 6193 | P-4451 | EG | Barrows Dr. | 6 | Asbestos Cement | 61 | 58 | 1.85 out of 5 | $442 | 26,932 |
| Distribution Main | 6194 | P-4451 | EG | Barrows Dr. | 6 | Asbestos Cement | 616 | 58 | 1.85 out of 5 | $442 | 272,287 |
| Distribution Main | 6195 | P-4979 | EG | Barrows Dr. | 6 | Unknown | 4 | 58 | 1 out of 5 | $442 | 1,771 |
| Transmission Main | 5782 | P-4132 | EG | Bassett Circle | 20 | Ductile Iron | 299 | 36 | 0.14 out of 5 | $442 | 132,138 |
| Transmission Main | 6004 | P-4132 | EG | Bassett Circle | 20 | Ductile Iron | 22 | 36 | 0.14 out of 5 | $442 | 9,539 |
| Transmission Main | 6005 | P-4132 | EG | Bassett Circle | 20 | Ductile Iron | 470 | 36 | 0.14 out of 5 | $442 | 207,554 |
| Transmission Main | 10440 | P-4132 | EG | Bassett Circle | 20 | Ductile Iron | 259 | 36 | 0.14 out of 5 | $442 | 114,299 |
| Transmission Main | 10441 | P-4132 | EG | Bassett Circle | 20 | Ductile Iron | 182 | 36 | 0.14 out of 5 | $442 | 80,303 |
| Distribution Main | 2476 | P-4427 | EG | Bayberry Lane | 6 | Asbestos Cement | 1,159 | 50 | 1.85 out of 5 | $442 | 512,494 |
| Distribution Main | 5279 | P-4004 | EG | Bear Swamp Rd. | 8 | Asbestos Cement | 478 | 41 | 1.14 out of 5 | $442 | 211,057 |
| Distribution Main | 5280 | P-4004 | EG | Bear Swamp Rd. | 8 | Asbestos Cement | 216 | 41 | 1.14 out of 5 | $442 | 95,606 |
| Distribution Main | 6367 | P-4004 | EG | Bear Swamp Rd. | 8 | Asbestos Cement | 6 | 41 | 1.14 out of 5 | $442 | 2,845 |
| Distribution Main | 8312 | P-4815 | EG | Beechcrest Rd | 8 | Ductile Iron | 51 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8313 | P-4815 | EG | Beechcrest Rd | 8 | Ductile Iron | 747 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11459 | P-4815 | EG | Beechcrest Rd | 8 | Ductile Iron | 116 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9165 | P-4621 | EG | Bicknell Ave | 12 | Ductile Iron | 190 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9166 | P-4621 | EG | Bicknell Ave | 12 | Ductile Iron | 128 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9167 | P-4621 | EG | Bicknell Ave | 12 | Ductile Iron | 24 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6064 | P-4418 | EG | Birchwood Way | 6 | Asbestos Cement | 350 | 50 | 1.85 out of 5 | $442 | 154,541 |
| Distribution Main | 6065 | P-4418 | EG | Birchwood Way | 6 | Asbestos Cement | 18 | 50 | 1.85 out of 5 | $442 | 7,982 |
| Distribution Main | 6487 | P-4423 | EG | Birchwood Way | 6 | Asbestos Cement | 289 | 50 | 1.85 out of 5 | $442 | 127,946 |
| Distribution Main | 6500 | P-4424 | EG | Birchwood Way | 6 | Asbestos Cement | 43 | 50 | 1.85 out of 5 | $442 | 19,119 |
| Distribution Main | 6501 | P-4424 | EG | Birchwood Way | 6 | Asbestos Cement | 211 | 50 | 1.85 out of 5 | $442 | 93,316 |
| Distribution Main | 4026 | P-4450 | EG | Blueberry Dr | 6 | Asbestos Cement | 1,056 | 58 | 1.85 out of 5 | $442 | 466,745 |
| Distribution Main | 5959 | P-4452 | EG | Blueberry Dr | 6 | Asbestos Cement | 545 | 58 | 1.85 out of 5 | $442 | 240,761 |
| Distribution Main | 9474 | P-40035 | EG | Bond St | 0.75 | Copper | 312 | UNK | 1.99 out of 5 | $442 | 137,749 |
| Transmission Main | 967 | P-4992 | EG | Boulder Way | 20 | Ductile Iron | 13 | 36 | 0.14 out of 5 | $442 | 5,553 |
| Transmission Main | 2025 | P-4879 | EG | Boulder Way | 20 | Ductile Iron | 728 | 36 | 0.14 out of 5 | $442 | 321,933 |
| Transmission Main | 2026 | P-4879 | EG | Boulder Way | 20 | Ductile Iron | 15 | 36 | 0.14 out of 5 | $442 | 6,731 |
| Transmission Main | 2028 | P-4992 | EG | Boulder Way | 20 | Ductile Iron | 904 | 36 | 0.14 out of 5 | $442 | 399,379 |
| Transmission Main | 2029 | P-4992 | EG | Boulder Way | 20 | Ductile Iron | 519 | 36 | 0.14 out of 5 | $442 | 229,445 |
| Distribution Main | 6793 | P-4330 | EG | Bow St. | 8 | Asbestos Cement | 346 | 50 | 1.14 out of 5 | $442 | 152,757 |
| Distribution Main | 6794 | P-4330 | EG | Bow St. | 8 | Asbestos Cement | 64 | 50 | 1.14 out of 5 | $442 | 28,478 |
| Distribution Main | 6809 | P-4329 | EG | Bow St. | 8 | Asbestos Cement | 1,060 | 50 | 1.14 out of 5 | $442 | 468,443 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 12186 | | EG | Bow St. | 8 | Asbestos Cement | 741 | 50 | 1.14 out of 5 | $442 | 327,477 |
| Distribution Main | 12187 | | EG | Bow St. | 8 | Asbestos Cement | 190 | 50 | 1.14 out of 5 | $442 | 83,902 |
| Distribution Main | 6800 | P-4301 | EG | Boxwood Dr. | 6 | Asbestos Cement | 471 | 51 | 1.85 out of 5 | $442 | 208,268 |
| Distribution Main | 6801 | P-4301 | EG | Boxwood Dr. | 6 | Asbestos Cement | 516 | 51 | 1.85 out of 5 | $442 | 227,908 |
| Distribution Main | 4511 | P-4568 | EG | Brayton St. | 8 | Ductile Iron | 333 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4512 | P-4568 | EG | Brayton St. | 8 | Ductile Iron | 391 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6271 | P-4568 | EG | Brayton St. | 8 | Ductile Iron | 145 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3321 | P-4597 | EG | Bridge St. | 8 | Ductile Iron | 12 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3322 | P-4597 | EG | Bridge St. | 8 | Ductile Iron | 187 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4259 | P-4693 | EG | Bridge St. | 8 | Ductile Iron | 237 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 361 | P-4519 | EG | Brisas Cir. | 8 | Asbestos Cement | 190 | 52 | 1.14 out of 5 | $442 | 83,793 |
| Distribution Main | 362 | P-4520 | EG | Brisas Cir. | 8 | Asbestos Cement | 717 | 52 | 1.14 out of 5 | $442 | 316,880 |
| Distribution Main | 363 | P-4520 | EG | Brisas Cir. | 8 | Asbestos Cement | 69 | 52 | 1.14 out of 5 | $442 | 30,498 |
| Distribution Main | 3218 | P-4517 | EG | Brisas Cir. | 8 | Asbestos Cement | 18 | 52 | 1.14 out of 5 | $442 | 7,789 |
| Distribution Main | 4176 | P-4518 | EG | Brisas Cir. | 8 | Asbestos Cement | 270 | 52 | 1.14 out of 5 | $442 | 119,432 |
| Distribution Main | 4177 | P-4518 | EG | Brisas Cir. | 8 | Asbestos Cement | 443 | 52 | 1.14 out of 5 | $442 | 195,827 |
| Distribution Main | 6346 | P-4517 | EG | Brisas Cir. | 8 | Asbestos Cement | 334 | 52 | 1.14 out of 5 | $442 | 147,537 |
| Distribution Main | 5895 | P-4151 | EG | Brookfield Dr. | 8 | Ductile Iron | 57 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5896 | P-4151 | EG | Brookfield Dr. | 8 | Ductile Iron | 616 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 189 | P-4508 | EG | Brookside Dr. | 6 | Asbestos Cement | 720 | 69 | 2 out of 5 | $442 | 318,439 |
| Distribution Main | 375 | P-4509 | EG | Brookside Dr. | 6 | Asbestos Cement | 243 | 69 | 2 out of 5 | $442 | 107,420 |
| Distribution Main | 6149 | P-4349 | EG | Bunker Hill Ln. | 8 | Asbestos Cement | 588 | 55 | 1.14 out of 5 | $442 | 259,948 |
| Distribution Main | 9240 | P-4203 | EG | Canonchet Tr | 8 | Ductile Iron | 316 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9237 | P-4201 | EG | Canonicus Tr | 8 | Ductile Iron | 3 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9239 | P-4201 | EG | Canonicus Tr | 8 | Ductile Iron | 13 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9243 | P-4205 | EG | Canonicus Tr | 8 | Ductile Iron | 413 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9247 | P-4205 | EG | Canonicus Tr | 8 | Ductile Iron | 53 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6386 | P-4201 | EG | Canonicus Tr. | 8 | Ductile Iron | 491 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6591 | P-4059 | EG | Cardinal Lane Easement | 8 | Asbestos Cement | 20 | 42 | 1.14 out of 5 | $442 | 8,711 |
| Distribution Main | 10346 | P-4059 | EG | Cardinal Lane Easement | 8 | Asbestos Cement | 11 | 42 | 1.14 out of 5 | $442 | 4,937 |
| Distribution Main | 11653 | P-4068 | EG | Cardinal Lane Easement | 8 | Asbestos Cement | 6 | 42 | 1.14 out of 5 | $442 | 2,798 |
| Distribution Main | 4360 | P-4068 | EG | Cardinal Ln. | 8 | Asbestos Cement | 31 | 47 | 1.14 out of 5 | $442 | 13,487 |
| Distribution Main | 5796 | P-4049 | EG | Cardinal Ln. | 8 | Asbestos Cement | 742 | 47 | 1.14 out of 5 | $442 | 327,758 |
| Distribution Main | 6778 | P-4047 | EG | Cardinal Ln. | 8 | Asbestos Cement | 30 | 47 | 1.14 out of 5 | $442 | 13,427 |
| Distribution Main | 6779 | P-4047 | EG | Cardinal Ln. | 8 | Asbestos Cement | 357 | 47 | 1.14 out of 5 | $442 | 157,857 |
| Distribution Main | 9439 | P-4068 | EG | Cardinal Ln. | 8 | Asbestos Cement | 73 | 47 | 1.14 out of 5 | $442 | 32,487 |
| Distribution Main | 5655 | P-4096 | EG | Cartier Ct. | 6 | Ductile Iron | 366 | 33 | 0.85 out of 5 | $442 | 161,907 |
| Distribution Main | 5656 | P-4096 | EG | Cartier Ct. | 6 | Ductile Iron | 94 | 33 | 0.85 out of 5 | $442 | 41,396 |
| Distribution Main | 5406 | P-4654 | EG | Castle St. | 8 | Ductile Iron | 3 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5407 | P-4650 | EG | Castle St. | 8 | Ductile Iron | 138 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5408 | P-4650 | EG | Castle St. | 8 | Ductile Iron | 106 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5419 | P-4654 | EG | Castle St. | 8 | Ductile Iron | 326 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6233 | P-4649 | EG | Castle St. | 8 | Ductile Iron | 11 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6649 | P-4650 | EG | Castle St. | 8 | Ductile Iron | 3 | 19 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10361 | P-4649 | EG | Castle St. | 8 | Ductile Iron | 160 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10522 | P-4649 | EG | Castle St. | 8 | Ductile Iron | 71 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5524 | P-4091 | EG | Cavalier Dr. | 8 | Ductile Iron | 350 | 38 | 0.14 out of 5 | $442 | 154,695 |
| Distribution Main | 5525 | P-4091 | EG | Cavalier Dr. | 8 | Ductile Iron | 508 | 38 | 0.14 out of 5 | $442 | 224,688 |
| Distribution Main | 5527 | P-4093 | EG | Cavalier Dr. | 8 | Ductile Iron | 405 | 38 | 0.14 out of 5 | $442 | 179,142 |
| Distribution Main | 5528 | P-4093 | EG | Cavalier Dr. | 8 | Ductile Iron | 128 | 38 | 0.14 out of 5 | $442 | 56,574 |
| Distribution Main | 5529 | P-4093 | EG | Cavalier Dr. | 8 | Ductile Iron | 508 | 38 | 0.14 out of 5 | $442 | 224,315 |
| Distribution Main | 5530 | P-4093 | EG | Cavalier Dr. | 8 | Ductile Iron | 46 | 38 | 0.14 out of 5 | $442 | 20,508 |
| Distribution Main | 5532 | P-4093 | EG | Cavalier Dr. | 8 | Ductile Iron | 14 | 38 | 0.14 out of 5 | $442 | 6,192 |
| Distribution Main | 5657 | P-4091 | EG | Cavalier Dr. | 8 | Ductile Iron | 14 | 38 | 0.14 out of 5 | $442 | 6,089 |
| Distribution Main | 5658 | P-4093 | EG | Cavalier Dr. | 8 | Ductile Iron | 14 | 38 | 0.14 out of 5 | $442 | 6,272 |
| Distribution Main | 116 | | EG | Cedar Ave | | Unknown | 70 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 9378 | P-40031 | EG | Cedar Ave | 8 | Ductile Iron | 13 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9379 | P-40031 | EG | Cedar Ave | 8 | Ductile Iron | 18 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 117 | P-4527 | EG | Cedar Ave. | 8 | Asbestos Cement | 79 | 53 | 1.14 out of 5 | $442 | 34,718 |
| Distribution Main | 357 | P-4696 | EG | Cedar Ave. | 8 | Ductile Iron | 260 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 358 | P-4437 | EG | Cedar Ave. | 8 | Asbestos Cement | 482 | 53 | 1.14 out of 5 | $442 | 213,075 |
| Distribution Main | 359 | P-40030 | EG | Cedar Ave. | 8 | Asbestos Cement | 20 | 53 | 1.14 out of 5 | $442 | 8,800 |
| Distribution Main | 373 | P-4499 | EG | Cedar Ave. | 8 | Asbestos Cement | 37 | 53 | 1.14 out of 5 | $442 | 16,303 |
| Distribution Main | 661 | P-4524 | EG | Cedar Ave. | 8 | Asbestos Cement | 169 | 53 | 1.14 out of 5 | $442 | 74,744 |
| Distribution Main | 4023 | P-4503 | EG | Cedar Ave. | 8 | Ductile Iron | 448 | 40 | 0.14 out of 5 | $442 | 197,923 |
| Distribution Main | 4156 | P-4499 | EG | Cedar Ave. | 8 | Asbestos Cement | 602 | 53 | 1.14 out of 5 | $442 | 266,248 |
| Distribution Main | 4157 | P-4499 | EG | Cedar Ave. | 8 | Asbestos Cement | 5 | 53 | 1.14 out of 5 | $442 | 2,261 |
| Distribution Main | 4181 | P-4523 | EG | Cedar Ave. | 8 | Ductile Iron | 749 | 40 | 0.14 out of 5 | $442 | 331,076 |
| Distribution Main | 4186 | P-40030 | EG | Cedar Ave. | 8 | Asbestos Cement | 1,085 | 53 | 1.14 out of 5 | $442 | 479,533 |
| Distribution Main | 5615 | P-4503 | EG | Cedar Ave. | 8 | Ductile Iron | 22 | 40 | 0.14 out of 5 | $442 | 9,939 |
| Distribution Main | 5616 | P-4503 | EG | Cedar Ave. | 8 | Ductile Iron | 325 | 40 | 0.14 out of 5 | $442 | 143,511 |
| Distribution Main | 5617 | P-4503 | EG | Cedar Ave. | 8 | Ductile Iron | 10 | 40 | 0.14 out of 5 | $442 | 4,305 |
| Distribution Main | 6196 | P-4523 | EG | Cedar Ave. | 8 | Ductile Iron | 811 | 40 | 0.14 out of 5 | $442 | 358,620 |
| Distribution Main | 6206 | P-4524 | EG | Cedar Ave. | 8 | Asbestos Cement | 12 | 53 | 1.14 out of 5 | $442 | 5,493 |
| Distribution Main | 6207 | P-4524 | EG | Cedar Ave. | 8 | Asbestos Cement | 135 | 53 | 1.14 out of 5 | $442 | 59,531 |
| Distribution Main | 6564 | P-4501 | EG | Cedar Ave. | 8 | Asbestos Cement | 237 | 53 | 1.14 out of 5 | $442 | 104,584 |
| Distribution Main | 6565 | P-4501 | EG | Cedar Ave. | 8 | Asbestos Cement | 869 | 53 | 1.14 out of 5 | $442 | 384,212 |
| Distribution Main | 6720 | P-4523 | EG | Cedar Ave. | 8 | Ductile Iron | 27 | 40 | 0.14 out of 5 | $442 | 11,834 |
| Distribution Main | 11247 | P-40030 | EG | Cedar Ave. | 8 | Asbestos Cement | 371 | 53 | 1.14 out of 5 | $442 | 164,183 |
| Distribution Main | 3845 | P-4270 | EG | Chestnut Dr. | 8 | Asbestos Cement | 549 | 51 | 1.14 out of 5 | $442 | 242,844 |
| Distribution Main | 4893 | P-4271 | EG | Chestnut Dr. | 8 | Asbestos Cement | 379 | 51 | 1.14 out of 5 | $442 | 167,510 |
| Distribution Main | 4894 | P-4258 | EG | Chestnut Dr. | 8 | Asbestos Cement | 418 | 51 | 1.14 out of 5 | $442 | 184,854 |
| Distribution Main | 4897 | P-4261 | EG | Chestnut Dr. | 8 | Asbestos Cement | 97 | 51 | 1.14 out of 5 | $442 | 42,889 |
| Distribution Main | 4898 | P-4261 | EG | Chestnut Dr. | 8 | Asbestos Cement | 818 | 51 | 1.14 out of 5 | $442 | 361,384 |
| Distribution Main | 5585 | P-4261 | EG | Chestnut Dr. | 8 | Asbestos Cement | 166 | 51 | 1.14 out of 5 | $442 | 73,390 |
| Distribution Main | 5662 | P-4041 | EG | Chestnut Dr. | 8 | Asbestos Cement | 361 | 51 | 1.14 out of 5 | $442 | 159,459 |
| Distribution Main | 5665 | P-4055 | EG | Chestnut Dr. | 8 | Asbestos Cement | 165 | 51 | 1.14 out of 5 | $442 | 72,866 |
| Distribution Main | 6781 | | EG | Chestnut Dr. | 6 | Asbestos Cement | 473 | 51 | 1.85 out of 5 | $442 | 209,129 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6782 | | EG | Chestnut Dr. | 6 | Asbestos Cement | 575 | 51 | 1.85 out of 5 | $442 | 254,043 |
| Distribution Main | 6788 | P-4257 | EG | Chestnut Dr. | 8 | Asbestos Cement | 21 | 51 | 1.14 out of 5 | $442 | 9,376 |
| Distribution Main | 6789 | P-4257 | EG | Chestnut Dr. | 8 | Asbestos Cement | 466 | 51 | 1.14 out of 5 | $442 | 205,843 |
| Distribution Main | 11273 | P-4258 | EG | Chestnut Dr. | 8 | Asbestos Cement | 13 | 51 | 1.14 out of 5 | $442 | 5,541 |
| Distribution Main | 11825 | P-4261 | EG | Chestnut Dr. | 8 | Asbestos Cement | 13 | 51 | 1.14 out of 5 | $442 | 5,951 |
| Distribution Main | 3830 | P-4161 | EG | Chief Botelho Dr. | 8 | Ductile Iron | 65 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3831 | P-4161 | EG | Chief Botelho Dr. | 8 | Ductile Iron | 313 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3832 | P-4161 | EG | Chief Botelho Dr. | 8 | Ductile Iron | 80 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 904 | P-4686 | EG | Church St. | 8 | Ductile Iron | 23 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3856 | P-4570 | EG | Church St. | 8 | Ductile Iron | 98 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3858 | P-4965 | EG | Church St. | 8 | Ductile Iron | 29 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4502 | P-4688 | EG | Church St. | 8 | Ductile Iron | 304 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4503 | P-4686 | EG | Church St. | 8 | Ductile Iron | 115 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4504 | P-4686 | EG | Church St. | 8 | Ductile Iron | 216 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4505 | P-4686 | EG | Church St. | 8 | Ductile Iron | 415 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4513 | P-4684 | EG | Church St. | 8 | Ductile Iron | 301 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6272 | P-4969 | EG | Church St. | 8 | Ductile Iron | 204 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6758 | P-4570 | EG | Church St. | 8 | Ductile Iron | 23 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9014 | P-4569 | EG | Church St. | 8 | Ductile Iron | 65 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9015 | P-4570 | EG | Church St. | 8 | Ductile Iron | 123 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9023 | P-4686 | EG | Church St. | 12 | Ductile Iron | 3 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9024 | P-4570 | EG | Church St. | 12 | Ductile Iron | 4 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 455 | P-4387 | EG | Cindyann Dr. | 8 | Asbestos Cement | 948 | 56 | 1.14 out of 5 | $442 | 418,876 |
| Distribution Main | 456 | P-4387 | EG | Cindyann Dr. | 8 | Asbestos Cement | 50 | 56 | 1.14 out of 5 | $442 | 21,931 |
| Distribution Main | 5247 | P-4479 | EG | Cindyann Dr. | 8 | Asbestos Cement | 155 | 56 | 1.14 out of 5 | $442 | 68,631 |
| Distribution Main | 5248 | P-4982 | EG | Cindyann Dr. | 8 | Asbestos Cement | 47 | 56 | 1.14 out of 5 | $442 | 20,777 |
| Distribution Main | 5249 | P-4982 | EG | Cindyann Dr. | 8 | Asbestos Cement | 636 | 56 | 1.14 out of 5 | $442 | 281,009 |
| Distribution Main | 5413 | P-4477 | EG | Cindyann Dr. | 8 | Asbestos Cement | 322 | 56 | 1.14 out of 5 | $442 | 142,315 |
| Distribution Main | 5414 | P-4477 | EG | Cindyann Dr. | 8 | Asbestos Cement | 524 | 56 | 1.14 out of 5 | $442 | 231,792 |
| Distribution Main | 5949 | P-4345 | EG | Cindyann Dr. | 8 | Asbestos Cement | 44 | 56 | 1.14 out of 5 | $442 | 19,660 |
| Distribution Main | 5950 | P-4345 | EG | Cindyann Dr. | 8 | Asbestos Cement | 469 | 56 | 1.14 out of 5 | $442 | 207,514 |
| Distribution Main | 6332 | P-4481 | EG | Cindyann Dr. | 8 | Asbestos Cement | 257 | 56 | 1.14 out of 5 | $442 | 113,608 |
| Distribution Main | 6333 | P-4482 | EG | Cindyann Dr. | 8 | Asbestos Cement | 394 | 56 | 1.14 out of 5 | $442 | 174,158 |
| Distribution Main | 6376 | P-4980 | EG | Cindyann Dr. | 8 | Asbestos Cement | 202 | 56 | 1.14 out of 5 | $442 | 89,276 |
| Distribution Main | 6380 | P-4388 | EG | Cindyann Dr. | 8 | Asbestos Cement | 830 | 56 | 1.14 out of 5 | $442 | 366,704 |
| Distribution Main | 6381 | P-4388 | EG | Cindyann Dr. | 8 | Asbestos Cement | 961 | 56 | 1.14 out of 5 | $442 | 424,705 |
| Distribution Main | 11829 | P-4982 | EG | Cindyann Dr. | 8 | Asbestos Cement | 31 | 56 | 1.14 out of 5 | $442 | 13,655 |
| Transmission Main | 4494 | P-4149 | EG | Clauson Court | 16 | Ductile Iron | 359 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5894 | P-4149 | EG | Clauson Court | 16 | Ductile Iron | 136 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4200 | P-4117 | EG | Clemente Dr. | 6 | Asbestos Cement | 10 | 56 | 1.85 out of 5 | $442 | 4,312 |
| Distribution Main | 4203 | P-4142 | EG | Clemente Dr. | 6 | Asbestos Cement | 58 | 56 | 1.85 out of 5 | $442 | 25,696 |
| Distribution Main | 4204 | P-4142 | EG | Clemente Dr. | 6 | Asbestos Cement | 157 | 56 | 1.85 out of 5 | $442 | 69,251 |
| Distribution Main | 6136 | P-4117 | EG | Clemente Dr. | 6 | Asbestos Cement | 482 | 56 | 1.85 out of 5 | $442 | 212,949 |
| Transmission Main | 4260 | P-4591 | EG | Cliff St. | 12 | Ductile Iron | 73 | 23 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 5401 | P-4591 | EG | Cliff St. | 12 | Ductile Iron | 382 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6719 | P-4947 | EG | Cliff St. | 12 | Ductile Iron | 116 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 10905 | P-4947 | EG | Cliff St. | 12 | Ductile Iron | 148 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 118 | P-4485 | EG | Clover Hill Ct. | 6 | Asbestos Cement | 163 | 43 | 1.85 out of 5 | $442 | 72,227 |
| Distribution Main | 6495 | P-4430 | EG | Coddington Ct. | 6 | Asbestos Cement | 173 | 49 | 1.85 out of 5 | $442 | 76,457 |
| Distribution Main | 2510 | P-4988 | EG | Cole Circle | 8 | Ductile Iron | 309 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4051 | P-4405 | EG | Cora St. | 8 | Ductile Iron | 351 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4052 | P-4405 | EG | Cora St. | 8 | Ductile Iron | 735 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8603 | P-40023 | EG | Cora St. | 6 | Ductile Iron | 15 | 20 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8606 | P-40025 | EG | Cora St. | 6 | Ductile Iron | 17 | 20 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11239 | P-4405 | EG | Cora St. | 8 | Ductile Iron | 146 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6494 | P-4433 | EG | Country Ct. | 6 | Asbestos Cement | 94 | 49 | 1.85 out of 5 | $442 | 41,468 |
| Distribution Main | 6282 | P-4804 | EG | Court House Ln | 6 | Ductile Iron | 202 | 24 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 5005 | P-4341 | EG | Crest Ridge Dr. | 8 | Asbestos Cement | 522 | 50 | 1.14 out of 5 | $442 | 230,868 |
| Distribution Main | 5006 | P-4990 | EG | Crest Ridge Dr. | 8 | Asbestos Cement | 121 | 50 | 1.14 out of 5 | $442 | 53,367 |
| Distribution Main | 5947 | P-4340 | EG | Crest Ridge Dr. | 8 | Asbestos Cement | 32 | 50 | 1.14 out of 5 | $442 | 14,081 |
| Distribution Main | 5948 | P-4340 | EG | Crest Ridge Dr. | 8 | Asbestos Cement | 834 | 50 | 1.85 out of 5 | $442 | 368,712 |
| Distribution Main | 2505 | P-4461 | EG | Cresthill Dr. | 6 | Asbestos Cement | 345 | 61 | 2 out of 5 | $442 | 152,302 |
| Distribution Main | 5620 | P-4459 | EG | Cresthill Dr. | 6 | Asbestos Cement | 345 | 61 | 2 out of 5 | $442 | 152,316 |
| Distribution Main | 5621 | P-4459 | EG | Cresthill Dr. | 6 | Asbestos Cement | 287 | 61 | 2 out of 5 | $442 | 126,867 |
| Transmission Main | 2046 | | EG | Cricket Cir | 12 | Unknown | 38 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9706 | | EG | Cricket Cir | 8 | Unknown | 35 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5463 | P-4660 | EG | Crompton Ave. | 6 | Ductile Iron | 675 | 32 | 0.85 out of 5 | $442 | 298,251 |
| Distribution Main | 5464 | P-4660 | EG | Crompton Ave. | 6 | Ductile Iron | 280 | 32 | 0.85 out of 5 | $442 | 123,885 |
| Distribution Main | 5465 | P-4660 | EG | Crompton Ave. | 6 | Ductile Iron | 186 | 32 | 0.85 out of 5 | $442 | 82,042 |
| Distribution Main | 6733 | P-4660 | EG | Crompton Ave. | 6 | Ductile Iron | 12 | 32 | 0.85 out of 5 | $442 | 5,487 |
| Distribution Main | 9444 | P-4660 | EG | Crompton Ave. | 6 | Ductile Iron | 198 | 32 | 0.85 out of 5 | $442 | 87,652 |
| Distribution Main | 9445 | P-4660 | EG | Crompton Ave. | 6 | Ductile Iron | 161 | 32 | 0.85 out of 5 | $442 | 70,958 |
| Distribution Main | 11817 | P-4660 | EG | Crompton Ave. | 6 | Ductile Iron | 429 | 32 | 0.85 out of 5 | $442 | 189,796 |
| Transmission Main | 262 | P-4185 | EG | Crompton Rd. | 16 | Ductile Iron | 443 | 28 | 0.14 out of 5 | $442 | 196,025 |
| Transmission Main | 263 | P-4185 | EG | Crompton Rd. | 16 | Ductile Iron | 364 | 28 | 0.14 out of 5 | $442 | 160,754 |
| Transmission Main | 264 | P-4185 | EG | Crompton Rd. | 16 | Ductile Iron | 181 | 28 | 0.14 out of 5 | $442 | 80,150 |
| Transmission Main | 265 | P-4185 | EG | Crompton Rd. | 16 | Ductile Iron | 430 | 28 | 0.14 out of 5 | $442 | 190,131 |
| Transmission Main | 275 | P-4673 | EG | Crompton Rd. | 16 | Ductile Iron | 218 | 28 | 0.14 out of 5 | $442 | 96,324 |
| Transmission Main | 1034 | P-4185 | EG | Crompton Rd. | 16 | Ductile Iron | 478 | 28 | 0.14 out of 5 | $442 | 211,422 |
| Transmission Main | 1628 | P-4184 | EG | Crompton Rd. | 16 | Ductile Iron | 303 | 28 | 0.14 out of 5 | $442 | 133,869 |
| Transmission Main | 1629 | P-4184 | EG | Crompton Rd. | 16 | Ductile Iron | 409 | 28 | 0.14 out of 5 | $442 | 180,825 |
| Transmission Main | 11846 | P-4185 | EG | Crompton Rd. | 16 | Ductile Iron | 251 | 28 | 0.14 out of 5 | $442 | 110,964 |
| Transmission Main | 11847 | P-4185 | EG | Crompton Rd. | 16 | Ductile Iron | 522 | 28 | 0.14 out of 5 | $442 | 230,524 |
| Transmission Main | 11848 | P-4185 | EG | Crompton Rd. | 16 | Ductile Iron | 467 | 28 | 0.14 out of 5 | $442 | 206,373 |
| Transmission Main | 9168 | P-4619 | EG | Crop St | 12 | Ductile Iron | 6 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9169 | P-4619 | EG | Crop St | 12 | Ductile Iron | 297 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3656 | P-4415 | EG | Crossways Rd. | 6 | Asbestos Cement | 147 | 60 | 1.85 out of 5 | $442 | 65,085 |
| Distribution Main | 5290 | P-4415 | EG | Crossways Rd. | 6 | Asbestos Cement | 34 | 60 | 1.85 out of 5 | $442 | 15,056 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6141 | P-4700 | EG | Crossways Rd. | 6 | Ductile Iron | 191 | 22 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 6473 | P-4393 | EG | Crossways Rd. | 6 | Ductile Iron | 98 | 30 | 0.85 out of 5 | $442 | 43,471 |
| Distribution Main | 12174 | | EG | Crossways Rd. | 6 | Ductile Iron | 66 | 22 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 12175 | | EG | Crossways Rd. | 6 | Ductile Iron | 19 | 22 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 6345 | P-4122 | EG | Crystal Ct. | 6 | Asbestos Cement | 157 | 44 | 1.85 out of 5 | $442 | 69,242 |
| Distribution Main | 6022 | P-4121 | EG | Crystal Dr. | 8 | Asbestos Cement | 953 | 44 | 1.14 out of 5 | $442 | 421,218 |
| Distribution Main | 6023 | P-4121 | EG | Crystal Dr. | 8 | Asbestos Cement | 3 | 44 | 1.14 out of 5 | $442 | 1,444 |
| Distribution Main | 6573 | P-4123 | EG | Crystal Dr. | 8 | Asbestos Cement | 647 | 44 | 1.14 out of 5 | $442 | 285,897 |
| Distribution Main | 3929 | P-4256 | EG | Cypress Court | 6 | Asbestos Cement | 369 | 51 | 1.85 out of 5 | $442 | 163,302 |
| Distribution Main | 2506 | P-4455 | EG | Dalehill Dr. | 8 | Asbestos Cement | 212 | 59 | 1.14 out of 5 | $442 | 93,824 |
| Distribution Main | 2507 | P-4455 | EG | Dalehill Dr. | 8 | Asbestos Cement | 8 | 59 | 1.14 out of 5 | $442 | 3,346 |
| Distribution Main | 4027 | P-4502 | EG | Dalehill Dr. | 8 | Asbestos Cement | 6 | 59 | 1.14 out of 5 | $442 | 2,546 |
| Distribution Main | 4996 | P-4502 | EG | Dalehill Dr. | 8 | Asbestos Cement | 535 | 59 | 1.14 out of 5 | $442 | 236,576 |
| Distribution Main | 4997 | P-4502 | EG | Dalehill Dr. | 8 | Asbestos Cement | 55 | 59 | 1.14 out of 5 | $442 | 24,382 |
| Distribution Main | 5619 | P-4456 | EG | Dalehill Dr. | 6 | Asbestos Cement | 448 | 59 | 1.85 out of 5 | $442 | 198,203 |
| Distribution Main | 5957 | P-4453 | EG | Dalehill Dr. | 6 | Asbestos Cement | 404 | 59 | 1.85 out of 5 | $442 | 178,611 |
| Distribution Main | 5960 | P-4462 | EG | Dalehill Dr. | 8 | Asbestos Cement | 41 | 59 | 1.14 out of 5 | $442 | 17,979 |
| Distribution Main | 5961 | P-4462 | EG | Dalehill Dr. | 8 | Asbestos Cement | 406 | 59 | 1.14 out of 5 | $442 | 179,519 |
| Distribution Main | 6578 | P-4136 | EG | Darl Ct. | 8 | PVC | 362 | 33 | 0.43 out of 5 | $442 | 159,922 |
| Distribution Main | 6579 | P-4136 | EG | Darl Ct. | 8 | PVC | 13 | 33 | 0.43 out of 5 | $442 | 5,605 |
| Distribution Main | 6228 | P-4607 | EG | Dedford St. | 6 | Asbestos Cement | 148 | 49 | 1.85 out of 5 | $442 | 65,625 |
| Distribution Main | 6690 | P-4607 | EG | Dedford St. | 6 | Asbestos Cement | 5 | 49 | 1.85 out of 5 | $442 | 2,284 |
| Distribution Main | 3911 | P-4476 | EG | Deep Meadow Drive | 8 | Ductile Iron | 45 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4989 | P-4476 | EG | Deep Meadow Drive | 8 | Ductile Iron | 54 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5236 | P-4476 | EG | Deep Meadow Drive | 8 | Ductile Iron | 253 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10442 | P-4476 | EG | Deep Meadow Drive | 8 | Ductile Iron | 252 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5833 | P-4037 | EG | Deerfield Dr | 8 | Asbestos Cement | 8 | 45 | 1.14 out of 5 | $442 | 3,710 |
| Distribution Main | 6589 | P-4037 | EG | Deerfield Dr | 8 | Asbestos Cement | 284 | 45 | 1.14 out of 5 | $442 | 125,699 |
| Distribution Main | 6590 | P-4037 | EG | Deerfield Dr | 8 | Asbestos Cement | 234 | 45 | 1.14 out of 5 | $442 | 103,447 |
| Distribution Main | 3303 | P-4038 | EG | Deerfield Dr. | 8 | Asbestos Cement | 67 | 45 | 1.14 out of 5 | $442 | 29,536 |
| Distribution Main | 5816 | P-4022 | EG | Deerfield Dr. | 8 | PVC | 533 | 32 | 0.43 out of 5 | $442 | 235,710 |
| Distribution Main | 5820 | P-4036 | EG | Deerfield Dr. | 8 | PVC | 100 | 32 | 0.43 out of 5 | $442 | 44,043 |
| Distribution Main | 5821 | P-4033 | EG | Deerfield Dr. | 8 | PVC | 534 | 32 | 0.43 out of 5 | $442 | 235,898 |
| Distribution Main | 5823 | P-4035 | EG | Deerfield Dr. | 8 | PVC | 56 | 32 | 0.43 out of 5 | $442 | 24,548 |
| Distribution Main | 5824 | P-4035 | EG | Deerfield Dr. | 8 | PVC | 581 | 32 | 0.43 out of 5 | $442 | 256,878 |
| Distribution Main | 6582 | P-4022 | EG | Deerfield Dr. | 8 | PVC | 61 | 32 | 0.43 out of 5 | $442 | 27,131 |
| Distribution Main | 6583 | P-4022 | EG | Deerfield Dr. | 8 | PVC | 224 | 32 | 0.43 out of 5 | $442 | 98,875 |
| Distribution Main | 6588 | P-4039 | EG | Deerfield Dr. | 8 | Asbestos Cement | 550 | 45 | 1.14 out of 5 | $442 | 243,231 |
| Distribution Main | 6713 | P-4036 | EG | Deerfield Dr. | 8 | PVC | 581 | 32 | 0.43 out of 5 | $442 | 256,590 |
| Distribution Main | 6714 | P-4036 | EG | Deerfield Dr. | 8 | PVC | 23 | 32 | 0.43 out of 5 | $442 | 10,019 |
| Distribution Main | 3853 | P-4331 | EG | Devon Court | 6 | Asbestos Cement | 691 | 50 | 1.85 out of 5 | $442 | 305,216 |
| Distribution Main | 3854 | P-4331 | EG | Devon Court | 6 | Asbestos Cement | 25 | 50 | 1.85 out of 5 | $442 | 11,046 |
| Distribution Main | 2047 | | EG | Division Rd | 8 | Ductile Iron | 55 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9003 | P-4881 | EG | Division Rd | 8 | Ductile Iron | 16 | 13 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 9091 | P-4758 | EG | Division Rd | 16 | Ductile Iron | 394 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9092 | P-4758 | EG | Division Rd | 16 | Ductile Iron | 252 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9093 | P-4849 | EG | Division Rd | 12 | Ductile Iron | 32 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9094 | P-4882 | EG | Division Rd | 16 | Ductile Iron | 283 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9095 | P-4882 | EG | Division Rd | 16 | Ductile Iron | 37 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9351 | | EG | Division Rd | 6 | Ductile Iron | 53 | 8 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 11539 | P-4882 | EG | Division Rd | 16 | Ductile Iron | 158 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11856 | P-4882 | EG | Division Rd | 16 | Ductile Iron | 72 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12101 | P-4758 | EG | Division Rd | 16 | Ductile Iron | 322 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12102 | P-4758 | EG | Division Rd | 16 | Ductile Iron | 127 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12103 | P-4882 | EG | Division Rd | 16 | Ductile Iron | 6 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 33 | P-4754 | EG | Division Road | 16 | Ductile Iron | 26 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 64 | | EG | Division Road | 16 | Ductile Iron | 9 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 461 | P-4705 | EG | Division Road | 12 | Asbestos Cement | 22 | 48 | 1.14 out of 5 | $442 | 9,715 |
| Transmission Main | 511 | P-4706 | EG | Division Road | 12 | Asbestos Cement | 774 | 48 | 1.14 out of 5 | $442 | 342,042 |
| Transmission Main | 512 | P-4706 | EG | Division Road | 12 | Asbestos Cement | 576 | 48 | 1.14 out of 5 | $442 | 254,729 |
| Transmission Main | 776 | P-4780 | EG | Division Road | 12 | Asbestos Cement | 397 | 48 | 1.14 out of 5 | $442 | 175,582 |
| Transmission Main | 777 | P-4706 | EG | Division Road | 12 | Asbestos Cement | 3 | 48 | 1.14 out of 5 | $442 | 1,455 |
| Transmission Main | 778 | P-4706 | EG | Division Road | 12 | Asbestos Cement | 613 | 48 | 1.14 out of 5 | $442 | 271,147 |
| Transmission Main | 779 | P-4706 | EG | Division Road | 12 | Asbestos Cement | 577 | 48 | 1.14 out of 5 | $442 | 254,833 |
| Transmission Main | 780 | P-4706 | EG | Division Road | 12 | Asbestos Cement | 215 | 48 | 1.14 out of 5 | $442 | 95,048 |
| Transmission Main | 781 | P-4706 | EG | Division Road | 12 | Asbestos Cement | 310 | 48 | 1.14 out of 5 | $442 | 137,187 |
| Transmission Main | 965 | P-4706 | EG | Division Road | 12 | Asbestos Cement | 281 | 48 | 1.14 out of 5 | $442 | 124,140 |
| Transmission Main | 975 | P-4180 | EG | Division Road | 12 | Asbestos Cement | 16 | 62 | 1.29 out of 5 | $442 | 7,268 |
| Transmission Main | 976 | | EG | Division Road | 12 | Asbestos Cement | 46 | 62 | 1.29 out of 5 | $442 | 20,197 |
| Transmission Main | 977 | P-4706 | EG | Division Road | 12 | Asbestos Cement | 65 | 48 | 1.14 out of 5 | $442 | 28,551 |
| Transmission Main | 1674 | P-4754 | EG | Division Road | 16 | Ductile Iron | 422 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1675 | P-4754 | EG | Division Road | 16 | Ductile Iron | 882 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1676 | P-4754 | EG | Division Road | 16 | Ductile Iron | 529 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1677 | P-4168 | EG | Division Road | 16 | Ductile Iron | 29 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1678 | P-4168 | EG | Division Road | 16 | Ductile Iron | 588 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1679 | P-4168 | EG | Division Road | 16 | Ductile Iron | 232 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1680 | P-4168 | EG | Division Road | 16 | Ductile Iron | 751 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1681 | P-4168 | EG | Division Road | 16 | Ductile Iron | 4 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2045 | | EG | Division Road | 12 | Asbestos Cement | 18 | 62 | 1.29 out of 5 | $442 | 8,064 |
| Transmission Main | 2048 | P-4780 | EG | Division Road | 12 | Asbestos Cement | 350 | 48 | 1.14 out of 5 | $442 | 154,807 |
| Transmission Main | 6340 | P-4705 | EG | Division Road | 12 | Asbestos Cement | 582 | 48 | 1.14 out of 5 | $442 | 257,128 |
| Transmission Main | 119 | P-4678 | EG | Division St. | 12 | Asbestos Cement | 415 | 62 | 1.29 out of 5 | $442 | 183,233 |
| Transmission Main | 120 | P-4678 | EG | Division St. | 12 | Asbestos Cement | 379 | 62 | 1.29 out of 5 | $442 | 167,500 |
| Distribution Main | 303 | P-4568 | EG | Division St. | 8 | Ductile Iron | 18 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2253 | P-4561 | EG | Division St. | 8 | Cast Iron | 39 | 129 | 1.86 out of 5 | $442 | 17,099 |
| Transmission Main | 2523 | P-4560 | EG | Division St. | 12 | Asbestos Cement | 468 | 62 | 1.29 out of 5 | $442 | 206,957 |
| Distribution Main | 2912 | P-4713 | EG | Division St. | 8 | Cast Iron | 215 | 129 | 1.86 out of 5 | $442 | 95,142 |
| Distribution Main | 2913 | P-4713 | EG | Division St. | 8 | Cast Iron | 74 | 129 | 1.86 out of 5 | $442 | 32,491 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2914 | P-4567 | EG | Division St. | 8 | Cast Iron | 120 | 129 | 1.86 out of 5 | $442 | 52,957 |
| Transmission Main | 3222 | P-4583 | EG | Division St. | 12 | Asbestos Cement | 12 | 62 | 1.29 out of 5 | $442 | 5,194 |
| Distribution Main | 3223 | P-4885 | EG | Division St. | 2 | Copper | 453 | UNK | 1.99 out of 5 | $442 | 200,319 |
| Transmission Main | 3460 | P-4497 | EG | Division St. | 12 | Asbestos Cement | 605 | 62 | 1.14 out of 5 | $442 | 267,309 |
| Transmission Main | 3912 | P-4674 | EG | Division St. | 12 | Asbestos Cement | 919 | 62 | 1.29 out of 5 | $442 | 406,412 |
| Transmission Main | 3913 | P-4674 | EG | Division St. | 12 | Asbestos Cement | 800 | 62 | 2 out of 5 | $442 | 353,666 |
| Transmission Main | 3914 | P-4674 | EG | Division St. | 12 | Asbestos Cement | 49 | 62 | 1.29 out of 5 | $442 | 21,556 |
| Transmission Main | 3915 | P-4674 | EG | Division St. | 12 | Asbestos Cement | 22 | 62 | 1.29 out of 5 | $442 | 9,753 |
| Transmission Main | 3938 | P-4526 | EG | Division St. | 12 | Asbestos Cement | 818 | 62 | 1.29 out of 5 | $442 | 361,492 |
| Transmission Main | 4155 | P-4498 | EG | Division St. | 12 | Asbestos Cement | 563 | 62 | 1.29 out of 5 | $442 | 248,980 |
| Distribution Main | 4525 | P-4550 | EG | Division St. | 6 | Cast Iron | 412 | 133 | 2.57 out of 5 | $442 | 182,212 |
| Distribution Main | 4526 | P-4550 | EG | Division St. | 6 | Cast Iron | 305 | 133 | 2.57 out of 5 | $442 | 134,644 |
| Distribution Main | 4533 | | EG | Division St. | 8 | Cast Iron | 66 | 129 | 1.86 out of 5 | $442 | 28,989 |
| Distribution Main | 4534 | P-4564 | EG | Division St. | 8 | Cast Iron | 238 | 129 | 1.86 out of 5 | $442 | 105,105 |
| Distribution Main | 4535 | P-4539 | EG | Division St. | 6 | Cast Iron | 333 | 129 | 2.57 out of 5 | $442 | 147,172 |
| Transmission Main | 4539 | P-4602 | EG | Division St. | 12 | Asbestos Cement | 14 | 62 | 1.29 out of 5 | $442 | 5,985 |
| Distribution Main | 5035 | P-4567 | EG | Division St. | 8 | Cast Iron | 125 | 129 | 1.86 out of 5 | $442 | 55,418 |
| Distribution Main | 5036 | P-4567 | EG | Division St. | 8 | Cast Iron | 7 | 129 | 1.86 out of 5 | $442 | 3,268 |
| Distribution Main | 5039 | P-4886 | EG | Division St. | 8 | Asbestos Cement | 88 | UNK | 0.85 out of 5 | $442 | 38,925 |
| Transmission Main | 5040 | P-4583 | EG | Division St. | 12 | Asbestos Cement | 342 | 62 | 1.29 out of 5 | $442 | 151,253 |
| Transmission Main | 5410 | P-4463 | EG | Division St. | 12 | Asbestos Cement | 472 | 62 | 1.29 out of 5 | $442 | 208,486 |
| Transmission Main | 5411 | P-4463 | EG | Division St. | 12 | Asbestos Cement | 15 | 62 | 1.14 out of 5 | $442 | 6,630 |
| Transmission Main | 5412 | P-4676 | EG | Division St. | 12 | Asbestos Cement | 16 | 62 | 1.29 out of 5 | $442 | 7,080 |
| Transmission Main | 5428 | P-4538 | EG | Division St. | 12 | Asbestos Cement | 936 | 62 | 1.29 out of 5 | $442 | 413,575 |
| Transmission Main | 5787 | P-4676 | EG | Division St. | 12 | Asbestos Cement | 31 | 62 | 1.29 out of 5 | $442 | 13,543 |
| Transmission Main | 5966 | P-4497 | EG | Division St. | 12 | Asbestos Cement | 14 | 62 | 1.29 out of 5 | $442 | 6,049 |
| Transmission Main | 5967 | P-4463 | EG | Division St. | 12 | Asbestos Cement | 41 | 62 | 1.29 out of 5 | $442 | 18,247 |
| Transmission Main | 6288 | P-4602 | EG | Division St. | 12 | Asbestos Cement | 14 | 62 | 1.29 out of 5 | $442 | 5,993 |
| Distribution Main | 6289 | P-4563 | EG | Division St. | 8 | Cast Iron | 249 | 129 | 1.86 out of 5 | $442 | 110,184 |
| Distribution Main | 6290 | P-4562 | EG | Division St. | 8 | Cast Iron | 21 | 129 | 1.86 out of 5 | $442 | 9,164 |
| Transmission Main | 6304 | P-4521 | EG | Division St. | 12 | Asbestos Cement | 1,053 | 62 | 1.14 out of 5 | $442 | 465,467 |
| Transmission Main | 6305 | P-4583 | EG | Division St. | 12 | Asbestos Cement | 508 | 62 | 1.29 out of 5 | $442 | 224,372 |
| Distribution Main | 6306 | P-4885 | EG | Division St. | 2 | Copper | 61 | UNK | 1.99 out of 5 | $442 | 26,816 |
| Transmission Main | 6324 | P-4674 | EG | Division St. | 12 | Asbestos Cement | 518 | 62 | 1.29 out of 5 | $442 | 229,016 |
| Transmission Main | 6327 | P-4465 | EG | Division St. | 12 | Asbestos Cement | 107 | 62 | 1.29 out of 5 | $442 | 47,121 |
| Transmission Main | 6328 | P-4465 | EG | Division St. | 12 | Asbestos Cement | 492 | 62 | 1.29 out of 5 | $442 | 217,501 |
| Transmission Main | 6329 | P-4674 | EG | Division St. | 12 | Asbestos Cement | 325 | 62 | 1.29 out of 5 | $442 | 143,686 |
| Transmission Main | 6330 | P-4674 | EG | Division St. | 12 | Asbestos Cement | 294 | 62 | 1.29 out of 5 | $442 | 130,143 |
| Transmission Main | 6334 | P-4676 | EG | Division St. | 12 | Asbestos Cement | 8 | 62 | 1.29 out of 5 | $442 | 3,476 |
| Transmission Main | 6335 | P-4676 | EG | Division St. | 12 | Asbestos Cement | 5 | 62 | 1.29 out of 5 | $442 | 2,201 |
| Transmission Main | 6336 | P-4674 | EG | Division St. | 12 | Asbestos Cement | 14 | 48 | 1.14 out of 5 | $442 | 6,143 |
| Transmission Main | 6338 | P-4466 | EG | Division St. | 12 | Asbestos Cement | 457 | 62 | 1.29 out of 5 | $442 | 202,060 |
| Transmission Main | 6566 | P-4701 | EG | Division St. | 12 | Asbestos Cement | 124 | 62 | 1.14 out of 5 | $442 | 54,853 |
| Transmission Main | 6567 | P-4701 | EG | Division St. | 12 | Asbestos Cement | 701 | 62 | 1.29 out of 5 | $442 | 309,840 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 6715 | P-4702 | EG | Division St. | 12 | Asbestos Cement | 250 | 62 | 1.29 out of 5 | $442 | 110,580 |
| Distribution Main | 6764 | P-4563 | EG | Division St. | 8 | Cast Iron | 30 | 129 | 1.86 out of 5 | $442 | 13,186 |
| Distribution Main | 6765 | P-4563 | EG | Division St. | 8 | Cast Iron | 13 | 129 | 1.86 out of 5 | $442 | 5,719 |
| Distribution Main | 6768 | P-4562 | EG | Division St. | 8 | Cast Iron | 30 | 129 | 1.86 out of 5 | $442 | 13,192 |
| Distribution Main | 6769 | P-4562 | EG | Division St. | 8 | Cast Iron | 232 | 129 | 1.86 out of 5 | $442 | 102,441 |
| Distribution Main | 6770 | P-4560 | EG | Division St. | 8 | Cast Iron | 15 | 129 | 1.86 out of 5 | $442 | 6,582 |
| Distribution Main | 6771 | P-4560 | EG | Division St. | 8 | Cast Iron | 402 | 129 | 1.86 out of 5 | $442 | 177,487 |
| Transmission Main | 9010 | P-4583 | EG | Division St. | 12 | Asbestos Cement | 229 | 62 | 1.29 out of 5 | $442 | 101,090 |
| Transmission Main | 9011 | P-4583 | EG | Division St. | 12 | Asbestos Cement | 182 | 62 | 1.29 out of 5 | $442 | 80,397 |
| Transmission Main | 9012 | P-4583 | EG | Division St. | 12 | Asbestos Cement | 168 | 62 | 1.29 out of 5 | $442 | 74,300 |
| Transmission Main | 9013 | P-4583 | EG | Division St. | 12 | Asbestos Cement | 65 | 62 | 1.29 out of 5 | $442 | 28,566 |
| Distribution Main | 9137 | | EG | Division St. | 8 | Cast Iron | 60 | 129 | 1.86 out of 5 | $442 | 26,594 |
| Distribution Main | 9138 | P-4893 | EG | Division St. | 6 | Cast Iron | 229 | 129 | 2.57 out of 5 | $442 | 101,093 |
| Distribution Main | 9308 | P-4559 | EG | Division St. | 8 | Cast Iron | 4 | 129 | 1.86 out of 5 | $442 | 1,878 |
| Distribution Main | 9309 | P-4559 | EG | Division St. | 8 | Cast Iron | 251 | 129 | 1.86 out of 5 | $442 | 110,924 |
| Distribution Main | 9484 | P-4558 | EG | Division St. | 6 | Cast Iron | 102 | 131 | 2.57 out of 5 | $442 | 45,118 |
| Distribution Main | 9485 | P-4558 | EG | Division St. | 6 | Cast Iron | 12 | 133 | 2.57 out of 5 | $442 | 5,279 |
| Distribution Main | 11255 | P-4539 | EG | Division St. | 6 | Cast Iron | 6 | 129 | 2.57 out of 5 | $442 | 2,733 |
| Distribution Main | 11271 | P-4561 | EG | Division St. | 8 | Cast Iron | 11 | 129 | 1.86 out of 5 | $442 | 4,987 |
| Transmission Main | 11350 | P-4702 | EG | Division St. | 12 | Asbestos Cement | 51 | 62 | 1.14 out of 5 | $442 | 22,545 |
| Distribution Main | 11548 | | EG | Division St. | 8 | Cast Iron | 4 | 129 | 1.86 out of 5 | $442 | 1,551 |
| Distribution Main | 11951 | P-4713 | EG | Division St. | 8 | Cast Iron | 36 | 129 | 1.86 out of 5 | $442 | 15,792 |
| Distribution Main | 12106 | P-4558 | EG | Division St. | 6 | Cast Iron | 68 | 133 | 2.57 out of 5 | $442 | 29,984 |
| Distribution Main | 372 | | EG | Division St. Prv | 8 | Ductile Iron | 10 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4499 | | EG | Division St. Prv | 8 | Ductile Iron | 18 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5415 | | EG | Division St. Prv | 8 | Ductile Iron | 24 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6339 | | EG | Division St. Prv | 8 | Ductile Iron | 4 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6043 | P-4324 | EG | Downing Street | 8 | Asbestos Cement | 406 | 50 | 1.14 out of 5 | $442 | 179,531 |
| Distribution Main | 6044 | P-4324 | EG | Downing Street | 8 | Asbestos Cement | 1,001 | 50 | 1.14 out of 5 | $442 | 442,321 |
| Distribution Main | 11827 | P-4324 | EG | Downing Street | 8 | Asbestos Cement | 22 | 50 | 1.14 out of 5 | $442 | 9,745 |
| Distribution Main | 9162 | P-4616 | EG | Duke St | 8 | Ductile Iron | 208 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9174 | P-4628 | EG | Duke St | 8 | Ductile Iron | 424 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9179 | P-4646 | EG | Duke St | 8 | Ductile Iron | 119 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9180 | P-4644 | EG | Duke St | 8 | Ductile Iron | 366 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9181 | P-4644 | EG | Duke St | 8 | Ductile Iron | 18 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9192 | P-4904 | EG | Duke St | 8 | Ductile Iron | 227 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9193 | P-4904 | EG | Duke St | 8 | Ductile Iron | 49 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9200 | P-4644 | EG | Duke St | 8 | Ductile Iron | 16 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11553 | P-4904 | EG | Duke St | 8 | Ductile Iron | 137 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1893 | P-4627 | EG | Duke St. | 8 | Ductile Iron | 100 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9199 | P-4646 | EG | Duke St. | 8 | Ductile Iron | 230 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9304 | P-4646 | EG | Duke St. | 8 | Ductile Iron | 3 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5822 | P-4034 | EG | Eagle Ln. | 8 | PVC | 390 | 32 | 0.43 out of 5 | $442 | 172,530 |
| Transmission Main | 4486 | P-4027 | EG | Easement | 16 | Ductile Iron | 290 | 25 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 4489 | P-4027 | EG | Easement | 16 | Ductile Iron | 32 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4490 | P-4027 | EG | Easement | 16 | Ductile Iron | 573 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4589 | P-4005 | EG | Easement | 12 | Ductile Iron | 460 | 30 | 0.14 out of 5 | $442 | 203,466 |
| Transmission Main | 5724 | P-4149 | EG | Easement | 16 | Ductile Iron | 703 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5725 | P-4149 | EG | Easement | 16 | Ductile Iron | 513 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5729 | P-4027 | EG | Easement | 16 | Ductile Iron | 316 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5732 | P-4149 | EG | Easement | 16 | Ductile Iron | 8 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5733 | P-4149 | EG | Easement | 16 | Ductile Iron | 142 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5734 | P-4027 | EG | Easement | 16 | Ductile Iron | 6 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6119 | P-4252 | EG | Edward Road | 6 | Asbestos Cement | 27 | 56 | 1.85 out of 5 | $442 | 11,933 |
| Distribution Main | 6120 | P-4252 | EG | Edward Road | 6 | Asbestos Cement | 509 | 56 | 1.85 out of 5 | $442 | 225,015 |
| Distribution Main | 11325 | P-4252 | EG | Edward Road | 6 | Asbestos Cement | 4 | 56 | 1.85 out of 5 | $442 | 1,568 |
| Transmission Main | 6712 | | EG | Eg Well Station 1 | 12 | Ductile Iron | 240 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3916 | P-4553 | EG | Eldredge Ave. | 8 | Ductile Iron | 312 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4514 | P-4683 | EG | Eldredge Ave. | 8 | Ductile Iron | 81 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4515 | P-4683 | EG | Eldredge Ave. | 8 | Ductile Iron | 414 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10381 | P-4557 | EG | Eldredge Ave. | 8 | Ductile Iron | 209 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4207 | P-4272 | EG | Eugene St. | 6 | Asbestos Cement | 731 | 51 | 1.85 out of 5 | $442 | 323,018 |
| Distribution Main | 4208 | P-4272 | EG | Eugene St. | 6 | Asbestos Cement | 438 | 51 | 1.85 out of 5 | $442 | 193,543 |
| Transmission Main | 6122 | P-4229 | EG | Eugene St. | 20 | Asbestos Cement | 1,478 | 55 | 1.14 out of 5 | $442 | 653,462 |
| Distribution Main | 1894 | P-4629 | EG | Exchange St. | 8 | Ductile Iron | 464 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5518 | P-4098 | EG | Ezechial Carrie Rd. | 8 | PVC | 1,130 | 35 | 0.43 out of 5 | $442 | 499,359 |
| Distribution Main | 5653 | P-4098 | EG | Ezechial Carrie Rd. | 8 | PVC | 20 | 35 | 0.43 out of 5 | $442 | 8,784 |
| Distribution Main | 5875 | P-498 | EG | Ezechial Carrie Rd. | 8 | PVC | 29 | 35 | 0.43 out of 5 | $442 | 12,762 |
| Distribution Main | 3654 | P-4342 | EG | Fairfield Ave. | 6 | Ductile Iron | 190 | 21 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 4194 | P-4350 | EG | Fairfield Ave. | 6 | Ductile Iron | 195 | 21 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 5468 | | EG | Fairfield Ave. | 6 | Ductile Iron | 6 | 21 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 5469 | P-4353 | EG | Fairfield Ave. | 6 | Ductile Iron | 59 | 21 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 5470 | P-4353 | EG | Fairfield Ave. | 6 | Ductile Iron | 27 | UNK | 0.71 out of 5 | $442 | 11,862 |
| Distribution Main | 6482 | P-4335 | EG | Fairfield Ave. | 6 | Ductile Iron | 180 | 21 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 6483 | P-4335 | EG | Fairfield Ave. | 6 | Ductile Iron | 24 | 21 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 6484 | P-4348 | EG | Fairfield Ave. | 6 | Ductile Iron | 200 | 21 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 5834 | P-4038 | EG | Falcon Cir. | 8 | Asbestos Cement | 1,018 | 45 | 1.14 out of 5 | $442 | 450,145 |
| Distribution Main | 5835 | P-4038 | EG | Falcon Cir. | 8 | Asbestos Cement | 996 | 45 | 1.14 out of 5 | $442 | 440,299 |
| Distribution Main | 5836 | P-4038 | EG | Falcon Cir. | 8 | Asbestos Cement | 15 | 45 | 1.14 out of 5 | $442 | 6,575 |
| Distribution Main | 6481 | P-4338 | EG | Farifield Ave. | 6 | Ductile Iron | 217 | 21 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 5650 | P-4133 | EG | Fernwood Dr | 6 | Ductile Iron | 17 | 36 | 0.85 out of 5 | $442 | 7,335 |
| Distribution Main | 6017 | P-4133 | EG | Fernwood Dr | 6 | Ductile Iron | 220 | 36 | 0.85 out of 5 | $442 | 97,155 |
| Transmission Main | 6003 | P-4132 | EG | Fernwood Dr. | 20 | Ductile Iron | 55 | 36 | 0.14 out of 5 | $442 | 24,140 |
| Transmission Main | 6011 | P-4132 | EG | Fernwood Dr. | 20 | Ductile Iron | 60 | 36 | 0.14 out of 5 | $442 | 26,554 |
| Transmission Main | 6014 | P-4134 | EG | Fernwood Dr. | 20 | Ductile Iron | 41 | 36 | 0.14 out of 5 | $442 | 18,034 |
| Transmission Main | 6341 | P-4134 | EG | Fernwood Dr. | 20 | Ductile Iron | 39 | 36 | 0.14 out of 5 | $442 | 17,232 |
| Transmission Main | 6342 | P-4134 | EG | Fernwood Dr. | 20 | Ductile Iron | 885 | 36 | 0.14 out of 5 | $442 | 391,336 |
| Transmission Main | 6572 | P-4994 | EG | Fernwood Dr. | 20 | Ductile Iron | 198 | 36 | 0.14 out of 5 | $442 | 87,681 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6155 | P-4468 | EG | Field Stone Dr. | 6 | Ductile Iron | 376 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 4265 | P-4946 | EG | Fifth Av | 6 | Asbestos Cement | 30 | 51 | 1.85 out of 5 | $442 | 13,236 |
| Distribution Main | 5673 | P-4946 | EG | Fifth Av | 6 | Asbestos Cement | 211 | 51 | 1.85 out of 5 | $442 | 93,144 |
| Distribution Main | 9314 | | EG | First Ave | 6 | Ductile Iron | 26 | 9 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 666 | P-4515 | EG | First Ave. | 8 | Asbestos Cement | 486 | 52 | 1.14 out of 5 | $442 | 214,994 |
| Transmission Main | 1076 | P-4662 | EG | First Ave. | 12 | Ductile Iron | 75 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1899 | P-4586 | EG | First Ave. | 6 | Cast Iron | 166 | 133 | 2.57 out of 5 | $442 | 73,373 |
| Distribution Main | 1900 | P-4969 | EG | First Ave. | 8 | Ductile Iron | 15 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4174 | P-4532 | EG | First Ave. | 6 | Cast Iron | 272 | 133 | 2.57 out of 5 | $442 | 120,012 |
| Distribution Main | 4175 | P-4532 | EG | First Ave. | 6 | Cast Iron | 23 | 133 | 2.57 out of 5 | $442 | 10,256 |
| Distribution Main | 4261 | P-4593 | EG | First Ave. | 6 | Cast Iron | 54 | 133 | 2.57 out of 5 | $442 | 23,948 |
| Distribution Main | 5418 | P-4590 | EG | First Ave. | 6 | Cast Iron | 686 | 133 | 2.57 out of 5 | $442 | 303,315 |
| Distribution Main | 5425 | P-4532 | EG | First Ave. | 6 | Cast Iron | 8 | 133 | 2.57 out of 5 | $442 | 3,621 |
| Distribution Main | 6268 | P-4586 | EG | First Ave. | 6 | Cast Iron | 25 | 133 | 2.57 out of 5 | $442 | 11,137 |
| Distribution Main | 6347 | | EG | First Ave. | 8 | Asbestos Cement | 7 | 52 | 1.14 out of 5 | $442 | 3,250 |
| Distribution Main | 6350 | P-4703 | EG | First Ave. | 8 | Asbestos Cement | 558 | 52 | 1.14 out of 5 | $442 | 246,643 |
| Distribution Main | 6630 | P-4581 | EG | First Ave. | 6 | Cast Iron | 236 | 133 | 2.57 out of 5 | $442 | 104,303 |
| Distribution Main | 6632 | P-4588 | EG | First Ave. | 6 | Cast Iron | 14 | 133 | 2.57 out of 5 | $442 | 6,199 |
| Distribution Main | 6633 | P-4588 | EG | First Ave. | 6 | Cast Iron | 183 | 133 | 2.57 out of 5 | $442 | 80,756 |
| Transmission Main | 6642 | | EG | First Ave. | 12 | Ductile Iron | 15 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6718 | P-4585 | EG | First Ave. | 6 | Cast Iron | 199 | 131 | 2.57 out of 5 | $442 | 88,081 |
| Transmission Main | 6724 | P-4940 | EG | First Ave. | 12 | Ductile Iron | 63 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6727 | P-4703 | EG | First Ave. | 8 | Asbestos Cement | 247 | 52 | 1.14 out of 5 | $442 | 109,106 |
| Distribution Main | 9443 | P-4593 | EG | First Ave. | 6 | Cast Iron | 362 | 133 | 2.57 out of 5 | $442 | 160,163 |
| Distribution Main | 11005 | P-4970 | EG | First Ave. | 8 | Ductile Iron | 14 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11151 | P-4586 | EG | First Ave. | 6 | Cast Iron | 51 | 133 | 2.57 out of 5 | $442 | 22,560 |
| Distribution Main | 11332 | P-4703 | EG | First Ave. | 8 | Asbestos Cement | 5 | 52 | 1.14 out of 5 | $442 | 2,169 |
| Distribution Main | 11347 | P-4581 | EG | First Ave. | 6 | Cast Iron | 6 | 133 | 2.57 out of 5 | $442 | 2,761 |
| Distribution Main | 6784 | P-4280 | EG | Flintstone Court | 6 | Asbestos Cement | 5 | 51 | 1.85 out of 5 | $442 | 2,017 |
| Distribution Main | 6785 | P-4280 | EG | Flintstone Court | 6 | Asbestos Cement | 335 | 51 | 1.85 out of 5 | $442 | 148,153 |
| Distribution Main | 5209 | P-4941 | EG | Fourth Ave. | 6 | PVC | 701 | 36 | 1.14 out of 5 | $442 | 309,839 |
| Distribution Main | 5399 | P-4664 | EG | Fourth Ave. | 6 | Asbestos Cement | 240 | 68 | 2 out of 5 | $442 | 106,058 |
| Distribution Main | 5400 | P-4664 | EG | Fourth Ave. | 6 | Asbestos Cement | 6 | 68 | 2 out of 5 | $442 | 2,505 |
| Distribution Main | 5422 | P-4666 | EG | Fourth Ave. | 6 | PVC | 332 | 36 | 1.14 out of 5 | $442 | 146,960 |
| Distribution Main | 6639 | P-4941 | EG | Fourth Ave. | 6 | PVC | 59 | 36 | 1.14 out of 5 | $442 | 26,016 |
| Distribution Main | 3939 | P-4944 | EG | Fourth St | 6 | Unknown | 254 | 68 | 1.14 out of 5 | $442 | 112,118 |
| Distribution Main | 5417 | P-4945 | EG | Fourth St | 6 | Unknown | 179 | 68 | 1.14 out of 5 | $442 | 79,125 |
| Distribution Main | 970 | P-4172 | EG | Fox Run | 8 | Asbestos Cement | 14 | 39 | 1 out of 5 | $442 | 6,249 |
| Distribution Main | 974 | P-4171 | EG | Fox Run | 8 | Asbestos Cement | 608 | 39 | 1 out of 5 | $442 | 268,926 |
| Distribution Main | 2037 | P-4172 | EG | Fox Run | 8 | Asbestos Cement | 606 | 39 | 1 out of 5 | $442 | 268,038 |
| Distribution Main | 2038 | P-4172 | EG | Fox Run | 8 | Asbestos Cement | 976 | 39 | 1 out of 5 | $442 | 431,565 |
| Distribution Main | 5666 | P-4057 | EG | Franklin Rd. | 8 | Asbestos Cement | 439 | 51 | 1.14 out of 5 | $442 | 194,241 |
| Distribution Main | 5667 | P-4057 | EG | Franklin Rd. | 8 | Asbestos Cement | 271 | 51 | 1.14 out of 5 | $442 | 119,771 |
| Distribution Main | 5788 | P-4072 | EG | Frederick T. Miller Way | 8 | Ductile Iron | 14 | 19 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 5789 | P-4072 | EG | Frederick T. Miller Way | 8 | Ductile Iron | 411 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9062 | P-40005 | EG | Frenchtown Rd | 12 | Asbestos Cement | 9 | 55 | 1.14 out of 5 | $442 | 3,769 |
| Transmission Main | 749 | P-4855 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 96 | 55 | 1.14 out of 5 | $442 | 42,502 |
| Transmission Main | 750 | P-4855 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 159 | 55 | 1.14 out of 5 | $442 | 70,207 |
| Transmission Main | 751 | | EG | Frenchtown Rd. | 12 | Ductile Iron | 15 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 752 | P-4855 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 677 | 55 | 1.14 out of 5 | $442 | 299,035 |
| Transmission Main | 753 | P-4855 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 21 | 55 | 1.14 out of 5 | $442 | 9,464 |
| Transmission Main | 754 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 410 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 755 | | EG | Frenchtown Rd. | 12 | Asbestos Cement | 4 | 55 | 1.14 out of 5 | $442 | 1,555 |
| Transmission Main | 756 | P-4371 | EG | Frenchtown Rd. | 16 | Ductile Iron | 32 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 758 | P-4855 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 732 | 55 | 1.14 out of 5 | $442 | 323,537 |
| Transmission Main | 1929 | P-40019 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 15 | 55 | 1.14 out of 5 | $442 | 6,495 |
| Transmission Main | 1930 | P-4855 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 130 | 55 | 1.14 out of 5 | $442 | 57,336 |
| Transmission Main | 1931 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 48 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1932 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 13 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1933 | | EG | Frenchtown Rd. | 12 | Asbestos Cement | 39 | 55 | 1.14 out of 5 | $442 | 17,446 |
| Transmission Main | 1934 | P-4728 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 355 | 55 | 1.14 out of 5 | $442 | 157,031 |
| Transmission Main | 1935 | P-4728 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 662 | 55 | 1.14 out of 5 | $442 | 292,692 |
| Transmission Main | 1936 | P-4730 | EG | Frenchtown Rd. | 16 | Ductile Iron | 187 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1937 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 579 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1938 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 460 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1939 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 574 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1942 | P-4728 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 73 | 55 | 1.14 out of 5 | $442 | 32,190 |
| Transmission Main | 1943 | P-4855 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 659 | 55 | 1.14 out of 5 | $442 | 291,358 |
| Transmission Main | 1944 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 18 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1945 | P-4855 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 359 | 55 | 1.14 out of 5 | $442 | 158,867 |
| Transmission Main | 1946 | P-4855 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 5 | 55 | 1.14 out of 5 | $442 | 2,124 |
| Transmission Main | 1947 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 179 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1948 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 487 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2915 | P-4855 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 31 | 55 | 1.14 out of 5 | $442 | 13,735 |
| Transmission Main | 2975 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 704 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2976 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 80 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 3301 | P-4063 | EG | Frenchtown Rd. | 12 | Ductile Iron | 30 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4139 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 349 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4140 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 88 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4141 | P-4831 | EG | Frenchtown Rd. | 16 | Ductile Iron | 526 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4142 | P-4730 | EG | Frenchtown Rd. | 16 | Ductile Iron | 546 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4143 | | EG | Frenchtown Rd. | 12 | Asbestos Cement | 4 | 55 | 1.14 out of 5 | $442 | 1,594 |
| Transmission Main | 4355 | P-4743 | EG | Frenchtown Rd. | 16 | Ductile Iron | 7 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4356 | P-4843 | EG | Frenchtown Rd. | 12 | Ductile Iron | 773 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4361 | P-4056 | EG | Frenchtown Rd. | 12 | Ductile Iron | 47 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4362 | P-4056 | EG | Frenchtown Rd. | 12 | Ductile Iron | 390 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4363 | P-4060 | EG | Frenchtown Rd. | 16 | Asbestos Cement | 749 | 49 | 1.14 out of 5 | $442 | 331,127 |
| Transmission Main | 4366 | P-40071 | EG | Frenchtown Rd. | 12 | Ductile Iron | 887 | 22 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 4382 | P-4855 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 754 | 55 | 1.14 out of 5 | $442 | 333,051 |
| Transmission Main | 4383 | P-4855 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 692 | 55 | 1.14 out of 5 | $442 | 305,819 |
| Transmission Main | 4925 | | EG | Frenchtown Rd. | 16 | Ductile Iron | 27 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4926 | | EG | Frenchtown Rd. | 16 | Ductile Iron | 5 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4927 | | EG | Frenchtown Rd. | 16 | Ductile Iron | 8 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4985 | | EG | Frenchtown Rd. | 16 | PVC | 471 | 32 | 0.43 out of 5 | $442 | 208,032 |
| Transmission Main | 4986 | P-4855 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 336 | 55 | 1.14 out of 5 | $442 | 148,427 |
| Transmission Main | 4987 | P-4855 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 511 | 55 | 1.14 out of 5 | $442 | 226,013 |
| Transmission Main | 5278 | P-4001 | EG | Frenchtown Rd. | 16 | Ductile Iron | 369 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5281 | P-4001 | EG | Frenchtown Rd. | 16 | Ductile Iron | 975 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5282 | P-4001 | EG | Frenchtown Rd. | 16 | Ductile Iron | 39 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5283 | P-4001 | EG | Frenchtown Rd. | 16 | Ductile Iron | 3 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5284 | P-4001 | EG | Frenchtown Rd. | 16 | Ductile Iron | 699 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5670 | P-4105 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 252 | 55 | 1.14 out of 5 | $442 | 111,294 |
| Transmission Main | 5706 | P-4113 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 446 | 49 | 1.14 out of 5 | $442 | 197,017 |
| Transmission Main | 5707 | P-4113 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 203 | 49 | 1.14 out of 5 | $442 | 89,808 |
| Transmission Main | 5708 | P-4722 | EG | Frenchtown Rd. | 20 | Asbestos Cement | 103 | 49 | 1.14 out of 5 | $442 | 45,399 |
| Transmission Main | 5709 | P-4722 | EG | Frenchtown Rd. | 20 | Asbestos Cement | 314 | 49 | 1.14 out of 5 | $442 | 138,810 |
| Transmission Main | 5719 | P-4371 | EG | Frenchtown Rd. | 16 | Ductile Iron | 472 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5720 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 218 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5721 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 346 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5722 | P-4731 | EG | Frenchtown Rd. | 12 | Ductile Iron | 6 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5723 | P-40019 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 339 | 55 | 1.14 out of 5 | $442 | 149,654 |
| Transmission Main | 5799 | P-4075 | EG | Frenchtown Rd. | 20 | Asbestos Cement | 723 | 49 | 1.14 out of 5 | $442 | 319,780 |
| Transmission Main | 5800 | P-4075 | EG | Frenchtown Rd. | 20 | Asbestos Cement | 833 | 49 | 1.14 out of 5 | $442 | 368,097 |
| Transmission Main | 5801 | P-4721 | EG | Frenchtown Rd. | 20 | Asbestos Cement | 99 | 49 | 1.14 out of 5 | $442 | 43,850 |
| Transmission Main | 5802 | P-4721 | EG | Frenchtown Rd. | 20 | Asbestos Cement | 845 | 49 | 1.14 out of 5 | $442 | 373,551 |
| Transmission Main | 5873 | P-4114 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 45 | 55 | 1.14 out of 5 | $442 | 19,861 |
| Transmission Main | 5874 | P-4114 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 940 | 55 | 1.14 out of 5 | $442 | 415,475 |
| Transmission Main | 5880 | P-4859 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 97 | 55 | 1.14 out of 5 | $442 | 42,980 |
| Transmission Main | 5881 | P-4859 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 1,029 | 55 | 1.14 out of 5 | $442 | 454,851 |
| Transmission Main | 5888 | P-4114 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 8 | 55 | 1.14 out of 5 | $442 | 3,644 |
| Transmission Main | 6360 | P-4003 | EG | Frenchtown Rd. | 16 | Asbestos Cement | 10 | 49 | 1.14 out of 5 | $442 | 4,395 |
| Transmission Main | 6361 | P-4003 | EG | Frenchtown Rd. | 16 | Asbestos Cement | 745 | 49 | 1.14 out of 5 | $442 | 329,499 |
| Transmission Main | 6362 | | EG | Frenchtown Rd. | 16 | Ductile Iron | 2 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6366 | P-4002 | EG | Frenchtown Rd. | 16 | Asbestos Cement | 437 | 49 | 1.14 out of 5 | $442 | 193,254 |
| Transmission Main | 6691 | P-4104 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 7 | 55 | 1.14 out of 5 | $442 | 2,989 |
| Transmission Main | 6692 | P-4104 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 407 | 55 | 1.14 out of 5 | $442 | 180,062 |
| Transmission Main | 9060 | P-40005 | EG | Frenchtown Rd. | 20 | Asbestos Cement | 38 | 49 | 1.14 out of 5 | $442 | 16,862 |
| Transmission Main | 9061 | P-40005 | EG | Frenchtown Rd. | 20 | Asbestos Cement | 408 | 49 | 1.14 out of 5 | $442 | 180,152 |
| Transmission Main | 9063 | P-4075 | EG | Frenchtown Rd. | 20 | Asbestos Cement | 37 | 49 | 1.14 out of 5 | $442 | 16,532 |
| Transmission Main | 10432 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 428 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 10433 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 344 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 10434 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 84 | 22 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 10435 | P-4731 | EG | Frenchtown Rd. | 16 | Ductile Iron | 220 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11152 | P-4728 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 64 | 55 | 1.14 out of 5 | $442 | 28,354 |
| Transmission Main | 11207 | P-4060 | EG | Frenchtown Rd. | 16 | Asbestos Cement | 11 | 49 | 1.14 out of 5 | $442 | 4,723 |
| Transmission Main | 11208 | P-4063 | EG | Frenchtown Rd. | 12 | Ductile Iron | 5 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11209 | P-40005 | EG | Frenchtown Rd. | 20 | Asbestos Cement | 11 | 49 | 1.14 out of 5 | $442 | 4,810 |
| Transmission Main | 11246 | P-4730 | EG | Frenchtown Rd. | 16 | Ductile Iron | 48 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11314 | P-4721 | EG | Frenchtown Rd. | 20 | Asbestos Cement | 35 | 49 | 1.14 out of 5 | $442 | 15,518 |
| Transmission Main | 11315 | P-4721 | EG | Frenchtown Rd. | 20 | Asbestos Cement | 7 | 49 | 1.14 out of 5 | $442 | 3,047 |
| Transmission Main | 11828 | P-4721 | EG | Frenchtown Rd. | 20 | Asbestos Cement | 532 | 49 | 1.14 out of 5 | $442 | 235,131 |
| Transmission Main | 11873 | P-4728 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 237 | 55 | 1.14 out of 5 | $442 | 104,730 |
| Transmission Main | 11874 | P-4728 | EG | Frenchtown Rd. | 12 | Asbestos Cement | 292 | 55 | 1.14 out of 5 | $442 | 129,060 |
| Transmission Main | 4357 | | EG | Frenchtown Road Tank Ease | 16 | Asbestos Cement | 5 | 49 | 1.14 out of 5 | $442 | 2,170 |
| Transmission Main | 4358 | P-4059 | EG | Frenchtown Road Tank Ease | 12 | Ductile Iron | 754 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4359 | P-4058 | EG | Frenchtown Road Tank Ease | 12 | Ductile Iron | 9 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4364 | P-4059 | EG | Frenchtown Road Tank Ease | 12 | Ductile Iron | 13 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5045 | P-4066 | EG | Frenchtown Road Tank Ease | 16 | Asbestos Cement | 7 | 49 | 1.14 out of 5 | $442 | 2,915 |
| Transmission Main | 5046 | P-4066 | EG | Frenchtown Road Tank Ease | 16 | Asbestos Cement | 22 | 49 | 1.14 out of 5 | $442 | 9,801 |
| Transmission Main | 5793 | P-4066 | EG | Frenchtown Road Tank Ease | 16 | Asbestos Cement | 5 | 49 | 1.14 out of 5 | $442 | 2,152 |
| Transmission Main | 5794 | P-4066 | EG | Frenchtown Road Tank Ease | 16 | Asbestos Cement | 7 | 49 | 1.14 out of 5 | $442 | 3,056 |
| Distribution Main | 5795 | P-4066 | EG | Frenchtown Road Tank Ease | 8 | Ductile Iron | 12 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5797 | P-4064 | EG | Frenchtown Road Tank Ease | 20 | Asbestos Cement | 650 | 49 | 1.14 out of 5 | $442 | 287,283 |
| Transmission Main | 5798 | P-4064 | EG | Frenchtown Road Tank Ease | 20 | Asbestos Cement | 77 | 49 | 1.14 out of 5 | $442 | 34,145 |
| Transmission Main | 6586 | P-4059 | EG | Frenchtown Road Tank Ease | 20 | Asbestos Cement | 8 | 49 | 1.14 out of 5 | $442 | 3,555 |
| Distribution Main | 6773 | P-4066 | EG | Frenchtown Road Tank Ease | 8 | Ductile Iron | 24 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6774 | P-4066 | EG | Frenchtown Road Tank Ease | 16 | Asbestos Cement | 31 | 49 | 1.14 out of 5 | $442 | 13,559 |
| Transmission Main | 10345 | P-4065 | EG | Frenchtown Road Tank Ease | 12 | Ductile Iron | 5 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4053 | P-4414 | EG | Friendly Rd. | 6 | Ductile Iron | 55 | 31 | 0.85 out of 5 | $442 | 24,458 |
| Distribution Main | 4054 | P-4414 | EG | Friendly Rd. | 6 | Ductile Iron | 645 | 31 | 0.85 out of 5 | $442 | 284,933 |
| Distribution Main | 6411 | P-4377 | EG | Friendly Rd. | 6 | Ductile Iron | 460 | 31 | 0.85 out of 5 | $442 | 203,477 |
| Distribution Main | 1897 | P-4577 | EG | Friendship St. | 6 | Asbestos Cement | 28 | 69 | 2 out of 5 | $442 | 12,333 |
| Distribution Main | 1898 | P-4577 | EG | Friendship St. | 6 | Asbestos Cement | 220 | 69 | 2 out of 5 | $442 | 97,330 |
| Transmission Main | 5416 | P-4592 | EG | Friendship St. | 12 | Ductile Iron | 260 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6226 | P-4579 | EG | Friendship St. | 4 | Cast Iron | 14 | 133 | 3.29 out of 5 | $442 | 6,045 |
| Distribution Main | 6227 | P-4579 | EG | Friendship St. | 4 | Cast Iron | 221 | 133 | 3.29 out of 5 | $442 | 97,564 |
| Transmission Main | 6716 | P-4947 | EG | Friendship St. | 12 | Ductile Iron | 252 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9890 | | EG | Fry Brook Dr | 8 | Ductile Iron | 1 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5625 | P-4460 | EG | Gladridge Dr. | 6 | Asbestos Cement | 174 | 61 | 2 out of 5 | $442 | 76,766 |
| Distribution Main | 5626 | P-4460 | EG | Gladridge Dr. | 6 | Asbestos Cement | 196 | 61 | 2 out of 5 | $442 | 86,845 |
| Distribution Main | 3840 | P-40027 | EG | Glenn Dr. | 8 | Ductile Iron | 23 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3841 | P-4396 | EG | Glenn Dr. | 6 | Asbestos Cement | 12 | 59 | 1.85 out of 5 | $442 | 5,108 |
| Distribution Main | 3842 | P-4396 | EG | Glenn Dr. | 6 | Asbestos Cement | 114 | 59 | 1.85 out of 5 | $442 | 50,422 |
| Distribution Main | 6409 | P-4396 | EG | Glenn Dr. | 6 | Asbestos Cement | 1,037 | 59 | 1.85 out of 5 | $442 | 458,448 |
| Distribution Main | 4035 | P-4365 | EG | Gould Pl. | 6 | Asbestos Cement | 56 | 61 | 2 out of 5 | $442 | 24,611 |
| Distribution Main | 4036 | P-4365 | EG | Gould Pl. | 6 | Asbestos Cement | 679 | 61 | 2 out of 5 | $442 | 300,210 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3298 | P-4723 | EG | Graham Way | 8 | Ductile Iron | 314 | 30 | 0.14 out of 5 | $442 | 138,650 |
| Distribution Main | 3299 | P-4723 | EG | Graham Way | 8 | Ductile Iron | 525 | 30 | 0.14 out of 5 | $442 | 231,858 |
| Distribution Main | 5863 | P-4725 | EG | Graham Way | 8 | Ductile Iron | 115 | 30 | 0.14 out of 5 | $442 | 50,904 |
| Distribution Main | 5866 | P-4725 | EG | Graham Way | 8 | Ductile Iron | 211 | 30 | 0.14 out of 5 | $442 | 93,181 |
| Distribution Main | 5867 | P-4725 | EG | Graham Way | 8 | Ductile Iron | 181 | 30 | 0.14 out of 5 | $442 | 79,950 |
| Distribution Main | 3846 | P-4316 | EG | Grandview Road | 6 | Asbestos Cement | 573 | 51 | 1.85 out of 5 | $442 | 253,387 |
| Distribution Main | 3847 | P-4316 | EG | Grandview Road | 6 | Asbestos Cement | 36 | 51 | 1.85 out of 5 | $442 | 15,752 |
| Distribution Main | 3848 | P-4317 | EG | Grandview Road | 6 | Asbestos Cement | 377 | 51 | 1.85 out of 5 | $442 | 166,769 |
| Distribution Main | 4889 | P-4402 | EG | Grandview Road | 6 | Asbestos Cement | 252 | 51 | 1.85 out of 5 | $442 | 111,409 |
| Distribution Main | 4890 | P-4274 | EG | Grandview Road | 6 | Asbestos Cement | 188 | 51 | 1.85 out of 5 | $442 | 82,957 |
| Distribution Main | 4895 | P-4260 | EG | Grandview Road | 6 | Asbestos Cement | 431 | 51 | 1.85 out of 5 | $442 | 190,361 |
| Distribution Main | 4899 | P-4316 | EG | Grandview Road | 6 | Asbestos Cement | 121 | 51 | 1.85 out of 5 | $442 | 53,458 |
| Distribution Main | 5612 | P-4268 | EG | Grandview Road | 6 | Asbestos Cement | 629 | 58 | 1.85 out of 5 | $442 | 278,192 |
| Distribution Main | 5613 | P-4288 | EG | Grandview Road | 6 | Asbestos Cement | 270 | 58 | 1.85 out of 5 | $442 | 119,261 |
| Distribution Main | 5614 | P-4288 | EG | Grandview Road | 6 | Asbestos Cement | 440 | 51 | 1.85 out of 5 | $442 | 194,632 |
| Distribution Main | 6464 | P-4403 | EG | Grandview Road | 6 | Asbestos Cement | 104 | 51 | 1.85 out of 5 | $442 | 45,969 |
| Distribution Main | 10233 | P-4274 | EG | Grandview Road | 6 | Asbestos Cement | 138 | 51 | 1.85 out of 5 | $442 | 61,100 |
| Distribution Main | 968 | P-4129 | EG | Granite Dr. | 6 | Asbestos Cement | 516 | 44 | 1.85 out of 5 | $442 | 227,949 |
| Distribution Main | 969 | P-4129 | EG | Granite Dr. | 6 | Asbestos Cement | 282 | 44 | 1.85 out of 5 | $442 | 124,809 |
| Distribution Main | 3463 | P-4127 | EG | Granite Dr. | 6 | Asbestos Cement | 399 | 44 | 1.85 out of 5 | $442 | 176,247 |
| Distribution Main | 6024 | P-4127 | EG | Granite Dr. | 6 | Asbestos Cement | 13 | 44 | 1.85 out of 5 | $442 | 5,906 |
| Distribution Main | 2906 | P-4375 | EG | Grassland Road | 6 | Ductile Iron | 241 | 31 | 0.85 out of 5 | $442 | 106,636 |
| Distribution Main | 2907 | P-4375 | EG | Grassland Road | 6 | Ductile Iron | 19 | 31 | 0.85 out of 5 | $442 | 8,465 |
| Distribution Main | 2478 | P-4436 | EG | Grasslands Rd | 8 | Cast Iron | 6 | 82 | 1.72 out of 5 | $442 | 2,613 |
| Distribution Main | 6491 | P-40029 | EG | Grasslands Rd | 8 | Cast Iron | 111 | 82 | 1.72 out of 5 | $442 | 49,128 |
| Distribution Main | 6492 | P-40029 | EG | Grasslands Rd | 8 | Cast Iron | 3 | 82 | 1.72 out of 5 | $442 | 1,342 |
| Distribution Main | 6374 | P-4391 | EG | Great Rd. | 8 | Asbestos Cement | 813 | 50 | 1.14 out of 5 | $442 | 359,132 |
| Distribution Main | 2511 | P-4989 | EG | Great Road | 8 | Ductile Iron | 627 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2512 | P-4989 | EG | Great Road | 8 | Ductile Iron | 329 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11175 | P-4989 | EG | Great Road | 8 | Ductile Iron | 37 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6325 | P-4464 | EG | Green Bush Rd. | 8 | Ductile Iron | 9 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6326 | P-4464 | EG | Green Bush Rd. | 12 | Ductile Iron | 13 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9497 | P-4464 | EG | Green Bush Rd. | 8 | Ductile Iron | 31 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9498 | P-4464 | EG | Green Bush Rd. | 8 | Ductile Iron | 38 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9136 | | EG | Greene St | 4 | Ductile Iron | 19 | 9 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 4256 | P-4599 | EG | Greene St. | 8 | Ductile Iron | 26 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6241 | P-4600 | EG | Greene St. | 8 | Ductile Iron | 565 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6242 | P-4600 | EG | Greene St. | 8 | Ductile Iron | 37 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6244 | P-4599 | EG | Greene St. | 8 | Ductile Iron | 313 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12089 | P-4600 | EG | Greene St. | 8 | Ductile Iron | 56 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12090 | P-4600 | EG | Greene St. | 8 | Ductile Iron | 27 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3941 | | EG | Greenwich Blvd | 2 | Unknown | 56 | 41 | 1.71 out of 5 | $442 | 24,640 |
| Distribution Main | 6255 | | EG | Greenwich Blvd | 2 | Unknown | 5 | 41 | 1.71 out of 5 | $442 | 2,018 |
| Distribution Main | 9475 | P-40037 | EG | Greenwich Blvd | 1.5 | Galvanized Iron | 397 | 41 | 3.14 out of 5 | $442 | 175,628 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 908 | P-4483 | EG | Greenwich Blvd. | 2 | PVC | 433 | 49 | 2 out of 5 | $442 | 191,224 |
| Distribution Main | 3943 | P-4410 | EG | Greenwich Blvd. | 2 | PVC | 151 | 41 | 2 out of 5 | $442 | 66,619 |
| Distribution Main | 6261 | P-4410 | EG | Greenwich Blvd. | 2 | PVC | 25 | 41 | 2 out of 5 | $442 | 11,227 |
| Distribution Main | 6059 | P-4266 | EG | Hamilton Dr. | 6 | Asbestos Cement | 805 | 51 | 1.85 out of 5 | $442 | 355,714 |
| Distribution Main | 6060 | P-4266 | EG | Hamilton Dr. | 6 | Asbestos Cement | 900 | 51 | 1.85 out of 5 | $442 | 397,671 |
| Distribution Main | 11830 | P-4266 | EG | Hamilton Dr. | 6 | Asbestos Cement | 341 | 51 | 1.85 out of 5 | $442 | 150,801 |
| Distribution Main | 4992 | P-4364 | EG | Hanaford Dr. | 6 | Asbestos Cement | 199 | 51 | 1.85 out of 5 | $442 | 88,032 |
| Distribution Main | 4993 | P-4364 | EG | Hanaford Dr. | 6 | Asbestos Cement | 7 | 51 | 1.85 out of 5 | $442 | 2,919 |
| Distribution Main | 4994 | P-4366 | EG | Hanaford Dr. | 6 | Asbestos Cement | 876 | 51 | 1.85 out of 5 | $442 | 387,218 |
| Distribution Main | 6394 | P-4363 | EG | Hanaford Dr. | 6 | Asbestos Cement | 453 | 51 | 1.85 out of 5 | $442 | 200,358 |
| Distribution Main | 6029 | P-4356 | EG | Hanaford Drive | 6 | Asbestos Cement | 505 | 50 | 1.85 out of 5 | $442 | 223,247 |
| Distribution Main | 3214 | P-4235 | EG | Harwood Rd. | 6 | Cast Iron | 638 | 87 | 2.43 out of 5 | $442 | 281,860 |
| Distribution Main | 3215 | P-4235 | EG | Harwood Rd. | 6 | Cast Iron | 450 | 87 | 2.43 out of 5 | $442 | 198,736 |
| Distribution Main | 4024 | P-4458 | EG | Hemlock Dr. | 8 | Asbestos Cement | 850 | 50 | 1.14 out of 5 | $442 | 375,659 |
| Distribution Main | 4025 | P-4458 | EG | Hemlock Dr. | 8 | Asbestos Cement | 38 | 50 | 1.14 out of 5 | $442 | 16,667 |
| Distribution Main | 4028 | P-4458 | EG | Hemlock Dr. | 8 | Asbestos Cement | 49 | 50 | 1.14 out of 5 | $442 | 21,852 |
| Distribution Main | 4029 | P-4449 | EG | Hemlock Dr. | 8 | Asbestos Cement | 57 | 50 | 1.14 out of 5 | $442 | 25,338 |
| Distribution Main | 4152 | | EG | Hemlock Dr. | 8 | Asbestos Cement | 34 | 50 | 1.14 out of 5 | $442 | 15,182 |
| Distribution Main | 5623 | P-4447 | EG | Hemlock Dr. | 8 | Asbestos Cement | 36 | 50 | 1.14 out of 5 | $442 | 15,936 |
| Distribution Main | 5627 | P-4458 | EG | Hemlock Dr. | 6 | Asbestos Cement | 58 | 50 | 1.85 out of 5 | $442 | 25,570 |
| Distribution Main | 5958 | P-4449 | EG | Hemlock Dr. | 8 | Asbestos Cement | 716 | 50 | 1.14 out of 5 | $442 | 316,586 |
| Distribution Main | 6191 | P-4447 | EG | Hemlock Dr. | 8 | Asbestos Cement | 212 | 50 | 1.14 out of 5 | $442 | 93,912 |
| Distribution Main | 6192 | P-4447 | EG | Hemlock Dr. | 8 | Asbestos Cement | 188 | 50 | 1.14 out of 5 | $442 | 83,234 |
| Distribution Main | 11768 | P-4458 | EG | Hemlock Dr. | 8 | Asbestos Cement | 536 | 50 | 1.14 out of 5 | $442 | 237,008 |
| Distribution Main | 4903 | P-4299 | EG | Hickory Dr. | 8 | Asbestos Cement | 67 | 51 | 1.14 out of 5 | $442 | 29,523 |
| Distribution Main | 4904 | P-4300 | EG | Hickory Dr. | 8 | Asbestos Cement | 270 | 51 | 1.14 out of 5 | $442 | 119,351 |
| Distribution Main | 4905 | P-4295 | EG | Hickory Dr. | 8 | Asbestos Cement | 261 | 51 | 1.14 out of 5 | $442 | 115,312 |
| Distribution Main | 4906 | P-4295 | EG | Hickory Dr. | 8 | Asbestos Cement | 134 | 51 | 1.14 out of 5 | $442 | 59,276 |
| Distribution Main | 8317 | P-4809 | EG | Hidden Lane | 8 | Ductile Iron | 716 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8318 | P-4809 | EG | Hidden Lane | 8 | Ductile Iron | 15 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10106 | P-4811 | EG | Hidden Lane | 8 | Ductile Iron | 398 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11460 | P-4809 | EG | Hidden Lane | 8 | Ductile Iron | 170 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 855 | P-4050 | EG | High Hawk Rd. | 8 | Asbestos Cement | 511 | 49 | 1.14 out of 5 | $442 | 225,793 |
| Distribution Main | 856 | P-4046 | EG | High Hawk Rd. | 8 | Asbestos Cement | 9 | 49 | 1.14 out of 5 | $442 | 3,838 |
| Distribution Main | 4365 | P-40004 | EG | High Hawk Rd. | 8 | Asbestos Cement | 38 | 49 | 1.14 out of 5 | $442 | 16,917 |
| Distribution Main | 5043 | P-4052 | EG | High Hawk Rd. | 8 | Asbestos Cement | 77 | 49 | 1.14 out of 5 | $442 | 34,048 |
| Distribution Main | 5044 | P-4052 | EG | High Hawk Rd. | 8 | Asbestos Cement | 366 | 49 | 1.14 out of 5 | $442 | 161,750 |
| Transmission Main | 5811 | P-4023 | EG | High Hawk Rd. | 12 | PVC | 307 | 33 | 0.43 out of 5 | $442 | 135,837 |
| Transmission Main | 5812 | P-4023 | EG | High Hawk Rd. | 12 | PVC | 18 | 33 | 0.43 out of 5 | $442 | 8,036 |
| Transmission Main | 5813 | P-4019 | EG | High Hawk Rd. | 12 | PVC | 366 | 33 | 0.43 out of 5 | $442 | 161,930 |
| Distribution Main | 5837 | P-4053 | EG | High Hawk Rd. | 8 | Asbestos Cement | 989 | 49 | 1.14 out of 5 | $442 | 437,286 |
| Transmission Main | 5838 | P-4040 | EG | High Hawk Rd. | 12 | PVC | 712 | 33 | 0.43 out of 5 | $442 | 314,808 |
| Transmission Main | 5839 | P-4040 | EG | High Hawk Rd. | 12 | PVC | 13 | 33 | 0.43 out of 5 | $442 | 5,606 |
| Distribution Main | 5858 | P-4042 | EG | High Hawk Rd. | 8 | Asbestos Cement | 493 | 49 | 1.14 out of 5 | $442 | 217,831 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 5859 | P-4042 | EG | High Hawk Rd. | 8 | Asbestos Cement | 884 | 49 | 1.14 out of 5 | $442 | 390,899 |
| Transmission Main | 5917 | P-4029 | EG | High Hawk Rd. | 12 | PVC | 213 | 33 | 0.43 out of 5 | $442 | 94,281 |
| Transmission Main | 6292 | P-4018 | EG | High Hawk Rd. | 12 | PVC | 283 | 33 | 0.43 out of 5 | $442 | 124,916 |
| Transmission Main | 6293 | P-4018 | EG | High Hawk Rd. | 12 | PVC | 200 | 33 | 0.43 out of 5 | $442 | 88,253 |
| Distribution Main | 6587 | P-4053 | EG | High Hawk Rd. | 8 | Asbestos Cement | 943 | 49 | 1.14 out of 5 | $442 | 416,811 |
| Distribution Main | 6592 | P-4046 | EG | High Hawk Rd. | 8 | Asbestos Cement | 135 | 49 | 1.14 out of 5 | $442 | 59,604 |
| Distribution Main | 6777 | P-4042 | EG | High Hawk Rd. | 8 | Asbestos Cement | 56 | 49 | 1.14 out of 5 | $442 | 24,872 |
| Distribution Main | 12085 | P-4042 | EG | High Hawk Rd. | 8 | Asbestos Cement | 24 | 49 | 1.14 out of 5 | $442 | 10,801 |
| Distribution Main | 6006 | P-4995 | EG | Hill Dr | 6 | Ductile Iron | 527 | 27 | 0.85 out of 5 | $442 | 233,126 |
| Distribution Main | 6008 | P-4995 | EG | Hill Dr | 6 | Ductile Iron | 6 | 27 | 0.85 out of 5 | $442 | 2,727 |
| Distribution Main | 5244 | P-4217 | EG | Holly Hill Ct. | 6 | Asbestos Cement | 155 | 51 | 1.85 out of 5 | $442 | 68,314 |
| Distribution Main | 5474 | P-4500 | EG | Howland Farms | 8 | Ductile Iron | 467 | 29 | 0.14 out of 5 | $442 | 206,579 |
| Distribution Main | 5475 | P-4500 | EG | Howland Farms | 8 | Ductile Iron | 1,331 | 29 | 0.14 out of 5 | $442 | 588,278 |
| Distribution Main | 11824 | P-4500 | EG | Howland Farms | 8 | Ductile Iron | 46 | 29 | 0.14 out of 5 | $442 | 20,406 |
| Distribution Main | 374 | P-4373 | EG | Howland Rd. | 8 | Asbestos Cement | 48 | 57 | 1.14 out of 5 | $442 | 21,297 |
| Distribution Main | 3837 | P-4382 | EG | Howland Rd. | 8 | Ductile Iron | 296 | 42 | 0.29 out of 5 | $442 | 130,888 |
| Distribution Main | 4995 | P-4978 | EG | Howland Rd. | 8 | Asbestos Cement | 148 | 57 | 1.14 out of 5 | $442 | 65,605 |
| Distribution Main | 5962 | P-4454 | EG | Howland Rd. | 8 | Asbestos Cement | 299 | 57 | 1.14 out of 5 | $442 | 132,136 |
| Distribution Main | 5963 | P-4488 | EG | Howland Rd. | 8 | Asbestos Cement | 559 | 57 | 1.14 out of 5 | $442 | 247,171 |
| Distribution Main | 6186 | P-4373 | EG | Howland Rd. | 8 | Asbestos Cement | 847 | 57 | 1.14 out of 5 | $442 | 374,396 |
| Distribution Main | 6187 | P-4373 | EG | Howland Rd. | 8 | Asbestos Cement | 1,094 | 57 | 1.14 out of 5 | $442 | 483,686 |
| Distribution Main | 6190 | P-4487 | EG | Howland Rd. | 8 | Asbestos Cement | 170 | 57 | 1.14 out of 5 | $442 | 75,196 |
| Distribution Main | 6399 | P-4376 | EG | Howland Rd. | 8 | Ductile Iron | 107 | 42 | 0.29 out of 5 | $442 | 47,223 |
| Distribution Main | 6400 | P-4376 | EG | Howland Rd. | 8 | Ductile Iron | 241 | 42 | 0.29 out of 5 | $442 | 106,629 |
| Distribution Main | 6401 | P-4381 | EG | Howland Rd. | 8 | Ductile Iron | 468 | 42 | 0.29 out of 5 | $442 | 207,002 |
| Distribution Main | 6402 | P-4382 | EG | Howland Rd. | 8 | Ductile Iron | 21 | 42 | 0.29 out of 5 | $442 | 9,111 |
| Distribution Main | 6568 | P-4978 | EG | Howland Rd. | 8 | Asbestos Cement | 453 | 57 | 1.14 out of 5 | $442 | 200,343 |
| Distribution Main | 6569 | P-4978 | EG | Howland Rd. | 8 | Asbestos Cement | 605 | 57 | 1.14 out of 5 | $442 | 267,347 |
| Distribution Main | 5668 | P-4106 | EG | Hugenot Dr. | 8 | Asbestos Cement | 36 | 43 | 1.14 out of 5 | $442 | 16,024 |
| Distribution Main | 5669 | P-4106 | EG | Hugenot Dr. | 8 | Asbestos Cement | 548 | 43 | 1.14 out of 5 | $442 | 242,377 |
| Distribution Main | 6699 | P-4107 | EG | Hugenot Dr. | 8 | Asbestos Cement | 300 | 44 | 1.14 out of 5 | $442 | 132,445 |
| Distribution Main | 6700 | P-4107 | EG | Hugenot Dr. | 8 | Asbestos Cement | 257 | 44 | 1.14 out of 5 | $442 | 113,527 |
| Distribution Main | 5879 | P-4100 | EG | Huling Ln. | 8 | Ductile Iron | 15 | 35 | 0.14 out of 5 | $442 | 6,478 |
| Distribution Main | 6693 | P-4099 | EG | Huling Ln. | 8 | Ductile Iron | 375 | 35 | 0.14 out of 5 | $442 | 165,932 |
| Distribution Main | 6694 | P-4099 | EG | Huling Ln. | 8 | Ductile Iron | 80 | 35 | 0.14 out of 5 | $442 | 35,578 |
| Distribution Main | 6695 | P-4100 | EG | Huling Ln. | 8 | Ductile Iron | 596 | 35 | 0.14 out of 5 | $442 | 263,273 |
| Transmission Main | 5276 | P-4008 | EG | Hunters Crossing Rd. | 12 | Ductile Iron | 69 | 30 | 0.14 out of 5 | $442 | 30,536 |
| Transmission Main | 5277 | P-4008 | EG | Hunters Crossing Rd. | 12 | Ductile Iron | 475 | 30 | 0.14 out of 5 | $442 | 209,907 |
| Transmission Main | 11845 | P-4008 | EG | Hunters Crossing Rd. | 12 | Ductile Iron | 277 | 30 | 0.14 out of 5 | $442 | 122,628 |
| Distribution Main | 9472 | P-4977 | EG | Hutchins Court | 1.5 | Copper | 256 | 67 | 2.43 out of 5 | $442 | 113,030 |
| Distribution Main | 300 | P-4679 | EG | Hyland Ave. | 8 | Ductile Iron | 26 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1235 | P-4679 | EG | Hyland Ave. | 8 | Ductile Iron | 105 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1236 | P-4679 | EG | Hyland Ave. | 8 | Ductile Iron | 483 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1237 | P-4543 | EG | Hyland Ave. | 8 | Ductile Iron | 185 | 17 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6152 | P-4471 | EG | Ivy Guarded Way | 6 | Ductile Iron | 47 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 6153 | P-4471 | EG | Ivy Guarded Way | 6 | Ductile Iron | 195 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 3924 | P-4251 | EG | Jefferson Dr. | 8 | Asbestos Cement | 915 | 51 | 1.14 out of 5 | $442 | 404,651 |
| Distribution Main | 3925 | P-4251 | EG | Jefferson Dr. | 8 | Asbestos Cement | 700 | 51 | 1.14 out of 5 | $442 | 309,320 |
| Distribution Main | 11826 | P-4251 | EG | Jefferson Dr. | 8 | Asbestos Cement | 144 | 51 | 1.14 out of 5 | $442 | 63,820 |
| Distribution Main | 5671 | P-4111 | EG | Jodie Beth Cir. | 8 | Ductile Iron | 18 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5862 | P-4111 | EG | Jodie Beth Cir. | 8 | Ductile Iron | 6 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5864 | P-4111 | EG | Jodie Beth Cir. | 8 | Ductile Iron | 463 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5865 | P-4111 | EG | Jodie Beth Cir. | 8 | Ductile Iron | 218 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5868 | P-4111 | EG | Jodie Beth Cir. | 8 | Ductile Iron | 6 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5882 | P-4109 | EG | Jodie Beth Cir. | 8 | Asbestos Cement | 798 | 46 | 1.14 out of 5 | $442 | 352,573 |
| Distribution Main | 5883 | P-4109 | EG | Jodie Beth Cir. | 8 | Asbestos Cement | 572 | 46 | 1.14 out of 5 | $442 | 252,868 |
| Distribution Main | 6697 | P-4109 | EG | Jodie Beth Cir. | 8 | Asbestos Cement | 22 | 46 | 1.14 out of 5 | $442 | 9,881 |
| Distribution Main | 5951 | P-4386 | EG | John Alden Rd. | 6 | Asbestos Cement | 253 | 49 | 1.85 out of 5 | $442 | 111,747 |
| Distribution Main | 8820 | P-4826 | EG | Judge Torres Ln | 8 | Ductile Iron | 573 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8821 | P-4826 | EG | Judge Torres Ln | 8 | Ductile Iron | 99 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11515 | P-4826 | EG | Judge Torres Ln | 8 | Ductile Iron | 356 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11854 | P-4826 | EG | Judge Torres Ln | 8 | Ductile Iron | 27 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3302 | P-4006 | EG | Juniper Drive | 12 | Ductile Iron | 8 | 30 | 0.14 out of 5 | $442 | 3,546 |
| Transmission Main | 3461 | P-4011 | EG | Juniper Drive | 12 | Ductile Iron | 14 | 27 | 0.14 out of 5 | $442 | 6,075 |
| Transmission Main | 4587 | P-4006 | EG | Juniper Drive | 12 | Ductile Iron | 222 | 30 | 0.14 out of 5 | $442 | 98,246 |
| Transmission Main | 4588 | P-4006 | EG | Juniper Drive | 12 | Ductile Iron | 489 | 30 | 0.14 out of 5 | $442 | 216,118 |
| Distribution Main | 5267 | P-4013 | EG | Juniper Drive | 8 | Ductile Iron | 321 | 27 | 0.14 out of 5 | $442 | 141,838 |
| Transmission Main | 5268 | P-4009 | EG | Juniper Drive | 12 | Ductile Iron | 415 | 27 | 0.14 out of 5 | $442 | 183,530 |
| Transmission Main | 5269 | P-4009 | EG | Juniper Drive | 12 | Ductile Iron | 5 | 27 | 0.14 out of 5 | $442 | 2,201 |
| Transmission Main | 5272 | P-4011 | EG | Juniper Drive | 12 | Ductile Iron | 166 | 27 | 0.14 out of 5 | $442 | 73,590 |
| Transmission Main | 5273 | P-4011 | EG | Juniper Drive | 12 | Ductile Iron | 210 | 27 | 0.14 out of 5 | $442 | 92,615 |
| Transmission Main | 5274 | P-4009 | EG | Juniper Drive | 12 | Ductile Iron | 61 | 27 | 0.14 out of 5 | $442 | 26,799 |
| Transmission Main | 5275 | P-4009 | EG | Juniper Drive | 12 | Ductile Iron | 365 | 27 | 0.14 out of 5 | $442 | 161,184 |
| Transmission Main | 1233 | P-4007 | EG | Juniper Rd. | 12 | Ductile Iron | 135 | 30 | 0.14 out of 5 | $442 | 59,794 |
| Transmission Main | 1234 | P-4007 | EG | Juniper Rd. | 12 | Ductile Iron | 403 | 30 | 0.14 out of 5 | $442 | 178,010 |
| Distribution Main | 4182 | P-4976 | EG | Kenson Dr. | 6 | Asbestos Cement | 514 | 69 | 2 out of 5 | $442 | 227,179 |
| Distribution Main | 4183 | P-4976 | EG | Kenson Dr. | 6 | Asbestos Cement | 59 | 69 | 2 out of 5 | $442 | 25,985 |
| Distribution Main | 12184 | | EG | Kenson Dr. | 6 | Asbestos Cement | 483 | 69 | 2 out of 5 | $442 | 213,488 |
| Distribution Main | 454 | P-4389 | EG | Kent Dr. | 8 | Asbestos Cement | 830 | 51 | 1.14 out of 5 | $442 | 367,056 |
| Distribution Main | 457 | P-4387 | EG | Kent Dr. | 8 | Asbestos Cement | 49 | 51 | 1.14 out of 5 | $442 | 21,772 |
| Distribution Main | 2508 | P-4390 | EG | Kent Dr. | 8 | Asbestos Cement | 423 | 51 | 1.14 out of 5 | $442 | 187,054 |
| Distribution Main | 2509 | P-4390 | EG | Kent Dr. | 8 | Asbestos Cement | 60 | 51 | 1.14 out of 5 | $442 | 26,560 |
| Distribution Main | 4037 | P-4352 | EG | Kent Dr. | 6 | Asbestos Cement | 443 | 51 | 1.85 out of 5 | $442 | 195,619 |
| Distribution Main | 4038 | P-4352 | EG | Kent Dr. | 6 | Asbestos Cement | 550 | 51 | 1.85 out of 5 | $442 | 243,301 |
| Distribution Main | 4991 | P-4361 | EG | Kent Dr. | 6 | Asbestos Cement | 10 | 51 | 1.85 out of 5 | $442 | 4,487 |
| Distribution Main | 6375 | P-4389 | EG | Kent Dr. | 8 | Asbestos Cement | 29 | 51 | 1.14 out of 5 | $442 | 12,747 |
| Distribution Main | 6377 | P-4984 | EG | Kent Dr. | 8 | Asbestos Cement | 137 | 51 | 1.14 out of 5 | $442 | 60,405 |
| Distribution Main | 6378 | P-4984 | EG | Kent Dr. | 8 | Asbestos Cement | 32 | 51 | 1.14 out of 5 | $442 | 14,258 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6396 | P-4362 | EG | Kent Dr. | 6 | Asbestos Cement | 676 | 51 | 1.85 out of 5 | $442 | 298,916 |
| Distribution Main | 6397 | P-4362 | EG | Kent Dr. | 6 | Asbestos Cement | 511 | 51 | 1.85 out of 5 | $442 | 225,765 |
| Distribution Main | 6398 | P-4361 | EG | Kent Dr. | 6 | Asbestos Cement | 330 | 51 | 1.85 out of 5 | $442 | 145,915 |
| Distribution Main | 10206 | P-4986 | EG | Kent Dr. | 8 | Asbestos Cement | 8 | 51 | 1.14 out of 5 | $442 | 3,755 |
| Distribution Main | 9350 | | EG | Kenyon Ave | 4 | Ductile Iron | 30 | 8 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 360 | P-4544 | EG | Kenyon Ave. | 6 | Cast Iron | 308 | 133 | 2.57 out of 5 | $442 | 136,040 |
| Distribution Main | 665 | P-4527 | EG | Kenyon Ave. | 8 | Asbestos Cement | 350 | 70 | 1.29 out of 5 | $442 | 154,596 |
| Distribution Main | 913 | P-4540 | EG | Kenyon Ave. | 6 | Cast Iron | 180 | 133 | 2.57 out of 5 | $442 | 79,415 |
| Distribution Main | 2394 | P-4544 | EG | Kenyon Ave. | 6 | Cast Iron | 21 | 133 | 2.57 out of 5 | $442 | 9,281 |
| Distribution Main | 3933 | P-4545 | EG | Kenyon Ave. | 6 | Cast Iron | 244 | 133 | 2.57 out of 5 | $442 | 107,709 |
| Distribution Main | 3936 | P-4549 | EG | Kenyon Ave. | 6 | Cast Iron | 36 | 133 | 2.57 out of 5 | $442 | 15,776 |
| Distribution Main | 4164 | P-4542 | EG | Kenyon Ave. | 6 | Cast Iron | 118 | 133 | 2.57 out of 5 | $442 | 52,020 |
| Distribution Main | 4165 | P-4542 | EG | Kenyon Ave. | 6 | Cast Iron | 51 | 133 | 2.57 out of 5 | $442 | 22,557 |
| Distribution Main | 4180 | P-4527 | EG | Kenyon Ave. | 8 | Asbestos Cement | 243 | 53 | 1.14 out of 5 | $442 | 107,569 |
| Distribution Main | 4184 | P-4527 | EG | Kenyon Ave. | 8 | Asbestos Cement | 292 | 70 | 1.29 out of 5 | $442 | 128,860 |
| Distribution Main | 5424 | P-4531 | EG | Kenyon Ave. | 8 | Asbestos Cement | 10 | 70 | 1.29 out of 5 | $442 | 4,636 |
| Transmission Main | 5426 | P-4234 | EG | Kenyon Ave. | 20 | Asbestos Cement | 23 | 55 | 1.14 out of 5 | $442 | 10,345 |
| Transmission Main | 5427 | P-4234 | EG | Kenyon Ave. | 20 | Asbestos Cement | 1,619 | 55 | 1.14 out of 5 | $442 | 715,813 |
| Distribution Main | 5688 | P-4975 | EG | Kenyon Ave. | 8 | Ductile Iron | 5 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5689 | P-4975 | EG | Kenyon Ave. | 8 | Ductile Iron | 18 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6199 | P-4973 | EG | Kenyon Ave. | 8 | Ductile Iron | 20 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6210 | P-4531 | EG | Kenyon Ave. | 8 | Asbestos Cement | 1,027 | 70 | 2 out of 5 | $442 | 454,069 |
| Distribution Main | 6211 | P-4531 | EG | Kenyon Ave. | 8 | Asbestos Cement | 14 | 70 | 1.29 out of 5 | $442 | 6,115 |
| Transmission Main | 6212 | P-4234 | EG | Kenyon Ave. | 20 | Asbestos Cement | 72 | 55 | 1.14 out of 5 | $442 | 32,021 |
| Transmission Main | 6213 | P-4234 | EG | Kenyon Ave. | 20 | Asbestos Cement | 35 | 55 | 1.14 out of 5 | $442 | 15,585 |
| Distribution Main | 6276 | P-4549 | EG | Kenyon Ave. | 6 | Cast Iron | 565 | 133 | 2.57 out of 5 | $442 | 249,671 |
| Distribution Main | 9448 | P-4542 | EG | Kenyon Ave. | 6 | Cast Iron | 114 | 133 | 2.57 out of 5 | $442 | 50,184 |
| Transmission Main | 9449 | P-2649 | EG | Kenyon Ave. | 20 | Asbestos Cement | 79 | 55 | 1.14 out of 5 | $442 | 34,844 |
| Transmission Main | 9450 | P-4235 | EG | Kenyon Ave. | 20 | Asbestos Cement | 712 | 55 | 1.14 out of 5 | $442 | 314,668 |
| Transmission Main | 9451 | P-4235 | EG | Kenyon Ave. | 20 | Asbestos Cement | 609 | 55 | 1.14 out of 5 | $442 | 269,366 |
| Transmission Main | 9452 | P-4235 | EG | Kenyon Ave. | 20 | Asbestos Cement | 381 | 55 | 1.14 out of 5 | $442 | 168,252 |
| Distribution Main | 11326 | P-4973 | EG | Kenyon Ave. | 8 | Ductile Iron | 16 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9238 | P-4202 | EG | King Philip Tr | 8 | Ductile Iron | 197 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9241 | P-4200 | EG | King Philip Tr | 8 | Ductile Iron | 61 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9242 | P-4200 | EG | King Philip Tr | 8 | Ductile Iron | 157 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10969 | P-40011 | EG | King Philip Tr | 8 | Ductile Iron | 97 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11561 | P-4200 | EG | King Philip Tr | 8 | Ductile Iron | 38 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6388 | P-4211 | EG | King Philip Tr. | 8 | Ductile Iron | 233 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9170 | P-4900 | EG | King St | 12 | Ductile Iron | 49 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9172 | P-4618 | EG | King St | 6 | Ductile Iron | 13 | 8 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9175 | P-4908 | EG | King St | 6 | Ductile Iron | 10 | 8 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9176 | P-4908 | EG | King St | 6 | Ductile Iron | 8 | 8 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9177 | P-4906 | EG | King St | 6 | Ductile Iron | 7 | 8 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9178 | P-4906 | EG | King St | 6 | Ductile Iron | 1 | 8 | 0.71 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9194 | P-4906 | EG | King St | 8 | Ductile Iron | 6 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9195 | P-4628 | EG | King St | 8 | Ductile Iron | 5 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11551 | P-4900 | EG | King St | 12 | Ductile Iron | 6 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1895 | P-4618 | EG | King St. | 6 | Cast Iron | 13 | 133 | 2.57 out of 5 | $442 | 5,825 |
| Distribution Main | 1896 | P-4618 | EG | King St. | 6 | Cast Iron | 16 | 133 | 2.57 out of 5 | $442 | 6,883 |
| Distribution Main | 2410 | P-4617 | EG | King St. | 6 | Cast Iron | 110 | 133 | 2.57 out of 5 | $442 | 48,745 |
| Distribution Main | 4849 | P-4622 | EG | King St. | 6 | Cast Iron | 12 | 32 | 1.99 out of 5 | $442 | 5,513 |
| Distribution Main | 4850 | P-4622 | EG | King St. | 6 | Cast Iron | 19 | 32 | 1.99 out of 5 | $442 | 8,224 |
| Distribution Main | 4851 | P-4622 | EG | King St. | 6 | Cast Iron | 8 | 32 | 1.99 out of 5 | $442 | 3,503 |
| Distribution Main | 5535 | P-4902 | EG | King St. | 2 | Copper | 70 | 32 | 2.14 out of 5 | $442 | 30,761 |
| Distribution Main | 5537 | P-4901 | EG | King St. | 6 | Cast Iron | 73 | 32 | 1.99 out of 5 | $442 | 32,352 |
| Distribution Main | 5676 | P-4615 | EG | King St. | 6 | Cast Iron | 209 | 133 | 2.57 out of 5 | $442 | 92,405 |
| Distribution Main | 6277 | P-4613 | EG | King St. | 6 | Cast Iron | 224 | 133 | 2.57 out of 5 | $442 | 99,023 |
| Distribution Main | 6686 | P-4910 | EG | King St. | 8 | Cast Iron | 13 | 133 | 1.86 out of 5 | $442 | 5,859 |
| Distribution Main | 6717 | P-4618 | EG | King St. | 6 | Cast Iron | 57 | 133 | 2.57 out of 5 | $442 | 25,029 |
| Distribution Main | 6732 | P-4622 | EG | King St. | 6 | Cast Iron | 287 | 32 | 1.99 out of 5 | $442 | 126,823 |
| Distribution Main | 6734 | P-4901 | EG | King St. | 6 | Ductile Iron | 2 | 4 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 6736 | P-4902 | EG | King St. | 2 | Copper | 2 | 32 | 2.14 out of 5 | $442 | 934 |
| Distribution Main | 6761 | P-4613 | EG | King St. | 6 | Cast Iron | 22 | 133 | 2.57 out of 5 | $442 | 9,612 |
| Distribution Main | 6763 | P-4910 | EG | King St. | 8 | Cast Iron | 6 | 133 | 1.86 out of 5 | $442 | 2,680 |
| Distribution Main | 9446 | P-4615 | EG | King St. | 6 | Cast Iron | 5 | 133 | 2.57 out of 5 | $442 | 2,084 |
| Distribution Main | 9447 | P-4615 | EG | King St. | 6 | Cast Iron | 11 | 133 | 2.57 out of 5 | $442 | 4,740 |
| Distribution Main | 5506 | P-4110 | EG | Kirker Dr. | 8 | Asbestos Cement | 393 | 46 | 1.14 out of 5 | $442 | 173,609 |
| Distribution Main | 5507 | P-4110 | EG | Kirker Dr. | 8 | Asbestos Cement | 540 | 46 | 1.14 out of 5 | $442 | 238,736 |
| Distribution Main | 664 | P-4529 | EG | Knollwood Ave. | 6 | Asbestos Cement | 170 | 69 | 2 out of 5 | $442 | 75,211 |
| Distribution Main | 4187 | P-4529 | EG | Knollwood Ave. | 6 | Asbestos Cement | 32 | 69 | 2 out of 5 | $442 | 13,923 |
| Distribution Main | 4188 | P-4528 | EG | Knollwood Ave. | 6 | Asbestos Cement | 1,128 | 69 | 2 out of 5 | $442 | 498,425 |
| Distribution Main | 4189 | P-4528 | EG | Knollwood Ave. | 6 | Asbestos Cement | 116 | 69 | 2 out of 5 | $442 | 51,484 |
| Distribution Main | 6208 | P-4529 | EG | Knollwood Ave. | 6 | Asbestos Cement | 662 | 69 | 2 out of 5 | $442 | 292,433 |
| Distribution Main | 6209 | P-4528 | EG | Knollwood Ave. | 6 | Asbestos Cement | 29 | 69 | 2 out of 5 | $442 | 12,850 |
| Distribution Main | 2908 | P-4422 | EG | Lafayette Dr. | 6 | Asbestos Cement | 27 | 50 | 1.85 out of 5 | $442 | 11,785 |
| Distribution Main | 6142 | P-4422 | EG | Lafayette Dr. | 6 | Asbestos Cement | 456 | 50 | 1.85 out of 5 | $442 | 201,646 |
| Distribution Main | 6143 | P-4422 | EG | Lafayette Dr. | 6 | Asbestos Cement | 614 | 50 | 1.85 out of 5 | $442 | 271,440 |
| Distribution Main | 6476 | P-4419 | EG | Landover Dr. | 6 | Asbestos Cement | 310 | 60 | 1.85 out of 5 | $442 | 137,204 |
| Distribution Main | 6477 | P-4421 | EG | Landover Dr. | 6 | Asbestos Cement | 278 | 60 | 1.85 out of 5 | $442 | 122,702 |
| Distribution Main | 5600 | P-4326 | EG | Larch Rd. | 6 | Asbestos Cement | 418 | 50 | 1.85 out of 5 | $442 | 184,949 |
| Distribution Main | 5606 | P-4327 | EG | Larch Rd. | 6 | Asbestos Cement | 355 | 50 | 1.85 out of 5 | $442 | 156,773 |
| Distribution Main | 5607 | P-4327 | EG | Larch Rd. | 6 | Asbestos Cement | 680 | 50 | 1.85 out of 5 | $442 | 300,438 |
| Distribution Main | 5601 | P-4310 | EG | Laurel Hill Rd. | 6 | Asbestos Cement | 932 | 60 | 1.85 out of 5 | $442 | 412,104 |
| Distribution Main | 5602 | P-4310 | EG | Laurel Hill Rd. | 6 | Asbestos Cement | 29 | 60 | 1.85 out of 5 | $442 | 12,637 |
| Distribution Main | 6407 | P-4304 | EG | Laurel Hill Rd. | 6 | Asbestos Cement | 849 | 60 | 1.85 out of 5 | $442 | 375,374 |
| Distribution Main | 9230 | P-40016 | EG | Laurel Ln | 8 | Ductile Iron | 258 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5841 | P-4086 | EG | Laurel Woods Dr. | 8 | Ductile Iron | 352 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5842 | P-4087 | EG | Laurel Woods Dr. | 8 | Ductile Iron | 647 | 24 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 5843 | P-4087 | EG | Laurel Woods Dr. | 8 | Ductile Iron | 28 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5845 | P-4087 | EG | Laurel Woods Dr. | 8 | Ductile Iron | 18 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5846 | P-4087 | EG | Laurel Woods Dr. | 8 | Ductile Iron | 342 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5847 | P-4088 | EG | Laurel Woods Dr. | 8 | Ductile Iron | 1,211 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5848 | P-4086 | EG | Laurel Woods Dr. | 8 | Ductile Iron | 447 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5844 | P-4089 | EG | Laurel Woods Easement | 8 | Ductile Iron | 423 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4146 | P-4426 | EG | Le Baron Dr. | 6 | Asbestos Cement | 269 | 51 | 1.85 out of 5 | $442 | 119,095 |
| Distribution Main | 4190 | P-40028 | EG | Le Baron Dr. | 6 | Asbestos Cement | 127 | 51 | 1.85 out of 5 | $442 | 55,954 |
| Distribution Main | 4191 | | EG | Le Baron Dr. | 6 | Unknown | 87 | UNK | 0.71 out of 5 | $442 | 38,601 |
| Transmission Main | 6063 | P-4232 | EG | Le Baron Dr. | 20 | Asbestos Cement | 998 | 55 | 1.14 out of 5 | $442 | 441,258 |
| Distribution Main | 6144 | P-4426 | EG | Le Baron Dr. | 6 | Asbestos Cement | 12 | 51 | 1.85 out of 5 | $442 | 5,125 |
| Distribution Main | 6468 | P-4420 | EG | Le Baron Dr. | 6 | Asbestos Cement | 182 | 51 | 1.85 out of 5 | $442 | 80,329 |
| Distribution Main | 6485 | P-4425 | EG | Le Baron Dr. | 6 | Asbestos Cement | 76 | 51 | 1.85 out of 5 | $442 | 33,773 |
| Distribution Main | 6486 | P-4438 | EG | Le Baron Dr. | 6 | Asbestos Cement | 185 | 51 | 1.85 out of 5 | $442 | 81,805 |
| Distribution Main | 11340 | P-4420 | EG | Le Baron Dr. | 6 | Asbestos Cement | 5 | 51 | 1.85 out of 5 | $442 | 2,140 |
| Distribution Main | 6490 | P-4436 | EG | Lebaron Dr. | 6 | Asbestos Cement | 120 | 65 | 2 out of 5 | $442 | 53,131 |
| Distribution Main | 6200 | P-4541 | EG | Ledge Rd. | 8 | Ductile Iron | 72 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6201 | P-4541 | EG | Ledge Rd. | 8 | Ductile Iron | 352 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6202 | P-4541 | EG | Ledge Rd. | 8 | Ductile Iron | 222 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9004 | P-4541 | EG | Ledge Rd. | 8 | Ductile Iron | 35 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3651 | P-4154 | EG | Lenihan Lane | 8 | Ductile Iron | 488 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3652 | P-4154 | EG | Lenihan Lane | 8 | Ductile Iron | 636 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5728 | P-4824 | EG | Lenihan Lane | 8 | Ductile Iron | 958 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9994 | P-4154 | EG | Lenihan Lane | 8 | Ductile Iron | 320 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11223 | P-4154 | EG | Lenihan Lane | 8 | Ductile Iron | 128 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8819 | P-4155 | EG | Lenihan Ln | 8 | Ductile Iron | 591 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9051 | | EG | Lenihan Ln | 2 | Ductile Iron | 19 | 17 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 9993 | P-4824 | EG | Lenihan Ln | 8 | Ductile Iron | 136 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10295 | | EG | Lenihan Ln | 8 | Ductile Iron | 247 | 4 | 0 out of 5 | N/A | $0 |
| Distribution Main | 893 | P-4604 | EG | Liberty St. | 8 | Ductile Iron | 18 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 894 | P-4604 | EG | Liberty St. | 8 | Ductile Iron | 397 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 895 | P-4604 | EG | Liberty St. | 8 | Ductile Iron | 19 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6243 | P-4950 | EG | Liberty St. | 8 | Ductile Iron | 273 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10904 | P-4953 | EG | Liberty St. | 8 | Ductile Iron | 49 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2477 | P-4351 | EG | Lilian Street | 6 | Asbestos Cement | 475 | 57 | 1.85 out of 5 | $442 | 210,013 |
| Distribution Main | 3659 | P-4428 | EG | Lillibridge Dr. | 6 | Asbestos Cement | 616 | 57 | 1.85 out of 5 | $442 | 272,125 |
| Distribution Main | 6052 | P-4128 | EG | Limerock Dr. | 6 | Asbestos Cement | 776 | 42 | 1.85 out of 5 | $442 | 343,073 |
| Distribution Main | 6053 | P-4128 | EG | Limerock Dr. | 6 | Asbestos Cement | 243 | 42 | 1.85 out of 5 | $442 | 107,271 |
| Distribution Main | 6230 | P-4691 | EG | Lincoln St. | 8 | Ductile Iron | 268 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9028 | P-4691 | EG | Lincoln St. | 8 | Ductile Iron | 174 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10382 | | EG | Lincoln St. | 8 | Ductile Iron | 33 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 899 | P-4648 | EG | Lion St. | 6 | Ductile Iron | 4 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 5786 | P-4653 | EG | Lion St. | 8 | Ductile Iron | 230 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6236 | P-4648 | EG | Lion St. | 8 | Ductile Iron | 5 | 19 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6239 | P-4648 | EG | Lion St. | 6 | Ductile Iron | 31 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 6760 | P-4648 | EG | Lion St. | 8 | Ductile Iron | 152 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4900 | P-4277 | EG | Locust Drive | 6 | Asbestos Cement | 724 | 51 | 1.85 out of 5 | $442 | 319,967 |
| Distribution Main | 4901 | P-4277 | EG | Locust Drive | 6 | Asbestos Cement | 32 | 51 | 1.85 out of 5 | $442 | 14,064 |
| Distribution Main | 4250 | | EG | London St | 4 | Unknown | 4 | UNK | 1.42 out of 5 | $442 | 1,643 |
| Distribution Main | 4264 | P-4647 | EG | London St | 6 | Ductile Iron | 120 | 32 | 0.85 out of 5 | $442 | 53,204 |
| Distribution Main | 6752 | P-4647 | EG | London St | 6 | Ductile Iron | 4 | 32 | 0.85 out of 5 | $442 | 1,663 |
| Distribution Main | 9182 | P-4642 | EG | London St | 8 | Ductile Iron | 154 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9183 | P-4926 | EG | London St | 12 | Ductile Iron | 2 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9184 | P-4926 | EG | London St | 12 | Ductile Iron | 18 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9305 | P-4643 | EG | London St | 6 | Ductile Iron | 12 | 8 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10910 | P-4636 | EG | London St | 8 | Ductile Iron | 55 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11552 | P-4642 | EG | London St | 8 | Ductile Iron | 12 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12105 | P-4642 | EG | London St | 8 | Ductile Iron | 12 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4263 | P-4929 | EG | London St. | 6 | Cast Iron | 15 | 133 | 2.57 out of 5 | $442 | 6,472 |
| Distribution Main | 6237 | P-4930 | EG | London St. | 6 | Ductile Iron | 66 | 32 | 0.85 out of 5 | $442 | 29,231 |
| Distribution Main | 6238 | P-4930 | EG | London St. | 6 | Ductile Iron | 37 | 32 | 0.85 out of 5 | $442 | 16,409 |
| Transmission Main | 6245 | P-4638 | EG | London St. | 12 | Asbestos Cement | 173 | 60 | 1.14 out of 5 | $442 | 76,251 |
| Distribution Main | 6247 | | EG | London St. | 6 | Cast Iron | 38 | 133 | 2.57 out of 5 | $442 | 16,783 |
| Distribution Main | 6643 | P-4643 | EG | London St. | 6 | Cast Iron | 55 | 133 | 2.57 out of 5 | $442 | 24,329 |
| Transmission Main | 6722 | P-4635 | EG | London St. | 12 | Asbestos Cement | 63 | 60 | 1.14 out of 5 | $442 | 27,657 |
| Transmission Main | 6738 | P-4638 | EG | London St. | 12 | Asbestos Cement | 6 | 60 | 1.14 out of 5 | $442 | 2,867 |
| Distribution Main | 6751 | P-4930 | EG | London St. | 6 | Ductile Iron | 3 | 32 | 0.85 out of 5 | $442 | 1,449 |
| Distribution Main | 6753 | P-4929 | EG | London St. | 6 | Cast Iron | 16 | 133 | 2.57 out of 5 | $442 | 7,215 |
| Transmission Main | 9202 | P-4638 | EG | London St. | 12 | Ductile Iron | 23 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 884 | P-4645 | EG | Long St. | 8 | Ductile Iron | 225 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5403 | P-4651 | EG | Long St. | 8 | Ductile Iron | 125 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5405 | P-4652 | EG | Long St. | 8 | Ductile Iron | 5 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5409 | P-4651 | EG | Long St. | 8 | Ductile Iron | 8 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6234 | P-4652 | EG | Long St. | 8 | Ductile Iron | 242 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6235 | P-4652 | EG | Long St. | 8 | Ductile Iron | 23 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6759 | P-4651 | EG | Long St. | 8 | Ductile Iron | 3 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3875 | | EG | Longmeadow Dr. | 8 | Ductile Iron | 19 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 3876 | | EG | Longmeadow Dr. | 8 | Ductile Iron | 4 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 3877 | | EG | Longmeadow Dr. | 8 | Ductile Iron | 223 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 3878 | | EG | Longmeadow Dr. | 8 | Ductile Iron | 485 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 4092 | | EG | Longmeadow Dr. | 8 | Ductile Iron | 195 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 4093 | | EG | Longmeadow Dr. | 8 | Ductile Iron | 412 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4094 | | EG | Longmeadow Dr. | 8 | Ductile Iron | 44 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4928 | P-4000 | EG | Longmeadow Dr. | 8 | Ductile Iron | 745 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4929 | P-4000 | EG | Longmeadow Dr. | 8 | Ductile Iron | 275 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6353 | P-4000 | EG | Longmeadow Dr. | 8 | Ductile Iron | 366 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6354 | P-4000 | EG | Longmeadow Dr. | 8 | Ductile Iron | 11 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6355 | P-4000 | EG | Longmeadow Dr. | 8 | Ductile Iron | 40 | 16 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6356 | P-4000 | EG | Longmeadow Dr. | 8 | Ductile Iron | 121 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6357 | P-4000 | EG | Longmeadow Dr. | 8 | Ductile Iron | 83 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6363 | P-4000 | EG | Longmeadow Dr. | 8 | Ductile Iron | 65 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8822 | P-4829 | EG | Lovegreen Ln | 8 | Ductile Iron | 386 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8823 | P-4829 | EG | Lovegreen Ln | 8 | Ductile Iron | 414 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6574 | P-4137 | EG | Lynn Cir. | 8 | PVC | 24 | 33 | 0.43 out of 5 | $442 | 10,806 |
| Distribution Main | 6575 | P-4137 | EG | Lynn Cir. | 8 | PVC | 172 | 33 | 0.43 out of 5 | $442 | 75,850 |
| Distribution Main | 6580 | P-4135 | EG | Lynn Cir. | 8 | PVC | 583 | 33 | 0.43 out of 5 | $442 | 257,492 |
| Distribution Main | 6581 | P-4135 | EG | Lynn Cir. | 8 | PVC | 701 | 33 | 0.43 out of 5 | $442 | 310,040 |
| Distribution Main | 11837 | P-4135 | EG | Lynn Cir. | 8 | PVC | 369 | 33 | 0.43 out of 5 | $442 | 163,236 |
| Distribution Main | 11838 | P-4135 | EG | Lynn Cir. | 8 | PVC | 552 | 33 | 0.43 out of 5 | $442 | 244,177 |
| Distribution Main | 10178 | | EG | Main St | 4 | Ductile Iron | 1 | 17 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 883 | P-4935 | EG | Main St. | 10 | Ductile Iron | 24 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 885 | P-4932 | EG | Main St. | 10 | Ductile Iron | 6 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 886 | P-4641 | EG | Main St. | 10 | Cast Iron | 3 | 133 | 1.86 out of 5 | $442 | 1,434 |
| Distribution Main | 887 | P-4641 | EG | Main St. | 10 | Cast Iron | 320 | 133 | 1.86 out of 5 | $442 | 141,477 |
| Distribution Main | 890 | P-4598 | EG | Main St. | 10 | Cast Iron | 169 | 133 | 1.86 out of 5 | $442 | 74,844 |
| Distribution Main | 891 | P-4949 | EG | Main St. | 10 | Ductile Iron | 14 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 892 | P-4657 | EG | Main St. | 10 | Cast Iron | 290 | 133 | 1.86 out of 5 | $442 | 128,323 |
| Distribution Main | 4251 | P-4279 | EG | Main St. | 10 | Cast Iron | 245 | 133 | 1.86 out of 5 | $442 | 108,125 |
| Distribution Main | 4253 | P-4937 | EG | Main St. | 10 | Ductile Iron | 22 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4257 | P-4633 | EG | Main St. | 8 | Cast Iron | 413 | 133 | 1.86 out of 5 | $442 | 182,595 |
| Distribution Main | 4258 | P-4633 | EG | Main St. | 8 | Cast Iron | 342 | 133 | 1.86 out of 5 | $442 | 150,979 |
| Distribution Main | 4423 | P-4594 | EG | Main St. | 10 | Cast Iron | 399 | 133 | 1.86 out of 5 | $442 | 176,296 |
| Distribution Main | 4578 | P-4692 | EG | Main St. | 10 | Cast Iron | 6 | 133 | 1.86 out of 5 | $442 | 2,847 |
| Distribution Main | 4579 | P-4692 | EG | Main St. | 10 | Cast Iron | 234 | 133 | 1.86 out of 5 | $442 | 103,567 |
| Distribution Main | 5674 | P-4612 | EG | Main St. | 8 | Cast Iron | 5 | 133 | 1.86 out of 5 | $442 | 2,421 |
| Distribution Main | 5675 | P-4612 | EG | Main St. | 8 | Cast Iron | 18 | 133 | 1.86 out of 5 | $442 | 8,055 |
| Distribution Main | 5677 | P-4687 | EG | Main St. | 8 | Cast Iron | 194 | 133 | 1.86 out of 5 | $442 | 85,921 |
| Distribution Main | 5680 | P-4263 | EG | Main St. | 10 | Ductile Iron | 250 | 33 | 0.14 out of 5 | $442 | 110,488 |
| Distribution Main | 5681 | P-4263 | EG | Main St. | 10 | Ductile Iron | 93 | 33 | 0.14 out of 5 | $442 | 41,120 |
| Distribution Main | 5684 | P-4924 | EG | Main St. | 10 | Cast Iron | 19 | 133 | 1.86 out of 5 | $442 | 8,395 |
| Distribution Main | 5685 | P-4924 | EG | Main St. | 10 | Cast Iron | 49 | 133 | 1.86 out of 5 | $442 | 21,839 |
| Distribution Main | 5686 | P-4633 | EG | Main St. | 8 | Cast Iron | 2 | 133 | 1.86 out of 5 | $442 | 743 |
| Distribution Main | 6248 | P-40036 | EG | Main St. | 10 | Ductile Iron | 327 | 33 | 0.14 out of 5 | $442 | 144,589 |
| Distribution Main | 6257 | P-4279 | EG | Main St. | 10 | Cast Iron | 197 | 133 | 1.86 out of 5 | $442 | 87,130 |
| Distribution Main | 6259 | P-4594 | EG | Main St. | 10 | Cast Iron | 19 | 133 | 1.86 out of 5 | $442 | 8,420 |
| Distribution Main | 6273 | P-4612 | EG | Main St. | 8 | Cast Iron | 113 | 133 | 1.86 out of 5 | $442 | 49,993 |
| Distribution Main | 6274 | P-4612 | EG | Main St. | 8 | Cast Iron | 228 | 133 | 1.86 out of 5 | $442 | 100,577 |
| Distribution Main | 6275 | P-4612 | EG | Main St. | 8 | Cast Iron | 157 | 133 | 1.86 out of 5 | $442 | 69,194 |
| Distribution Main | 6281 | P-4612 | EG | Main St. | 8 | Cast Iron | 53 | 133 | 1.86 out of 5 | $442 | 23,547 |
| Distribution Main | 6638 | P-40036 | EG | Main St. | 10 | Ductile Iron | 14 | 33 | 0.14 out of 5 | $442 | 6,071 |
| Distribution Main | 6641 | P-4279 | EG | Main St. | 10 | Cast Iron | 10 | 133 | 1.86 out of 5 | $442 | 4,317 |
| Distribution Main | 6688 | P-4279 | EG | Main St. | 10 | Cast Iron | 23 | 133 | 1.86 out of 5 | $442 | 10,154 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6689 | P-4279 | EG | Main St. | 10 | Cast Iron | 25 | 133 | 1.86 out of 5 | $442 | 10,838 |
| Distribution Main | 6729 | P-4623 | EG | Main St. | 8 | Cast Iron | 31 | 133 | 1.86 out of 5 | $442 | 13,827 |
| Distribution Main | 6730 | P-4623 | EG | Main St. | 8 | Cast Iron | 255 | 133 | 1.86 out of 5 | $442 | 112,554 |
| Distribution Main | 6766 | P-4891 | EG | Main St. | 8 | Cast Iron | 15 | 133 | 1.86 out of 5 | $442 | 6,808 |
| Distribution Main | 6767 | P-4892 | EG | Main St. | 8 | Cast Iron | 5 | 133 | 1.86 out of 5 | $442 | 2,034 |
| Distribution Main | 9006 | P-4657 | EG | Main St. | 10 | Cast Iron | 4 | 133 | 1.86 out of 5 | $442 | 1,758 |
| Distribution Main | 9027 | P-4911 | EG | Main St. | 10 | Ductile Iron | 6 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9312 | P-4598 | EG | Main St. | 10 | Ductile Iron | 13 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9442 | P-4939 | EG | Main St. | 10 | Cast Iron | 67 | 133 | 1.86 out of 5 | $442 | 29,741 |
| Distribution Main | 10906 | P-4657 | EG | Main St. | 10 | Ductile Iron | 10 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10980 | P-4931 | EG | Main St. | 10 | Ductile Iron | 5 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11007 | P-4623 | EG | Main St. | 10 | Ductile Iron | 4 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11008 | P-4936 | EG | Main St. | 10 | Ductile Iron | 15 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11311 | P-4612 | EG | Main St. | 8 | Cast Iron | 10 | 133 | 1.86 out of 5 | $442 | 4,488 |
| Distribution Main | 11312 | P-4612 | EG | Main St. | 8 | Cast Iron | 3 | 133 | 1.86 out of 5 | $442 | 1,302 |
| Distribution Main | 11815 | P-4623 | EG | Main St. | 8 | Cast Iron | 14 | 133 | 1.86 out of 5 | $442 | 6,074 |
| Distribution Main | 12091 | P-4612 | EG | Main St. | 8 | Cast Iron | 64 | 133 | 1.86 out of 5 | $442 | 28,429 |
| Transmission Main | 5270 | P-4010 | EG | Mallard Way | 12 | Ductile Iron | 450 | 27 | 0.14 out of 5 | $442 | 199,043 |
| Transmission Main | 5271 | P-4010 | EG | Mallard Way | 12 | Ductile Iron | 297 | 27 | 0.14 out of 5 | $442 | 131,057 |
| Distribution Main | 1814 | P-4394 | EG | Maplewood Dr. | 8 | Asbestos Cement | 478 | 59 | 1.14 out of 5 | $442 | 211,261 |
| Distribution Main | 4891 | P-4395 | EG | Maplewood Dr. | 8 | Asbestos Cement | 728 | 59 | 1.14 out of 5 | $442 | 321,766 |
| Distribution Main | 4892 | P-4395 | EG | Maplewood Dr. | 8 | Asbestos Cement | 232 | 59 | 1.14 out of 5 | $442 | 102,481 |
| Distribution Main | 4902 | P-4290 | EG | Maplewood Dr. | 8 | Asbestos Cement | 790 | 59 | 1.14 out of 5 | $442 | 348,981 |
| Distribution Main | 6145 | P-4290 | EG | Maplewood Dr. | 8 | Asbestos Cement | 22 | 59 | 1.14 out of 5 | $442 | 9,700 |
| Distribution Main | 11811 | P-4395 | EG | Maplewood Dr. | 8 | Asbestos Cement | 26 | 59 | 1.14 out of 5 | $442 | 11,660 |
| Distribution Main | 5783 | P-4918 | EG | Marion St. | 6 | Unknown | 159 | UNK | 0.71 out of 5 | $442 | 70,371 |
| Distribution Main | 5784 | P-4918 | EG | Marion St. | 4 | Cast Iron | 12 | 133 | 3.29 out of 5 | $442 | 5,390 |
| Distribution Main | 5785 | P-4918 | EG | Marion St. | 4 | Cast Iron | 162 | 133 | 3.29 out of 5 | $442 | 71,558 |
| Distribution Main | 6278 | P-4610 | EG | Marion St. | 4 | Cast Iron | 404 | 133 | 3.29 out of 5 | $442 | 178,721 |
| Distribution Main | 6755 | P-4918 | EG | Marion St. | 4 | Cast Iron | 3 | 133 | 3.29 out of 5 | $442 | 1,460 |
| Distribution Main | 6757 | P-4610 | EG | Marion St. | 4 | Cast Iron | 18 | 133 | 3.29 out of 5 | $442 | 8,001 |
| Distribution Main | 10380 | | EG | Marlborough St | 4 | Ductile Iron | 25 | UNK | 1.42 out of 5 | $442 | 11,126 |
| Distribution Main | 889 | P-4656 | EG | Marlborough St. | 8 | Ductile Iron | 550 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4424 | P-4695 | EG | Marlborough St. | 8 | Ductile Iron | 66 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5678 | P-4659 | EG | Marlborough St. | 8 | Ductile Iron | 235 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5679 | P-4659 | EG | Marlborough St. | 8 | Ductile Iron | 38 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6231 | P-4596 | EG | Marlborough St. | 8 | Ductile Iron | 21 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6232 | P-4596 | EG | Marlborough St. | 8 | Ductile Iron | 255 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6240 | P-4639 | EG | Marlborough St. | 12 | Ductile Iron | 386 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6246 | P-4595 | EG | Marlborough St. | 8 | Ductile Iron | 140 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6647 | P-4625 | EG | Marlborough St. | 12 | Asbestos Cement | 492 | 63 | 1.29 out of 5 | $442 | 217,544 |
| Transmission Main | 6648 | P-4625 | EG | Marlborough St. | 12 | Asbestos Cement | 18 | 63 | 1.29 out of 5 | $442 | 7,888 |
| Distribution Main | 9029 | P-4659 | EG | Marlborough St. | 8 | Ductile Iron | 7 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9030 | P-4659 | EG | Marlborough St. | 8 | Ductile Iron | 55 | 17 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9031 | P-4656 | EG | Marlborough St. | 8 | Ductile Iron | 6 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9481 | P-4656 | EG | Marlborough St. | 8 | Ductile Iron | 45 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9482 | P-4639 | EG | Marlborough St. | 12 | Ductile Iron | 26 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9483 | P-4639 | EG | Marlborough St. | 12 | Ductile Iron | 4 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10848 | P-4614 | EG | Marlborough St. | 12 | Asbestos Cement | 614 | 63 | 1.29 out of 5 | $442 | 271,387 |
| Transmission Main | 10849 | P-4928 | EG | Marlborough St. | 12 | Asbestos Cement | 332 | 63 | 1.29 out of 5 | $442 | 146,690 |
| Transmission Main | 10907 | P-4928 | EG | Marlborough St. | 12 | Ductile Iron | 5 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10908 | P-4928 | EG | Marlborough St. | 12 | Ductile Iron | 3 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11329 | P-4595 | EG | Marlborough St. | 8 | Ductile Iron | 93 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9888 | P-40003 | EG | Mary Elizabeth Way | 8 | Ductile Iron | 509 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9889 | P-40003 | EG | Mary Elizabeth Way | 8 | Ductile Iron | 10 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5898 | P-4139 | EG | Mawney Brook Dr. | 8 | Ductile Iron | 44 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5899 | P-4139 | EG | Mawney Brook Dr. | 8 | Ductile Iron | 160 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5900 | P-4139 | EG | Mawney Brook Dr. | 8 | Ductile Iron | 363 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3667 | P-4578 | EG | Mawney St. | 4 | Cast Iron | 23 | 133 | 3.29 out of 5 | $442 | 10,347 |
| Distribution Main | 6634 | P-4587 | EG | Mawney St. | 4 | Cast Iron | 449 | 133 | 3.29 out of 5 | $442 | 198,602 |
| Distribution Main | 12185 | | EG | Mawney St. | 4 | Cast Iron | 820 | 133 | 3.29 out of 5 | $442 | 362,289 |
| Distribution Main | 5008 | P-4384 | EG | Mayflower Dr. | 6 | Asbestos Cement | 274 | 50 | 1.85 out of 5 | $442 | 121,315 |
| Distribution Main | 5009 | P-4384 | EG | Mayflower Dr. | 6 | Asbestos Cement | 178 | 50 | 1.85 out of 5 | $442 | 78,793 |
| Distribution Main | 5010 | P-4357 | EG | Mayflower Dr. | 6 | Asbestos Cement | 193 | 50 | 1.85 out of 5 | $442 | 85,085 |
| Distribution Main | 5246 | P-4385 | EG | Mayflower Dr. | 6 | Asbestos Cement | 419 | 50 | 1.85 out of 5 | $442 | 185,055 |
| Distribution Main | 6150 | P-4385 | EG | Mayflower Dr. | 6 | Asbestos Cement | 16 | 50 | 1.85 out of 5 | $442 | 7,088 |
| Distribution Main | 10075 | P-4273 | EG | Mcgraw Ct. | 6 | Ductile Iron | 13 | 28 | 0.85 out of 5 | $442 | 5,642 |
| Distribution Main | 10076 | P-4273 | EG | Mcgraw Ct. | 6 | Ductile Iron | 268 | 28 | 0.85 out of 5 | $442 | 118,315 |
| Distribution Main | 3645 | P-4144 | EG | Mcpartland Way | 8 | Ductile Iron | 39 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3646 | P-4144 | EG | Mcpartland Way | 8 | Ductile Iron | 146 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3647 | P-4144 | EG | Mcpartland Way | 8 | Ductile Iron | 507 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3648 | P-4144 | EG | Mcpartland Way | 8 | Ductile Iron | 35 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9981 | P-4145 | EG | Mcpartland Way | 8 | Ductile Iron | 933 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10125 | P-4145 | EG | Mcpartland Way | 8 | Ductile Iron | 27 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10126 | P-4145 | EG | Mcpartland Way | 8 | Ductile Iron | 746 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 757 | | EG | Meadowbrook Road | 6 | PVC | 3 | 55 | 1.28 out of 5 | $442 | 1,536 |
| Distribution Main | 1808 | P-40021 | EG | Meadowbrook Road | 6 | Ductile Iron | 19 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 1812 | P-40020 | EG | Meadowbrook Road | 6 | PVC | 480 | 55 | 1.28 out of 5 | $442 | 212,227 |
| Distribution Main | 3639 | P-40020 | EG | Meadowbrook Road | 6 | PVC | 533 | 55 | 1.28 out of 5 | $442 | 235,749 |
| Distribution Main | 5508 | P-40022 | EG | Meadowbrook Road | 6 | Ductile Iron | 126 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 5515 | P-40022 | EG | Meadowbrook Road | 6 | Ductile Iron | 4 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 5718 | P-40020 | EG | Meadowbrook Road | 6 | PVC | 15 | 55 | 1.28 out of 5 | $442 | 6,782 |
| Distribution Main | 6389 | P-40022 | EG | Meadowbrook Road | 6 | Ductile Iron | 4 | 18 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 6 | P-4671 | EG | Middle Rd | 12 | Asbestos Cement | 122 | 57 | 1.14 out of 5 | $442 | 53,896 |
| Distribution Main | 4173 | | EG | Middle Rd | 8 | Unknown | 13 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 9666 | | EG | Middle Rd | 6 | Ductile Iron | 10 | 7 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10179 | P-4212 | EG | Middle Rd | 4 | Ductile Iron | 7 | 18 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 10180 | P-4212 | EG | Middle Rd | 4 | Ductile Iron | 44 | 18 | 1.42 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10374 | | EG | Middle Rd | 6 | Ductile Iron | 15 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 5 | P-4672 | EG | Middle Rd Prv | 8 | Ductile Iron | 11 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 561 | | EG | Middle Rd. | 12 | Ductile Iron | 29 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 564 | P-4806 | EG | Middle Rd. | 12 | Ductile Iron | 21 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 660 | P-4527 | EG | Middle Rd. | 8 | Ductile Iron | 25 | 32 | 0.14 out of 5 | $442 | 11,101 |
| Transmission Main | 3649 | P-4143 | EG | Middle Rd. | 16 | Ductile Iron | 538 | 16 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3650 | | EG | Middle Rd. | 16 | Ductile Iron | 10 | 16 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3653 | P-4148 | EG | Middle Rd. | 16 | Ductile Iron | 1,136 | 16 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3901 | P-4807 | EG | Middle Rd. | 12 | Ductile Iron | 901 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3902 | P-4807 | EG | Middle Rd. | 12 | Ductile Iron | 9 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4096 | P-4806 | EG | Middle Rd. | 16 | Ductile Iron | 756 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4097 | P-4806 | EG | Middle Rd. | 16 | Ductile Iron | 53 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4098 | P-4806 | EG | Middle Rd. | 12 | Ductile Iron | 8 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4100 | P-4807 | EG | Middle Rd. | 12 | Ductile Iron | 10 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4150 | P-4444 | EG | Middle Rd. | 8 | Ductile Iron | 493 | 32 | 0.14 out of 5 | $442 | 218,003 |
| Distribution Main | 4151 | P-4444 | EG | Middle Rd. | 8 | Ductile Iron | 379 | 32 | 0.14 out of 5 | $442 | 167,308 |
| Transmission Main | 4172 | P-4233 | EG | Middle Rd. | 20 | Asbestos Cement | 879 | 55 | 1.14 out of 5 | $442 | 388,632 |
| Distribution Main | 4178 | P-4525 | EG | Middle Rd. | 8 | Ductile Iron | 41 | 32 | 0.14 out of 5 | $442 | 18,054 |
| Distribution Main | 4179 | P-4525 | EG | Middle Rd. | 8 | Ductile Iron | 614 | 32 | 0.14 out of 5 | $442 | 271,566 |
| Distribution Main | 4243 | P-4525 | EG | Middle Rd. | 8 | Ductile Iron | 211 | 32 | 0.14 out of 5 | $442 | 93,145 |
| Distribution Main | 4244 | P-4525 | EG | Middle Rd. | 8 | Ductile Iron | 555 | 32 | 0.14 out of 5 | $442 | 245,525 |
| Transmission Main | 4245 | P-4233 | EG | Middle Rd. | 20 | Asbestos Cement | 1,188 | 55 | 1.14 out of 5 | $442 | 525,030 |
| Transmission Main | 4487 | P-4138 | EG | Middle Rd. | 16 | Ductile Iron | 816 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4488 | P-4138 | EG | Middle Rd. | 16 | Ductile Iron | 49 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4492 | P-4158 | EG | Middle Rd. | 16 | Ductile Iron | 235 | 26 | 0.14 out of 5 | $442 | 103,811 |
| Transmission Main | 4493 | P-4158 | EG | Middle Rd. | 16 | Ductile Iron | 61 | 26 | 0.14 out of 5 | $442 | 27,041 |
| Transmission Main | 4497 | P-4157 | EG | Middle Rd. | 16 | Ductile Iron | 820 | 26 | 0.14 out of 5 | $442 | 362,349 |
| Transmission Main | 4498 | P-4157 | EG | Middle Rd. | 16 | Ductile Iron | 112 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5001 | P-4213 | EG | Middle Rd. | 12 | Asbestos Cement | 641 | 57 | 1.14 out of 5 | $442 | 283,337 |
| Transmission Main | 5002 | P-4213 | EG | Middle Rd. | 12 | Asbestos Cement | 591 | 57 | 1.14 out of 5 | $442 | 261,213 |
| Transmission Main | 5003 | P-4344 | EG | Middle Rd. | 12 | Asbestos Cement | 224 | 57 | 1.14 out of 5 | $442 | 99,050 |
| Transmission Main | 5004 | P-4344 | EG | Middle Rd. | 12 | Asbestos Cement | 485 | 57 | 1.14 out of 5 | $442 | 214,243 |
| Transmission Main | 5007 | P-4336 | EG | Middle Rd. | 12 | Asbestos Cement | 599 | 57 | 1.14 out of 5 | $442 | 264,927 |
| Distribution Main | 5586 | P-4337 | EG | Middle Rd. | 8 | Ductile Iron | 21 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5587 | P-4398 | EG | Middle Rd. | 8 | Ductile Iron | 121 | 32 | 0.14 out of 5 | $442 | 53,667 |
| Distribution Main | 5588 | P-4398 | EG | Middle Rd. | 8 | Ductile Iron | 72 | 32 | 0.14 out of 5 | $442 | 31,972 |
| Distribution Main | 5590 | P-4392 | EG | Middle Rd. | 8 | Ductile Iron | 305 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5591 | P-4392 | EG | Middle Rd. | 8 | Ductile Iron | 22 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5592 | P-4397 | EG | Middle Rd. | 8 | Ductile Iron | 322 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5593 | P-4367 | EG | Middle Rd. | 8 | Ductile Iron | 79 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5595 | P-4368 | EG | Middle Rd. | 8 | Ductile Iron | 481 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5596 | P-4339 | EG | Middle Rd. | 8 | Ductile Iron | 325 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5648 | P-4118 | EG | Middle Rd. | 12 | Asbestos Cement | 611 | 46 | 1.14 out of 5 | $442 | 270,118 |
| Transmission Main | 5649 | P-4118 | EG | Middle Rd. | 12 | Asbestos Cement | 309 | 46 | 1.14 out of 5 | $442 | 136,556 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 5730 | P-4138 | EG | Middle Rd. | 16 | Ductile Iron | 7 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5731 | | EG | Middle Rd. | 16 | Ductile Iron | 3 | 16 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6002 | P-4719 | EG | Middle Rd. | 12 | Ductile Iron | 47 | 36 | 0.14 out of 5 | $442 | 20,737 |
| Transmission Main | 6007 | P-4116 | EG | Middle Rd. | 20 | Ductile Iron | 1,164 | 36 | 0.14 out of 5 | $442 | 514,682 |
| Transmission Main | 6009 | P-4726 | EG | Middle Rd. | 12 | Ductile Iron | 640 | 28 | 0.14 out of 5 | $442 | 282,703 |
| Transmission Main | 6010 | P-4726 | EG | Middle Rd. | 12 | Ductile Iron | 444 | 28 | 0.14 out of 5 | $442 | 196,208 |
| Transmission Main | 6018 | P-4727 | EG | Middle Rd. | 12 | Asbestos Cement | 649 | 46 | 1.14 out of 5 | $442 | 286,739 |
| Transmission Main | 6025 | P-4671 | EG | Middle Rd. | 12 | Steel | 379 | 18 | 0.57 out of 5 | N/A | $0 |
| Transmission Main | 6026 | P-4671 | EG | Middle Rd. | 12 | Steel | 8 | 18 | 0.57 out of 5 | N/A | $0 |
| Transmission Main | 6030 | P-4118 | EG | Middle Rd. | 12 | Asbestos Cement | 6 | 46 | 1.14 out of 5 | $442 | 2,614 |
| Transmission Main | 6031 | P-4213 | EG | Middle Rd. | 12 | Asbestos Cement | 7 | 57 | 1.14 out of 5 | $442 | 3,014 |
| Distribution Main | 6188 | P-4371 | EG | Middle Rd. | 8 | Ductile Iron | 10 | 32 | 0.14 out of 5 | $442 | 4,289 |
| Distribution Main | 6189 | P-4371 | EG | Middle Rd. | 8 | Ductile Iron | 721 | 32 | 0.14 out of 5 | $442 | 318,523 |
| Distribution Main | 6390 | P-4368 | EG | Middle Rd. | 8 | Ductile Iron | 440 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6403 | P-4371 | EG | Middle Rd. | 8 | Ductile Iron | 585 | 32 | 0.14 out of 5 | $442 | 258,558 |
| Distribution Main | 6406 | P-4398 | EG | Middle Rd. | 8 | Ductile Iron | 183 | 32 | 0.14 out of 5 | $442 | 80,947 |
| Transmission Main | 6571 | P-4719 | EG | Middle Rd. | 20 | Ductile Iron | 21 | 36 | 0.14 out of 5 | $442 | 9,365 |
| Transmission Main | 8882 | P-4157 | EG | Middle Rd. | 16 | Ductile Iron | 175 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9072 | | EG | Middle Rd. | 16 | Ductile Iron | 17 | 16 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9438 | P-4140 | EG | Middle Rd. | 16 | Ductile Iron | 244 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10107 | P-4130 | EG | Middle Rd. | 20 | Ductile Iron | 3 | 28 | 0.14 out of 5 | $442 | 1,215 |
| Transmission Main | 10244 | P-4343 | EG | Middle Rd. | 12 | Ductile Iron | 12 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10245 | P-4343 | EG | Middle Rd. | 12 | Ductile Iron | 9 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10250 | P-4233 | EG | Middle Rd. | 20 | Asbestos Cement | 129 | 55 | 1.14 out of 5 | $442 | 56,921 |
| Distribution Main | 10354 | | EG | Middle Rd. | 6 | PVC | 14 | 35 | 1.14 out of 5 | $442 | 6,196 |
| Distribution Main | 10372 | P-4397 | EG | Middle Rd. | 8 | Ductile Iron | 89 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 10375 | P-4337 | EG | Middle Rd. | 8 | Ductile Iron | 12 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11079 | | EG | Middle Rd. | 12 | Ductile Iron | 23 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11254 | P-4158 | EG | Middle Rd. | 16 | Ductile Iron | 41 | 26 | 0.14 out of 5 | $442 | 18,340 |
| Transmission Main | 11279 | P-4213 | EG | Middle Rd. | 12 | Asbestos Cement | 273 | 57 | 1.14 out of 5 | $442 | 120,516 |
| Transmission Main | 11280 | P-4213 | EG | Middle Rd. | 12 | Asbestos Cement | 226 | 57 | 1.14 out of 5 | $442 | 99,759 |
| Distribution Main | 11333 | P-4368 | EG | Middle Rd. | 8 | Ductile Iron | 48 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11514 | P-4148 | EG | Middle Rd. | 16 | Ductile Iron | 14 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11646 | P-4343 | EG | Middle Rd. | 12 | Ductile Iron | 1 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11647 | P-4344 | EG | Middle Rd. | 12 | Ductile Iron | 2 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11813 | P-4726 | EG | Middle Rd. | 12 | Ductile Iron | 501 | 28 | 0.14 out of 5 | $442 | 221,661 |
| Transmission Main | 11818 | P-4213 | EG | Middle Rd. | 12 | Asbestos Cement | 136 | 57 | 1.14 out of 5 | $442 | 60,083 |
| Transmission Main | 11822 | P-4726 | EG | Middle Rd. | 12 | Ductile Iron | 283 | 28 | 0.14 out of 5 | $442 | 125,256 |
| Transmission Main | 11823 | P-4726 | EG | Middle Rd. | 12 | Ductile Iron | 428 | 28 | 0.14 out of 5 | $442 | 189,124 |
| Transmission Main | 11849 | P-4726 | EG | Middle Rd. | 12 | Ductile Iron | 71 | 28 | 0.14 out of 5 | $442 | 31,280 |
| Transmission Main | 12084 | P-4118 | EG | Middle Rd. | 12 | Asbestos Cement | 172 | 46 | 1.14 out of 5 | $442 | 76,113 |
| Transmission Main | 12232 | | EG | Middle Rd. | 16 | Ductile Iron | 76 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 12234 | | EG | Middle Rd. | 16 | Ductile Iron | 88 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10246 | P-4672 | EG | Middle Rd. Prv | 8 | Ductile Iron | 7 | 18 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10247 | P-4224 | EG | Middle Rd. Prv | 8 | Ductile Iron | 11 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3661 | P-4440 | EG | Midlands Dr. | 6 | Asbestos Cement | 540 | 45 | 1.85 out of 5 | $442 | 238,841 |
| Transmission Main | 3821 | P-4160 | EG | Miss Fry Dr. | 16 | Ductile Iron | 43 | 26 | 0.14 out of 5 | $442 | 18,984 |
| Transmission Main | 3822 | P-4167 | EG | Miss Fry Dr. | 16 | Ductile Iron | 330 | 26 | 0.14 out of 5 | $442 | 145,944 |
| Transmission Main | 3823 | P-4167 | EG | Miss Fry Dr. | 16 | Ductile Iron | 126 | 26 | 0.14 out of 5 | $442 | 55,756 |
| Transmission Main | 3826 | P-4160 | EG | Miss Fry Dr. | 16 | Ductile Iron | 540 | 26 | 0.14 out of 5 | $442 | 238,760 |
| Transmission Main | 3827 | P-4160 | EG | Miss Fry Dr. | 16 | Ductile Iron | 8 | 26 | 0.14 out of 5 | $442 | 3,465 |
| Transmission Main | 3828 | P-4162 | EG | Miss Fry Dr. | 16 | Ductile Iron | 445 | 26 | 0.14 out of 5 | $442 | 196,787 |
| Transmission Main | 3829 | P-4162 | EG | Miss Fry Dr. | 16 | Ductile Iron | 522 | 26 | 0.14 out of 5 | $442 | 230,596 |
| Transmission Main | 4491 | P-4160 | EG | Miss Fry Dr. | 16 | Ductile Iron | 24 | 26 | 0.14 out of 5 | $442 | 10,729 |
| Transmission Main | 4854 | P-4167 | EG | Miss Fry Dr. | 16 | Ductile Iron | 471 | 26 | 0.14 out of 5 | $442 | 208,270 |
| Transmission Main | 10092 | P-4167 | EG | Miss Fry Dr. | 16 | Ductile Iron | 396 | 26 | 0.14 out of 5 | $442 | 175,180 |
| Distribution Main | 3843 | P-4281 | EG | Misty Oak Dr. | 8 | PVC | 486 | 35 | 0.43 out of 5 | $442 | 214,646 |
| Distribution Main | 3844 | P-4282 | EG | Misty Oak Dr. | 8 | PVC | 23 | 35 | 0.43 out of 5 | $442 | 10,338 |
| Distribution Main | 6783 | P-4275 | EG | Misty Oak Dr. | 8 | Asbestos Cement | 273 | 54 | 1.14 out of 5 | $442 | 120,781 |
| Distribution Main | 6786 | P-4282 | EG | Misty Oak Dr. | 8 | PVC | 13 | 35 | 0.43 out of 5 | $442 | 5,705 |
| Distribution Main | 6787 | P-4282 | EG | Misty Oak Dr. | 8 | PVC | 462 | 35 | 0.43 out of 5 | $442 | 204,023 |
| Distribution Main | 5884 | P-4108 | EG | Monroe Dr. | 6 | Asbestos Cement | 20 | 44 | 1.85 out of 5 | $442 | 9,051 |
| Distribution Main | 6698 | P-4108 | EG | Monroe Dr. | 6 | Asbestos Cement | 504 | 44 | 1.85 out of 5 | $442 | 222,667 |
| Distribution Main | 6756 | P-4919 | EG | Montrose St. | 4 | Cast Iron | 266 | 133 | 3.29 out of 5 | $442 | 117,755 |
| Transmission Main | 3640 | P-40040 | EG | Moosehorn Rd. | 16 | Ductile Iron | 75 | 26 | 0.14 out of 5 | $442 | 33,322 |
| Transmission Main | 3641 | P-4159 | EG | Moosehorn Rd. | 16 | Ductile Iron | 476 | 26 | 0.14 out of 5 | $442 | 210,586 |
| Transmission Main | 3642 | P-4159 | EG | Moosehorn Rd. | 16 | Ductile Iron | 467 | 26 | 0.14 out of 5 | $442 | 206,542 |
| Transmission Main | 3643 | P-4159 | EG | Moosehorn Rd. | 16 | Ductile Iron | 438 | 26 | 0.14 out of 5 | $442 | 193,425 |
| Transmission Main | 3644 | P-4159 | EG | Moosehorn Rd. | 16 | Ductile Iron | 13 | 26 | 0.14 out of 5 | $442 | 5,755 |
| Transmission Main | 5735 | P-40040 | EG | Moosehorn Rd. | 16 | Ductile Iron | 12 | 26 | 0.14 out of 5 | $442 | 5,226 |
| Distribution Main | 458 | P-4983 | EG | Moss Ln | 8 | Unknown | 182 | 35 | 0.14 out of 5 | $442 | 80,438 |
| Distribution Main | 6780 | P-4283 | EG | Mullberry Ct. | 6 | PVC | 212 | 35 | 1.14 out of 5 | $442 | 93,906 |
| Distribution Main | 6710 | P-4259 | EG | New Castle Drive | 8 | PVC | 441 | 41 | 0.57 out of 5 | $442 | 194,974 |
| Distribution Main | 6711 | P-4267 | EG | New Castle Drive | 8 | PVC | 134 | 41 | 0.57 out of 5 | $442 | 59,159 |
| Distribution Main | 9659 | | EG | New London | 2 | Unknown | 51 | 7 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 4032 | P-4378 | EG | Nichols Ln | 6 | Asbestos Cement | 211 | 51 | 1.85 out of 5 | $442 | 93,373 |
| Distribution Main | 4033 | P-4378 | EG | Nichols Ln | 6 | Asbestos Cement | 832 | 51 | 1.85 out of 5 | $442 | 367,661 |
| Distribution Main | 5503 | P-4322 | EG | North Gate Dr. | 8 | Asbestos Cement | 274 | 50 | 1.14 out of 5 | $442 | 121,257 |
| Distribution Main | 6054 | P-4221 | EG | Oak Dell Cir. | 8 | Asbestos Cement | 845 | 51 | 1.14 out of 5 | $442 | 373,499 |
| Distribution Main | 6055 | P-4221 | EG | Oak Dell Cir. | 8 | Asbestos Cement | 261 | 51 | 1.14 out of 5 | $442 | 115,418 |
| Distribution Main | 6709 | P-4991 | EG | Oak Dell Cir. | 8 | Asbestos Cement | 143 | 51 | 1.14 out of 5 | $442 | 63,227 |
| Distribution Main | 5628 | P-4457 | EG | Oakwood Dr. | 6 | Asbestos Cement | 220 | 60 | 1.85 out of 5 | $442 | 97,251 |
| Distribution Main | 5629 | P-4457 | EG | Oakwood Dr. | 6 | Asbestos Cement | 975 | 60 | 1.85 out of 5 | $442 | 430,768 |
| Distribution Main | 8813 | P-4808 | EG | Old Farm Road | 8 | Ductile Iron | 758 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8814 | P-4808 | EG | Old Farm Road | 8 | Ductile Iron | 70 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3664 | P-4491 | EG | Old Greenwich Dr. | 6 | Asbestos Cement | 236 | 47 | 1.85 out of 5 | $442 | 104,093 |
| Distribution Main | 3665 | P-4490 | EG | Old Greenwich Dr. | 6 | Asbestos Cement | 75 | 47 | 1.85 out of 5 | $442 | 33,053 |
| Distribution Main | 4149 | P-4489 | EG | Old Greenwich Dr. | 6 | Asbestos Cement | 54 | 47 | 1.85 out of 5 | $442 | 23,869 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4999 | P-4491 | EG | Old Greenwich Dr. | 6 | Asbestos Cement | 9 | 47 | 1.85 out of 5 | $442 | 3,937 |
| Transmission Main | 9096 | P-4755 | EG | Old Quaker Ln | 16 | Ductile Iron | 595 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9099 | P-4755 | EG | Old Quaker Ln | 16 | Ductile Iron | 123 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9100 | P-4755 | EG | Old Quaker Ln | 16 | Ductile Iron | 146 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5809 | P-4030 | EG | Osprey Dr. | 8 | PVC | 684 | 32 | 0.43 out of 5 | $442 | 302,192 |
| Distribution Main | 5810 | P-4030 | EG | Osprey Dr. | 8 | PVC | 357 | 32 | 0.43 out of 5 | $442 | 157,717 |
| Distribution Main | 6372 | P-4031 | EG | Osprey Dr. | 8 | PVC | 427 | 32 | 0.43 out of 5 | $442 | 188,903 |
| Distribution Main | 11844 | P-4030 | EG | Osprey Dr. | 8 | PVC | 445 | 32 | 0.43 out of 5 | $442 | 196,593 |
| Distribution Main | 2395 | P-4533 | EG | Overbrook Ln. | 6 | Asbestos Cement | 672 | 64 | 2.71 out of 5 | $442 | 297,202 |
| Distribution Main | 3934 | P-4534 | EG | Overbrook Ln. | 6 | Asbestos Cement | 154 | 64 | 2 out of 5 | $442 | 68,180 |
| Distribution Main | 3935 | P-4534 | EG | Overbrook Ln. | 6 | Asbestos Cement | 72 | 64 | 2 out of 5 | $442 | 31,666 |
| Distribution Main | 3937 | P-4533 | EG | Overbrook Ln. | 6 | Asbestos Cement | 3 | 64 | 2 out of 5 | $442 | 1,343 |
| Distribution Main | 2905 | P-4354 | EG | Overfield Rd. | 6 | Ductile Iron | 392 | 30 | 0.85 out of 5 | $442 | 173,226 |
| Distribution Main | 3657 | P-4697 | EG | Overfield Rd. | 6 | Ductile Iron | 31 | 30 | 0.85 out of 5 | $442 | 13,558 |
| Distribution Main | 3658 | P-4697 | EG | Overfield Rd. | 6 | Ductile Iron | 739 | 30 | 0.85 out of 5 | $442 | 326,669 |
| Distribution Main | 4185 | P-4697 | EG | Overfield Rd. | 6 | Ductile Iron | 77 | 30 | 0.85 out of 5 | $442 | 33,877 |
| Distribution Main | 6131 | P-4354 | EG | Overfield Rd. | 6 | Ductile Iron | 269 | 30 | 0.85 out of 5 | $442 | 118,756 |
| Distribution Main | 6132 | P-4354 | EG | Overfield Rd. | 6 | Ductile Iron | 17 | 30 | 0.85 out of 5 | $442 | 7,362 |
| Distribution Main | 6133 | P-4354 | EG | Overfield Rd. | 6 | Ductile Iron | 264 | 30 | 0.85 out of 5 | $442 | 116,636 |
| Distribution Main | 6474 | P-4698 | EG | Overfield Rd. | 6 | Ductile Iron | 433 | 30 | 0.85 out of 5 | $442 | 191,399 |
| Distribution Main | 6475 | P-4354 | EG | Overfield Rd. | 6 | Ductile Iron | 6 | 30 | 0.85 out of 5 | $442 | 2,518 |
| Distribution Main | 5390 | P-4044 | EG | Owl Tree Ln. | 8 | Ductile Iron | 26 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5391 | P-4044 | EG | Owl Tree Ln. | 8 | Ductile Iron | 362 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9959 | P-4044 | EG | Owl Tree Ln. | 8 | Asbestos Cement | 54 | 47 | 1.14 out of 5 | $442 | 23,666 |
| Distribution Main | 9960 | P-4044 | EG | Owl Tree Ln. | 8 | Ductile Iron | 40 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4856 | P-4073 | EG | Pardon'S Wood Ln. | 8 | Ductile Iron | 284 | 26 | 0.14 out of 5 | $442 | 125,694 |
| Distribution Main | 4857 | P-4073 | EG | Pardon'S Wood Ln. | 8 | Ductile Iron | 45 | 26 | 0.14 out of 5 | $442 | 19,692 |
| Distribution Main | 5869 | P-4073 | EG | Pardon'S Wood Ln. | 8 | Ductile Iron | 70 | 26 | 0.14 out of 5 | $442 | 30,994 |
| Distribution Main | 5870 | P-4073 | EG | Pardon'S Wood Ln. | 8 | Ductile Iron | 380 | 26 | 0.14 out of 5 | $442 | 167,902 |
| Distribution Main | 4804 | P-4164 | EG | Partridge Run | 8 | Ductile Iron | 322 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4805 | P-4164 | EG | Partridge Run | 8 | Ductile Iron | 579 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4855 |  | EG | Partridge Run | 8 | Ductile Iron | 6 | 26 | 0.14 out of 5 | $442 | 2,660 |
| Distribution Main | 4861 |  | EG | Partridge Run | 8 | Ductile Iron | 3 | 26 | 0.14 out of 5 | $442 | 1,314 |
| Distribution Main | 6295 | P-40042 | EG | Partridge Run | 8 | Ductile Iron | 367 | 26 | 0.14 out of 5 | $442 | 162,238 |
| Distribution Main | 10096 | P-40042 | EG | Partridge Run | 8 | Ductile Iron | 546 | 26 | 0.14 out of 5 | $442 | 241,374 |
| Distribution Main | 10097 | P-40042 | EG | Partridge Run | 8 | Ductile Iron | 199 | 26 | 0.14 out of 5 | $442 | 87,988 |
| Distribution Main | 10098 |  | EG | Partridge Run | 8 | Ductile Iron | 23 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11266 | P-4164 | EG | Partridge Run | 8 | Ductile Iron | 46 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11852 | P-40042 | EG | Partridge Run | 8 | Ductile Iron | 17 | 26 | 0.14 out of 5 | $442 | 7,696 |
| Distribution Main | 11853 | P-4164 | EG | Partridge Run | 8 | Ductile Iron | 365 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3859 | P-4967 | EG | Pearl St. | 1.5 | Copper | 87 | UNK | 1.99 out of 5 | $442 | 38,518 |
| Distribution Main | 9016 | P-4966 | EG | Pearl St. | 8 | Ductile Iron | 20 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4153 | P-4493 | EG | Pegwin Dr. | 6 | Asbestos Cement | 24 | 55 | 1.85 out of 5 | $442 | 10,449 |
| Distribution Main | 4154 | P-4493 | EG | Pegwin Dr. | 6 | Asbestos Cement | 435 | 55 | 1.85 out of 5 | $442 | 192,101 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4998 | P-4493 | EG | Pegwin Dr. | 6 | Asbestos Cement | 7 | 55 | 1.85 out of 5 | $442 | 3,266 |
| Distribution Main | 5964 | P-4494 | EG | Pegwin Dr. | 6 | Asbestos Cement | 729 | 55 | 1.85 out of 5 | $442 | 322,157 |
| Distribution Main | 5965 | P-4494 | EG | Pegwin Dr. | 6 | Asbestos Cement | 17 | 55 | 1.85 out of 5 | $442 | 7,666 |
| Distribution Main | 9226 | P-4194 | EG | Pequot Tr | 8 | Ductile Iron | 43 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9227 | P-4194 | EG | Pequot Tr | 8 | Ductile Iron | 898 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9233 | P-4199 | EG | Pequot Tr | 8 | Ductile Iron | 128 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9244 | P-4202 | EG | Pequot Tr | 8 | Ductile Iron | 511 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9245 | P-4199 | EG | Pequot Tr | 8 | Ductile Iron | 594 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9246 | P-4206 | EG | Pequot Tr | 8 | Ductile Iron | 631 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11556 | P-4194 | EG | Pequot Tr | 8 | Ductile Iron | 155 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11557 | P-4191 | EG | Pequot Tr | 8 | Ductile Iron | 127 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11560 | P-4190 | EG | Pequot Tr | 8 | Ductile Iron | 89 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12160 | P-4202 | EG | Pequot Tr | 8 | Ductile Iron | 113 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5467 | P-4353 | EG | Pettine St. | 1 | Copper | 331 | 66 | 2.43 out of 5 | $442 | 146,257 |
| Distribution Main | 11303 | P-4353 | EG | Pettine St. | 1 | Copper | 18 | 66 | 2.43 out of 5 | $442 | 7,786 |
| Transmission Main | 5805 | P-40000 | EG | Pheasant Dr. | 12 | PVC | 334 | 30 | 0.43 out of 5 | $442 | 147,724 |
| Transmission Main | 5806 | P-40000 | EG | Pheasant Dr. | 12 | PVC | 103 | 30 | 0.43 out of 5 | $442 | 45,625 |
| Transmission Main | 5807 | P-4024 | EG | Pheasant Dr. | 16 | Ductile Iron | 688 | 26 | 0.14 out of 5 | $442 | 304,150 |
| Transmission Main | 5808 | P-4024 | EG | Pheasant Dr. | 16 | Ductile Iron | 712 | 26 | 0.14 out of 5 | $442 | 314,587 |
| Transmission Main | 5814 | P-4024 | EG | Pheasant Dr. | 16 | Ductile Iron | 110 | 26 | 0.14 out of 5 | $442 | 48,786 |
| Transmission Main | 5815 | P-4024 | EG | Pheasant Dr. | 16 | Ductile Iron | 231 | 26 | 0.14 out of 5 | $442 | 101,883 |
| Transmission Main | 5901 | P-4026 | EG | Pheasant Dr. | 16 | Ductile Iron | 558 | 26 | 0.14 out of 5 | $442 | 246,439 |
| Distribution Main | 5946 | P-4999 | EG | Pheasant Dr. | 8 | Ductile Iron | 32 | 26 | 0.14 out of 5 | $442 | 14,184 |
| Transmission Main | 11318 | P-4026 | EG | Pheasant Dr. | 16 | Ductile Iron | 6 | 26 | 0.14 out of 5 | $442 | 2,520 |
| Distribution Main | 2903 | P-4429 | EG | Phillips Dr. | 6 | Asbestos Cement | 465 | 49 | 1.85 out of 5 | $442 | 205,659 |
| Distribution Main | 2909 | P-4412 | EG | Phillips Dr. | 6 | Asbestos Cement | 8 | 49 | 1.85 out of 5 | $442 | 3,478 |
| Distribution Main | 4192 | P-4411 | EG | Phillips Dr. | 6 | Asbestos Cement | 240 | 49 | 1.85 out of 5 | $442 | 105,996 |
| Distribution Main | 6467 | P-4412 | EG | Phillips Dr. | 6 | Asbestos Cement | 281 | 49 | 1.85 out of 5 | $442 | 124,216 |
| Distribution Main | 6488 | P-4432 | EG | Phillips Dr. | 6 | Asbestos Cement | 285 | 49 | 1.85 out of 5 | $442 | 125,938 |
| Distribution Main | 6489 | P-4436 | EG | Phillips Dr. | 6 | Asbestos Cement | 37 | 49 | 1.85 out of 5 | $442 | 16,188 |
| Distribution Main | 6496 | P-4431 | EG | Phillips Dr. | 6 | Asbestos Cement | 57 | 49 | 1.85 out of 5 | $442 | 25,404 |
| Distribution Main | 6497 | P-4431 | EG | Phillips Dr. | 6 | Asbestos Cement | 391 | 49 | 1.85 out of 5 | $442 | 172,828 |
| Distribution Main | 11191 | P-4429 | EG | Phillips Dr. | 6 | Asbestos Cement | 7 | 49 | 1.85 out of 5 | $442 | 3,248 |
| Distribution Main | 301 | P-4922 | EG | Pierce St | 8 | Ductile Iron | 11 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9007 | P-4921 | EG | Pierce St | 6 | Ductile Iron | 8 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9008 | P-4923 | EG | Pierce St | 6 | Ductile Iron | 5 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9153 | P-4889 | EG | Pierce St | 6 | Ductile Iron | 11 | 8 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9311 | P-4921 | EG | Pierce St | 8 | Ductile Iron | 9 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11575 | P-4922 | EG | Pierce St | 8 | Ductile Iron | 6 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 900 | P-4685 | EG | Pierce St. | 6 | Cast Iron | 316 | 133 | 2.57 out of 5 | $442 | 139,530 |
| Distribution Main | 901 | P-4685 | EG | Pierce St. | 6 | Cast Iron | 181 | 133 | 2.57 out of 5 | $442 | 80,051 |
| Distribution Main | 902 | P-4608 | EG | Pierce St. | 6 | Cast Iron | 23 | 133 | 2.57 out of 5 | $442 | 10,215 |
| Distribution Main | 903 | P-4608 | EG | Pierce St. | 6 | Cast Iron | 186 | 133 | 2.57 out of 5 | $442 | 82,025 |
| Distribution Main | 2409 | P-4611 | EG | Pierce St. | 6 | Cast Iron | 4 | 133 | 2.57 out of 5 | $442 | 1,786 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3860 | P-4608 | EG | Pierce St. | 8 | Ductile Iron | 8 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3861 | P-4685 | EG | Pierce St. | 8 | Ductile Iron | 6 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6220 | P-4606 | EG | Pierce St. | 6 | Cast Iron | 283 | 133 | 2.57 out of 5 | $442 | 125,171 |
| Distribution Main | 6279 | P-4611 | EG | Pierce St. | 6 | Cast Iron | 392 | 133 | 2.57 out of 5 | $442 | 173,299 |
| Distribution Main | 6280 | P-4611 | EG | Pierce St. | 6 | Cast Iron | 191 | 133 | 2.57 out of 5 | $442 | 84,411 |
| Distribution Main | 6739 | P-4611 | EG | Pierce St. | 6 | Cast Iron | 7 | 133 | 2.57 out of 5 | $442 | 3,130 |
| Distribution Main | 9025 | P-4608 | EG | Pierce St. | 6 | Ductile Iron | 2 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9026 | P-4685 | EG | Pierce St. | 6 | Ductile Iron | 2 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 5245 | P-4214 | EG | Pine Hill Dr. | 8 | Asbestos Cement | 34 | 51 | 1.14 out of 5 | $442 | 15,097 |
| Distribution Main | 6028 | P-4214 | EG | Pine Hill Dr. | 8 | Asbestos Cement | 457 | 51 | 1.14 out of 5 | $442 | 201,820 |
| Distribution Main | 112 | P-4736 | EG | Post Rd | 10 | Cast Iron | 324 | 133 | 1.86 out of 5 | $442 | 143,052 |
| Distribution Main | 9612 | | EG | Post Rd | 2 | Copper | 47 | 7 | 1.99 out of 5 | N/A | $0 |
| Transmission Main | 304 | P-4241 | EG | Post Rd. | 16 | Ductile Iron | 472 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 376 | P-4736 | EG | Post Rd. | 10 | Cast Iron | 876 | 133 | 1.86 out of 5 | $442 | 387,318 |
| Distribution Main | 377 | P-4736 | EG | Post Rd. | 10 | Cast Iron | 47 | 133 | 1.86 out of 5 | $442 | 20,559 |
| Transmission Main | 1940 | P-4241 | EG | Post Rd. | 16 | Ductile Iron | 14 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1941 | P-4241 | EG | Post Rd. | 16 | Ductile Iron | 280 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2904 | P-4292 | EG | Post Rd. | 10 | Ductile Iron | 7 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2977 | P-4067 | EG | Post Rd. | 10 | Ductile Iron | 691 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2978 | P-4067 | EG | Post Rd. | 10 | Ductile Iron | 301 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3449 | P-4067 | EG | Post Rd. | 10 | Ductile Iron | 192 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3689 | P-4736 | EG | Post Rd. | 10 | Cast Iron | 242 | 133 | 1.86 out of 5 | $442 | 107,040 |
| Distribution Main | 3940 | | EG | Post Rd. | 10 | Ductile Iron | 40 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3942 | P-4306 | EG | Post Rd. | 10 | Ductile Iron | 646 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3944 | P-40072 | EG | Post Rd. | 10 | Ductile Iron | 611 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4039 | P-4276 | EG | Post Rd. | 10 | Cast Iron | 465 | 133 | 1.86 out of 5 | $442 | 205,542 |
| Distribution Main | 4040 | P-40032 | EG | Post Rd. | 10 | Ductile Iron | 199 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4045 | P-4272 | EG | Post Rd. | 10 | Cast Iron | 340 | 133 | 1.86 out of 5 | $442 | 150,462 |
| Distribution Main | 4046 | P-4272 | EG | Post Rd. | 10 | Cast Iron | 638 | 133 | 1.86 out of 5 | $442 | 282,091 |
| Distribution Main | 4147 | P-4739 | EG | Post Rd. | 10 | Ductile Iron | 528 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4193 | P-4735 | EG | Post Rd. | 20 | Ductile Iron | 647 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4195 | P-4227 | EG | Post Rd. | 20 | Asbestos Cement | 426 | 55 | 1.14 out of 5 | $442 | 188,211 |
| Transmission Main | 4196 | P-4227 | EG | Post Rd. | 20 | Asbestos Cement | 54 | 55 | 1.14 out of 5 | $442 | 23,901 |
| Distribution Main | 4197 | P-4735 | EG | Post Rd. | 10 | Cast Iron | 382 | 133 | 1.86 out of 5 | $442 | 168,928 |
| Distribution Main | 4198 | P-4737 | EG | Post Rd. | 10 | Cast Iron | 5 | 133 | 1.86 out of 5 | $442 | 1,991 |
| Distribution Main | 4199 | P-4278 | EG | Post Rd. | 10 | Ductile Iron | 296 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4205 | | EG | Post Rd. | 6 | Ductile Iron | 9 | 23 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 4206 | P-4289 | EG | Post Rd. | 10 | Ductile Iron | 408 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4246 | P-4737 | EG | Post Rd. | 10 | Cast Iron | 493 | 133 | 1.86 out of 5 | $442 | 217,716 |
| Distribution Main | 4247 | P-4737 | EG | Post Rd. | 10 | Cast Iron | 29 | 133 | 1.86 out of 5 | $442 | 12,676 |
| Transmission Main | 4983 | | EG | Post Rd. | 12 | Ductile Iron | 27 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4984 | P-4269 | EG | Post Rd. | 10 | Cast Iron | 304 | 133 | 1.86 out of 5 | $442 | 134,288 |
| Transmission Main | 4988 | P-4241 | EG | Post Rd. | 16 | Ductile Iron | 74 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5429 | P-4865 | EG | Post Rd. | 10 | Ductile Iron | 6 | 23 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 5582 | P-4734 | EG | Post Rd. | 20 | Ductile Iron | 138 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5583 | P-4734 | EG | Post Rd. | 20 | Ductile Iron | 397 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5584 | P-4734 | EG | Post Rd. | 20 | Ductile Iron | 106 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5717 | P-4241 | EG | Post Rd. | 16 | Ductile Iron | 69 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6118 | P-4278 | EG | Post Rd. | 10 | Ductile Iron | 973 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6121 | P-4272 | EG | Post Rd. | 10 | Cast Iron | 230 | 133 | 1.86 out of 5 | $442 | 101,551 |
| Distribution Main | 6134 | P-4272 | EG | Post Rd. | 10 | Cast Iron | 119 | 133 | 1.86 out of 5 | $442 | 52,762 |
| Distribution Main | 6135 | P-4272 | EG | Post Rd. | 10 | Cast Iron | 653 | 133 | 1.86 out of 5 | $442 | 288,631 |
| Distribution Main | 6138 | P-4269 | EG | Post Rd. | 10 | Cast Iron | 655 | 133 | 1.86 out of 5 | $442 | 289,661 |
| Distribution Main | 6139 | P-4269 | EG | Post Rd. | 10 | Cast Iron | 31 | 133 | 1.86 out of 5 | $442 | 13,645 |
| Distribution Main | 6140 | P-4699 | EG | Post Rd. | 10 | Ductile Iron | 963 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6251 | P-4865 | EG | Post Rd. | 10 | Ductile Iron | 193 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6252 | P-4865 | EG | Post Rd. | 10 | Ductile Iron | 388 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6253 | | EG | Post Rd. | 10 | Ductile Iron | 3 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6254 | P-4321 | EG | Post Rd. | 10 | Ductile Iron | 566 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6256 | P-4321 | EG | Post Rd. | 10 | Ductile Iron | 93 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6260 | P-4312 | EG | Post Rd. | 10 | Ductile Iron | 28 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6469 | P-4303 | EG | Post Rd. | 10 | Ductile Iron | 51 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6470 | P-4303 | EG | Post Rd. | 10 | Ductile Iron | 145 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6471 | P-4294 | EG | Post Rd. | 10 | Ductile Iron | 192 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6472 | P-4292 | EG | Post Rd. | 10 | Ductile Iron | 204 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6635 | P-4312 | EG | Post Rd. | 10 | Ductile Iron | 18 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9882 | P-4734 | EG | Post Rd. | 16 | Ductile Iron | 16 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9883 | P-4239 | EG | Post Rd. | 12 | Ductile Iron | 56 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9885 | P-4239 | EG | Post Rd. | 12 | Ductile Iron | 50 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9887 | | EG | Post Rd. | 12 | Ductile Iron | 69 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10272 | | EG | Post Rd. | 6 | Ductile Iron | 32 | 23 | 0.85 out of 5 | N/A | $0 |
| Transmission Main | 10282 | P-4734 | EG | Post Rd. | 16 | Ductile Iron | 8 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10283 | P-40052 | EG | Post Rd. | 10 | Cast Iron | 256 | 133 | 1.86 out of 5 | $442 | 113,313 |
| Distribution Main | 10284 | P-4067 | EG | Post Rd. | 10 | Ductile Iron | 386 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10285 | P-4067 | EG | Post Rd. | 10 | Ductile Iron | 36 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11050 | | EG | Post Rd. | 16 | Ductile Iron | 48 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11051 | P-4067 | EG | Post Rd. | 10 | Ductile Iron | 34 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11052 | P-4269 | EG | Post Rd. | 10 | Cast Iron | 7 | 133 | 1.86 out of 5 | $442 | 2,954 |
| Distribution Main | 11053 | P-4067 | EG | Post Rd. | 10 | Ductile Iron | 21 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11197 | P-4734 | EG | Post Rd. | 16 | Ductile Iron | 4 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11219 | P-4067 | EG | Post Rd. | 10 | Ductile Iron | 78 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11816 | P-4736 | EG | Post Rd. | 10 | Cast Iron | 106 | 133 | 1.86 out of 5 | $442 | 46,980 |
| Distribution Main | 12176 | | EG | Post Rd. | 10 | Ductile Iron | 376 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2911 | P-4346 | EG | Power St. | 6 | PVC | 301 | 36 | 1.14 out of 5 | $442 | 133,011 |
| Distribution Main | 5630 | P-4504 | EG | Pricewood Dr. | 6 | Asbestos Cement | 690 | 61 | 2 out of 5 | $442 | 305,037 |
| Distribution Main | 4254 | P-4682 | EG | Proctor Ave. | 8 | Ductile Iron | 404 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4255 | P-4680 | EG | Proctor Ave. | 8 | Ductile Iron | 237 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6351 | P-4548 | EG | Proctor Ave. | 6 | Cast Iron | 333 | 133 | 2.57 out of 5 | $442 | 147,070 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9005 | P-4548 | EG | Proctor Ave. | 8 | Ductile Iron | 18 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11001 | P-4680 | EG | Proctor Ave. | 8 | Ductile Iron | 5 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5690 | P-4580 | EG | Prospect St. | 6 | Asbestos Cement | 42 | 70 | 2 out of 5 | $442 | 18,635 |
| Transmission Main | 6225 | P-4955 | EG | Prospect St. | 12 | Ductile Iron | 6 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6229 | P-4580 | EG | Prospect St. | 12 | Ductile Iron | 426 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6264 | P-4589 | EG | Prospect St. | 6 | Asbestos Cement | 250 | 70 | 2 out of 5 | $442 | 110,576 |
| Distribution Main | 6265 | P-4589 | EG | Prospect St. | 6 | Asbestos Cement | 202 | 70 | 2 out of 5 | $442 | 89,072 |
| Transmission Main | 6645 | P-4580 | EG | Prospect St. | 12 | Ductile Iron | 7 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6646 | P-4580 | EG | Prospect St. | 12 | Ductile Iron | 7 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6723 | P-4581 | EG | Prospect St. | 12 | Ductile Iron | 250 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6744 | P-4955 | EG | Prospect St. | 12 | Ductile Iron | 244 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6745 | P-4955 | EG | Prospect St. | 12 | Ductile Iron | 25 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11328 | P-4955 | EG | Prospect St. | 12 | Ductile Iron | 4 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5840 | P-4082 | EG | Quail Ct. | 8 | PVC | 247 | 40 | 0.43 out of 5 | $442 | 109,366 |
| Transmission Main | 9098 | P-4755 | EG | Quaker Ln | 16 | Ductile Iron | 1,071 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9101 | P-10006 | EG | Quaker Ln | 16 | Ductile Iron | 1,202 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10329 | P-4631 | EG | Queen St | 8 | Ductile Iron | 41 | 4 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10330 | P-4631 | EG | Queen St | 8 | Ductile Iron | 10 | 4 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10331 | P-4631 | EG | Queen St | 6 | Ductile Iron | 2 | 4 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 897 | P-4930 | EG | Queen St. | 6 | Cast Iron | 454 | 133 | 2.57 out of 5 | $442 | 200,791 |
| Distribution Main | 898 | P-4930 | EG | Queen St. | 6 | Cast Iron | 8 | 133 | 2.57 out of 5 | $442 | 3,755 |
| Distribution Main | 5402 | P-4624 | EG | Queen St. | 6 | Cast Iron | 428 | 133 | 2.57 out of 5 | $442 | 189,183 |
| Distribution Main | 5536 | P-4917 | EG | Queen St. | 8 | Asbestos Cement | 10 | 44 | 1.14 out of 5 | $442 | 4,400 |
| Distribution Main | 6291 | P-4916 | EG | Queen St. | 8 | Cast Iron | 9 | 133 | 1.86 out of 5 | $442 | 4,136 |
| Distribution Main | 6737 | P-4631 | EG | Queen St. | 6 | Asbestos Cement | 297 | 44 | 1.85 out of 5 | $442 | 131,334 |
| Distribution Main | 6762 | P-4624 | EG | Queen St. | 6 | Cast Iron | 29 | 133 | 2.57 out of 5 | $442 | 12,824 |
| Distribution Main | 9196 | P-4912 | EG | Queen St. | 8 | Ductile Iron | 24 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9197 | P-4913 | EG | Queen St. | 6 | Ductile Iron | 4 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9198 | P-4914 | EG | Queen St. | 6 | Ductile Iron | 4 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10909 | P-4914 | EG | Queen St. | 8 | Ductile Iron | 15 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11748 | P-4930 | EG | Queen St. | 6 | Cast Iron | 8 | 133 | 2.57 out of 5 | $442 | 3,495 |
| Distribution Main | 5826 | P-4032 | EG | Rabbit Run | 8 | PVC | 193 | 32 | 0.43 out of 5 | $442 | 85,371 |
| Distribution Main | 5827 | P-4032 | EG | Rabbit Run | 8 | PVC | 487 | 32 | 0.43 out of 5 | $442 | 215,427 |
| Transmission Main | 302 | P-4571 | EG | Rector St. | 12 | Ductile Iron | 40 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 3857 | P-4571 | EG | Rector St. | 12 | Ductile Iron | 47 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4506 | P-4572 | EG | Rector St. | 12 | Ductile Iron | 10 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4507 | P-4601 | EG | Rector St. | 12 | Ductile Iron | 5 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4508 | P-4601 | EG | Rector St. | 12 | Ductile Iron | 744 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4509 | P-4571 | EG | Rector St. | 12 | Ductile Iron | 11 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4510 | P-4571 | EG | Rector St. | 12 | Ductile Iron | 2 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4586 | P-4603 | EG | Rector St. | 12 | Ductile Iron | 67 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5672 | P-4572 | EG | Rector St. | 12 | Ductile Iron | 49 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6217 | P-4572 | EG | Rector St. | 12 | Ductile Iron | 383 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6721 | P-4601 | EG | Rector St. | 12 | Ductile Iron | 12 | 17 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3909 | P-4486 | EG | Red Barn Ln. | 8 | Asbestos Cement | 55 | 46 | 1.14 out of 5 | $442 | 24,517 |
| Distribution Main | 3910 | P-4486 | EG | Red Barn Ln. | 8 | Asbestos Cement | 418 | 46 | 1.14 out of 5 | $442 | 184,566 |
| Distribution Main | 6384 | P-4484 | EG | Red Barn Ln. | 8 | Asbestos Cement | 167 | 46 | 1.14 out of 5 | $442 | 73,623 |
| Distribution Main | 6385 | P-4484 | EG | Red Barn Ln. | 8 | Asbestos Cement | 869 | 46 | 1.14 out of 5 | $442 | 384,171 |
| Distribution Main | 10231 | P-4484 | EG | Red Barn Ln. | 8 | Asbestos Cement | 399 | 46 | 1.14 out of 5 | $442 | 176,506 |
| Distribution Main | 11831 | P-4486 | EG | Red Barn Ln. | 8 | Asbestos Cement | 46 | 46 | 1.14 out of 5 | $442 | 20,423 |
| Distribution Main | 6804 | P-4318 | EG | Red Oak Rd. | 6 | Asbestos Cement | 809 | 51 | 1.85 out of 5 | $442 | 357,421 |
| Distribution Main | 6498 | P-4434 | EG | Reed Place | 6 | Asbestos Cement | 5 | 50 | 1.85 out of 5 | $442 | 2,236 |
| Distribution Main | 6499 | P-4434 | EG | Reed Place | 6 | Asbestos Cement | 281 | 50 | 1.85 out of 5 | $442 | 124,019 |
| Distribution Main | 9476 | P-4942 | EG | Reilly Av | 1 | Copper | 261 | 63 | 2.43 out of 5 | $442 | 115,547 |
| Distribution Main | 5521 | P-4092 | EG | Remy Place | 8 | Ductile Iron | 8 | 38 | 0.14 out of 5 | $442 | 3,409 |
| Distribution Main | 5531 | P-4092 | EG | Remy Place | 8 | Ductile Iron | 293 | 38 | 0.14 out of 5 | $442 | 129,547 |
| Distribution Main | 5660 | P-4092 | EG | Remy Place | 8 | Ductile Iron | 3 | 38 | 0.14 out of 5 | $442 | 1,485 |
| Distribution Main | 5661 | P-4092 | EG | Remy Place | 8 | Ductile Iron | 10 | 38 | 0.14 out of 5 | $442 | 4,232 |
| Distribution Main | 3862 | P-4609 | EG | Revolution St. | 6 | Asbestos Cement | 345 | 75 | 2 out of 5 | $442 | 152,620 |
| Distribution Main | 3863 | P-4609 | EG | Revolution St. | 6 | Unknown | 351 | UNK | 0.71 out of 5 | $442 | 155,149 |
| Distribution Main | 1901 | P-4576 | EG | Reynolds St. | 4 | Cast Iron | 607 | 133 | 3.29 out of 5 | $442 | 268,177 |
| Distribution Main | 6214 | P-4584 | EG | Reynolds St. | 4 | Cast Iron | 416 | 133 | 3.29 out of 5 | $442 | 183,825 |
| Distribution Main | 6221 | P-4576 | EG | Reynolds St. | 4 | Cast Iron | 19 | 133 | 3.29 out of 5 | $442 | 8,285 |
| Distribution Main | 6631 | P-4584 | EG | Reynolds St. | 4 | Cast Iron | 8 | 133 | 3.29 out of 5 | $442 | 3,427 |
| Distribution Main | 5860 | P-4724 | EG | Rhodes Way | 8 | Ductile Iron | 3 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5861 | P-4724 | EG | Rhodes Way | 8 | Ductile Iron | 331 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9234 | P-4188 | EG | Ridge Rd | 8 | Ductile Iron | 60 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9235 | P-4187 | EG | Ridge Rd | 8 | Ductile Iron | 227 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9236 | P-4187 | EG | Ridge Rd | 8 | Ductile Iron | 165 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10968 | P-4188 | EG | Ridge Rd | 8 | Ductile Iron | 203 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3660 | P-4441 | EG | Ridgefield Dr. | 8 | Asbestos Cement | 157 | 45 | 1.14 out of 5 | $442 | 69,455 |
| Distribution Main | 4020 | P-4441 | EG | Ridgefield Dr. | 8 | Asbestos Cement | 262 | 45 | 1.14 out of 5 | $442 | 115,758 |
| Distribution Main | 4201 | P-4439 | EG | Ridgefield Dr. | 8 | Asbestos Cement | 423 | 45 | 1.14 out of 5 | $442 | 187,002 |
| Distribution Main | 4202 | P-4439 | EG | Ridgefield Dr. | 8 | Asbestos Cement | 74 | 45 | 1.14 out of 5 | $442 | 32,759 |
| Distribution Main | 6297 | P-4443 | EG | Ridgefield Dr. | 8 | Asbestos Cement | 408 | 45 | 1.14 out of 5 | $442 | 180,460 |
| Distribution Main | 3917 | P-4250 | EG | River Farm Drive | 8 | Ductile Iron | 204 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3918 | P-4249 | EG | River Farm Drive | 8 | Ductile Iron | 445 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3919 | P-4249 | EG | River Farm Drive | 8 | Ductile Iron | 472 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3920 | P-4249 | EG | River Farm Drive | 8 | Ductile Iron | 129 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3921 | P-4247 | EG | River Farm Drive | 8 | Ductile Iron | 328 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3922 | P-4247 | EG | River Farm Drive | 8 | Ductile Iron | 411 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3926 | P-4250 | EG | River Farm Drive | 8 | Ductile Iron | 251 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5663 | P-4248 | EG | River Farm Drive | 8 | Asbestos Cement | 5 | 51 | 1.14 out of 5 | $442 | 2,196 |
| Distribution Main | 5664 | P-4248 | EG | River Farm Drive | 8 | Asbestos Cement | 427 | 51 | 1.14 out of 5 | $442 | 188,927 |
| Distribution Main | 6057 | P-4249 | EG | River Farm Drive | 8 | Ductile Iron | 125 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6058 | P-4249 | EG | River Farm Drive | 8 | Ductile Iron | 424 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11850 | P-4247 | EG | River Farm Drive | 8 | Ductile Iron | 396 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11851 | P-4247 | EG | River Farm Drive | 8 | Ductile Iron | 6 | 21 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3452 | P-4083 | EG | River Run | 8 | PVC | 35 | 40 | 0.43 out of 5 | $442 | 15,259 |
| Distribution Main | 3453 | P-4083 | EG | River Run | 8 | PVC | 708 | 40 | 0.43 out of 5 | $442 | 312,995 |
| Distribution Main | 3454 | P-4081 | EG | River Run | 8 | PVC | 115 | 40 | 0.43 out of 5 | $442 | 50,847 |
| Distribution Main | 3455 | P-4081 | EG | River Run | 8 | PVC | 1,058 | 40 | 0.43 out of 5 | $442 | 467,832 |
| Distribution Main | 3457 | P-4084 | EG | River Run | 8 | PVC | 554 | 40 | 0.43 out of 5 | $442 | 244,713 |
| Distribution Main | 6584 | P-4080 | EG | River Run | 8 | PVC | 1,089 | 40 | 0.43 out of 5 | $442 | 481,202 |
| Distribution Main | 6585 | P-4080 | EG | River Run | 8 | PVC | 66 | 40 | 0.43 out of 5 | $442 | 29,175 |
| Distribution Main | 11834 | P-4080 | EG | River Run | 8 | PVC | 85 | 40 | 0.43 out of 5 | $442 | 37,679 |
| Distribution Main | 6373 | P-4048 | EG | Robin Circle | 6 | Asbestos Cement | 398 | 47 | 1.85 out of 5 | $442 | 175,900 |
| Distribution Main | 8314 | P-4816 | EG | Rock Way | 8 | Ductile Iron | 642 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8315 | P-4816 | EG | Rock Way | 8 | Ductile Iron | 97 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8316 | P-4816 | EG | Rock Way | 8 | Ductile Iron | 580 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11855 | P-4816 | EG | Rock Way | 8 | Ductile Iron | 44 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 906 | P-4594 | EG | Rocky Hollow Rd. | 6 | Ductile Iron | 18 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 6258 | P-4694 | EG | Rocky Hollow Rd. | 6 | Ductile Iron | 25 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 6746 | P-4661 | EG | Rocky Hollow Rd. | 8 | Ductile Iron | 143 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6747 | P-4661 | EG | Rocky Hollow Rd. | 8 | Ductile Iron | 52 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6748 | P-4938 | EG | Rocky Hollow Rd. | 8 | Ductile Iron | 74 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6754 | P-4694 | EG | Rocky Hollow Rd. | 8 | Ductile Iron | 152 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11351 | P-4694 | EG | Rocky Hollow Rd. | 8 | Ductile Iron | 34 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9997 | | EG | Rocky Hollow Road | 4 | Ductile Iron | 25 | 13 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 5726 | P-4156 | EG | Romano Ct. | 8 | Ductile Iron | 32 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5727 | P-4156 | EG | Romano Ct. | 8 | Ductile Iron | 629 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3456 | P-4085 | EG | Rosewood Ct. | 8 | PVC | 139 | 40 | 0.43 out of 5 | $442 | 61,593 |
| Distribution Main | 966 | P-4993 | EG | Round Hill Ct | 6 | Unknown | 275 | 35 | 0.85 out of 5 | $442 | 121,439 |
| Distribution Main | 459 | P-4981 | EG | Salley Ann Dr. | 8 | Asbestos Cement | 226 | 35 | 1 out of 5 | $442 | 100,074 |
| Distribution Main | 121 | P-4467 | EG | Sanctuary Dr. | 8 | Ductile Iron | 428 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 122 | P-4467 | EG | Sanctuary Dr. | 8 | Ductile Iron | 44 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4158 | P-4473 | EG | Sanctuary Dr. | 8 | Ductile Iron | 96 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4159 | P-4473 | EG | Sanctuary Dr. | 8 | Ductile Iron | 75 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4160 | P-4474 | EG | Sanctuary Dr. | 8 | Ductile Iron | 406 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4161 | P-4473 | EG | Sanctuary Dr. | 8 | Ductile Iron | 506 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4162 | P-4473 | EG | Sanctuary Dr. | 8 | Ductile Iron | 10 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4500 | P-4467 | EG | Sanctuary Dr. | 8 | Ductile Iron | 5 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4501 | P-4467 | EG | Sanctuary Dr. | 8 | Ductile Iron | 527 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5235 | P-4469 | EG | Sanctuary Dr. | 8 | Ductile Iron | 20 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6154 | P-4469 | EG | Sanctuary Dr. | 8 | Ductile Iron | 290 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6156 | P-4472 | EG | Sanctuary Dr. | 8 | Ductile Iron | 149 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6157 | P-4472 | EG | Sanctuary Dr. | 8 | Ductile Iron | 51 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6337 | P-4467 | EG | Sanctuary Dr. | 8 | Ductile Iron | 5 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10232 | P-4472 | EG | Sanctuary Dr. | 8 | Ductile Iron | 129 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11292 | P-4469 | EG | Sanctuary Dr. | 8 | Ductile Iron | 4 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6301 | P-4442 | EG | Sarah'S Trace | 8 | PVC | 26 | 30 | 0.43 out of 5 | $442 | 11,514 |
| Distribution Main | 6302 | P-4442 | EG | Sarah'S Trace | 8 | PVC | 557 | 30 | 0.43 out of 5 | $442 | 246,156 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9479 | P-4948 | EG | School Ln | 1 | Copper | 151 | UNK | 1.99 out of 5 | $442 | 66,731 |
| Distribution Main | 9480 | P-4948 | EG | School Ln | 1 | Copper | 30 | UNK | 1.99 out of 5 | $442 | 13,433 |
| Transmission Main | 896 | P-4669 | EG | Second St. | 12 | Ductile Iron | 499 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6640 | P-4663 | EG | Second St. | 12 | Ductile Iron | 752 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 8319 | P-4812 | EG | Secret Lane | 8 | Ductile Iron | 350 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5818 | P-4020 | EG | Sheep Farm Dr | 12 | PVC | 716 | 32 | 0.43 out of 5 | $442 | 316,657 |
| Transmission Main | 5819 | P-4020 | EG | Sheep Farm Dr | 12 | PVC | 772 | 32 | 0.43 out of 5 | $442 | 341,202 |
| Transmission Main | 6370 | P-4020 | EG | Sheep Farm Dr | 12 | PVC | 13 | 32 | 0.43 out of 5 | $442 | 5,963 |
| Transmission Main | 5817 | P-40001 | EG | Sheep Farm Dr. | 12 | PVC | 15 | 32 | 0.43 out of 5 | $442 | 6,537 |
| Distribution Main | 5825 | P-4021 | EG | Sheep Farm Dr. | 8 | PVC | 389 | 32 | 0.43 out of 5 | $442 | 171,853 |
| Transmission Main | 6358 | P-40001 | EG | Sheep Farm Dr. | 12 | PVC | 145 | 32 | 0.43 out of 5 | $442 | 64,110 |
| Transmission Main | 6359 | P-40001 | EG | Sheep Farm Dr. | 12 | PVC | 19 | 32 | 0.43 out of 5 | $442 | 8,538 |
| Distribution Main | 6371 | P-4021 | EG | Sheep Farm Dr. | 8 | PVC | 7 | 32 | 0.43 out of 5 | $442 | 3,199 |
| Transmission Main | 1611 | P-4814 | EG | Shippeetown Rd | 12 | Ductile Iron | 480 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1612 | P-4814 | EG | Shippeetown Rd | 12 | Ductile Iron | 60 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3129 | P-4996 | EG | Shippeetown Rd | 12 | Ductile Iron | 29 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4099 | P-4996 | EG | Shippeetown Rd | 12 | Ductile Iron | 7 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8310 | P-4814 | EG | Shippeetown Rd | 12 | Ductile Iron | 14 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8311 | P-4814 | EG | Shippeetown Rd | 12 | Ductile Iron | 14 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8320 | P-4741 | EG | Shippeetown Rd | 12 | Ductile Iron | 515 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8321 | P-4741 | EG | Shippeetown Rd | 12 | Ductile Iron | 46 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8322 | P-4998 | EG | Shippeetown Rd | 8 | Ductile Iron | 24 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10979 | P-4997 | EG | Shippeetown Rd | 12 | Ductile Iron | 27 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11461 | P-4741 | EG | Shippeetown Rd | 12 | Ductile Iron | 27 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11462 | P-4741 | EG | Shippeetown Rd | 12 | Ductile Iron | 169 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 504 | P-4183 | EG | Shippeetown Rd. | 16 | Ductile Iron | 54 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 509 | P-4183 | EG | Shippeetown Rd. | 16 | Ductile Iron | 996 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1614 | P-4814 | EG | Shippeetown Rd. | 12 | Ductile Iron | 647 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2001 | P-4183 | EG | Shippeetown Rd. | 16 | Ductile Iron | 443 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 168 | P-4177 | EG | Signal Ridge Way | 20 | Ductile Iron | 96 | 36 | 0.14 out of 5 | $442 | 42,617 |
| Transmission Main | 169 | P-4177 | EG | Signal Ridge Way | 20 | Ductile Iron | 529 | 36 | 0.14 out of 5 | $442 | 233,666 |
| Transmission Main | 963 | P-4177 | EG | Signal Ridge Way | 20 | Ductile Iron | 18 | 36 | 0.14 out of 5 | $442 | 7,928 |
| Distribution Main | 964 | P-4880 | EG | Signal Ridge Way | 8 | Ductile Iron | 443 | 30 | 0.14 out of 5 | $442 | 195,905 |
| Transmission Main | 971 | P-4176 | EG | Signal Ridge Way | 12 | Asbestos Cement | 504 | 39 | 1 out of 5 | $442 | 222,881 |
| Transmission Main | 972 | P-4176 | EG | Signal Ridge Way | 12 | Asbestos Cement | 48 | 39 | 1 out of 5 | $442 | 21,103 |
| Transmission Main | 973 | P-4173 | EG | Signal Ridge Way | 12 | Asbestos Cement | 311 | 39 | 1 out of 5 | $442 | 137,350 |
| Transmission Main | 2024 | P-4178 | EG | Signal Ridge Way | 12 | Asbestos Cement | 388 | 39 | 1 out of 5 | $442 | 171,631 |
| Transmission Main | 2027 | P-4880 | EG | Signal Ridge Way | 12 | Ductile Iron | 20 | 39 | 0.14 out of 5 | $442 | 9,060 |
| Transmission Main | 2032 | P-4174 | EG | Signal Ridge Way | 12 | Asbestos Cement | 58 | 39 | 1 out of 5 | $442 | 25,777 |
| Transmission Main | 2033 | P-4179 | EG | Signal Ridge Way | 20 | Ductile Iron | 765 | 36 | 0.14 out of 5 | $442 | 338,168 |
| Transmission Main | 2035 | P-4174 | EG | Signal Ridge Way | 12 | Asbestos Cement | 45 | 39 | 1 out of 5 | $442 | 19,752 |
| Transmission Main | 2036 | P-4174 | EG | Signal Ridge Way | 12 | Asbestos Cement | 618 | 39 | 1 out of 5 | $442 | 272,950 |
| Transmission Main | 2039 | P-4173 | EG | Signal Ridge Way | 12 | Asbestos Cement | 10 | 39 | 1 out of 5 | $442 | 4,610 |
| Transmission Main | 2040 | P-4179 | EG | Signal Ridge Way | 20 | Ductile Iron | 761 | 36 | 0.14 out of 5 | $442 | 336,389 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 2041 | P-4179 | EG | Signal Ridge Way | 20 | Ductile Iron | 35 | 36 | 0.14 out of 5 | $442 | 15,663 |
| Transmission Main | 2042 | P-4176 | EG | Signal Ridge Way | 12 | Asbestos Cement | 34 | 39 | 1 out of 5 | $442 | 14,991 |
| Transmission Main | 2043 | P-4179 | EG | Signal Ridge Way | 20 | Ductile Iron | 34 | 36 | 0.14 out of 5 | $442 | 15,130 |
| Transmission Main | 2044 | P-4179 | EG | Signal Ridge Way | 20 | Ductile Iron | 12 | 36 | 0.14 out of 5 | $442 | 5,105 |
| Transmission Main | 9440 | P-4179 | EG | Signal Ridge Way | 20 | Ductile Iron | 390 | 36 | 0.14 out of 5 | $442 | 172,247 |
| Distribution Main | 460 | P-4985 | EG | Silo Lane | 8 | Asbestos Cement | 22 | 35 | 1 out of 5 | $442 | 9,511 |
| Distribution Main | 6379 | P-4985 | EG | Silo Lane | 8 | Asbestos Cement | 130 | 35 | 1 out of 5 | $442 | 57,372 |
| Distribution Main | 10207 | | EG | Silo Lane | 8 | Asbestos Cement | 238 | 35 | 1 out of 5 | $442 | 105,309 |
| Distribution Main | 1815 | | EG | Silverwood Dr. | 6 | Asbestos Cement | 66 | 51 | 1.85 out of 5 | $442 | 29,061 |
| Distribution Main | 3849 | P-4298 | EG | Silverwood Dr. | 6 | Asbestos Cement | 198 | 51 | 1.85 out of 5 | $442 | 87,683 |
| Distribution Main | 5610 | P-4394 | EG | Silverwood Dr. | 6 | Asbestos Cement | 260 | 51 | 1.85 out of 5 | $442 | 114,965 |
| Distribution Main | 5611 | P-4297 | EG | Silverwood Dr. | 6 | Asbestos Cement | 222 | 51 | 1.85 out of 5 | $442 | 98,110 |
| Distribution Main | 6799 | P-4298 | EG | Silverwood Dr. | 6 | Asbestos Cement | 94 | 51 | 1.85 out of 5 | $442 | 41,535 |
| Distribution Main | 10234 | P-4297 | EG | Silverwood Dr. | 6 | Asbestos Cement | 44 | 51 | 1.85 out of 5 | $442 | 19,241 |
| Distribution Main | 662 | P-4668 | EG | Sixth Ave. | 6 | Cast Iron | 12 | 129 | 2.57 out of 5 | $442 | 5,475 |
| Distribution Main | 663 | P-40038 | EG | Sixth Ave. | 6 | Cast Iron | 236 | 129 | 2.57 out of 5 | $442 | 104,390 |
| Distribution Main | 907 | P-4207 | EG | Sixth Ave. | 10 | Ductile Iron | 3 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4267 | P-4668 | EG | Sixth Ave. | 6 | Cast Iron | 11 | 129 | 2.57 out of 5 | $442 | 4,819 |
| Distribution Main | 4268 | P-4668 | EG | Sixth Ave. | 6 | Cast Iron | 219 | 129 | 2.57 out of 5 | $442 | 96,926 |
| Distribution Main | 6203 | P-4667 | EG | Sixth Ave. | 6 | Cast Iron | 218 | 129 | 2.57 out of 5 | $442 | 96,398 |
| Distribution Main | 6204 | P-4943 | EG | Sixth Ave. | 6 | Cast Iron | 464 | 129 | 2.57 out of 5 | $442 | 204,912 |
| Distribution Main | 6205 | P-4943 | EG | Sixth Ave. | 6 | Cast Iron | 14 | 129 | 2.57 out of 5 | $442 | 6,121 |
| Distribution Main | 6249 | P-4207 | EG | Sixth Ave. | 10 | Ductile Iron | 4 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6262 | P-4207 | EG | Sixth Ave. | 10 | Ductile Iron | 6 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6263 | P-4207 | EG | Sixth Ave. | 10 | Ductile Iron | 22 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6636 | P-4207 | EG | Sixth Ave. | 10 | Ductile Iron | 9 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6637 | P-4670 | EG | Sixth Ave. | 12 | Ductile Iron | 212 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 10249 | P-4668 | EG | Sixth Ave. | 12 | Ductile Iron | 13 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9223 | P-40014 | EG | Sleepy Hollow Rd | 8 | Ductile Iron | 603 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9224 | P-4198 | EG | Sleepy Hollow Rd | 8 | Ductile Iron | 376 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9225 | P-4198 | EG | Sleepy Hollow Rd | 8 | Ductile Iron | 38 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10967 | P-40013 | EG | Sleepy Hollow Rd | 8 | Ductile Iron | 324 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9125 | P-4837 | EG | So County Tr | 6 | Ductile Iron | 3 | UNK | 0.71 out of 5 | $442 | 1,218 |
| Transmission Main | 462 | P-4830 | EG | So County Tr. | 12 | Asbestos Cement | 14 | 56 | 1.14 out of 5 | $442 | 6,051 |
| Transmission Main | 1813 | P-4743 | EG | So County Tr. | 12 | Asbestos Cement | 80 | 55 | 1.14 out of 5 | $442 | 35,142 |
| Transmission Main | 3458 | P-4830 | EG | So County Tr. | 12 | Asbestos Cement | 499 | 56 | 1.14 out of 5 | $442 | 220,634 |
| Transmission Main | 3459 | P-4830 | EG | So County Tr. | 12 | Asbestos Cement | 87 | 56 | 1.14 out of 5 | $442 | 38,329 |
| Transmission Main | 5476 | P-4115 | EG | So County Tr. | 12 | Asbestos Cement | 660 | 55 | 1.14 out of 5 | $442 | 291,728 |
| Transmission Main | 5477 | P-4115 | EG | So County Tr. | 12 | Asbestos Cement | 148 | 55 | 1.14 out of 5 | $442 | 65,335 |
| Transmission Main | 5885 | P-4743 | EG | So County Tr. | 12 | Asbestos Cement | 8 | 56 | 1.14 out of 5 | $442 | 3,737 |
| Transmission Main | 5886 | P-4743 | EG | So County Tr. | 12 | Asbestos Cement | 334 | 55 | 1.14 out of 5 | $442 | 147,567 |
| Transmission Main | 5887 | P-4743 | EG | So County Tr. | 12 | Asbestos Cement | 844 | 55 | 1.14 out of 5 | $442 | 373,127 |
| Transmission Main | 5889 | P-4115 | EG | So County Tr. | 12 | Asbestos Cement | 799 | 55 | 1.14 out of 5 | $442 | 353,081 |
| Transmission Main | 5890 | P-4115 | EG | So County Tr. | 12 | Asbestos Cement | 19 | 55 | 1.14 out of 5 | $442 | 8,317 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 5891 | P-4115 | EG | So County Tr. | 12 | Asbestos Cement | 337 | 55 | 1.14 out of 5 | $442 | 149,041 |
| Transmission Main | 5952 | P-4863 | EG | So County Tr. | 12 | Asbestos Cement | 693 | 56 | 1.14 out of 5 | $442 | 306,132 |
| Transmission Main | 6032 | P-4182 | EG | So County Tr. | 12 | Asbestos Cement | 11 | 56 | 1.14 out of 5 | $442 | 5,071 |
| Transmission Main | 6033 | P-4182 | EG | So County Tr. | 12 | Asbestos Cement | 573 | 56 | 1.14 out of 5 | $442 | 253,149 |
| Transmission Main | 6034 | P-4182 | EG | So County Tr. | 12 | Asbestos Cement | 742 | 56 | 1.14 out of 5 | $442 | 327,765 |
| Transmission Main | 6035 | P-4115 | EG | So County Tr. | 12 | Asbestos Cement | 204 | 55 | 1.14 out of 5 | $442 | 90,172 |
| Transmission Main | 6036 | P-4115 | EG | So County Tr. | 12 | Asbestos Cement | 467 | 55 | 1.14 out of 5 | $442 | 206,532 |
| Transmission Main | 6038 | P-4115 | EG | So County Tr. | 12 | Asbestos Cement | 25 | 55 | 1.14 out of 5 | $442 | 10,964 |
| Transmission Main | 6045 | P-4182 | EG | So County Tr. | 12 | Asbestos Cement | 509 | 56 | 1.14 out of 5 | $442 | 224,829 |
| Transmission Main | 6046 | P-4182 | EG | So County Tr. | 12 | Asbestos Cement | 398 | 56 | 1.14 out of 5 | $442 | 175,893 |
| Transmission Main | 6047 | P-4784 | EG | So County Tr. | 12 | Asbestos Cement | 417 | 56 | 1.14 out of 5 | $442 | 184,139 |
| Transmission Main | 6048 | P-4784 | EG | So County Tr. | 12 | Asbestos Cement | 408 | 56 | 1.14 out of 5 | $442 | 180,158 |
| Transmission Main | 6049 | P-4883 | EG | So County Tr. | 12 | Asbestos Cement | 508 | 56 | 1.14 out of 5 | $442 | 224,588 |
| Transmission Main | 6050 | P-4883 | EG | So County Tr. | 12 | Asbestos Cement | 495 | 56 | 1.14 out of 5 | $442 | 218,878 |
| Transmission Main | 6051 | P-4863 | EG | So County Tr. | 12 | Asbestos Cement | 483 | 56 | 1.14 out of 5 | $442 | 213,526 |
| Transmission Main | 6701 | P-4115 | EG | So County Tr. | 12 | Asbestos Cement | 15 | 55 | 1.14 out of 5 | $442 | 6,563 |
| Transmission Main | 6702 | P-4115 | EG | So County Tr. | 12 | Asbestos Cement | 776 | 55 | 1.14 out of 5 | $442 | 343,050 |
| Transmission Main | 6703 | P-4115 | EG | So County Tr. | 12 | Asbestos Cement | 1,151 | 55 | 1.14 out of 5 | $442 | 508,720 |
| Transmission Main | 9707 | | EG | So County Tr. | 12 | Ductile Iron | 13 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9708 | | EG | So County Tr. | 8 | Ductile Iron | 12 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11316 | P-4115 | EG | So County Tr. | 12 | Asbestos Cement | 191 | 55 | 1.14 out of 5 | $442 | 84,385 |
| Transmission Main | 11321 | P-4863 | EG | So County Tr. | 12 | Asbestos Cement | 191 | 56 | 1.14 out of 5 | $442 | 84,574 |
| Transmission Main | 11323 | P-4784 | EG | So County Tr. | 12 | Asbestos Cement | 75 | 56 | 1.14 out of 5 | $442 | 33,293 |
| Transmission Main | 11819 | P-4115 | EG | So County Tr. | 12 | Asbestos Cement | 608 | 55 | 1.14 out of 5 | $442 | 268,806 |
| Transmission Main | 12087 | P-4784 | EG | So County Tr. | 12 | Asbestos Cement | 80 | 56 | 1.14 out of 5 | $442 | 35,390 |
| Transmission Main | 12088 | P-4863 | EG | So County Tr. | 12 | Asbestos Cement | 73 | 56 | 1.14 out of 5 | $442 | 32,367 |
| Distribution Main | 2910 | P-4370 | EG | So. Pierce Rd. | 8 | Ductile Iron | 224 | 36 | 0.14 out of 5 | $442 | 98,855 |
| Distribution Main | 3655 | P-4360 | EG | So. Pierce Rd. | 8 | Ductile Iron | 242 | 36 | 0.14 out of 5 | $442 | 106,803 |
| Distribution Main | 3838 | P-4399 | EG | So. Pierce Rd. | 8 | Ductile Iron | 6 | 36 | 0.14 out of 5 | $442 | 2,601 |
| Distribution Main | 3839 | P-4399 | EG | So. Pierce Rd. | 8 | Ductile Iron | 722 | 36 | 0.14 out of 5 | $442 | 319,202 |
| Distribution Main | 5597 | P-4399 | EG | So. Pierce Rd. | 8 | Ductile Iron | 257 | 36 | 0.14 out of 5 | $442 | 113,733 |
| Distribution Main | 5598 | P-4399 | EG | So. Pierce Rd. | 8 | Ductile Iron | 678 | 36 | 0.14 out of 5 | $442 | 299,861 |
| Distribution Main | 6137 | P-4360 | EG | So. Pierce Rd. | 8 | Ductile Iron | 10 | 36 | 0.14 out of 5 | $442 | 4,501 |
| Distribution Main | 6478 | P-4359 | EG | So. Pierce Rd. | 8 | Ductile Iron | 233 | 36 | 0.14 out of 5 | $442 | 102,916 |
| Distribution Main | 6479 | P-4409 | EG | So. Pierce Rd. | 8 | Ductile Iron | 147 | 36 | 0.14 out of 5 | $442 | 64,858 |
| Distribution Main | 6480 | P-4409 | EG | So. Pierce Rd. | 8 | Ductile Iron | 329 | 36 | 0.14 out of 5 | $442 | 145,323 |
| Distribution Main | 10242 | P-4323 | EG | So. Pierce Rd. | 8 | Ductile Iron | 45 | 36 | 0.14 out of 5 | $442 | 20,054 |
| Distribution Main | 4248 | P-4956 | EG | Somerset St. | 2 | Copper | 313 | 81 | 2.57 out of 5 | $442 | 138,537 |
| Distribution Main | 6644 | P-4952 | EG | Somerset St. | 1.5 | Copper | 247 | 81 | 2.57 out of 5 | $442 | 109,365 |
| Distribution Main | 9009 | P-4951 | EG | Somerset St. | 6 | Ductile Iron | 39 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 5830 | P-4016 | EG | Sonnet Dr. | 8 | PVC | 481 | 32 | 0.43 out of 5 | $442 | 212,420 |
| Distribution Main | 5831 | P-4016 | EG | Sonnet Dr. | 8 | PVC | 132 | 32 | 0.43 out of 5 | $442 | 58,317 |
| Distribution Main | 9349 | | EG | South County Tr | 6 | Ductile Iron | 2 | 8 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9831 | | EG | South County Tr | 8 | Ductile Iron | 6 | 11 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9832 | | EG | South County Tr | 8 | Ductile Iron | 6 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9982 | | EG | South County Tr | 4 | Ductile Iron | 1 | 6 | 1.42 out of 5 | N/A | $0 |
| Transmission Main | 1809 | P-40012 | EG | South County Tr. | 12 | Asbestos Cement | 91 | 56 | 1.14 out of 5 | $442 | 40,079 |
| Transmission Main | 1810 | P-40012 | EG | South County Tr. | 12 | Asbestos Cement | 484 | 56 | 1.14 out of 5 | $442 | 214,034 |
| Transmission Main | 1811 | P-4743 | EG | South County Tr. | 12 | Asbestos Cement | 15 | 56 | 1.14 out of 5 | $442 | 6,684 |
| Transmission Main | 1816 | P-4209 | EG | South County Tr. | 12 | Asbestos Cement | 1,075 | 56 | 1.14 out of 5 | $442 | 474,966 |
| Transmission Main | 1817 | P-4209 | EG | South County Tr. | 12 | Asbestos Cement | 371 | 56 | 1.14 out of 5 | $442 | 163,763 |
| Distribution Main | 4924 | P-4209 | EG | South County Tr. | 10 | HDPE | 536 | 2 | 0.28 out of 5 | N/A | $0 |
| Transmission Main | 5509 | P-4186 | EG | South County Tr. | 12 | Asbestos Cement | 200 | 56 | 1.14 out of 5 | $442 | 88,293 |
| Transmission Main | 5510 | P-4186 | EG | South County Tr. | 12 | Asbestos Cement | 376 | 56 | 1.14 out of 5 | $442 | 166,324 |
| Transmission Main | 5511 | P-4210 | EG | South County Tr. | 12 | Asbestos Cement | 164 | 56 | 1.14 out of 5 | $442 | 72,425 |
| Transmission Main | 5512 | P-4210 | EG | South County Tr. | 12 | Asbestos Cement | 65 | 56 | 1.14 out of 5 | $442 | 28,648 |
| Transmission Main | 5513 | P-40008 | EG | South County Tr. | 12 | Asbestos Cement | 16 | 56 | 1.14 out of 5 | $442 | 6,945 |
| Transmission Main | 5514 | P-40008 | EG | South County Tr. | 12 | Asbestos Cement | 773 | 56 | 1.14 out of 5 | $442 | 341,612 |
| Transmission Main | 5516 | P-4209 | EG | South County Tr. | 12 | Asbestos Cement | 337 | 56 | 1.14 out of 5 | $442 | 148,810 |
| Transmission Main | 5517 | P-4209 | EG | South County Tr. | 12 | Asbestos Cement | 275 | 56 | 1.14 out of 5 | $442 | 121,676 |
| Transmission Main | 5871 | P-40012 | EG | South County Tr. | 12 | Asbestos Cement | 416 | 56 | 1.14 out of 5 | $442 | 183,717 |
| Transmission Main | 5872 | P-40012 | EG | South County Tr. | 12 | Asbestos Cement | 569 | 56 | 1.14 out of 5 | $442 | 251,320 |
| Transmission Main | 6387 | P-40009 | EG | South County Tr. | 12 | Asbestos Cement | 48 | 56 | 1.14 out of 5 | $442 | 21,287 |
| Transmission Main | 6704 | P-4837 | EG | South County Tr. | 12 | Asbestos Cement | 520 | 56 | 1.14 out of 5 | $442 | 229,704 |
| Transmission Main | 6705 | P-4208 | EG | South County Tr. | 12 | Ductile Iron | 1,067 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6706 | | EG | South County Tr. | 12 | Asbestos Cement | 1 | 56 | 1.14 out of 5 | $442 | 338 |
| Transmission Main | 6707 | P-4837 | EG | South County Tr. | 12 | Asbestos Cement | 137 | 56 | 1.14 out of 5 | $442 | 60,769 |
| Transmission Main | 6708 | P-4837 | EG | South County Tr. | 12 | Asbestos Cement | 117 | 56 | 1.14 out of 5 | $442 | 51,914 |
| Transmission Main | 9380 | P-4837 | EG | South County Tr. | 12 | Asbestos Cement | 167 | 56 | 1.14 out of 5 | $442 | 73,876 |
| Transmission Main | 9381 | P-4837 | EG | South County Tr. | 12 | Asbestos Cement | 105 | 56 | 1.14 out of 5 | $442 | 46,569 |
| Transmission Main | 9384 | P-40017 | EG | South County Tr. | 12 | Ductile Iron | 30 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9441 | P-0012 | EG | South County Tr. | 12 | Asbestos Cement | 53 | 56 | 1.14 out of 5 | $442 | 23,315 |
| Transmission Main | 10603 | P-4209 | EG | South County Tr. | 12 | Ductile Iron | 74 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10604 | P-4209 | EG | South County Tr. | 12 | Ductile Iron | 29 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11304 | P-4186 | EG | South County Tr. | 12 | Asbestos Cement | 163 | 56 | 1.14 out of 5 | $442 | 72,161 |
| Transmission Main | 11305 | P-4210 | EG | South County Tr. | 12 | Asbestos Cement | 17 | 56 | 1.14 out of 5 | $442 | 7,543 |
| Transmission Main | 11306 | P-40008 | EG | South County Tr. | 12 | Asbestos Cement | 4 | 56 | 1.14 out of 5 | $442 | 1,798 |
| Transmission Main | 11307 | P-40008 | EG | South County Tr. | 12 | Asbestos Cement | 12 | 56 | 1.14 out of 5 | $442 | 5,358 |
| Transmission Main | 11308 | P-40008 | EG | South County Tr. | 12 | Asbestos Cement | 14 | 56 | 1.14 out of 5 | $442 | 6,223 |
| Transmission Main | 11348 | P-4208 | EG | South County Tr. | 12 | Ductile Iron | 50 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11349 | P-4837 | EG | South County Tr. | 12 | Asbestos Cement | 113 | 56 | 1.14 out of 5 | $442 | 49,851 |
| Transmission Main | 11820 | P-4209 | EG | South County Tr. | 12 | Asbestos Cement | 456 | 56 | 1.14 out of 5 | $442 | 201,466 |
| Transmission Main | 11821 | P-4209 | EG | South County Tr. | 12 | Asbestos Cement | 15 | 56 | 1.14 out of 5 | $442 | 6,712 |
| Transmission Main | 12073 | P-4209 | EG | South County Tr. | 12 | Asbestos Cement | 194 | 56 | 1.14 out of 5 | $442 | 85,937 |
| Transmission Main | 12083 | P-4186 | EG | South County Tr. | 12 | Asbestos Cement | 187 | 56 | 1.14 out of 5 | $442 | 82,582 |
| Transmission Main | 12086 | P-40012 | EG | South County Tr. | 12 | Asbestos Cement | 302 | 56 | 1.14 out of 5 | $442 | 133,621 |
| Distribution Main | 9346 | P-4115 | EG | South County Trail | 8 | Ductile Iron | 4 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9983 | | EG | South County Trail | 6 | Ductile Iron | 3 | 6 | 0.71 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9984 | | EG | South County Trail | 6 | Ductile Iron | 6 | 6 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 10086 | | EG | South County Trail | 12 | Ductile Iron | 72 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6393 | P-40026 | EG | South Pierce Rd. | 20 | Asbestos Cement | 33 | 55 | 1.14 out of 5 | $442 | 14,607 |
| Transmission Main | 6463 | P-4230 | EG | South Pierce Rd. | 20 | Asbestos Cement | 1,395 | 55 | 1.14 out of 5 | $442 | 616,805 |
| Distribution Main | 6000 | P-4025 | EG | Sparrow Ln. | 8 | Ductile Iron | 371 | 26 | 0.14 out of 5 | $442 | 163,854 |
| Distribution Main | 6001 | P-4025 | EG | Sparrow Ln. | 8 | Ductile Iron | 355 | 26 | 0.14 out of 5 | $442 | 156,887 |
| Distribution Main | 9478 | | EG | Spring St | | Unknown | 20 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 305 | P-4925 | EG | Spring St. | 6 | Cast Iron | 337 | 133 | 2.57 out of 5 | $442 | 148,750 |
| Transmission Main | 905 | P-4957 | EG | Spring St. | 12 | Cast Iron | 9 | 133 | 1.86 out of 5 | $442 | 4,198 |
| Distribution Main | 909 | P-4546 | EG | Spring St. | 8 | Ductile Iron | 10 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1902 | P-4575 | EG | Spring St. | 6 | Cast Iron | 74 | 133 | 2.57 out of 5 | $442 | 32,699 |
| Distribution Main | 1903 | P-4556 | EG | Spring St. | 6 | Cast Iron | 168 | 133 | 2.57 out of 5 | $442 | 74,421 |
| Distribution Main | 1904 | P-4556 | EG | Spring St. | 6 | Cast Iron | 14 | 133 | 2.57 out of 5 | $442 | 6,328 |
| Distribution Main | 1905 | P-4547 | EG | Spring St. | 6 | Cast Iron | 81 | 133 | 2.57 out of 5 | $442 | 36,000 |
| Distribution Main | 1906 | P-4546 | EG | Spring St. | 6 | Cast Iron | 388 | 133 | 2.57 out of 5 | $442 | 171,637 |
| Distribution Main | 1907 | P-4546 | EG | Spring St. | 6 | Cast Iron | 294 | 133 | 2.57 out of 5 | $442 | 130,050 |
| Distribution Main | 3666 | P-4573 | EG | Spring St. | 6 | Cast Iron | 145 | 133 | 2.57 out of 5 | $442 | 63,962 |
| Distribution Main | 4378 | P-4920 | EG | Spring St. | 6 | Cast Iron | 19 | 133 | 2.57 out of 5 | $442 | 8,218 |
| Distribution Main | 6218 | P-4605 | EG | Spring St. | 6 | Cast Iron | 350 | 133 | 2.57 out of 5 | $442 | 154,581 |
| Transmission Main | 6219 | P-4957 | EG | Spring St. | 12 | Cast Iron | 41 | 133 | 1.86 out of 5 | $442 | 17,976 |
| Distribution Main | 6222 | P-4556 | EG | Spring St. | 6 | Cast Iron | 28 | 133 | 2.57 out of 5 | $442 | 12,430 |
| Transmission Main | 6223 | P-4582 | EG | Spring St. | 12 | Ductile Iron | 14 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6224 | P-4582 | EG | Spring St. | 12 | Ductile Iron | 6 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6269 | P-4605 | EG | Spring St. | 6 | Cast Iron | 12 | 133 | 2.57 out of 5 | $442 | 5,474 |
| Distribution Main | 6270 | P-4605 | EG | Spring St. | 6 | Cast Iron | 41 | 133 | 2.57 out of 5 | $442 | 18,278 |
| Distribution Main | 6740 | P-4602 | EG | Spring St. | 6 | Cast Iron | 293 | 133 | 2.57 out of 5 | $442 | 129,584 |
| Distribution Main | 6741 | P-4574 | EG | Spring St. | 6 | Cast Iron | 116 | 133 | 2.57 out of 5 | $442 | 51,234 |
| Distribution Main | 6742 | P-4574 | EG | Spring St. | 6 | Cast Iron | 277 | 133 | 2.57 out of 5 | $442 | 122,239 |
| Transmission Main | 6743 | P-4582 | EG | Spring St. | 12 | Ductile Iron | 83 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9019 | P-4546 | EG | Spring St. | 6 | Ductile Iron | 4 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9020 | P-4547 | EG | Spring St. | 6 | Ductile Iron | 4 | 17 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 9310 | P-4573 | EG | Spring St. | 12 | Cast Iron | 6 | 133 | 1.86 out of 5 | $442 | 2,680 |
| Transmission Main | 10984 | P-4582 | EG | Spring St. | 12 | Ductile Iron | 3 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10991 | P-4547 | EG | Spring St. | 8 | Ductile Iron | 10 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11327 | P-4605 | EG | Spring St. | 6 | Cast Iron | 41 | 133 | 2.57 out of 5 | $442 | 18,014 |
| Distribution Main | 370 | P-4223 | EG | Spring Valley Dr. | 8 | Asbestos Cement | 751 | 51 | 1.14 out of 5 | $442 | 331,854 |
| Distribution Main | 371 | P-4223 | EG | Spring Valley Dr. | 8 | Asbestos Cement | 13 | 51 | 1.14 out of 5 | $442 | 5,557 |
| Distribution Main | 600 | P-4222 | EG | Spring Valley Dr. | 8 | Asbestos Cement | 479 | 51 | 1.14 out of 5 | $442 | 211,905 |
| Distribution Main | 5237 | P-4220 | EG | Spring Valley Dr. | 8 | Asbestos Cement | 654 | 51 | 1.14 out of 5 | $442 | 289,063 |
| Distribution Main | 5238 | P-4219 | EG | Spring Valley Dr. | 8 | Asbestos Cement | 232 | 51 | 1.14 out of 5 | $442 | 102,526 |
| Distribution Main | 5239 | P-4219 | EG | Spring Valley Dr. | 8 | Asbestos Cement | 187 | 51 | 1.14 out of 5 | $442 | 82,760 |
| Distribution Main | 5240 | P-4216 | EG | Spring Valley Dr. | 8 | Asbestos Cement | 29 | 51 | 1.14 out of 5 | $442 | 12,963 |
| Distribution Main | 5241 | P-4216 | EG | Spring Valley Dr. | 8 | Asbestos Cement | 830 | 51 | 1.14 out of 5 | $442 | 366,783 |
| Distribution Main | 5242 | P-4215 | EG | Spring Valley Dr. | 8 | Asbestos Cement | 401 | 51 | 1.14 out of 5 | $442 | 177,190 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 5243 | P-4213 | EG | Spring Valley Dr. | 8 | Asbestos Cement | 527 | 51 | 1.14 out of 5 | $442 | 233,044 |
| Distribution Main | 3874 | P-4045 | EG | Squirrel Lane | 8 | Ductile Iron | 38 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5310 | P-4818 | EG | Squirrel Lane | 8 | Ductile Iron | 257 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5311 | P-4817 | EG | Squirrel Lane | 8 | Ductile Iron | 517 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5312 | P-4817 | EG | Squirrel Lane | 8 | Ductile Iron | 80 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 857 | P-4043 | EG | Squirrel Ln. | 8 | Asbestos Cement | 616 | 47 | 1.14 out of 5 | $442 | 272,139 |
| Distribution Main | 6775 | P-4045 | EG | Squirrel Ln. | 8 | Asbestos Cement | 12 | 47 | 1.14 out of 5 | $442 | 5,479 |
| Distribution Main | 6776 | P-4045 | EG | Squirrel Ln. | 8 | Asbestos Cement | 121 | 47 | 1.14 out of 5 | $442 | 53,678 |
| Distribution Main | 3462 | P-4124 | EG | Stoneridge Dr. | 8 | Asbestos Cement | 453 | 44 | 1.14 out of 5 | $442 | 200,353 |
| Distribution Main | 6012 | P-4125 | EG | Stoneridge Dr. | 8 | Asbestos Cement | 492 | 46 | 1.14 out of 5 | $442 | 217,438 |
| Distribution Main | 6013 | P-4125 | EG | Stoneridge Dr. | 8 | Asbestos Cement | 934 | 46 | 1.14 out of 5 | $442 | 412,711 |
| Transmission Main | 6015 | P-4126 | EG | Stoneridge Dr. | 20 | Ductile Iron | 58 | 36 | 0.14 out of 5 | $442 | 25,767 |
| Transmission Main | 6016 | P-4126 | EG | Stoneridge Dr. | 20 | Ductile Iron | 502 | 36 | 0.14 out of 5 | $442 | 221,780 |
| Distribution Main | 6019 | P-4120 | EG | Stoneridge Dr. | 8 | Asbestos Cement | 769 | 46 | 1.14 out of 5 | $442 | 339,876 |
| Distribution Main | 6020 | P-4120 | EG | Stoneridge Dr. | 8 | Asbestos Cement | 518 | 46 | 1.14 out of 5 | $442 | 229,153 |
| Distribution Main | 6021 | P-4125 | EG | Stoneridge Dr. | 8 | Asbestos Cement | 61 | 44 | 1.14 out of 5 | $442 | 26,773 |
| Distribution Main | 6343 | P-4119 | EG | Stoneridge Dr. | 8 | Asbestos Cement | 446 | 46 | 1.14 out of 5 | $442 | 196,946 |
| Distribution Main | 6344 | P-4119 | EG | Stoneridge Dr. | 8 | Asbestos Cement | 34 | 46 | 1.14 out of 5 | $442 | 15,089 |
| Distribution Main | 6576 | P-4120 | EG | Stoneridge Dr. | 8 | Asbestos Cement | 22 | 46 | 1.14 out of 5 | $442 | 9,700 |
| Distribution Main | 6577 | P-4120 | EG | Stoneridge Dr. | 8 | Asbestos Cement | 208 | 46 | 1.14 out of 5 | $442 | 92,141 |
| Distribution Main | 11835 | P-4125 | EG | Stoneridge Dr. | 8 | Asbestos Cement | 455 | 46 | 1.14 out of 5 | $442 | 201,276 |
| Distribution Main | 6027 | P-4218 | EG | Sunset Dr. | 8 | Asbestos Cement | 1,107 | 51 | 1.14 out of 5 | $442 | 489,190 |
| Distribution Main | 3923 | P-4264 | EG | Sycamore Dr. | 8 | Asbestos Cement | 236 | 51 | 1.14 out of 5 | $442 | 104,266 |
| Distribution Main | 3932 | P-4265 | EG | Sycamore Dr. | 8 | Asbestos Cement | 196 | 51 | 1.14 out of 5 | $442 | 86,520 |
| Distribution Main | 4896 | P-4255 | EG | Sycamore Dr. | 8 | Asbestos Cement | 475 | 51 | 1.14 out of 5 | $442 | 210,120 |
| Distribution Main | 6790 | P-4265 | EG | Sycamore Dr. | 8 | Asbestos Cement | 215 | 51 | 1.14 out of 5 | $442 | 94,982 |
| Distribution Main | 6791 | P-4253 | EG | Sycamore Dr. | 8 | Asbestos Cement | 334 | 51 | 1.14 out of 5 | $442 | 147,619 |
| Distribution Main | 6792 | P-4253 | EG | Sycamore Dr. | 8 | Asbestos Cement | 78 | 51 | 1.14 out of 5 | $442 | 34,498 |
| Distribution Main | 3216 | P-4513 | EG | Sylvan Dr. | 6 | Asbestos Cement | 13 | 69 | 2 out of 5 | $442 | 5,527 |
| Distribution Main | 3217 | P-4513 | EG | Sylvan Dr. | 6 | Asbestos Cement | 194 | 69 | 2 out of 5 | $442 | 85,775 |
| Distribution Main | 5423 | P-4510 | EG | Sylvan Dr. | 8 | Asbestos Cement | 343 | 70 | 1.29 out of 5 | $442 | 151,476 |
| Distribution Main | 5618 | P-4506 | EG | Sylvan Dr. | 8 | Asbestos Cement | 249 | 70 | 1.29 out of 5 | $442 | 109,996 |
| Distribution Main | 6348 | P-4511 | EG | Sylvan Dr. | 8 | Asbestos Cement | 48 | 70 | 1.29 out of 5 | $442 | 21,090 |
| Distribution Main | 6349 | P-4511 | EG | Sylvan Dr. | 8 | Asbestos Cement | 587 | 70 | 1.29 out of 5 | $442 | 259,417 |
| Distribution Main | 6561 | P-4505 | EG | Sylvan Dr. | 8 | Asbestos Cement | 287 | 70 | 1.29 out of 5 | $442 | 126,982 |
| Distribution Main | 9097 | P-4506 | EG | Sylvan Dr. | 8 | Asbestos Cement | 19 | 70 | 1.29 out of 5 | $442 | 8,490 |
| Distribution Main | 5953 | P-4478 | EG | Tall Pine Dr. | 8 | Asbestos Cement | 126 | 47 | 1.14 out of 5 | $442 | 55,677 |
| Distribution Main | 5954 | P-4478 | EG | Tall Pine Dr. | 8 | Asbestos Cement | 467 | 47 | 1.14 out of 5 | $442 | 206,447 |
| Distribution Main | 5608 | P-4333 | EG | Tamarack Dr. | 8 | Asbestos Cement | 593 | 50 | 1.14 out of 5 | $442 | 261,940 |
| Distribution Main | 5609 | P-4333 | EG | Tamarack Dr. | 8 | Asbestos Cement | 539 | 50 | 1.14 out of 5 | $442 | 238,215 |
| Distribution Main | 6039 | P-4332 | EG | Tamarack Dr. | 8 | Asbestos Cement | 504 | 50 | 1.14 out of 5 | $442 | 222,976 |
| Distribution Main | 6040 | P-4332 | EG | Tamarack Dr. | 8 | Asbestos Cement | 57 | 50 | 1.14 out of 5 | $442 | 25,316 |
| Distribution Main | 6041 | P-4325 | EG | Tamarack Dr. | 8 | Asbestos Cement | 81 | 50 | 1.14 out of 5 | $442 | 35,641 |
| Distribution Main | 6042 | P-4325 | EG | Tamarack Dr. | 8 | Asbestos Cement | 391 | 50 | 1.14 out of 5 | $442 | 172,989 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3850 | | EG | Tanglewood Dr. | 8 | Unknown | 20 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 4888 | P-4315 | EG | Tanglewood Dr. | 8 | Asbestos Cement | 670 | 60 | 1.14 out of 5 | $442 | 296,105 |
| Distribution Main | 5605 | P-4308 | EG | Tanglewood Dr. | 8 | Asbestos Cement | 374 | 60 | 1.14 out of 5 | $442 | 165,176 |
| Distribution Main | 6408 | P-4302 | EG | Tanglewood Dr. | 8 | Asbestos Cement | 901 | 60 | 1.14 out of 5 | $442 | 398,322 |
| Distribution Main | 6795 | P-4319 | EG | Tanglewood Dr. | 8 | Asbestos Cement | 39 | 60 | 1.14 out of 5 | $442 | 17,290 |
| Distribution Main | 6796 | P-4319 | EG | Tanglewood Dr. | 8 | Asbestos Cement | 112 | 50 | 1.14 out of 5 | $442 | 49,711 |
| Distribution Main | 6802 | P-435 | EG | Tanglewood Dr. | 8 | Asbestos Cement | 53 | 60 | 1.14 out of 5 | $442 | 23,644 |
| Distribution Main | 6803 | P-435 | EG | Tanglewood Dr. | 8 | Asbestos Cement | 36 | 60 | 1.14 out of 5 | $442 | 15,973 |
| Distribution Main | 6805 | P-4313 | EG | Tanglewood Dr. | 8 | Asbestos Cement | 390 | 60 | 1.14 out of 5 | $442 | 172,426 |
| Distribution Main | 6806 | P-4320 | EG | Tanglewood Dr. | 8 | Asbestos Cement | 232 | 60 | 1.14 out of 5 | $442 | 102,635 |
| Distribution Main | 6807 | P-4307 | EG | Tanglewood Dr. | 8 | Asbestos Cement | 314 | 60 | 1.14 out of 5 | $442 | 138,726 |
| Distribution Main | 6808 | P-4307 | EG | Tanglewood Dr. | 8 | Asbestos Cement | 90 | 60 | 1.14 out of 5 | $442 | 39,711 |
| Distribution Main | 6493 | P-4406 | EG | Taylor Cir. | 6 | Asbestos Cement | 244 | 51 | 1.85 out of 5 | $442 | 107,663 |
| Distribution Main | 8604 | P-40024 | EG | Taylor Cir. | 6 | Ductile Iron | 2 | 20 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8605 | P-40024 | EG | Taylor Cir. | 6 | Ductile Iron | 34 | 20 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11341 | P-4406 | EG | Taylor Cir. | 6 | Asbestos Cement | 141 | 51 | 1.85 out of 5 | $442 | 62,152 |
| Distribution Main | 3930 | P-4254 | EG | Teakwood Court | 6 | Asbestos Cement | 347 | 51 | 1.85 out of 5 | $442 | 153,539 |
| Distribution Main | 3931 | P-4254 | EG | Teakwood Court | 6 | Asbestos Cement | 64 | 51 | 1.85 out of 5 | $442 | 28,400 |
| Distribution Main | 6797 | P-4296 | EG | Terrace Dr. | 6 | Asbestos Cement | 820 | 51 | 1.85 out of 5 | $442 | 362,596 |
| Distribution Main | 6798 | P-4296 | EG | Terrace Dr. | 6 | Asbestos Cement | 16 | 51 | 1.85 out of 5 | $442 | 6,957 |
| Distribution Main | 11812 | P-4296 | EG | Terrace Dr. | 6 | Asbestos Cement | 398 | 51 | 1.85 out of 5 | $442 | 175,976 |
| Distribution Main | 4266 | P-40039 | EG | Third St | 6 | Unknown | 151 | 69 | 1.14 out of 5 | $442 | 66,803 |
| Distribution Main | 5208 | P-4665 | EG | Third St. | 6 | Asbestos Cement | 187 | 69 | 2 out of 5 | $442 | 82,856 |
| Distribution Main | 3873 | P-4825 | EG | Tillinghast Rd | 8 | Ductile Iron | 38 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3300 | P-40007 | EG | Tillinghast Rd. | 12 | Ductile Iron | 83 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4367 | P-4821 | EG | Tillinghast Rd. | 12 | Ductile Iron | 504 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4368 | P-4717 | EG | Tillinghast Rd. | 12 | Ductile Iron | 646 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4369 | P-4070 | EG | Tillinghast Rd. | 12 | Ductile Iron | 371 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4370 | P-4070 | EG | Tillinghast Rd. | 12 | Ductile Iron | 49 | 26 | 0.14 out of 5 | $442 | 21,831 |
| Transmission Main | 4371 | P-4821 | EG | Tillinghast Rd. | 12 | Ductile Iron | 84 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4372 | P-4821 | EG | Tillinghast Rd. | 12 | Ductile Iron | 591 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4377 | P-4822 | EG | Tillinghast Rd. | 20 | Ductile Iron | 776 | 26 | 0.14 out of 5 | $442 | 342,834 |
| Transmission Main | 4797 | P-4076 | EG | Tillinghast Rd. | 20 | Ductile Iron | 637 | 36 | 0.14 out of 5 | $442 | 281,578 |
| Transmission Main | 4798 | P-4076 | EG | Tillinghast Rd. | 20 | Ductile Iron | 496 | 36 | 0.14 out of 5 | $442 | 219,019 |
| Transmission Main | 4799 | P-4717 | EG | Tillinghast Rd. | 12 | Ductile Iron | 111 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4800 | P-4078 | EG | Tillinghast Rd. | 20 | Ductile Iron | 1,368 | 36 | 0.14 out of 5 | $442 | 604,489 |
| Transmission Main | 4801 | P-4078 | EG | Tillinghast Rd. | 20 | Ductile Iron | 564 | 36 | 0.14 out of 5 | $442 | 249,466 |
| Transmission Main | 4802 | P-4078 | EG | Tillinghast Rd. | 20 | Ductile Iron | 476 | 36 | 0.14 out of 5 | $442 | 210,487 |
| Transmission Main | 4803 | P-4078 | EG | Tillinghast Rd. | 20 | Ductile Iron | 996 | 36 | 0.14 out of 5 | $442 | 440,307 |
| Transmission Main | 4858 | P-4070 | EG | Tillinghast Rd. | 12 | Ductile Iron | 319 | 26 | 0.14 out of 5 | $442 | 141,056 |
| Transmission Main | 4859 | P-4070 | EG | Tillinghast Rd. | 12 | Ductile Iron | 564 | 26 | 0.14 out of 5 | $442 | 249,439 |
| Transmission Main | 4860 | P-4070 | EG | Tillinghast Rd. | 12 | Ductile Iron | 467 | 26 | 0.14 out of 5 | $442 | 206,506 |
| Transmission Main | 5285 | P-4071 | EG | Tillinghast Rd. | 12 | Ductile Iron | 819 | 26 | 0.14 out of 5 | $442 | 362,027 |
| Transmission Main | 5286 | P-4071 | EG | Tillinghast Rd. | 12 | Ductile Iron | 30 | 19 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 5287 | P-4070 | EG | Tillinghast Rd. | 12 | Ductile Iron | 324 | 26 | 0.14 out of 5 | $442 | 143,405 |
| Transmission Main | 5288 | P-4070 | EG | Tillinghast Rd. | 12 | Ductile Iron | 1,064 | 26 | 0.14 out of 5 | $442 | 470,278 |
| Transmission Main | 5289 | P-4070 | EG | Tillinghast Rd. | 12 | Ductile Iron | 74 | 26 | 0.14 out of 5 | $442 | 32,783 |
| Transmission Main | 5792 | P-4070 | EG | Tillinghast Rd. | 12 | Ductile Iron | 145 | 26 | 0.14 out of 5 | $442 | 64,291 |
| Transmission Main | 5803 | P-4077 | EG | Tillinghast Rd. | 20 | Ductile Iron | 422 | 36 | 0.14 out of 5 | $442 | 186,592 |
| Transmission Main | 5804 | P-4077 | EG | Tillinghast Rd. | 20 | Ductile Iron | 436 | 36 | 0.14 out of 5 | $442 | 192,653 |
| Transmission Main | 6294 | P-4078 | EG | Tillinghast Rd. | 20 | Ductile Iron | 23 | 36 | 0.14 out of 5 | $442 | 10,197 |
| Transmission Main | 9064 | P-4821 | EG | Tillinghast Rd. | 12 | Ductile Iron | 458 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9065 | P-4076 | EG | Tillinghast Rd. | 20 | Ductile Iron | 143 | 36 | 0.14 out of 5 | $442 | 63,127 |
| Transmission Main | 9066 | P-4076 | EG | Tillinghast Rd. | 20 | Ductile Iron | 346 | 36 | 0.14 out of 5 | $442 | 152,886 |
| Transmission Main | 10269 | P-4717 | EG | Tillinghast Rd. | 12 | Ductile Iron | 10 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11251 | P-4070 | EG | Tillinghast Rd. | 12 | Ductile Iron | 19 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11252 | P-4821 | EG | Tillinghast Rd. | 12 | Ductile Iron | 30 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11265 | P-4078 | EG | Tillinghast Rd. | 20 | Ductile Iron | 10 | 36 | 0.14 out of 5 | $442 | 4,527 |
| Transmission Main | 11294 | P-4071 | EG | Tillinghast Rd. | 12 | Ductile Iron | 24 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11836 | P-4078 | EG | Tillinghast Rd. | 20 | Ductile Iron | 15 | 36 | 0.14 out of 5 | $442 | 6,572 |
| Distribution Main | 5307 | P-4820 | EG | Tina Ct | 8 | Ductile Iron | 207 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5308 | P-4820 | EG | Tina Ct | 8 | Ductile Iron | 177 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5309 | P-4819 | EG | Tina Ct | 8 | Ductile Iron | 129 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10267 | P-4820 | EG | Tina Ct | 8 | Ductile Iron | 122 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10268 | P-4820 | EG | Tina Ct | 8 | Ductile Iron | 11 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5603 | P-4311 | EG | Tory Ln. | 6 | Asbestos Cement | 500 | 60 | 2.57 out of 5 | $442 | 220,957 |
| Distribution Main | 5604 | P-4311 | EG | Tory Ln. | 6 | Asbestos Cement | 16 | 60 | 1.85 out of 5 | $442 | 7,237 |
| Distribution Main | 3851 | P-4314 | EG | Trappers Ln. | 6 | Asbestos Cement | 12 | 60 | 1.85 out of 5 | $442 | 5,209 |
| Distribution Main | 3852 | P-4314 | EG | Trappers Ln. | 6 | Asbestos Cement | 390 | 60 | 1.85 out of 5 | $442 | 172,599 |
| Distribution Main | 6123 | P-4328 | EG | Tucker St. | 6 | Asbestos Cement | 509 | 57 | 1.85 out of 5 | $442 | 224,870 |
| Distribution Main | 6466 | P-4328 | EG | Tucker St. | 6 | Asbestos Cement | 3 | 57 | 1.85 out of 5 | $442 | 1,454 |
| Distribution Main | 4163 | P-4493 | EG | Twin Pond Easement | 8 | Ductile Iron | 6 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6151 | P-4475 | EG | Twin Pond Easement | 8 | Ductile Iron | 539 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5000 | P-4492 | EG | Twin Pond Rd. | 6 | Asbestos Cement | 7 | 54 | 1.85 out of 5 | $442 | 3,059 |
| Distribution Main | 5955 | P-4492 | EG | Twin Pond Rd. | 6 | Asbestos Cement | 421 | 54 | 1.85 out of 5 | $442 | 186,263 |
| Distribution Main | 5956 | P-4492 | EG | Twin Pond Rd. | 6 | Asbestos Cement | 159 | 54 | 1.85 out of 5 | $442 | 70,318 |
| Distribution Main | 888 | P-4658 | EG | Union St. | 8 | Ductile Iron | 217 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4249 | P-4934 | EG | Union St. | 8 | Ductile Iron | 75 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6687 | P-4933 | EG | Union St. | 8 | Ductile Iron | 143 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6731 | P-4954 | EG | Union St. | 8 | Ductile Iron | 24 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6750 | P-4658 | EG | Union St. | 8 | Ductile Iron | 20 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4262 | P-4401 | EG | Upland Ave. | 8 | Ductile Iron | 598 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5430 | | EG | Upland Ave. | 6 | Asbestos Cement | 6 | 51 | 1.85 out of 5 | $442 | 2,544 |
| Distribution Main | 5682 | P-4400 | EG | Upland Ave. | 6 | Asbestos Cement | 153 | 51 | 1.85 out of 5 | $442 | 67,682 |
| Distribution Main | 5683 | P-4400 | EG | Upland Ave. | 6 | Asbestos Cement | 54 | 51 | 1.85 out of 5 | $442 | 23,946 |
| Distribution Main | 6250 | P-4400 | EG | Upland Ave. | 6 | Asbestos Cement | 11 | 51 | 1.85 out of 5 | $442 | 4,889 |
| Distribution Main | 9231 | P-4197 | EG | Valley Rd | 8 | Ductile Iron | 27 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9232 | P-4197 | EG | Valley Rd | 8 | Ductile Iron | 965 | 8 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 11559 | P-4189 | EG | Valley Rd | 8 | Ductile Iron | 188 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6562 | P-4507 | EG | Verndale Dr. | 6 | Asbestos Cement | 207 | 71 | 2 out of 5 | $442 | 91,713 |
| Distribution Main | 6563 | P-4507 | EG | Verndale Dr. | 6 | Asbestos Cement | 829 | 71 | 2 out of 5 | $442 | 366,433 |
| Distribution Main | 11343 | P-4507 | EG | Verndale Dr. | 6 | Asbestos Cement | 8 | 71 | 2 out of 5 | $442 | 3,714 |
| Distribution Main | 9473 | P-40033 | EG | Victory St | 1 | Copper | 313 | 50 | 2.28 out of 5 | $442 | 138,141 |
| Distribution Main | 4041 | | EG | Victory St. | 6 | Asbestos Cement | 14 | 50 | 1.85 out of 5 | $442 | 6,175 |
| Distribution Main | 4148 | P-4347 | EG | Victory St. | 6 | Asbestos Cement | 250 | 50 | 1.85 out of 5 | $442 | 110,343 |
| Distribution Main | 4425 | P-4595 | EG | Vine St. | 8 | Ductile Iron | 259 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4252 | P-4805 | EG | Vine Street | 6 | Ductile Iron | 176 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9032 | P-4805 | EG | Vine Street | 8 | Ductile Iron | 17 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9904 | P-4805 | EG | Vine Street | 6 | Ductile Iron | 95 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 6465 | P-4408 | EG | Violet Ct. | 6 | Asbestos Cement | 92 | 51 | 1.85 out of 5 | $442 | 40,657 |
| Distribution Main | 6266 | P-4971 | EG | Virginia Av | 1 | Unknown | 235 | UNK | 1.42 out of 5 | $442 | 103,767 |
| Distribution Main | 6725 | P-4530 | EG | Virginia Ave. | 6 | Asbestos Cement | 734 | 69 | 2 out of 5 | $442 | 324,544 |
| Distribution Main | 6726 | P-4530 | EG | Virginia Ave. | 6 | Asbestos Cement | 41 | 69 | 2 out of 5 | $442 | 17,950 |
| Distribution Main | 3927 | P-4262 | EG | Walnut Dr. | 6 | Asbestos Cement | 169 | 51 | 1.85 out of 5 | $442 | 74,651 |
| Distribution Main | 3928 | P-4262 | EG | Walnut Dr. | 6 | Asbestos Cement | 238 | 51 | 1.85 out of 5 | $442 | 105,382 |
| Distribution Main | 5599 | P-4261 | EG | Walnut Dr. | 6 | Asbestos Cement | 697 | 51 | 1.85 out of 5 | $442 | 308,098 |
| Distribution Main | 2513 | P-4417 | EG | Wanton Shippee Rd. | 6 | Asbestos Cement | 576 | 64 | 2 out of 5 | $442 | 254,569 |
| Distribution Main | 2514 | P-4417 | EG | Wanton Shippee Rd. | 6 | Asbestos Cement | 334 | 64 | 2 out of 5 | $442 | 147,515 |
| Distribution Main | 2030 | P-4175 | EG | Watch Hill | 8 | Asbestos Cement | 60 | 36 | 1 out of 5 | $442 | 26,622 |
| Distribution Main | 2031 | P-4175 | EG | Watch Hill | 8 | Asbestos Cement | 721 | 36 | 1 out of 5 | $442 | 318,742 |
| Distribution Main | 2034 | P-4170 | EG | Watch Hill | 8 | Asbestos Cement | 66 | 36 | 1 out of 5 | $442 | 29,287 |
| Distribution Main | 11840 | P-4175 | EG | Watch Hill | 8 | Asbestos Cement | 687 | 36 | 1 out of 5 | $442 | 303,552 |
| Distribution Main | 11841 | P-4175 | EG | Watch Hill | 8 | Asbestos Cement | 582 | 36 | 1 out of 5 | $442 | 257,154 |
| Distribution Main | 11842 | P-4175 | EG | Watch Hill | 8 | Asbestos Cement | 568 | 36 | 1 out of 5 | $442 | 251,042 |
| Distribution Main | 11843 | P-4175 | EG | Watch Hill | 8 | Asbestos Cement | 688 | 36 | 1 out of 5 | $442 | 304,055 |
| Distribution Main | 12181 | | EG | Watch Hill | 8 | Asbestos Cement | 836 | 36 | 1 out of 5 | $442 | 369,731 |
| Distribution Main | 10327 | P-4632 | EG | Water St | 8 | Ductile Iron | 493 | 4 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10328 | P-4903 | EG | Water St | 6 | Ductile Iron | 4 | 4 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 12131 | P-4632 | EG | Water St | 8 | Ductile Iron | 18 | 4 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5404 | P-4655 | EG | Water St. | 6 | Ductile Iron | 268 | 4 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 6749 | P-4655 | EG | Water St. | 6 | Ductile Iron | 907 | 32 | 0.85 out of 5 | $442 | 401,025 |
| Distribution Main | 10326 | P-4903 | EG | Water St. | 6 | Ductile Iron | 28 | 4 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 910 | P-4962 | EG | West St. | 8 | Ductile Iron | 18 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 911 | P-4554 | EG | West St. | 6 | Cast Iron | 18 | 133 | 2.57 out of 5 | $442 | 8,175 |
| Distribution Main | 912 | P-4554 | EG | West St. | 6 | Cast Iron | 466 | 133 | 2.57 out of 5 | $442 | 206,007 |
| Distribution Main | 3855 | P-4960 | EG | West St. | 8 | Ductile Iron | 25 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5687 | P-4552 | EG | West St. | 6 | Cast Iron | 300 | 133 | 2.57 out of 5 | $442 | 132,725 |
| Distribution Main | 6215 | P-4555 | EG | West St. | 6 | Cast Iron | 6 | 133 | 2.57 out of 5 | $442 | 2,489 |
| Distribution Main | 6216 | P-4555 | EG | West St. | 6 | Cast Iron | 357 | 133 | 2.57 out of 5 | $442 | 157,954 |
| Distribution Main | 6728 | P-4959 | EG | West St. | 8 | Ductile Iron | 15 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9017 | P-4964 | EG | West St. | 6 | Ductile Iron | 4 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9018 | P-4963 | EG | West St. | 6 | Ductile Iron | 5 | 17 | 0.71 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9021 | P-4959 | EG | West St. | 6 | Ductile Iron | 3 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9022 | P-4961 | EG | West St. | 6 | Ductile Iron | 3 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10903 | P-4964 | EG | West St. | 8 | Ductile Iron | 18 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3819 | P-4165 | EG | Westfield Dr | 16 | Ductile Iron | 178 | 28 | 0.14 out of 5 | $442 | 78,872 |
| Transmission Main | 4930 | P-4165 | EG | Westfield Dr | 16 | Ductile Iron | 347 | 28 | 0.14 out of 5 | $442 | 153,256 |
| Transmission Main | 10091 | P-4165 | EG | Westfield Dr | 16 | Ductile Iron | 109 | 28 | 0.14 out of 5 | $442 | 48,292 |
| Transmission Main | 1682 | P-4166 | EG | Westfield Dr. | 16 | Ductile Iron | 60 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2018 | P-4166 | EG | Westfield Dr. | 16 | Ductile Iron | 13 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2019 | P-4166 | EG | Westfield Dr. | 16 | Ductile Iron | 239 | 26 | 0.14 out of 5 | $442 | 105,451 |
| Transmission Main | 2020 | P-4166 | EG | Westfield Dr. | 16 | Ductile Iron | 596 | 26 | 0.14 out of 5 | $442 | 263,380 |
| Transmission Main | 2021 | P-4166 | EG | Westfield Dr. | 16 | Ductile Iron | 283 | 26 | 0.14 out of 5 | $442 | 125,162 |
| Transmission Main | 2022 | P-4166 | EG | Westfield Dr. | 16 | Ductile Iron | 343 | 26 | 0.14 out of 5 | $442 | 151,765 |
| Transmission Main | 2023 | P-4166 | EG | Westfield Dr. | 16 | Ductile Iron | 58 | 26 | 0.14 out of 5 | $442 | 25,705 |
| Distribution Main | 3820 | P-4152 | EG | Westfield Dr. | 8 | Ductile Iron | 780 | 28 | 0.14 out of 5 | $442 | 344,626 |
| Transmission Main | 3833 | P-4166 | EG | Westfield Dr. | 16 | Ductile Iron | 72 | 26 | 0.14 out of 5 | $442 | 31,959 |
| Transmission Main | 3834 | P-4166 | EG | Westfield Dr. | 16 | Ductile Iron | 426 | 26 | 0.14 out of 5 | $442 | 188,291 |
| Transmission Main | 4931 | P-4153 | EG | Westfield Dr. | 16 | Ductile Iron | 390 | 28 | 0.14 out of 5 | $442 | 172,526 |
| Transmission Main | 5781 | P-40041 | EG | Westfield Dr. | 16 | Ductile Iron | 14 | 28 | 0.14 out of 5 | $442 | 5,987 |
| Transmission Main | 5790 | P-4153 | EG | Westfield Dr. | 16 | Ductile Iron | 265 | 28 | 0.14 out of 5 | $442 | 117,018 |
| Transmission Main | 5791 | P-4153 | EG | Westfield Dr. | 16 | Ductile Iron | 56 | 28 | 0.14 out of 5 | $442 | 24,916 |
| Transmission Main | 5892 | P-4153 | EG | Westfield Dr. | 16 | Ductile Iron | 498 | 28 | 0.14 out of 5 | $442 | 220,297 |
| Transmission Main | 5893 | P-4153 | EG | Westfield Dr. | 16 | Ductile Iron | 102 | 28 | 0.14 out of 5 | $442 | 44,936 |
| Distribution Main | 5897 | P-4150 | EG | Westfield Dr. | 8 | Ductile Iron | 287 | 28 | 0.14 out of 5 | $442 | 127,055 |
| Transmission Main | 11236 | P-4166 | EG | Westfield Dr. | 16 | Ductile Iron | 4 | 26 | 0.14 out of 5 | $442 | 1,834 |
| Transmission Main | 11317 | P-4153 | EG | Westfield Dr. | 16 | Ductile Iron | 2 | 28 | 0.14 out of 5 | $442 | 745 |
| Transmission Main | 3324 | P-4231 | EG | Westwood Dr. | 20 | Asbestos Cement | 1,693 | 55 | 1.14 out of 5 | $442 | 748,113 |
| Distribution Main | 4021 | P-4416 | EG | Westwood Dr. | 6 | Asbestos Cement | 37 | 50 | 1.85 out of 5 | $442 | 16,152 |
| Distribution Main | 4022 | P-4416 | EG | Westwood Dr. | 6 | Asbestos Cement | 1,085 | 50 | 1.85 out of 5 | $442 | 479,491 |
| Distribution Main | 9228 | P-4192 | EG | Wildwood Tr | 8 | Ductile Iron | 921 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9319 | P-40015 | EG | Wildwood Tr | 8 | Ductile Iron | 12 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11558 | P-40015 | EG | Wildwood Tr | 8 | Ductile Iron | 182 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3824 | P-4163 | EG | William Corr Way | 8 | Ductile Iron | 487 | 26 | 0.14 out of 5 | $442 | 215,147 |
| Distribution Main | 3825 | P-4163 | EG | William Corr Way | 8 | Ductile Iron | 95 | 26 | 0.14 out of 5 | $442 | 42,032 |
| Distribution Main | 6146 | P-4169 | EG | Winchester Drive | 8 | Asbestos Cement | 418 | 41 | 1.14 out of 5 | $442 | 184,841 |
| Distribution Main | 6147 | P-4169 | EG | Winchester Drive | 8 | Asbestos Cement | 136 | 41 | 1.14 out of 5 | $442 | 60,198 |
| Distribution Main | 6148 | P-4169 | EG | Winchester Drive | 8 | Asbestos Cement | 22 | 41 | 1.14 out of 5 | $442 | 9,653 |
| Distribution Main | 9173 | P-4905 | EG | Wine St | 8 | Ductile Iron | 228 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4030 | P-4383 | EG | Winthrop Road | 6 | Asbestos Cement | 421 | 51 | 1.85 out of 5 | $442 | 186,137 |
| Distribution Main | 4031 | P-4383 | EG | Winthrop Road | 6 | Asbestos Cement | 609 | 51 | 1.85 out of 5 | $442 | 269,166 |
| Distribution Main | 3835 | P-4012 | EG | Wood Duck Ct. | 8 | Ductile Iron | 14 | 27 | 0.14 out of 5 | $442 | 6,279 |
| Distribution Main | 3836 | P-4012 | EG | Wood Duck Ct. | 8 | Ductile Iron | 386 | 27 | 0.14 out of 5 | $442 | 170,730 |
| Distribution Main | 5828 | P-4017 | EG | Woodbridge Dr. | 8 | PVC | 681 | 41 | 0.57 out of 5 | $442 | 300,975 |
| Distribution Main | 5829 | P-4017 | EG | Woodbridge Dr. | 8 | PVC | 814 | 41 | 0.57 out of 5 | $442 | 359,708 |
| Distribution Main | 5832 | P-4017 | EG | Woodbridge Dr. | 8 | PVC | 602 | 41 | 0.57 out of 5 | $442 | 265,981 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6364 | P-4015 | EG | Woodbridge Dr. | 8 | PVC | 360 | 41 | 0.57 out of 5 | $442 | 158,980 |
| Distribution Main | 6365 | P-4015 | EG | Woodbridge Dr. | 8 | PVC | 46 | 41 | 0.57 out of 5 | $442 | 20,212 |
| Distribution Main | 6368 | P-4014 | EG | Woodbridge Dr. | 8 | PVC | 918 | 41 | 0.57 out of 5 | $442 | 405,757 |
| Distribution Main | 6369 | P-4014 | EG | Woodbridge Dr. | 8 | PVC | 23 | 41 | 0.57 out of 5 | $442 | 10,342 |
| Distribution Main | 11832 | P-4014 | EG | Woodbridge Dr. | 8 | PVC | 408 | 41 | 0.57 out of 5 | $442 | 180,354 |
| Distribution Main | 6410 | P-4413 | EG | Woodland Rd. | 6 | Asbestos Cement | 937 | 50 | 1.85 out of 5 | $442 | 414,360 |
| Transmission Main | 9382 | P-40018 | NK | Quaker Ln | 12 | Ductile Iron | 686 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9383 | P-40018 | NK | Quaker Ln | 12 | Ductile Iron | 38 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9385 | | NK | Quaker Ln | 8 | Ductile Iron | 45 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10460 | | NK | Quaker Ln | 12 | Ductile Iron | 562 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11577 | P-40018 | NK | Quaker Ln | 12 | Ductile Iron | 377 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2654 | P-6002 | SCIT | Blossom Ln | 8 | Asbestos Cement | 86 | 46 | 1.14 out of 5 | $442 | 38,073 |
| Distribution Main | 2655 | P-6002 | SCIT | Blossom Ln | 8 | Asbestos Cement | 91 | 46 | 1.14 out of 5 | $442 | 40,153 |
| Distribution Main | 9991 | P-6001 | SCIT | Blossom Ln | 8 | Asbestos Cement | 368 | 46 | 1.14 out of 5 | $442 | 162,598 |
| Distribution Main | 9992 | P-6001 | SCIT | Blossom Ln | 8 | Asbestos Cement | 60 | 46 | 1.14 out of 5 | $442 | 26,645 |
| Distribution Main | 9812 | P-6085 | SCIT | Brown St | 8 | Ductile Iron | 176 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9542 | | SCIT | Clinton Ave | 12 | Ductile Iron | 54 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9543 | P-6086 | SCIT | Clinton Ave | 12 | Ductile Iron | 19 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9544 | | SCIT | Clinton Ave | 12 | Ductile Iron | 27 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1283 | P-6086 | SCIT | Clinton Ave. | 16 | Asbestos Cement | 387 | 47 | 1.14 out of 5 | $442 | 170,922 |
| Transmission Main | 1284 | P-6086 | SCIT | Clinton Ave. | 16 | Asbestos Cement | 436 | 47 | 1.14 out of 5 | $442 | 192,931 |
| Transmission Main | 1865 | | SCIT | Clinton Ave. | 30 | Ductile Iron | 95 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8202 | P-6059 | SCIT | Clinton Ave. | 24 | Ductile Iron | 172 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8203 | P-6059 | SCIT | Clinton Ave. | 24 | Ductile Iron | 545 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8211 | P-6086 | SCIT | Clinton Ave. | 24 | Ductile Iron | 13 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8212 | P-6086 | SCIT | Clinton Ave. | 24 | Ductile Iron | 128 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8254 | P-6059 | SCIT | Clinton Ave. | 16 | Asbestos Cement | 334 | 47 | 1.14 out of 5 | $442 | 147,601 |
| Transmission Main | 8255 | P-6059 | SCIT | Clinton Ave. | 16 | Asbestos Cement | 22 | 47 | 1.14 out of 5 | $442 | 9,513 |
| Transmission Main | 9541 | P-6086 | SCIT | Clinton Ave. | 24 | Ductile Iron | 74 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9545 | P-6059 | SCIT | Clinton Ave. | 24 | Ductile Iron | 7 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9546 | | SCIT | Clinton Ave. | 24 | Ductile Iron | 8 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9547 | P-6086 | SCIT | Clinton Ave. | 24 | Ductile Iron | 25 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10395 | | SCIT | Clinton Ave. | 16 | Ductile Iron | 4 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10396 | | SCIT | Clinton Ave. | 20 | Ductile Iron | 2 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10993 | P-6059 | SCIT | Clinton Ave. | 24 | Ductile Iron | 5 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11113 | P-6086 | SCIT | Clinton Ave. | 16 | Asbestos Cement | 108 | 47 | 1.14 out of 5 | $442 | 47,781 |
| Transmission Main | 11148 | | SCIT | Clinton Ave. | 30 | Ductile Iron | 8 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11449 | P-6059 | SCIT | Clinton Ave. | 24 | Ductile Iron | 15 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11586 | P-6059 | SCIT | Clinton Ave. | 16 | Asbestos Cement | 16 | 47 | 1.14 out of 5 | $442 | 7,099 |
| Transmission Main | 12067 | P-6086 | SCIT | Clinton Ave. | 16 | Asbestos Cement | 2 | 47 | 1.14 out of 5 | $442 | 939 |
| Transmission Main | 12165 | P-6086 | SCIT | Clinton Ave. | 24 | Ductile Iron | 50 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 93 | P-8508 | SCIT | Colvin St. | 20 | Ductile Iron | 51 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8247 | P-8508 | SCIT | Colvin St. | 24 | Ductile Iron | 370 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8248 | P-8508 | SCIT | Colvin St. | 24 | Ductile Iron | 131 | 15 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 8251 | P-6091 | SCIT | Colvin St. | 24 | Ductile Iron | 465 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8252 | P-6091 | SCIT | Colvin St. | 24 | Ductile Iron | 676 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8735 | P-6091 | SCIT | Colvin St. | 24 | Ductile Iron | 343 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10393 | P-6061 | SCIT | Colvin St. | 24 | Ductile Iron | 20 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10394 | P-6061 | SCIT | Colvin St. | 24 | Ductile Iron | 21 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11454 | P-8508 | SCIT | Colvin St. | 24 | Ductile Iron | 57 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9722 | P-6032 | SCIT | Country Ln | 8 | Ductile Iron | 242 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11593 | P-6031 | SCIT | Country Ln | 8 | Ductile Iron | 56 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1273 | P-6027 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 269 | 28 | 0.14 out of 5 | $442 | 118,949 |
| Transmission Main | 1274 | P-6023 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 531 | 28 | 0.14 out of 5 | $442 | 234,782 |
| Transmission Main | 1275 | P-6023 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 328 | 28 | 0.14 out of 5 | $442 | 144,786 |
| Transmission Main | 1277 | P-6027 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 5 | 28 | 0.14 out of 5 | $442 | 2,138 |
| Transmission Main | 1278 | P-6027 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 361 | 28 | 0.14 out of 5 | $442 | 159,489 |
| Transmission Main | 1279 | P-6027 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 125 | 28 | 0.14 out of 5 | $442 | 55,374 |
| Transmission Main | 2565 | P-6023 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 46 | 28 | 0.14 out of 5 | $442 | 20,499 |
| Transmission Main | 2566 | P-6027 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 3 | 28 | 0.14 out of 5 | $442 | 1,376 |
| Transmission Main | 2567 | P-6027 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 115 | 28 | 0.14 out of 5 | $442 | 50,951 |
| Transmission Main | 2568 | | SCIT | Cranberry Dr. | 16 | Ductile Iron | 18 | 28 | 0.14 out of 5 | $442 | 7,913 |
| Transmission Main | 2569 | P-6027 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 339 | 28 | 0.14 out of 5 | $442 | 150,005 |
| Transmission Main | 2572 | P-6027 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 7 | 28 | 0.14 out of 5 | $442 | 3,109 |
| Transmission Main | 2573 | | SCIT | Cranberry Dr. | 16 | Ductile Iron | 28 | 28 | 0.14 out of 5 | $442 | 12,317 |
| Transmission Main | 8708 | P-6025 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 5 | 28 | 0.14 out of 5 | $442 | 2,158 |
| Transmission Main | 8711 | P-6025 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 90 | 28 | 0.14 out of 5 | $442 | 39,616 |
| Transmission Main | 8712 | P-6025 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 243 | 28 | 0.14 out of 5 | $442 | 107,563 |
| Distribution Main | 10599 | P-6023 | SCIT | Cranberry Dr. | 8 | Ductile Iron | 41 | 28 | 0.14 out of 5 | $442 | 18,050 |
| Transmission Main | 11907 | P-6023 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 24 | 28 | 0.14 out of 5 | $442 | 10,562 |
| Transmission Main | 11908 | P-6027 | SCIT | Cranberry Dr. | 16 | Ductile Iron | 48 | 28 | 0.14 out of 5 | $442 | 21,273 |
| Distribution Main | 1282 | P-6050 | SCIT | Doray Dr. | 8 | Asbestos Cement | 257 | 61 | 1.29 out of 5 | $442 | 113,595 |
| Distribution Main | 2665 | P-6051 | SCIT | Doray Dr. | 8 | Asbestos Cement | 299 | 61 | 1.29 out of 5 | $442 | 132,206 |
| Distribution Main | 7535 | P-6130 | SCIT | Eagle Dr | 8 | Ductile Iron | 21 | 28 | 0.14 out of 5 | $442 | 9,188 |
| Distribution Main | 7536 | P-6132 | SCIT | Eagle Dr | 8 | Ductile Iron | 27 | 28 | 0.14 out of 5 | $442 | 12,038 |
| Distribution Main | 7753 | P-6130 | SCIT | Eagle Dr | 8 | Ductile Iron | 10 | 28 | 0.14 out of 5 | $442 | 4,373 |
| Distribution Main | 7754 | P-6130 | SCIT | Eagle Dr | 8 | Ductile Iron | 4 | 28 | 0.14 out of 5 | $442 | 1,716 |
| Distribution Main | 9723 | P-6030 | SCIT | Garden Ln | 8 | Ductile Iron | 458 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9724 | P-6030 | SCIT | Garden Ln | 8 | Ductile Iron | 3 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9810 | P-6084 | SCIT | Goddard St | 8 | Ductile Iron | 231 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9811 | P-6121 | SCIT | Goddard St | 8 | Ductile Iron | 36 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11611 | P-6121 | SCIT | Goddard St | 8 | Ductile Iron | 19 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9809 | P-6084 | SCIT | Goddard St. | 8 | Ductile Iron | 13 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 617 | P-6009 | SCIT | Harrington Ave. | 6 | PVC | 149 | 33 | 1.14 out of 5 | $442 | 65,926 |
| Distribution Main | 618 | P-6008 | SCIT | Harrington Ave. | 6 | Cast Iron | 156 | 83 | 2.43 out of 5 | $442 | 68,926 |
| Distribution Main | 619 | P-6008 | SCIT | Harrington Ave. | 6 | Cast Iron | 389 | 83 | 2.43 out of 5 | $442 | 171,966 |
| Distribution Main | 10083 | P-6009 | SCIT | Harrington Ave. | 8 | Ductile Iron | 35 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11080 | P-6009 | SCIT | Harrington Ave. | 6 | PVC | 5 | 33 | 1.14 out of 5 | $442 | 2,308 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 11903 | P-6008 | SCIT | Harrington Ave. | 6 | Cast Iron | 261 | 83 | 2.43 out of 5 | $442 | 115,240 |
| Distribution Main | 2659 | P-6007 | SCIT | High St. | 6 | PVC | 494 | 33 | 1.14 out of 5 | $442 | 218,257 |
| Distribution Main | 2660 | P-6007 | SCIT | High St. | 6 | PVC | 335 | 33 | 1.14 out of 5 | $442 | 148,282 |
| Distribution Main | 87 | | SCIT | Hill St | 8 | Ductile Iron | 23 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10600 | P-6028 | SCIT | Hope Av | 16 | Ductile Iron | 640 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10601 | P-5119 | SCIT | Hope Av | 16 | Ductile Iron | 3 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10602 | P-5119 | SCIT | Hope Av | 16 | Ductile Iron | 12 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10959 | P-6035 | SCIT | Hope Av | 16 | Ductile Iron | 196 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10960 | P-6022 | SCIT | Hope Av | 16 | Ductile Iron | 205 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9813 | P-6134 | SCIT | Hope Ave | 12 | Ductile Iron | 10 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9814 | P-6134 | SCIT | Hope Ave | 12 | Ductile Iron | 52 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1430 | P-6021 | SCIT | Hope Ave. | 8 | Asbestos Cement | 169 | 52 | 1.14 out of 5 | $442 | 74,791 |
| Distribution Main | 1431 | P-6021 | SCIT | Hope Ave. | 8 | Asbestos Cement | 634 | 52 | 1.14 out of 5 | $442 | 280,245 |
| Distribution Main | 1432 | P-6021 | SCIT | Hope Ave. | 8 | Asbestos Cement | 26 | 52 | 1.14 out of 5 | $442 | 11,545 |
| Transmission Main | 8219 | P-6087 | SCIT | Hope Ave. | 24 | Ductile Iron | 539 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8220 | P-6087 | SCIT | Hope Ave. | 24 | Ductile Iron | 28 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8221 | P-6021 | SCIT | Hope Ave. | 24 | Ductile Iron | 698 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8256 | P-6021 | SCIT | Hope Ave. | 8 | Asbestos Cement | 92 | 52 | 1.14 out of 5 | $442 | 40,490 |
| Distribution Main | 8269 | P-6021 | SCIT | Hope Ave. | 8 | Asbestos Cement | 130 | 52 | 1.14 out of 5 | $442 | 57,468 |
| Distribution Main | 8270 | P-6021 | SCIT | Hope Ave. | 8 | Asbestos Cement | 173 | 52 | 1.14 out of 5 | $442 | 76,267 |
| Distribution Main | 8271 | P-6087 | SCIT | Hope Ave. | 8 | Asbestos Cement | 711 | 52 | 1.14 out of 5 | $442 | 314,478 |
| Distribution Main | 8733 | P-6021 | SCIT | Hope Ave. | 8 | Asbestos Cement | 15 | 52 | 1.14 out of 5 | $442 | 6,730 |
| Transmission Main | 9815 | P-6133 | SCIT | Hope Ave. | 16 | Asbestos Cement | 15 | 63 | 1.29 out of 5 | $442 | 6,843 |
| Transmission Main | 9816 | P-6021 | SCIT | Hope Ave. | 16 | Asbestos Cement | 7 | 63 | 1.29 out of 5 | $442 | 3,032 |
| Distribution Main | 9913 | P-6021 | SCIT | Hope Ave. | 8 | Ductile Iron | 13 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9914 | P-6133 | SCIT | Hope Ave. | 16 | Ductile Iron | 2 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9915 | P-6133 | SCIT | Hope Ave. | 16 | Ductile Iron | 3 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10397 | P-6087 | SCIT | Hope Ave. | 24 | Ductile Iron | 100 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10398 | P-6087 | SCIT | Hope Ave. | 24 | Ductile Iron | 298 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10597 | P-6133 | SCIT | Hope Ave. | 16 | Ductile Iron | 3 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10961 | P-6022 | SCIT | Hope Ave. | 16 | Ductile Iron | 3 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11457 | P-6021 | SCIT | Hope Ave. | 8 | Asbestos Cement | 9 | 52 | 1.14 out of 5 | $442 | 3,850 |
| Transmission Main | 11612 | P-6021 | SCIT | Hope Ave. | 16 | Asbestos Cement | 3 | 63 | 1.29 out of 5 | $442 | 1,148 |
| Distribution Main | 12206 | P-6021 | SCIT | Hope Ave. | 8 | Asbestos Cement | 169 | 52 | 1.14 out of 5 | $442 | 74,735 |
| Transmission Main | 154 | P-6016 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 36 | 28 | 0.14 out of 5 | $442 | 15,719 |
| Transmission Main | 155 | P-6016 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 320 | 28 | 0.14 out of 5 | $442 | 141,499 |
| Distribution Main | 156 | P-6125 | SCIT | Hope Furnace Rd. | 8 | Ductile Iron | 16 | 28 | 0.14 out of 5 | $442 | 7,025 |
| Distribution Main | 157 | P-6123 | SCIT | Hope Furnace Rd. | 8 | Ductile Iron | 26 | 28 | 0.14 out of 5 | $442 | 11,569 |
| Transmission Main | 158 | P-6122 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 280 | 28 | 0.14 out of 5 | $442 | 123,618 |
| Transmission Main | 159 | P-6122 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 185 | 28 | 0.14 out of 5 | $442 | 81,978 |
| Transmission Main | 786 | P-6124 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 369 | 28 | 0.14 out of 5 | $442 | 162,944 |
| Transmission Main | 787 | P-6124 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 205 | 28 | 0.14 out of 5 | $442 | 90,807 |
| Transmission Main | 1102 | P-6016 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 114 | 28 | 0.14 out of 5 | $442 | 50,279 |
| Transmission Main | 1103 | P-6016 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 128 | 28 | 0.14 out of 5 | $442 | 56,741 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 6162 | P-6018 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 175 | 28 | 0.14 out of 5 | $442 | 77,446 |
| Transmission Main | 6163 | P-6018 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 544 | 28 | 0.14 out of 5 | $442 | 240,337 |
| Transmission Main | 6164 | P-6020 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 281 | 28 | 0.14 out of 5 | $442 | 124,266 |
| Transmission Main | 6165 | P-6020 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 176 | 28 | 0.14 out of 5 | $442 | 77,948 |
| Distribution Main | 6166 | P-6126 | SCIT | Hope Furnace Rd. | 8 | Ductile Iron | 10 | 28 | 0.14 out of 5 | $442 | 4,597 |
| Transmission Main | 7703 | P-6018 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 7 | 28 | 0.14 out of 5 | $442 | 2,972 |
| Distribution Main | 7750 | P-6126 | SCIT | Hope Furnace Rd. | 8 | Ductile Iron | 9 | 28 | 0.14 out of 5 | $442 | 3,972 |
| Transmission Main | 7751 | P-6120 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 6 | 28 | 0.14 out of 5 | $442 | 2,860 |
| Distribution Main | 10429 | P-6122 | SCIT | Hope Furnace Rd. | 8 | Asbestos Cement | 26 | 28 | 1 out of 5 | $442 | 11,568 |
| Transmission Main | 11905 | P-6018 | SCIT | Hope Furnace Rd. | 12 | Ductile Iron | 341 | 28 | 0.14 out of 5 | $442 | 150,558 |
| Transmission Main | 88 | P-7891 | SCIT | Hope Furnace Road | 24 | Ductile Iron | 45 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 89 | P-7891 | SCIT | Hope Furnace Road | 24 | Ductile Iron | 6 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6167 | P-6129 | SCIT | Howard Ave. | 12 | Ductile Iron | 45 | 28 | 0.14 out of 5 | $442 | 19,812 |
| Transmission Main | 6168 | P-6129 | SCIT | Howard Ave. | 12 | Ductile Iron | 302 | 28 | 0.14 out of 5 | $442 | 133,662 |
| Distribution Main | 7530 | | SCIT | Howard Ave. | 8 | Unknown | 5 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 7533 | P-6131 | SCIT | Howard Ave. | 12 | Ductile Iron | 38 | 28 | 0.14 out of 5 | $442 | 16,755 |
| Transmission Main | 7534 | P-6131 | SCIT | Howard Ave. | 12 | Ductile Iron | 42 | 28 | 0.14 out of 5 | $442 | 18,557 |
| Transmission Main | 7537 | P-6127 | SCIT | Howard Ave. | 12 | Ductile Iron | 421 | 28 | 0.14 out of 5 | $442 | 186,180 |
| Transmission Main | 7538 | P-6127 | SCIT | Howard Ave. | 12 | Ductile Iron | 78 | 28 | 0.14 out of 5 | $442 | 34,379 |
| Transmission Main | 7539 | P-6127 | SCIT | Howard Ave. | 12 | Ductile Iron | 482 | 28 | 0.14 out of 5 | $442 | 212,962 |
| Transmission Main | 7696 | P-6127 | SCIT | Howard Ave. | 12 | Ductile Iron | 435 | 28 | 0.14 out of 5 | $442 | 192,354 |
| Transmission Main | 7697 | P-6127 | SCIT | Howard Ave. | 12 | Ductile Iron | 31 | 28 | 0.14 out of 5 | $442 | 13,803 |
| Transmission Main | 7698 | P-6019 | SCIT | Howard Ave. | 12 | Ductile Iron | 213 | 28 | 0.14 out of 5 | $442 | 94,261 |
| Transmission Main | 7699 | P-6129 | SCIT | Howard Ave. | 12 | Ductile Iron | 291 | 28 | 0.14 out of 5 | $442 | 128,764 |
| Transmission Main | 7700 | P-6107 | SCIT | Howard Ave. | 12 | Ductile Iron | 512 | 28 | 0.14 out of 5 | $442 | 226,353 |
| Transmission Main | 7701 | P-6107 | SCIT | Howard Ave. | 12 | Ductile Iron | 84 | 28 | 0.14 out of 5 | $442 | 37,333 |
| Transmission Main | 7702 | | SCIT | Howard Ave. | 12 | Ductile Iron | 42 | 28 | 0.14 out of 5 | $442 | 18,623 |
| Transmission Main | 11400 | P-6127 | SCIT | Howard Ave. | 12 | Ductile Iron | 4 | 28 | 0.14 out of 5 | $442 | 1,943 |
| Transmission Main | 11401 | P-6019 | SCIT | Howard Ave. | 12 | Ductile Iron | 29 | 28 | 0.14 out of 5 | $442 | 12,921 |
| Transmission Main | 11906 | P-6127 | SCIT | Howard Ave. | 12 | Ductile Iron | 51 | 28 | 0.14 out of 5 | $442 | 22,721 |
| Distribution Main | 90 | P-6013 | SCIT | Howard Lane | 8 | Ductile Iron | 114 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 614 | P-6081 | SCIT | Ives St. | 6 | Cast Iron | 215 | 80 | 2.28 out of 5 | $442 | 95,076 |
| Distribution Main | 615 | P-6081 | SCIT | Ives St. | 6 | Cast Iron | 29 | 80 | 2.28 out of 5 | $442 | 12,671 |
| Distribution Main | 2650 | P-6082 | SCIT | Ives St. Easement | 4 | Cast Iron | 21 | 80 | 3 out of 5 | $442 | 9,441 |
| Distribution Main | 2651 | P-6082 | SCIT | Ives St. Easement | 4 | Cast Iron | 176 | 80 | 3 out of 5 | $442 | 77,877 |
| Distribution Main | 10569 | | SCIT | Jackson Flat Rd | 8 | Ductile Iron | 720 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 82 | P-6061 | SCIT | Jackson Flat Rd. | 8 | Ductile Iron | 12 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 92 | | SCIT | Jackson Flat Rd. | 8 | Ductile Iron | 69 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 480 | P-6052 | SCIT | Jackson Flat Rd. | 8 | Ductile Iron | 329 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8209 | P-6053 | SCIT | Jackson Flat Rd. | 8 | Ductile Iron | 318 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8210 | P-6053 | SCIT | Jackson Flat Rd. | 8 | Ductile Iron | 19 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8734 | P-6118 | SCIT | Jackson Flat Rd. | 6 | Ductile Iron | 367 | 29 | 0.85 out of 5 | $442 | 162,374 |
| Transmission Main | 8736 | P-6041 | SCIT | Jackson Flat Rd. | 24 | Ductile Iron | 130 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9616 | P-6116 | SCIT | Jackson Flat Rd. | 8 | Asbestos Cement | 57 | UNK | 0.85 out of 5 | $442 | 25,240 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 11904 | P-6053 | SCIT | Jackson Flat Rd. | 8 | Ductile Iron | 50 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 84 | P-6093 | SCIT | Jackson Flat Road | 8 | Ductile Iron | 24 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8213 | P-6093 | SCIT | Jackson Flat Road | 6 | Ductile Iron | 9 | 15 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 726 | P-6026 | SCIT | Kerri Ct. | 16 | Ductile Iron | 12 | 28 | 0.14 out of 5 | $442 | 5,199 |
| Transmission Main | 8709 | P-6026 | SCIT | Kerri Ct. | 16 | Ductile Iron | 382 | 28 | 0.14 out of 5 | $442 | 168,906 |
| Transmission Main | 8710 | P-6026 | SCIT | Kerri Ct. | 16 | Ductile Iron | 221 | 28 | 0.14 out of 5 | $442 | 97,801 |
| Distribution Main | 85 | P-6082 | SCIT | Main St. (Sci) | 8 | Ductile Iron | 20 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8217 | P-6014 | SCIT | Main St. (Sci) | 8 | Ductile Iron | 377 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8218 | P-6014 | SCIT | Main St. (Sci) | 8 | Ductile Iron | 270 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8266 | P-6010 | SCIT | Main St. (Sci) | 8 | Ductile Iron | 333 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8267 | P-6010 | SCIT | Main St. (Sci) | 8 | Ductile Iron | 191 | 52 | 0.29 out of 5 | $442 | 84,525 |
| Distribution Main | 9585 | P-6141 | SCIT | Main St. (Sci) | 8 | Ductile Iron | 117 | 30 | 0.14 out of 5 | $442 | 51,601 |
| Distribution Main | 9586 | P-6141 | SCIT | Main St. (Sci) | 8 | Ductile Iron | 24 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11110 | P-6010 | SCIT | Main St. (Sci) | 8 | Ductile Iron | 10 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11111 | P-6010 | SCIT | Main St. (Sci) | 8 | Ductile Iron | 229 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11112 | P-6010 | SCIT | Main St. (Sci) | 8 | Ductile Iron | 23 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11451 | P-6014 | SCIT | Main St. (Sci) | 8 | Ductile Iron | 244 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12151 | P-6014 | SCIT | Main St. (Sci) | 8 | Ductile Iron | 9 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9720 | P-6029 | SCIT | Meadow Rd | 8 | Ductile Iron | 187 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9721 | P-6034 | SCIT | Meadow Rd | 8 | Ductile Iron | 62 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10598 | P-6029 | SCIT | Meadow Rd | 8 | Ductile Iron | 25 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11591 | P-6034 | SCIT | Meadow Rd | 8 | Ductile Iron | 175 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11592 | P-6034 | SCIT | Meadow Rd | 8 | Ductile Iron | 58 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 86 | P-6013 | SCIT | Mill St | 8 | Ductile Iron | 34 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 616 | | SCIT | Mill St. | 6 | Cast Iron | 46 | 132 | 2.57 out of 5 | $442 | 20,481 |
| Distribution Main | 1238 | P-6013 | SCIT | Mill St. | 6 | Cast Iron | 410 | 132 | 2.57 out of 5 | $442 | 181,263 |
| Distribution Main | 1239 | P-6013 | SCIT | Mill St. | 6 | Cast Iron | 371 | 132 | 2.57 out of 5 | $442 | 164,133 |
| Distribution Main | 8043 | P-6013 | SCIT | Mill St. | 6 | Cast Iron | 128 | 132 | 2.57 out of 5 | $442 | 56,726 |
| Distribution Main | 11902 | P-6013 | SCIT | Mill St. | 6 | Cast Iron | 14 | 132 | 2.57 out of 5 | $442 | 6,090 |
| Distribution Main | 12065 | P-6013 | SCIT | Mill St. | 6 | Cast Iron | 20 | 132 | 2.57 out of 5 | $442 | 8,755 |
| Distribution Main | 91 | P-6080 | SCIT | North Rd. | 8 | Ductile Iron | 45 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 623 | P-6080 | SCIT | North Rd. | 6 | Cast Iron | 124 | 80 | 2.28 out of 5 | $442 | 54,908 |
| Distribution Main | 1190 | P-6012 | SCIT | North Rd. | 6 | PVC | 6 | 33 | 1.14 out of 5 | $442 | 2,785 |
| Distribution Main | 1191 | P-6006 | SCIT | North Rd. | 6 | PVC | 287 | 33 | 1.14 out of 5 | $442 | 126,823 |
| Distribution Main | 1192 | P-6006 | SCIT | North Rd. | 6 | PVC | 95 | 33 | 1.14 out of 5 | $442 | 42,009 |
| Distribution Main | 1193 | P-6004 | SCIT | North Rd. | 6 | PVC | 9 | 33 | 1.14 out of 5 | $442 | 3,871 |
| Distribution Main | 1194 | P-6078 | SCIT | North Rd. | 8 | Asbestos Cement | 558 | 46 | 1.14 out of 5 | $442 | 246,749 |
| Distribution Main | 1195 | P-6078 | SCIT | North Rd. | 8 | Asbestos Cement | 202 | 46 | 1.14 out of 5 | $442 | 89,302 |
| Distribution Main | 1196 | P-6003 | SCIT | North Rd. | 8 | Asbestos Cement | 14 | 47 | 1.14 out of 5 | $442 | 6,116 |
| Distribution Main | 1240 | P-6080 | SCIT | North Rd. | 6 | Cast Iron | 85 | 80 | 2.28 out of 5 | $442 | 37,472 |
| Distribution Main | 2658 | P-6012 | SCIT | North Rd. | 6 | PVC | 376 | 33 | 1.14 out of 5 | $442 | 166,326 |
| Distribution Main | 2661 | P-6006 | SCIT | North Rd. | 6 | PVC | 279 | 33 | 1.14 out of 5 | $442 | 123,483 |
| Distribution Main | 2662 | P-6006 | SCIT | North Rd. | 6 | PVC | 85 | 33 | 1.14 out of 5 | $442 | 37,490 |
| Distribution Main | 2663 | P-6004 | SCIT | North Rd. | 6 | PVC | 301 | 33 | 1.14 out of 5 | $442 | 133,172 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2664 | P-6004 | SCIT | North Rd. | 6 | PVC | 182 | 33 | 1.14 out of 5 | $442 | 80,385 |
| Distribution Main | 2652 | P-6000 | SCIT | Orchard Dr. | 8 | Asbestos Cement | 755 | 46 | 1.14 out of 5 | $442 | 333,590 |
| Distribution Main | 2653 | P-6000 | SCIT | Orchard Dr. | 8 | Asbestos Cement | 287 | 46 | 1.14 out of 5 | $442 | 127,046 |
| Distribution Main | 2656 | P-6000 | SCIT | Orchard Dr. | 8 | Asbestos Cement | 747 | 46 | 1.14 out of 5 | $442 | 330,262 |
| Distribution Main | 2657 | P-6000 | SCIT | Orchard Dr. | 8 | Asbestos Cement | 27 | 46 | 1.14 out of 5 | $442 | 12,126 |
| Transmission Main | 1276 | P-6024 | SCIT | Pasture View Ln. | 16 | Ductile Iron | 1 | 28 | 0.14 out of 5 | $442 | 361 |
| Transmission Main | 2570 | P-6024 | SCIT | Pasture View Ln. | 16 | Ductile Iron | 135 | 28 | 0.14 out of 5 | $442 | 59,732 |
| Transmission Main | 2571 | P-6024 | SCIT | Pasture View Ln. | 16 | Ductile Iron | 344 | 28 | 0.14 out of 5 | $442 | 151,969 |
| Transmission Main | 8707 | P-6024 | SCIT | Pasture View Ln. | 16 | Ductile Iron | 6 | 28 | 0.14 out of 5 | $442 | 2,507 |
| Distribution Main | 71 | P-6049 | SCIT | Patnode Ave | 6 | Ductile Iron | 225 | 26 | 0.85 out of 5 | $442 | 99,543 |
| Distribution Main | 9655 | P-6049 | SCIT | Patnode Ave. | 6 | Asbestos Cement | 298 | 63 | 2 out of 5 | $442 | 131,500 |
| Distribution Main | 622 | P-6120 | SCIT | Reservation Dr. | 6 | Asbestos Cement | 502 | 55 | 1.85 out of 5 | $442 | 221,768 |
| Distribution Main | 7752 | | SCIT | Talbut Rd. | 8 | Ductile Iron | 24 | 28 | 0.14 out of 5 | $442 | 10,512 |
| Distribution Main | 7755 | P-6128 | SCIT | Talbut Rd. | 8 | Ductile Iron | 24 | 28 | 0.14 out of 5 | $442 | 10,450 |
| Distribution Main | 620 | P-6079 | SCIT | White Ln. | 6 | PVC | 4 | 31 | 1.14 out of 5 | $442 | 1,557 |
| Distribution Main | 621 | P-6079 | SCIT | White Ln. | 6 | PVC | 553 | 31 | 1.14 out of 5 | $442 | 244,286 |
| Distribution Main | 3219 | P-2265 | WAR | Abigail St | 6 | Asbestos Cement | 115 | 66 | 2 out of 5 | $442 | 50,653 |
| Distribution Main | 5547 | P-2254 | WAR | Abigail St | 8 | Ductile Iron | 23 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6887 | P-2265 | WAR | Abigail St | 6 | Asbestos Cement | 20 | 66 | 2 out of 5 | $442 | 8,712 |
| Distribution Main | 6888 | P-2265 | WAR | Abigail St | 6 | Asbestos Cement | 453 | 66 | 2 out of 5 | $442 | 200,179 |
| Distribution Main | 10366 | P-2954 | WAR | Abigail St | 6 | Ductile Iron | 13 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9863 | P-2565 | WAR | Adelaide Ave | 8 | Ductile Iron | 266 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9876 | P-2567 | WAR | Adelaide Ave | 8 | Ductile Iron | 310 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9877 | P-2567 | WAR | Adelaide Ave | 8 | Ductile Iron | 641 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11619 | P-2567 | WAR | Adelaide Ave | 8 | Ductile Iron | 84 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7233 | P-2161 | WAR | Alanna Ct | 8 | Ductile Iron | 468 | 29 | 0.14 out of 5 | $442 | 207,064 |
| Distribution Main | 6515 | P-2434 | WAR | Alger Av | 8 | Cast Iron | 36 | 129 | 1.86 out of 5 | $442 | 15,942 |
| Distribution Main | 6850 | P-2434 | WAR | Alger Av | 8 | Cast Iron | 242 | 129 | 1.86 out of 5 | $442 | 107,117 |
| Distribution Main | 10543 | | WAR | Alger Av | 8 | Ductile Iron | 64 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10544 | P-2435 | WAR | Alger Av | 8 | Ductile Iron | 367 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10545 | P-2435 | WAR | Alger Av | 8 | Ductile Iron | 365 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7234 | P-2162 | WAR | Alicia Ct | 8 | Ductile Iron | 396 | 29 | 0.14 out of 5 | $442 | 174,994 |
| Distribution Main | 9279 | P-2877 | WAR | Alvin St | 8 | Ductile Iron | 23 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9716 | P-2878 | WAR | Alvin St | 2 | Copper | 8 | 11 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 9717 | P-2878 | WAR | Alvin St | 2 | Copper | 4 | 11 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 9464 | P-2879 | WAR | Alvin Street | 1.5 | Copper | 362 | 82 | 2.57 out of 5 | $442 | 159,842 |
| Distribution Main | 6988 | P-2512 | WAR | Andover Dr | 6 | Asbestos Cement | 467 | 57 | 1.85 out of 5 | $442 | 206,397 |
| Distribution Main | 7303 | P-2740 | WAR | Ann Nolst Ct. | 8 | Ductile Iron | 300 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7304 | P-2740 | WAR | Ann Nolst Ct. | 8 | Ductile Iron | 153 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7310 | P-2741 | WAR | Ann Nolst Ct. | 8 | Ductile Iron | 24 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7313 | P-2740 | WAR | Ann Nolst Ct. | 8 | Ductile Iron | 48 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7314 | P-2740 | WAR | Ann Nolst Ct. | 8 | Ductile Iron | 139 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9204 | P-2412 | WAR | Arnold Ave | 12 | Ductile Iron | 7 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10401 | P-2412 | WAR | Arnold Ave | 12 | Ductile Iron | 3 | 8 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 10402 | P-2412 | WAR | Arnold Ave | 12 | Ductile Iron | 271 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5204 | P-2600 | WAR | Arnolds Neck Dr. | 8 | Asbestos Cement | 593 | 73 | 1.29 out of 5 | $442 | 261,995 |
| Distribution Main | 5205 | P-2600 | WAR | Arnolds Neck Dr. | 8 | Asbestos Cement | 55 | 73 | 1.29 out of 5 | $442 | 24,367 |
| Distribution Main | 5225 | P-2599 | WAR | Arnolds Neck Dr. | 8 | Asbestos Cement | 353 | 73 | 1.29 out of 5 | $442 | 155,955 |
| Distribution Main | 5565 | P-2423 | WAR | Arnolds Neck Dr. | 8 | Ductile Iron | 446 | 26 | 0.14 out of 5 | $442 | 196,965 |
| Distribution Main | 5566 | P-2423 | WAR | Arnolds Neck Dr. | 8 | Ductile Iron | 275 | 26 | 0.14 out of 5 | $442 | 121,681 |
| Distribution Main | 5638 | P-2601 | WAR | Arnolds Neck Dr. | 8 | Asbestos Cement | 640 | 73 | 1.29 out of 5 | $442 | 282,859 |
| Distribution Main | 5639 | P-2601 | WAR | Arnolds Neck Dr. | 8 | Asbestos Cement | 599 | 73 | 1.29 out of 5 | $442 | 264,587 |
| Distribution Main | 6439 | P-2606 | WAR | Arnolds Neck Dr. | 8 | Asbestos Cement | 194 | 73 | 1.29 out of 5 | $442 | 85,740 |
| Distribution Main | 6441 | P-2605 | WAR | Arnolds Neck Dr. | 8 | Asbestos Cement | 352 | 73 | 1.29 out of 5 | $442 | 155,803 |
| Distribution Main | 6442 | P-2605 | WAR | Arnolds Neck Dr. | 8 | Asbestos Cement | 383 | 73 | 1.29 out of 5 | $442 | 169,447 |
| Distribution Main | 7052 | P-2601 | WAR | Arnolds Neck Dr. | 8 | Asbestos Cement | 7 | 73 | 1.29 out of 5 | $442 | 3,088 |
| Distribution Main | 10947 | P-2423 | WAR | Arnolds Neck Dr. | 8 | Ductile Iron | 606 | 26 | 0.14 out of 5 | $442 | 267,753 |
| Distribution Main | 11926 | P-2600 | WAR | Arnolds Neck Dr. | 8 | Asbestos Cement | 218 | 73 | 1.29 out of 5 | $442 | 96,135 |
| Distribution Main | 11927 | P-2601 | WAR | Arnolds Neck Dr. | 8 | Asbestos Cement | 14 | 73 | 1.29 out of 5 | $442 | 6,307 |
| Distribution Main | 11928 | P-2605 | WAR | Arnolds Neck Dr. | 8 | Asbestos Cement | 23 | 73 | 1.29 out of 5 | $442 | 10,301 |
| Distribution Main | 11931 | P-2423 | WAR | Arnolds Neck Dr. | 8 | Ductile Iron | 43 | 26 | 0.14 out of 5 | $442 | 18,932 |
| Distribution Main | 4462 | P-2121 | WAR | Arrowhead Way | 8 | PVC | 58 | 31 | 0.43 out of 5 | $442 | 25,446 |
| Distribution Main | 4463 | P-2121 | WAR | Arrowhead Way | 8 | PVC | 586 | 31 | 0.43 out of 5 | $442 | 259,116 |
| Distribution Main | 6426 | P-2708 | WAR | Ashmont St. | 6 | Asbestos Cement | 158 | 62 | 2 out of 5 | $442 | 69,863 |
| Distribution Main | 6430 | P-2457 | WAR | Ashmont St. | 6 | Asbestos Cement | 144 | 62 | 2 out of 5 | $442 | 63,630 |
| Distribution Main | 7092 | P-2457 | WAR | Ashmont St. | 6 | Asbestos Cement | 6 | 62 | 2 out of 5 | $442 | 2,518 |
| Distribution Main | 7361 | P-2707 | WAR | Ashmont St. | 8 | Ductile Iron | 243 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10951 | P-2708 | WAR | Ashmont St. | 8 | Ductile Iron | 40 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6851 | P-2415 | WAR | Azalea Ct. | 6 | Asbestos Cement | 14 | 65 | 2 out of 5 | $442 | 6,089 |
| Distribution Main | 6852 | P-2415 | WAR | Azalea Ct. | 6 | Asbestos Cement | 404 | 65 | 2 out of 5 | $442 | 178,379 |
| Distribution Main | 10736 | P-2550 | WAR | Baker St | 8 | Ductile Iron | 390 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10737 | P-2552 | WAR | Baker St | 8 | Ductile Iron | 22 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11715 | P-2552 | WAR | Baker St | 8 | Ductile Iron | 437 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11918 | P-2550 | WAR | Baker St | 8 | Ductile Iron | 71 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10720 | | WAR | Bald Hill Av | 16 | Ductile Iron | 264 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9651 | | WAR | Bald Hill Rd | 10 | Ductile Iron | 13 | 26 | 0.14 out of 5 | $442 | 5,900 |
| Transmission Main | 10699 | | WAR | Bald Hill Rd | 42 | Asbestos Cement | 4,774 | UNK | 0.85 out of 5 | $442 | 2,110,113 |
| Transmission Main | 1359 | P-2231 | WAR | Bald Hill Rd. | 24 | Asbestos Cement | 309 | 35 | 1 out of 5 | $442 | 136,730 |
| Transmission Main | 2682 | P-2231 | WAR | Bald Hill Rd. | 24 | Asbestos Cement | 710 | 35 | 1 out of 5 | $442 | 314,007 |
| Transmission Main | 2683 | P-2231 | WAR | Bald Hill Rd. | 24 | Asbestos Cement | 532 | 35 | 1 out of 5 | $442 | 235,073 |
| Transmission Main | 5355 | P-2667 | WAR | Bald Hill Rd. | 24 | Asbestos Cement | 698 | 35 | 1 out of 5 | $442 | 308,731 |
| Transmission Main | 5356 | P-2667 | WAR | Bald Hill Rd. | 24 | Asbestos Cement | 796 | 35 | 1 out of 5 | $442 | 351,693 |
| Transmission Main | 7443 | P-2896 | WAR | Bald Hill Rd. | 24 | Asbestos Cement | 70 | 35 | 1 out of 5 | $442 | 30,905 |
| Transmission Main | 7764 | P-2667 | WAR | Bald Hill Rd. | 24 | Asbestos Cement | 475 | 35 | 1 out of 5 | $442 | 210,160 |
| Transmission Main | 7765 | P-2667 | WAR | Bald Hill Rd. | 24 | Asbestos Cement | 689 | 35 | 1 out of 5 | $442 | 304,515 |
| Transmission Main | 9493 | P-2667 | WAR | Bald Hill Rd. | 24 | Asbestos Cement | 534 | 35 | 1 out of 5 | $442 | 235,857 |
| Transmission Main | 9494 | P-2667 | WAR | Bald Hill Rd. | 24 | Asbestos Cement | 29 | 35 | 1 out of 5 | $442 | 12,647 |
| Transmission Main | 11183 | P-2231 | WAR | Bald Hill Rd. | 24 | Asbestos Cement | 448 | 35 | 1 out of 5 | $442 | 197,996 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 11582 | P-2667 | WAR | Bald Hill Rd. | 24 | Asbestos Cement | 463 | 35 | 1 out of 5 | $442 | 204,513 |
| Transmission Main | 11922 | P-2667 | WAR | Bald Hill Rd. | 24 | Asbestos Cement | 47 | 35 | 1 out of 5 | $442 | 20,773 |
| Transmission Main | 11924 | P-2231 | WAR | Bald Hill Rd. | 24 | Asbestos Cement | 204 | 35 | 1 out of 5 | $442 | 90,252 |
| Transmission Main | 4394 | | WAR | Bald Hill Rd. Ps | 24 | Asbestos Cement | 110 | 35 | 1 out of 5 | $442 | 48,827 |
| Transmission Main | 4395 | | WAR | Bald Hill Rd. Ps | 24 | Asbestos Cement | 11 | 35 | 1 out of 5 | $442 | 5,015 |
| Transmission Main | 4396 | | WAR | Bald Hill Rd. Ps | 24 | Asbestos Cement | 99 | 35 | 1 out of 5 | $442 | 43,870 |
| Distribution Main | 3413 | P-2864 | WAR | Bald Hill Road | 6 | PVC | 10 | 39 | 1.14 out of 5 | $442 | 4,595 |
| Distribution Main | 5480 | P-2864 | WAR | Bald Hill Road | 6 | PVC | 73 | 39 | 1.14 out of 5 | $442 | 32,293 |
| Distribution Main | 5482 | P-2863 | WAR | Bald Hill Road | 8 | PVC | 117 | 39 | 0.43 out of 5 | $442 | 51,751 |
| Distribution Main | 7470 | P-2863 | WAR | Bald Hill Road | 6 | PVC | 158 | 39 | 1.14 out of 5 | $442 | 70,028 |
| Distribution Main | 7471 | P-2863 | WAR | Bald Hill Road | 6 | PVC | 205 | 39 | 1.14 out of 5 | $442 | 90,562 |
| Distribution Main | 7472 | P-2865 | WAR | Bald Hill Road | 6 | PVC | 111 | 39 | 1.14 out of 5 | $442 | 49,250 |
| Distribution Main | 7473 | P-2864 | WAR | Bald Hill Road | 6 | PVC | 30 | 39 | 1.14 out of 5 | $442 | 13,470 |
| Distribution Main | 4883 | | WAR | Baldwin Rd. | 6 | Asbestos Cement | 160 | 59 | 1.85 out of 5 | $442 | 70,500 |
| Distribution Main | 4884 | P-2011 | WAR | Baldwin Rd. | 6 | Asbestos Cement | 489 | 59 | 1.85 out of 5 | $442 | 215,959 |
| Distribution Main | 4885 | P-2011 | WAR | Baldwin Rd. | 6 | Asbestos Cement | 69 | 59 | 1.85 out of 5 | $442 | 30,511 |
| Distribution Main | 5439 | P-2012 | WAR | Baldwin Rd. | 6 | Asbestos Cement | 3 | 59 | 1.85 out of 5 | $442 | 1,493 |
| Distribution Main | 5440 | P-2012 | WAR | Baldwin Rd. | 6 | Asbestos Cement | 174 | 59 | 1.85 out of 5 | $442 | 77,112 |
| Distribution Main | 6111 | P-2013 | WAR | Baldwin Rd. | 6 | Asbestos Cement | 560 | 59 | 1.85 out of 5 | $442 | 247,658 |
| Distribution Main | 6945 | P-2009 | WAR | Baldwin Rd. | 6 | Asbestos Cement | 490 | 59 | 1.85 out of 5 | $442 | 216,778 |
| Distribution Main | 6962 | P-2017 | WAR | Baldwin Rd. | 6 | Asbestos Cement | 142 | 59 | 1.85 out of 5 | $442 | 62,834 |
| Distribution Main | 6963 | P-2017 | WAR | Baldwin Rd. | 6 | Asbestos Cement | 393 | 59 | 1.85 out of 5 | $442 | 173,597 |
| Distribution Main | 7008 | P-2523 | WAR | Bangor St. | 6 | Asbestos Cement | 474 | 69 | 2 out of 5 | $442 | 209,379 |
| Distribution Main | 7009 | P-2523 | WAR | Bangor St. | 6 | Asbestos Cement | 5 | 69 | 2 out of 5 | $442 | 2,189 |
| Distribution Main | 5494 | P-2587 | WAR | Bay View Ave. | 10 | Cast Iron | 21 | 91 | 1.72 out of 5 | $442 | 9,223 |
| Distribution Main | 5495 | P-2587 | WAR | Bay View Ave. | 10 | Cast Iron | 1,154 | 91 | 1.72 out of 5 | $442 | 510,057 |
| Distribution Main | 5496 | P-2661 | WAR | Bay View Ave. | 6 | Asbestos Cement | 6 | 54 | 1.85 out of 5 | $442 | 2,618 |
| Transmission Main | 6827 | P-2588 | WAR | Bay View Ave. | 12 | Cast Iron | 7 | 91 | 1.72 out of 5 | $442 | 2,922 |
| Transmission Main | 6839 | P-2588 | WAR | Bay View Ave. | 12 | Cast Iron | 6 | 91 | 1.72 out of 5 | $442 | 2,567 |
| Transmission Main | 6849 | P-2592 | WAR | Bay View Ave. | 12 | Cast Iron | 660 | 91 | 1.72 out of 5 | $442 | 291,547 |
| Distribution Main | 6899 | P-2587 | WAR | Bay View Ave. | 10 | Ductile Iron | 5 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6900 | P-2587 | WAR | Bay View Ave. | 12 | Cast Iron | 18 | 91 | 1.72 out of 5 | $442 | 7,928 |
| Transmission Main | 6906 | P-2590 | WAR | Bay View Ave. | 12 | Cast Iron | 67 | 91 | 1.72 out of 5 | $442 | 29,573 |
| Transmission Main | 6907 | P-2590 | WAR | Bay View Ave. | 12 | Cast Iron | 506 | 91 | 1.72 out of 5 | $442 | 223,782 |
| Transmission Main | 6913 | P-2588 | WAR | Bay View Ave. | 12 | Cast Iron | 184 | 91 | 1.72 out of 5 | $442 | 81,455 |
| Distribution Main | 6930 | P-2661 | WAR | Bay View Ave. | 6 | Asbestos Cement | 516 | 54 | 1.85 out of 5 | $442 | 228,123 |
| Distribution Main | 9591 | P-2587 | WAR | Bay View Ave. | 10 | Ductile Iron | 13 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9592 | P-2587 | WAR | Bay View Ave. | 10 | Ductile Iron | 18 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9593 | P-2661 | WAR | Bay View Ave. | 6 | Asbestos Cement | 4 | 54 | 1.85 out of 5 | $442 | 1,653 |
| Distribution Main | 9594 | P-2661 | WAR | Bay View Ave. | 6 | Asbestos Cement | 40 | 54 | 1.85 out of 5 | $442 | 17,601 |
| Distribution Main | 7111 | P-2351 | WAR | Bay Vista Pl. | 2 | Copper | 359 | 55 | 2.28 out of 5 | $442 | 158,612 |
| Distribution Main | 876 | P-2426 | WAR | Beacon Hill Drive | 8 | Asbestos Cement | 223 | 44 | 1.85 out of 5 | $442 | 98,731 |
| Distribution Main | 877 | P-2426 | WAR | Beacon Hill Drive | 8 | Asbestos Cement | 173 | 44 | 1.14 out of 5 | $442 | 76,331 |
| Distribution Main | 10562 | P-2797 | WAR | Becker St | 8 | Ductile Iron | 37 | 2 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10563 | P-2797 | WAR | Becker St | 8 | Ductile Iron | 481 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8638 | P-2921 | WAR | Benefit St. | 1.5 | Copper | 202 | 87 | 2.57 out of 5 | $442 | 89,293 |
| Distribution Main | 8639 | P-2921 | WAR | Benefit St. | 1.5 | Copper | 534 | 87 | 2.57 out of 5 | $442 | 236,149 |
| Distribution Main | 6889 | P-2952 | WAR | Benjamin St | 8 | Asbestos Cement | 19 | 68 | 1.29 out of 5 | $442 | 8,508 |
| Distribution Main | 6908 | P-2269 | WAR | Benjamin St | 6 | Asbestos Cement | 155 | 68 | 2 out of 5 | $442 | 68,469 |
| Distribution Main | 6909 | P-2269 | WAR | Benjamin St | 6 | Asbestos Cement | 554 | 68 | 2 out of 5 | $442 | 244,989 |
| Distribution Main | 6831 | P-2591 | WAR | Berkeley Rd. | 6 | Cast Iron | 208 | 91 | 2.43 out of 5 | $442 | 92,062 |
| Distribution Main | 6898 | P-2591 | WAR | Berkeley Rd. | 6 | Cast Iron | 2 | 91 | 2.43 out of 5 | $442 | 915 |
| Distribution Main | 6922 | P-2591 | WAR | Berkeley Rd. | 6 | Cast Iron | 331 | 91 | 2.43 out of 5 | $442 | 146,368 |
| Distribution Main | 6923 | P-2591 | WAR | Berkeley Rd. | 6 | Cast Iron | 41 | 91 | 2.43 out of 5 | $442 | 18,323 |
| Distribution Main | 6832 | P-2589 | WAR | Beverly Rd. | 6 | Cast Iron | 283 | 80 | 2.28 out of 5 | $442 | 124,979 |
| Distribution Main | 6924 | P-2589 | WAR | Beverly Rd. | 6 | Cast Iron | 7 | 80 | 2.28 out of 5 | $442 | 3,027 |
| Transmission Main | 9164 | P-4898 | WAR | Bicknell Ave | 12 | Ductile Iron | 29 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9303 | P-4898 | WAR | Bicknell Ave | 8 | Ductile Iron | 6 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11550 | P-4898 | WAR | Bicknell Ave | 12 | Ductile Iron | 4 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4477 | P-2075 | WAR | Birkshire Dr. | 8 | Asbestos Cement | 782 | 55 | 1.14 out of 5 | $442 | 345,622 |
| Distribution Main | 4478 | P-2075 | WAR | Birkshire Dr. | 8 | Asbestos Cement | 72 | 55 | 1.14 out of 5 | $442 | 31,728 |
| Distribution Main | 4482 | P-2069 | WAR | Birkshire Dr. | 8 | Asbestos Cement | 312 | 55 | 1.14 out of 5 | $442 | 137,906 |
| Distribution Main | 4483 | P-2069 | WAR | Birkshire Dr. | 8 | Asbestos Cement | 177 | 55 | 1.14 out of 5 | $442 | 78,161 |
| Distribution Main | 6533 | P-2075 | WAR | Birkshire Dr. | 8 | Asbestos Cement | 4 | 55 | 1.14 out of 5 | $442 | 1,678 |
| Distribution Main | 6309 | P-2730 | WAR | Bishop Rd. | 6 | Asbestos Cement | 280 | 50 | 1.85 out of 5 | $442 | 123,685 |
| Distribution Main | 6593 | P-2059 | WAR | Bishop Rd. | 6 | Ductile Iron | 244 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9140 | P-2403 | WAR | Blackmore St | 8 | Ductile Iron | 194 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9141 | P-2403 | WAR | Blackmore St | 8 | Ductile Iron | 309 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9147 | P-2403 | WAR | Blackmore St | 8 | Ductile Iron | 60 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10734 | P-2546 | WAR | Blade St | 6 | Ductile Iron | 456 | 1 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10735 | P-2857 | WAR | Blade St | 6 | Ductile Iron | 661 | 1 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11917 | P-2857 | WAR | Blade St | 6 | Ductile Iron | 217 | 1 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 4864 | P-2250 | WAR | Blair Dr | 8 | Asbestos Cement | 355 | 49 | 1.14 out of 5 | $442 | 156,785 |
| Distribution Main | 7291 | P-2113 | WAR | Blossom Ct | 8 | PVC | 297 | 32 | 0.43 out of 5 | $442 | 131,236 |
| Distribution Main | 5227 | P-2502 | WAR | Blue Hill Dr | 6 | Asbestos Cement | 209 | 65 | 2 out of 5 | $442 | 92,557 |
| Distribution Main | 5228 | P-2502 | WAR | Blue Hill Dr | 6 | Asbestos Cement | 39 | 65 | 2 out of 5 | $442 | 17,045 |
| Distribution Main | 5446 | P-2497 | WAR | Blue Hill Dr | 6 | Asbestos Cement | 214 | 65 | 2 out of 5 | $442 | 94,639 |
| Distribution Main | 5447 | P-2497 | WAR | Blue Hill Dr | 6 | Asbestos Cement | 47 | 65 | 2 out of 5 | $442 | 20,969 |
| Distribution Main | 5449 | P-2501 | WAR | Blue Hill Dr | 6 | Asbestos Cement | 250 | 65 | 2 out of 5 | $442 | 110,396 |
| Distribution Main | 6984 | P-2496 | WAR | Blue Hill Dr | 6 | Asbestos Cement | 290 | 65 | 2 out of 5 | $442 | 128,260 |
| Distribution Main | 9102 | P-2816 | WAR | Blue Hill Dr | 8 | Ductile Iron | 48 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9270 | P-2909 | WAR | Blue Hill Dr | 8 | Ductile Iron | 26 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9932 | P-2816 | WAR | Blue Hill Dr | 8 | Ductile Iron | 56 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6673 | P-2141 | WAR | Blue Ridge Rd | 8 | Ductile Iron | 414 | 29 | 0.14 out of 5 | $442 | 182,790 |
| Distribution Main | 6674 | P-2141 | WAR | Blue Ridge Rd | 8 | Ductile Iron | 74 | 29 | 0.14 out of 5 | $442 | 32,659 |
| Distribution Main | 6675 | P-2146 | WAR | Blue Ridge Rd | 8 | Ductile Iron | 59 | 29 | 0.14 out of 5 | $442 | 26,174 |
| Distribution Main | 6676 | P-2146 | WAR | Blue Ridge Rd | 8 | Ductile Iron | 348 | 29 | 0.14 out of 5 | $442 | 153,659 |
| Distribution Main | 6677 | P-2156 | WAR | Blue Ridge Rd | 8 | Ductile Iron | 337 | 29 | 0.14 out of 5 | $442 | 148,952 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6678 | P-2157 | WAR | Blue Ridge Rd | 8 | Ductile Iron | 119 | 29 | 0.14 out of 5 | $442 | 52,536 |
| Distribution Main | 7228 | P-2156 | WAR | Blue Ridge Rd | 8 | Ductile Iron | 57 | 29 | 0.14 out of 5 | $442 | 25,277 |
| Distribution Main | 7229 | P-2156 | WAR | Blue Ridge Rd | 8 | Ductile Iron | 22 | 29 | 0.14 out of 5 | $442 | 9,838 |
| Distribution Main | 4464 | P-2927 | WAR | Bokar St | 6 | Ductile Iron | 6 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 4465 | P-2927 | WAR | Bokar St | 6 | Ductile Iron | 294 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8630 | P-2462 | WAR | Bokar St | 8 | Ductile Iron | 31 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8631 | P-2462 | WAR | Bokar St | 8 | Ductile Iron | 201 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8632 | P-2468 | WAR | Bokar St | 8 | Ductile Iron | 250 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8634 | P-2927 | WAR | Bokar St | 6 | Ductile Iron | 71 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8635 | P-2471 | WAR | Bokar St | 8 | Ductile Iron | 115 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8636 | P-2927 | WAR | Bokar St | 6 | Ductile Iron | 50 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10203 | P-2468 | WAR | Bokar St | 8 | Ductile Iron | 3 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10369 | P-2927 | WAR | Bokar St | 6 | Ductile Iron | 9 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 759 | P-2051 | WAR | Boulder View Dr. | 8 | Asbestos Cement | 43 | 42 | 1.14 out of 5 | $442 | 19,198 |
| Distribution Main | 760 | P-2051 | WAR | Boulder View Dr. | 8 | Asbestos Cement | 208 | 42 | 1.14 out of 5 | $442 | 92,078 |
| Distribution Main | 5696 | P-2034 | WAR | Boulder View Dr. | 8 | Asbestos Cement | 297 | 42 | 1.14 out of 5 | $442 | 131,327 |
| Distribution Main | 5697 | P-2033 | WAR | Boulder View Dr. | 8 | PVC | 10 | 31 | 0.43 out of 5 | $442 | 4,527 |
| Distribution Main | 7061 | P-2034 | WAR | Boulder View Dr. | 8 | Asbestos Cement | 20 | 42 | 1.14 out of 5 | $442 | 8,843 |
| Distribution Main | 7235 | P-2715 | WAR | Boulder View Dr. | 8 | PVC | 786 | 31 | 0.43 out of 5 | $442 | 347,467 |
| Distribution Main | 9266 | | WAR | Bragger St | 2 | HDPE | 35 | 11 | 1.71 out of 5 | N/A | $0 |
| Distribution Main | 3401 | P-278 | WAR | Brayton Ave. | 8 | Ductile Iron | 605 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3402 | P-278 | WAR | Brayton Ave. | 8 | Ductile Iron | 132 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4388 | P-278 | WAR | Brayton Ave. | 8 | Ductile Iron | 117 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9281 | P-2880 | WAR | Breana Ln | 8 | Ductile Iron | 18 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9293 | P-2880 | WAR | Breana Ln | 8 | Ductile Iron | 2 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5483 | P-2525 | WAR | Breana Ln. | 6 | Ductile Iron | 354 | 31 | 0.85 out of 5 | $442 | 156,524 |
| Distribution Main | 5484 | P-2525 | WAR | Breana Ln. | 6 | Ductile Iron | 141 | 31 | 0.85 out of 5 | $442 | 62,403 |
| Distribution Main | 7384 | P-2541 | WAR | Brian Dr. | 8 | Asbestos Cement | 554 | 55 | 1.14 out of 5 | $442 | 244,759 |
| Distribution Main | 6070 | P-2096 | WAR | Brianwood Ct | 6 | Ductile Iron | 219 | 27 | 0.85 out of 5 | $442 | 96,608 |
| Distribution Main | 6071 | P-2096 | WAR | Brianwood Ct | 6 | Ductile Iron | 25 | 27 | 0.85 out of 5 | $442 | 11,042 |
| Distribution Main | 3323 | P-2663 | WAR | Briarbrook Dr. | 8 | Ductile Iron | 548 | 34 | 0.14 out of 5 | $442 | 242,419 |
| Distribution Main | 6298 | P-2665 | WAR | Briarbrook Dr. | 8 | Ductile Iron | 311 | 34 | 0.14 out of 5 | $442 | 137,632 |
| Distribution Main | 10769 | P-2639 | WAR | Bridal Av | 8 | Ductile Iron | 585 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10896 | P-2640 | WAR | Bridal Av | 8 | Ductile Iron | 228 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10897 | P-2640 | WAR | Bridal Av | 8 | Ductile Iron | 173 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12156 | P-2639 | WAR | Bridal Av | 8 | Ductile Iron | 31 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12167 | P-2639 | WAR | Bridal Av | 8 | Ductile Iron | 21 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4517 | P-2945 | WAR | Brier Court | 2 | Copper | 245 | 79 | 2.43 out of 5 | $442 | 108,176 |
| Distribution Main | 6082 | P-2108 | WAR | Brightwater Dr. | 8 | PVC | 65 | 32 | 0.43 out of 5 | $442 | 28,943 |
| Distribution Main | 6083 | P-2108 | WAR | Brightwater Dr. | 8 | PVC | 655 | 32 | 0.43 out of 5 | $442 | 289,702 |
| Distribution Main | 8290 | P-2813 | WAR | Broadbent St | 8 | Ductile Iron | 86 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8291 | P-2813 | WAR | Broadbent St | 8 | Ductile Iron | 155 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2840 | P-2207 | WAR | Brookline Dr. | 8 | PVC | 45 | 31 | 0.43 out of 5 | $442 | 19,765 |
| Distribution Main | 2841 | P-2207 | WAR | Brookline Dr. | 8 | PVC | 45 | 31 | 0.43 out of 5 | $442 | 19,758 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3304 | P-2186 | WAR | Brookline Dr. | 8 | PVC | 406 | 31 | 0.43 out of 5 | $442 | 179,663 |
| Distribution Main | 5456 | P-2208 | WAR | Brookline Dr. | 8 | PVC | 93 | 31 | 0.43 out of 5 | $442 | 41,005 |
| Distribution Main | 6653 | P-2207 | WAR | Brookline Dr. | 8 | PVC | 527 | 31 | 0.43 out of 5 | $442 | 233,044 |
| Distribution Main | 6654 | P-2208 | WAR | Brookline Dr. | 8 | PVC | 79 | 31 | 0.43 out of 5 | $442 | 34,929 |
| Distribution Main | 6655 | P-2208 | WAR | Brookline Dr. | 8 | PVC | 403 | 31 | 0.43 out of 5 | $442 | 178,106 |
| Distribution Main | 6656 | P-2205 | WAR | Brookline Dr. | 8 | PVC | 243 | 31 | 0.43 out of 5 | $442 | 107,615 |
| Distribution Main | 10494 | | WAR | Brookside Dr | 8 | Ductile Iron | 5 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7334 | P-2344 | WAR | Bruce Ln. | 6 | Asbestos Cement | 203 | 73 | 2 out of 5 | $442 | 89,582 |
| Distribution Main | 7335 | P-2344 | WAR | Bruce Ln. | 6 | Asbestos Cement | 371 | 73 | 2 out of 5 | $442 | 164,202 |
| Distribution Main | 10738 | P-2551 | WAR | Burton St | 8 | Ductile Iron | 302 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2239 | P-2644 | WAR | Cactus St. | 8 | Asbestos Cement | 17 | 63 | 1.29 out of 5 | $442 | 7,316 |
| Distribution Main | 4427 | P-2642 | WAR | Cactus St. | 8 | Asbestos Cement | 160 | 63 | 1.29 out of 5 | $442 | 70,614 |
| Distribution Main | 4428 | P-2642 | WAR | Cactus St. | 8 | Asbestos Cement | 70 | 63 | 1.29 out of 5 | $442 | 31,160 |
| Distribution Main | 4429 | P-2641 | WAR | Cactus St. | 8 | Asbestos Cement | 419 | 63 | 1.29 out of 5 | $442 | 185,071 |
| Distribution Main | 4431 | P-2644 | WAR | Cactus St. | 8 | Asbestos Cement | 61 | 63 | 1.29 out of 5 | $442 | 26,926 |
| Distribution Main | 6423 | P-2475 | WAR | Calhoun Ave. | 6 | Ductile Iron | 239 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 7251 | P-2477 | WAR | Calhoun Ave. | 6 | Ductile Iron | 142 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 7252 | P-2477 | WAR | Calhoun Ave. | 6 | Ductile Iron | 45 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 2839 | P-2936 | WAR | Candle Hill Court | 1.5 | Copper | 318 | 63 | 2.43 out of 5 | $442 | 140,687 |
| Distribution Main | 5452 | P-2500 | WAR | Cardinal St. | 6 | Asbestos Cement | 11 | 65 | 2 out of 5 | $442 | 4,726 |
| Distribution Main | 6990 | P-2500 | WAR | Cardinal St. | 6 | Asbestos Cement | 31 | 65 | 2 out of 5 | $442 | 13,616 |
| Distribution Main | 6991 | P-2500 | WAR | Cardinal St. | 6 | Asbestos Cement | 363 | 65 | 2 out of 5 | $442 | 160,276 |
| Distribution Main | 7024 | P-2026 | WAR | Carriage Hill Dr. | 8 | Asbestos Cement | 7 | 39 | 1 out of 5 | $442 | 3,096 |
| Distribution Main | 7048 | P-2026 | WAR | Carriage Hill Dr. | 8 | Asbestos Cement | 21 | 39 | 1 out of 5 | $442 | 9,424 |
| Distribution Main | 7057 | P-2026 | WAR | Carriage Hill Dr. | 6 | Asbestos Cement | 126 | 39 | 1.71 out of 5 | $442 | 55,714 |
| Distribution Main | 7058 | P-2026 | WAR | Carriage Hill Dr. | 6 | Asbestos Cement | 199 | 39 | 1.71 out of 5 | $442 | 87,749 |
| Distribution Main | 3407 | P-2695 | WAR | Carrs Ln. | 6 | Ductile Iron | 270 | 28 | 0.85 out of 5 | $442 | 119,219 |
| Distribution Main | 3412 | | WAR | Carrs Ln. | 6 | Ductile Iron | 79 | 28 | 0.85 out of 5 | $442 | 34,775 |
| Distribution Main | 7478 | P-2695 | WAR | Carrs Ln. | 6 | Ductile Iron | 34 | 28 | 0.85 out of 5 | $442 | 15,191 |
| Distribution Main | 7479 | | WAR | Carrs Ln. | 6 | Ductile Iron | 6 | 28 | 0.85 out of 5 | $442 | 2,809 |
| Distribution Main | 7480 | P-2695 | WAR | Carrs Ln. | 8 | Ductile Iron | 18 | 28 | 0.14 out of 5 | $442 | 7,741 |
| Distribution Main | 7481 | P-2695 | WAR | Carrs Ln. | 8 | Ductile Iron | 220 | 28 | 0.14 out of 5 | $442 | 97,109 |
| Distribution Main | 8637 | P-2695 | WAR | Carrs Ln. | 6 | Ductile Iron | 11 | 28 | 0.85 out of 5 | $442 | 4,950 |
| Distribution Main | 9276 | P-2884 | WAR | Carson Ave | 8 | Ductile Iron | 13 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9277 | P-2884 | WAR | Carson Ave | 8 | Ductile Iron | 2 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9291 | P-2886 | WAR | Carson Ave | 6 | Ductile Iron | 3 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 5485 | P-2490 | WAR | Carson Ave. | 6 | Asbestos Cement | 4 | 47 | 1.85 out of 5 | $442 | 1,825 |
| Distribution Main | 5486 | P-2490 | WAR | Carson Ave. | 6 | Asbestos Cement | 370 | 47 | 1.85 out of 5 | $442 | 163,668 |
| Distribution Main | 7084 | P-2491 | WAR | Carson Ave. | 6 | Asbestos Cement | 156 | 47 | 1.85 out of 5 | $442 | 69,018 |
| Distribution Main | 7358 | P-2943 | WAR | Carvin Court | 2 | Copper | 181 | 79 | 2.43 out of 5 | $442 | 79,976 |
| Distribution Main | 2515 | P-2218 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 463 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2516 | P-2222 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 219 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2517 | P-2222 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 34 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2518 | P-2219 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 54 | 21 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4595 | P-2223 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 309 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4596 | P-2223 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 5 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4597 | P-2219 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 80 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4598 | P-2219 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 152 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4599 | P-2219 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 439 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5969 | P-2223 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 199 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5970 | P-2222 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 254 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5971 | P-2221 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 24 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5972 | P-2221 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 445 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5973 | P-2219 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 226 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5974 | P-2222 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 428 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5975 | P-2222 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 167 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5976 | P-2218 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 7 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10182 | P-2222 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 90 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10350 | P-2222 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 191 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11322 | P-2221 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 4 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11967 | P-2222 | WAR | Castle Rocks Rd. | 8 | Ductile Iron | 78 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5448 | P-2498 | WAR | Caverly St. | 6 | Asbestos Cement | 401 | 64 | 2 out of 5 | $442 | 177,065 |
| Distribution Main | 6992 | P-2498 | WAR | Caverly St. | 6 | Asbestos Cement | 12 | 64 | 2 out of 5 | $442 | 5,327 |
| Distribution Main | 11302 | P-2498 | WAR | Caverly St. | 6 | Asbestos Cement | 9 | 64 | 2 out of 5 | $442 | 3,838 |
| Distribution Main | 6815 | P-2594 | WAR | Cedar St. | 6 | Asbestos Cement | 1,067 | 53 | 1.85 out of 5 | $442 | 471,554 |
| Distribution Main | 6816 | P-2595 | WAR | Cedar St. | 6 | Cast Iron | 17 | 83 | 2.43 out of 5 | $442 | 7,722 |
| Distribution Main | 6855 | P-2695 | WAR | Cedar St. | 6 | Cast Iron | 685 | 83 | 2.43 out of 5 | $442 | 302,878 |
| Distribution Main | 6856 | P-2695 | WAR | Cedar St. | 6 | Cast Iron | 856 | 83 | 2.43 out of 5 | $442 | 378,414 |
| Distribution Main | 6876 | P-2594 | WAR | Cedar St. | 6 | Asbestos Cement | 16 | 53 | 1.85 out of 5 | $442 | 6,924 |
| Distribution Main | 6877 | P-2597 | WAR | Cedar St. | 8 | Ductile Iron | 21 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9595 | P-2594 | WAR | Cedar St. | 6 | Ductile Iron | 26 | 22 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 9269 | P-2906 | WAR | Centennial St | 8 | Ductile Iron | 28 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9289 | P-2907 | WAR | Centennial St | 6 | Ductile Iron | 3 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 5703 | P-2486 | WAR | Centennial St. | 6 | Asbestos Cement | 240 | 77 | 2 out of 5 | $442 | 106,276 |
| Distribution Main | 7033 | P-2484 | WAR | Centennial St. | 6 | Asbestos Cement | 184 | 77 | 2 out of 5 | $442 | 81,149 |
| Transmission Main | 1741 | P-2420 | WAR | Centerville Rd. | 12 | Ductile Iron | 203 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 1742 | P-2420 | WAR | Centerville Rd. | 12 | Ductile Iron | 71 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 11142 | P-2420 | WAR | Centerville Rd. | 12 | Ductile Iron | 9 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 9696 | | WAR | Centerville Rd | 10 | Ductile Iron | 20 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10756 | P-2420 | WAR | Centerville Rd | 12 | Ductile Iron | 62 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10757 | P-2420 | WAR | Centerville Rd | 12 | Ductile Iron | 18 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1740 | P-2685 | WAR | Centerville Rd. | 12 | Cast Iron | 293 | 91 | 1.72 out of 5 | $442 | 129,502 |
| Transmission Main | 2579 | P-2427 | WAR | Centerville Rd. | 12 | Asbestos Cement | 874 | 61 | 1.29 out of 5 | $442 | 386,500 |
| Distribution Main | 3594 | P-2749 | WAR | Centerville Rd. | 8 | Cast Iron | 9 | 87 | 1.72 out of 5 | $442 | 3,985 |
| Distribution Main | 3595 | P-2722 | WAR | Centerville Rd. | 8 | Cast Iron | 216 | 87 | 1.72 out of 5 | $442 | 95,418 |
| Distribution Main | 3596 | P-2722 | WAR | Centerville Rd. | 8 | Cast Iron | 46 | 87 | 1.72 out of 5 | $442 | 20,432 |
| Distribution Main | 4057 | P-2427 | WAR | Centerville Rd. | 8 | Asbestos Cement | 248 | 61 | 1.29 out of 5 | $442 | 109,435 |
| Transmission Main | 4380 | P-2485 | WAR | Centerville Rd. | 12 | Cast Iron | 262 | 91 | 1.72 out of 5 | $442 | 115,877 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 4381 | P-2485 | WAR | Centerville Rd. | 12 | Cast Iron | 25 | 91 | 1.72 out of 5 | $442 | 11,201 |
| Transmission Main | 4880 | P-2784 | WAR | Centerville Rd. | 12 | Asbestos Cement | 862 | 61 | 1.29 out of 5 | $442 | 380,977 |
| Transmission Main | 4881 | P-2784 | WAR | Centerville Rd. | 12 | Asbestos Cement | 456 | 61 | 1.29 out of 5 | $442 | 201,666 |
| Transmission Main | 4886 | P-2020 | WAR | Centerville Rd. | 12 | Asbestos Cement | 264 | 61 | 1.29 out of 5 | $442 | 116,805 |
| Transmission Main | 4887 | P-2020 | WAR | Centerville Rd. | 12 | Asbestos Cement | 512 | 61 | 1.29 out of 5 | $442 | 226,200 |
| Distribution Main | 5220 | P-2768 | WAR | Centerville Rd. | 8 | Cast Iron | 346 | 87 | 1.72 out of 5 | $442 | 152,717 |
| Distribution Main | 5221 | P-2024 | WAR | Centerville Rd. | 8 | Asbestos Cement | 177 | 65 | 1.29 out of 5 | $442 | 78,176 |
| Distribution Main | 5222 | P-2024 | WAR | Centerville Rd. | 8 | Asbestos Cement | 401 | 65 | 1.29 out of 5 | $442 | 177,171 |
| Distribution Main | 5223 | P-2768 | WAR | Centerville Rd. | 8 | Cast Iron | 15 | 87 | 1.72 out of 5 | $442 | 6,631 |
| Transmission Main | 5433 | P-2018 | WAR | Centerville Rd. | 12 | Asbestos Cement | 359 | 61 | 1.29 out of 5 | $442 | 158,686 |
| Transmission Main | 5435 | P-2004 | WAR | Centerville Rd. | 12 | Asbestos Cement | 49 | 61 | 1.29 out of 5 | $442 | 21,588 |
| Transmission Main | 5436 | P-2004 | WAR | Centerville Rd. | 12 | Asbestos Cement | 399 | 61 | 1.29 out of 5 | $442 | 176,554 |
| Transmission Main | 5437 | P-2020 | WAR | Centerville Rd. | 12 | Asbestos Cement | 112 | 61 | 1.29 out of 5 | $442 | 49,584 |
| Transmission Main | 5438 | P-2020 | WAR | Centerville Rd. | 12 | Asbestos Cement | 9 | 61 | 1.29 out of 5 | $442 | 3,850 |
| Transmission Main | 5444 | P-2021 | WAR | Centerville Rd. | 12 | Asbestos Cement | 74 | 61 | 1.29 out of 5 | $442 | 32,587 |
| Transmission Main | 5445 | P-2021 | WAR | Centerville Rd. | 12 | Asbestos Cement | 168 | 61 | 1.29 out of 5 | $442 | 74,282 |
| Transmission Main | 6093 | P-2023 | WAR | Centerville Rd. | 12 | Asbestos Cement | 656 | 61 | 1.29 out of 5 | $442 | 290,042 |
| Transmission Main | 6110 | | WAR | Centerville Rd. | 12 | Asbestos Cement | 4 | 61 | 1.29 out of 5 | $442 | 1,690 |
| Transmission Main | 6159 | P-2024 | WAR | Centerville Rd. | 12 | Asbestos Cement | 998 | 61 | 1.29 out of 5 | $442 | 441,209 |
| Transmission Main | 6160 | P-2024 | WAR | Centerville Rd. | 12 | Asbestos Cement | 18 | 61 | 1.29 out of 5 | $442 | 7,783 |
| Transmission Main | 6946 | P-2021 | WAR | Centerville Rd. | 12 | Asbestos Cement | 16 | 61 | 1.29 out of 5 | $442 | 7,114 |
| Transmission Main | 6975 | P-2004 | WAR | Centerville Rd. | 12 | Asbestos Cement | 253 | 61 | 1.29 out of 5 | $442 | 111,797 |
| Transmission Main | 6976 | P-2004 | WAR | Centerville Rd. | 12 | Asbestos Cement | 205 | 61 | 1.29 out of 5 | $442 | 90,501 |
| Distribution Main | 6998 | P-2749 | WAR | Centerville Rd. | 8 | Cast Iron | 135 | 87 | 1.72 out of 5 | $442 | 59,672 |
| Distribution Main | 7042 | P-2024 | WAR | Centerville Rd. | 8 | Asbestos Cement | 16 | 65 | 1.29 out of 5 | $442 | 6,923 |
| Distribution Main | 7043 | P-2768 | WAR | Centerville Rd. | 8 | Cast Iron | 2 | 87 | 1.72 out of 5 | $442 | 953 |
| Distribution Main | 7044 | P-2768 | WAR | Centerville Rd. | 8 | Cast Iron | 7 | 87 | 1.72 out of 5 | $442 | 2,903 |
| Distribution Main | 7045 | P-2721 | WAR | Centerville Rd. | 8 | Cast Iron | 462 | 87 | 1.72 out of 5 | $442 | 204,368 |
| Transmission Main | 7086 | P-2024 | WAR | Centerville Rd. | 12 | Asbestos Cement | 105 | 65 | 1.29 out of 5 | $442 | 46,322 |
| Transmission Main | 7207 | P-2000 | WAR | Centerville Rd. | 12 | Asbestos Cement | 381 | 61 | 1.29 out of 5 | $442 | 168,183 |
| Transmission Main | 7208 | P-2000 | WAR | Centerville Rd. | 12 | Asbestos Cement | 553 | 61 | 1.29 out of 5 | $442 | 244,570 |
| Distribution Main | 10358 | P-2427 | WAR | Centerville Rd. | 8 | Asbestos Cement | 121 | 61 | 1.29 out of 5 | $442 | 53,393 |
| Transmission Main | 10359 | P-2427 | WAR | Centerville Rd. | 12 | Asbestos Cement | 19 | 61 | 1.29 out of 5 | $442 | 8,208 |
| Transmission Main | 10360 | P-2427 | WAR | Centerville Rd. | 12 | Asbestos Cement | 40 | 61 | 1.29 out of 5 | $442 | 17,837 |
| Distribution Main | 10711 | P-2024 | WAR | Centerville Rd. | 8 | Asbestos Cement | 427 | 65 | 1.29 out of 5 | $442 | 188,885 |
| Distribution Main | 10712 | P-2024 | WAR | Centerville Rd. | 8 | Ductile Iron | 8 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10949 | P-2024 | WAR | Centerville Rd. | 12 | Asbestos Cement | 58 | 65 | 1.29 out of 5 | $442 | 25,800 |
| Distribution Main | 10995 | P-2024 | WAR | Centerville Rd. | 8 | Ductile Iron | 4 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11272 | P-2020 | WAR | Centerville Rd. | 12 | Asbestos Cement | 71 | 61 | 1.29 out of 5 | $442 | 31,505 |
| Transmission Main | 11324 | P-2023 | WAR | Centerville Rd. | 12 | Asbestos Cement | 8 | 61 | 1.29 out of 5 | $442 | 3,691 |
| Transmission Main | 11362 | P-2000 | WAR | Centerville Rd. | 12 | Asbestos Cement | 234 | 61 | 1.29 out of 5 | $442 | 103,408 |
| Transmission Main | 11654 | P-2427 | WAR | Centerville Rd. | 12 | Asbestos Cement | 14 | 61 | 1.29 out of 5 | $442 | 6,100 |
| Distribution Main | 11936 | P-2024 | WAR | Centerville Rd. | 8 | Asbestos Cement | 168 | 65 | 1.29 out of 5 | $442 | 74,209 |
| Distribution Main | 4577 | P-2397 | WAR | Chace St. | 8 | Ductile Iron | 10 | 32 | 0.14 out of 5 | $442 | 4,283 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6879 | P-2396 | WAR | Chace St. | 8 | Ductile Iron | 265 | 32 | 0.14 out of 5 | $442 | 117,290 |
| Distribution Main | 6883 | P-2397 | WAR | Chace St. | 8 | Ductile Iron | 215 | 32 | 0.14 out of 5 | $442 | 94,983 |
| Distribution Main | 7011 | P-2517 | WAR | Chapel St. | 6 | Asbestos Cement | 454 | 69 | 2 out of 5 | $442 | 200,535 |
| Distribution Main | 6853 | P-2440 | WAR | Chepiwonxet Way | 8 | Ductile Iron | 255 | 35 | 0.14 out of 5 | $442 | 112,632 |
| Distribution Main | 6854 | P-2440 | WAR | Chepiwonxet Way | 8 | Ductile Iron | 328 | 35 | 0.14 out of 5 | $442 | 145,192 |
| Distribution Main | 5471 | P-2393 | WAR | Chevy Ct. | 2 | Copper | 238 | 64 | 2.43 out of 5 | $442 | 105,256 |
| Distribution Main | 7356 | P-2393 | WAR | Chevy Ct. | 2 | Copper | 53 | 64 | 2.43 out of 5 | $442 | 23,586 |
| Distribution Main | 10559 | P-2303 | WAR | Cindy Ln | 8 | Ductile Iron | 463 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10560 | P-2303 | WAR | Cindy Ln | 8 | Ductile Iron | 471 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10561 | P-2304 | WAR | Cindy Ln | 8 | Ductile Iron | 57 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11674 | P-2304 | WAR | Cindy Ln | 8 | Ductile Iron | 277 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6443 | P-2479 | WAR | Clyde Ave. | 6 | Asbestos Cement | 7 | 52 | 1.85 out of 5 | $442 | 3,309 |
| Distribution Main | 7089 | P-2479 | WAR | Clyde Ave. | 6 | Asbestos Cement | 395 | 52 | 1.85 out of 5 | $442 | 174,681 |
| Distribution Main | 1232 | P-2202 | WAR | Cobble Hill Rd. | 8 | Asbestos Cement | 155 | 59 | 1.14 out of 5 | $442 | 68,406 |
| Distribution Main | 3620 | P-2147 | WAR | Cobble Hill Rd. | 8 | Asbestos Cement | 60 | 59 | 1.14 out of 5 | $442 | 26,710 |
| Distribution Main | 3622 | P-2145 | WAR | Cobble Hill Rd. | 8 | Asbestos Cement | 46 | 59 | 1.14 out of 5 | $442 | 20,553 |
| Distribution Main | 3623 | P-2145 | WAR | Cobble Hill Rd. | 8 | Asbestos Cement | 541 | 59 | 1.14 out of 5 | $442 | 239,240 |
| Distribution Main | 5472 | P-2151 | WAR | Cobble Hill Rd. | 8 | Asbestos Cement | 199 | 59 | 1.14 out of 5 | $442 | 87,824 |
| Distribution Main | 5750 | P-2145 | WAR | Cobble Hill Rd. | 8 | Asbestos Cement | 402 | 59 | 1.14 out of 5 | $442 | 177,830 |
| Distribution Main | 11946 | P-2145 | WAR | Cobble Hill Rd. | 8 | Asbestos Cement | 49 | 59 | 1.14 out of 5 | $442 | 21,612 |
| Distribution Main | 3625 | P-2201 | WAR | Cobble Hill Road | 8 | Asbestos Cement | 125 | 59 | 1.14 out of 5 | $442 | 55,402 |
| Distribution Main | 3626 | P-2201 | WAR | Cobble Hill Road | 8 | Asbestos Cement | 153 | 59 | 1.14 out of 5 | $442 | 67,775 |
| Distribution Main | 5777 | P-2178 | WAR | Cobble Hill Road | 8 | Asbestos Cement | 711 | 59 | 1.14 out of 5 | $442 | 314,284 |
| Distribution Main | 1732 | P-2543 | WAR | College Hill Rd. | 8 | PVC | 28 | 34 | 0.43 out of 5 | $442 | 12,558 |
| Distribution Main | 1733 | P-2543 | WAR | College Hill Rd. | 8 | PVC | 210 | 34 | 0.43 out of 5 | $442 | 93,006 |
| Distribution Main | 7380 | P-2859 | WAR | College Hill Rd. | 8 | PVC | 123 | 34 | 0.43 out of 5 | $442 | 54,411 |
| Distribution Main | 5575 | P-2915 | WAR | College St | 4 | Cast Iron | 405 | 109 | 3.29 out of 5 | $442 | 179,004 |
| Distribution Main | 5576 | P-2915 | WAR | College St | 4 | Cast Iron | 13 | 109 | 3.29 out of 5 | $442 | 5,587 |
| Distribution Main | 7379 | P-2861 | WAR | College View Ct | 4 | Ductile Iron | 302 | 30 | 1.57 out of 5 | $442 | 133,275 |
| Distribution Main | 9211 | P-2860 | WAR | College View Ct | 6 | Ductile Iron | 5 | 30 | 0.85 out of 5 | $442 | 2,229 |
| Distribution Main | 9212 | P-2860 | WAR | College View Ct | 6 | Ductile Iron | 7 | 30 | 0.85 out of 5 | $442 | 3,078 |
| Distribution Main | 4548 | P-2914 | WAR | Colonial Ave. | 8 | Ductile Iron | 22 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4549 | P-2615 | WAR | Colonial Ave. | 8 | Ductile Iron | 14 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4552 | P-2615 | WAR | Colonial Ave. | 8 | Ductile Iron | 195 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5568 | P-2914 | WAR | Colonial Ave. | 8 | Ductile Iron | 174 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5569 | P-2914 | WAR | Colonial Ave. | 8 | Ductile Iron | 252 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5015 | | WAR | Commonwealth Av | 8 | Ductile Iron | 541 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 10556 | P-2299 | WAR | Commonwealth Av | 8 | Ductile Iron | 54 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10570 | | WAR | Commonwealth Av | 8 | Ductile Iron | 659 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10571 | | WAR | Commonwealth Av | 8 | Ductile Iron | 318 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10578 | P-2296 | WAR | Commonwealth Av | 16 | Ductile Iron | 93 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10714 | P-2296 | WAR | Commonwealth Av | 16 | Ductile Iron | 752 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10715 | P-2296 | WAR | Commonwealth Av | 16 | Ductile Iron | 922 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10716 | P-2542 | WAR | Commonwealth Av | 16 | Ductile Iron | 655 | 1 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 10717 | P-2542 | WAR | Commonwealth Av | 16 | Ductile Iron | 649 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10992 | P-2301 | WAR | Commonwealth Av | 8 | Ductile Iron | 33 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11676 | | WAR | Commonwealth Av | 8 | Ductile Iron | 185 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11708 | P-2538 | WAR | Commonwealth Av | 16 | Ductile Iron | 249 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11916 | P-2542 | WAR | Commonwealth Av | 16 | Ductile Iron | 121 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11921 | P-2542 | WAR | Commonwealth Av | 16 | Ductile Iron | 407 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11923 | P-2296 | WAR | Commonwealth Av | 16 | Ductile Iron | 152 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12143 | P-2542 | WAR | Commonwealth Av | 16 | Ductile Iron | 131 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12215 | P-2296 | WAR | Commonwealth Av | 16 | Ductile Iron | 81 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6100 | P-2299 | WAR | Commonwealth Ave. | 8 | Asbestos Cement | 33 | 60 | 1.14 out of 5 | $442 | 14,449 |
| Distribution Main | 6101 | P-2299 | WAR | Commonwealth Ave. | 8 | Asbestos Cement | 5 | 60 | 1.14 out of 5 | $442 | 2,258 |
| Distribution Main | 6103 | P-2314 | WAR | Commonwealth Ave. | 8 | Ductile Iron | 409 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6158 | P-2308 | WAR | Commonwealth Ave. | 8 | Asbestos Cement | 305 | 60 | 1.14 out of 5 | $442 | 134,915 |
| Distribution Main | 6949 | P-2299 | WAR | Commonwealth Ave. | 8 | Asbestos Cement | 528 | 60 | 1.14 out of 5 | $442 | 233,493 |
| Distribution Main | 6950 | P-2299 | WAR | Commonwealth Ave. | 8 | Asbestos Cement | 497 | 60 | 1.14 out of 5 | $442 | 219,884 |
| Distribution Main | 6952 | P-2313 | WAR | Commonwealth Ave. | 8 | Ductile Iron | 554 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6953 | P-2313 | WAR | Commonwealth Ave. | 8 | Ductile Iron | 20 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10530 | P-2308 | WAR | Commonwealth Ave. | 8 | Asbestos Cement | 258 | 60 | 1.14 out of 5 | $442 | 113,977 |
| Distribution Main | 10531 | P-2308 | WAR | Commonwealth Ave. | 8 | Asbestos Cement | 7 | 60 | 1.14 out of 5 | $442 | 3,197 |
| Distribution Main | 11932 | P-2313 | WAR | Commonwealth Ave. | 8 | Ductile Iron | 27 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6075 | P-2152 | WAR | Contour Rd. | 8 | PVC | 292 | 31 | 0.43 out of 5 | $442 | 129,137 |
| Distribution Main | 7324 | P-2153 | WAR | Contour Rd. | 8 | PVC | 493 | 31 | 0.43 out of 5 | $442 | 217,946 |
| Distribution Main | 7325 | P-2153 | WAR | Contour Rd. | 8 | PVC | 4 | 31 | 0.43 out of 5 | $442 | 1,880 |
| Distribution Main | 6847 | P-2747 | WAR | Corey Ave. | 6 | Cast Iron | 309 | 132 | 2.57 out of 5 | $442 | 136,362 |
| Distribution Main | 6848 | P-2747 | WAR | Corey Ave. | 6 | Cast Iron | 86 | 132 | 2.57 out of 5 | $442 | 37,884 |
| Distribution Main | 6892 | P-2748 | WAR | Corey Ave. | 8 | Ductile Iron | 123 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6925 | P-2747 | WAR | Corey Ave. | 6 | Cast Iron | 13 | 132 | 2.57 out of 5 | $442 | 5,849 |
| Distribution Main | 7114 | P-2331 | WAR | Country Ln. | 6 | Asbestos Cement | 874 | 71 | 2 out of 5 | $442 | 386,297 |
| Distribution Main | 9608 | P-2331 | WAR | Country Ln. | 8 | Ductile Iron | 65 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9609 | P-2331 | WAR | Country Ln. | 6 | Ductile Iron | 5 | 22 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 9610 | P-2331 | WAR | Country Ln. | 6 | Ductile Iron | 7 | 22 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 10553 | P-2322 | WAR | Country View Dr | 8 | Ductile Iron | 74 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10554 | P-2322 | WAR | Country View Dr | 8 | Ductile Iron | 536 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10555 | | WAR | Country View Dr | 6 | Ductile Iron | 11 | 2 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11673 | P-2322 | WAR | Country View Dr | 8 | Ductile Iron | 73 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12135 | P-2322 | WAR | Country View Dr | 8 | Ductile Iron | 52 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 871 | P-2333 | WAR | Country View Dr. | 8 | Asbestos Cement | 367 | 51 | 1.14 out of 5 | $442 | 162,147 |
| Distribution Main | 878 | P-2339 | WAR | Country View Dr. | 8 | Asbestos Cement | 269 | 51 | 1.14 out of 5 | $442 | 118,814 |
| Distribution Main | 879 | P-2339 | WAR | Country View Dr. | 8 | Asbestos Cement | 518 | 51 | 1.14 out of 5 | $442 | 229,051 |
| Distribution Main | 4293 | P-2311 | WAR | Country View Dr. | 8 | Asbestos Cement | 812 | 51 | 1.14 out of 5 | $442 | 359,006 |
| Distribution Main | 4294 | P-2311 | WAR | Country View Dr. | 8 | Asbestos Cement | 167 | 51 | 1.14 out of 5 | $442 | 73,762 |
| Distribution Main | 10483 | P-2322 | WAR | Country View Dr. | 8 | Asbestos Cement | 546 | 51 | 1.14 out of 5 | $442 | 241,246 |
| Distribution Main | 10551 | P-2333 | WAR | Country View Dr. | 8 | Asbestos Cement | 41 | 51 | 1.14 out of 5 | $442 | 18,035 |
| Distribution Main | 10552 | P-2333 | WAR | Country View Dr. | 8 | Asbestos Cement | 7 | 51 | 1.14 out of 5 | $442 | 2,912 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 3312 | P-2330 | WAR | Coweset Rd | 12 | Ductile Iron | 43 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 3313 | P-2335 | WAR | Coweset Rd | 12 | Ductile Iron | 9 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 3618 | P-2134 | WAR | Coweset Rd | 12 | Ductile Iron | 33 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5740 | P-2134 | WAR | Coweset Rd | 12 | Ductile Iron | 181 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11210 | P-2330 | WAR | Coweset Rd | 12 | Ductile Iron | 11 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11211 | P-2335 | WAR | Coweset Rd | 12 | Ductile Iron | 6 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11212 | P-2335 | WAR | Coweset Rd | 12 | Ductile Iron | 5 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5082 | P-2182 | WAR | Cowesett Ave. | 12 | Asbestos Cement | 259 | 53 | 1.14 out of 5 | $442 | 114,506 |
| Transmission Main | 5357 | P-2180 | WAR | Cowesett Ave. | 12 | Asbestos Cement | 186 | 53 | 1.14 out of 5 | $442 | 82,405 |
| Transmission Main | 5358 | P-2180 | WAR | Cowesett Ave. | 12 | Asbestos Cement | 10 | 53 | 1.14 out of 5 | $442 | 4,434 |
| Transmission Main | 8002 | P-2180 | WAR | Cowesett Ave. | 12 | Asbestos Cement | 193 | 53 | 1.14 out of 5 | $442 | 85,398 |
| Distribution Main | 6074 | P-2111 | WAR | Cowesett Green Rd. | 8 | PVC | 3 | 33 | 0.43 out of 5 | $442 | 1,293 |
| Distribution Main | 6076 | P-2109 | WAR | Cowesett Green Rd. | 8 | PVC | 304 | 33 | 0.43 out of 5 | $442 | 134,409 |
| Distribution Main | 6079 | P-2114 | WAR | Cowesett Green Rd. | 8 | PVC | 267 | 33 | 0.43 out of 5 | $442 | 117,976 |
| Distribution Main | 6080 | P-2114 | WAR | Cowesett Green Rd. | 8 | PVC | 4 | 33 | 0.43 out of 5 | $442 | 1,594 |
| Distribution Main | 6084 | P-2112 | WAR | Cowesett Green Rd. | 8 | PVC | 585 | 33 | 0.43 out of 5 | $442 | 258,595 |
| Distribution Main | 7316 | P-2111 | WAR | Cowesett Green Rd. | 8 | PVC | 409 | 33 | 0.43 out of 5 | $442 | 180,705 |
| Distribution Main | 7326 | P-2115 | WAR | Cowesett Green Rd. | 8 | PVC | 108 | 33 | 0.43 out of 5 | $442 | 47,881 |
| Distribution Main | 7327 | P-2115 | WAR | Cowesett Green Rd. | 8 | PVC | 627 | 33 | 0.43 out of 5 | $442 | 277,212 |
| Distribution Main | 1599 | | WAR | Cowesett Rd. | 10 | Unknown | 33 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 2222 | P-2180 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 40 | 53 | 1.14 out of 5 | $442 | 17,759 |
| Transmission Main | 2223 | P-2180 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 415 | 53 | 1.14 out of 5 | $442 | 183,481 |
| Transmission Main | 2842 | P-2079 | WAR | Cowesett Rd. | 12 | Ductile Iron | 268 | 31 | 0.14 out of 5 | $442 | 118,260 |
| Distribution Main | 3325 | P-2135 | WAR | Cowesett Rd. | 8 | Ductile Iron | 41 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4234 | P-2136 | WAR | Cowesett Rd. | 8 | Ductile Iron | 41 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4235 | P-2134 | WAR | Cowesett Rd. | 12 | Ductile Iron | 5 | 31 | 0.14 out of 5 | $442 | 2,345 |
| Transmission Main | 4236 | P-2077 | WAR | Cowesett Rd. | 12 | Ductile Iron | 49 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4237 | P-2077 | WAR | Cowesett Rd. | 12 | Ductile Iron | 111 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4467 | P-2357 | WAR | Cowesett Rd. | 12 | Ductile Iron | 42 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4469 | P-2738 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 140 | 53 | 1.14 out of 5 | $442 | 61,926 |
| Transmission Main | 4470 | P-2738 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 224 | 53 | 1.14 out of 5 | $442 | 99,032 |
| Transmission Main | 4471 | P-2737 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 310 | 53 | 1.14 out of 5 | $442 | 137,081 |
| Transmission Main | 4472 | P-2082 | WAR | Cowesett Rd. | 12 | Ductile Iron | 310 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4473 | P-2082 | WAR | Cowesett Rd. | 12 | Ductile Iron | 300 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4474 | P-2083 | WAR | Cowesett Rd. | 12 | Ductile Iron | 4 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4476 | P-2076 | WAR | Cowesett Rd. | 12 | Ductile Iron | 219 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5028 | P-2081 | WAR | Cowesett Rd. | 12 | Ductile Iron | 315 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5029 | P-2081 | WAR | Cowesett Rd. | 12 | Ductile Iron | 150 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5030 | P-2092 | WAR | Cowesett Rd. | 12 | Ductile Iron | 304 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5031 | P-2092 | WAR | Cowesett Rd. | 12 | Ductile Iron | 51 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5466 | P-2095 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 951 | 53 | 1.14 out of 5 | $442 | 420,393 |
| Transmission Main | 5577 | P-2456 | WAR | Cowesett Rd. | 12 | Ductile Iron | 11 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5578 | P-2335 | WAR | Cowesett Rd. | 12 | Ductile Iron | 440 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5579 | P-2335 | WAR | Cowesett Rd. | 12 | Ductile Iron | 441 | 22 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 5580 | P-2336 | WAR | Cowesett Rd. | 12 | Ductile Iron | 7 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5743 | P-2077 | WAR | Cowesett Rd. | 12 | Ductile Iron | 3 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6307 | P-2082 | WAR | Cowesett Rd. | 12 | Ductile Iron | 158 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6414 | P-2355 | WAR | Cowesett Rd. | 12 | Ductile Iron | 22 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6415 | P-2355 | WAR | Cowesett Rd. | 12 | Ductile Iron | 386 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6419 | P-2336 | WAR | Cowesett Rd. | 12 | Ductile Iron | 116 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6420 | P-2336 | WAR | Cowesett Rd. | 12 | Ductile Iron | 29 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6424 | P-2356 | WAR | Cowesett Rd. | 12 | Ductile Iron | 337 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6425 | P-2452 | WAR | Cowesett Rd. | 12 | Ductile Iron | 120 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6440 | P-2335 | WAR | Cowesett Rd. | 12 | Ductile Iron | 11 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6519 | P-2357 | WAR | Cowesett Rd. | 12 | Ductile Iron | 467 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6529 | P-2076 | WAR | Cowesett Rd. | 12 | Ductile Iron | 4 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6609 | P-2083 | WAR | Cowesett Rd. | 12 | Ductile Iron | 128 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6610 | P-2092 | WAR | Cowesett Rd. | 12 | Ductile Iron | 7 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6664 | P-2082 | WAR | Cowesett Rd. | 12 | Ductile Iron | 4 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6665 | P-2076 | WAR | Cowesett Rd. | 12 | Ductile Iron | 7 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6666 | P-2076 | WAR | Cowesett Rd. | 12 | Ductile Iron | 4 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6680 | P-2138 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 98 | 53 | 1.14 out of 5 | $442 | 43,394 |
| Transmission Main | 6683 | P-2177 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 107 | 53 | 1.14 out of 5 | $442 | 47,506 |
| Transmission Main | 6684 | P-2177 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 379 | 53 | 1.14 out of 5 | $442 | 167,566 |
| Transmission Main | 6685 | P-2180 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 904 | 53 | 1.14 out of 5 | $442 | 399,667 |
| Transmission Main | 7255 | P-2335 | WAR | Cowesett Rd. | 12 | Ductile Iron | 7 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 7256 | P-2357 | WAR | Cowesett Rd. | 12 | Ductile Iron | 4 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 7257 | P-2357 | WAR | Cowesett Rd. | 12 | Ductile Iron | 81 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 7271 | P-2959 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 969 | 53 | 1.14 out of 5 | $442 | 428,372 |
| Transmission Main | 7322 | P-2095 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 52 | 53 | 1.14 out of 5 | $442 | 22,952 |
| Transmission Main | 7448 | P-2105 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 100 | 53 | 1.14 out of 5 | $442 | 44,303 |
| Transmission Main | 7449 | P-2105 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 154 | 53 | 1.14 out of 5 | $442 | 68,245 |
| Transmission Main | 7499 | P-2138 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 1,360 | 53 | 1.14 out of 5 | $442 | 601,020 |
| Transmission Main | 7500 | P-2138 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 249 | 53 | 1.14 out of 5 | $442 | 110,036 |
| Distribution Main | 7501 | | WAR | Cowesett Rd. | 8 | Unknown | 27 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 7502 | | WAR | Cowesett Rd. | 8 | Unknown | 5 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 10919 | P-2959 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 41 | 53 | 1.14 out of 5 | $442 | 18,247 |
| Transmission Main | 10920 | P-2166 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 68 | 53 | 1.14 out of 5 | $442 | 29,881 |
| Transmission Main | 11282 | P-2081 | WAR | Cowesett Rd. | 12 | Ductile Iron | 59 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11371 | P-2095 | WAR | Cowesett Rd. | 12 | Asbestos Cement | 6 | 53 | 1.14 out of 5 | $442 | 2,649 |
| Transmission Main | 11937 | P-2081 | WAR | Cowesett Rd. | 12 | Ductile Iron | 94 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11962 | P-2092 | WAR | Cowesett Rd. | 12 | Ductile Iron | 94 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4543 | P-2623 | WAR | Coyle St. | 4 | Cast Iron | 225 | 109 | 3.29 out of 5 | $442 | 99,586 |
| Distribution Main | 5556 | P-2621 | WAR | Coyle St. | 4 | Cast Iron | 242 | 109 | 3.29 out of 5 | $442 | 106,914 |
| Distribution Main | 10567 | P-2307 | WAR | Craig Rd | 8 | Ductile Iron | 250 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10933 | P-2897 | WAR | Craig Rd | 8 | Ductile Iron | 293 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10934 | P-2897 | WAR | Craig Rd | 8 | Ductile Iron | 47 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10935 | P-2899 | WAR | Craig Rd | 8 | Ductile Iron | 235 | 2 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2241 | P-1311 | WAR | Creamer Ave. | 8 | Ductile Iron | 165 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2242 | P-1311 | WAR | Creamer Ave. | 8 | Ductile Iron | 130 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4116 | P-1310 | WAR | Creamer Ave. | 8 | Ductile Iron | 322 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7354 | P-2390 | WAR | Creston Way | 6 | Asbestos Cement | 493 | 80 | 2 out of 5 | $442 | 217,796 |
| Distribution Main | 4519 | P-2942 | WAR | Crestwood Rd. | 8 | Asbestos Cement | 322 | 80 | 1.29 out of 5 | $442 | 142,158 |
| Distribution Main | 6087 | P-2383 | WAR | Crestwood Rd. | 6 | Asbestos Cement | 375 | 80 | 2 out of 5 | $442 | 165,683 |
| Distribution Main | 6089 | P-2944 | WAR | Crestwood Rd. | 6 | Asbestos Cement | 373 | 80 | 2 out of 5 | $442 | 165,036 |
| Distribution Main | 6090 | P-2381 | WAR | Crestwood Rd. | 6 | Asbestos Cement | 13 | 80 | 2 out of 5 | $442 | 5,729 |
| Distribution Main | 6668 | P-2387 | WAR | Crestwood Rd. | 6 | Asbestos Cement | 5 | 80 | 2 out of 5 | $442 | 1,992 |
| Distribution Main | 6669 | P-2387 | WAR | Crestwood Rd. | 6 | Asbestos Cement | 845 | 80 | 2 out of 5 | $442 | 373,506 |
| Distribution Main | 7125 | P-2381 | WAR | Crestwood Rd. | 6 | Asbestos Cement | 740 | 80 | 2 out of 5 | $442 | 326,976 |
| Distribution Main | 7126 | P-2381 | WAR | Crestwood Rd. | 6 | Asbestos Cement | 5 | 80 | 2 out of 5 | $442 | 2,319 |
| Distribution Main | 7127 | P-2942 | WAR | Crestwood Rd. | 8 | Asbestos Cement | 11 | 80 | 1.29 out of 5 | $442 | 4,738 |
| Distribution Main | 7177 | P-2383 | WAR | Crestwood Rd. | 6 | Asbestos Cement | 8 | 80 | 2 out of 5 | $442 | 3,340 |
| Distribution Main | 7346 | P-2386 | WAR | Crestwood Rd. | 8 | Asbestos Cement | 194 | 80 | 1.29 out of 5 | $442 | 85,764 |
| Distribution Main | 7347 | P-2385 | WAR | Crestwood Rd. | 8 | Asbestos Cement | 1 | 80 | 1.29 out of 5 | $442 | 484 |
| Distribution Main | 7348 | P-2385 | WAR | Crestwood Rd. | 8 | Asbestos Cement | 331 | 80 | 1.29 out of 5 | $442 | 146,460 |
| Distribution Main | 7351 | P-2384 | WAR | Crestwood Rd. | 8 | Asbestos Cement | 83 | 80 | 1.29 out of 5 | $442 | 36,799 |
| Distribution Main | 11939 | P-2381 | WAR | Crestwood Rd. | 6 | Asbestos Cement | 41 | 80 | 2 out of 5 | $442 | 17,942 |
| Distribution Main | 1165 | P-2643 | WAR | Crocus St. | 6 | Asbestos Cement | 652 | 63 | 2 out of 5 | $442 | 288,114 |
| Distribution Main | 6417 | P-2470 | WAR | Cumberland Rd. | 8 | Ductile Iron | 579 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6418 | P-2470 | WAR | Cumberland Rd. | 8 | Ductile Iron | 599 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8633 | P-2469 | WAR | Cumberland Rd. | 8 | Ductile Iron | 176 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11334 | P-2470 | WAR | Cumberland Rd. | 8 | Ductile Iron | 13 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5499 | P-2583 | WAR | D'Agnillo Dr. | 8 | Asbestos Cement | 89 | 42 | 1.14 out of 5 | $442 | 39,397 |
| Distribution Main | 5500 | P-2583 | WAR | D'Agnillo Dr. | 8 | Asbestos Cement | 867 | 42 | 1.14 out of 5 | $442 | 383,307 |
| Distribution Main | 6833 | P-2583 | WAR | D'Agnillo Dr. | 8 | Asbestos Cement | 181 | 42 | 1.14 out of 5 | $442 | 79,792 |
| Distribution Main | 6834 | P-2583 | WAR | D'Agnillo Dr. | 8 | Asbestos Cement | 690 | 42 | 1.14 out of 5 | $442 | 304,844 |
| Distribution Main | 6928 | P-2583 | WAR | D'Agnillo Dr. | 8 | Asbestos Cement | 17 | 42 | 1.14 out of 5 | $442 | 7,647 |
| Distribution Main | 7185 | P-2091 | WAR | Darling St. | 8 | Ductile Iron | 29 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7186 | P-2091 | WAR | Darling St. | 8 | Ductile Iron | 712 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7241 | | WAR | Darling St. | 8 | Ductile Iron | 91 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5396 | P-2433 | WAR | Dawn Ln. | 8 | Asbestos Cement | 313 | 48 | 1.14 out of 5 | $442 | 138,340 |
| Distribution Main | 5397 | P-2433 | WAR | Dawn Ln. | 8 | Asbestos Cement | 153 | 48 | 1.14 out of 5 | $442 | 67,521 |
| Distribution Main | 5989 | P-2388 | WAR | Dexterdale Dr. | 8 | Asbestos Cement | 7 | 80 | 1.29 out of 5 | $442 | 3,261 |
| Distribution Main | 6671 | P-2388 | WAR | Dexterdale Dr. | 8 | Asbestos Cement | 162 | 80 | 1.29 out of 5 | $442 | 71,619 |
| Distribution Main | 7352 | P-2389 | WAR | Dexterdale Dr. | 8 | Asbestos Cement | 12 | 80 | 1.29 out of 5 | $442 | 5,476 |
| Distribution Main | 7353 | P-2389 | WAR | Dexterdale Dr. | 8 | Asbestos Cement | 909 | 80 | 1.29 out of 5 | $442 | 401,826 |
| Distribution Main | 365 | P-2043 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 268 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 366 | P-2043 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 55 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 369 | P-2027 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 390 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5213 | P-2025 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 108 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5692 | P-2725 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 480 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5985 | P-2084 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 11 | 19 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6596 | P-2087 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 542 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6597 | P-2087 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 613 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6603 | P-2054 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 5 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6604 | P-2054 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 97 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6605 | P-2053 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 423 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6606 | P-2086 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 12 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6607 | P-2086 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 143 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6611 | P-2084 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 301 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7022 | P-2025 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 460 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7023 | P-2027 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 8 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7025 | P-2919 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 37 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7026 | P-2919 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 530 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7028 | P-2724 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 137 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7029 | P-2724 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 6 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7056 | P-2025 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 8 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7097 | P-2053 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 162 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7184 | P-2044 | WAR | Diamond Hill Rd. | 8 | Ductile Iron | 20 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9154 | P-4888 | WAR | Division St | 12 | Ductile Iron | 7 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9156 | P-4564 | WAR | Division St | 8 | Ductile Iron | 3 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9157 | P-4897 | WAR | Division St | 8 | Ductile Iron | 15 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9158 | P-4566 | WAR | Division St | 12 | Ductile Iron | 27 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9159 | P-4566 | WAR | Division St | 12 | Ductile Iron | 232 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9190 | P-4895 | WAR | Division St | 8 | Ductile Iron | 6 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9191 | P-4895 | WAR | Division St | 6 | Ductile Iron | 6 | 8 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9306 | P-4887 | WAR | Division St | 8 | Ductile Iron | 1 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9307 | P-4888 | WAR | Division St | 8 | Ductile Iron | 2 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10852 | P-4897 | WAR | Division St | 12 | Ductile Iron | 7 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10853 | P-4565 | WAR | Division St | 12 | Ductile Iron | 215 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10954 | P-4887 | WAR | Division St | 12 | Ductile Iron | 6 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11549 | P-4565 | WAR | Division St | 12 | Ductile Iron | 13 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4852 | P-4899 | WAR | Divison Street | 6 | Cast Iron | 315 | UNK | 1.85 out of 5 | $442 | 139,183 |
| Distribution Main | 4853 | P-4899 | WAR | Divison Street | 6 | Cast Iron | 11 | UNK | 1.85 out of 5 | $442 | 4,852 |
| Distribution Main | 5037 | P-4899 | WAR | Divison Street | 6 | Cast Iron | 14 | UNK | 1.85 out of 5 | $442 | 6,249 |
| Distribution Main | 9871 | P-2568 | WAR | Dongay Ave | 8 | Ductile Iron | 244 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4882 | P-2016 | WAR | Douglas Rd. | 6 | Asbestos Cement | 498 | 59 | 1.85 out of 5 | $442 | 220,323 |
| Distribution Main | 5434 | P-2008 | WAR | Douglas Rd. | 6 | Asbestos Cement | 835 | 59 | 1.85 out of 5 | $442 | 369,093 |
| Distribution Main | 6108 | P-2014 | WAR | Douglas Rd. | 6 | Asbestos Cement | 380 | 59 | 1.85 out of 5 | $442 | 168,024 |
| Distribution Main | 6109 | P-2014 | WAR | Douglas Rd. | 6 | Asbestos Cement | 726 | 59 | 1.85 out of 5 | $442 | 320,731 |
| Distribution Main | 6961 | P-2015 | WAR | Douglas Rd. | 6 | Asbestos Cement | 213 | 59 | 1.85 out of 5 | $442 | 94,328 |
| Distribution Main | 6973 | P-2014 | WAR | Douglas Rd. | 6 | Asbestos Cement | 25 | 59 | 1.85 out of 5 | $442 | 10,962 |
| Distribution Main | 6974 | P-2014 | WAR | Douglas Rd. | 6 | Asbestos Cement | 256 | 59 | 1.85 out of 5 | $442 | 113,309 |
| Distribution Main | 11915 | P-2014 | WAR | Douglas Rd. | 6 | Asbestos Cement | 39 | 59 | 1.85 out of 5 | $442 | 17,199 |
| Distribution Main | 875 | P-2332 | WAR | Downing Ln. | 8 | Ductile Iron | 517 | 47 | 0.29 out of 5 | $442 | 228,548 |
| Distribution Main | 5218 | P-2036 | WAR | Drum Rock Ave | 8 | Cast Iron | 517 | 87 | 1.72 out of 5 | $442 | 228,598 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 5219 | P-2036 | WAR | Drum Rock Ave | 8 | Cast Iron | 291 | 87 | 1.72 out of 5 | $442 | 128,532 |
| Distribution Main | 8323 | P-2036 | WAR | Drum Rock Ave | 6 | Asbestos Cement | 279 | 52 | 1.85 out of 5 | $442 | 123,299 |
| Distribution Main | 9490 | P-2036 | WAR | Drum Rock Ave | 8 | Cast Iron | 152 | 87 | 1.72 out of 5 | $442 | 67,103 |
| Distribution Main | 9491 | P-2036 | WAR | Drum Rock Ave | 8 | Cast Iron | 431 | 87 | 1.72 out of 5 | $442 | 190,324 |
| Distribution Main | 9142 | P-2406 | WAR | Duane St | 8 | Ductile Iron | 163 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9143 | P-2406 | WAR | Duane St | 8 | Ductile Iron | 339 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9148 | P-2408 | WAR | Duane St | 8 | Ductile Iron | 52 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9149 | P-2408 | WAR | Duane St | 8 | Ductile Iron | 401 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9161 | P-2408 | WAR | Duane St | 8 | Ductile Iron | 47 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12159 | P-2408 | WAR | Duane St | 8 | Ductile Iron | 25 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5215 | | WAR | Duchess St. | 8 | Ductile Iron | 119 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7030 | P-2038 | WAR | Duchess St. | 8 | Ductile Iron | 601 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7031 | P-2038 | WAR | Duchess St. | 8 | Ductile Iron | 235 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9163 | P-4616 | WAR | Duke St | 8 | Ductile Iron | 38 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5441 | P-2007 | WAR | Dunmore Rd. | 8 | Asbestos Cement | 257 | 59 | 1.14 out of 5 | $442 | 113,578 |
| Distribution Main | 7298 | P-2741 | WAR | Easement | 8 | Ductile Iron | 7 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7323 | P-2741 | WAR | Easement | 8 | Ductile Iron | 382 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9042 | | WAR | Easement | 4 | Ductile Iron | 6 | 11 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 9044 | P-2548 | WAR | Easement | 6 | Ductile Iron | 119 | 16 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9045 | P-2548 | WAR | Easement | 6 | Ductile Iron | 166 | 16 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11372 | P-2741 | WAR | Easement | 8 | Ductile Iron | 8 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 10700 | | WAR | East Av | 42 | Asbestos Cement | 1,010 | UNK | 0.85 out of 5 | $442 | 446,581 |
| Transmission Main | 10718 | | WAR | East Av | 16 | Ductile Iron | 478 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10719 | | WAR | East Av | 16 | Ductile Iron | 189 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10721 | | WAR | East Av | 16 | Ductile Iron | 52 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10722 | | WAR | East Av | 16 | Ductile Iron | 215 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11709 | | WAR | East Av | 16 | Ductile Iron | 94 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11710 | | WAR | East Av | 16 | Ductile Iron | 137 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11711 | | WAR | East Av | 16 | Ductile Iron | 47 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11914 | | WAR | East Av | 16 | Ductile Iron | 112 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12195 | | WAR | East Av | 16 | Ductile Iron | 27 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12196 | | WAR | East Av | 16 | Ductile Iron | 12 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10058 | P-2850 | WAR | East Ave | 16 | Ductile Iron | 219 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2835 | P-2133 | WAR | Edmond Cir. | 6 | Asbestos Cement | 101 | 65 | 2 out of 5 | $442 | 44,751 |
| Distribution Main | 5753 | P-2133 | WAR | Edmond Cir. | 6 | Asbestos Cement | 32 | 65 | 2 out of 5 | $442 | 14,090 |
| Distribution Main | 5778 | P-2132 | WAR | Edmond Cir. | 6 | Asbestos Cement | 18 | 65 | 2 out of 5 | $442 | 7,863 |
| Distribution Main | 2833 | P-2129 | WAR | Edmond Dr. | 8 | Asbestos Cement | 39 | 65 | 1.29 out of 5 | $442 | 17,425 |
| Distribution Main | 2834 | P-2129 | WAR | Edmond Dr. | 8 | Asbestos Cement | 111 | 65 | 1.29 out of 5 | $442 | 48,885 |
| Distribution Main | 4225 | P-2130 | WAR | Edmond Dr. | 8 | Asbestos Cement | 112 | 65 | 1.29 out of 5 | $442 | 49,605 |
| Distribution Main | 4226 | P-2130 | WAR | Edmond Dr. | 8 | Asbestos Cement | 154 | 65 | 1.29 out of 5 | $442 | 67,886 |
| Distribution Main | 4238 | P-2732 | WAR | Edmond Dr. | 8 | Asbestos Cement | 392 | 65 | 1.29 out of 5 | $442 | 173,155 |
| Distribution Main | 4867 | P-2130 | WAR | Edmond Dr. | 8 | Asbestos Cement | 290 | 65 | 1.29 out of 5 | $442 | 128,296 |
| Distribution Main | 5744 | P-2128 | WAR | Edmond Dr. | 8 | Asbestos Cement | 4 | 65 | 1.29 out of 5 | $442 | 1,952 |
| Distribution Main | 5758 | P-2128 | WAR | Edmond Dr. | 8 | Asbestos Cement | 633 | 65 | 1.29 out of 5 | $442 | 279,736 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10542 | P-2443 | WAR | Elisha St | 8 | Ductile Iron | 256 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11672 | P-2443 | WAR | Elisha St | 8 | Ductile Iron | 210 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 865 | P-2648 | WAR | Elmer Ave. | 8 | Ductile Iron | 30 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1153 | P-2648 | WAR | Elmer Ave. | 8 | Ductile Iron | 139 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1154 | P-2648 | WAR | Elmer Ave. | 8 | Ductile Iron | 276 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3590 | P-2279 | WAR | Emily Ln. | 8 | Ductile Iron | 25 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6996 | P-2279 | WAR | Emily Ln. | 8 | Ductile Iron | 160 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6997 | P-2279 | WAR | Emily Ln. | 8 | Ductile Iron | 125 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2528 | P-2575 | WAR | Fairmount Dr. | 6 | Asbestos Cement | 9 | 69 | 2 out of 5 | $442 | 3,879 |
| Distribution Main | 2529 | | WAR | Fairmount Dr. | 6 | Unknown | 41 | 69 | 1.14 out of 5 | $442 | 18,192 |
| Transmission Main | 2530 | P-2575 | WAR | Fairmount Dr. | 20 | Asbestos Cement | 7 | 69 | 1.29 out of 5 | $442 | 3,023 |
| Distribution Main | 4529 | P-2575 | WAR | Fairmount Dr. | 6 | Asbestos Cement | 293 | 69 | 2 out of 5 | $442 | 129,367 |
| Distribution Main | 4530 | P-2575 | WAR | Fairmount Dr. | 6 | Asbestos Cement | 482 | 69 | 2 out of 5 | $442 | 213,234 |
| Transmission Main | 6286 | P-2649 | WAR | Fairmount Dr. | 20 | Asbestos Cement | 261 | 55 | 1.14 out of 5 | $442 | 115,464 |
| Transmission Main | 6287 | P-2649 | WAR | Fairmount Dr. | 20 | Asbestos Cement | 436 | 55 | 1.14 out of 5 | $442 | 192,583 |
| Distribution Main | 3137 | P-2282 | WAR | Fishs Lane | 8 | Asbestos Cement | 638 | 52 | 1.14 out of 5 | $442 | 281,788 |
| Distribution Main | 8278 | P-2287 | WAR | Flagg Ave. | 8 | Ductile Iron | 597 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8295 | P-2815 | WAR | Flagg Ave. | 8 | Ductile Iron | 179 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5431 | | WAR | Forbes St | 6 | Ductile Iron | 6 | 26 | 0.85 out of 5 | $442 | 2,589 |
| Distribution Main | 10574 | | WAR | Forbes St | 8 | Ductile Iron | 95 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5902 | P-2326 | WAR | Forbes St. | 6 | Asbestos Cement | 110 | 46 | 1.85 out of 5 | $442 | 48,758 |
| Distribution Main | 6956 | P-2326 | WAR | Forbes St. | 6 | Asbestos Cement | 152 | 46 | 1.85 out of 5 | $442 | 67,055 |
| Distribution Main | 6957 | P-2326 | WAR | Forbes St. | 6 | Asbestos Cement | 18 | 46 | 1.85 out of 5 | $442 | 8,113 |
| Distribution Main | 11319 | P-2326 | WAR | Forbes St. | 6 | Asbestos Cement | 23 | 46 | 1.85 out of 5 | $442 | 10,030 |
| Distribution Main | 11356 | P-2326 | WAR | Forbes St. | 6 | Asbestos Cement | 2 | 46 | 1.85 out of 5 | $442 | 785 |
| Distribution Main | 8279 | P-2814 | WAR | Founder Ave. | 8 | Ductile Iron | 281 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8285 | P-2292 | WAR | Founder Ave. | 8 | Ductile Iron | 481 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8286 | P-2292 | WAR | Founder Ave. | 8 | Ductile Iron | 184 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5018 | P-2363 | WAR | Fred Humlak Wy. | 6 | PVC | 688 | 37 | 1.14 out of 5 | $442 | 304,140 |
| Distribution Main | 5019 | P-2363 | WAR | Fred Humlak Wy. | 6 | PVC | 16 | 37 | 1.14 out of 5 | $442 | 7,112 |
| Distribution Main | 5987 | P-2362 | WAR | Fred Humlak Wy. | 6 | PVC | 22 | 37 | 1.14 out of 5 | $442 | 9,589 |
| Distribution Main | 6523 | P-2465 | WAR | Friar Tuck Rd. | 8 | Ductile Iron | 291 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6941 | P-2450 | WAR | Garnet St. | 8 | Ductile Iron | 18 | 27 | 0.14 out of 5 | $442 | 7,795 |
| Distribution Main | 6942 | P-2450 | WAR | Garnet St. | 8 | Ductile Iron | 305 | 27 | 0.14 out of 5 | $442 | 134,685 |
| Distribution Main | 10536 | P-2450 | WAR | Garnet St. | 8 | Ductile Iron | 61 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 870 | P-2300 | WAR | Gauvin Dr. | 8 | Asbestos Cement | 53 | 52 | 1.14 out of 5 | $442 | 23,566 |
| Distribution Main | 872 | P-2281 | WAR | Gauvin Dr. | 8 | Asbestos Cement | 397 | 52 | 1.14 out of 5 | $442 | 175,426 |
| Distribution Main | 880 | P-2306 | WAR | Gauvin Dr. | 8 | Asbestos Cement | 195 | 52 | 1.14 out of 5 | $442 | 86,221 |
| Distribution Main | 1081 | P-2281 | WAR | Gauvin Dr. | 8 | Asbestos Cement | 305 | 52 | 1.14 out of 5 | $442 | 134,987 |
| Distribution Main | 4292 | P-2300 | WAR | Gauvin Dr. | 8 | Asbestos Cement | 315 | 52 | 1.14 out of 5 | $442 | 139,344 |
| Distribution Main | 9930 | P-2285 | WAR | Gauvin Dr. | 8 | Asbestos Cement | 181 | 52 | 1.14 out of 5 | $442 | 79,968 |
| Distribution Main | 9931 | P-2285 | WAR | Gauvin Dr. | 8 | Asbestos Cement | 166 | 52 | 1.14 out of 5 | $442 | 73,567 |
| Distribution Main | 11094 | P-2281 | WAR | Gauvin Dr. | 8 | Asbestos Cement | 4 | 52 | 1.14 out of 5 | $442 | 1,574 |
| Distribution Main | 6982 | P-2816 | WAR | Gentian Ave. | 8 | Ductile Iron | 145 | 14 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2240 | P-1493 | WAR | Gerald St. | 8 | Ductile Iron | 130 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2246 | P-1493 | WAR | Gerald St. | 8 | Ductile Iron | 95 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4426 | P-1986 | WAR | Gerald St. | 8 | Ductile Iron | 169 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4430 | P-1987 | WAR | Gerald St. | 1.25 | Copper | 105 | UNK | 1.99 out of 5 | $442 | 46,606 |
| Distribution Main | 9669 | P-1608 | WAR | Gerald St. | 8 | Ductile Iron | 45 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3591 | P-2428 | WAR | Gilbane St. | 8 | Asbestos Cement | 6 | 52 | 1.14 out of 5 | $442 | 2,555 |
| Distribution Main | 3601 | P-2276 | WAR | Gilbane St. | 8 | Asbestos Cement | 5 | 52 | 1.14 out of 5 | $442 | 2,308 |
| Distribution Main | 5487 | P-2428 | WAR | Gilbane St. | 8 | Asbestos Cement | 19 | 52 | 1.14 out of 5 | $442 | 8,417 |
| Distribution Main | 5488 | P-2428 | WAR | Gilbane St. | 8 | Asbestos Cement | 619 | 52 | 1.14 out of 5 | $442 | 273,637 |
| Distribution Main | 6999 | P-2276 | WAR | Gilbane St. | 8 | Asbestos Cement | 629 | 52 | 1.14 out of 5 | $442 | 278,079 |
| Distribution Main | 11941 | P-2428 | WAR | Gilbane St. | 8 | Asbestos Cement | 467 | 52 | 1.14 out of 5 | $442 | 206,594 |
| Distribution Main | 8276 | P-2288 | WAR | Gilbert St. | 8 | Ductile Iron | 359 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8277 | P-2288 | WAR | Gilbert St. | 8 | Ductile Iron | 548 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8287 | P-2293 | WAR | Gilbert St. | 8 | Ductile Iron | 336 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8288 | P-2293 | WAR | Gilbert St. | 8 | Ductile Iron | 328 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8289 | P-2291 | WAR | Gilbert St. | 8 | Ductile Iron | 242 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9934 | P-2286 | WAR | Gilbert St. | 8 | Ductile Iron | 106 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9935 | P-2290 | WAR | Gilbert St. | 8 | Ductile Iron | 148 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9936 | P-2286 | WAR | Gilbert St. | 8 | Ductile Iron | 136 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9937 | P-2288 | WAR | Gilbert St. | 8 | Ductile Iron | 32 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10576 | P-2293 | WAR | Gilbert St. | 8 | Ductile Iron | 30 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11458 | P-2293 | WAR | Gilbert St. | 8 | Ductile Iron | 4 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11625 | P-2291 | WAR | Gilbert St. | 8 | Ductile Iron | 6 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4862 | P-2252 | WAR | Gilbert Stuart Dr | 8 | Asbestos Cement | 29 | 46 | 1.14 out of 5 | $442 | 12,855 |
| Distribution Main | 4863 | P-2252 | WAR | Gilbert Stuart Dr | 8 | Asbestos Cement | 884 | 46 | 1.14 out of 5 | $442 | 390,828 |
| Distribution Main | 6933 | P-2252 | WAR | Gilbert Stuart Dr | 8 | Asbestos Cement | 25 | 46 | 1.14 out of 5 | $442 | 11,171 |
| Distribution Main | 11952 | P-2252 | WAR | Gilbert Stuart Dr | 8 | Asbestos Cement | 210 | 46 | 1.14 out of 5 | $442 | 92,762 |
| Distribution Main | 4865 | P-2247 | WAR | Gilbert Stuart Dr. | 8 | Asbestos Cement | 620 | 53 | 1.14 out of 5 | $442 | 274,252 |
| Distribution Main | 4866 | P-2247 | WAR | Gilbert Stuart Dr. | 8 | Asbestos Cement | 35 | 53 | 1.14 out of 5 | $442 | 15,330 |
| Distribution Main | 5552 | P-2245 | WAR | Gilbert Stuart Dr. | 8 | Asbestos Cement | 24 | 53 | 1.14 out of 5 | $442 | 10,567 |
| Distribution Main | 6812 | P-2248 | WAR | Gilbert Stuart Dr. | 8 | Asbestos Cement | 307 | 49 | 1.14 out of 5 | $442 | 135,716 |
| Distribution Main | 6884 | P-2245 | WAR | Gilbert Stuart Dr. | 8 | Asbestos Cement | 13 | 53 | 1.14 out of 5 | $442 | 5,533 |
| Distribution Main | 6903 | P-2248 | WAR | Gilbert Stuart Dr. | 8 | Asbestos Cement | 303 | 53 | 1.14 out of 5 | $442 | 133,925 |
| Distribution Main | 6904 | P-2245 | WAR | Gilbert Stuart Dr. | 8 | Asbestos Cement | 268 | 53 | 1.14 out of 5 | $442 | 118,311 |
| Distribution Main | 6905 | P-2245 | WAR | Gilbert Stuart Dr. | 8 | Asbestos Cement | 837 | 53 | 1.14 out of 5 | $442 | 369,749 |
| Distribution Main | 6935 | P-2233 | WAR | Gilbert Stuart Dr. | 8 | Asbestos Cement | 643 | 53 | 1.14 out of 5 | $442 | 284,151 |
| Distribution Main | 6936 | P-2233 | WAR | Gilbert Stuart Dr. | 8 | Asbestos Cement | 290 | 53 | 1.14 out of 5 | $442 | 127,996 |
| Distribution Main | 6939 | P-2254 | WAR | Gilbert Stuart Dr. | 8 | Asbestos Cement | 951 | 53 | 1.14 out of 5 | $442 | 420,384 |
| Distribution Main | 6940 | P-2254 | WAR | Gilbert Stuart Dr. | 8 | Asbestos Cement | 633 | 53 | 1.14 out of 5 | $442 | 279,989 |
| Distribution Main | 6608 | P-2085 | WAR | Ginger St. | 8 | Ductile Iron | 438 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6524 | P-2476 | WAR | Glass St. | 6 | Ductile Iron | 231 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 10568 | P-2900 | WAR | Globe St | 8 | Ductile Iron | 172 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6508 | P-2416 | WAR | Goodwin St. | 1.5 | Copper | 387 | 89 | 2.57 out of 5 | $442 | 171,246 |
| Distribution Main | 6512 | P-2416 | WAR | Goodwin St. | 6 | Cast Iron | 13 | 89 | 2.43 out of 5 | $442 | 5,710 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6859 | P-2416 | WAR | Goodwin St. | 6 | Cast Iron | 402 | 89 | 2.43 out of 5 | $442 | 177,707 |
| Distribution Main | 6860 | P-2416 | WAR | Goodwin St. | 6 | Cast Iron | 2 | 89 | 2.43 out of 5 | $442 | 1,091 |
| Distribution Main | 9282 | P-2883 | WAR | Gorton Holden Ter | 8 | Ductile Iron | 22 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7006 | P-2528 | WAR | Gorton Holden Ter. | 6 | Asbestos Cement | 184 | 41 | 1.85 out of 5 | $442 | 81,503 |
| Distribution Main | 7007 | P-2528 | WAR | Gorton Holden Ter. | 6 | Asbestos Cement | 320 | 41 | 1.85 out of 5 | $442 | 141,482 |
| Distribution Main | 5501 | P-2654 | WAR | Governors Dr. | 6 | Ductile Iron | 8 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 5502 | P-2654 | WAR | Governors Dr. | 6 | Ductile Iron | 25 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 5541 | P-2654 | WAR | Governors Dr. | 8 | Ductile Iron | 709 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5542 | P-2654 | WAR | Governors Dr. | 8 | Ductile Iron | 145 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5543 | P-2267 | WAR | Governors Dr. | 8 | Ductile Iron | 3 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5545 | P-2267 | WAR | Governors Dr. | 8 | Ductile Iron | 21 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5546 | P-2267 | WAR | Governors Dr. | 8 | Ductile Iron | 351 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5548 | P-2263 | WAR | Governors Dr. | 8 | Ductile Iron | 271 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5549 | P-2263 | WAR | Governors Dr. | 8 | Ductile Iron | 430 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10564 | P-2897 | WAR | Granite St | 8 | Ductile Iron | 11 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10565 | P-2897 | WAR | Granite St | 8 | Ductile Iron | 110 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10936 | | WAR | Granite St | 8 | Ductile Iron | 128 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11675 | P-2897 | WAR | Granite St | 8 | Ductile Iron | 41 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9271 | P-2910 | WAR | Great Oak Dr | 8 | Ductile Iron | 28 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7066 | P-2488 | WAR | Great Oak Dr. | 8 | Ductile Iron | 206 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7067 | P-2488 | WAR | Great Oak Dr. | 8 | Ductile Iron | 111 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6299 | P-2664 | WAR | Green Hill Way | 8 | Ductile Iron | 72 | 34 | 0.14 out of 5 | $442 | 31,970 |
| Distribution Main | 6300 | P-2664 | WAR | Green Hill Way | 8 | Ductile Iron | 301 | 34 | 0.14 out of 5 | $442 | 132,924 |
| Distribution Main | 6081 | P-2116 | WAR | Green Meadow Dr | 8 | PVC | 171 | 33 | 0.43 out of 5 | $442 | 75,517 |
| Distribution Main | 3903 | P-2890 | WAR | Greenbush Road | 8 | Ductile Iron | 185 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3904 | P-2890 | WAR | Greenbush Road | 8 | Ductile Iron | 3 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3905 | P-2890 | WAR | Greenbush Road | 8 | Ductile Iron | 15 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3906 | P-2889 | WAR | Greenbush Road | 8 | PVC | 46 | 31 | 0.43 out of 5 | $442 | 20,119 |
| Transmission Main | 10753 | P-2902 | WAR | Greenwich Av | 12 | Ductile Iron | 17 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10763 | P-2633 | WAR | Greenwich Av | 12 | Ductile Iron | 331 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10764 | P-2633 | WAR | Greenwich Av | 12 | Ductile Iron | 263 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9262 | P-2634 | WAR | Greenwich Ave | 12 | Ductile Iron | 411 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9263 | P-2634 | WAR | Greenwich Ave | 12 | Ductile Iron | 166 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9264 | P-2902 | WAR | Greenwich Ave | 12 | Ductile Iron | 17 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9267 | P-2634 | WAR | Greenwich Ave | 12 | Ductile Iron | 57 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9268 | P-2634 | WAR | Greenwich Ave | 12 | Ductile Iron | 498 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9272 | P-2489 | WAR | Greenwich Ave | 12 | Ductile Iron | 161 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9273 | P-2527 | WAR | Greenwich Ave | 12 | Ductile Iron | 213 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9283 | P-2758 | WAR | Greenwich Ave | 12 | Ductile Iron | 295 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9284 | P-2531 | WAR | Greenwich Ave | 8 | Ductile Iron | 326 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9296 | P-2634 | WAR | Greenwich Ave | 12 | Ductile Iron | 50 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9297 | P-2634 | WAR | Greenwich Ave | 12 | Ductile Iron | 217 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9725 | P-2868 | WAR | Greenwich Ave | 6 | Ductile Iron | 5 | 11 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 10937 | P-20011 | WAR | Greenwich Ave | 12 | Ductile Iron | 304 | 11 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 10938 | P-2487 | WAR | Greenwich Ave | 12 | Ductile Iron | 111 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10939 | P-2487 | WAR | Greenwich Ave | 12 | Ductile Iron | 334 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10941 | P-2903 | WAR | Greenwich Ave | 12 | Ductile Iron | 151 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10942 | P-2903 | WAR | Greenwich Ave | 12 | Ductile Iron | 216 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11564 | P-2634 | WAR | Greenwich Ave | 12 | Ductile Iron | 126 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11566 | P-2876 | WAR | Greenwich Ave | 12 | Ductile Iron | 231 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11567 | P-2521 | WAR | Greenwich Ave | 12 | Ductile Iron | 269 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11568 | P-2526 | WAR | Greenwich Ave | 12 | Ductile Iron | 277 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11569 | P-2527 | WAR | Greenwich Ave | 12 | Ductile Iron | 162 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11570 | P-2527 | WAR | Greenwich Ave | 12 | Ductile Iron | 8 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11571 | P-2872 | WAR | Greenwich Ave | 12 | Ductile Iron | 33 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11572 | P-2537 | WAR | Greenwich Ave | 8 | Ductile Iron | 323 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11573 | P-2872 | WAR | Greenwich Ave | 8 | Ductile Iron | 125 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11574 | P-2529 | WAR | Greenwich Ave | 8 | Ductile Iron | 124 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12148 | P-2487 | WAR | Greenwich Ave | 12 | Ductile Iron | 25 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12149 | P-2903 | WAR | Greenwich Ave | 12 | Ductile Iron | 33 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12152 | P-2526 | WAR | Greenwich Ave | 12 | Ductile Iron | 11 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10752 | P-2420 | WAR | Greenwich Ave. | 12 | Ductile Iron | 8 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 10011 | | WAR | Greenwich Blvd | 12 | Ductile Iron | 57 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10012 | | WAR | Greenwich Blvd | 12 | Ductile Iron | 24 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9295 | | WAR | Greenwood Commons | 8 | Ductile Iron | 7 | 11 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9151 | P-2411 | WAR | Hall St. | 12 | Ductile Iron | 37 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9152 | P-2411 | WAR | Hall St. | 12 | Ductile Iron | 365 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9205 | P-4889 | WAR | Hall St. | 12 | Ductile Iron | 6 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6077 | P-2110 | WAR | Hallmark Dr | 8 | PVC | 409 | 32 | 0.43 out of 5 | $442 | 180,923 |
| Distribution Main | 6078 | P-2110 | WAR | Hallmark Dr | 8 | PVC | 294 | 32 | 0.43 out of 5 | $442 | 130,095 |
| Distribution Main | 10248 | | WAR | Harbour Ln | 1 | Copper | 95 | 2 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 6947 | P-2022 | WAR | Hardig Rd. | 8 | Asbestos Cement | 105 | 47 | 1.14 out of 5 | $442 | 46,396 |
| Distribution Main | 6948 | P-2022 | WAR | Hardig Rd. | 8 | Asbestos Cement | 6 | 47 | 1.14 out of 5 | $442 | 2,537 |
| Transmission Main | 10509 | P-2104 | WAR | Hardig Rd. | 12 | Ductile Iron | 56 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 10510 | P-2104 | WAR | Hardig Rd. | 12 | Ductile Iron | 11 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 10511 | P-2104 | WAR | Hardig Rd. | 12 | Ductile Iron | 194 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 10513 | | WAR | Hardig Rd. | 12 | Ductile Iron | 14 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11668 | P-2104 | WAR | Hardig Rd. | 12 | Ductile Iron | 10 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5203 | P-2927 | WAR | Harrop Ave. | 6 | Cast Iron | 19 | 86 | 2.43 out of 5 | $442 | 8,467 |
| Distribution Main | 5224 | P-2597 | WAR | Harrop Ave. | 6 | Cast Iron | 7 | 86 | 2.43 out of 5 | $442 | 2,912 |
| Distribution Main | 5701 | P-2597 | WAR | Harrop Ave. | 6 | Cast Iron | 627 | 86 | 2.43 out of 5 | $442 | 277,249 |
| Distribution Main | 5702 | P-2597 | WAR | Harrop Ave. | 6 | Cast Iron | 21 | 86 | 2.43 out of 5 | $442 | 9,222 |
| Distribution Main | 7040 | P-2424 | WAR | Harrop Ave. | 8 | Asbestos Cement | 641 | 73 | 1.29 out of 5 | $442 | 283,528 |
| Distribution Main | 7041 | P-2424 | WAR | Harrop Ave. | 8 | Asbestos Cement | 46 | 73 | 1.29 out of 5 | $442 | 20,480 |
| Distribution Main | 2836 | P-2272 | WAR | Hedgerow Dr. | 6 | Asbestos Cement | 172 | 54 | 1.85 out of 5 | $442 | 75,903 |
| Distribution Main | 2837 | P-2197 | WAR | Hedgerow Dr. | 8 | Asbestos Cement | 171 | 54 | 1.14 out of 5 | $442 | 75,505 |
| Distribution Main | 3630 | P-2211 | WAR | Hedgerow Dr. | 8 | Asbestos Cement | 223 | 54 | 1.14 out of 5 | $442 | 98,649 |
| Distribution Main | 3631 | P-2210 | WAR | Hedgerow Dr. | 8 | Asbestos Cement | 112 | 54 | 1.14 out of 5 | $442 | 49,535 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3632 | P-2191 | WAR | Hedgerow Dr. | 8 | Asbestos Cement | 172 | 54 | 1.14 out of 5 | $442 | 75,951 |
| Distribution Main | 3633 | P-2191 | WAR | Hedgerow Dr. | 8 | Asbestos Cement | 51 | 54 | 1.14 out of 5 | $442 | 22,441 |
| Distribution Main | 4874 | P-2271 | WAR | Hedgerow Dr. | 8 | Asbestos Cement | 398 | 54 | 1.14 out of 5 | $442 | 176,110 |
| Distribution Main | 4875 | P-2212 | WAR | Hedgerow Dr. | 2 | Copper | 148 | 54 | 2.28 out of 5 | $442 | 65,574 |
| Distribution Main | 5775 | P-2270 | WAR | Hedgerow Dr. | 8 | Asbestos Cement | 117 | 54 | 1.14 out of 5 | $442 | 51,845 |
| Distribution Main | 5776 | P-2270 | WAR | Hedgerow Dr. | 8 | Asbestos Cement | 425 | 54 | 1.14 out of 5 | $442 | 187,993 |
| Distribution Main | 10537 | P-2445 | WAR | Herbert St | 8 | Ductile Iron | 502 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10538 | P-2446 | WAR | Herbert St | 8 | Ductile Iron | 124 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10952 | P-2447 | WAR | Herbert St | 8 | Ductile Iron | 31 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10953 | P-2447 | WAR | Herbert St | 8 | Ductile Iron | 179 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11669 | P-2446 | WAR | Herbert St | 8 | Ductile Iron | 67 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11670 | P-2446 | WAR | Herbert St | 8 | Ductile Iron | 25 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3221 | P-2240 | WAR | Heritage Dr. | 8 | Asbestos Cement | 15 | 53 | 1.14 out of 5 | $442 | 6,514 |
| Distribution Main | 5538 | P-2232 | WAR | Heritage Dr. | 8 | Asbestos Cement | 7 | 55 | 1.14 out of 5 | $442 | 3,089 |
| Distribution Main | 6303 | P-2235 | WAR | Heritage Dr. | 8 | Asbestos Cement | 312 | 53 | 1.14 out of 5 | $442 | 137,765 |
| Distribution Main | 6885 | P-2232 | WAR | Heritage Dr. | 8 | Asbestos Cement | 118 | 55 | 1.14 out of 5 | $442 | 52,124 |
| Distribution Main | 6886 | P-2232 | WAR | Heritage Dr. | 8 | Asbestos Cement | 496 | 55 | 1.14 out of 5 | $442 | 219,229 |
| Distribution Main | 6896 | P-2240 | WAR | Heritage Dr. | 8 | Asbestos Cement | 299 | 53 | 1.14 out of 5 | $442 | 131,941 |
| Distribution Main | 6897 | P-2240 | WAR | Heritage Dr. | 8 | Asbestos Cement | 761 | 53 | 1.14 out of 5 | $442 | 336,507 |
| Distribution Main | 6937 | P-2243 | WAR | Heritage Dr. | 8 | Asbestos Cement | 256 | 53 | 1.14 out of 5 | $442 | 113,309 |
| Distribution Main | 6938 | P-2243 | WAR | Heritage Dr. | 8 | Asbestos Cement | 564 | 53 | 1.14 out of 5 | $442 | 249,467 |
| Distribution Main | 6825 | P-2400 | WAR | Hesper Dr. | 8 | Ductile Iron | 11 | 32 | 0.14 out of 5 | $442 | 4,996 |
| Distribution Main | 6826 | P-2400 | WAR | Hesper Dr. | 8 | Ductile Iron | 525 | 32 | 0.14 out of 5 | $442 | 231,903 |
| Distribution Main | 6427 | P-2453 | WAR | Hibiscus Ln. | 8 | Ductile Iron | 5 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7243 | P-2455 | WAR | Hibiscus Ln. | 8 | Ductile Iron | 239 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7244 | P-2455 | WAR | Hibiscus Ln. | 8 | Ductile Iron | 214 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7253 | P-2453 | WAR | Hibiscus Ln. | 8 | Ductile Iron | 252 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7254 | P-2453 | WAR | Hibiscus Ln. | 8 | Ductile Iron | 82 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11963 | P-2455 | WAR | Hibiscus Ln. | 8 | Ductile Iron | 121 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7112 | P-2346 | WAR | Highland Ave. | 8 | Asbestos Cement | 579 | 66 | 1.29 out of 5 | $442 | 255,793 |
| Distribution Main | 7113 | P-2346 | WAR | Highland Ave. | 8 | Asbestos Cement | 425 | 66 | 1.29 out of 5 | $442 | 187,939 |
| Distribution Main | 7116 | P-2342 | WAR | Highland Ave. | 8 | Cast Iron | 37 | 83 | 1.72 out of 5 | $442 | 16,134 |
| Distribution Main | 7117 | P-2342 | WAR | Highland Ave. | 8 | Cast Iron | 644 | 83 | 1.72 out of 5 | $442 | 284,545 |
| Distribution Main | 7337 | P-2345 | WAR | Highland Ave. | 8 | Cast Iron | 104 | 83 | 1.72 out of 5 | $442 | 46,170 |
| Distribution Main | 7338 | P-2345 | WAR | Highland Ave. | 8 | Cast Iron | 748 | 83 | 1.72 out of 5 | $442 | 330,753 |
| Distribution Main | 9604 | P-2342 | WAR | Highland Ave. | 8 | Ductile Iron | 31 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11947 | P-2345 | WAR | Highland Ave. | 8 | Cast Iron | 300 | 83 | 1.72 out of 5 | $442 | 132,518 |
| Distribution Main | 6868 | P-2414 | WAR | Highpoint Dr. | 6 | Asbestos Cement | 627 | 65 | 2 out of 5 | $442 | 277,105 |
| Distribution Main | 6869 | P-2414 | WAR | Highpoint Dr. | 6 | Asbestos Cement | 59 | 65 | 2 out of 5 | $442 | 25,900 |
| Distribution Main | 10572 | | WAR | Hilary St | 8 | Ductile Iron | 125 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10573 | P-2324 | WAR | Hilary St | 8 | Ductile Iron | 225 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10566 | P-2898 | WAR | Hilburt St | 8 | Ductile Iron | 139 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2524 | P-2578 | WAR | Hill Top Dr. | 6 | Asbestos Cement | 6 | 71 | 2 out of 5 | $442 | 2,583 |
| Distribution Main | 2525 | P-2578 | WAR | Hill Top Dr. | 6 | Asbestos Cement | 490 | 71 | 2 out of 5 | $442 | 216,523 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4585 | P-2574 | WAR | Hill Top Dr. | 6 | Asbestos Cement | 325 | 71 | 2 out of 5 | $442 | 143,523 |
| Distribution Main | 5032 | P-2576 | WAR | Hill Top Dr. | 6 | Asbestos Cement | 2 | 71 | 2 out of 5 | $442 | 729 |
| Distribution Main | 5033 | P-2576 | WAR | Hill Top Dr. | 6 | Asbestos Cement | 695 | 71 | 2.71 out of 5 | $442 | 307,202 |
| Transmission Main | 5034 | P-2650 | WAR | Hill Top Dr. | 20 | Asbestos Cement | 320 | 55 | 1.14 out of 5 | $442 | 141,262 |
| Distribution Main | 5042 | P-2578 | WAR | Hill Top Dr. | 6 | Asbestos Cement | 341 | 71 | 2 out of 5 | $442 | 150,515 |
| Distribution Main | 11257 | P-2574 | WAR | Hill Top Dr. | 6 | Asbestos Cement | 5 | 71 | 2 out of 5 | $442 | 2,375 |
| Distribution Main | 5694 | P-2031 | WAR | Hollow Ct. | 6 | Asbestos Cement | 348 | 42 | 1.85 out of 5 | $442 | 153,795 |
| Distribution Main | 4495 | P-2262 | WAR | Indian Hill Rd. | 6 | Ductile Iron | 35 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 4496 | P-2262 | WAR | Indian Hill Rd. | 6 | Ductile Iron | 319 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11970 | P-2262 | WAR | Indian Hill Rd. | 6 | Ductile Iron | 224 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 367 | P-2040 | WAR | Irene St. | 8 | Ductile Iron | 163 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5214 | P-2041 | WAR | Irene St. | 8 | Ductile Iron | 82 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5699 | P-2040 | WAR | Irene St. | 8 | Ductile Iron | 265 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7065 | P-2505 | WAR | Irondale St. | 6 | Asbestos Cement | 508 | 65 | 2 out of 5 | $442 | 224,444 |
| Distribution Main | 7004 | P-2535 | WAR | Ironwood Ct. | 1 | Copper | 209 | 62 | 2.43 out of 5 | $442 | 92,338 |
| Distribution Main | 7106 | P-2348 | WAR | Island View Dr. | 8 | Asbestos Cement | 204 | 44 | 1.14 out of 5 | $442 | 90,048 |
| Distribution Main | 7107 | P-2348 | WAR | Island View Dr. | 8 | Asbestos Cement | 8 | 44 | 1.14 out of 5 | $442 | 3,335 |
| Distribution Main | 7336 | P-2349 | WAR | Island View Dr. | 8 | Asbestos Cement | 359 | 44 | 1.14 out of 5 | $442 | 158,685 |
| Distribution Main | 7340 | P-2348 | WAR | Island View Dr. | 8 | Asbestos Cement | 8 | 44 | 1.14 out of 5 | $442 | 3,649 |
| Distribution Main | 9872 | P-2570 | WAR | Jambray Ave | 8 | Ductile Iron | 292 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9873 | P-2570 | WAR | Jambray Ave | 8 | Ductile Iron | 93 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9880 | P-2573 | WAR | Jambray Ave | 8 | Ductile Iron | 869 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9881 | P-2573 | WAR | Jambray Ave | 8 | Ductile Iron | 308 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11620 | P-2573 | WAR | Jambray Ave | 8 | Ductile Iron | 70 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4461 | P-2093 | WAR | Jerry St. | 6 | Ductile Iron | 7 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 6068 | P-2093 | WAR | Jerry St. | 6 | Ductile Iron | 85 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 6069 | P-2093 | WAR | Jerry St. | 6 | Ductile Iron | 218 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 6502 | P-2438 | WAR | John Wickes Ave. | 6 | Ductile Iron | 3 | 31 | 0.85 out of 5 | $442 | 1,232 |
| Distribution Main | 6503 | P-2438 | WAR | John Wickes Ave. | 6 | Ductile Iron | 648 | 31 | 0.85 out of 5 | $442 | 286,375 |
| Distribution Main | 10549 | P-2438 | WAR | John Wickes Ave. | 6 | Ductile Iron | 15 | 2 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10550 | P-2438 | WAR | John Wickes Ave. | 6 | Ductile Iron | 16 | 2 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 6875 | P-2259 | WAR | Joseph Ct | 8 | PVC | 525 | 33 | 0.43 out of 5 | $442 | 231,919 |
| Distribution Main | 10208 | P-2259 | WAR | Joseph Ct | 8 | PVC | 601 | 33 | 0.43 out of 5 | $442 | 265,501 |
| Distribution Main | 10209 | P-2259 | WAR | Joseph Ct | 8 | PVC | 635 | 33 | 0.43 out of 5 | $442 | 280,758 |
| Distribution Main | 11954 | P-2259 | WAR | Joseph Ct | 8 | PVC | 433 | 33 | 0.43 out of 5 | $442 | 191,533 |
| Distribution Main | 6088 | P-2394 | WAR | Joyce Glen | 1 | Copper | 188 | 63 | 2.43 out of 5 | $442 | 83,166 |
| Distribution Main | 6612 | P-2045 | WAR | Judge St. | 8 | Asbestos Cement | 24 | 58 | 1.14 out of 5 | $442 | 10,635 |
| Distribution Main | 7359 | P-2045 | WAR | Judge St. | 6 | Asbestos Cement | 234 | 58 | 1.85 out of 5 | $442 | 103,525 |
| Distribution Main | 6672 | P-2144 | WAR | Katelyn Ct. | 8 | Ductile Iron | 400 | 29 | 0.14 out of 5 | $442 | 176,842 |
| Distribution Main | 7383 | P-2539 | WAR | Kearsage Dr. | 8 | Asbestos Cement | 304 | 56 | 1.14 out of 5 | $442 | 134,365 |
| Distribution Main | 11379 | P-2539 | WAR | Kearsage Dr. | 8 | Asbestos Cement | 129 | 56 | 1.14 out of 5 | $442 | 57,135 |
| Distribution Main | 9146 | P-2409 | WAR | Ladd St | 8 | Ductile Iron | 240 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9189 | P-2404 | WAR | Ladd St | 8 | Ductile Iron | 241 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10850 | P-2457 | WAR | Ladd St | 8 | Ductile Iron | 238 | 8 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4538 | P-2409 | WAR | Ladd St. | 4 | Cast Iron | 42 | 129 | 3.29 out of 5 | $442 | 18,766 |
| Distribution Main | 5759 | P-2174 | WAR | Ladderlook Road | 8 | Asbestos Cement | 987 | 59 | 1.14 out of 5 | $442 | 436,473 |
| Distribution Main | 5760 | P-2174 | WAR | Ladderlook Road | 8 | Asbestos Cement | 9 | 59 | 1.14 out of 5 | $442 | 3,830 |
| Distribution Main | 9280 | P-2881 | WAR | Lancaster Ave | 8 | Ductile Iron | 19 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9292 | P-2881 | WAR | Lancaster Ave | 6 | Ductile Iron | 2 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 7010 | P-2518 | WAR | Lancaster Ave. | 6 | Asbestos Cement | 265 | 69 | 2 out of 5 | $442 | 117,041 |
| Distribution Main | 7012 | P-2882 | WAR | Lancaster Ave. | 6 | Asbestos Cement | 232 | 69 | 2 out of 5 | $442 | 102,384 |
| Distribution Main | 7014 | P-2508 | WAR | Lancaster Ave. | 6 | Asbestos Cement | 123 | 69 | 2 out of 5 | $442 | 54,341 |
| Distribution Main | 7015 | P-2508 | WAR | Lancaster Ave. | 6 | Asbestos Cement | 476 | 69 | 2 out of 5 | $442 | 210,460 |
| Distribution Main | 7016 | P-2506 | WAR | Lancaster Ave. | 6 | Asbestos Cement | 242 | 69 | 2 out of 5 | $442 | 106,976 |
| Distribution Main | 7076 | P-2524 | WAR | Lancaster Ave. | 6 | Asbestos Cement | 138 | 69 | 2 out of 5 | $442 | 60,829 |
| Distribution Main | 7077 | P-2524 | WAR | Lancaster Ave. | 6 | Asbestos Cement | 114 | 69 | 2 out of 5 | $442 | 50,254 |
| Distribution Main | 4870 | P-2163 | WAR | Landmark Rd. | 8 | Asbestos Cement | 1,105 | 63 | 1.29 out of 5 | $442 | 488,623 |
| Distribution Main | 7176 | P-2712 | WAR | Lantern Ln. | 6 | Asbestos Cement | 560 | 73 | 2 out of 5 | $442 | 247,655 |
| Distribution Main | 4379 | P-2028 | WAR | Larchmont Rd. | 6 | Asbestos Cement | 559 | 57 | 1.85 out of 5 | $442 | 247,211 |
| Distribution Main | 5691 | P-2028 | WAR | Larchmont Rd. | 8 | Asbestos Cement | 6 | 57 | 1.14 out of 5 | $442 | 2,712 |
| Distribution Main | 5698 | | WAR | Larchmont Rd. | 6 | Asbestos Cement | 15 | 57 | 1.85 out of 5 | $442 | 6,608 |
| Distribution Main | 5981 | P-2049 | WAR | Larchmont Rd. | 6 | Asbestos Cement | 251 | 57 | 1.85 out of 5 | $442 | 110,811 |
| Distribution Main | 7046 | P-2028 | WAR | Larchmont Rd. | 6 | Asbestos Cement | 26 | 57 | 1.85 out of 5 | $442 | 11,702 |
| Distribution Main | 7047 | P-2028 | WAR | Larchmont Rd. | 6 | Asbestos Cement | 682 | 57 | 2.57 out of 5 | $442 | 301,452 |
| Distribution Main | 7062 | P-2028 | WAR | Larchmont Rd. | 8 | Asbestos Cement | 4 | 57 | 1.14 out of 5 | $442 | 1,637 |
| Distribution Main | 7064 | | WAR | Larchmont Rd. | 6 | Asbestos Cement | 79 | 57 | 1.85 out of 5 | $442 | 34,975 |
| Distribution Main | 7369 | P-2046 | WAR | Larchmont Rd. | 6 | Asbestos Cement | 192 | 57 | 1.85 out of 5 | $442 | 84,781 |
| Distribution Main | 7370 | P-2046 | WAR | Larchmont Rd. | 6 | Asbestos Cement | 421 | 57 | 1.85 out of 5 | $442 | 186,011 |
| Transmission Main | 10195 | | WAR | Larchwood Dr | 12 | PVC | 4 | 32 | 0.43 out of 5 | $442 | 1,851 |
| Transmission Main | 10196 | | WAR | Larchwood Dr | 12 | PVC | 38 | 32 | 0.43 out of 5 | $442 | 16,791 |
| Transmission Main | 6066 | P-2120 | WAR | Larchwood Dr. | 12 | PVC | 194 | 32 | 0.43 out of 5 | $442 | 85,749 |
| Transmission Main | 6067 | P-2120 | WAR | Larchwood Dr. | 12 | PVC | 507 | 32 | 0.43 out of 5 | $442 | 223,927 |
| Transmission Main | 7319 | P-2122 | WAR | Larchwood Dr. | 12 | PVC | 336 | 32 | 0.43 out of 5 | $442 | 148,702 |
| Transmission Main | 10187 | P-2120 | WAR | Larchwood Dr. | 12 | PVC | 21 | 32 | 0.43 out of 5 | $442 | 9,388 |
| Transmission Main | 10188 | P-2120 | WAR | Larchwood Dr. | 12 | PVC | 315 | 32 | 0.43 out of 5 | $442 | 139,082 |
| Transmission Main | 10189 | P-2122 | WAR | Larchwood Dr. | 12 | PVC | 14 | 32 | 0.43 out of 5 | $442 | 6,035 |
| Transmission Main | 10190 | P-2122 | WAR | Larchwood Dr. | 12 | PVC | 410 | 32 | 0.43 out of 5 | $442 | 181,090 |
| Transmission Main | 10191 | P-2126 | WAR | Larchwood Dr. | 12 | PVC | 417 | 32 | 0.43 out of 5 | $442 | 184,409 |
| Transmission Main | 10192 | P-2126 | WAR | Larchwood Dr. | 12 | PVC | 257 | 32 | 0.43 out of 5 | $442 | 113,482 |
| Transmission Main | 10193 | P-2126 | WAR | Larchwood Dr. | 12 | PVC | 137 | 32 | 0.43 out of 5 | $442 | 60,644 |
| Transmission Main | 10194 | P-2126 | WAR | Larchwood Dr. | 12 | PVC | 576 | 32 | 0.43 out of 5 | $442 | 254,544 |
| Transmission Main | 10197 | P-2120 | WAR | Larchwood Dr. | 12 | PVC | 160 | 32 | 0.43 out of 5 | $442 | 70,606 |
| Transmission Main | 10198 | P-2126 | WAR | Larchwood Dr. | 12 | PVC | 7 | 32 | 0.43 out of 5 | $442 | 3,187 |
| Transmission Main | 10199 | P-2126 | WAR | Larchwood Dr. | 12 | PVC | 216 | 32 | 0.43 out of 5 | $442 | 95,356 |
| Transmission Main | 10915 | P-2119 | WAR | Larchwood Dr. | 12 | PVC | 363 | 32 | 0.43 out of 5 | $442 | 160,634 |
| Transmission Main | 10916 | P-2124 | WAR | Larchwood Dr. | 12 | PVC | 187 | 32 | 0.43 out of 5 | $442 | 82,600 |
| Transmission Main | 11643 | P-2126 | WAR | Larchwood Dr. | 12 | PVC | 201 | 32 | 0.43 out of 5 | $442 | 89,020 |
| Transmission Main | 12214 | P-2122 | WAR | Larchwood Dr. | 12 | PVC | 136 | 32 | 0.43 out of 5 | $442 | 60,130 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4295 | P-2312 | WAR | Ledgemont Dr. | 8 | Asbestos Cement | 646 | 52 | 1.14 out of 5 | $442 | 285,392 |
| Distribution Main | 6094 | P-2316 | WAR | Leon Whipple Rd. | 8 | Ductile Iron | 4 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6095 | P-2316 | WAR | Leon Whipple Rd. | 8 | Ductile Iron | 194 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6104 | P-2316 | WAR | Leon Whipple Rd. | 8 | Ductile Iron | 11 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6106 | P-2316 | WAR | Leon Whipple Rd. | 8 | Ductile Iron | 472 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6107 | P-2316 | WAR | Leon Whipple Rd. | 8 | Ductile Iron | 8 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6951 | P-2315 | WAR | Leon Whipple Rd. | 8 | Ductile Iron | 355 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9874 | P-2569 | WAR | Levesque St | 8 | Ductile Iron | 44 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9875 | P-2569 | WAR | Levesque St | 8 | Ductile Iron | 301 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9878 | P-2571 | WAR | Levesque St | 8 | Ductile Iron | 386 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9879 | P-2571 | WAR | Levesque St | 8 | Ductile Iron | 470 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9917 | P-2571 | WAR | Levesque St | 8 | Ductile Iron | 126 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6657 | P-2206 | WAR | Lisa Marie Cir. | 8 | PVC | 532 | 31 | 0.43 out of 5 | $442 | 235,315 |
| Distribution Main | 6658 | P-2206 | WAR | Lisa Marie Cir. | 8 | PVC | 7 | 31 | 0.43 out of 5 | $442 | 3,180 |
| Distribution Main | 7355 | P-2941 | WAR | Little Lane | 1 | Copper | 207 | 70 | 2.43 out of 5 | $442 | 91,413 |
| Distribution Main | 9325 | P-2652 | WAR | Love Ln | 8 | Ductile Iron | 49 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9326 | P-2658 | WAR | Love Ln | 8 | Ductile Iron | 26 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10210 | P-2652 | WAR | Love Ln | 8 | Ductile Iron | 6 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 3311 | P-2330 | WAR | Love Ln. | 12 | Ductile Iron | 15 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4231 | P-2273 | WAR | Love Ln. | 12 | Ductile Iron | 151 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4232 | P-2273 | WAR | Love Ln. | 12 | Ductile Iron | 338 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 4527 | P-2657 | WAR | Love Ln. | 12 | Asbestos Cement | 25 | 62 | 1.29 out of 5 | $442 | 10,898 |
| Transmission Main | 4528 | P-2657 | WAR | Love Ln. | 12 | Asbestos Cement | 19 | 62 | 1.29 out of 5 | $442 | 8,471 |
| Transmission Main | 4584 | P-2574 | WAR | Love Ln. | 20 | Asbestos Cement | 15 | 55 | 1.14 out of 5 | $442 | 6,688 |
| Transmission Main | 5553 | P-2657 | WAR | Love Ln. | 12 | Asbestos Cement | 913 | 62 | 1.29 out of 5 | $442 | 403,459 |
| Transmission Main | 5554 | P-2657 | WAR | Love Ln. | 12 | Asbestos Cement | 1,369 | 62 | 1.29 out of 5 | $442 | 605,062 |
| Transmission Main | 5736 | P-2330 | WAR | Love Ln. | 16 | Ductile Iron | 300 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5737 | P-2330 | WAR | Love Ln. | 16 | Ductile Iron | 224 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5738 | P-2139 | WAR | Love Ln. | 12 | Ductile Iron | 574 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5739 | P-2139 | WAR | Love Ln. | 12 | Ductile Iron | 299 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5741 | P-2338 | WAR | Love Ln. | 16 | Ductile Iron | 351 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5742 | P-2338 | WAR | Love Ln. | 16 | Ductile Iron | 152 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5745 | P-2164 | WAR | Love Ln. | 12 | Ductile Iron | 503 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5746 | P-2164 | WAR | Love Ln. | 12 | Ductile Iron | 120 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5748 | P-2377 | WAR | Love Ln. | 16 | Ductile Iron | 157 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5749 | P-2377 | WAR | Love Ln. | 16 | Ductile Iron | 844 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5766 | P-2165 | WAR | Love Ln. | 12 | Ductile Iron | 478 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5767 | P-2165 | WAR | Love Ln. | 12 | Ductile Iron | 521 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5773 | P-2596 | WAR | Love Ln. | 16 | Ductile Iron | 262 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5774 | P-2596 | WAR | Love Ln. | 16 | Ductile Iron | 1,389 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6828 | P-2273 | WAR | Love Ln. | 12 | Ductile Iron | 68 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6837 | P-2659 | WAR | Love Ln. | 12 | Ductile Iron | 63 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6890 | P-2832 | WAR | Love Ln. | 16 | Ductile Iron | 254 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 6891 | P-2832 | WAR | Love Ln. | 16 | Ductile Iron | 241 | 22 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 6914 | P-2829 | WAR | Love Ln. | 20 | Asbestos Cement | 698 | 55 | 1.14 out of 5 | $442 | 308,300 |
| Transmission Main | 6917 | P-2828 | WAR | Love Ln. | 20 | Asbestos Cement | 149 | 55 | 1.14 out of 5 | $442 | 65,637 |
| Transmission Main | 6918 | P-2828 | WAR | Love Ln. | 20 | Asbestos Cement | 438 | 55 | 1.14 out of 5 | $442 | 193,394 |
| Transmission Main | 6919 | P-2659 | WAR | Love Ln. | 12 | Asbestos Cement | 75 | 62 | 1.29 out of 5 | $442 | 33,205 |
| Transmission Main | 6920 | P-2830 | WAR | Love Ln. | 20 | Asbestos Cement | 215 | 55 | 1.14 out of 5 | $442 | 94,842 |
| Transmission Main | 9486 | P-2651 | WAR | Love Ln. | 20 | Asbestos Cement | 126 | 55 | 1.14 out of 5 | $442 | 55,763 |
| Transmission Main | 9487 | P-2659 | WAR | Love Ln. | 20 | Asbestos Cement | 70 | 55 | 1.14 out of 5 | $442 | 30,816 |
| Transmission Main | 9589 | P-2831 | WAR | Love Ln. | 12 | Asbestos Cement | 127 | 62 | 1.29 out of 5 | $442 | 56,231 |
| Transmission Main | 9590 | P-2651 | WAR | Love Ln. | 20 | Asbestos Cement | 99 | 55 | 1.14 out of 5 | $442 | 43,596 |
| Transmission Main | 9599 | P-2164 | WAR | Love Ln. | 12 | Ductile Iron | 262 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9600 | P-2164 | WAR | Love Ln. | 12 | Ductile Iron | 223 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9601 | P-2596 | WAR | Love Ln. | 16 | Ductile Iron | 1,269 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9605 | P-2139 | WAR | Love Ln. | 12 | Ductile Iron | 254 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9606 | P-2139 | WAR | Love Ln. | 12 | Ductile Iron | 52 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9607 | P-2343 | WAR | Love Ln. | 16 | Ductile Iron | 226 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9611 | P-2659 | WAR | Love Ln. | 20 | Ductile Iron | 6 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11950 | P-2273 | WAR | Love Ln. | 12 | Ductile Iron | 73 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11964 | P-2164 | WAR | Love Ln. | 12 | Ductile Iron | 461 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11965 | P-2164 | WAR | Love Ln. | 12 | Ductile Iron | 555 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11966 | P-2164 | WAR | Love Ln. | 12 | Ductile Iron | 473 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 12209 | P-2164 | WAR | Love Ln. | 12 | Ductile Iron | 78 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 12210 | P-2139 | WAR | Love Ln. | 12 | Ductile Iron | 152 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9265 | P-2904 | WAR | Luther Ave | 6 | Ductile Iron | 41 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9465 | P-2905 | WAR | Luther Ave | 1 | Copper | 240 | UNK | 1.99 out of 5 | $442 | 106,094 |
| Distribution Main | 11565 | | WAR | Luther Ave | 6 | Ductile Iron | 1 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 7321 | P-2127 | WAR | Macera Cir. | 8 | PVC | 345 | 31 | 0.43 out of 5 | $442 | 152,563 |
| Distribution Main | 1212 | P-2744 | WAR | Major Potter Rd. | 8 | Ductile Iron | 768 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1738 | | WAR | Major Potter Rd. | 8 | PVC | 3 | 31 | 0.43 out of 5 | $442 | 1,323 |
| Distribution Main | 1739 | | WAR | Major Potter Rd. | 8 | PVC | 16 | 31 | 0.43 out of 5 | $442 | 7,126 |
| Transmission Main | 2519 | P-2103 | WAR | Major Potter Rd. | 12 | Ductile Iron | 261 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2520 | P-2224 | WAR | Major Potter Rd. | 12 | Ductile Iron | 128 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2521 | P-2224 | WAR | Major Potter Rd. | 12 | Ductile Iron | 88 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2522 | P-2224 | WAR | Major Potter Rd. | 12 | Ductile Iron | 77 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3309 | P-2258 | WAR | Major Potter Rd. | 8 | Asbestos Cement | 642 | 44 | 1.14 out of 5 | $442 | 283,721 |
| Distribution Main | 3624 | P-2261 | WAR | Major Potter Rd. | 8 | Asbestos Cement | 500 | 44 | 1.14 out of 5 | $442 | 220,888 |
| Distribution Main | 4239 | P-2185 | WAR | Major Potter Rd. | 8 | PVC | 293 | 33 | 0.43 out of 5 | $442 | 129,533 |
| Distribution Main | 4240 | P-2185 | WAR | Major Potter Rd. | 8 | PVC | 252 | 33 | 0.43 out of 5 | $442 | 111,484 |
| Transmission Main | 4695 | | WAR | Major Potter Rd. | 12 | Unknown | 9 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 4873 | P-2260 | WAR | Major Potter Rd. | 8 | Asbestos Cement | 264 | 44 | 1.14 out of 5 | $442 | 116,827 |
| Transmission Main | 4913 | P-2743 | WAR | Major Potter Rd. | 12 | Asbestos Cement | 355 | 42 | 1.14 out of 5 | $442 | 157,063 |
| Transmission Main | 4914 | P-2743 | WAR | Major Potter Rd. | 12 | Asbestos Cement | 11 | 42 | 1.14 out of 5 | $442 | 4,688 |
| Transmission Main | 5903 | P-2224 | WAR | Major Potter Rd. | 12 | Ductile Iron | 262 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6383 | P-2745 | WAR | Major Potter Rd. | 8 | Ductile Iron | 4 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6650 | P-2225 | WAR | Major Potter Rd. | 12 | PVC | 413 | 22 | 0.43 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6651 | P-2184 | WAR | Major Potter Rd. | 8 | PVC | 136 | 33 | 0.43 out of 5 | $442 | 60,110 |
| Distribution Main | 6652 | P-2184 | WAR | Major Potter Rd. | 8 | PVC | 450 | 33 | 0.43 out of 5 | $442 | 198,939 |
| Distribution Main | 6735 | P-2744 | WAR | Major Potter Rd. | 8 | Ductile Iron | 17 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6871 | P-2257 | WAR | Major Potter Rd. | 8 | PVC | 313 | 33 | 0.43 out of 5 | $442 | 138,510 |
| Distribution Main | 6872 | P-2257 | WAR | Major Potter Rd. | 8 | PVC | 84 | 33 | 0.43 out of 5 | $442 | 37,002 |
| Distribution Main | 6873 | P-2256 | WAR | Major Potter Rd. | 8 | PVC | 24 | 33 | 0.43 out of 5 | $442 | 10,720 |
| Distribution Main | 6874 | P-2256 | WAR | Major Potter Rd. | 8 | PVC | 177 | 33 | 0.43 out of 5 | $442 | 78,436 |
| Transmission Main | 7179 | P-2103 | WAR | Major Potter Rd. | 12 | Ductile Iron | 3 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7181 | P-2103 | WAR | Major Potter Rd. | 8 | Ductile Iron | 3 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 7182 | P-2118 | WAR | Major Potter Rd. | 12 | PVC | 215 | 31 | 0.43 out of 5 | $442 | 95,238 |
| Distribution Main | 7281 | P-2645 | WAR | Major Potter Rd. | 8 | PVC | 544 | 36 | 0.43 out of 5 | $442 | 240,378 |
| Distribution Main | 7282 | P-2645 | WAR | Major Potter Rd. | 8 | PVC | 515 | 36 | 0.43 out of 5 | $442 | 227,421 |
| Distribution Main | 7287 | P-2745 | WAR | Major Potter Rd. | 8 | Ductile Iron | 11 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7292 | P-2646 | WAR | Major Potter Rd. | 12 | Asbestos Cement | 128 | 42 | 1.14 out of 5 | $442 | 56,503 |
| Transmission Main | 9298 | P-2746 | WAR | Major Potter Rd. | 12 | PVC | 314 | 36 | 0.43 out of 5 | $442 | 138,687 |
| Transmission Main | 9299 | P-2646 | WAR | Major Potter Rd. | 12 | PVC | 578 | 36 | 0.43 out of 5 | $442 | 255,385 |
| Transmission Main | 9300 | P-2646 | WAR | Major Potter Rd. | 12 | PVC | 274 | 36 | 0.43 out of 5 | $442 | 121,231 |
| Distribution Main | 9596 | P-2261 | WAR | Major Potter Rd. | 8 | Ductile Iron | 12 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9597 | P-2261 | WAR | Major Potter Rd. | 8 | Ductile Iron | 33 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11106 | P-2744 | WAR | Major Potter Rd. | 8 | Ductile Iron | 17 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11955 | P-2645 | WAR | Major Potter Rd. | 8 | PVC | 137 | 36 | 0.43 out of 5 | $442 | 60,378 |
| Distribution Main | 11956 | P-2645 | WAR | Major Potter Rd. | 8 | PVC | 362 | 36 | 0.43 out of 5 | $442 | 160,002 |
| Distribution Main | 11957 | P-2645 | WAR | Major Potter Rd. | 8 | PVC | 484 | 36 | 0.43 out of 5 | $442 | 214,060 |
| Distribution Main | 11958 | P-2645 | WAR | Major Potter Rd. | 8 | PVC | 426 | 36 | 0.43 out of 5 | $442 | 188,289 |
| Distribution Main | 11959 | P-2645 | WAR | Major Potter Rd. | 8 | PVC | 497 | 36 | 0.43 out of 5 | $442 | 219,829 |
| Distribution Main | 11960 | P-2645 | WAR | Major Potter Rd. | 8 | PVC | 473 | 36 | 0.43 out of 5 | $442 | 208,944 |
| Distribution Main | 11961 | P-2645 | WAR | Major Potter Rd. | 8 | PVC | 55 | 36 | 0.43 out of 5 | $442 | 24,479 |
| Transmission Main | 12221 | P-2646 | WAR | Major Potter Rd. | 12 | Asbestos Cement | 10 | 42 | 1.14 out of 5 | $442 | 4,431 |
| Distribution Main | 10541 | P-2950 | WAR | Manton St | 8 | Ductile Iron | 165 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5711 | P-2088 | WAR | Mark Allen Dr. | 8 | Ductile Iron | 417 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5712 | P-2088 | WAR | Mark Allen Dr. | 8 | Ductile Iron | 44 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6598 | P-2088 | WAR | Mark Allen Dr. | 8 | Ductile Iron | 289 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6599 | P-2088 | WAR | Mark Allen Dr. | 8 | Ductile Iron | 129 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9160 | P-4614 | WAR | Marlborough St | 12 | Ductile Iron | 12 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6679 | P-2175 | WAR | Martingale Dr. | 8 | Asbestos Cement | 582 | 39 | 1 out of 5 | $442 | 257,252 |
| Distribution Main | 7232 | P-2176 | WAR | Martingale Dr. | 8 | Asbestos Cement | 588 | 39 | 1 out of 5 | $442 | 260,117 |
| Distribution Main | 5492 | | WAR | Masthead Dr | 6 | Ductile Iron | 11 | 52 | 1 out of 5 | $442 | 4,899 |
| Distribution Main | 5022 | P-2362 | WAR | Masthead Dr. | 6 | Asbestos Cement | 506 | 52 | 1.85 out of 5 | $442 | 223,439 |
| Distribution Main | 5988 | P-2362 | WAR | Masthead Dr. | 6 | Asbestos Cement | 2 | 52 | 1.85 out of 5 | $442 | 1,034 |
| Distribution Main | 11281 | P-2362 | WAR | Masthead Dr. | 6 | Asbestos Cement | 37 | 52 | 1.85 out of 5 | $442 | 16,440 |
| Distribution Main | 5211 | P-2483 | WAR | Matteson Ave. | 8 | Cast Iron | 259 | 86 | 1.72 out of 5 | $442 | 114,421 |
| Distribution Main | 7049 | P-2924 | WAR | Matteson Ave. | 1.5 | Cast Iron | 157 | 86 | 3.14 out of 5 | $442 | 69,397 |
| Distribution Main | 7053 | P-2483 | WAR | Matteson Ave. | 8 | Cast Iron | 9 | 86 | 1.72 out of 5 | $442 | 3,954 |
| Distribution Main | 11290 | P-2483 | WAR | Matteson Ave. | 8 | Cast Iron | 4 | 86 | 1.72 out of 5 | $442 | 1,562 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4550 | P-2418 | WAR | Meadow St | 4 | Cast Iron | 484 | 91 | 3.14 out of 5 | $442 | 213,711 |
| Distribution Main | 4551 | P-2418 | WAR | Meadow St | 4 | Cast Iron | 15 | 91 | 3.14 out of 5 | $442 | 6,508 |
| Distribution Main | 5555 | P-2418 | WAR | Meadow St | 4 | Cast Iron | 17 | 91 | 3.14 out of 5 | $442 | 7,515 |
| Distribution Main | 4868 | P-2143 | WAR | Meeting House Dr. | 8 | Ductile Iron | 44 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5747 | P-2143 | WAR | Meeting House Dr. | 8 | Asbestos Cement | 275 | 63 | 1.29 out of 5 | $442 | 121,752 |
| Distribution Main | 7320 | P-2125 | WAR | Michelle Cir. | 8 | PVC | 286 | 31 | 0.43 out of 5 | $442 | 126,376 |
| Distribution Main | 5450 | P-2495 | WAR | Montgomery St. | 6 | Asbestos Cement | 864 | 67 | 2 out of 5 | $442 | 381,902 |
| Distribution Main | 5451 | P-2495 | WAR | Montgomery St. | 6 | Asbestos Cement | 6 | 67 | 2 out of 5 | $442 | 2,713 |
| Distribution Main | 7017 | P-2507 | WAR | Montgomery St. | 6 | Asbestos Cement | 254 | 67 | 2 out of 5 | $442 | 112,440 |
| Distribution Main | 9495 | P-2917 | WAR | Music Ln | 6 | Ductile Iron | 19 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9144 | P-2956 | WAR | N Marlborough St | 8 | Ductile Iron | 163 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9145 | P-2956 | WAR | N Marlborough St | 8 | Ductile Iron | 246 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9150 | P-2410 | WAR | N Marlborough St | 8 | Ductile Iron | 399 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9155 | P-2410 | WAR | N Marlborough St | 8 | Ductile Iron | 44 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10851 | P-4896 | WAR | N Marlborough St | 8 | Ductile Iron | 9 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4479 | P-2065 | WAR | Nanci Karen Dr. | 8 | Asbestos Cement | 346 | 42 | 1.14 out of 5 | $442 | 152,731 |
| Distribution Main | 4480 | P-2065 | WAR | Nanci Karen Dr. | 8 | Asbestos Cement | 146 | 42 | 1.14 out of 5 | $442 | 64,678 |
| Distribution Main | 5259 | P-2064 | WAR | Nanci Karen Dr. | 8 | Asbestos Cement | 353 | 42 | 1.14 out of 5 | $442 | 156,189 |
| Distribution Main | 5262 | P-2067 | WAR | Nanci Karen Dr. | 8 | Asbestos Cement | 234 | 42 | 1.14 out of 5 | $442 | 103,465 |
| Distribution Main | 5263 | P-2067 | WAR | Nanci Karen Dr. | 8 | Asbestos Cement | 2 | 42 | 1.14 out of 5 | $442 | 1,002 |
| Distribution Main | 7364 | P-2066 | WAR | Nanci Karen Dr. | 8 | Asbestos Cement | 56 | 42 | 1.14 out of 5 | $442 | 24,811 |
| Distribution Main | 7365 | P-2066 | WAR | Nanci Karen Dr. | 8 | Asbestos Cement | 456 | 42 | 1.14 out of 5 | $442 | 201,730 |
| Distribution Main | 11373 | P-2066 | WAR | Nanci Karen Dr. | 8 | Asbestos Cement | 41 | 42 | 1.14 out of 5 | $442 | 18,193 |
| Distribution Main | 5768 | P-2168 | WAR | Nancy Allen Dr. | 8 | Asbestos Cement | 242 | 58 | 1.14 out of 5 | $442 | 106,998 |
| Distribution Main | 9598 | P-2168 | WAR | Nancy Allen Dr. | 8 | Ductile Iron | 56 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6102 | P-2321 | WAR | Natalie Ln. | 8 | Ductile Iron | 168 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6932 | P-2242 | WAR | Nathaniel Green Dr. | 6 | Asbestos Cement | 695 | 55 | 1.85 out of 5 | $442 | 307,349 |
| Distribution Main | 10534 | P-2451 | WAR | Neptune St | 8 | Ductile Iron | 120 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10535 | P-2451 | WAR | Neptune St | 8 | Ductile Iron | 83 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5393 | P-2430 | WAR | New England Way | 8 | Asbestos Cement | 88 | 52 | 1.14 out of 5 | $442 | 38,984 |
| Distribution Main | 5394 | P-2430 | WAR | New England Way | 8 | Asbestos Cement | 248 | 52 | 1.14 out of 5 | $442 | 109,658 |
| Distribution Main | 5489 | P-2429 | WAR | New England Way | 8 | Asbestos Cement | 432 | 52 | 1.14 out of 5 | $442 | 191,155 |
| Distribution Main | 6096 | P-2320 | WAR | Nicolas Ln. | 8 | Ductile Iron | 53 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6097 | P-2320 | WAR | Nicolas Ln. | 8 | Ductile Iron | 231 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6098 | P-2318 | WAR | Nicolas Ln. | 8 | Ductile Iron | 4 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6099 | P-2318 | WAR | Nicolas Ln. | 8 | Ductile Iron | 228 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6105 | P-2317 | WAR | Nicolas Ln. | 8 | Ductile Iron | 389 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4233 | P-2154 | WAR | North Winnisquam Dr. | 8 | PVC | 163 | 31 | 0.43 out of 5 | $442 | 71,855 |
| Distribution Main | 5473 |  | WAR | North Winnisquam Dr. | 8 | PVC | 47 | 31 | 0.43 out of 5 | $442 | 20,767 |
| Distribution Main | 6985 | P-2513 | WAR | Northbridge Ave. | 8 | Asbestos Cement | 588 | 57 | 1.14 out of 5 | $442 | 260,018 |
| Distribution Main | 6986 | P-2514 | WAR | Northbridge Ave. | 8 | Asbestos Cement | 55 | 57 | 1.14 out of 5 | $442 | 24,521 |
| Distribution Main | 6987 | P-2514 | WAR | Northbridge Ave. | 8 | Asbestos Cement | 817 | 57 | 1.14 out of 5 | $442 | 361,155 |
| Distribution Main | 10546 | P-2437 | WAR | Oak Grove Av | 8 | Ductile Iron | 299 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10547 | P-2437 | WAR | Oak Grove Av | 8 | Ductile Iron | 44 | 2 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10710 | | WAR | Oak Grove Av | 6 | Ductile Iron | 9 | 2 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11354 | P-2437 | WAR | Oak Grove Av | 8 | Ductile Iron | 9 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6863 | P-2439 | WAR | Oak Grove St. | 8 | Ductile Iron | 230 | 35 | 0.14 out of 5 | $442 | 101,556 |
| Distribution Main | 11353 | P-2439 | WAR | Oak Grove St. | 8 | Ductile Iron | 174 | 35 | 0.14 out of 5 | $442 | 76,861 |
| Distribution Main | 4541 | P-2627 | WAR | Oak St. | 4 | Cast Iron | 195 | 109 | 3.29 out of 5 | $442 | 86,190 |
| Distribution Main | 4542 | P-2627 | WAR | Oak St. | 4 | Cast Iron | 10 | 109 | 3.29 out of 5 | $442 | 4,499 |
| Distribution Main | 5562 | P-2627 | WAR | Oak St. | 4 | Cast Iron | 14 | 109 | 3.29 out of 5 | $442 | 6,226 |
| Distribution Main | 5573 | P-2629 | WAR | Oak St. | 8 | Ductile Iron | 178 | 29 | 0.14 out of 5 | $442 | 78,807 |
| Distribution Main | 5574 | P-2629 | WAR | Oak St. | 8 | Ductile Iron | 43 | 29 | 0.14 out of 5 | $442 | 18,898 |
| Distribution Main | 7039 | P-2629 | WAR | Oak St. | 8 | Ductile Iron | 15 | 29 | 0.14 out of 5 | $442 | 6,477 |
| Distribution Main | 11256 | P-2627 | WAR | Oak St. | 4 | Cast Iron | 9 | 109 | 3.29 out of 5 | $442 | 3,818 |
| Distribution Main | 6600 | P-2731 | WAR | Oberlin Dr. | 8 | Ductile Iron | 265 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6602 | P-2732 | WAR | Oberlin Dr. | 8 | Ductile Iron | 539 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7187 | P-2089 | WAR | Oberlin Dr. | 8 | Ductile Iron | 453 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7054 | P-2920 | WAR | Octave Street | 8 | Ductile Iron | 59 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9864 | P-2564 | WAR | Odonnell Ave | 8 | Ductile Iron | 356 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9865 | P-2564 | WAR | Odonnell Ave | 8 | Ductile Iron | 19 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9870 | P-2867 | WAR | Odonnell Ave | 8 | Ductile Iron | 117 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10415 | P-2563 | WAR | Odonnell Ave | 8 | Ductile Iron | 41 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12117 | P-2866 | WAR | Odonnell Ave | 8 | Ductile Iron | 64 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9287 | P-2869 | WAR | Old East Ave | 8 | Ductile Iron | 23 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9288 | P-2869 | WAR | Old East Ave | 8 | Ductile Iron | 7 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7001 | P-2536 | WAR | Old East Ave. | 6 | Asbestos Cement | 11 | 62 | 2 out of 5 | $442 | 5,006 |
| Distribution Main | 7005 | P-2532 | WAR | Old East Ave. | 8 | Asbestos Cement | 227 | 62 | 1.29 out of 5 | $442 | 100,305 |
| Distribution Main | 7074 | P-2534 | WAR | Old East Ave. | 8 | Asbestos Cement | 223 | 62 | 1.29 out of 5 | $442 | 98,476 |
| Distribution Main | 7075 | P-2534 | WAR | Old East Ave. | 8 | Asbestos Cement | 23 | 62 | 1.29 out of 5 | $442 | 10,228 |
| Distribution Main | 4876 | P-2203 | WAR | Old Lyme Dr. | 8 | Asbestos Cement | 428 | 59 | 1.14 out of 5 | $442 | 188,962 |
| Distribution Main | 4227 | P-2198 | WAR | Old Oak Dr. | 8 | Asbestos Cement | 537 | 52 | 1.14 out of 5 | $442 | 237,369 |
| Distribution Main | 8996 | | WAR | Old Quaker Ln | 10 | Asbestos Cement | 139 | UNK | 0.85 out of 5 | $442 | 61,238 |
| Distribution Main | 8999 | P-4707 | WAR | Old Quaker Ln | 8 | Ductile Iron | 301 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9000 | | WAR | Old Quaker Ln | 4 | Ductile Iron | 29 | 16 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 9002 | P-4707 | WAR | Old Quaker Ln | 8 | Ductile Iron | 212 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11536 | | WAR | Old Quaker Ln | 10 | Asbestos Cement | 25 | UNK | 0.85 out of 5 | $442 | 11,112 |
| Distribution Main | 11538 | P-4707 | WAR | Old Quaker Ln | 8 | Ductile Iron | 16 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5226 | P-2499 | WAR | Ontario Ave. | 6 | Asbestos Cement | 231 | 64 | 2 out of 5 | $442 | 102,141 |
| Distribution Main | 3599 | P-2720 | WAR | Orchard Ave. | 8 | Ductile Iron | 958 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3600 | P-2720 | WAR | Orchard Ave. | 8 | Ductile Iron | 26 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10703 | | WAR | Orchard Ave. | 8 | Ductile Iron | 442 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 364 | P-2042 | WAR | Orient St. | 8 | Ductile Iron | 358 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 368 | P-2042 | WAR | Orient St. | 8 | Ductile Iron | 229 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7027 | P-2726 | WAR | Osborne St. | 8 | Asbestos Cement | 44 | 55 | 1.14 out of 5 | $442 | 19,358 |
| Distribution Main | 7063 | P-2726 | WAR | Osborne St. | 6 | Asbestos Cement | 158 | 55 | 1.85 out of 5 | $442 | 69,918 |
| Distribution Main | 5497 | P-2584 | WAR | Overhill Rd. | 6 | Cast Iron | 845 | 133 | 2.57 out of 5 | $442 | 373,471 |
| Distribution Main | 5498 | P-2584 | WAR | Overhill Rd. | 6 | Cast Iron | 33 | 133 | 2.57 out of 5 | $442 | 14,662 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6835 | P-2584 | WAR | Overhill Rd. | 6 | Cast Iron | 10 | 133 | 2.57 out of 5 | $442 | 4,310 |
| Distribution Main | 6929 | P-2584 | WAR | Overhill Rd. | 6 | Cast Iron | 2 | 133 | 2.57 out of 5 | $442 | 799 |
| Distribution Main | 11948 | P-2584 | WAR | Overhill Rd. | 6 | Cast Iron | 433 | 133 | 2.57 out of 5 | $442 | 191,546 |
| Distribution Main | 7230 | P-2171 | WAR | Paddock Dr. | 8 | Asbestos Cement | 52 | 39 | 1 out of 5 | $442 | 23,099 |
| Distribution Main | 7231 | P-2171 | WAR | Paddock Dr. | 8 | Asbestos Cement | 873 | 39 | 1 out of 5 | $442 | 385,986 |
| Distribution Main | 11953 | P-2171 | WAR | Paddock Dr. | 8 | Asbestos Cement | 55 | 39 | 1 out of 5 | $442 | 24,508 |
| Distribution Main | 10775 | P-2679 | WAR | Panto St | 8 | Ductile Iron | 175 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10776 | P-2637 | WAR | Panto St | 8 | Ductile Iron | 352 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10777 | P-2637 | WAR | Panto St | 8 | Ductile Iron | 290 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10923 | P-2636 | WAR | Panto St | 8 | Ductile Iron | 289 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7318 | P-2123 | WAR | Pasco Cir. | 8 | PVC | 626 | 31 | 0.43 out of 5 | $442 | 276,843 |
| Distribution Main | 9046 | P-2933 | WAR | Patrick Way | 8 | Ductile Iron | 293 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9047 | P-2933 | WAR | Patrick Way | 8 | Ductile Iron | 173 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7109 | P-2334 | WAR | Patterson Ave. | 6 | Asbestos Cement | 5 | 73 | 2 out of 5 | $442 | 2,363 |
| Distribution Main | 7115 | P-2341 | WAR | Patterson Ave. | 6 | Asbestos Cement | 344 | 73 | 2 out of 5 | $442 | 152,091 |
| Distribution Main | 7328 | P-2340 | WAR | Patterson Ave. | 6 | Asbestos Cement | 347 | 73 | 2 out of 5 | $442 | 153,209 |
| Distribution Main | 7332 | P-2334 | WAR | Patterson Ave. | 6 | Asbestos Cement | 72 | 73 | 2 out of 5 | $442 | 31,663 |
| Distribution Main | 7333 | P-2334 | WAR | Patterson Ave. | 6 | Asbestos Cement | 451 | 73 | 2 out of 5 | $442 | 199,144 |
| Distribution Main | 7345 | P-2341 | WAR | Patterson Ave. | 6 | Asbestos Cement | 16 | 73 | 2 out of 5 | $442 | 6,874 |
| Distribution Main | 5581 | P-2607 | WAR | Paul Ave. | 6 | Asbestos Cement | 233 | 73 | 2 out of 5 | $442 | 103,007 |
| Distribution Main | 6421 | P-2608 | WAR | Paul Ave. | 6 | Asbestos Cement | 75 | 73 | 2 out of 5 | $442 | 33,099 |
| Distribution Main | 6422 | P-2608 | WAR | Paul Ave. | 6 | Asbestos Cement | 56 | 73 | 2 out of 5 | $442 | 24,727 |
| Distribution Main | 9921 | P-2608 | WAR | Paul Ave. | 6 | Ductile Iron | 121 | 29 | 0.85 out of 5 | $442 | 53,596 |
| Distribution Main | 6681 | P-2179 | WAR | Peaceful Ln. | 8 | Ductile Iron | 291 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6682 | P-2179 | WAR | Peaceful Ln. | 8 | Ductile Iron | 76 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4228 | P-2714 | WAR | Peacock Rd. | 8 | Ductile Iron | 23 | 27 | 0.14 out of 5 | $442 | 10,229 |
| Distribution Main | 4229 | P-2714 | WAR | Peacock Rd. | 8 | Ductile Iron | 446 | 27 | 0.14 out of 5 | $442 | 197,250 |
| Distribution Main | 4230 | P-2934 | WAR | Peacock Rd. | 8 | Asbestos Cement | 198 | 47 | 1.14 out of 5 | $442 | 87,700 |
| Distribution Main | 9489 | P-2713 | WAR | Peacock Rd. | 8 | Ductile Iron | 184 | 27 | 0.14 out of 5 | $442 | 81,230 |
| Distribution Main | 5968 | P-2102 | WAR | Pender John Ct. | 8 | Ductile Iron | 170 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5979 | P-2102 | WAR | Pender John Ct. | 8 | Ductile Iron | 333 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6964 | P-2010 | WAR | Pitman Rd. | 6 | Asbestos Cement | 951 | 59 | 1.85 out of 5 | $442 | 420,185 |
| Distribution Main | 6965 | P-2010 | WAR | Pitman Rd. | 6 | Asbestos Cement | 45 | 59 | 1.85 out of 5 | $442 | 19,939 |
| Distribution Main | 5453 | P-2503 | WAR | Plantation St. | 6 | Asbestos Cement | 2 | 60 | 1.85 out of 5 | $442 | 904 |
| Distribution Main | 5454 | P-2503 | WAR | Plantation St. | 6 | Asbestos Cement | 590 | 60 | 1.85 out of 5 | $442 | 260,591 |
| Distribution Main | 6983 | P-2503 | WAR | Plantation St. | 6 | Asbestos Cement | 290 | 60 | 1.85 out of 5 | $442 | 127,979 |
| Distribution Main | 5559 | P-2620 | WAR | Pleasant St. | 4 | Cast Iron | 354 | 109 | 3.29 out of 5 | $442 | 156,300 |
| Distribution Main | 5560 | P-2911 | WAR | Pleasant St. | 2 | Copper | 203 | 29 | 2.14 out of 5 | $442 | 89,716 |
| Distribution Main | 5561 | P-2630 | WAR | Pleasant St. | 8 | Ductile Iron | 420 | 29 | 0.14 out of 5 | $442 | 185,473 |
| Distribution Main | 10539 | P-2444 | WAR | Plymouth St | 8 | Ductile Iron | 336 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10540 | P-2444 | WAR | Plymouth St | 8 | Ductile Iron | 136 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11671 | P-2444 | WAR | Plymouth St | 8 | Ductile Iron | 27 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7070 | P-2492 | WAR | Pond View Dr. | 6 | Asbestos Cement | 302 | 47 | 1.85 out of 5 | $442 | 133,700 |
| Distribution Main | 7071 | P-2492 | WAR | Pond View Dr. | 6 | Asbestos Cement | 163 | 47 | 1.85 out of 5 | $442 | 72,091 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10742 | P-2554 | WAR | Pontiac St | 8 | Ductile Iron | 528 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10743 | P-2557 | WAR | Pontiac St | 8 | Ductile Iron | 263 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11716 | P-2554 | WAR | Pontiac St | 8 | Ductile Iron | 35 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11718 | P-2555 | WAR | Pontiac St | 8 | Ductile Iron | 306 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7245 | P-2454 | WAR | Poppy Pl. | 8 | Ductile Iron | 211 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7246 | P-2454 | WAR | Poppy Pl. | 8 | Ductile Iron | 11 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9203 | P-2376 | WAR | Post Rd | 16 | Ductile Iron | 3 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9315 | | WAR | Post Rd | 6 | Ductile Iron | 2 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9316 | | WAR | Post Rd | 6 | Ductile Iron | 36 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9333 | | WAR | Post Rd | 4 | Ductile Iron | 25 | 9 | 1.42 out of 5 | N/A | $0 |
| Transmission Main | 9884 | P-4269 | WAR | Post Rd | 12 | Unknown | 41 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 9886 | | WAR | Post Rd | 12 | Unknown | 2 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 10754 | P-2614 | WAR | Post Rd | 8 | Ductile Iron | 410 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10755 | P-2614 | WAR | Post Rd | 8 | Ductile Iron | 360 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10758 | | WAR | Post Rd | 8 | Ductile Iron | 257 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10759 | P-2912 | WAR | Post Rd | 8 | Ductile Iron | 630 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10760 | P-2912 | WAR | Post Rd | 8 | Ductile Iron | 186 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10943 | P-2619 | WAR | Post Rd | 8 | Ductile Iron | 235 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10944 | P-2619 | WAR | Post Rd | 8 | Ductile Iron | 61 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10945 | P-2618 | WAR | Post Rd | 8 | Ductile Iron | 163 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10946 | P-2617 | WAR | Post Rd | 8 | Ductile Iron | 223 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11196 | P-4269 | WAR | Post Rd | 12 | Unknown | 11 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 12191 | P-2618 | WAR | Post Rd | 8 | Ductile Iron | 86 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12199 | P-2614 | WAR | Post Rd | 8 | Ductile Iron | 206 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12217 | P-2912 | WAR | Post Rd | 8 | Ductile Iron | 64 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12225 | | WAR | Post Rd | 8 | Ductile Iron | 113 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12226 | P-2619 | WAR | Post Rd | 8 | Ductile Iron | 32 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12228 | P-2619 | WAR | Post Rd | 8 | Ductile Iron | 83 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2237 | P-2353 | WAR | Post Rd. | 16 | Ductile Iron | 17 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2250 | P-2376 | WAR | Post Rd. | 16 | Ductile Iron | 369 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2251 | P-2958 | WAR | Post Rd. | 16 | Ductile Iron | 26 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2252 | P-2958 | WAR | Post Rd. | 16 | Ductile Iron | 10 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4518 | P-2347 | WAR | Post Rd. | 16 | Ductile Iron | 15 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4540 | P-4563 | WAR | Post Rd. | 16 | Ductile Iron | 12 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4553 | P-2704 | WAR | Post Rd. | 12 | Cast Iron | 200 | 91 | 1.72 out of 5 | $442 | 88,180 |
| Transmission Main | 4581 | P-2705 | WAR | Post Rd. | 12 | Cast Iron | 133 | 91 | 1.72 out of 5 | $442 | 58,707 |
| Distribution Main | 4582 | P-2706 | WAR | Post Rd. | 8 | Cast Iron | 21 | 91 | 1.72 out of 5 | $442 | 9,287 |
| Distribution Main | 4583 | P-2703 | WAR | Post Rd. | 8 | Cast Iron | 23 | 129 | 1.86 out of 5 | $442 | 10,213 |
| Transmission Main | 5016 | P-2364 | WAR | Post Rd. | 16 | Ductile Iron | 526 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5017 | P-2364 | WAR | Post Rd. | 16 | Ductile Iron | 27 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5020 | P-2364 | WAR | Post Rd. | 16 | Ductile Iron | 450 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5021 | P-2364 | WAR | Post Rd. | 16 | Ductile Iron | 84 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5038 | P-4891 | WAR | Post Rd. | 16 | Ductile Iron | 43 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5210 | P-2422 | WAR | Post Rd. | 16 | Ductile Iron | 16 | 20 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 5212 | P-2482 | WAR | Post Rd. | 16 | Ductile Iron | 18 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5216 | P-2482 | WAR | Post Rd. | 16 | Ductile Iron | 148 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5455 | P-2365 | WAR | Post Rd. | 16 | Ductile Iron | 29 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5571 | P-2610 | WAR | Post Rd. | 8 | Cast Iron | 119 | 120 | 1.86 out of 5 | $442 | 52,704 |
| Distribution Main | 5572 | P-2626 | WAR | Post Rd. | 2 | Copper | 246 | 73 | 2.43 out of 5 | $442 | 108,577 |
| Transmission Main | 5642 | P-2478 | WAR | Post Rd. | 16 | Ductile Iron | 15 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5700 | P-2480 | WAR | Post Rd. | 16 | Ductile Iron | 76 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6072 | P-2458 | WAR | Post Rd. | 16 | Ductile Iron | 222 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6073 | P-2458 | WAR | Post Rd. | 16 | Ductile Iron | 457 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6284 | P-2373 | WAR | Post Rd. | 16 | Ductile Iron | 17 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6285 | P-2375 | WAR | Post Rd. | 16 | Ductile Iron | 595 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6412 | | WAR | Post Rd. | 12 | Unknown | 16 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 6413 | P-2928 | WAR | Post Rd. | 16 | Ductile Iron | 55 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6416 | P-2458 | WAR | Post Rd. | 16 | Ductile Iron | 6 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6428 | P-2458 | WAR | Post Rd. | 16 | Ductile Iron | 24 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6431 | P-2783 | WAR | Post Rd. | 16 | Ductile Iron | 12 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6432 | P-2474 | WAR | Post Rd. | 16 | Ductile Iron | 17 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6433 | P-2925 | WAR | Post Rd. | 16 | Ductile Iron | 57 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6434 | P-2478 | WAR | Post Rd. | 16 | Ductile Iron | 179 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6435 | P-2478 | WAR | Post Rd. | 16 | Ductile Iron | 67 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6436 | P-2480 | WAR | Post Rd. | 16 | Ductile Iron | 21 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6437 | P-2460 | WAR | Post Rd. | 16 | Ductile Iron | 142 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6438 | P-2460 | WAR | Post Rd. | 16 | Ductile Iron | 108 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6504 | P-2368 | WAR | Post Rd. | 16 | Ductile Iron | 31 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6505 | P-2368 | WAR | Post Rd. | 16 | Ductile Iron | 196 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6506 | P-2449 | WAR | Post Rd. | 16 | Ductile Iron | 174 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6507 | P-2369 | WAR | Post Rd. | 16 | Ductile Iron | 129 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6509 | P-2366 | WAR | Post Rd. | 16 | Ductile Iron | 13 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6513 | P-2365 | WAR | Post Rd. | 16 | Ductile Iron | 487 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6514 | P-2365 | WAR | Post Rd. | 16 | Ductile Iron | 13 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6518 | P-2928 | WAR | Post Rd. | 16 | Ductile Iron | 26 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6520 | | WAR | Post Rd. | 12 | Unknown | 5 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 6670 | P-2364 | WAR | Post Rd. | 16 | Ductile Iron | 26 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6772 | P-2375 | WAR | Post Rd. | 16 | Ductile Iron | 12 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6817 | | WAR | Post Rd. | 6 | Unknown | 29 | UNK | 0.71 out of 5 | $442 | 12,934 |
| Distribution Main | 6818 | | WAR | Post Rd. | 6 | Unknown | 4 | UNK | 0.71 out of 5 | $442 | 1,624 |
| Transmission Main | 6819 | P-2372 | WAR | Post Rd. | 16 | Ductile Iron | 41 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6820 | P-2372 | WAR | Post Rd. | 16 | Ductile Iron | 20 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6821 | P-2370 | WAR | Post Rd. | 16 | Ductile Iron | 256 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6822 | P-2370 | WAR | Post Rd. | 16 | Ductile Iron | 382 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6829 | P-2371 | WAR | Post Rd. | 16 | Ductile Iron | 7 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6830 | P-2371 | WAR | Post Rd. | 16 | Ductile Iron | 575 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6836 | P-2370 | WAR | Post Rd. | 16 | Ductile Iron | 35 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6841 | P-2570 | WAR | Post Rd. | 16 | Ductile Iron | 34 | 20 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 6842 | P-2372 | WAR | Post Rd. | 16 | Ductile Iron | 5 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6843 | P-2372 | WAR | Post Rd. | 16 | Ductile Iron | 207 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6844 | P-2373 | WAR | Post Rd. | 16 | Ductile Iron | 204 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6857 | P-2692 | WAR | Post Rd. | 16 | Ductile Iron | 35 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6858 | P-2368 | WAR | Post Rd. | 16 | Ductile Iron | 6 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6861 | P-2366 | WAR | Post Rd. | 16 | Ductile Iron | 291 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6862 | P-2366 | WAR | Post Rd. | 16 | Ductile Iron | 207 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6864 | P-2692 | WAR | Post Rd. | 16 | Ductile Iron | 567 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6870 | P-2365 | WAR | Post Rd. | 16 | Ductile Iron | 34 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6878 | P-2371 | WAR | Post Rd. | 16 | Ductile Iron | 156 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6882 | P-2371 | WAR | Post Rd. | 16 | Ductile Iron | 32 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6902 | P-2373 | WAR | Post Rd. | 16 | Ductile Iron | 4 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6910 | P-2371 | WAR | Post Rd. | 16 | Ductile Iron | 12 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6979 | P-2699 | WAR | Post Rd. | 12 | Cast Iron | 25 | 91 | 1.72 out of 5 | $442 | 11,118 |
| Distribution Main | 6980 | P-2610 | WAR | Post Rd. | 8 | Cast Iron | 79 | 120 | 1.86 out of 5 | $442 | 35,077 |
| Distribution Main | 7032 | P-2610 | WAR | Post Rd. | 8 | Cast Iron | 36 | 120 | 1.86 out of 5 | $442 | 15,891 |
| Transmission Main | 7035 | P-2422 | WAR | Post Rd. | 16 | Ductile Iron | 315 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7036 | P-2422 | WAR | Post Rd. | 16 | Ductile Iron | 476 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7037 | P-2422 | WAR | Post Rd. | 16 | Ductile Iron | 690 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7038 | P-2422 | WAR | Post Rd. | 16 | Ductile Iron | 197 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7051 | P-2482 | WAR | Post Rd. | 16 | Ductile Iron | 137 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7090 | P-2783 | WAR | Post Rd. | 16 | Ductile Iron | 272 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7091 | P-2783 | WAR | Post Rd. | 16 | Ductile Iron | 149 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7096 | P-2458 | WAR | Post Rd. | 16 | Ductile Iron | 131 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7101 | P-2347 | WAR | Post Rd. | 16 | Ductile Iron | 331 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7102 | P-2347 | WAR | Post Rd. | 16 | Ductile Iron | 201 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7103 | P-2353 | WAR | Post Rd. | 16 | Ductile Iron | 86 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7104 | P-2353 | WAR | Post Rd. | 16 | Ductile Iron | 386 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7105 | P-2352 | WAR | Post Rd. | 16 | Ductile Iron | 135 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7183 | P-2364 | WAR | Post Rd. | 16 | Ductile Iron | 189 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7249 | P-2474 | WAR | Post Rd. | 16 | Ductile Iron | 224 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7250 | P-2472 | WAR | Post Rd. | 16 | Ductile Iron | 21 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7290 | P-2353 | WAR | Post Rd. | 16 | Ductile Iron | 10 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7317 | P-2458 | WAR | Post Rd. | 16 | Ductile Iron | 21 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7329 | P-2353 | WAR | Post Rd. | 16 | Ductile Iron | 9 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7331 | P-2352 | WAR | Post Rd. | 16 | Ductile Iron | 20 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10484 | P-2702 | WAR | Post Rd. | 8 | Cast Iron | 42 | 129 | 1.86 out of 5 | $442 | 18,429 |
| Distribution Main | 10485 | P-2701 | WAR | Post Rd. | 8 | Cast Iron | 253 | 129 | 1.86 out of 5 | $442 | 111,691 |
| Transmission Main | 10748 | P-2704 | WAR | Post Rd. | 12 | Cast Iron | 124 | 91 | 1.72 out of 5 | $442 | 54,608 |
| Distribution Main | 10749 | | WAR | Post Rd. | 8 | Cast Iron | 4 | 129 | 1.86 out of 5 | $442 | 1,909 |
| Transmission Main | 10914 | P-2373 | WAR | Post Rd. | 16 | Ductile Iron | 7 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10955 | P-2375 | WAR | Post Rd. | 16 | Ductile Iron | 6 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11313 | P-2480 | WAR | Post Rd. | 16 | Ductile Iron | 8 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11355 | P-2371 | WAR | Post Rd. | 16 | Ductile Iron | 105 | 20 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 11357 | P-2783 | WAR | Post Rd. | 16 | Ductile Iron | 25 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11359 | P-2347 | WAR | Post Rd. | 16 | Ductile Iron | 60 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11664 | P-2702 | WAR | Post Rd. | 8 | Cast Iron | 46 | 129 | 1.86 out of 5 | $442 | 20,508 |
| Distribution Main | 11933 | P-2701 | WAR | Post Rd. | 8 | Cast Iron | 56 | 129 | 1.86 out of 5 | $442 | 24,625 |
| Transmission Main | 11949 | P-2365 | WAR | Post Rd. | 16 | Ductile Iron | 386 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11968 | P-2353 | WAR | Post Rd. | 16 | Ductile Iron | 55 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11969 | P-2422 | WAR | Post Rd. | 16 | Ductile Iron | 32 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12212 | P-2364 | WAR | Post Rd. | 16 | Ductile Iron | 3 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12236 | | WAR | Post Rd. | 12 | Cast Iron | 274 | 91 | 1.72 out of 5 | $442 | 121,080 |
| Distribution Main | 5558 | P-2691 | WAR | Prospect St. | 8 | Ductile Iron | 360 | 29 | 0.14 out of 5 | $442 | 159,270 |
| Distribution Main | 5563 | P-2628 | WAR | Prospect St. | 8 | Ductile Iron | 329 | 29 | 0.14 out of 5 | $442 | 145,265 |
| Distribution Main | 5564 | P-2628 | WAR | Prospect St. | 8 | Ductile Iron | 31 | 29 | 0.14 out of 5 | $442 | 13,839 |
| Distribution Main | 9344 | | WAR | Providence St | 6 | Ductile Iron | 24 | 8 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9345 | | WAR | Providence St | 6 | Ductile Iron | 36 | 8 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9866 | P-1762 | WAR | Providence St | 8 | Ductile Iron | 13 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5026 | P-2072 | WAR | Quaid Ln. | 8 | Asbestos Cement | 280 | 54 | 1.14 out of 5 | $442 | 123,659 |
| Distribution Main | 5027 | P-2072 | WAR | Quaid Ln. | 8 | Asbestos Cement | 38 | 54 | 1.14 out of 5 | $442 | 16,799 |
| Distribution Main | 7239 | P-2070 | WAR | Quaid Ln. | 8 | Asbestos Cement | 385 | 54 | 1.14 out of 5 | $442 | 170,045 |
| Distribution Main | 7240 | P-2070 | WAR | Quaid Ln. | 8 | Asbestos Cement | 47 | 54 | 1.14 out of 5 | $442 | 20,820 |
| Distribution Main | 3538 | | WAR | Quail Ridge Lane | 8 | Ductile Iron | 3 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 8521 | P-2894 | WAR | Quaker Lane | 6 | Ductile Iron | 44 | 20 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 463 | P-4711 | WAR | Quaker Ln. | 12 | Asbestos Cement | 12 | 50 | 1.14 out of 5 | $442 | 5,255 |
| Transmission Main | 978 | P-2196 | WAR | Quaker Ln. | 20 | Asbestos Cement | 73 | 50 | 1.14 out of 5 | $442 | 32,050 |
| Transmission Main | 979 | P-2196 | WAR | Quaker Ln. | 20 | Asbestos Cement | 819 | 50 | 1.14 out of 5 | $442 | 361,919 |
| Transmission Main | 1873 | P-2698 | WAR | Quaker Ln. | 20 | Asbestos Cement | 14 | 50 | 1.14 out of 5 | $442 | 6,054 |
| Transmission Main | 1874 | P-2698 | WAR | Quaker Ln. | 20 | Asbestos Cement | 917 | 50 | 1.14 out of 5 | $442 | 405,338 |
| Transmission Main | 3417 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 87 | 39 | 1 out of 5 | $442 | 38,569 |
| Transmission Main | 3418 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 526 | 39 | 1 out of 5 | $442 | 232,531 |
| Transmission Main | 3419 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 671 | 39 | 1 out of 5 | $442 | 296,738 |
| Transmission Main | 3420 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 244 | 39 | 1 out of 5 | $442 | 107,875 |
| Transmission Main | 3421 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 79 | 39 | 1 out of 5 | $442 | 35,100 |
| Transmission Main | 3422 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 257 | 39 | 1 out of 5 | $442 | 113,537 |
| Transmission Main | 3423 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 95 | 39 | 1 out of 5 | $442 | 41,893 |
| Transmission Main | 3424 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 67 | 39 | 1 out of 5 | $442 | 29,772 |
| Transmission Main | 3425 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 214 | 39 | 1 out of 5 | $442 | 94,659 |
| Transmission Main | 3426 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 80 | 39 | 1 out of 5 | $442 | 35,519 |
| Transmission Main | 3427 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 276 | 39 | 1 out of 5 | $442 | 122,121 |
| Transmission Main | 3430 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 72 | 39 | 1 out of 5 | $442 | 32,028 |
| Transmission Main | 3431 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 46 | 39 | 1 out of 5 | $442 | 20,448 |
| Transmission Main | 3543 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 879 | 39 | 1.14 out of 5 | $442 | 388,374 |
| Transmission Main | 3544 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 347 | 39 | 1 out of 5 | $442 | 153,292 |
| Transmission Main | 3809 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 10 | 39 | 1.14 out of 5 | $442 | 4,241 |
| Transmission Main | 4216 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 675 | 39 | 1 out of 5 | $442 | 298,467 |
| Transmission Main | 4217 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 540 | 39 | 1 out of 5 | $442 | 238,707 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 4774 | P-2188 | WAR | Quaker Ln. | 16 | Asbestos Cement | 13 | 39 | 1 out of 5 | $442 | 5,559 |
| Transmission Main | 5075 | P-2230 | WAR | Quaker Ln. | 24 | Asbestos Cement | 130 | 39 | 1 out of 5 | $442 | 57,408 |
| Transmission Main | 5076 | P-2230 | WAR | Quaker Ln. | 24 | Asbestos Cement | 153 | 39 | 1 out of 5 | $442 | 67,636 |
| Transmission Main | 5091 | P-2698 | WAR | Quaker Ln. | 20 | Asbestos Cement | 24 | 50 | 1.14 out of 5 | $442 | 10,471 |
| Transmission Main | 5651 | P-4711 | WAR | Quaker Ln. | 20 | Asbestos Cement | 9 | 50 | 1.14 out of 5 | $442 | 3,842 |
| Transmission Main | 5652 | P-4711 | WAR | Quaker Ln. | 20 | Asbestos Cement | 896 | 50 | 1.14 out of 5 | $442 | 396,009 |
| Transmission Main | 6331 | P-4711 | WAR | Quaker Ln. | 12 | Asbestos Cement | 16 | 50 | 1.14 out of 5 | $442 | 7,149 |
| Transmission Main | 6516 | P-4710 | WAR | Quaker Ln. | 20 | Asbestos Cement | 17 | 50 | 1.14 out of 5 | $442 | 7,330 |
| Transmission Main | 6517 | P-4710 | WAR | Quaker Ln. | 20 | Asbestos Cement | 373 | 50 | 1.14 out of 5 | $442 | 165,070 |
| Transmission Main | 6811 | P-4710 | WAR | Quaker Ln. | 20 | Asbestos Cement | 880 | 50 | 1.14 out of 5 | $442 | 388,987 |
| Transmission Main | 11218 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 168 | 39 | 1 out of 5 | $442 | 74,035 |
| Transmission Main | 11248 | P-2188 | WAR | Quaker Ln. | 24 | Asbestos Cement | 38 | 39 | 1 out of 5 | $442 | 16,716 |
| Transmission Main | 11352 | P-4710 | WAR | Quaker Ln. | 20 | Asbestos Cement | 5 | 50 | 1.14 out of 5 | $442 | 2,223 |
| Transmission Main | 12211 | P-4710 | WAR | Quaker Ln. | 20 | Asbestos Cement | 143 | 50 | 1.14 out of 5 | $442 | 63,046 |
| Distribution Main | 7002 | P-2533 | WAR | Quinlan Ct. | 1 | Copper | 45 | 62 | 2.43 out of 5 | $442 | 19,971 |
| Distribution Main | 7003 | P-2533 | WAR | Quinlan Ct. | 1 | Copper | 166 | 62 | 2.43 out of 5 | $442 | 73,275 |
| Distribution Main | 10747 | P-2560 | WAR | Railroad Row | 8 | Ductile Iron | 683 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11719 | P-2560 | WAR | Railroad Row | 8 | Ductile Iron | 16 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2838 | P-2940 | WAR | Red Chimney Dr. | 1.5 | Copper | 164 | 63 | 2.43 out of 5 | $442 | 72,310 |
| Distribution Main | 3310 | P-2142 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 113 | 63 | 1.29 out of 5 | $442 | 49,929 |
| Distribution Main | 3621 | P-2159 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 307 | 63 | 1.29 out of 5 | $442 | 135,771 |
| Distribution Main | 3629 | P-2167 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 35 | 63 | 1.29 out of 5 | $442 | 15,521 |
| Distribution Main | 3634 | P-2170 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 142 | 63 | 1.29 out of 5 | $442 | 62,960 |
| Distribution Main | 3635 | P-2169 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 235 | 63 | 1.29 out of 5 | $442 | 104,088 |
| Distribution Main | 3636 | P-2160 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 505 | 63 | 1.29 out of 5 | $442 | 223,072 |
| Distribution Main | 3637 | P-2160 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 163 | 63 | 1.29 out of 5 | $442 | 71,848 |
| Distribution Main | 3638 | P-2939 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 331 | 63 | 1.29 out of 5 | $442 | 146,418 |
| Distribution Main | 4241 | P-2155 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 300 | 63 | 1.29 out of 5 | $442 | 132,787 |
| Distribution Main | 4869 | P-2140 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 55 | 63 | 1.29 out of 5 | $442 | 24,139 |
| Distribution Main | 4871 | P-2172 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 73 | 63 | 1.29 out of 5 | $442 | 32,110 |
| Distribution Main | 4872 | P-2172 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 117 | 63 | 1.29 out of 5 | $442 | 51,533 |
| Distribution Main | 5754 | P-2140 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 264 | 63 | 1.29 out of 5 | $442 | 116,744 |
| Distribution Main | 5755 | P-2140 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 428 | 63 | 1.29 out of 5 | $442 | 189,054 |
| Distribution Main | 5761 | P-2169 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 45 | 63 | 1.29 out of 5 | $442 | 19,825 |
| Distribution Main | 5763 | P-2173 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 417 | 63 | 1.29 out of 5 | $442 | 184,201 |
| Distribution Main | 5764 | P-2167 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 885 | 63 | 1.29 out of 5 | $442 | 391,000 |
| Distribution Main | 5765 | P-2167 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 313 | 63 | 1.29 out of 5 | $442 | 138,321 |
| Distribution Main | 5771 | P-2935 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 165 | 63 | 1.29 out of 5 | $442 | 72,723 |
| Distribution Main | 5772 | P-2935 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 139 | 63 | 1.29 out of 5 | $442 | 61,239 |
| Distribution Main | 9488 | P-2167 | WAR | Red Chimney Dr. | 8 | Asbestos Cement | 121 | 63 | 1.29 out of 5 | $442 | 53,683 |
| Distribution Main | 6444 | P-2473 | WAR | Reeland Ave. | 6 | Asbestos Cement | 4 | 54 | 1.85 out of 5 | $442 | 1,638 |
| Distribution Main | 7247 | P-2473 | WAR | Reeland Ave. | 6 | Asbestos Cement | 52 | 54 | 1.85 out of 5 | $442 | 23,029 |
| Distribution Main | 7248 | P-2473 | WAR | Reeland Ave. | 6 | Asbestos Cement | 448 | 54 | 1.85 out of 5 | $442 | 198,174 |
| Distribution Main | 6954 | P-2319 | WAR | Remy Cir | 8 | Ductile Iron | 37 | 24 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6955 | P-2319 | WAR | Remy Cir | 8 | Ductile Iron | 367 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6445 | P-2459 | WAR | Rice St. | 6 | Asbestos Cement | 26 | 27 | 1.71 out of 5 | $442 | 11,549 |
| Distribution Main | 6446 | P-2459 | WAR | Rice St. | 6 | Asbestos Cement | 295 | 27 | 1.71 out of 5 | $442 | 130,212 |
| Distribution Main | 7093 | P-2459 | WAR | Rice St. | 6 | Asbestos Cement | 8 | 27 | 1.71 out of 5 | $442 | 3,415 |
| Distribution Main | 10459 | P-2459 | WAR | Rice St. | 6 | Ductile Iron | 154 | 27 | 0.85 out of 5 | $442 | 68,047 |
| Distribution Main | 7242 | P-2463 | WAR | Rip Van Winkle Cir | 8 | Ductile Iron | 88 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6521 | P-2466 | WAR | Rip Van Winkle Cir. | 8 | Ductile Iron | 771 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6522 | P-2466 | WAR | Rip Van Winkle Cir. | 8 | Ductile Iron | 106 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4933 | | WAR | Riverdale Avenue | 6 | Unknown | 101 | UNK | 0.71 out of 5 | $442 | 44,653 |
| Distribution Main | 9477 | P-2926 | WAR | Robin Hill Rd. | 2 | Unknown | 203 | UNK | 1.42 out of 5 | $442 | 89,877 |
| Distribution Main | 5539 | P-2246 | WAR | Roelker Dr. | 8 | Asbestos Cement | 299 | 55 | 1.14 out of 5 | $442 | 131,945 |
| Distribution Main | 6880 | P-2246 | WAR | Roelker Dr. | 8 | Asbestos Cement | 7 | 55 | 1.14 out of 5 | $442 | 3,034 |
| Distribution Main | 6881 | P-2246 | WAR | Roelker Dr. | 8 | Asbestos Cement | 243 | 55 | 1.14 out of 5 | $442 | 107,376 |
| Distribution Main | 10739 | P-2553 | WAR | Rossi St | 8 | Ductile Iron | 332 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9274 | P-2887 | WAR | Rutherford Ave | 8 | Ductile Iron | 19 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9275 | P-2887 | WAR | Rutherford Ave | 8 | Ductile Iron | 2 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9290 | P-2887 | WAR | Rutherford Ave | 6 | Ductile Iron | 2 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 7018 | P-2493 | WAR | Rutherford Ave. | 6 | Asbestos Cement | 68 | 69 | 2 out of 5 | $442 | 29,903 |
| Distribution Main | 7019 | P-2493 | WAR | Rutherford Ave. | 6 | Asbestos Cement | 166 | 69 | 2 out of 5 | $442 | 73,493 |
| Distribution Main | 7020 | P-2696 | WAR | Rutherford Ave. | 6 | Asbestos Cement | 472 | 69 | 2 out of 5 | $442 | 208,496 |
| Distribution Main | 7081 | P-2493 | WAR | Rutherford Ave. | 6 | Asbestos Cement | 63 | 69 | 2 out of 5 | $442 | 27,878 |
| Distribution Main | 7083 | P-2494 | WAR | Rutherford Ave. | 6 | Asbestos Cement | 288 | 69 | 2 out of 5 | $442 | 127,391 |
| Distribution Main | 7069 | P-2697 | WAR | Rutherford Ct. | 6 | Asbestos Cement | 208 | 69 | 2 out of 5 | $442 | 91,999 |
| Distribution Main | 5258 | P-2728 | WAR | Sage Dr. | 6 | Asbestos Cement | 244 | 50 | 1.85 out of 5 | $442 | 107,716 |
| Distribution Main | 5260 | P-2052 | WAR | Sage Dr. | 6 | Asbestos Cement | 9 | 50 | 1.85 out of 5 | $442 | 4,052 |
| Distribution Main | 5261 | P-2052 | WAR | Sage Dr. | 6 | Asbestos Cement | 114 | 50 | 1.85 out of 5 | $442 | 50,186 |
| Distribution Main | 6310 | P-2727 | WAR | Sage Dr. | 6 | Asbestos Cement | 369 | 50 | 1.85 out of 5 | $442 | 163,169 |
| Distribution Main | 7236 | P-2052 | WAR | Sage Dr. | 6 | Asbestos Cement | 311 | 50 | 1.85 out of 5 | $442 | 137,386 |
| Distribution Main | 11330 | P-2727 | WAR | Sage Dr. | 6 | Asbestos Cement | 3 | 50 | 1.85 out of 5 | $442 | 1,343 |
| Distribution Main | 6810 | P-2581 | WAR | Sammartino Cir. | 8 | Asbestos Cement | 2 | 43 | 1.14 out of 5 | $442 | 987 |
| Distribution Main | 6921 | P-2582 | WAR | Sammartino Cir. | 8 | Asbestos Cement | 146 | 43 | 1.14 out of 5 | $442 | 64,583 |
| Distribution Main | 6927 | P-2581 | WAR | Sammartino Cir. | 8 | Asbestos Cement | 499 | 43 | 1.14 out of 5 | $442 | 220,668 |
| Distribution Main | 2832 | P-2736 | WAR | Sandro Cir. | 6 | Asbestos Cement | 162 | 65 | 2 out of 5 | $442 | 71,593 |
| Distribution Main | 3619 | P-2734 | WAR | Sandro Dr. | 6 | Asbestos Cement | 259 | 65 | 2 out of 5 | $442 | 114,641 |
| Distribution Main | 5756 | P-2735 | WAR | Sandro Dr. | 6 | Asbestos Cement | 11 | 65 | 2 out of 5 | $442 | 4,993 |
| Distribution Main | 5757 | P-2735 | WAR | Sandro Dr. | 6 | Asbestos Cement | 556 | 65 | 2 out of 5 | $442 | 245,967 |
| Distribution Main | 4600 | P-2228 | WAR | Sandy Brook Ct. | 8 | PVC | 111 | 29 | 0.43 out of 5 | $442 | 49,103 |
| Distribution Main | 5980 | P-2048 | WAR | Saxony Dr. | 6 | Asbestos Cement | 517 | 57 | 1.85 out of 5 | $442 | 228,664 |
| Distribution Main | 5982 | P-2056 | WAR | Saxony Dr. | 6 | Asbestos Cement | 62 | 57 | 1.85 out of 5 | $442 | 27,572 |
| Distribution Main | 7237 | P-2056 | WAR | Saxony Dr. | 6 | Asbestos Cement | 564 | 57 | 1.85 out of 5 | $442 | 249,289 |
| Distribution Main | 7238 | P-2056 | WAR | Saxony Dr. | 6 | Asbestos Cement | 33 | 57 | 1.85 out of 5 | $442 | 14,490 |
| Distribution Main | 7068 | P-2510 | WAR | Scarsdale St. | 6 | Asbestos Cement | 291 | 67 | 2 out of 5 | $442 | 128,597 |
| Distribution Main | 7082 | P-2509 | WAR | Scarsdale St. | 6 | Asbestos Cement | 412 | 67 | 2 out of 5 | $442 | 182,166 |
| Distribution Main | 9938 | P-2510 | WAR | Scarsdale St. | 6 | Asbestos Cement | 30 | 67 | 2 out of 5 | $442 | 13,087 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 11626 | P-2510 | WAR | Scarsdale St. | 6 | Asbestos Cement | 21 | 67 | 2 out of 5 | $442 | 9,113 |
| Transmission Main | 10577 | | WAR | School Rd | 12 | Ductile Iron | 53 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7339 | P-2350 | WAR | Sea Breeze Ln. | 6 | Asbestos Cement | 176 | 44 | 1.85 out of 5 | $442 | 77,743 |
| Distribution Main | 1351 | P-120 | WAR | Setian Ln. | 8 | Asbestos Cement | 7 | 43 | 1.14 out of 5 | $442 | 3,209 |
| Distribution Main | 2328 | P-120 | WAR | Setian Ln. | 8 | Asbestos Cement | 392 | 43 | 1.14 out of 5 | $442 | 173,436 |
| Distribution Main | 2329 | P-120 | WAR | Setian Ln. | 8 | Asbestos Cement | 93 | 43 | 1.14 out of 5 | $442 | 40,935 |
| Distribution Main | 4601 | P-2226 | WAR | Shadowbrook Dr. | 8 | PVC | 696 | 29 | 0.43 out of 5 | $442 | 307,717 |
| Distribution Main | 6661 | P-2227 | WAR | Shadowbrook Dr. | 8 | PVC | 754 | 29 | 0.43 out of 5 | $442 | 333,189 |
| Distribution Main | 10135 | P-2226 | WAR | Shadowbrook Dr. | 8 | PVC | 40 | 29 | 0.43 out of 5 | $442 | 17,701 |
| Distribution Main | 10136 | P-2226 | WAR | Shadowbrook Dr. | 8 | PVC | 99 | 29 | 0.43 out of 5 | $442 | 43,968 |
| Distribution Main | 10137 | P-2227 | WAR | Shadowbrook Dr. | 8 | PVC | 9 | 29 | 0.43 out of 5 | $442 | 3,963 |
| Distribution Main | 10138 | P-2227 | WAR | Shadowbrook Dr. | 8 | PVC | 607 | 29 | 0.43 out of 5 | $442 | 268,337 |
| Distribution Main | 4536 | P-2577 | WAR | Shady Glen Dr. | 6 | Asbestos Cement | 840 | 71 | 2 out of 5 | $442 | 371,429 |
| Distribution Main | 5635 | P-2602 | WAR | Shattock Ave. | 6 | Asbestos Cement | 322 | 73 | 2 out of 5 | $442 | 142,421 |
| Distribution Main | 5636 | P-2923 | WAR | Shattock Ave. | 6 | Ductile Iron | 220 | 73 | 1.14 out of 5 | $442 | 97,161 |
| Distribution Main | 5637 | P-2923 | WAR | Shattock Ave. | 6 | Ductile Iron | 10 | 73 | 1.14 out of 5 | $442 | 4,357 |
| Distribution Main | 5710 | P-2923 | WAR | Shattock Ave. | 6 | Ductile Iron | 15 | 73 | 1.14 out of 5 | $442 | 6,713 |
| Distribution Main | 6447 | P-2461 | WAR | Shenandoah Rd. | 8 | Ductile Iron | 11 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6527 | P-2461 | WAR | Shenandoah Rd. | 8 | Ductile Iron | 535 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6528 | P-2461 | WAR | Shenandoah Rd. | 8 | Ductile Iron | 140 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7094 | P-2467 | WAR | Shenandoah Rd. | 8 | Ductile Iron | 550 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7095 | P-2467 | WAR | Shenandoah Rd. | 8 | Ductile Iron | 320 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10950 | P-2461 | WAR | Shenandoah Rd. | 8 | Ductile Iron | 5 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11929 | P-2461 | WAR | Shenandoah Rd. | 8 | Ductile Iron | 522 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11930 | P-2467 | WAR | Shenandoah Rd. | 8 | Ductile Iron | 227 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4877 | P-2938 | WAR | Silent Drive | 2 | Copper | 111 | 52 | 2.28 out of 5 | $442 | 48,873 |
| Distribution Main | 5904 | P-2101 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 270 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5977 | P-2099 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 40 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5978 | P-2099 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 437 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7180 | P-2101 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 6 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7293 | P-2097 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 31 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7294 | P-2097 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 1,649 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7295 | P-2097 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 201 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7296 | P-2097 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 191 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7297 | P-2097 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 328 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7299 | P-2100 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 97 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7300 | P-2100 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 4 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7301 | P-2100 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 363 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7302 | P-2100 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 5 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7307 | P-2100 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 5 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7308 | P-2100 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 497 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7311 | P-2100 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 401 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7312 | P-2100 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 124 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7315 | P-2100 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 276 | 22 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10202 | P-2100 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 88 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10917 | P-2100 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 3 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10918 | P-2100 | WAR | Sleepy Hollow Farm Dr. | 8 | Ductile Iron | 147 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3307 | P-2217 | WAR | Slient Dr. | 8 | Asbestos Cement | 182 | 53 | 1.14 out of 5 | $442 | 80,441 |
| Distribution Main | 4878 | P-2937 | WAR | Slient Dr. | 8 | Asbestos Cement | 207 | 53 | 1.14 out of 5 | $442 | 91,427 |
| Distribution Main | 10778 | P-2638 | WAR | Sophia Dr | 8 | Ductile Iron | 459 | 0 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10779 | P-2638 | WAR | Sophia Dr | 8 | Ductile Iron | 530 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2526 | P-2579 | WAR | Spencer Ave. | 10 | Cast Iron | 50 | 129 | 1.86 out of 5 | $442 | 22,225 |
| Distribution Main | 2527 | P-2579 | WAR | Spencer Ave. | 10 | Cast Iron | 470 | 129 | 1.86 out of 5 | $442 | 207,547 |
| Distribution Main | 4537 | P-2579 | WAR | Spencer Ave. | 10 | Cast Iron | 141 | 129 | 1.86 out of 5 | $442 | 62,269 |
| Distribution Main | 5041 | P-4968 | WAR | Spencer Ave. | 10 | Cast Iron | 28 | 129 | 1.86 out of 5 | $442 | 12,528 |
| Distribution Main | 6838 | P-2593 | WAR | Spencer Ave. | 6 | Cast Iron | 350 | 83 | 2.43 out of 5 | $442 | 154,858 |
| Distribution Main | 6840 | P-2586 | WAR | Spencer Ave. | 10 | Cast Iron | 259 | 129 | 1.86 out of 5 | $442 | 114,258 |
| Distribution Main | 6901 | P-2585 | WAR | Spencer Ave. | 10 | Cast Iron | 824 | 129 | 1.86 out of 5 | $442 | 364,347 |
| Distribution Main | 6911 | P-2593 | WAR | Spencer Ave. | 6 | Cast Iron | 19 | 83 | 2.43 out of 5 | $442 | 8,532 |
| Distribution Main | 6912 | P-2593 | WAR | Spencer Ave. | 6 | Cast Iron | 350 | 83 | 2.43 out of 5 | $442 | 154,748 |
| Distribution Main | 6915 | P-2580 | WAR | Spencer Ave. | 10 | Cast Iron | 182 | 129 | 1.86 out of 5 | $442 | 80,232 |
| Distribution Main | 6916 | P-2580 | WAR | Spencer Ave. | 10 | Cast Iron | 406 | 129 | 1.86 out of 5 | $442 | 179,439 |
| Distribution Main | 6926 | P-2586 | WAR | Spencer Ave. | 10 | Cast Iron | 40 | 129 | 1.86 out of 5 | $442 | 17,472 |
| Distribution Main | 7305 | P-2742 | WAR | Spencer Hill Ct. | 8 | Ductile Iron | 57 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7306 | P-2742 | WAR | Spencer Hill Ct. | 8 | Ductile Iron | 282 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7309 | P-2741 | WAR | Spencer Hill Ct. | 8 | Ductile Iron | 122 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4475 | P-2080 | WAR | Spinnaker Ln. | 8 | Ductile Iron | 7 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 6532 | P-2080 | WAR | Spinnaker Ln. | 8 | Ductile Iron | 416 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7098 | P-2080 | WAR | Spinnaker Ln. | 8 | Ductile Iron | 197 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7099 | P-2080 | WAR | Spinnaker Ln. | 8 | Ductile Iron | 173 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4544 | P-2624 | WAR | Spruce St. | 4 | Cast Iron | 357 | 109 | 3.29 out of 5 | $442 | 157,963 |
| Distribution Main | 5570 | P-2625 | WAR | Spruce St. | 6 | PVC | 356 | 34 | 1.14 out of 5 | $442 | 157,239 |
| Distribution Main | 5640 | P-2603 | WAR | Staples Ave. | 6 | Asbestos Cement | 833 | 73 | 2 out of 5 | $442 | 368,244 |
| Distribution Main | 5641 | P-2603 | WAR | Staples Ave. | 6 | Asbestos Cement | 592 | 73 | 2 out of 5 | $442 | 261,609 |
| Distribution Main | 7050 | P-2603 | WAR | Staples Ave. | 6 | Asbestos Cement | 7 | 73 | 2 out of 5 | $442 | 3,078 |
| Distribution Main | 7087 | P-2604 | WAR | Staples Ave. | 6 | Asbestos Cement | 6 | 73 | 2 out of 5 | $442 | 2,681 |
| Distribution Main | 7088 | P-2604 | WAR | Staples Ave. | 6 | Asbestos Cement | 592 | 73 | 2 out of 5 | $442 | 261,729 |
| Distribution Main | 2238 | P-2930 | WAR | Stiness Dr. | 2 | Copper | 133 | 83 | 2.57 out of 5 | $442 | 58,929 |
| Distribution Main | 7110 | P-2361 | WAR | Stiness Dr. | 2 | Copper | 408 | 83 | 2.57 out of 5 | $442 | 180,453 |
| Distribution Main | 7119 | P-2358 | WAR | Stiness Dr. | 6 | PVC | 418 | 31 | 1.14 out of 5 | $442 | 184,925 |
| Distribution Main | 7120 | P-2358 | WAR | Stiness Dr. | 6 | PVC | 130 | 31 | 1.14 out of 5 | $442 | 57,491 |
| Distribution Main | 7341 | P-2930 | WAR | Stiness Dr. | 2 | Copper | 21 | 83 | 2.57 out of 5 | $442 | 9,242 |
| Distribution Main | 7344 | P-2358 | WAR | Stiness Dr. | 6 | PVC | 10 | 31 | 1.14 out of 5 | $442 | 4,437 |
| Distribution Main | 3305 | P-2213 | WAR | Stubtoe Dr. | 8 | Asbestos Cement | 358 | 52 | 1.14 out of 5 | $442 | 158,363 |
| Distribution Main | 3306 | P-2214 | WAR | Stubtoe Dr. | 8 | Asbestos Cement | 429 | 52 | 1.14 out of 5 | $442 | 189,758 |
| Distribution Main | 5762 | P-2193 | WAR | Stubtoe Dr. | 8 | Asbestos Cement | 522 | 52 | 1.14 out of 5 | $442 | 230,940 |
| Distribution Main | 4481 | P-2078 | WAR | Sturbridge Dr. | 8 | Asbestos Cement | 5 | 40 | 1 out of 5 | $442 | 1,995 |
| Distribution Main | 5025 | P-2074 | WAR | Sturbridge Dr. | 8 | Asbestos Cement | 449 | 40 | 1 out of 5 | $442 | 198,329 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 6530 | P-2078 | WAR | Sturbridge Dr. | 8 | Asbestos Cement | 558 | 40 | 1 out of 5 | $442 | 246,524 |
| Distribution Main | 6531 | P-2078 | WAR | Sturbridge Dr. | 8 | Asbestos Cement | 300 | 40 | 1 out of 5 | $442 | 132,735 |
| Distribution Main | 7367 | P-2073 | WAR | Sturbridge Dr. | 8 | Asbestos Cement | 412 | 40 | 1 out of 5 | $442 | 182,043 |
| Distribution Main | 7368 | P-2073 | WAR | Sturbridge Dr. | 8 | Asbestos Cement | 157 | 40 | 1 out of 5 | $442 | 69,427 |
| Distribution Main | 3899 | P-137 | WAR | Sturbridge Way | 8 | Ductile Iron | 117 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3900 | P-137 | WAR | Sturbridge Way | 8 | Ductile Iron | 357 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4829 | P-137 | WAR | Sturbridge Way | 8 | Ductile Iron | 195 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11762 | P-137 | WAR | Sturbridge Way | 8 | Ductile Iron | 24 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10746 | P-2853 | WAR | Sue St | 8 | Ductile Iron | 223 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5984 | P-2055 | WAR | Superior St. | 8 | Asbestos Cement | 13 | 57 | 1.14 out of 5 | $442 | 5,638 |
| Distribution Main | 7360 | P-2055 | WAR | Superior St. | 6 | Asbestos Cement | 327 | 57 | 1.85 out of 5 | $442 | 144,562 |
| Distribution Main | 10204 | P-2057 | WAR | Superior St. | 6 | Asbestos Cement | 127 | 57 | 1.85 out of 5 | $442 | 55,970 |
| Distribution Main | 10205 | P-2057 | WAR | Superior St. | 6 | Asbestos Cement | 221 | 57 | 1.85 out of 5 | $442 | 97,522 |
| Distribution Main | 8292 | P-2289 | WAR | Sutter Ave. | 8 | Ductile Iron | 493 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8293 | P-2816 | WAR | Sutter Ave. | 8 | Ductile Iron | 142 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8294 | P-2816 | WAR | Sutter Ave. | 8 | Ductile Iron | 33 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1434 | P-1313 | WAR | Sykes St. | 4 | Ductile Iron | 9 | 20 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 2243 | P-1313 | WAR | Sykes St. | 8 | Ductile Iron | 512 | 20 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8280 | P-2283 | WAR | Tanner Ave. | 8 | Ductile Iron | 794 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8283 | P-2817 | WAR | Tanner Ave. | 8 | Ductile Iron | 625 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8284 | P-2817 | WAR | Tanner Ave. | 8 | Ductile Iron | 84 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9933 | P-2284 | WAR | Tanner Ave. | 8 | Ductile Iron | 389 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5490 | P-2709 | WAR | Taylor Ln. | 8 | Ductile Iron | 82 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5491 | P-2709 | WAR | Taylor Ln. | 8 | Ductile Iron | 123 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6429 | P-2709 | WAR | Taylor Ln. | 8 | Ductile Iron | 8 | 16 | 0 out of 5 | N/A | $0 |
| Transmission Main | 6943 | P-2187 | WAR | Telmore Rd. | 12 | Asbestos Cement | 894 | 46 | 1.14 out of 5 | $442 | 395,092 |
| Transmission Main | 6944 | P-2187 | WAR | Telmore Rd. | 12 | Asbestos Cement | 141 | 46 | 1.14 out of 5 | $442 | 62,370 |
| Distribution Main | 9285 | P-2870 | WAR | Thames Ave | 8 | Ductile Iron | 38 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9286 | P-2871 | WAR | Thames Ave | 2 | HDPE | 31 | 11 | 1.71 out of 5 | N/A | $0 |
| Distribution Main | 7013 | P-2530 | WAR | Thames Ave. | 2 | Copper | 563 | 79 | 2.43 out of 5 | $442 | 248,784 |
| Distribution Main | 10740 | P-2547 | WAR | Tillinghast Av | 6 | Ductile Iron | 17 | 1 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10741 | P-2547 | WAR | Tillinghast Av | 6 | Ductile Iron | 376 | 1 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 4384 | P-2858 | WAR | Tillinghast Ave | 8 | Ductile Iron | 101 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4385 | P-2858 | WAR | Tillinghast Ave | 8 | Ductile Iron | 177 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9415 | P-2858 | WAR | Tillinghast Ave | 8 | Ductile Iron | 12 | 16 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10698 | | WAR | Tillinghast Ave | 42 | Asbestos Cement | 1,036 | UNK | 0.85 out of 5 | $442 | 457,926 |
| Distribution Main | 10733 | P-2856 | WAR | Tillinghast Ave | 8 | Ductile Iron | 4 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9043 | P-2548 | WAR | Tillinghast Ave Easement | 8 | Ductile Iron | 15 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11540 | P-2858 | WAR | Tillinghast Ave Easement | 8 | Ductile Iron | 4 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2979 | P-2548 | WAR | Tillinghast Ave. | 6 | Ductile Iron | 519 | 16 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 7129 | P-2545 | WAR | Tillinghast Ave. | 6 | Ductile Iron | 62 | 24 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 7130 | P-2545 | WAR | Tillinghast Ave. | 6 | Ductile Iron | 513 | 24 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 10723 | P-2545 | WAR | Tillinghast Ave. | 6 | Ductile Iron | 25 | 24 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 11361 | P-2545 | WAR | Tillinghast Ave. | 6 | Ductile Iron | 59 | 24 | 0.85 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 5769 | P-2158 | WAR | Timberline Rd. | 8 | Asbestos Cement | 846 | 63 | 1.29 out of 5 | $442 | 373,742 |
| Distribution Main | 5770 | P-2158 | WAR | Timberline Rd. | 8 | Asbestos Cement | 427 | 63 | 1.29 out of 5 | $442 | 188,759 |
| Distribution Main | 11938 | P-2158 | WAR | Timberline Rd. | 8 | Asbestos Cement | 574 | 63 | 1.29 out of 5 | $442 | 253,763 |
| Distribution Main | 6525 | P-2337 | WAR | Tivoli Ct. | 8 | Ductile Iron | 138 | 31 | 0.14 out of 5 | $442 | 60,988 |
| Distribution Main | 6526 | P-2337 | WAR | Tivoli Ct. | 8 | Ductile Iron | 482 | 31 | 0.14 out of 5 | $442 | 213,079 |
| Distribution Main | 10176 | | WAR | Toll Gate Rd | 4 | Copper | 34 | 17 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 3907 | | WAR | Tollgate Rd | 2 | Unknown | 9 | UNK | 1.42 out of 5 | $442 | 3,911 |
| Distribution Main | 3908 | | WAR | Tollgate Rd | 2 | Unknown | 7 | UNK | 1.42 out of 5 | $442 | 3,100 |
| Distribution Main | 9103 | | WAR | Tollgate Rd | 2 | Unknown | 27 | UNK | 1.42 out of 5 | $442 | 12,116 |
| Distribution Main | 9976 | | WAR | Tollgate Rd | 6 | Ductile Iron | 25 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9977 | | WAR | Tollgate Rd | 6 | Ductile Iron | 1 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10575 | | WAR | Tollgate Rd | 6 | Ductile Iron | 9 | 2 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 10579 | P-2833 | WAR | Tollgate Rd | 16 | Ductile Iron | 672 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10580 | P-2833 | WAR | Tollgate Rd | 16 | Ductile Iron | 16 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10581 | P-2719 | WAR | Tollgate Rd | 16 | Ductile Iron | 611 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10582 | P-2710 | WAR | Tollgate Rd | 16 | Ductile Iron | 164 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10583 | P-2323 | WAR | Tollgate Rd | 16 | Ductile Iron | 49 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10584 | P-2323 | WAR | Tollgate Rd | 16 | Ductile Iron | 526 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10585 | P-2328 | WAR | Tollgate Rd | 16 | Ductile Iron | 375 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10586 | P-2964 | WAR | Tollgate Rd | 16 | Ductile Iron | 1,008 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10587 | P-2964 | WAR | Tollgate Rd | 16 | Ductile Iron | 225 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10588 | P-2278 | WAR | Tollgate Rd | 16 | Ductile Iron | 215 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10589 | P-2717 | WAR | Tollgate Rd | 16 | Ductile Iron | 406 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10590 | P-2717 | WAR | Tollgate Rd | 16 | Ductile Iron | 82 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10940 | P-2278 | WAR | Tollgate Rd | 16 | Ductile Iron | 93 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11677 | P-2833 | WAR | Tollgate Rd | 16 | Ductile Iron | 459 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11678 | P-2310 | WAR | Tollgate Rd | 16 | Ductile Iron | 420 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11679 | P-2833 | WAR | Tollgate Rd | 16 | Ductile Iron | 156 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11681 | P-2327 | WAR | Tollgate Rd | 16 | Ductile Iron | 103 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11682 | P-2328 | WAR | Tollgate Rd | 16 | Ductile Iron | 23 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11683 | P-2717 | WAR | Tollgate Rd | 16 | Ductile Iron | 82 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12136 | P-2323 | WAR | Tollgate Rd | 16 | Ductile Iron | 71 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12137 | P-2323 | WAR | Tollgate Rd | 16 | Ductile Iron | 6 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12138 | P-2323 | WAR | Tollgate Rd | 16 | Ductile Iron | 117 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12170 | P-2710 | WAR | Tollgate Rd | 16 | Ductile Iron | 11 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 866 | P-2647 | WAR | Tollgate Rd. | 10 | Cast Iron | 95 | 91 | 1.72 out of 5 | $442 | 41,988 |
| Distribution Main | 1148 | P-2862 | WAR | Tollgate Rd. | 10 | Cast Iron | 387 | 91 | 1.72 out of 5 | $442 | 171,092 |
| Distribution Main | 1149 | P-2862 | WAR | Tollgate Rd. | 10 | Cast Iron | 133 | 91 | 1.72 out of 5 | $442 | 58,913 |
| Distribution Main | 1152 | P-2647 | WAR | Tollgate Rd. | 10 | Cast Iron | 73 | 91 | 1.72 out of 5 | $442 | 32,324 |
| Distribution Main | 2146 | P-2862 | WAR | Tollgate Rd. | 10 | Cast Iron | 150 | 91 | 1.72 out of 5 | $442 | 66,301 |
| Distribution Main | 3408 | P-2862 | WAR | Tollgate Rd. | 10 | Cast Iron | 198 | 91 | 1.72 out of 5 | $442 | 87,522 |
| Distribution Main | 3409 | P-2862 | WAR | Tollgate Rd. | 10 | Cast Iron | 504 | 91 | 1.72 out of 5 | $442 | 222,889 |
| Distribution Main | 3410 | P-2862 | WAR | Tollgate Rd. | 10 | Cast Iron | 605 | 91 | 1.72 out of 5 | $442 | 267,259 |
| Distribution Main | 3411 | P-2862 | WAR | Tollgate Rd. | 10 | Cast Iron | 456 | 91 | 1.72 out of 5 | $442 | 201,425 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 3597 | P-2776 | WAR | Tollgate Rd. | 12 | Cast Iron | 754 | 91 | 1.72 out of 5 | $442 | 333,481 |
| Distribution Main | 4796 | P-2298 | WAR | Tollgate Rd. | 10 | Cast Iron | 220 | 91 | 1.72 out of 5 | $442 | 97,039 |
| Transmission Main | 7085 | P-2716 | WAR | Tollgate Rd. | 12 | Cast Iron | 61 | 91 | 1.72 out of 5 | $442 | 27,119 |
| Distribution Main | 7474 | P-2298 | WAR | Tollgate Rd. | 10 | Cast Iron | 109 | 91 | 1.72 out of 5 | $442 | 48,079 |
| Distribution Main | 7476 | P-2298 | WAR | Tollgate Rd. | 10 | Cast Iron | 1,487 | 91 | 1.72 out of 5 | $442 | 657,117 |
| Distribution Main | 7477 | P-2298 | WAR | Tollgate Rd. | 10 | Cast Iron | 84 | 91 | 1.72 out of 5 | $442 | 36,937 |
| Distribution Main | 10978 | P-2298 | WAR | Tollgate Rd. | 10 | Cast Iron | 4 | 91 | 1.72 out of 5 | $442 | 1,722 |
| Distribution Main | 11925 | P-2862 | WAR | Tollgate Rd. | 10 | Cast Iron | 381 | 91 | 1.72 out of 5 | $442 | 168,392 |
| Distribution Main | 4468 | P-2733 | WAR | Tomahawk Ct. | 6 | Asbestos Cement | 197 | 69 | 2 out of 5 | $442 | 86,983 |
| Distribution Main | 6601 | P-2733 | WAR | Tomahawk Ct. | 8 | Ductile Iron | 48 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10370 | P-2733 | WAR | Tomahawk Ct. | 6 | Asbestos Cement | 6 | 69 | 2 out of 5 | $442 | 2,856 |
| Distribution Main | 10371 | P-2733 | WAR | Tomahawk Ct. | 6 | Asbestos Cement | 237 | 69 | 2 out of 5 | $442 | 104,734 |
| Distribution Main | 6659 | P-2209 | WAR | Turtle Creek Dr. | 8 | PVC | 49 | 31 | 0.43 out of 5 | $442 | 21,438 |
| Distribution Main | 6660 | P-2209 | WAR | Turtle Creek Dr. | 8 | PVC | 324 | 31 | 0.43 out of 5 | $442 | 143,112 |
| Distribution Main | 10118 | | WAR | Vale St | 1.25 | Copper | 39 | 46 | 2.28 out of 5 | $442 | 17,369 |
| Distribution Main | 5432 | P-2327 | WAR | Vale St. | 8 | Ductile Iron | 41 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6958 | P-2329 | WAR | Vale St. | 6 | Asbestos Cement | 182 | 46 | 1.85 out of 5 | $442 | 80,467 |
| Distribution Main | 4466 | P-2354 | WAR | Valentine Cir. | 6 | Asbestos Cement | 9 | 46 | 1.85 out of 5 | $442 | 3,916 |
| Distribution Main | 6085 | P-2360 | WAR | Valentine Cir. | 2 | Copper | 198 | 46 | 2.28 out of 5 | $442 | 87,497 |
| Distribution Main | 7100 | P-2354 | WAR | Valentine Cir. | 6 | Asbestos Cement | 166 | 46 | 1.85 out of 5 | $442 | 73,503 |
| Distribution Main | 7108 | P-2359 | WAR | Valentine Cir. | 6 | Cast Iron | 29 | 83 | 2.43 out of 5 | $442 | 12,635 |
| Distribution Main | 7121 | P-2929 | WAR | Valentine Cir. | 2 | Copper | 16 | 46 | 2.28 out of 5 | $442 | 7,216 |
| Distribution Main | 7122 | P-2359 | WAR | Valentine Cir. | 6 | Cast Iron | 508 | 83 | 2.43 out of 5 | $442 | 224,605 |
| Distribution Main | 7123 | P-2359 | WAR | Valentine Cir. | 6 | Cast Iron | 10 | 83 | 2.43 out of 5 | $442 | 4,204 |
| Distribution Main | 7330 | P-2360 | WAR | Valentine Cir. | 6 | Asbestos Cement | 123 | 46 | 1.85 out of 5 | $442 | 54,565 |
| Distribution Main | 7342 | P-2929 | WAR | Valentine Cir. | 2 | Copper | 10 | 46 | 2.28 out of 5 | $442 | 4,585 |
| Distribution Main | 7343 | P-2359 | WAR | Valentine Cir. | 6 | Cast Iron | 15 | 83 | 2.43 out of 5 | $442 | 6,789 |
| Distribution Main | 6893 | P-2251 | WAR | Valley Brook Dr. | 8 | Asbestos Cement | 7 | 46 | 1.14 out of 5 | $442 | 3,089 |
| Distribution Main | 6894 | P-2251 | WAR | Valley Brook Dr. | 8 | Asbestos Cement | 160 | 46 | 1.14 out of 5 | $442 | 70,652 |
| Distribution Main | 6895 | P-2249 | WAR | Valley Brook Dr. | 8 | Asbestos Cement | 697 | 46 | 1.14 out of 5 | $442 | 308,208 |
| Distribution Main | 9278 | P-2874 | WAR | Vancouver Ave | 8 | Ductile Iron | 17 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9294 | P-2874 | WAR | Vancouver Ave | 6 | Ductile Iron | 2 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 5704 | P-2515 | WAR | Vancouver Ave. | 6 | Asbestos Cement | 467 | 69 | 2 out of 5 | $442 | 206,345 |
| Distribution Main | 5705 | P-2511 | WAR | Vancouver Ave. | 6 | Asbestos Cement | 428 | 69 | 2 out of 5 | $442 | 189,377 |
| Distribution Main | 6989 | P-2515 | WAR | Vancouver Ave. | 6 | Asbestos Cement | 13 | 69 | 2 out of 5 | $442 | 5,536 |
| Distribution Main | 6993 | P-2515 | WAR | Vancouver Ave. | 6 | Asbestos Cement | 115 | 69 | 2 out of 5 | $442 | 50,969 |
| Distribution Main | 6994 | P-2515 | WAR | Vancouver Ave. | 6 | Asbestos Cement | 149 | 69 | 2 out of 5 | $442 | 65,681 |
| Distribution Main | 6995 | P-2504 | WAR | Vancouver Ave. | 6 | Asbestos Cement | 441 | 69 | 2 out of 5 | $442 | 195,060 |
| Distribution Main | 7072 | P-2516 | WAR | Vancouver Ave. | 6 | Asbestos Cement | 231 | 69 | 2 out of 5 | $442 | 101,937 |
| Distribution Main | 7073 | P-2516 | WAR | Vancouver Ave. | 6 | Asbestos Cement | 125 | 69 | 2 out of 5 | $442 | 55,283 |
| Distribution Main | 7078 | P-2520 | WAR | Vancouver Ave. | 6 | Asbestos Cement | 226 | 69 | 2 out of 5 | $442 | 100,011 |
| Distribution Main | 7079 | P-2520 | WAR | Vancouver Ave. | 6 | Asbestos Cement | 38 | 69 | 2 out of 5 | $442 | 17,015 |
| Distribution Main | 7080 | P-2519 | WAR | Vancouver Ave. | 6 | Asbestos Cement | 256 | 69 | 2 out of 5 | $442 | 113,110 |
| Distribution Main | 3220 | P-2239 | WAR | Varnum Dr. | 8 | Asbestos Cement | 18 | 55 | 1.14 out of 5 | $442 | 8,040 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 5550 | P-2238 | WAR | Varnum Dr. | 8 | Asbestos Cement | 192 | 55 | 1.14 out of 5 | $442 | 84,789 |
| Distribution Main | 5551 | P-2238 | WAR | Varnum Dr. | 8 | Asbestos Cement | 1,475 | 55 | 1.14 out of 5 | $442 | 651,831 |
| Distribution Main | 6352 | P-2238 | WAR | Varnum Dr. | 8 | Asbestos Cement | 12 | 55 | 1.14 out of 5 | $442 | 5,516 |
| Distribution Main | 6813 | P-2239 | WAR | Varnum Dr. | 8 | Asbestos Cement | 626 | 55 | 1.14 out of 5 | $442 | 276,592 |
| Distribution Main | 6814 | P-2239 | WAR | Varnum Dr. | 8 | Asbestos Cement | 927 | 55 | 1.14 out of 5 | $442 | 409,648 |
| Distribution Main | 6934 | P-2237 | WAR | Varnum Dr. | 8 | Asbestos Cement | 506 | 55 | 1.14 out of 5 | $442 | 223,487 |
| Distribution Main | 11940 | P-2239 | WAR | Varnum Dr. | 8 | Asbestos Cement | 60 | 55 | 1.14 out of 5 | $442 | 26,362 |
| Distribution Main | 11942 | P-2239 | WAR | Varnum Dr. | 8 | Asbestos Cement | 153 | 55 | 1.14 out of 5 | $442 | 67,710 |
| Distribution Main | 6823 | P-2398 | WAR | Venus Dr. | 8 | Ductile Iron | 7 | 32 | 0.14 out of 5 | $442 | 3,048 |
| Distribution Main | 6824 | P-2398 | WAR | Venus Dr. | 8 | Ductile Iron | 267 | 32 | 0.14 out of 5 | $442 | 117,860 |
| Distribution Main | 6845 | P-2399 | WAR | Venus Dr. | 8 | Ductile Iron | 107 | 32 | 0.14 out of 5 | $442 | 47,134 |
| Distribution Main | 6846 | P-2399 | WAR | Venus Dr. | 8 | Ductile Iron | 265 | 32 | 0.14 out of 5 | $442 | 117,290 |
| Distribution Main | 5779 | P-2148 | WAR | Verdant Ln. | 8 | Asbestos Cement | 474 | 47 | 1.14 out of 5 | $442 | 209,568 |
| Distribution Main | 10761 | P-2632 | WAR | Veterans Memorial Dr | 8 | Ductile Iron | 524 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10762 | P-2632 | WAR | Veterans Memorial Dr | 8 | Ductile Iron | 249 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11934 | P-2632 | WAR | Veterans Memorial Dr | 8 | Ductile Iron | 366 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12168 | P-2632 | WAR | Veterans Memorial Dr | 6 | Ductile Iron | 36 | UNK | 0.71 out of 5 | $442 | 16,069 |
| Distribution Main | 12192 | P-2632 | WAR | Veterans Memorial Dr | 8 | Ductile Iron | 253 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12216 | P-2632 | WAR | Veterans Memorial Dr | 8 | Ductile Iron | 56 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12230 | P-2632 | WAR | Veterans Memorial Dr | 8 | Ductile Iron | 152 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9660 | P-2931 | WAR | Viceroy Rd | 8 | Ductile Iron | 5 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9661 | P-2931 | WAR | Viceroy Rd | 8 | Ductile Iron | 69 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5983 | P-2062 | WAR | Viceroy Rd. | 6 | Asbestos Cement | 438 | 57 | 1.85 out of 5 | $442 | 193,632 |
| Distribution Main | 6308 | P-2058 | WAR | Viceroy Rd. | 6 | Asbestos Cement | 948 | 57 | 1.85 out of 5 | $442 | 419,117 |
| Distribution Main | 6594 | P-2060 | WAR | Viceroy Rd. | 6 | Asbestos Cement | 19 | 57 | 1.85 out of 5 | $442 | 8,523 |
| Distribution Main | 6595 | P-2060 | WAR | Viceroy Rd. | 6 | Asbestos Cement | 198 | 57 | 1.85 out of 5 | $442 | 87,607 |
| Distribution Main | 7055 | P-2047 | WAR | Viceroy Rd. | 6 | Asbestos Cement | 429 | 57 | 1.85 out of 5 | $442 | 189,670 |
| Distribution Main | 7362 | P-2061 | WAR | Viceroy Rd. | 6 | Asbestos Cement | 92 | 57 | 1.85 out of 5 | $442 | 40,712 |
| Distribution Main | 7363 | P-2061 | WAR | Viceroy Rd. | 6 | Asbestos Cement | 6 | 57 | 1.85 out of 5 | $442 | 2,676 |
| Distribution Main | 2244 | P-1309 | WAR | Waite St. | 6 | Asbestos Cement | 339 | 69 | 2 out of 5 | $442 | 149,903 |
| Distribution Main | 4117 | | WAR | Waite St. | 6 | Ductile Iron | 20 | UNK | 0.71 out of 5 | $442 | 8,791 |
| Distribution Main | 9862 | P-1761 | WAR | Wallace Ave | 8 | Ductile Iron | 384 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5693 | P-2030 | WAR | Wampum Dr. | 8 | Asbestos Cement | 326 | 42 | 1.14 out of 5 | $442 | 144,074 |
| Distribution Main | 5695 | P-2032 | WAR | Wampum Dr. | 8 | Asbestos Cement | 31 | 42 | 1.14 out of 5 | $442 | 13,799 |
| Distribution Main | 7059 | P-2032 | WAR | Wampum Dr. | 8 | Asbestos Cement | 200 | 42 | 1.14 out of 5 | $442 | 88,423 |
| Distribution Main | 7060 | P-2032 | WAR | Wampum Dr. | 8 | Asbestos Cement | 23 | 42 | 1.14 out of 5 | $442 | 10,284 |
| Distribution Main | 4545 | P-2613 | WAR | Water St. | 8 | Ductile Iron | 469 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4546 | P-2613 | WAR | Water St. | 8 | Ductile Iron | 257 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4547 | P-2613 | WAR | Water St. | 8 | Ductile Iron | 73 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5202 | P-2611 | WAR | Water St. | 8 | Ductile Iron | 107 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5557 | P-2613 | WAR | Water St. | 8 | Ductile Iron | 44 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5567 | P-2611 | WAR | Water St. | 6 | Ductile Iron | 23 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 7034 | P-2611 | WAR | Water St. | 6 | Ductile Iron | 20 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 6981 | P-2485 | WAR | Weber Ave. | 6 | Asbestos Cement | 465 | 40 | 1.71 out of 5 | $442 | 205,481 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 5540 | P-2266 | WAR | Welthian Ct. | 6 | Asbestos Cement | 7 | 66 | 2 out of 5 | $442 | 2,927 |
| Distribution Main | 5544 | P-2953 | WAR | Welthian Ct. | 1 | Copper | 175 | 66 | 2.43 out of 5 | $442 | 77,213 |
| Distribution Main | 6931 | P-2266 | WAR | Welthian Ct. | 6 | Asbestos Cement | 341 | 66 | 2 out of 5 | $442 | 150,896 |
| Distribution Main | 10744 | P-2558 | WAR | West Pontiac St | 8 | Ductile Iron | 100 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10745 | P-2855 | WAR | West Pontiac St | 8 | Ductile Iron | 370 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11717 | P-2854 | WAR | West Pontiac St | 8 | Ductile Iron | 20 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11920 | P-2854 | WAR | West Pontiac St | 8 | Ductile Iron | 17 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7118 | P-2392 | WAR | Westchester Way | 6 | Asbestos Cement | 547 | 53 | 1.85 out of 5 | $442 | 241,685 |
| Distribution Main | 7124 | | WAR | Westchester Way | 6 | Unknown | 382 | 53 | 1 out of 5 | $442 | 168,922 |
| Distribution Main | 7349 | P-2391 | WAR | Westchester Way | 6 | Asbestos Cement | 25 | 53 | 1.85 out of 5 | $442 | 10,894 |
| Distribution Main | 7350 | P-2391 | WAR | Westchester Way | 6 | Asbestos Cement | 230 | 53 | 1.85 out of 5 | $442 | 101,681 |
| Distribution Main | 7357 | P-2392 | WAR | Westchester Way | 6 | Asbestos Cement | 24 | 53 | 1.85 out of 5 | $442 | 10,600 |
| Distribution Main | 11360 | P-2392 | WAR | Westchester Way | 6 | Asbestos Cement | 40 | 53 | 1.85 out of 5 | $442 | 17,742 |
| Distribution Main | 5493 | P-2947 | WAR | Weymouth Ln | 8 | Ductile Iron | 5 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6510 | P-2947 | WAR | Weymouth Ln | 8 | Ductile Iron | 311 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6511 | P-2947 | WAR | Weymouth Ln | 8 | Ductile Iron | 76 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4460 | P-2738 | WAR | Whispering Ln. | 6 | PVC | 385 | 31 | 1.14 out of 5 | $442 | 170,173 |
| Distribution Main | 10557 | P-2301 | WAR | Whitehall Dr | 8 | Ductile Iron | 229 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10558 | P-2301 | WAR | Whitehall Dr | 8 | Ductile Iron | 43 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10847 | P-2302 | WAR | Whitehall Dr | 8 | Ductile Iron | 180 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5395 | P-2432 | WAR | Wilcar St | 8 | Asbestos Cement | 149 | 48 | 1.14 out of 5 | $442 | 65,892 |
| Distribution Main | 5398 | P-2431 | WAR | Wilcar St. | 8 | Asbestos Cement | 354 | 48 | 1.14 out of 5 | $442 | 156,420 |
| Distribution Main | 9139 | P-2401 | WAR | Williams St | 8 | Ductile Iron | 257 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10911 | P-2955 | WAR | Williams St | 8 | Ductile Iron | 59 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10912 | P-2955 | WAR | Williams St | 8 | Ductile Iron | 34 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10913 | P-2401 | WAR | Williams St | 8 | Ductile Iron | 242 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6283 | P-2955 | WAR | Williams St. | 4 | Cast Iron | 36 | 129 | 3.29 out of 5 | $442 | 16,109 |
| Distribution Main | 4516 | P-2380 | WAR | Windemere Way | 8 | Asbestos Cement | 9 | 80 | 1.29 out of 5 | $442 | 3,893 |
| Distribution Main | 6086 | P-2711 | WAR | Windemere Way | 8 | Asbestos Cement | 443 | 80 | 1.29 out of 5 | $442 | 195,727 |
| Distribution Main | 6091 | P-2710 | WAR | Windemere Way | 8 | Asbestos Cement | 196 | 80 | 1.29 out of 5 | $442 | 86,517 |
| Distribution Main | 6092 | P-2710 | WAR | Windemere Way | 8 | Asbestos Cement | 42 | 80 | 1.29 out of 5 | $442 | 18,653 |
| Distribution Main | 6534 | P-2378 | WAR | Windemere Way | 8 | Asbestos Cement | 344 | 80 | 1.29 out of 5 | $442 | 151,849 |
| Distribution Main | 7175 | P-2380 | WAR | Windemere Way | 8 | Asbestos Cement | 634 | 80 | 1.29 out of 5 | $442 | 280,138 |
| Distribution Main | 7178 | P-2710 | WAR | Windemere Way | 8 | Asbestos Cement | 13 | 80 | 1.29 out of 5 | $442 | 5,638 |
| Distribution Main | 9602 | P-2378 | WAR | Windermere Way | 8 | Ductile Iron | 5 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9603 | P-2378 | WAR | Windermere Way | 8 | Ductile Iron | 28 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3598 | P-2295 | WAR | Winman Ct. | 8 | Ductile Iron | 49 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7000 | P-2295 | WAR | Winman Ct. | 8 | Ductile Iron | 4 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7021 | P-2295 | WAR | Winman Ct. | 8 | Ductile Iron | 493 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 8281 | ?-229P-2295 | WAR | Winman Ct. | 8 | Ductile Iron | 22 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 8282 | ?-229P-2295 | WAR | Winman Ct. | 8 | Ductile Iron | 55 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3308 | P-2216 | WAR | Winnisquam Dr. | 8 | Asbestos Cement | 433 | 53 | 1.14 out of 5 | $442 | 191,244 |
| Distribution Main | 3627 | P-2199 | WAR | Winnisquam Dr. | 8 | Asbestos Cement | 308 | 53 | 1.14 out of 5 | $442 | 136,093 |
| Distribution Main | 3628 | P-2200 | WAR | Winnisquam Dr. | 8 | Asbestos Cement | 123 | 53 | 1.14 out of 5 | $442 | 54,527 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4222 | P-2215 | WAR | Winnisquam Dr. | 8 | Asbestos Cement | 200 | 53 | 1.14 out of 5 | $442 | 88,400 |
| Distribution Main | 4223 | P-2215 | WAR | Winnisquam Dr. | 8 | Asbestos Cement | 9 | 53 | 1.14 out of 5 | $442 | 4,157 |
| Distribution Main | 4224 | P-2215 | WAR | Winnisquam Dr. | 8 | Asbestos Cement | 34 | 53 | 1.14 out of 5 | $442 | 15,223 |
| Distribution Main | 4242 | P-2215 | WAR | Winnisquam Dr. | 8 | Asbestos Cement | 10 | 53 | 1.14 out of 5 | $442 | 4,408 |
| Distribution Main | 5751 | P-2194 | WAR | Winnisquam Dr. | 8 | Asbestos Cement | 262 | 53 | 1.14 out of 5 | $442 | 115,943 |
| Distribution Main | 5752 | P-2194 | WAR | Winnisquam Dr. | 8 | Asbestos Cement | 54 | 53 | 1.14 out of 5 | $442 | 23,807 |
| Distribution Main | 5780 | P-2194 | WAR | Winnisquam Dr. | 8 | Asbestos Cement | 18 | 53 | 1.14 out of 5 | $442 | 8,026 |
| Distribution Main | 6865 | P-2417 | WAR | Wolverstone Rd. | 6 | PVC | 429 | 44 | 1.28 out of 5 | $442 | 189,658 |
| Distribution Main | 6866 | P-2417 | WAR | Wolverstone Rd. | 6 | PVC | 331 | 44 | 1.28 out of 5 | $442 | 146,476 |
| Distribution Main | 6867 | P-2417 | WAR | Wolverstone Rd. | 6 | PVC | 213 | 44 | 1.28 out of 5 | $442 | 94,289 |
| Distribution Main | 4484 | P-2071 | WAR | Zinnia St. | 8 | Asbestos Cement | 369 | 42 | 1.14 out of 5 | $442 | 163,292 |
| Distribution Main | 4485 | P-2068 | WAR | Zinnia St. | 8 | Asbestos Cement | 383 | 42 | 1.14 out of 5 | $442 | 169,382 |
| Distribution Main | 7366 | P-2063 | WAR | Zinnia St. | 8 | Asbestos Cement | 269 | 42 | 1.14 out of 5 | $442 | 118,790 |
| Distribution Main | 7566 | P-3009 | WG | Bailey Dr. | 8 | Asbestos Cement | 653 | 48 | 1.14 out of 5 | $442 | 288,653 |
| Distribution Main | 7567 | P-3009 | WG | Bailey Dr. | 8 | Asbestos Cement | 560 | 48 | 1.14 out of 5 | $442 | 247,531 |
| Distribution Main | 7681 | P-3008 | WG | Bailey Dr. | 8 | Asbestos Cement | 101 | 48 | 1.14 out of 5 | $442 | 44,444 |
| Distribution Main | 7552 | P-3043 | WG | Brant Tr. | 6 | Asbestos Cement | 11 | 54 | 1.85 out of 5 | $442 | 4,794 |
| Distribution Main | 7553 | P-3043 | WG | Brant Tr. | 6 | Asbestos Cement | 65 | 54 | 1.85 out of 5 | $442 | 28,870 |
| Distribution Main | 8088 | P-3086 | WG | Buck Hollow Rd | 8 | Ductile Iron | 829 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 8089 | P-3086 | WG | Buck Hollow Rd | 8 | Ductile Iron | 574 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 11427 | P-3086 | WG | Buck Hollow Rd | 8 | Ductile Iron | 216 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 11428 | P-3086 | WG | Buck Hollow Rd | 8 | Ductile Iron | 19 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 7136 | P-3027 | WG | Cambio Ct. | 6 | Asbestos Cement | 375 | 42 | 1.85 out of 5 | $442 | 165,579 |
| Transmission Main | 1671 | P-3080 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 1,081 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1672 | P-3080 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 606 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1673 | P-3080 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 41 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1747 | P-3080 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 274 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3686 | P-40043 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 9 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4580 | P-40043 | WG | Carrs Pond Rd. | 16 | Ductile Iron | 53 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4978 | P-3054 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 44 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4979 | P-3054 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 915 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4980 | P-3080 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 38 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4981 | P-3080 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 668 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5713 | P-3056 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 675 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5715 | P-3056 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 118 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5716 | P-3056 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 908 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8880 | P-3056 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 105 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9922 | P-3080 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 38 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9990 | P-3080 | WG | Carrs Pond Rd. | 20 | Ductile Iron | 25 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2974 | P-3055 | WG | Carrs Pond Rd. Tank | 16 | Ductile Iron | 713 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3450 | P-3137 | WG | Carrs Pond Rd. Tank | 12 | Ductile Iron | 37 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4221 | | WG | Carrs Pond Rd. Tank | 12 | Ductile Iron | 264 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5714 | P-3055 | WG | Carrs Pond Rd. Tank | 16 | Ductile Iron | 32 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9910 | P-3055 | WG | Carrs Pond Rd. Tank | 12 | Ductile Iron | 16 | 18 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 9911 | P-3055 | WG | Carrs Pond Rd. Tank | 12 | Ductile Iron | 24 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7663 | P-3014 | WG | Cheyene Tr. | 6 | Asbestos Cement | 515 | 48 | 1.85 out of 5 | $442 | 227,810 |
| Distribution Main | 7268 | P-3022 | WG | Clubhouse Rd. | 6 | Asbestos Cement | 332 | 48 | 1.85 out of 5 | $442 | 146,812 |
| Distribution Main | 7639 | P-3022 | WG | Clubhouse Rd. | 6 | Asbestos Cement | 209 | 48 | 1.85 out of 5 | $442 | 92,571 |
| Distribution Main | 7640 | P-3022 | WG | Clubhouse Rd. | 6 | Asbestos Cement | 482 | 48 | 1.85 out of 5 | $442 | 213,057 |
| Distribution Main | 7655 | P-3023 | WG | Clubhouse Rd. | 6 | Asbestos Cement | 589 | 48 | 1.85 out of 5 | $442 | 260,424 |
| Distribution Main | 7656 | P-3023 | WG | Clubhouse Rd. | 6 | Asbestos Cement | 524 | 48 | 1.85 out of 5 | $442 | 231,784 |
| Distribution Main | 7659 | P-3020 | WG | Clubhouse Rd. | 6 | Asbestos Cement | 23 | 48 | 1.85 out of 5 | $442 | 10,209 |
| Distribution Main | 7660 | P-3020 | WG | Clubhouse Rd. | 6 | Asbestos Cement | 625 | 48 | 1.85 out of 5 | $442 | 276,314 |
| Distribution Main | 7679 | P-3015 | WG | Comanche Trail | 8 | Asbestos Cement | 541 | 48 | 1.14 out of 5 | $442 | 239,253 |
| Distribution Main | 8085 | P-3087 | WG | Deer Run Rd | 8 | Ductile Iron | 1,267 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8086 | P-3087 | WG | Deer Run Rd | 8 | Ductile Iron | 576 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 11426 | P-3087 | WG | Deer Run Rd | 8 | Ductile Iron | 522 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 11429 | P-3087 | WG | Deer Run Rd | 8 | Ductile Iron | 28 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 505 | P-3135 | WG | Division Road | 16 | Ductile Iron | 499 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 506 | P-3135 | WG | Division Road | 16 | Ductile Iron | 189 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 507 | P-3101 | WG | Division Road | 16 | Ductile Iron | 868 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 508 | P-3101 | WG | Division Road | 16 | Ductile Iron | 120 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2002 | P-3101 | WG | Division Road | 16 | Ductile Iron | 183 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2003 | P-3053 | WG | Division Road | 16 | Ductile Iron | 891 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2004 | P-3059 | WG | Division Road | 20 | Ductile Iron | 1,163 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2005 | P-3059 | WG | Division Road | 20 | Ductile Iron | 1,088 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2006 | P-3057 | WG | Division Road | 20 | Ductile Iron | 1,433 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2007 | P-3057 | WG | Division Road | 20 | Ductile Iron | 688 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2008 | P-3133 | WG | Division Road | 20 | Ductile Iron | 70 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2009 | P-3133 | WG | Division Road | 20 | Ductile Iron | 979 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2010 | P-3133 | WG | Division Road | 20 | Ductile Iron | 114 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2011 | P-3135 | WG | Division Road | 16 | Ductile Iron | 600 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2012 | P-3101 | WG | Division Road | 16 | Ductile Iron | 3 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2014 | P-3135 | WG | Division Road | 16 | Ductile Iron | 3 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4982 | P-3059 | WG | Division Road | 20 | Ductile Iron | 810 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8879 | P-3101 | WG | Division Road | 16 | Ductile Iron | 195 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8881 | P-3057 | WG | Division Road | 20 | Ductile Iron | 194 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10099 | P-3059 | WG | Division Road | 20 | Ductile Iron | 97 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10101 | | WG | Division Road | 20 | Ductile Iron | 33 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11522 | P-3133 | WG | Division Road | 20 | Ductile Iron | 4 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8090 | P-3138 | WG | Doe Place | 8 | Ductile Iron | 450 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 7270 | P-3004 | WG | Easement | 8 | Asbestos Cement | 579 | 38 | 1 out of 5 | $442 | 255,882 |
| Distribution Main | 7680 | P-3063 | WG | Eddy St. | 8 | Asbestos Cement | 225 | 48 | 1.14 out of 5 | $442 | 99,423 |
| Transmission Main | 10002 | P-3111 | WG | Hopkins Hill Rd | 12 | Ductile Iron | 3 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10102 | | WG | Hopkins Hill Rd | 8 | Ductile Iron | 1 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10104 | P-3142 | WG | Hopkins Hill Rd | 6 | Unknown | 96 | UNK | 0.71 out of 5 | $442 | 42,634 |
| Transmission Main | 492 | P-3140 | WG | Hopkins Hill Rd. | 12 | Ductile Iron | 885 | 30 | 0.14 out of 5 | $442 | 391,369 |
| Transmission Main | 493 | P-3140 | WG | Hopkins Hill Rd. | 12 | Ductile Iron | 49 | 30 | 0.14 out of 5 | $442 | 21,520 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 494 | P-3047 | WG | Hopkins Hill Rd. | 16 | Ductile Iron | 540 | 31 | 0.14 out of 5 | $442 | 238,787 |
| Transmission Main | 2973 | P-3130 | WG | Hopkins Hill Rd. | 16 | Ductile Iron | 87 | 31 | 0.14 out of 5 | $442 | 38,577 |
| Transmission Main | 4095 | P-3131 | WG | Hopkins Hill Rd. | 12 | Ductile Iron | 51 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 4220 | P-3047 | WG | Hopkins Hill Rd. | 16 | Ductile Iron | 319 | 31 | 0.14 out of 5 | $442 | 141,167 |
| Transmission Main | 4815 | P-3058 | WG | Hopkins Hill Rd. | 20 | Ductile Iron | 810 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4835 | P-3110 | WG | Hopkins Hill Rd. | 20 | Ductile Iron | 78 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4836 | P-3046 | WG | Hopkins Hill Rd. | 20 | Ductile Iron | 818 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4837 | P-3046 | WG | Hopkins Hill Rd. | 20 | Ductile Iron | 359 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4919 | P-3046 | WG | Hopkins Hill Rd. | 20 | Ductile Iron | 221 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4920 | P-3046 | WG | Hopkins Hill Rd. | 20 | Ductile Iron | 38 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5314 | P-3046 | WG | Hopkins Hill Rd. | 20 | Ductile Iron | 302 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5315 | P-3110 | WG | Hopkins Hill Rd. | 20 | Ductile Iron | 24 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5316 | P-3110 | WG | Hopkins Hill Rd. | 20 | Ductile Iron | 768 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5317 | P-3058 | WG | Hopkins Hill Rd. | 20 | Ductile Iron | 1,296 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5318 | P-3129 | WG | Hopkins Hill Rd. | 20 | Ductile Iron | 43 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10100 | | WG | Hopkins Hill Rd. | 20 | Ductile Iron | 34 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11267 | P-3110 | WG | Hopkins Hill Rd. | 20 | Ductile Iron | 12 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11295 | P-3140 | WG | Hopkins Hill Rd. | 12 | Ductile Iron | 45 | 30 | 0.14 out of 5 | $442 | 19,843 |
| Transmission Main | 12062 | P-3140 | WG | Hopkins Hill Rd. | 12 | Ductile Iron | 282 | 30 | 0.14 out of 5 | $442 | 124,610 |
| Transmission Main | 12080 | P-3110 | WG | Hopkins Hill Rd. | 20 | Ductile Iron | 15 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10222 | P-3031 | WG | Lake Dr | 8 | Ductile Iron | 16 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5232 | P-3028 | WG | Lake Dr. | 8 | Asbestos Cement | 1,208 | 48 | 1.14 out of 5 | $442 | 533,989 |
| Distribution Main | 5233 | P-3028 | WG | Lake Dr. | 8 | Asbestos Cement | 80 | 48 | 1.14 out of 5 | $442 | 35,256 |
| Distribution Main | 7556 | P-3026 | WG | Lake Dr. | 8 | Asbestos Cement | 21 | 48 | 1.14 out of 5 | $442 | 9,217 |
| Distribution Main | 7557 | P-3026 | WG | Lake Dr. | 8 | Asbestos Cement | 558 | 48 | 1.14 out of 5 | $442 | 246,828 |
| Distribution Main | 7560 | P-3031 | WG | Lake Dr. | 8 | Asbestos Cement | 970 | 48 | 1.14 out of 5 | $442 | 428,574 |
| Distribution Main | 7661 | P-3028 | WG | Lake Dr. | 8 | Asbestos Cement | 39 | 48 | 1.14 out of 5 | $442 | 17,169 |
| Distribution Main | 7662 | P-3028 | WG | Lake Dr. | 8 | Asbestos Cement | 962 | 48 | 1.14 out of 5 | $442 | 425,252 |
| Distribution Main | 10123 | | WG | Lake Dr. | 8 | Asbestos Cement | 26 | 48 | 1.14 out of 5 | $442 | 11,304 |
| Distribution Main | 10124 | | WG | Lake Dr. | 8 | Asbestos Cement | 26 | 48 | 1.14 out of 5 | $442 | 11,335 |
| Distribution Main | 11291 | P-3028 | WG | Lake Dr. | 8 | Asbestos Cement | 9 | 48 | 1.14 out of 5 | $442 | 3,767 |
| Distribution Main | 11984 | P-3028 | WG | Lake Dr. | 8 | Asbestos Cement | 487 | 48 | 1.14 out of 5 | $442 | 215,087 |
| Distribution Main | 11985 | P-3028 | WG | Lake Dr. | 8 | Asbestos Cement | 10 | 48 | 1.14 out of 5 | $442 | 4,635 |
| Distribution Main | 7649 | P-3025 | WG | Mac Cue Point Rd. | 8 | Asbestos Cement | 207 | 48 | 1.14 out of 5 | $442 | 91,472 |
| Distribution Main | 5231 | P-7452 | WG | Melrose Dr. | 8 | Ductile Iron | 787 | 26 | 0.14 out of 5 | $442 | 347,938 |
| Distribution Main | 9920 | | WG | Mishnock Rd | 8 | Asbestos Cement | 22 | 49 | 1.14 out of 5 | $442 | 9,755 |
| Transmission Main | 10215 | P-3061 | WG | Mishnock Rd | 16 | Ductile Iron | 126 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10216 | P-3060 | WG | Mishnock Rd | 16 | Ductile Iron | 760 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10217 | P-3060 | WG | Mishnock Rd | 16 | Ductile Iron | 285 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10218 | | WG | Mishnock Rd | 16 | Ductile Iron | 800 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10219 | | WG | Mishnock Rd | 16 | Ductile Iron | 220 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10220 | P-3060 | WG | Mishnock Rd | 12 | Ductile Iron | 73 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10221 | P-3033 | WG | Mishnock Rd | 12 | Ductile Iron | 73 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10223 | | WG | Mishnock Rd | 16 | Ductile Iron | 408 | 5 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 10224 | | WG | Mishnock Rd | 16 | Ductile Iron | 284 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10225 | | WG | Mishnock Rd | 16 | Ductile Iron | 386 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10226 | | WG | Mishnock Rd | 16 | Ductile Iron | 324 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10227 | P-3036 | WG | Mishnock Rd | 12 | Ductile Iron | 5 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10228 | P-3035 | WG | Mishnock Rd | 6 | Ductile Iron | 21 | 5 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 10750 | | WG | Mishnock Rd | 16 | Ductile Iron | 5,310 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10751 | | WG | Mishnock Rd | 16 | Ductile Iron | 1,165 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10998 | P-3034 | WG | Mishnock Rd | 12 | Ductile Iron | 3 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11644 | P-3060 | WG | Mishnock Rd | 12 | Ductile Iron | 14 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4921 | P-3006 | WG | Mishnock Rd. | 12 | Asbestos Cement | 183 | 49 | 1.14 out of 5 | $442 | 80,994 |
| Transmission Main | 5353 | P-3006 | WG | Mishnock Rd. | 12 | Asbestos Cement | 3 | 49 | 1.14 out of 5 | $442 | 1,462 |
| Transmission Main | 5923 | P-3010 | WG | Mishnock Rd. | 12 | Asbestos Cement | 171 | 49 | 1.14 out of 5 | $442 | 75,791 |
| Transmission Main | 6628 | | WG | Mishnock Rd. | 12 | Asbestos Cement | 16 | 49 | 1.14 out of 5 | $442 | 6,982 |
| Transmission Main | 7561 | P-3010 | WG | Mishnock Rd. | 12 | Asbestos Cement | 177 | 49 | 1.14 out of 5 | $442 | 78,274 |
| Transmission Main | 7562 | P-3010 | WG | Mishnock Rd. | 12 | Asbestos Cement | 418 | 49 | 1.14 out of 5 | $442 | 184,613 |
| Transmission Main | 7563 | P-3034 | WG | Mishnock Rd. | 12 | Asbestos Cement | 175 | 49 | 1.14 out of 5 | $442 | 77,487 |
| Transmission Main | 7564 | P-3011 | WG | Mishnock Rd. | 12 | Asbestos Cement | 315 | 49 | 1.14 out of 5 | $442 | 139,390 |
| Transmission Main | 7565 | P-3011 | WG | Mishnock Rd. | 12 | Asbestos Cement | 63 | 49 | 1.14 out of 5 | $442 | 27,627 |
| Transmission Main | 7641 | P-3036 | WG | Mishnock Rd. | 12 | Asbestos Cement | 638 | 49 | 1.14 out of 5 | $442 | 282,039 |
| Transmission Main | 7642 | P-3036 | WG | Mishnock Rd. | 12 | Asbestos Cement | 497 | 49 | 1.14 out of 5 | $442 | 219,651 |
| Transmission Main | 7670 | P-3010 | WG | Mishnock Rd. | 12 | Asbestos Cement | 610 | 49 | 1.14 out of 5 | $442 | 269,800 |
| Transmission Main | 7671 | P-3011 | WG | Mishnock Rd. | 12 | Asbestos Cement | 355 | 49 | 1.14 out of 5 | $442 | 157,018 |
| Transmission Main | 7672 | P-3011 | WG | Mishnock Rd. | 12 | Asbestos Cement | 356 | 49 | 1.14 out of 5 | $442 | 157,285 |
| Transmission Main | 7673 | P-3034 | WG | Mishnock Rd. | 12 | Asbestos Cement | 174 | 49 | 1.14 out of 5 | $442 | 76,746 |
| Transmission Main | 7674 | P-3034 | WG | Mishnock Rd. | 12 | Asbestos Cement | 291 | 49 | 1.14 out of 5 | $442 | 128,668 |
| Transmission Main | 7675 | P-3033 | WG | Mishnock Rd. | 12 | Asbestos Cement | 575 | 49 | 1.14 out of 5 | $442 | 254,312 |
| Transmission Main | 7676 | P-3060 | WG | Mishnock Rd. | 12 | Asbestos Cement | 845 | 49 | 1.14 out of 5 | $442 | 373,575 |
| Transmission Main | 7677 | P-3060 | WG | Mishnock Rd. | 12 | Asbestos Cement | 1,014 | 49 | 1.14 out of 5 | $442 | 448,264 |
| Transmission Main | 10420 | P-3006 | WG | Mishnock Rd. | 12 | Asbestos Cement | 4 | 49 | 1.14 out of 5 | $442 | 1,749 |
| Transmission Main | 10421 | P-3006 | WG | Mishnock Rd. | 12 | Asbestos Cement | 174 | 49 | 1.14 out of 5 | $442 | 76,735 |
| Transmission Main | 11388 | P-3011 | WG | Mishnock Rd. | 12 | Asbestos Cement | 19 | 49 | 1.14 out of 5 | $442 | 8,204 |
| Transmission Main | 11656 | P-3006 | WG | Mishnock Rd. | 12 | Asbestos Cement | 15 | 49 | 1.14 out of 5 | $442 | 6,499 |
| Transmission Main | 11983 | P-3011 | WG | Mishnock Rd. | 12 | Asbestos Cement | 330 | 49 | 1.14 out of 5 | $442 | 145,875 |
| Distribution Main | 7266 | P-3018 | WG | Mohawk Tr. | 8 | Asbestos Cement | 155 | 48 | 1.14 out of 5 | $442 | 68,666 |
| Distribution Main | 7267 | P-3018 | WG | Mohawk Tr. | 8 | Asbestos Cement | 9 | 48 | 1.14 out of 5 | $442 | 3,976 |
| Distribution Main | 7568 | P-3012 | WG | Mohawk Tr. | 8 | Asbestos Cement | 14 | 48 | 1.14 out of 5 | $442 | 6,367 |
| Distribution Main | 7569 | P-3012 | WG | Mohawk Tr. | 8 | Asbestos Cement | 391 | 48 | 1.14 out of 5 | $442 | 172,871 |
| Distribution Main | 7667 | P-3017 | WG | Mohawk Tr. | 8 | Asbestos Cement | 119 | 48 | 1.14 out of 5 | $442 | 52,447 |
| Distribution Main | 7668 | P-3016 | WG | Mohawk Tr. | 8 | Asbestos Cement | 225 | 48 | 1.14 out of 5 | $442 | 99,235 |
| Distribution Main | 7669 | P-3012 | WG | Mohawk Tr. | 8 | Asbestos Cement | 13 | 48 | 1.14 out of 5 | $442 | 5,912 |
| Distribution Main | 7678 | P-3021 | WG | Mohawk Tr. | 8 | Asbestos Cement | 235 | 48 | 1.14 out of 5 | $442 | 103,922 |
| Transmission Main | 1995 | P-3136 | WG | Moosehorn Road | 16 | Ductile Iron | 5 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1996 | P-3136 | WG | Moosehorn Road | 16 | Ductile Iron | 31 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2013 | P-3136 | WG | Moosehorn Road | 16 | Ductile Iron | 3 | 18 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 10212 | | WG | Nooseneck Hill Rd | 16 | Ductile Iron | 73 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10213 | | WG | Nooseneck Hill Rd | 16 | Ductile Iron | 825 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10214 | | WG | Nooseneck Hill Rd | 16 | Ductile Iron | 664 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10706 | | WG | Nooseneck Hill Rd | 12 | HDPE | 50 | 5 | 0.28 out of 5 | N/A | $0 |
| Distribution Main | 10707 | | WG | Nooseneck Hill Rd | 2 | Copper | 2 | 5 | 1.99 out of 5 | N/A | $0 |
| Transmission Main | 10708 | | WG | Nooseneck Hill Rd | 16 | Ductile Iron | 115 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10709 | | WG | Nooseneck Hill Rd | 16 | Ductile Iron | 568 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11067 | | WG | Nooseneck Hill Rd | 16 | Ductile Iron | 14 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11068 | | WG | Nooseneck Hill Rd | 16 | Ductile Iron | 15 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11358 | | WG | Nooseneck Hill Rd | 16 | Ductile Iron | 11 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7137 | P-3040 | WG | Nooseneck Hill Rd. | 8 | Asbestos Cement | 220 | 54 | 1.14 out of 5 | $442 | 97,030 |
| Distribution Main | 7138 | P-3040 | WG | Nooseneck Hill Rd. | 8 | Asbestos Cement | 150 | 54 | 1.14 out of 5 | $442 | 66,453 |
| Distribution Main | 7140 | P-3042 | WG | Nooseneck Hill Rd. | 8 | Asbestos Cement | 167 | 54 | 1.14 out of 5 | $442 | 73,849 |
| Distribution Main | 7141 | P-3042 | WG | Nooseneck Hill Rd. | 8 | Asbestos Cement | 598 | 54 | 1.14 out of 5 | $442 | 264,420 |
| Distribution Main | 7142 | P-3038 | WG | Nooseneck Hill Rd. | 8 | Asbestos Cement | 127 | 54 | 1.14 out of 5 | $442 | 56,341 |
| Distribution Main | 7143 | P-3038 | WG | Nooseneck Hill Rd. | 8 | Asbestos Cement | 790 | 54 | 1.14 out of 5 | $442 | 349,254 |
| Distribution Main | 7146 | P-3044 | WG | Nooseneck Hill Rd. | 8 | Asbestos Cement | 140 | 54 | 1.14 out of 5 | $442 | 62,052 |
| Transmission Main | 7543 | P-3038 | WG | Nooseneck Hill Rd. | 12 | Asbestos Cement | 26 | 54 | 1.14 out of 5 | $442 | 11,285 |
| Distribution Main | 9437 | P-3044 | WG | Nooseneck Hill Rd. | 8 | Asbestos Cement | 299 | 54 | 1.14 out of 5 | $442 | 132,013 |
| Distribution Main | 7657 | P-3024 | WG | Old Hickory Rd. | 8 | Ductile Iron | 809 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7658 | P-3024 | WG | Old Hickory Rd. | 8 | Ductile Iron | 894 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9684 | P-3026 | WG | Old Hickory Rd. | 8 | Ductile Iron | 52 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5234 | P-7455 | WG | Pine Hill Rd. | 8 | Ductile Iron | 23 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7573 | P-7454 | WG | Pine Hill Rd. | 8 | Ductile Iron | 114 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7576 | P-7454 | WG | Pine Hill Rd. | 8 | Ductile Iron | 3 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7577 | P-7455 | WG | Pine Hill Rd. | 8 | Ductile Iron | 128 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7578 | P-7455 | WG | Pine Hill Rd. | 8 | Ductile Iron | 31 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7579 | P-7455 | WG | Pine Hill Rd. | 8 | Ductile Iron | 4 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7646 | | WG | Pine Hill Rd. | 8 | Ductile Iron | 4 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7650 | P-7455 | WG | Pine Hill Rd. | 8 | Ductile Iron | 4 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7558 | P-3032 | WG | Pine Tree Ln. | 8 | Asbestos Cement | 100 | 48 | 1.14 out of 5 | $442 | 44,223 |
| Distribution Main | 7559 | P-3032 | WG | Pine Tree Ln. | 8 | Asbestos Cement | 853 | 48 | 1.14 out of 5 | $442 | 377,117 |
| Distribution Main | 7684 | P-3028 | WG | Pine Tree Ln. | 8 | Asbestos Cement | 874 | 48 | 1.14 out of 5 | $442 | 386,454 |
| Distribution Main | 10229 | P-3032 | WG | Pine Tree Ln. | 8 | Ductile Iron | 26 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7580 | P-3000 | WG | Pinehill Rd. | 8 | Ductile Iron | 174 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7682 | P-3030 | WG | Pond View Ct. | 6 | Asbestos Cement | 671 | 43 | 1.85 out of 5 | $442 | 296,764 |
| Distribution Main | 7683 | P-3030 | WG | Pond View Ct. | 6 | Asbestos Cement | 47 | 43 | 1.85 out of 5 | $442 | 20,611 |
| Distribution Main | 7664 | P-3035 | WG | Ragnell Rd. | 6 | Asbestos Cement | 11 | 43 | 1.85 out of 5 | $442 | 4,784 |
| Distribution Main | 7665 | P-3035 | WG | Ragnell Rd. | 6 | Asbestos Cement | 450 | 43 | 1.85 out of 5 | $442 | 198,978 |
| Distribution Main | 10686 | P-3035 | WG | Ragnell Rd. | 2 | Copper | 137 | 43 | 2.28 out of 5 | $442 | 60,769 |
| Distribution Main | 7643 | P-3064 | WG | Roland Dr. | 8 | Asbestos Cement | 617 | 48 | 1.14 out of 5 | $442 | 272,695 |
| Distribution Main | 7644 | P-3064 | WG | Roland Dr. | 8 | Asbestos Cement | 683 | 48 | 1.14 out of 5 | $442 | 301,936 |
| Distribution Main | 11982 | P-3064 | WG | Roland Dr. | 8 | Asbestos Cement | 322 | 48 | 1.14 out of 5 | $442 | 142,111 |
| Distribution Main | 7647 | P-3015 | WG | Seminole Tr. | 8 | Asbestos Cement | 206 | 48 | 1.14 out of 5 | $442 | 91,124 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 7648 | P-3015 | WG | Seminole Tr. | 8 | Asbestos Cement | 318 | 48 | 1.14 out of 5 | $442 | 140,591 |
| Distribution Main | 7666 | P-3013 | WG | Seminole Tr. | 8 | Asbestos Cement | 340 | 48 | 1.14 out of 5 | $442 | 150,080 |
| Transmission Main | 68 | P-3051 | WG | Technology Park Tank | 16 | Ductile Iron | 265 | 31 | 0.14 out of 5 | $442 | 117,221 |
| Transmission Main | 65 | P-3132 | WG | Technology Way | 16 | Ductile Iron | 653 | 31 | 0.14 out of 5 | $442 | 288,448 |
| Transmission Main | 2982 | P-3050 | WG | Technology Way | 16 | Ductile Iron | 483 | 31 | 0.14 out of 5 | $442 | 213,330 |
| Transmission Main | 2983 | P-3050 | WG | Technology Way | 16 | Ductile Iron | 360 | 31 | 0.14 out of 5 | $442 | 159,280 |
| Transmission Main | 7623 | | WG | Technology Way | 12 | Unknown | 2 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 9131 | | WG | Technology Way | 6 | Ductile Iron | 54 | 8 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 9501 | P-3100 | WG | Technology Way | 16 | Ductile Iron | 108 | 31 | 0.14 out of 5 | $442 | 47,940 |
| Transmission Main | 9502 | P-3100 | WG | Technology Way | 16 | Ductile Iron | 1,103 | 31 | 0.14 out of 5 | $442 | 487,450 |
| Transmission Main | 9896 | P-3132 | WG | Technology Way | 16 | Ductile Iron | 74 | 31 | 0.14 out of 5 | $442 | 32,843 |
| Transmission Main | 9979 | P-3100 | WG | Technology Way | 16 | Ductile Iron | 76 | 31 | 0.14 out of 5 | $442 | 33,683 |
| Transmission Main | 9980 | P-3100 | WG | Technology Way | 16 | Ductile Iron | 334 | 31 | 0.14 out of 5 | $442 | 147,731 |
| Transmission Main | 11013 | P-3132 | WG | Technology Way | 16 | Ductile Iron | 372 | 31 | 0.14 out of 5 | $442 | 164,225 |
| Transmission Main | 11621 | P-3065 | WG | Technology Way | 16 | Ductile Iron | 23 | 31 | 0.14 out of 5 | $442 | 9,989 |
| Transmission Main | 11986 | P-3050 | WG | Technology Way | 16 | Ductile Iron | 42 | 31 | 0.14 out of 5 | $442 | 18,365 |
| Transmission Main | 12213 | P-3050 | WG | Technology Way | 16 | Ductile Iron | 447 | 31 | 0.14 out of 5 | $442 | 197,625 |
| Distribution Main | 3687 | | WG | Terrace Dr | 8 | Ductile Iron | 7 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3688 | | WG | Terrace Dr | 8 | Ductile Iron | 50 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8087 | P-3084 | WG | Tiffany Ln | 8 | Ductile Iron | 647 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 7144 | P-3041 | WG | Valerie Dr. | 8 | Asbestos Cement | 436 | 54 | 1.14 out of 5 | $442 | 192,585 |
| Distribution Main | 7145 | P-3041 | WG | Valerie Dr. | 8 | Asbestos Cement | 58 | 50 | 1.14 out of 5 | $442 | 25,556 |
| Distribution Main | 7555 | P-3039 | WG | Valerie Dr. | 8 | Ductile Iron | 6 | 29 | 0.14 out of 5 | $442 | 2,686 |
| Transmission Main | 7 | P-8424 | WG | Welgen - 95 Easement | 16 | Ductile Iron | 245 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 8 | P-8424 | WG | Welgen - 95 Easement | 16 | Ductile Iron | 49 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 51 | P-3052 | WG | Welgen - 95 Easement | 16 | Ductile Iron | 2,480 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 52 | P-3052 | WG | Welgen - 95 Easement | 16 | Ductile Iron | 531 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 53 | P-3052 | WG | Welgen - 95 Easement | 16 | Ductile Iron | 1,025 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 54 | P-3052 | WG | Welgen - 95 Easement | 16 | Ductile Iron | 108 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 55 | P-3052 | WG | Welgen - 95 Easement | 16 | Ductile Iron | 55 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 56 | P-3052 | WG | Welgen - 95 Easement | 16 | Ductile Iron | 257 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 57 | P-3052 | WG | Welgen - 95 Easement | 16 | Ductile Iron | 153 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 58 | P-3052 | WG | Welgen - 95 Easement | 16 | Ductile Iron | 106 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 59 | P-3052 | WG | Welgen - 95 Easement | 16 | Ductile Iron | 131 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1631 | P-3052 | WG | Welgen - 95 Easement | 16 | Ductile Iron | 101 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2189 | P-3052 | WG | Welgen - 95 Easement | 16 | Ductile Iron | 164 | 24 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11161 | P-3052 | WG | Welgen - 95 Easement | 16 | Ductile Iron | 105 | 24 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3093 | P-1830 | WW | Aberdeen St | 6 | Cast Iron | 349 | 97 | 2.43 out of 5 | $442 | 154,044 |
| Distribution Main | 3504 | P-971 | WW | Aberdeen St | 6 | Cast Iron | 759 | 97 | 2.43 out of 5 | $442 | 335,479 |
| Distribution Main | 3505 | P-971 | WW | Aberdeen St | 6 | Cast Iron | 46 | 97 | 2.43 out of 5 | $442 | 20,322 |
| Distribution Main | 8407 | P-1677 | WW | Aberdeen St | 8 | Ductile Iron | 353 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8408 | P-1677 | WW | Aberdeen St | 8 | Ductile Iron | 11 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8477 | P-1831 | WW | Aberdeen St | 6 | Ductile Iron | 35 | 10 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 8478 | P-970 | WW | Aberdeen St | 12 | Ductile Iron | 4 | 10 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 8479 | P-970 | WW | Aberdeen St | 12 | Ductile Iron | 140 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8480 | P-1829 | WW | Aberdeen St | 6 | Ductile Iron | 7 | 10 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 9672 | P-1828 | WW | Aberdeen St | 12 | Ductile Iron | 5 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 471 | | WW | Acorn La | 8 | Asbestos Cement | 9 | 46 | 1.14 out of 5 | $442 | 3,961 |
| Distribution Main | 1832 | P-52 | WW | Acorn La | 8 | Asbestos Cement | 359 | 46 | 1.14 out of 5 | $442 | 158,461 |
| Distribution Main | 2179 | P-55 | WW | Acorn La | 8 | Asbestos Cement | 548 | 46 | 1.14 out of 5 | $442 | 242,043 |
| Distribution Main | 2180 | P-55 | WW | Acorn La | 8 | Asbestos Cement | 505 | 46 | 1.14 out of 5 | $442 | 223,401 |
| Distribution Main | 3559 | P-53 | WW | Acorn La | 8 | Asbestos Cement | 186 | 46 | 1.14 out of 5 | $442 | 82,080 |
| Distribution Main | 3560 | P-53 | WW | Acorn La | 8 | Asbestos Cement | 37 | 46 | 1.14 out of 5 | $442 | 16,424 |
| Distribution Main | 4632 | P-54 | WW | Acorn La | 8 | Asbestos Cement | 208 | 46 | 1.14 out of 5 | $442 | 91,853 |
| Distribution Main | 4635 | P-54 | WW | Acorn La | 8 | Asbestos Cement | 43 | 46 | 1.14 out of 5 | $442 | 19,076 |
| Distribution Main | 4641 | P-53 | WW | Acorn La | 8 | Asbestos Cement | 27 | 46 | 1.14 out of 5 | $442 | 11,951 |
| Distribution Main | 11160 | P-54 | WW | Acorn La | 8 | Asbestos Cement | 20 | 46 | 1.14 out of 5 | $442 | 8,695 |
| Transmission Main | 1077 | P-1275 | WW | Acorn Ln | 12 | Ductile Iron | 627 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10147 | P-1458 | WW | Acorn Ln | 8 | Ductile Iron | 16 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10148 | P-1458 | WW | Acorn Ln | 8 | Ductile Iron | 10 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3674 | P-710 | WW | Agnes St | 6 | Cast Iron | 7 | 109 | 2.57 out of 5 | $442 | 2,912 |
| Distribution Main | 3783 | P-710 | WW | Agnes St | 6 | Cast Iron | 399 | 109 | 2.57 out of 5 | $442 | 176,154 |
| Distribution Main | 3522 | P-1909 | WW | Agnews Court | 6 | PVC | 148 | 38 | 1.14 out of 5 | $442 | 65,247 |
| Distribution Main | 3887 | | WW | Albion St | 6 | Asbestos Cement | 32 | 70 | 2 out of 5 | $442 | 13,986 |
| Distribution Main | 3888 | P-539 | WW | Albion St | 6 | Asbestos Cement | 419 | 70 | 2 out of 5 | $442 | 185,260 |
| Distribution Main | 5128 | P-539 | WW | Albion St | 6 | Asbestos Cement | 7 | 70 | 2 out of 5 | $442 | 3,178 |
| Distribution Main | 3585 | P-1733 | WW | Alden Dr | 8 | Ductile Iron | 18 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8912 | P-219 | WW | Alden Dr | 8 | Ductile Iron | 236 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8913 | P-1732 | WW | Alden Dr | 8 | Ductile Iron | 445 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8914 | P-1732 | WW | Alden Dr | 8 | Ductile Iron | 13 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8950 | P-1747 | WW | Alden Dr | 8 | Ductile Iron | 131 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8952 | P-203 | WW | Alden Dr | 8 | Ductile Iron | 388 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8953 | P-1743 | WW | Alden Dr | 8 | Ductile Iron | 26 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8959 | P-199 | WW | Alden Dr | 8 | Ductile Iron | 309 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9397 | P-202 | WW | Alden Dr | 8 | Ductile Iron | 136 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9400 | P-1733 | WW | Alden Dr | 8 | Ductile Iron | 22 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9401 | P-1733 | WW | Alden Dr | 8 | Ductile Iron | 5 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10929 | P-201 | WW | Alden Dr | 8 | Ductile Iron | 93 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10930 | P-201 | WW | Alden Dr | 8 | Ductile Iron | 25 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10931 | P-1747 | WW | Alden Dr | 8 | Ductile Iron | 110 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11529 | P-1743 | WW | Alden Dr | 8 | Ductile Iron | 87 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9733 | P-600 | WW | Aldrich St | 8 | Ductile Iron | 10 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9762 | P-600 | WW | Aldrich St | 8 | Ductile Iron | 422 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9763 | P-600 | WW | Aldrich St | 8 | Ductile Iron | 38 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9775 | P-1962 | WW | Aldrich St | 8 | Ductile Iron | 624 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11601 | P-1962 | WW | Aldrich St | 8 | Ductile Iron | 47 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 945 | P-9067 | WW | Alex St | 1 | Copper | 209 | 66 | 2.43 out of 5 | $442 | 92,532 |
| Transmission Main | 1201 | P-837 | WW | Alexander Dr | 12 | Ductile Iron | 286 | 18 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 1205 | P-837 | WW | Alexander Dr | 12 | Ductile Iron | 4 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1550 | P-836 | WW | Alexander Dr | 12 | Ductile Iron | 391 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1551 | P-836 | WW | Alexander Dr | 12 | Ductile Iron | 87 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1781 | P-836 | WW | Alexander Dr | 12 | Ductile Iron | 4 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12047 | P-836 | WW | Alexander Dr | 12 | Ductile Iron | 169 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8402 | P-972 | WW | Alpine St | 12 | Ductile Iron | 172 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8403 | P-972 | WW | Alpine St | 12 | Ductile Iron | 33 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8472 | P-974 | WW | Alpine St | 12 | Ductile Iron | 210 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8474 | P-1834 | WW | Alpine St | 12 | Ductile Iron | 34 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8527 | P-1228 | WW | Ames St | 16 | Ductile Iron | 149 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8528 | P-1228 | WW | Ames St | 16 | Ductile Iron | 232 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8529 | P-1924 | WW | Ames St | 12 | Ductile Iron | 21 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8984 | P-1211 | WW | Ames St | 16 | Ductile Iron | 74 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8985 | P-1612 | WW | Ames St | 12 | Ductile Iron | 50 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11042 | P-1228 | WW | Ames St | 16 | Ductile Iron | 22 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2961 | P-1720 | WW | Anderson Ave | 8 | Ductile Iron | 9 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2963 | P-82 | WW | Anderson Ave | 6 | Asbestos Cement | 117 | 78 | 2 out of 5 | $442 | 51,792 |
| Distribution Main | 2965 | P-82 | WW | Anderson Ave | 8 | Ductile Iron | 28 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6555 | P-102 | WW | Anderson Ave | 6 | Asbestos Cement | 173 | 78 | 2 out of 5 | $442 | 76,625 |
| Distribution Main | 6556 | P-102 | WW | Anderson Ave | 6 | Asbestos Cement | 48 | 78 | 2 out of 5 | $442 | 21,225 |
| Distribution Main | 8158 | P-82 | WW | Anderson Ave | 6 | Asbestos Cement | 48 | 78 | 2 out of 5 | $442 | 21,090 |
| Distribution Main | 9377 | P-82 | WW | Anderson Ave | 6 | Ductile Iron | 3 | 15 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 34 | P-693 | WW | Andrews Ave | 2 | Galvanized Iron | 844 | 109 | 3.57 out of 5 | $442 | 372,918 |
| Distribution Main | 132 | | WW | Andrews Ave | 6 | Cast Iron | 23 | 133 | 2.57 out of 5 | $442 | 10,383 |
| Distribution Main | 346 | P-1947 | WW | Andrews Ave | 6 | Cast Iron | 322 | 133 | 2.57 out of 5 | $442 | 142,383 |
| Distribution Main | 347 | P-1947 | WW | Andrews Ave | 6 | Cast Iron | 19 | 133 | 2.57 out of 5 | $442 | 8,554 |
| Distribution Main | 1608 | P-693 | WW | Andrews Ave | 2 | Galvanized Iron | 20 | 109 | 3.57 out of 5 | $442 | 8,832 |
| Distribution Main | 1609 | P-693 | WW | Andrews Ave | 2 | Galvanized Iron | 12 | 109 | 3.57 out of 5 | $442 | 5,243 |
| Distribution Main | 3258 | P-1951 | WW | Andrews Ave | 6 | Cast Iron | 235 | 89 | 2.43 out of 5 | $442 | 104,061 |
| Distribution Main | 3259 | P-1951 | WW | Andrews Ave | 6 | Cast Iron | 441 | 89 | 2.43 out of 5 | $442 | 194,928 |
| Distribution Main | 3669 | P-1951 | WW | Andrews Ave | 6 | Cast Iron | 341 | 89 | 2.43 out of 5 | $442 | 150,918 |
| Distribution Main | 3786 | P-1951 | WW | Andrews Ave | 6 | Cast Iron | 283 | 89 | 2.43 out of 5 | $442 | 125,036 |
| Distribution Main | 3787 | P-715 | WW | Andrews Ave | 2 | Galvanized Iron | 267 | 89 | 4.14 out of 5 | $442 | 118,063 |
| Distribution Main | 9520 | P-691 | WW | Andrews Ave | 6 | Cast Iron | 291 | 133 | 2.57 out of 5 | $442 | 128,437 |
| Distribution Main | 11745 | P-1948 | WW | Andrews Ave | 6 | Cast Iron | 133 | 133 | 2.57 out of 5 | $442 | 58,677 |
| Transmission Main | 3499 | P-837 | WW | Andrews Drive | 12 | Ductile Iron | 9 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3500 | P-837 | WW | Andrews Drive | 12 | Ductile Iron | 153 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9729 | P-936 | WW | Angell St | 6 | Ductile Iron | 29 | 22 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 10353 | P-919 | WW | Angell St | 8 | Ductile Iron | 1 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1792 | P-1853 | WW | Angell St. | 2 | Galvanized Iron | 237 | 91 | 3.43 out of 5 | $442 | 104,655 |
| Distribution Main | 1794 | P-937 | WW | Angell St. | 2 | Galvanized Iron | 261 | 91 | 4.14 out of 5 | $442 | 115,312 |
| Distribution Main | 3487 | P-936 | WW | Angell St. | 6 | Asbestos Cement | 25 | 42 | 2.57 out of 5 | $442 | 10,887 |
| Distribution Main | 3488 | P-936 | WW | Angell St. | 6 | Asbestos Cement | 411 | 42 | 1.85 out of 5 | $442 | 181,677 |
| Distribution Main | 3728 | P-936 | WW | Angell St. | 6 | Asbestos Cement | 8 | 42 | 1.85 out of 5 | $442 | 3,452 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9656 | P-1852 | WW | Angell St. | 2 | Galvanized Iron | 159 | 91 | 3.43 out of 5 | $442 | 70,343 |
| Distribution Main | 11222 | P-936 | WW | Angell St. | 6 | Asbestos Cement | 4 | 42 | 1.85 out of 5 | $442 | 1,650 |
| Distribution Main | 9905 | P-1945 | WW | April Ct | 8 | Ductile Iron | 195 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9906 | P-1945 | WW | April Ct | 8 | Ductile Iron | 20 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12118 | P-1945 | WW | April Ct | 8 | Ductile Iron | 7 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8176 | P-1512 | WW | Arcadia Rd | 8 | Ductile Iron | 360 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8177 | P-1512 | WW | Arcadia Rd | 8 | Ductile Iron | 207 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9648 | | WW | Archambault Ave | 6 | Ductile Iron | 5 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10004 | | WW | Archambault Ave | 2 | Copper | 195 | 83 | 2.57 out of 5 | $442 | 86,059 |
| Transmission Main | 160 | P-1624 | WW | Archambault Ave. | 12 | Asbestos Cement | 151 | 78 | 1.29 out of 5 | $442 | 66,633 |
| Transmission Main | 161 | P-1624 | WW | Archambault Ave. | 12 | Asbestos Cement | 52 | 78 | 1.29 out of 5 | $442 | 22,944 |
| Distribution Main | 323 | P-1047 | WW | Archambault Ave. | 6 | Cast Iron | 90 | 132 | 2.57 out of 5 | $442 | 39,622 |
| Transmission Main | 868 | P-726 | WW | Archambault Ave. | 12 | Asbestos Cement | 25 | 78 | 1.29 out of 5 | $442 | 10,910 |
| Distribution Main | 1068 | | WW | Archambault Ave. | 6 | Cast Iron | 8 | 132 | 2.57 out of 5 | $442 | 3,384 |
| Distribution Main | 1572 | P-745 | WW | Archambault Ave. | 6 | Cast Iron | 214 | 79 | 2.28 out of 5 | $442 | 94,550 |
| Distribution Main | 1877 | P-1046 | WW | Archambault Ave. | 6 | Cast Iron | 321 | 132 | 2.57 out of 5 | $442 | 141,806 |
| Distribution Main | 1878 | P-1046 | WW | Archambault Ave. | 6 | Cast Iron | 23 | 132 | 2.57 out of 5 | $442 | 10,288 |
| Distribution Main | 1881 | P-1047 | WW | Archambault Ave. | 6 | Cast Iron | 3 | 132 | 2.57 out of 5 | $442 | 1,339 |
| Transmission Main | 1883 | P-1050 | WW | Archambault Ave. | 12 | Asbestos Cement | 224 | 78 | 1.29 out of 5 | $442 | 98,929 |
| Distribution Main | 2386 | P-745 | WW | Archambault Ave. | 6 | Cast Iron | 24 | 79 | 2.28 out of 5 | $442 | 10,730 |
| Distribution Main | 2387 | P-1977 | WW | Archambault Ave. | 6 | Cast Iron | 42 | 79 | 2.28 out of 5 | $442 | 18,535 |
| Distribution Main | 2389 | | WW | Archambault Ave. | 6 | Cast Iron | 118 | 82 | 2.43 out of 5 | $442 | 52,210 |
| Transmission Main | 2487 | P-1979 | WW | Archambault Ave. | 12 | Asbestos Cement | 190 | 78 | 1.29 out of 5 | $442 | 83,894 |
| Transmission Main | 2488 | P-1979 | WW | Archambault Ave. | 12 | Asbestos Cement | 16 | 78 | 1.29 out of 5 | $442 | 7,125 |
| Transmission Main | 2491 | P-1675 | WW | Archambault Ave. | 12 | Asbestos Cement | 330 | 78 | 1.29 out of 5 | $442 | 146,009 |
| Transmission Main | 3130 | P-1314 | WW | Archambault Ave. | 12 | Asbestos Cement | 86 | 75 | 1.29 out of 5 | $442 | 38,129 |
| Transmission Main | 3131 | P-1049 | WW | Archambault Ave. | 12 | Asbestos Cement | 74 | 75 | 1.29 out of 5 | $442 | 32,814 |
| Transmission Main | 3244 | P-746 | WW | Archambault Ave. | 12 | Asbestos Cement | 313 | 78 | 1.29 out of 5 | $442 | 138,300 |
| Transmission Main | 3245 | P-746 | WW | Archambault Ave. | 12 | Asbestos Cement | 41 | 78 | 1.29 out of 5 | $442 | 18,250 |
| Transmission Main | 3251 | P-1049 | WW | Archambault Ave. | 12 | Asbestos Cement | 2 | 78 | 1.29 out of 5 | $442 | 1,003 |
| Transmission Main | 3252 | P-1049 | WW | Archambault Ave. | 12 | Asbestos Cement | 346 | 78 | 1.29 out of 5 | $442 | 153,038 |
| Transmission Main | 3773 | P-726 | WW | Archambault Ave. | 12 | Asbestos Cement | 384 | 78 | 1.29 out of 5 | $442 | 169,879 |
| Distribution Main | 3793 | | WW | Archambault Ave. | 6 | Cast Iron | 23 | 82 | 2.43 out of 5 | $442 | 9,955 |
| Transmission Main | 4287 | P-1314 | WW | Archambault Ave. | 12 | Asbestos Cement | 152 | 75 | 1.29 out of 5 | $442 | 67,392 |
| Transmission Main | 4289 | P-1338 | WW | Archambault Ave. | 12 | Asbestos Cement | 213 | 75 | 1.29 out of 5 | $442 | 94,002 |
| Transmission Main | 4290 | P-1338 | WW | Archambault Ave. | 12 | Asbestos Cement | 127 | 75 | 1.29 out of 5 | $442 | 56,028 |
| Distribution Main | 4291 | | WW | Archambault Ave. | 6 | Unknown | 4 | UNK | 0.71 out of 5 | $442 | 1,986 |
| Transmission Main | 11043 | P-1624 | WW | Archambault Ave. | 12 | Asbestos Cement | 14 | 78 | 1.29 out of 5 | $442 | 6,216 |
| Transmission Main | 11145 | P-1624 | WW | Archambault Ave. | 12 | Asbestos Cement | 4 | 78 | 1.29 out of 5 | $442 | 1,802 |
| Transmission Main | 11206 | P-746 | WW | Archambault Ave. | 12 | Asbestos Cement | 142 | 78 | 1.29 out of 5 | $442 | 62,932 |
| Transmission Main | 11250 | P-1314 | WW | Archambault Ave. | 12 | Asbestos Cement | 4 | 75 | 1.29 out of 5 | $442 | 1,766 |
| Transmission Main | 11993 | P-746 | WW | Archambault Ave. | 12 | Asbestos Cement | 39 | 78 | 1.29 out of 5 | $442 | 17,282 |
| Transmission Main | 12150 | P-746 | WW | Archambault Ave. | 12 | Asbestos Cement | 3 | 78 | 1.29 out of 5 | $442 | 1,510 |
| Distribution Main | 2435 | P-1388 | WW | Arrow Ct. | 6 | Ductile Iron | 213 | 28 | 0.85 out of 5 | $442 | 94,224 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2159 | P-579 | WW | Arthur St. | 2 | Galvanized Iron | 16 | 84 | 3.43 out of 5 | $442 | 6,897 |
| Distribution Main | 2392 | P-579 | WW | Arthur St. | 2 | Galvanized Iron | 538 | 84 | 3.43 out of 5 | $442 | 237,855 |
| Distribution Main | 2393 | P-579 | WW | Arthur St. | 2 | Galvanized Iron | 120 | 84 | 3.43 out of 5 | $442 | 53,095 |
| Distribution Main | 3111 | P-562 | WW | Arthur St. | 6 | Asbestos Cement | 11 | 79 | 2 out of 5 | $442 | 5,047 |
| Distribution Main | 3971 | P-562 | WW | Arthur St. | 6 | Asbestos Cement | 435 | 79 | 2 out of 5 | $442 | 192,478 |
| Distribution Main | 3972 | P-562 | WW | Arthur St. | 6 | Asbestos Cement | 28 | 79 | 2 out of 5 | $442 | 12,529 |
| Distribution Main | 3973 | P-571 | WW | Arthur St. | 6 | Asbestos Cement | 9 | 79 | 2 out of 5 | $442 | 4,143 |
| Distribution Main | 4306 | P-571 | WW | Arthur St. | 6 | Asbestos Cement | 7 | 79 | 2 out of 5 | $442 | 2,931 |
| Distribution Main | 4321 | P-562 | WW | Arthur St. | 6 | Asbestos Cement | 7 | 79 | 2 out of 5 | $442 | 3,204 |
| Distribution Main | 4332 | P-571 | WW | Arthur St. | 6 | Asbestos Cement | 325 | 79 | 2 out of 5 | $442 | 143,694 |
| Distribution Main | 5062 | P-579 | WW | Arthur St. | 2 | Galvanized Iron | 9 | 84 | 3.43 out of 5 | $442 | 4,052 |
| Distribution Main | 3890 | | WW | Ashton St. | 6 | PVC | 21 | 35 | 1.14 out of 5 | $442 | 9,082 |
| Distribution Main | 5110 | P-543 | WW | Ashton St. | 6 | PVC | 265 | 35 | 1.14 out of 5 | $442 | 117,013 |
| Distribution Main | 12024 | P-543 | WW | Ashton St. | 6 | PVC | 26 | 35 | 1.14 out of 5 | $442 | 11,675 |
| Distribution Main | 10731 | P-225 | WW | Aster St | 8 | Ductile Iron | 610 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10732 | P-226 | WW | Aster St | 8 | Ductile Iron | 181 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11714 | P-226 | WW | Aster St | 8 | Ductile Iron | 53 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 7131 | | WW | Aster St. | 6 | Asbestos Cement | 3 | 46 | 1.85 out of 5 | $442 | 1,454 |
| Distribution Main | 10119 | P-433 | WW | Atlantic Ave | 1 | Copper | 205 | UNK | 1.99 out of 5 | $442 | 90,784 |
| Distribution Main | 804 | P-433 | WW | Atlantic Ave. | 6 | Asbestos Cement | 13 | 53 | 1.85 out of 5 | $442 | 5,699 |
| Distribution Main | 805 | P-433 | WW | Atlantic Ave. | 6 | Asbestos Cement | 535 | 53 | 1.85 out of 5 | $442 | 236,473 |
| Distribution Main | 4438 | P-434 | WW | Atlantic Ave. | 6 | Asbestos Cement | 284 | 53 | 1.85 out of 5 | $442 | 125,632 |
| Distribution Main | 4439 | P-434 | WW | Atlantic Ave. | 6 | Asbestos Cement | 169 | 53 | 1.85 out of 5 | $442 | 74,682 |
| Distribution Main | 8406 | P-1832 | WW | Atwood St | 8 | Ductile Iron | 16 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8475 | P-1833 | WW | Atwood St | 6 | Ductile Iron | 5 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8476 | P-1833 | WW | Atwood St | 6 | Ductile Iron | 2 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9456 | P-1840 | WW | Atwood St | 1 | Unknown | 8 | UNK | 1.42 out of 5 | $442 | 3,529 |
| Distribution Main | 9457 | P-1840 | WW | Atwood St | 1 | Unknown | 244 | UNK | 1.42 out of 5 | $442 | 108,061 |
| Distribution Main | 3694 | P-973 | WW | Atwood St. | 6 | Asbestos Cement | 190 | 42 | 1.85 out of 5 | $442 | 84,002 |
| Distribution Main | 3695 | P-973 | WW | Atwood St. | 6 | Asbestos Cement | 487 | 42 | 1.85 out of 5 | $442 | 215,328 |
| Distribution Main | 10024 | P-1755 | WW | Auburn St | 8 | Ductile Iron | 204 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10025 | P-1755 | WW | Auburn St | 8 | Ductile Iron | 20 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10812 | P-282 | WW | Auburn St | 8 | Ductile Iron | 187 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3882 | P-449 | WW | Audrey Dr. | 6 | Asbestos Cement | 304 | 41 | 1.85 out of 5 | $442 | 134,154 |
| Distribution Main | 3883 | P-449 | WW | Audrey Dr. | 6 | Asbestos Cement | 212 | 41 | 1.85 out of 5 | $442 | 93,822 |
| Distribution Main | 1146 | P-300 | WW | Babcock St. | 8 | Asbestos Cement | 257 | 52 | 1.14 out of 5 | $442 | 113,592 |
| Distribution Main | 1147 | P-296 | WW | Babcock St. | 8 | Asbestos Cement | 221 | 52 | 1.14 out of 5 | $442 | 97,813 |
| Distribution Main | 1151 | P-298 | WW | Babcock St. | 8 | Asbestos Cement | 201 | 52 | 1.14 out of 5 | $442 | 88,742 |
| Distribution Main | 8706 | P-296 | WW | Babcock St. | 8 | Asbestos Cement | 86 | 52 | 1.14 out of 5 | $442 | 38,120 |
| Distribution Main | 1210 | P-681 | WW | Baker St. | 2 | Galvanized Iron | 33 | 119 | 3.57 out of 5 | $442 | 14,802 |
| Distribution Main | 3772 | P-1489 | WW | Baker St. | 2 | Galvanized Iron | 434 | 119 | 3.57 out of 5 | $442 | 191,935 |
| Distribution Main | 10017 | P-275 | WW | Ball Ave | 8 | Ductile Iron | 89 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10029 | P-275 | WW | Ball Ave | 8 | Ductile Iron | 196 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10030 | P-275 | WW | Ball Ave | 8 | Ductile Iron | 38 | 6 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 11630 | P-275 | WW | Ball Ave | 8 | Ductile Iron | 133 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11998 | P-275 | WW | Ball Ave | 8 | Ductile Iron | 53 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 608 | P-1052 | WW | Bank St. | 6 | Cast Iron | 23 | 129 | 2.57 out of 5 | $442 | 10,157 |
| Distribution Main | 9206 | P-1054 | WW | Bank St. | 8 | Ductile Iron | 248 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11554 | P-1981 | WW | Bank St. | 8 | Ductile Iron | 92 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10055 | P-250 | WW | Barbers Ct | 6 | Ductile Iron | 15 | 6 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 5206 | P-250 | WW | Barbers Ct. | 6 | Ductile Iron | 300 | 19 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 2851 | P-732 | WW | Barnes St. | 8 | Cast Iron | 100 | 83 | 1.72 out of 5 | $442 | 44,327 |
| Distribution Main | 3246 | P-744 | WW | Barnes St. | 8 | Cast Iron | 268 | 83 | 1.72 out of 5 | $442 | 118,293 |
| Distribution Main | 3800 | P-734 | WW | Barnes St. | 8 | Cast Iron | 14 | 83 | 1.72 out of 5 | $442 | 6,273 |
| Distribution Main | 3801 | P-734 | WW | Barnes St. | 8 | Cast Iron | 144 | 83 | 1.72 out of 5 | $442 | 63,612 |
| Distribution Main | 11190 | P-732 | WW | Barnes St. | 8 | Cast Iron | 79 | 83 | 2.43 out of 5 | $442 | 34,720 |
| Distribution Main | 11233 | P-734 | WW | Barnes St. | 8 | Cast Iron | 1 | 83 | 1.72 out of 5 | $442 | 613 |
| Distribution Main | 9764 | P-598 | WW | Barnold St | 8 | Ductile Iron | 387 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9778 | P-624 | WW | Barnold St | 8 | Ductile Iron | 556 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11602 | P-624 | WW | Barnold St | 8 | Ductile Iron | 109 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9734 | P-598 | WW | Barnold St. | 8 | Ductile Iron | 12 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4656 | P-504 | WW | Bayberry Dr. | 6 | Asbestos Cement | 3 | 55 | 1.85 out of 5 | $442 | 1,515 |
| Distribution Main | 4657 | P-504 | WW | Bayberry Dr. | 6 | Asbestos Cement | 740 | 55 | 1.85 out of 5 | $442 | 327,069 |
| Distribution Main | 3775 | P-698 | WW | Beauchene St. | 6 | Cast Iron | 22 | 131 | 2.57 out of 5 | $442 | 9,868 |
| Distribution Main | 3776 | P-698 | WW | Beauchene St. | 6 | Cast Iron | 205 | 131 | 2.57 out of 5 | $442 | 90,501 |
| Distribution Main | 10728 | P-229 | WW | Begonia St | 8 | Ductile Iron | 369 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10729 | P-229 | WW | Begonia St | 8 | Ductile Iron | 193 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10616 | P-405 | WW | Bel-Air Av | 8 | Ductile Iron | 212 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10617 | P-405 | WW | Bel-Air Av | 8 | Ductile Iron | 268 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3975 | P-575 | WW | Bell St. | 6 | Asbestos Cement | 461 | 44 | 1.85 out of 5 | $442 | 203,546 |
| Distribution Main | 4307 | P-575 | WW | Bell St. | 6 | Asbestos Cement | 11 | 44 | 1.85 out of 5 | $442 | 5,035 |
| Distribution Main | 2695 | P-8037 | WW | Bennett St. | 2 | Galvanized Iron | 300 | 119 | 3.57 out of 5 | $442 | 132,758 |
| Distribution Main | 2721 | P-9059 | WW | Bennett St. | 1 | Copper | 135 | 67 | 2.43 out of 5 | $442 | 59,494 |
| Distribution Main | 2724 | P-8037 | WW | Bennett St. | 2 | Galvanized Iron | 26 | 119 | 3.57 out of 5 | $442 | 11,363 |
| Distribution Main | 3127 | P-541 | WW | Berkeley St. | 2 | PVC | 159 | 35 | 1.85 out of 5 | $442 | 70,440 |
| Distribution Main | 3128 | P-541 | WW | Berkeley St. | 2 | PVC | 133 | 35 | 1.85 out of 5 | $442 | 58,918 |
| Distribution Main | 5126 | P-541 | WW | Berkeley St. | 2 | PVC | 23 | 35 | 1.85 out of 5 | $442 | 10,213 |
| Distribution Main | 3484 | P-938 | WW | Bettez St. | 4 | Cast Iron | 217 | 134 | 3.29 out of 5 | $442 | 96,084 |
| Distribution Main | 3485 | P-938 | WW | Bettez St. | 4 | Cast Iron | 327 | 134 | 3.29 out of 5 | $442 | 144,453 |
| Distribution Main | 3730 | P-938 | WW | Bettez St. | 4 | Cast Iron | 2 | 134 | 3.29 out of 5 | $442 | 880 |
| Distribution Main | 11760 | P-938 | WW | Bettez St. | 4 | Cast Iron | 247 | 134 | 3.29 out of 5 | $442 | 109,274 |
| Distribution Main | 1821 | P-151 | WW | Birchwood Ln | 8 | Asbestos Cement | 396 | 50 | 1.14 out of 5 | $442 | 175,087 |
| Distribution Main | 2216 | P-150 | WW | Birchwood Ln | 8 | Asbestos Cement | 123 | 50 | 1.14 out of 5 | $442 | 54,566 |
| Distribution Main | 2212 | P-141 | WW | Birchwood Ln. | 8 | Asbestos Cement | 365 | 50 | 1.14 out of 5 | $442 | 161,252 |
| Distribution Main | 4650 | P-148 | WW | Birchwood Ln. | 8 | Asbestos Cement | 61 | 50 | 1.14 out of 5 | $442 | 27,002 |
| Distribution Main | 4651 | P-148 | WW | Birchwood Ln. | 8 | Asbestos Cement | 4 | 50 | 1.14 out of 5 | $442 | 1,767 |
| Distribution Main | 10658 | | WW | Bishop St | 8 | Ductile Iron | 197 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10659 | P-373 | WW | Bishop St | 8 | Ductile Iron | 283 | 2 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 131 | P-1956 | WW | Blanchard St | 1 | Unknown | 15 | UNK | 1.42 out of 5 | $442 | 6,806 |
| Distribution Main | 3774 | P-1956 | WW | Blanchard St | 1 | Unknown | 84 | UNK | 1.42 out of 5 | $442 | 37,000 |
| Distribution Main | 174 | P-578 | WW | Bleach Ave | 6 | Cast Iron | 207 | 83 | 2.43 out of 5 | $442 | 91,648 |
| Distribution Main | 3105 | P-578 | WW | Bleach Ave | 8 | Ductile Iron | 13 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3106 | P-578 | WW | Bleach Ave | 8 | Ductile Iron | 11 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9370 | P-578 | WW | Bleach Ave | 6 | Ductile Iron | 5 | 14 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10015 | P-280 | WW | Blossom St | 8 | Ductile Iron | 179 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10019 | P-1754 | WW | Blossom St | 8 | Ductile Iron | 135 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10020 | P-1754 | WW | Blossom St | 8 | Ductile Iron | 133 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10811 | P-283 | WW | Blossom St | 8 | Ductile Iron | 406 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10813 | P-281 | WW | Blossom St | 8 | Ductile Iron | 236 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10791 | P-352 | WW | Border St | 8 | Ductile Iron | 407 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10792 | P-351 | WW | Border St | 8 | Ductile Iron | 601 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11732 | P-347 | WW | Border St | 8 | Ductile Iron | 236 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11733 | P-10068 | WW | Border St | 8 | Ductile Iron | 200 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12037 | P-10068 | WW | Border St | 8 | Ductile Iron | 166 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12038 | P-347 | WW | Border St | 8 | Ductile Iron | 210 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12041 | P-347 | WW | Border St | 8 | Ductile Iron | 157 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12201 | P-347 | WW | Border St | 8 | Ductile Iron | 144 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3672 | P-763 | WW | Bouchard St. | 6 | Asbestos Cement | 19 | 52 | 1.85 out of 5 | $442 | 8,377 |
| Distribution Main | 3785 | P-763 | WW | Bouchard St. | 6 | Asbestos Cement | 412 | 52 | 1.85 out of 5 | $442 | 182,202 |
| Distribution Main | 4824 | P-522 | WW | Boucher St. | 6 | Asbestos Cement | 12 | 51 | 1.85 out of 5 | $442 | 5,352 |
| Distribution Main | 4825 | P-522 | WW | Boucher St. | 6 | Asbestos Cement | 348 | 51 | 1.85 out of 5 | $442 | 153,969 |
| Distribution Main | 5095 | P-523 | WW | Boucher St. | 6 | Asbestos Cement | 214 | 51 | 1.85 out of 5 | $442 | 94,401 |
| Distribution Main | 10304 | P-1765 | WW | Bowen Ct | 6 | Ductile Iron | 160 | 25 | 0.85 out of 5 | N/A | $0 |
| Transmission Main | 7498 | P-265 | WW | Bowen Ct. | 12 | Ductile Iron | 126 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3096 | P-1660 | WW | Bradford Court | 6 | Asbestos Cement | 417 | 44 | 1.85 out of 5 | $442 | 184,252 |
| Distribution Main | 3525 | P-1661 | WW | Bradford Court | 6 | Asbestos Cement | 135 | 72 | 2.71 out of 5 | $442 | 59,540 |
| Distribution Main | 8386 | P-1660 | WW | Bradford Ct | 8 | Ductile Iron | 14 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8450 | P-1660 | WW | Bradford Ct | 6 | Ductile Iron | 5 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 3379 |  | WW | Bradley Court | 6 | Unknown | 158 | 79 | 1.14 out of 5 | $442 | 69,618 |
| Distribution Main | 9657 | P-1880 | WW | Bradley Ct | 1 | PVC | 93 | 28 | 1.85 out of 5 | $442 | 41,176 |
| Distribution Main | 289 | P-1287 | WW | Bradley Ct. | 6 | Cast Iron | 177 | 133 | 2.57 out of 5 | $442 | 78,410 |
| Distribution Main | 290 | P-1287 | WW | Bradley Ct. | 6 | Cast Iron | 54 | 133 | 2.57 out of 5 | $442 | 24,026 |
| Distribution Main | 4627 | P-59 | WW | Bramble Lane | 8 | Asbestos Cement | 665 | 46 | 1.14 out of 5 | $442 | 293,764 |
| Distribution Main | 4628 | P-59 | WW | Bramble Lane | 8 | Asbestos Cement | 521 | 46 | 1.14 out of 5 | $442 | 230,260 |
| Transmission Main | 464 | P-1372 | WW | Bratt Ln. | 12 | Ductile Iron | 616 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 465 |  | WW | Bratt Ln. | 8 | Ductile Iron | 12 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 983 | P-1372 | WW | Bratt Ln. | 12 | Ductile Iron | 413 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1833 | P-1376 | WW | Bratt Ln. | 8 | Asbestos Cement | 204 | 44 | 1.14 out of 5 | $442 | 90,068 |
| Distribution Main | 4642 | P-1371 | WW | Bratt Ln. | 8 | Asbestos Cement | 846 | 44 | 1.14 out of 5 | $442 | 373,786 |
| Distribution Main | 4643 | P-1371 | WW | Bratt Ln. | 8 | Asbestos Cement | 111 | 44 | 1.14 out of 5 | $442 | 48,933 |
| Transmission Main | 9500 | P-1372 | WW | Bratt Ln. | 12 | Ductile Iron | 217 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10164 | P-1371 | WW | Bratt Ln. | 8 | Asbestos Cement | 1 | 44 | 1.14 out of 5 | $442 | 383 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 11060 | P-1372 | WW | Bratt Ln. | 12 | Ductile Iron | 16 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11061 | P-1371 | WW | Bratt Ln. | 8 | Asbestos Cement | 6 | 44 | 1.14 out of 5 | $442 | 2,820 |
| Distribution Main | 12208 | P-1371 | WW | Bratt Ln. | 8 | Asbestos Cement | 70 | 44 | 1.14 out of 5 | $442 | 30,935 |
| Distribution Main | 10053 | P-278 | WW | Brayton Ave | 8 | Ductile Iron | 47 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1606 | P-1011 | WW | Brayton St. | 4 | Cast Iron | 261 | 134 | 3.29 out of 5 | $442 | 115,429 |
| Distribution Main | 1607 | P-1011 | WW | Brayton St. | 4 | Cast Iron | 462 | 134 | 3.29 out of 5 | $442 | 204,002 |
| Distribution Main | 4313 | P-548 | WW | Brewster Ave. | 6 | Cast Iron | 203 | 109 | 2.57 out of 5 | $442 | 89,811 |
| Distribution Main | 3432 | P-142 | WW | Brichwood Ln. | 8 | Asbestos Cement | 198 | 50 | 1.14 out of 5 | $442 | 87,635 |
| Distribution Main | 3433 | P-142 | WW | Brichwood Ln. | 8 | Asbestos Cement | 280 | 50 | 1.14 out of 5 | $442 | 123,666 |
| Distribution Main | 3988 | P-643 | WW | Bridal Ave. | 6 | Cast Iron | 169 | 97 | 2.43 out of 5 | $442 | 74,489 |
| Distribution Main | 3989 | P-645 | WW | Bridal Ave. | 6 | Cast Iron | 22 | 97 | 2.43 out of 5 | $442 | 9,583 |
| Distribution Main | 4006 | P-1614 | WW | Bridal Ave. | 6 | Cast Iron | 491 | 97 | 2.43 out of 5 | $442 | 216,890 |
| Distribution Main | 4007 | P-1614 | WW | Bridal Ave. | 6 | Cast Iron | 172 | 97 | 2.43 out of 5 | $442 | 76,163 |
| Distribution Main | 4326 | P-645 | WW | Bridal Ave. | 6 | Cast Iron | 96 | 97 | 2.43 out of 5 | $442 | 42,321 |
| Distribution Main | 9667 | P-1616 | WW | Bridal Ave. | 6 | Cast Iron | 71 | 97 | 2.43 out of 5 | $442 | 31,251 |
| Distribution Main | 9668 | P-1616 | WW | Bridal Ave. | 6 | Cast Iron | 37 | 97 | 2.43 out of 5 | $442 | 16,315 |
| Distribution Main | 12031 | | WW | Bridal Ave. | 6 | Cast Iron | 54 | UNK | 1.85 out of 5 | $442 | 23,850 |
| Distribution Main | 12032 | P-643 | WW | Bridal Ave. | 6 | Cast Iron | 3 | 97 | 2.43 out of 5 | $442 | 1,391 |
| Distribution Main | 12033 | P-1616 | WW | Bridal Ave. | 6 | Cast Iron | 4 | 97 | 2.43 out of 5 | $442 | 1,781 |
| Distribution Main | 431 | P-1017 | WW | Bridge St. | 6 | Cast Iron | 264 | 84 | 2.43 out of 5 | $442 | 116,873 |
| Distribution Main | 438 | P-997 | WW | Bridge St. | 4 | Cast Iron | 97 | 84 | 3.14 out of 5 | $442 | 42,989 |
| Distribution Main | 439 | P-1003 | WW | Bridge St. | 6 | Cast Iron | 12 | 84 | 2.43 out of 5 | $442 | 5,485 |
| Distribution Main | 1601 | P-997 | WW | Bridge St. | 4 | Cast Iron | 22 | 84 | 3.14 out of 5 | $442 | 9,616 |
| Distribution Main | 3328 | P-997 | WW | Bridge St. | 4 | Cast Iron | 432 | 84 | 3.14 out of 5 | $442 | 190,989 |
| Distribution Main | 3329 | P-997 | WW | Bridge St. | 4 | Cast Iron | 412 | 84 | 3.14 out of 5 | $442 | 181,933 |
| Distribution Main | 3336 | P-1003 | WW | Bridge St. | 6 | Cast Iron | 7 | 84 | 2.43 out of 5 | $442 | 3,125 |
| Distribution Main | 3349 | P-1017 | WW | Bridge St. | 6 | Cast Iron | 24 | 84 | 2.43 out of 5 | $442 | 10,518 |
| Distribution Main | 3363 | P-1002 | WW | Bridge St. | 6 | Cast Iron | 63 | 84 | 2.43 out of 5 | $442 | 27,693 |
| Distribution Main | 3364 | P-1002 | WW | Bridge St. | 6 | Cast Iron | 574 | 84 | 2.43 out of 5 | $442 | 253,809 |
| Distribution Main | 4137 | P-1192 | WW | Brisas Dr. | 6 | Asbestos Cement | 171 | 49 | 1.85 out of 5 | $442 | 75,421 |
| Distribution Main | 5160 | P-1192 | WW | Brisas Dr. | 6 | Asbestos Cement | 19 | 49 | 1.85 out of 5 | $442 | 8,216 |
| Transmission Main | 8387 | P-1910 | WW | Broad St | 12 | Ductile Iron | 6 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8388 | P-1910 | WW | Broad St | 12 | Ductile Iron | 340 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8456 | P-1910 | WW | Broad St | 12 | Ductile Iron | 32 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8424 | P-1816 | WW | Brook St | 8 | Ductile Iron | 19 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3196 | P-948 | WW | Brook St. | 6 | Ductile Iron | 353 | 27 | 0.85 out of 5 | $442 | 156,062 |
| Distribution Main | 3495 | P-948 | WW | Brook St. | 6 | Ductile Iron | 41 | 27 | 0.85 out of 5 | $442 | 18,223 |
| Distribution Main | 9455 | P-1817 | WW | Brook St. | 2 | Unknown | 220 | 27 | 1.57 out of 5 | $442 | 97,289 |
| Distribution Main | 8960 | P-203 | WW | Brookdale Dr | 8 | Ductile Iron | 10 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8961 | P-203 | WW | Brookdale Dr | 8 | Ductile Iron | 3 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8966 | P-203 | WW | Brookdale Dr | 6 | Ductile Iron | 6 | 9 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 4389 | | WW | Brookdale Dr. | 6 | Asbestos Cement | 18 | 62 | 2 out of 5 | $442 | 8,006 |
| Distribution Main | 4935 | P-203 | WW | Brookdale Dr. | 6 | Asbestos Cement | 707 | 62 | 2 out of 5 | $442 | 312,574 |
| Distribution Main | 4949 | P-203 | WW | Brookdale Dr. | 8 | Asbestos Cement | 47 | 62 | 1.29 out of 5 | $442 | 20,948 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 7482 | P-203 | WW | Brookdale Dr. | 8 | Asbestos Cement | 12 | 62 | 1.29 out of 5 | $442 | 5,200 |
| Distribution Main | 9614 | P-1793 | WW | Brookfield Dr | 1 | Copper | 118 | 64 | 2.43 out of 5 | $442 | 52,116 |
| Distribution Main | 1527 | | WW | Brookfield Dr. | 6 | Asbestos Cement | 9 | 47 | 1.85 out of 5 | $442 | 3,864 |
| Distribution Main | 1532 | P-1792 | WW | Brookfield Dr. | 6 | Ductile Iron | 63 | 22 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 3193 | P-848 | WW | Brookfield Dr. | 6 | Asbestos Cement | 141 | 47 | 2 out of 5 | $442 | 62,150 |
| Distribution Main | 3194 | | WW | Brookfield Dr. | 6 | Asbestos Cement | 143 | 47 | 1.85 out of 5 | $442 | 63,175 |
| Distribution Main | 12071 | P-1792 | WW | Brookfield Dr. | 6 | Ductile Iron | 7 | 22 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 134 | P-672 | WW | Brookside Ave. | 8 | Cast Iron | 35 | 97 | 1.72 out of 5 | $442 | 15,278 |
| Distribution Main | 2280 | P-702 | WW | Brookside Ave. | 8 | Ductile Iron | 136 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2281 | P-702 | WW | Brookside Ave. | 8 | Ductile Iron | 69 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2282 | P-672 | WW | Brookside Ave. | 8 | Cast Iron | 184 | 97 | 1.72 out of 5 | $442 | 81,399 |
| Distribution Main | 2887 | P-653 | WW | Brookside Ave. | 8 | Cast Iron | 37 | 134 | 1.86 out of 5 | $442 | 16,506 |
| Distribution Main | 2899 | P-655 | WW | Brookside Ave. | 8 | Cast Iron | 728 | 134 | 1.86 out of 5 | $442 | 321,916 |
| Distribution Main | 2900 | P-655 | WW | Brookside Ave. | 8 | Cast Iron | 56 | 134 | 1.86 out of 5 | $442 | 24,750 |
| Distribution Main | 3768 | P-664 | WW | Brookside Ave. | 10 | Cast Iron | 189 | 134 | 1.86 out of 5 | $442 | 83,443 |
| Distribution Main | 3769 | P-664 | WW | Brookside Ave. | 10 | Cast Iron | 312 | 134 | 1.86 out of 5 | $442 | 138,095 |
| Distribution Main | 3781 | P-701 | WW | Brookside Ave. | 8 | Cast Iron | 344 | 97 | 1.72 out of 5 | $442 | 152,129 |
| Distribution Main | 3782 | P-701 | WW | Brookside Ave. | 8 | Cast Iron | 12 | 97 | 1.72 out of 5 | $442 | 5,418 |
| Distribution Main | 3985 | P-655 | WW | Brookside Ave. | 8 | Cast Iron | 14 | 134 | 1.86 out of 5 | $442 | 6,059 |
| Distribution Main | 3986 | P-653 | WW | Brookside Ave. | 8 | Cast Iron | 484 | 134 | 1.86 out of 5 | $442 | 214,000 |
| Distribution Main | 3987 | P-653 | WW | Brookside Ave. | 8 | Cast Iron | 224 | 134 | 1.86 out of 5 | $442 | 99,196 |
| Distribution Main | 4703 | | WW | Brown St | 6 | Unknown | 365 | UNK | 0.71 out of 5 | $442 | 161,508 |
| Distribution Main | 4704 | | WW | Brown St | 6 | Unknown | 11 | UNK | 0.71 out of 5 | $442 | 5,080 |
| Distribution Main | 12015 | | WW | Brown St | 6 | Unknown | 3 | UNK | 0.71 out of 5 | $442 | 1,394 |
| Distribution Main | 9794 | P-637 | WW | Bryant Pl | 8 | Ductile Iron | 176 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9795 | P-637 | WW | Bryant Pl | 8 | Ductile Iron | 57 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9798 | P-637 | WW | Bryant Pl | 8 | Ductile Iron | 203 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3114 | P-521 | WW | Buckley Ave. | 6 | Asbestos Cement | 220 | 65 | 2 out of 5 | $442 | 97,084 |
| Distribution Main | 5096 | P-520 | WW | Buckley Ave. | 6 | Asbestos Cement | 248 | 65 | 2 out of 5 | $442 | 109,477 |
| Distribution Main | 5097 | P-520 | WW | Buckley Ave. | 6 | Asbestos Cement | 23 | 65 | 2 out of 5 | $442 | 10,264 |
| Distribution Main | 8428 | P-898 | WW | Buehler Dr | 8 | Ductile Iron | 30 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8499 | P-898 | WW | Buehler Dr | 6 | Ductile Iron | 12 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 481 | P-1795 | WW | Buehler Dr. | 6 | Asbestos Cement | 181 | 66 | 2 out of 5 | $442 | 80,071 |
| Distribution Main | 1007 | P-897 | WW | Buehler Dr. | 6 | Asbestos Cement | 241 | 66 | 2 out of 5 | $442 | 106,657 |
| Distribution Main | 11064 | P-1795 | WW | Buehler Dr. | 6 | Asbestos Cement | 27 | 66 | 2 out of 5 | $442 | 12,127 |
| Distribution Main | 8435 | P-1794 | WW | Bueller Dr | 6 | Ductile Iron | 17 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8436 | P-1794 | WW | Bueller Dr | 6 | Ductile Iron | 2 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9416 | P-1794 | WW | Bueller Dr | 8 | Ductile Iron | 4 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1408 | P-686 | WW | Burlingame Rd. | 8 | PVC | 191 | 38 | 0.43 out of 5 | $442 | 84,309 |
| Distribution Main | 1409 | P-686 | WW | Burlingame Rd. | 8 | PVC | 273 | 38 | 0.43 out of 5 | $442 | 120,487 |
| Distribution Main | 1553 | P-1786 | WW | Burlingame Rd. | 8 | PVC | 21 | 38 | 0.43 out of 5 | $442 | 9,299 |
| Distribution Main | 3188 | P-1786 | WW | Burlingame Rd. | 8 | PVC | 688 | 38 | 0.43 out of 5 | $442 | 304,172 |
| Distribution Main | 3189 | P-1786 | WW | Burlingame Rd. | 8 | PVC | 745 | 38 | 0.43 out of 5 | $442 | 329,114 |
| Distribution Main | 11128 | P-686 | WW | Burlingame Rd. | 8 | PVC | 14 | 38 | 0.43 out of 5 | $442 | 6,154 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 11204 | P-1786 | WW | Burlingame Rd. | 8 | PVC | 18 | 38 | 0.43 out of 5 | $442 | 7,946 |
| Distribution Main | 12070 | P-686 | WW | Burlingame Rd. | 8 | PVC | 13 | 38 | 0.43 out of 5 | $442 | 5,749 |
| Distribution Main | 10016 | P-1759 | WW | Burns St | 8 | Ductile Iron | 252 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10031 | P-1759 | WW | Burns St | 8 | Ductile Iron | 124 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4693 | P-1161 | WW | Campbell St. | 6 | Asbestos Cement | 404 | 67 | 2 out of 5 | $442 | 178,749 |
| Distribution Main | 4694 | P-1161 | WW | Campbell St. | 6 | Asbestos Cement | 922 | 67 | 2 out of 5 | $442 | 407,370 |
| Distribution Main | 5124 | P-1158 | WW | Campbell St. | 6 | Asbestos Cement | 16 | 67 | 2 out of 5 | $442 | 6,898 |
| Distribution Main | 2149 | P-297 | WW | Cantara St. | 6 | Asbestos Cement | 313 | 52 | 1.85 out of 5 | $442 | 138,271 |
| Distribution Main | 2150 | P-297 | WW | Cantara St. | 6 | Asbestos Cement | 308 | 52 | 1.85 out of 5 | $442 | 136,144 |
| Distribution Main | 2157 | P-1487 | WW | Capron St. | 2 | Cast Iron | 268 | 109 | 3.29 out of 5 | $442 | 118,457 |
| Distribution Main | 4309 | P-1486 | WW | Capron St. | 4 | Cast Iron | 10 | 109 | 3.29 out of 5 | $442 | 4,244 |
| Distribution Main | 4310 | P-1486 | WW | Capron St. | 4 | Cast Iron | 448 | 109 | 3.29 out of 5 | $442 | 198,009 |
| Distribution Main | 1751 | P-437 | WW | Carder St. | 6 | PVC | 488 | 33 | 1.14 out of 5 | $442 | 215,887 |
| Distribution Main | 1752 | P-437 | WW | Carder St. | 6 | PVC | 8 | 33 | 1.14 out of 5 | $442 | 3,490 |
| Distribution Main | 3120 | P-515 | WW | Carlson Cir. | 6 | Asbestos Cement | 8 | 69 | 2 out of 5 | $442 | 3,371 |
| Distribution Main | 3885 | P-529 | WW | Carlson Cir. | 6 | Asbestos Cement | 160 | 69 | 2 out of 5 | $442 | 70,793 |
| Distribution Main | 3886 | P-529 | WW | Carlson Cir. | 6 | Asbestos Cement | 462 | 69 | 2 out of 5 | $442 | 204,210 |
| Distribution Main | 4826 | P-515 | WW | Carlson Cir. | 6 | Asbestos Cement | 19 | 69 | 2 out of 5 | $442 | 8,305 |
| Distribution Main | 4827 | P-515 | WW | Carlson Cir. | 6 | Asbestos Cement | 278 | 69 | 2 out of 5 | $442 | 122,711 |
| Distribution Main | 5098 | P-516 | WW | Carlson Cir. | 6 | Asbestos Cement | 423 | 69 | 2 out of 5 | $442 | 186,924 |
| Distribution Main | 5135 | P-529 | WW | Carlson Cir. | 6 | Asbestos Cement | 211 | 69 | 2 out of 5 | $442 | 93,322 |
| Distribution Main | 10900 |  | WW | Carlson Cir. | 6 | Asbestos Cement | 6 | 69 | 2 out of 5 | $442 | 2,598 |
| Distribution Main | 2896 | P-549 | WW | Carlton Pl. | 6 | Asbestos Cement | 370 | 65 | 2 out of 5 | $442 | 163,334 |
| Distribution Main | 8675 | P-1775 | WW | Carnival Ter | 8 | Ductile Iron | 35 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8676 | P-1775 | WW | Carnival Ter | 8 | Ductile Iron | 560 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3564 | P-98 | WW | Carolyn Dr. | 8 | Asbestos Cement | 325 | 41 | 1.14 out of 5 | $442 | 143,686 |
| Distribution Main | 3565 | P-98 | WW | Carolyn Dr. | 8 | Asbestos Cement | 153 | 41 | 1.14 out of 5 | $442 | 67,518 |
| Distribution Main | 4134 | P-98 | WW | Carolyn Dr. | 8 | Asbestos Cement | 45 | 41 | 1.14 out of 5 | $442 | 19,956 |
| Distribution Main | 5161 | P-97 | WW | Carolyn Dr. | 8 | Asbestos Cement | 383 | 41 | 1.14 out of 5 | $442 | 169,391 |
| Distribution Main | 1721 | P-1950 | WW | Carpenters Court | 1 | Copper | 438 | 73 | 2.43 out of 5 | $442 | 193,773 |
| Distribution Main | 8934 | P-1 | WW | Carriage Rd | 8 | Ductile Iron | 4 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8939 | P-1 | WW | Carriage Rd | 6 | Ductile Iron | 3 | 9 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 2072 | P-856 | WW | Carrie Ann Dr. | 12 | Ductile Iron | 255 | 29 | 0.14 out of 5 | $442 | 112,599 |
| Transmission Main | 2074 | P-858 | WW | Carrie Ann Dr. | 12 | Ductile Iron | 49 | 29 | 0.14 out of 5 | $442 | 21,569 |
| Transmission Main | 2101 | P-856 | WW | Carrie Ann Dr. | 12 | Ductile Iron | 8 | 29 | 0.14 out of 5 | $442 | 3,345 |
| Transmission Main | 8052 | P-858 | WW | Carrie Ann Dr. | 12 | Ductile Iron | 22 | 29 | 0.14 out of 5 | $442 | 9,773 |
| Transmission Main | 8053 | P-858 | WW | Carrie Ann Dr. | 12 | Ductile Iron | 17 | 29 | 0.14 out of 5 | $442 | 7,717 |
| Distribution Main | 3435 | P-502 | WW | Cedar Dr. | 6 | Asbestos Cement | 247 | 51 | 1.85 out of 5 | $442 | 109,369 |
| Distribution Main | 3574 | P-501 | WW | Cedar Dr. | 6 | Asbestos Cement | 724 | 51 | 1.85 out of 5 | $442 | 319,889 |
| Distribution Main | 9715 | P-1809 | WW | Centracchio Ct | 6 | Ductile Iron | 22 | 27 | 0.85 out of 5 | $442 | 9,756 |
| Distribution Main | 10996 | P-1810 | WW | Centracchio Ct | 6 | Ductile Iron | 14 | 27 | 0.85 out of 5 | $442 | 6,260 |
| Distribution Main | 1767 | P-947 | WW | Centracchio St. | 6 | Ductile Iron | 71 | 27 | 0.85 out of 5 | $442 | 31,332 |
| Distribution Main | 1768 | P-947 | WW | Centracchio St. | 6 | Ductile Iron | 69 | 27 | 0.85 out of 5 | $442 | 30,662 |
| Distribution Main | 3195 | P-947 | WW | Centracchio St. | 6 | Ductile Iron | 36 | 27 | 0.85 out of 5 | $442 | 16,127 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3199 | P-945 | WW | Centracchio St. | 6 | PVC | 15 | 32 | 1.14 out of 5 | $442 | 6,609 |
| Distribution Main | 3200 | P-945 | WW | Centracchio St. | 6 | PVC | 312 | 32 | 1.14 out of 5 | $442 | 137,717 |
| Distribution Main | 3519 | P-946 | WW | Centracchio St. | 6 | Ductile Iron | 203 | 27 | 0.85 out of 5 | $442 | 89,688 |
| Transmission Main | 8609 | P-999 | WW | Central St | 12 | Ductile Iron | 129 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8612 | P-1004 | WW | Central St | 12 | Ductile Iron | 20 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8617 | P-1876 | WW | Central St | 8 | Ductile Iron | 12 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8618 | P-1876 | WW | Central St | 12 | Ductile Iron | 3 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8619 | P-1876 | WW | Central St | 12 | Ductile Iron | 4 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8620 | P-1874 | WW | Central St | 12 | Ductile Iron | 54 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8621 | P-1341 | WW | Central St | 12 | Ductile Iron | 70 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 429 | P-1001 | WW | Central St. | 8 | Cast Iron | 342 | 82 | 1.72 out of 5 | $442 | 151,349 |
| Distribution Main | 430 | P-1001 | WW | Central St. | 8 | Cast Iron | 462 | 82 | 1.72 out of 5 | $442 | 204,070 |
| Distribution Main | 443 | P-1342 | WW | Central St. | 6 | Cast Iron | 124 | 133 | 2.57 out of 5 | $442 | 54,617 |
| Distribution Main | 9421 | P-1342 | WW | Central St. | 6 | Cast Iron | 6 | 133 | 2.57 out of 5 | $442 | 2,435 |
| Distribution Main | 9529 | P-1000 | WW | Central St. | 8 | Cast Iron | 133 | 82 | 1.72 out of 5 | $442 | 58,808 |
| Distribution Main | 10665 | P-1106 | WW | Centre St | 8 | Ductile Iron | 438 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10666 | P-1106 | WW | Centre St | 8 | Ductile Iron | 471 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4559 | P-30 | WW | Chamber Road | 6 | Asbestos Cement | 24 | 51 | 1.85 out of 5 | $442 | 10,638 |
| Distribution Main | 4967 | P-30 | WW | Chamber Road | 6 | Asbestos Cement | 247 | 51 | 1.85 out of 5 | $442 | 109,087 |
| Distribution Main | 3396 | P-10037 | WW | Church St. | 4 | Cast Iron | 322 | 83 | 3.14 out of 5 | $442 | 142,286 |
| Distribution Main | 3397 | P-1081 | WW | Church St. | 6 | Cast Iron | 259 | 83 | 2.43 out of 5 | $442 | 114,597 |
| Distribution Main | 3398 | P-10037 | WW | Church St. | 4 | Cast Iron | 265 | 83 | 3.14 out of 5 | $442 | 116,932 |
| Distribution Main | 3399 | | WW | Church St. | 6 | Cast Iron | 6 | UNK | 1.85 out of 5 | $442 | 2,686 |
| Distribution Main | 4075 | P-1080 | WW | Church St. | 6 | Cast Iron | 46 | 83 | 2.43 out of 5 | $442 | 20,208 |
| Distribution Main | 4076 | P-1080 | WW | Church St. | 6 | Cast Iron | 129 | 134 | 2.57 out of 5 | $442 | 56,908 |
| Distribution Main | 4077 | P-1080 | WW | Church St. | 6 | Cast Iron | 633 | 134 | 2.57 out of 5 | $442 | 279,910 |
| Distribution Main | 4088 | | WW | Church St. | 6 | Cast Iron | 9 | 83 | 2.43 out of 5 | $442 | 3,767 |
| Distribution Main | 4089 | | WW | Church St. | 6 | Cast Iron | 2 | 83 | 2.43 out of 5 | $442 | 1,027 |
| Distribution Main | 4296 | P-1103 | WW | Church St. | 4 | Cast Iron | 109 | 83 | 3.14 out of 5 | $442 | 48,349 |
| Distribution Main | 4784 | P-1080 | WW | Church St. | 6 | Cast Iron | 175 | 134 | 2.57 out of 5 | $442 | 77,433 |
| Distribution Main | 5083 | P-1102 | WW | Church St. | 4 | Cast Iron | 601 | 83 | 3.14 out of 5 | $442 | 265,790 |
| Distribution Main | 5084 | P-1095 | WW | Church St. | 4 | Cast Iron | 208 | 83 | 3.14 out of 5 | $442 | 92,051 |
| Distribution Main | 5085 | | WW | Church St. | 4 | Cast Iron | 70 | 134 | 3.29 out of 5 | $442 | 30,942 |
| Distribution Main | 10675 | P-10040 | WW | Church St. | 4 | Cast Iron | 16 | 124 | 3.29 out of 5 | $442 | 7,152 |
| Distribution Main | 11771 | P-1080 | WW | Church St. | 6 | Cast Iron | 336 | 84 | 2.43 out of 5 | $442 | 148,719 |
| Distribution Main | 10021 | P-284 | WW | Circle Dr | 8 | Ductile Iron | 30 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10022 | P-284 | WW | Circle Dr | 8 | Ductile Iron | 219 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10026 | P-1756 | WW | Circle Dr | 8 | Ductile Iron | 26 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10027 | P-1756 | WW | Circle Dr | 8 | Ductile Iron | 46 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3547 | P-109 | WW | Claire St. | 6 | Asbestos Cement | 97 | 55 | 1.85 out of 5 | $442 | 43,073 |
| Distribution Main | 3548 | P-109 | WW | Claire St. | 6 | Asbestos Cement | 282 | 55 | 1.85 out of 5 | $442 | 124,770 |
| Distribution Main | 4645 | P-110 | WW | Claire St. | 6 | Asbestos Cement | 267 | 55 | 1.85 out of 5 | $442 | 117,809 |
| Distribution Main | 4646 | P-109 | WW | Claire St. | 6 | Asbestos Cement | 26 | 55 | 1.85 out of 5 | $442 | 11,595 |
| Distribution Main | 1528 | P-899 | WW | Cleveland St. | 6 | Asbestos Cement | 72 | 71 | 2 out of 5 | $442 | 31,783 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 1529 | P-899 | WW | Cleveland St. | 6 | Asbestos Cement | 133 | 71 | 2 out of 5 | $442 | 58,775 |
| Distribution Main | 1533 | P-903 | WW | Cleveland St. | 6 | Asbestos Cement | 134 | 71 | 2 out of 5 | $442 | 59,435 |
| Distribution Main | 1540 | P-901 | WW | Cleveland St. | 6 | Asbestos Cement | 4 | 71 | 2 out of 5 | $442 | 1,716 |
| Distribution Main | 1541 | P-901 | WW | Cleveland St. | 6 | Asbestos Cement | 321 | 71 | 2 out of 5 | $442 | 141,912 |
| Distribution Main | 1542 | P-904 | WW | Cleveland St. | 6 | Asbestos Cement | 229 | 71 | 2 out of 5 | $442 | 101,064 |
| Distribution Main | 3496 | P-906 | WW | Cleveland St. | 6 | Asbestos Cement | 213 | 71 | 2 out of 5 | $442 | 94,253 |
| Distribution Main | 3497 | P-899 | WW | Cleveland St. | 6 | Asbestos Cement | 583 | 71 | 2 out of 5 | $442 | 257,712 |
| Distribution Main | 1514 | P-921 | WW | Clyde St | 6 | Cast Iron | 215 | 133 | 2.57 out of 5 | $442 | 95,199 |
| Transmission Main | 8545 | P-831 | WW | Clyde St | 12 | Ductile Iron | 38 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8546 | P-1863 | WW | Clyde St | 6 | Ductile Iron | 20 | 13 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8579 | P-1863 | WW | Clyde St | 6 | Ductile Iron | 15 | 13 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9730 | P-1855 | WW | Clyde St | 6 | Ductile Iron | 60 | 22 | 0.85 out of 5 | N/A | $0 |
| Transmission Main | 9826 | P-831 | WW | Clyde St | 12 | Ductile Iron | 3 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9827 | P-831 | WW | Clyde St | 12 | Ductile Iron | 12 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9828 | P-820 | WW | Clyde St | 6 | Ductile Iron | 19 | 7 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 11615 | P-1859 | WW | Clyde St | 12 | Ductile Iron | 9 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2276 | P-1859 | WW | Clyde St. | 12 | PVC | 363 | 39 | 0.43 out of 5 | $442 | 160,568 |
| Transmission Main | 2278 | P-1358 | WW | Clyde St. | 12 | PVC | 136 | 39 | 0.43 out of 5 | $442 | 60,118 |
| Transmission Main | 2279 | P-1358 | WW | Clyde St. | 12 | PVC | 3 | 39 | 0.43 out of 5 | $442 | 1,538 |
| Distribution Main | 2956 | P-1861 | WW | Clyde St. | 6 | Cast Iron | 102 | 133 | 2.57 out of 5 | $442 | 45,104 |
| Distribution Main | 2957 | P-912 | WW | Clyde St. | 6 | Cast Iron | 609 | 133 | 2.57 out of 5 | $442 | 269,030 |
| Distribution Main | 2958 | P-912 | WW | Clyde St. | 6 | Cast Iron | 118 | 133 | 2.57 out of 5 | $442 | 52,294 |
| Distribution Main | 3469 | P-1353 | WW | Clyde St. | 6 | Cast Iron | 269 | 133 | 2.57 out of 5 | $442 | 118,808 |
| Distribution Main | 3482 | P-910 | WW | Clyde St. | 6 | Cast Iron | 290 | 134 | 2.57 out of 5 | $442 | 128,028 |
| Distribution Main | 3483 | P-910 | WW | Clyde St. | 6 | Cast Iron | 485 | 134 | 2.57 out of 5 | $442 | 214,586 |
| Distribution Main | 3507 | P-1353 | WW | Clyde St. | 6 | Cast Iron | 144 | 133 | 2.57 out of 5 | $442 | 63,649 |
| Distribution Main | 3508 | P-1354 | WW | Clyde St. | 6 | Cast Iron | 116 | 133 | 2.57 out of 5 | $442 | 51,203 |
| Distribution Main | 3737 | P-1863 | WW | Clyde St. | 6 | Cast Iron | 228 | 133 | 2.57 out of 5 | $442 | 100,829 |
| Distribution Main | 3738 | P-1863 | WW | Clyde St. | 6 | Cast Iron | 2 | 133 | 2.57 out of 5 | $442 | 789 |
| Transmission Main | 9825 | P-831 | WW | Clyde St. | 12 | PVC | 347 | 39 | 0.43 out of 5 | $442 | 153,354 |
| Distribution Main | 11221 | P-910 | WW | Clyde St. | 6 | Cast Iron | 16 | 134 | 2.57 out of 5 | $442 | 7,057 |
| Distribution Main | 12022 | P-912 | WW | Clyde St. | 6 | Cast Iron | 386 | 133 | 2.57 out of 5 | $442 | 170,803 |
| Distribution Main | 9801 | P-622 | WW | Coaches Ct | 8 | Ductile Iron | 203 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2437 | P-11 | WW | Cobblestone La. | 8 | Ductile Iron | 202 | 28 | 0.14 out of 5 | $442 | 89,447 |
| Distribution Main | 2438 | P-11 | WW | Cobblestone La. | 8 | Ductile Iron | 44 | 28 | 0.14 out of 5 | $442 | 19,622 |
| Distribution Main | 634 | P-468 | WW | Cochran St. | 6 | Asbestos Cement | 52 | 64 | 2 out of 5 | $442 | 23,030 |
| Distribution Main | 635 | P-468 | WW | Cochran St. | 6 | Asbestos Cement | 222 | 64 | 2 out of 5 | $442 | 98,269 |
| Distribution Main | 5150 | P-467 | WW | Cochran St. | 6 | Asbestos Cement | 480 | 64 | 2 out of 5 | $442 | 212,281 |
| Distribution Main | 5151 | P-467 | WW | Cochran St. | 6 | Asbestos Cement | 38 | 64 | 2 out of 5 | $442 | 16,677 |
| Distribution Main | 5152 | P-472 | WW | Cochran St. | 6 | Asbestos Cement | 724 | 64 | 2 out of 5 | $442 | 320,212 |
| Distribution Main | 5153 | P-472 | WW | Cochran St. | 6 | Asbestos Cement | 606 | 64 | 2 out of 5 | $442 | 267,901 |
| Distribution Main | 10680 | P-432 | WW | Coit Av | 8 | Ductile Iron | 10 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10681 | P-432 | WW | Coit Av | 8 | Ductile Iron | 16 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10682 | | WW | Coit Av | 8 | Ductile Iron | 1 | 2 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 633 | P-1476 | WW | Coit Ave. | 6 | Asbestos Cement | 275 | 51 | 1.85 out of 5 | $442 | 121,466 |
| Distribution Main | 636 | P-429 | WW | Coit Ave. | 6 | Cast Iron | 220 | 81 | 2.43 out of 5 | $442 | 97,382 |
| Distribution Main | 637 | P-429 | WW | Coit Ave. | 6 | Cast Iron | 26 | 81 | 2.43 out of 5 | $442 | 11,556 |
| Distribution Main | 638 | P-445 | WW | Coit Ave. | 6 | Cast Iron | 101 | 81 | 2.43 out of 5 | $442 | 44,847 |
| Distribution Main | 639 | P-448 | WW | Coit Ave. | 6 | Cast Iron | 143 | 81 | 2.43 out of 5 | $442 | 63,152 |
| Distribution Main | 640 | P-10021 | WW | Coit Ave. | 8 | Asbestos Cement | 168 | 51 | 1.14 out of 5 | $442 | 74,232 |
| Distribution Main | 803 | P-419 | WW | Coit Ave. | 6 | Cast Iron | 235 | 81 | 2.43 out of 5 | $442 | 103,916 |
| Distribution Main | 1211 | P-423 | WW | Coit Ave. | 6 | Cast Iron | 206 | 81 | 2.43 out of 5 | $442 | 91,052 |
| Distribution Main | 1748 | P-431 | WW | Coit Ave. | 6 | Cast Iron | 164 | 81 | 2.43 out of 5 | $442 | 72,298 |
| Distribution Main | 1749 | P-418 | WW | Coit Ave. | 6 | Cast Iron | 45 | 81 | 2.43 out of 5 | $442 | 19,757 |
| Distribution Main | 3135 | P-432 | WW | Coit Ave. | 6 | Cast Iron | 867 | 81 | 2.43 out of 5 | $442 | 383,337 |
| Distribution Main | 4445 | P-422 | WW | Coit Ave. | 6 | Cast Iron | 37 | 81 | 2.43 out of 5 | $442 | 16,539 |
| Distribution Main | 4446 | P-422 | WW | Coit Ave. | 6 | Cast Iron | 10 | 81 | 2.43 out of 5 | $442 | 4,264 |
| Distribution Main | 4667 | P-462 | WW | Coit Ave. | 8 | Asbestos Cement | 549 | 51 | 1.14 out of 5 | $442 | 242,849 |
| Distribution Main | 4670 | P-451 | WW | Coit Ave. | 6 | Cast Iron | 269 | 81 | 2.43 out of 5 | $442 | 118,865 |
| Distribution Main | 4675 | P-445 | WW | Coit Ave. | 6 | Cast Iron | 102 | 81 | 2.43 out of 5 | $442 | 45,099 |
| Distribution Main | 5143 | P-430 | WW | Coit Ave. | 6 | Cast Iron | 192 | 81 | 2.43 out of 5 | $442 | 84,915 |
| Distribution Main | 5149 | P-447 | WW | Coit Ave. | 6 | Cast Iron | 213 | 81 | 2.43 out of 5 | $442 | 94,138 |
| Distribution Main | 10899 | P-1477 | WW | Coit Ave. | 8 | Asbestos Cement | 129 | 51 | 1.14 out of 5 | $442 | 56,923 |
| Distribution Main | 11260 | P-462 | WW | Coit Ave. | 8 | Asbestos Cement | 216 | 51 | 1.14 out of 5 | $442 | 95,379 |
| Distribution Main | 12072 | P-431 | WW | Coit Ave. | 6 | Cast Iron | 13 | 81 | 2.43 out of 5 | $442 | 5,683 |
| Distribution Main | 4610 | P-128 | WW | Cold Spring Dr. | 8 | PVC | 226 | 34 | 0.43 out of 5 | $442 | 100,015 |
| Distribution Main | 4611 | P-130 | WW | Cold Spring Dr. | 8 | PVC | 133 | 34 | 0.43 out of 5 | $442 | 58,853 |
| Distribution Main | 4612 | P-130 | WW | Cold Spring Dr. | 8 | PVC | 600 | 34 | 0.43 out of 5 | $442 | 265,225 |
| Distribution Main | 12053 | P-130 | WW | Cold Spring Dr. | 8 | PVC | 401 | 34 | 0.43 out of 5 | $442 | 177,242 |
| Distribution Main | 1228 | P-597 | WW | Colonial Way | 8 | Ductile Iron | 42 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1229 | P-597 | WW | Colonial Way | 8 | Ductile Iron | 6 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4008 | P-597 | WW | Colonial Way | 6 | Asbestos Cement | 789 | 72 | 2 out of 5 | $442 | 348,526 |
| Distribution Main | 4336 | P-597 | WW | Colonial Way | 6 | Ductile Iron | 9 | 72 | 1.14 out of 5 | $442 | 3,768 |
| Distribution Main | 4708 | P-597 | WW | Colonial Way | 8 | Ductile Iron | 32 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9373 | P-597 | WW | Colonial Way | 6 | Ductile Iron | 3 | 14 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9374 | P-597 | WW | Colonial Way | 6 | Ductile Iron | 4 | 14 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9891 | P-597 | WW | Colonial Way | 6 | Ductile Iron | 16 | 14 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9466 | P-1866 | WW | Colvin St | 1 | Unknown | 160 | UNK | 1.42 out of 5 | $442 | 70,921 |
| Distribution Main | 1503 | P-1203 | WW | Colvin St. | 6 | Cast Iron | 14 | 79 | 2.28 out of 5 | $442 | 6,070 |
| Distribution Main | 3489 | P-1201 | WW | Colvin St. | 4 | Cast Iron | 208 | 134 | 3.29 out of 5 | $442 | 92,061 |
| Distribution Main | 3742 | P-1203 | WW | Colvin St. | 6 | Cast Iron | 379 | 79 | 2.28 out of 5 | $442 | 167,418 |
| Distribution Main | 3743 | P-1203 | WW | Colvin St. | 6 | Cast Iron | 26 | 79 | 2.28 out of 5 | $442 | 11,502 |
| Distribution Main | 11227 | P-1203 | WW | Colvin St. | 6 | Cast Iron | 3 | 79 | 2.28 out of 5 | $442 | 1,174 |
| Distribution Main | 10631 | P-394 | WW | Concord Av | 8 | Ductile Iron | 65 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10632 | P-394 | WW | Concord Av | 8 | Ductile Iron | 187 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10633 |  | WW | Concord Av | 8 | Ductile Iron | 247 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 469 |  | WW | Cone Dr. | 8 | Ductile Iron | 10 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1357 | P-1460 | WW | Cone Dr. | 12 | Ductile Iron | 312 | 19 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 2352 | P-1642 | WW | Cone Dr. | 12 | Ductile Iron | 38 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3558 | P-57 | WW | Cone Dr. | 8 | Asbestos Cement | 159 | 46 | 1.14 out of 5 | $442 | 70,477 |
| Distribution Main | 4631 | P-1456 | WW | Cone Dr. | 8 | Asbestos Cement | 195 | 46 | 1.14 out of 5 | $442 | 86,193 |
| Distribution Main | 4633 | P-58 | WW | Cone Dr. | 8 | Asbestos Cement | 629 | 46 | 1.14 out of 5 | $442 | 278,227 |
| Distribution Main | 4634 | P-58 | WW | Cone Dr. | 8 | Asbestos Cement | 271 | 46 | 1.14 out of 5 | $442 | 119,980 |
| Distribution Main | 4636 | P-1461 | WW | Cone Dr. | 8 | Asbestos Cement | 326 | 46 | 1.14 out of 5 | $442 | 144,199 |
| Distribution Main | 10149 | P-57 | WW | Cone Dr. | 8 | Asbestos Cement | 38 | 46 | 1.14 out of 5 | $442 | 16,817 |
| Distribution Main | 12078 | P-1461 | WW | Cone Dr. | 8 | Asbestos Cement | 43 | 46 | 1.14 out of 5 | $442 | 18,823 |
| Distribution Main | 9463 | P-1864 | WW | Coogan Ct | 1 | Unknown | 235 | UNK | 1.42 out of 5 | $442 | 103,736 |
| Distribution Main | 1726 | P-558 | WW | Cottage St. | 4 | Cast Iron | 287 | 109 | 3.29 out of 5 | $442 | 126,645 |
| Distribution Main | 1727 | P-558 | WW | Cottage St. | 4 | Cast Iron | 275 | 109 | 3.29 out of 5 | $442 | 121,469 |
| Distribution Main | 2888 | P-558 | WW | Cottage St. | 4 | Cast Iron | 8 | 109 | 3.29 out of 5 | $442 | 3,450 |
| Distribution Main | 1976 | P-483 | WW | Country Dr. | 8 | Asbestos Cement | 15 | 63 | 1.29 out of 5 | $442 | 6,662 |
| Distribution Main | 1980 | P-478 | WW | Country Dr. | 6 | Asbestos Cement | 15 | 63 | 2 out of 5 | $442 | 6,437 |
| Distribution Main | 1990 | P-475 | WW | Country Dr. | 8 | Asbestos Cement | 25 | 63 | 1.29 out of 5 | $442 | 10,910 |
| Distribution Main | 1991 | P-475 | WW | Country Dr. | 8 | Asbestos Cement | 602 | 63 | 1.29 out of 5 | $442 | 266,153 |
| Distribution Main | 3391 | P-478 | WW | Country Dr. | 6 | Asbestos Cement | 428 | 63 | 2 out of 5 | $442 | 189,263 |
| Distribution Main | 3392 | P-478 | WW | Country Dr. | 6 | Asbestos Cement | 315 | 63 | 2 out of 5 | $442 | 139,362 |
| Distribution Main | 3393 | P-483 | WW | Country Dr. | 8 | Asbestos Cement | 241 | 63 | 1.14 out of 5 | $442 | 106,400 |
| Distribution Main | 4213 | P-477 | WW | Country Dr. | 6 | Asbestos Cement | 244 | 63 | 2 out of 5 | $442 | 107,724 |
| Distribution Main | 5071 | P-476 | WW | Country Dr. | 8 | Asbestos Cement | 412 | 63 | 1.29 out of 5 | $442 | 182,156 |
| Distribution Main | 5072 | P-476 | WW | Country Dr. | 8 | Asbestos Cement | 43 | 63 | 1.29 out of 5 | $442 | 19,153 |
| Distribution Main | 9923 | P-1786 | WW | Countryside Way | 8 | Ductile Iron | 392 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9924 | P-1786 | WW | Countryside Way | 8 | Ductile Iron | 240 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1971 | P-1058 | WW | Coutu Ct. | 4 | Cast Iron | 278 | 83 | 3.14 out of 5 | $442 | 122,961 |
| Distribution Main | 3242 | P-1058 | WW | Coutu Ct. | 4 | Cast Iron | 11 | 83 | 3.14 out of 5 | $442 | 4,793 |
| Distribution Main | 644 | P-1474 | WW | Cowesett Ave. | 8 | Asbestos Cement | 29 | 79 | 1.29 out of 5 | $442 | 12,847 |
| Distribution Main | 651 | P-511 | WW | Cowesett Ave. | 8 | Asbestos Cement | 67 | 79 | 1.29 out of 5 | $442 | 29,640 |
| Distribution Main | 652 | P-465 | WW | Cowesett Ave. | 8 | Asbestos Cement | 32 | 79 | 1.29 out of 5 | $442 | 13,935 |
| Distribution Main | 653 | P-465 | WW | Cowesett Ave. | 8 | Asbestos Cement | 284 | 79 | 1.29 out of 5 | $442 | 125,585 |
| Distribution Main | 654 | P-464 | WW | Cowesett Ave. | 8 | Asbestos Cement | 392 | 79 | 1.29 out of 5 | $442 | 173,146 |
| Distribution Main | 1096 | P-1079 | WW | Cowesett Ave. | 6 | Cast Iron | 502 | 124 | 2.57 out of 5 | $442 | 221,708 |
| Transmission Main | 1977 | P-490 | WW | Cowesett Ave. | 12 | Asbestos Cement | 149 | 47 | 1.14 out of 5 | $442 | 65,807 |
| Transmission Main | 1987 | P-489 | WW | Cowesett Ave. | 12 | Asbestos Cement | 258 | 47 | 1.14 out of 5 | $442 | 113,887 |
| Transmission Main | 2152 | | WW | Cowesett Ave. | 12 | Asbestos Cement | 476 | 47 | 1.14 out of 5 | $442 | 210,408 |
| Distribution Main | 3125 | P-1134 | WW | Cowesett Ave. | 8 | Asbestos Cement | 5 | 79 | 1.29 out of 5 | $442 | 2,363 |
| Distribution Main | 3126 | P-1079 | WW | Cowesett Ave. | 6 | Cast Iron | 230 | 124 | 2.57 out of 5 | $442 | 101,649 |
| Distribution Main | 3879 | P-537 | WW | Cowesett Ave. | 8 | Asbestos Cement | 306 | 79 | 1.29 out of 5 | $442 | 135,070 |
| Distribution Main | 3889 | P-540 | WW | Cowesett Ave. | 8 | Asbestos Cement | 125 | 79 | 1.29 out of 5 | $442 | 55,285 |
| Distribution Main | 3892 | P-1135 | WW | Cowesett Ave. | 4 | Cast Iron | 995 | 124 | 3.29 out of 5 | $442 | 439,751 |
| Distribution Main | 3893 | P-1079 | WW | Cowesett Ave. | 6 | Cast Iron | 20 | 124 | 2.57 out of 5 | $442 | 9,028 |
| Distribution Main | 4665 | P-464 | WW | Cowesett Ave. | 8 | Asbestos Cement | 143 | 79 | 1.29 out of 5 | $442 | 63,418 |
| Distribution Main | 4672 | P-1474 | WW | Cowesett Ave. | 8 | Asbestos Cement | 8 | 79 | 1.29 out of 5 | $442 | 3,322 |
| Distribution Main | 4678 | P-538 | WW | Cowesett Ave. | 8 | Asbestos Cement | 187 | 79 | 1.29 out of 5 | $442 | 82,540 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 4681 | P-1473 | WW | Cowesett Ave. | 12 | Asbestos Cement | 257 | 54 | 1.14 out of 5 | $442 | 113,484 |
| Transmission Main | 4682 | P-1473 | WW | Cowesett Ave. | 12 | Asbestos Cement | 201 | 54 | 1.14 out of 5 | $442 | 88,878 |
| Distribution Main | 4778 | | WW | Cowesett Ave. | 8 | Asbestos Cement | 20 | 54 | 1.14 out of 5 | $442 | 9,056 |
| Distribution Main | 4783 | P-10039 | WW | Cowesett Ave. | 4 | Cast Iron | 20 | 124 | 3.29 out of 5 | $442 | 8,628 |
| Transmission Main | 4959 | P-474 | WW | Cowesett Ave. | 12 | Asbestos Cement | 24 | 47 | 1.14 out of 5 | $442 | 10,644 |
| Transmission Main | 5078 | P-2182 | WW | Cowesett Ave. | 12 | Asbestos Cement | 41 | 47 | 1.14 out of 5 | $442 | 17,912 |
| Transmission Main | 5079 | P-2182 | WW | Cowesett Ave. | 12 | Asbestos Cement | 156 | 47 | 1.14 out of 5 | $442 | 68,878 |
| Transmission Main | 5080 | P-490 | WW | Cowesett Ave. | 12 | Asbestos Cement | 10 | 47 | 1.14 out of 5 | $442 | 4,391 |
| Distribution Main | 5092 | P-1079 | WW | Cowesett Ave. | 6 | Cast Iron | 19 | 124 | 2.57 out of 5 | $442 | 8,556 |
| Distribution Main | 5093 | P-1134 | WW | Cowesett Ave. | 8 | Asbestos Cement | 482 | 79 | 1.29 out of 5 | $442 | 213,113 |
| Transmission Main | 5099 | P-1170 | WW | Cowesett Ave. | 12 | Asbestos Cement | 6 | 54 | 1.14 out of 5 | $442 | 2,502 |
| Distribution Main | 5101 | P-1135 | WW | Cowesett Ave. | 4 | Cast Iron | 130 | 124 | 3.29 out of 5 | $442 | 57,346 |
| Distribution Main | 5102 | P-541 | WW | Cowesett Ave. | 8 | Asbestos Cement | 238 | 79 | 1.29 out of 5 | $442 | 105,039 |
| Distribution Main | 5103 | P-540 | WW | Cowesett Ave. | 8 | Asbestos Cement | 89 | 79 | 1.29 out of 5 | $442 | 39,514 |
| Distribution Main | 5104 | P-10031 | WW | Cowesett Ave. | 8 | Asbestos Cement | 22 | 79 | 1.29 out of 5 | $442 | 9,826 |
| Distribution Main | 5105 | P-10031 | WW | Cowesett Ave. | 8 | Asbestos Cement | 166 | 79 | 1.29 out of 5 | $442 | 73,397 |
| Distribution Main | 5106 | P-533 | WW | Cowesett Ave. | 8 | Asbestos Cement | 146 | 79 | 1.29 out of 5 | $442 | 64,440 |
| Distribution Main | 5107 | P-533 | WW | Cowesett Ave. | 8 | Asbestos Cement | 588 | 79 | 1.29 out of 5 | $442 | 259,988 |
| Transmission Main | 5111 | P-1169 | WW | Cowesett Ave. | 12 | Asbestos Cement | 8 | 54 | 1.14 out of 5 | $442 | 3,617 |
| Transmission Main | 5112 | P-1169 | WW | Cowesett Ave. | 12 | Asbestos Cement | 645 | 54 | 1.14 out of 5 | $442 | 285,256 |
| Transmission Main | 5113 | P-1473 | WW | Cowesett Ave. | 12 | Asbestos Cement | 17 | 54 | 1.14 out of 5 | $442 | 7,316 |
| Transmission Main | 5114 | P-1473 | WW | Cowesett Ave. | 12 | Asbestos Cement | 547 | 54 | 1.14 out of 5 | $442 | 241,698 |
| Transmission Main | 5115 | P-1472 | WW | Cowesett Ave. | 12 | Asbestos Cement | 532 | 54 | 1.14 out of 5 | $442 | 235,155 |
| Distribution Main | 5125 | P-1137 | WW | Cowesett Ave. | 4 | Cast Iron | 5 | 124 | 3.29 out of 5 | $442 | 2,140 |
| Distribution Main | 5137 | P-510 | WW | Cowesett Ave. | 8 | Asbestos Cement | 431 | 79 | 1.29 out of 5 | $442 | 190,679 |
| Distribution Main | 5144 | P-1474 | WW | Cowesett Ave. | 8 | Asbestos Cement | 394 | 79 | 1.29 out of 5 | $442 | 174,063 |
| Transmission Main | 5147 | P-474 | WW | Cowesett Ave. | 12 | Asbestos Cement | 538 | 47 | 1.14 out of 5 | $442 | 237,958 |
| Transmission Main | 10501 | P-489 | WW | Cowesett Ave. | 12 | Asbestos Cement | 15 | 47 | 1.14 out of 5 | $442 | 6,642 |
| Transmission Main | 10502 | P-489 | WW | Cowesett Ave. | 12 | Asbestos Cement | 9 | 47 | 1.14 out of 5 | $442 | 4,161 |
| Transmission Main | 10503 | | WW | Cowesett Ave. | 12 | Asbestos Cement | 53 | 47 | 1.14 out of 5 | $442 | 23,467 |
| Distribution Main | 10986 | P-537 | WW | Cowesett Ave. | 8 | Asbestos Cement | 20 | 79 | 1.29 out of 5 | $442 | 8,987 |
| Distribution Main | 11288 | P-10031 | WW | Cowesett Ave. | 8 | Asbestos Cement | 71 | 79 | 1.29 out of 5 | $442 | 31,572 |
| Distribution Main | 11289 | P-533 | WW | Cowesett Ave. | 8 | Asbestos Cement | 3 | 79 | 1.29 out of 5 | $442 | 1,533 |
| Transmission Main | 11665 | P-489 | WW | Cowesett Ave. | 12 | Asbestos Cement | 5 | 47 | 1.14 out of 5 | $442 | 2,426 |
| Distribution Main | 12023 | P-1079 | WW | Cowesett Ave. | 6 | Cast Iron | 219 | 124 | 2.57 out of 5 | $442 | 96,990 |
| Transmission Main | 12133 | P-489 | WW | Cowesett Ave. | 12 | Asbestos Cement | 4 | 47 | 1.14 out of 5 | $442 | 1,809 |
| Transmission Main | 164 | P-1169 | WW | Cowesett Rd. | 12 | Asbestos Cement | 666 | 54 | 1.14 out of 5 | $442 | 294,221 |
| Transmission Main | 165 | P-1169 | WW | Cowesett Rd. | 12 | Asbestos Cement | 6 | 54 | 1.14 out of 5 | $442 | 2,709 |
| Transmission Main | 12058 | P-1169 | WW | Cowesett Rd. | 12 | Asbestos Cement | 281 | 54 | 1.14 out of 5 | $442 | 124,013 |
| Distribution Main | 3614 | P-745 | WW | Crawford St. | 6 | Cast Iron | 197 | 79 | 2.28 out of 5 | $442 | 87,190 |
| Distribution Main | 3615 | P-745 | WW | Crawford St. | 6 | Cast Iron | 63 | 79 | 2.28 out of 5 | $442 | 27,923 |
| Distribution Main | 3795 | P-745 | WW | Crawford St. | 6 | Cast Iron | 30 | 79 | 2.28 out of 5 | $442 | 13,350 |
| Distribution Main | 4282 | P-730 | WW | Crawford St. | 6 | Cast Iron | 237 | 83 | 2.43 out of 5 | $442 | 104,740 |
| Distribution Main | 10005 | P-745 | WW | Crawford St. | 6 | Cast Iron | 10 | 79 | 2.28 out of 5 | $442 | 4,323 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 1554 | P-849 | WW | Crestwood Dr. | 6 | Asbestos Cement | 227 | 62 | 2 out of 5 | $442 | 100,230 |
| Distribution Main | 1769 | P-833 | WW | Crestwood Dr. | 8 | PVC | 279 | 31 | 0.43 out of 5 | $442 | 123,300 |
| Distribution Main | 1771 | P-841 | WW | Crestwood Dr. | 8 | PVC | 497 | 31 | 0.43 out of 5 | $442 | 219,780 |
| Distribution Main | 1772 | P-841 | WW | Crestwood Dr. | 8 | PVC | 36 | 31 | 0.43 out of 5 | $442 | 15,847 |
| Distribution Main | 3198 | P-849 | WW | Crestwood Dr. | 6 | Asbestos Cement | 11 | 62 | 2 out of 5 | $442 | 4,902 |
| Distribution Main | 3511 | P-844 | WW | Crestwood Dr. | 8 | PVC | 345 | 31 | 0.43 out of 5 | $442 | 152,359 |
| Distribution Main | 3516 | P-846 | WW | Crestwood Dr. | 8 | PVC | 111 | 31 | 0.43 out of 5 | $442 | 48,892 |
| Distribution Main | 3517 | P-846 | WW | Crestwood Dr. | 8 | PVC | 117 | 31 | 0.43 out of 5 | $442 | 51,728 |
| Distribution Main | 641 | P-452 | WW | Crompton Ave. | 6 | Asbestos Cement | 36 | 69 | 2 out of 5 | $442 | 16,019 |
| Distribution Main | 642 | P-452 | WW | Crompton Ave. | 6 | Asbestos Cement | 751 | 69 | 2 out of 5 | $442 | 331,939 |
| Distribution Main | 10155 | | WW | Crompton Ave. | 8 | Ductile Iron | 12 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10997 | P-452 | WW | Crompton Ave. | 8 | Ductile Iron | 8 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 103 | | WW | Crompton/Setian Ln. Tank | 16 | Ductile Iron | 14 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2172 | | WW | Crompton/Setian Ln. Tank | 12 | Ductile Iron | 34 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2173 | | WW | Crompton/Setian Ln. Tank | 12 | Ductile Iron | 2 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2174 | | WW | Crompton/Setian Ln. Tank | 16 | Ductile Iron | 29 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2319 | | WW | Crompton/Setian Ln. Tank | 16 | Ductile Iron | 33 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2320 | | WW | Crompton/Setian Ln. Tank | 16 | Ductile Iron | 2 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2321 | | WW | Crompton/Setian Ln. Tank | 16 | Ductile Iron | 22 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2322 | | WW | Crompton/Setian Ln. Tank | 20 | Ductile Iron | 48 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2323 | | WW | Crompton/Setian Ln. Tank | 20 | Ductile Iron | 20 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2325 | | WW | Crompton/Setian Ln. Tank | 12 | Ductile Iron | 21 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2326 | | WW | Crompton/Setian Ln. Tank | 16 | Ductile Iron | 22 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2327 | | WW | Crompton/Setian Ln. Tank | 16 | Ductile Iron | 11 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11017 | | WW | Crompton/Setian Ln. Tank | 16 | Ductile Iron | 10 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11018 | | WW | Crompton/Setian Ln. Tank | 20 | Ductile Iron | 18 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11019 | | WW | Crompton/Setian Ln. Tank | 20 | Ductile Iron | 26 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 442 | P-985 | WW | Cross St. | 1 | Galvanized Iron | 22 | 91 | 3.43 out of 5 | $442 | 9,647 |
| Distribution Main | 3338 | P-985 | WW | Cross St. | 1 | Galvanized Iron | 286 | 91 | 3.43 out of 5 | $442 | 126,273 |
| Transmission Main | 1356 | P-1464 | WW | Crossbow La. | 16 | Ductile Iron | 737 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3554 | P-22 | WW | Crossbow La. | 8 | Asbestos Cement | 365 | 46 | 1.14 out of 5 | $442 | 161,428 |
| Distribution Main | 3555 | P-22 | WW | Crossbow La. | 8 | Asbestos Cement | 328 | 46 | 1.14 out of 5 | $442 | 145,164 |
| Distribution Main | 3561 | P-23 | WW | Crossbow La. | 8 | Asbestos Cement | 182 | 46 | 1.14 out of 5 | $442 | 80,286 |
| Distribution Main | 3562 | P-23 | WW | Crossbow La. | 8 | Asbestos Cement | 37 | 46 | 1.14 out of 5 | $442 | 16,440 |
| Distribution Main | 4743 | P-24 | WW | Crossbow La. | 8 | Ductile Iron | 214 | 28 | 0.14 out of 5 | $442 | 94,635 |
| Distribution Main | 4746 | P-1939 | WW | Crossbow La. | 8 | Ductile Iron | 277 | 28 | 0.14 out of 5 | $442 | 122,329 |
| Distribution Main | 8628 | P-25 | WW | Crossbow La. | 8 | Asbestos Cement | 235 | 46 | 1.85 out of 5 | $442 | 103,710 |
| Distribution Main | 11263 | P-1939 | WW | Crossbow La. | 8 | Ductile Iron | 9 | 28 | 0.14 out of 5 | $442 | 4,045 |
| Distribution Main | 11486 | P-25 | WW | Crossbow La. | 8 | Asbestos Cement | 230 | 46 | 1.14 out of 5 | $442 | 101,640 |
| Distribution Main | 2886 | P-652 | WW | Crossen St. | 6 | Cast Iron | 278 | 134 | 2.57 out of 5 | $442 | 122,736 |
| Distribution Main | 3108 | P-656 | WW | Crossen St. | 4 | Cast Iron | 15 | 134 | 3.29 out of 5 | $442 | 6,508 |
| Distribution Main | 4322 | P-656 | WW | Crossen St. | 4 | Cast Iron | 345 | 134 | 3.29 out of 5 | $442 | 152,635 |
| Distribution Main | 4323 | P-656 | WW | Crossen St. | 4 | Cast Iron | 47 | 134 | 3.29 out of 5 | $442 | 20,906 |
| Distribution Main | 8908 | P-218 | WW | Crossland Rd | 8 | Ductile Iron | 256 | 9 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 8917 | P-167 | WW | Crossland Rd | 8 | Ductile Iron | 225 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8921 | P-159 | WW | Crossland Rd | 8 | Ductile Iron | 242 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9394 | P-1721 | WW | Crossland Rd | 8 | Ductile Iron | 40 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9403 | P-1724 | WW | Crossland Rd | 8 | Ductile Iron | 157 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9404 | P-1724 | WW | Crossland Rd | 8 | Ductile Iron | 24 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9411 | P-1731 | WW | Crossland Rd | 8 | Ductile Iron | 241 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10833 | P-145 | WW | Crossland Rd | 8 | Ductile Iron | 257 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10927 | P-220 | WW | Crossland Rd | 8 | Ductile Iron | 218 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11525 | P-1724 | WW | Crossland Rd | 8 | Ductile Iron | 55 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 6557 | P-236 | WW | Crossland Rd. | 6 | Asbestos Cement | 649 | 80 | 2 out of 5 | $442 | 286,725 |
| Transmission Main | 10367 | P-76 | WW | Crudale Dr (Off-Road) | 12 | Ductile Iron | 369 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10368 | P-76 | WW | Crudale Dr (Off-Road) | 12 | Ductile Iron | 16 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1325 | P-75 | WW | Crudale Dr. | 12 | Ductile Iron | 399 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2805 | P-76 | WW | Crudale Dr. | 12 | Ductile Iron | 411 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2803 | P-74 | WW | Crudale Rd. | 12 | Ductile Iron | 9 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2804 | P-74 | WW | Crudale Rd. | 12 | Ductile Iron | 491 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10957 | P-71 | WW | Crudale Rd. | 12 | Ductile Iron | 93 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10958 | P-71 | WW | Crudale Rd. | 12 | Ductile Iron | 80 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1777 | P-1052 | WW | Curson St. | 6 | Cast Iron | 138 | 129 | 2.57 out of 5 | $442 | 61,053 |
| Distribution Main | 1778 | P-1052 | WW | Curson St. | 6 | Cast Iron | 150 | 129 | 2.57 out of 5 | $442 | 66,173 |
| Distribution Main | 1964 | P-1052 | WW | Curson St. | 6 | Cast Iron | 21 | 129 | 2.57 out of 5 | $442 | 9,228 |
| Distribution Main | 1965 | P-1051 | WW | Curson St. | 4 | Cast Iron | 278 | 84 | 3.14 out of 5 | $442 | 123,062 |
| Distribution Main | 1966 | P-753 | WW | Curson St. | 4 | Cast Iron | 111 | 84 | 3.14 out of 5 | $442 | 49,057 |
| Distribution Main | 1967 | P-1052 | WW | Curson St. | 6 | Cast Iron | 220 | 129 | 2.57 out of 5 | $442 | 97,327 |
| Distribution Main | 2383 |  | WW | Curson St. | 6 | Cast Iron | 238 | 72 | 2.28 out of 5 | $442 | 105,055 |
| Distribution Main | 2384 | P-758 | WW | Curson St. | 8 | Asbestos Cement | 512 | 72 | 1.29 out of 5 | $442 | 226,438 |
| Distribution Main | 2385 | P-758 | WW | Curson St. | 8 | Asbestos Cement | 33 | 72 | 1.29 out of 5 | $442 | 14,556 |
| Distribution Main | 3254 | P-1052 | WW | Curson St. | 4 | Cast Iron | 16 | 84 | 3.14 out of 5 | $442 | 7,182 |
| Distribution Main | 3264 | P-1291 | WW | Curson St. | 8 | Ductile Iron | 336 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3794 |  | WW | Curson St. | 6 | Cast Iron | 4 | 72 | 2.28 out of 5 | $442 | 1,810 |
| Distribution Main | 3805 | P-1055 | WW | Curson St. | 6 | Cast Iron | 31 | 72 | 2.28 out of 5 | $442 | 13,846 |
| Distribution Main | 3806 | P-1055 | WW | Curson St. | 6 | Cast Iron | 301 | 72 | 2.28 out of 5 | $442 | 133,119 |
| Distribution Main | 9521 | P-753 | WW | Curson St. | 4 | Cast Iron | 35 | 84 | 3.14 out of 5 | $442 | 15,501 |
| Distribution Main | 9522 | P-753 | WW | Curson St. | 4 | Cast Iron | 46 | 84 | 3.14 out of 5 | $442 | 20,175 |
| Distribution Main | 9649 | P-757 | WW | Curson St. | 8 | Asbestos Cement | 60 | 72 | 1.29 out of 5 | $442 | 26,428 |
| Distribution Main | 11021 | P-1052 | WW | Curson St. | 6 | Cast Iron | 15 | 129 | 2.57 out of 5 | $442 | 6,780 |
| Distribution Main | 11992 | P-1052 | WW | Curson St. | 6 | Cast Iron | 6 | 129 | 2.57 out of 5 | $442 | 2,853 |
| Transmission Main | 3190 | P-853 | WW | Cyr Ct. | 12 | Ductile Iron | 104 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3191 | P-853 | WW | Cyr Ct. | 12 | Ductile Iron | 212 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8648 | P-1327 | WW | Dairy Farm Rd. | 12 | Ductile Iron | 456 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10730 | P-227 | WW | Daisy St | 8 | Ductile Iron | 240 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11713 | P-228 | WW | Daisy St | 8 | Ductile Iron | 107 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4327 |  | WW | Dale Ave | 8 | Ductile Iron | 36 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9624 | P-1968 | WW | Dale Ave | 1 | Copper | 313 | 71 | 2.43 out of 5 | $442 | 138,184 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10150 | | WW | Dale Ave | 8 | Ductile Iron | 20 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10768 | P-10061 | WW | Danby St | 8 | Ductile Iron | 80 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4331 | P-1492 | WW | Danby St. | 8 | Ductile Iron | 133 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10607 | P-408 | WW | Davis St | 8 | Ductile Iron | 211 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10608 | P-408 | WW | Davis St | 8 | Ductile Iron | 388 | 2 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10159 | | WW | Dawes St | 6 | PVC | 5 | 28 | 1.14 out of 5 | $442 | 2,387 |
| Distribution Main | 162 | P-1480 | WW | Dawes St. | 1 | Copper | 215 | 84 | 2.57 out of 5 | $442 | 94,825 |
| Distribution Main | 4082 | P-519 | WW | Dawes St. | 6 | PVC | 73 | 28 | 1.14 out of 5 | $442 | 32,261 |
| Distribution Main | 4083 | P-519 | WW | Dawes St. | 6 | PVC | 297 | 28 | 1.14 out of 5 | $442 | 131,489 |
| Distribution Main | 10156 | P-10029 | WW | Dawes St. | 6 | PVC | 184 | 33 | 1.14 out of 5 | $442 | 81,463 |
| Distribution Main | 11241 | P-519 | WW | Dawes St. | 6 | PVC | 233 | 28 | 1.14 out of 5 | $442 | 102,793 |
| Distribution Main | 657 | P-453 | WW | Deborah Ct. | 6 | Ductile Iron | 216 | 29 | 0.85 out of 5 | $442 | 95,288 |
| Distribution Main | 658 | P-453 | WW | Deborah Ct. | 6 | Ductile Iron | 238 | 29 | 0.85 out of 5 | $442 | 105,123 |
| Distribution Main | 2210 | P-185 | WW | Deer Run Rd | 8 | PVC | 225 | 35 | 0.43 out of 5 | $442 | 99,661 |
| Distribution Main | 279 | P-1142 | WW | Deerfield Dr. | 8 | Asbestos Cement | 466 | 47 | 1.14 out of 5 | $442 | 205,792 |
| Distribution Main | 280 | P-1142 | WW | Deerfield Dr. | 8 | Asbestos Cement | 136 | 47 | 1.14 out of 5 | $442 | 59,933 |
| Distribution Main | 3122 | P-1146 | WW | Deerfield Dr. | 8 | Asbestos Cement | 293 | 47 | 1.14 out of 5 | $442 | 129,492 |
| Distribution Main | 3123 | P-1146 | WW | Deerfield Dr. | 8 | Asbestos Cement | 215 | 47 | 1.14 out of 5 | $442 | 95,101 |
| Distribution Main | 4819 | P-1145 | WW | Deerfield Dr. | 8 | Asbestos Cement | 269 | 47 | 1.14 out of 5 | $442 | 118,707 |
| Distribution Main | 4821 | P-1148 | WW | Deerfield Dr. | 8 | Asbestos Cement | 325 | 47 | 1.14 out of 5 | $442 | 143,811 |
| Distribution Main | 4823 | P-1144 | WW | Deerfield Dr. | 8 | Asbestos Cement | 315 | 47 | 1.14 out of 5 | $442 | 139,441 |
| Distribution Main | 10122 | P-1141 | WW | Deerfield Dr. | 8 | Asbestos Cement | 20 | 47 | 1.14 out of 5 | $442 | 8,818 |
| Distribution Main | 10034 | P-1766 | WW | Diaz Ct | 8 | Ductile Iron | 207 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10044 | P-1769 | WW | Dimasi Ct | 8 | Ductile Iron | 298 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1696 | P-1013 | WW | Dinsdale Ct. | 2 | Galvanized Iron | 364 | 89 | 4.14 out of 5 | $442 | 160,874 |
| Distribution Main | 104 | P-1217 | WW | Douglas St | 4 | Cast Iron | 593 | 70 | 3 out of 5 | $442 | 262,172 |
| Distribution Main | 3729 | P-1217 | WW | Douglas St. | 4 | Cast Iron | 29 | 70 | 3 out of 5 | $442 | 12,757 |
| Distribution Main | 4679 | P-530 | WW | Dounetos St. | 8 | Asbestos Cement | 643 | 65 | 1.29 out of 5 | $442 | 284,300 |
| Distribution Main | 4680 | P-530 | WW | Dounetos St. | 8 | Asbestos Cement | 25 | 65 | 1.29 out of 5 | $442 | 11,072 |
| Distribution Main | 4818 | P-528 | WW | Dounetos St. | 6 | Asbestos Cement | 267 | 65 | 2 out of 5 | $442 | 117,986 |
| Distribution Main | 1436 | P-1930 | WW | Downing Dr. | 6 | Asbestos Cement | 252 | 41 | 1.85 out of 5 | $442 | 111,165 |
| Distribution Main | 1437 | P-1930 | WW | Downing Dr. | 6 | Asbestos Cement | 24 | 41 | 1.85 out of 5 | $442 | 10,586 |
| Distribution Main | 1561 | P-804 | WW | Downing Dr. | 6 | Asbestos Cement | 66 | 41 | 1.85 out of 5 | $442 | 29,288 |
| Distribution Main | 1562 | P-804 | WW | Downing Dr. | 6 | Asbestos Cement | 62 | 41 | 1.85 out of 5 | $442 | 27,368 |
| Distribution Main | 1568 | P-1932 | WW | Downing Dr. | 6 | Unknown | 139 | 41 | 1 out of 5 | $442 | 61,500 |
| Distribution Main | 1569 | P-1930 | WW | Downing Dr. | 6 | Asbestos Cement | 9 | 41 | 1.85 out of 5 | $442 | 3,996 |
| Transmission Main | 382 | P-1530 | WW | Drawbridge Dr. | 16 | Ductile Iron | 315 | 28 | 0.14 out of 5 | $442 | 139,146 |
| Transmission Main | 1354 | P-1711 | WW | Drawbridge Dr. | 16 | Ductile Iron | 33 | 28 | 0.14 out of 5 | $442 | 14,708 |
| Transmission Main | 1355 | P-1711 | WW | Drawbridge Dr. | 16 | Ductile Iron | 147 | 28 | 0.14 out of 5 | $442 | 64,920 |
| Distribution Main | 1803 | P-1937 | WW | Drawbridge Dr. | 8 | Ductile Iron | 122 | 28 | 0.14 out of 5 | $442 | 54,088 |
| Transmission Main | 1804 | P-12 | WW | Drawbridge Dr. | 16 | Ductile Iron | 235 | 28 | 0.14 out of 5 | $442 | 103,833 |
| Transmission Main | 2422 | P-1936 | WW | Drawbridge Dr. | 16 | Ductile Iron | 9 | 28 | 0.14 out of 5 | $442 | 4,105 |
| Transmission Main | 2423 | P-1936 | WW | Drawbridge Dr. | 16 | Ductile Iron | 10 | 28 | 0.14 out of 5 | $442 | 4,596 |
| Distribution Main | 2434 | P-1386 | WW | Drawbridge Dr. | 8 | Ductile Iron | 286 | 28 | 0.14 out of 5 | $442 | 126,377 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2436 | P-1387 | WW | Drawbridge Dr. | 8 | Ductile Iron | 4 | 28 | 0.14 out of 5 | $442 | 1,764 |
| Distribution Main | 2441 | P-1387 | WW | Drawbridge Dr. | 8 | Ductile Iron | 233 | 28 | 0.14 out of 5 | $442 | 103,072 |
| Distribution Main | 2442 | P-1387 | WW | Drawbridge Dr. | 8 | Ductile Iron | 19 | 28 | 0.14 out of 5 | $442 | 8,461 |
| Transmission Main | 2444 | P-17 | WW | Drawbridge Dr. | 16 | Ductile Iron | 125 | 28 | 0.14 out of 5 | $442 | 55,381 |
| Transmission Main | 2445 | P-17 | WW | Drawbridge Dr. | 16 | Ductile Iron | 230 | 28 | 0.14 out of 5 | $442 | 101,676 |
| Transmission Main | 2446 | P-18 | WW | Drawbridge Dr. | 16 | Ductile Iron | 176 | 28 | 0.14 out of 5 | $442 | 77,619 |
| Transmission Main | 2447 | P-18 | WW | Drawbridge Dr. | 16 | Ductile Iron | 428 | 28 | 0.14 out of 5 | $442 | 189,081 |
| Transmission Main | 4448 | P-1378 | WW | Drawbridge Dr. | 16 | Ductile Iron | 293 | 28 | 0.14 out of 5 | $442 | 129,429 |
| Transmission Main | 4744 | P-1379 | WW | Drawbridge Dr. | 16 | Asbestos Cement | 70 | 46 | 1.14 out of 5 | $442 | 30,984 |
| Transmission Main | 4745 | P-1379 | WW | Drawbridge Dr. | 16 | Asbestos Cement | 3 | 46 | 1.14 out of 5 | $442 | 1,131 |
| Transmission Main | 12069 | P-1711 | WW | Drawbridge Dr. | 16 | Ductile Iron | 6 | 28 | 0.14 out of 5 | $442 | 2,461 |
| Distribution Main | 1725 | P-1491 | WW | Duke St. | 8 | Ductile Iron | 129 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3100 | P-1490 | WW | Duke St. | 6 | Ductile Iron | 7 | 15 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 4298 | P-1490 | WW | Duke St. | 8 | Ductile Iron | 388 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4299 | P-1490 | WW | Duke St. | 8 | Ductile Iron | 7 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10288 | P-1600 | WW | Dyer St | 8 | Ductile Iron | 243 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10291 | P-1600 | WW | Dyer St | 6 | Ductile Iron | 6 | 5 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10443 | | WW | Dyer St | 8 | Ductile Iron | 21 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10444 | | WW | Dyer St | 8 | Ductile Iron | 107 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10258 | | WW | E Greenwich Av | | Unknown | 5 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 8613 | P-1342 | WW | E Main St | 6 | Ductile Iron | 14 | 12 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8627 | P-1342 | WW | E Main St | 8 | Ductile Iron | 6 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10325 | | WW | E Main St | 4 | Cast Iron | 39 | 134 | 3.29 out of 5 | $442 | 17,455 |
| Distribution Main | 8427 | P-1803 | WW | Eagle St | 8 | Ductile Iron | 20 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10772 | P-366 | WW | Earl St | 8 | Ductile Iron | 347 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10773 | P-366 | WW | Earl St | 8 | Ductile Iron | 295 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11724 | P-343 | WW | Earl St | 8 | Ductile Iron | 286 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11725 | P-1988 | WW | Earl St | 8 | Ductile Iron | 192 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11726 | P-1988 | WW | Earl St | 8 | Ductile Iron | 41 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11727 | P-353 | WW | Earl St | 8 | Ductile Iron | 346 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11728 | P-360 | WW | Earl St | 8 | Ductile Iron | 103 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11729 | P-10066 | WW | Earl St | 8 | Ductile Iron | 194 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12034 | P-366 | WW | Earl St | 8 | Ductile Iron | 484 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12035 | P-1988 | WW | Earl St | 8 | Ductile Iron | 174 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12036 | P-349 | WW | Earl St | 8 | Ductile Iron | 122 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12043 | P-343 | WW | Earl St | 8 | Ductile Iron | 102 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12146 | P-366 | WW | Earl St | 8 | Ductile Iron | 161 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12161 | P-366 | WW | Earl St | 8 | Ductile Iron | 96 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12204 | P-343 | WW | Earl St | 8 | Ductile Iron | 236 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 394 | | WW | Earl St. | 6 | Cast Iron | 9 | 84 | 2.43 out of 5 | $442 | 4,059 |
| Distribution Main | 1045 | | WW | Earl St. | 6 | Cast Iron | 356 | 84 | 2.43 out of 5 | $442 | 157,439 |
| Distribution Main | 1046 | | WW | Earl St. | 6 | Cast Iron | 492 | 84 | 2.43 out of 5 | $442 | 217,448 |
| Distribution Main | 11900 | | WW | Earl St. | 6 | Cast Iron | 57 | 84 | 2.43 out of 5 | $442 | 25,139 |
| Distribution Main | 2156 | P-1156 | WW | Easement | 8 | PVC | 402 | 33 | 0.43 out of 5 | $442 | 177,865 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2181 | P-1450 | WW | Easement | 10 | PVC | 1,390 | 31 | 0.43 out of 5 | $442 | 614,373 |
| Transmission Main | 3192 | P-1268 | WW | Easement | 12 | Ductile Iron | 405 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4608 | P-1270 | WW | Easement | 8 | Ductile Iron | 294 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4609 | P-1270 | WW | Easement | 8 | Ductile Iron | 15 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4613 | P-1471 | WW | Easement | 8 | Asbestos Cement | 245 | 50 | 1.14 out of 5 | $442 | 108,113 |
| Distribution Main | 4614 | P-1471 | WW | Easement | 8 | Asbestos Cement | 4 | 50 | 1.14 out of 5 | $442 | 1,578 |
| Distribution Main | 11102 | P-1450 | WW | Easement | 10 | PVC | 7 | 31 | 0.43 out of 5 | $442 | 3,185 |
| Transmission Main | 1159 | P-80 | WW | Easement Connection | 16 | Ductile Iron | 8 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1160 | P-80 | WW | Easement Connection | 16 | Ductile Iron | 1,401 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1161 | P-80 | WW | Easement Connection | 16 | Ductile Iron | 4 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9647 | P-1625 | WW | Easement- Wildberry | 8 | Ductile Iron | 320 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10287 | | WW | Easement-Flat Top Condos | 8 | Ductile Iron | 587 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10289 | | WW | Easement-Flat Top Condos | 6 | Ductile Iron | 4 | 5 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10290 | | WW | Easement-Flat Top Condos | 6 | Ductile Iron | 3 | 5 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 10059 | P-2850 | WW | East Ave | 16 | Ductile Iron | 81 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11638 | P-230 | WW | East Ave | 16 | Ductile Iron | 34 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9697 | P-10006 | WW | East Greenwich Ave | 12 | Ductile Iron | 21 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 10144 | P-2970 | WW | East Greenwich Ave | 12 | Ductile Iron | 12 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 10255 | | WW | East Greenwich Ave | 8 | Asbestos Cement | 4 | 43 | 1.14 out of 5 | $442 | 1,906 |
| Transmission Main | 10256 | | WW | East Greenwich Ave | 12 | Ductile Iron | 3 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 10257 | | WW | East Greenwich Ave | 12 | Ductile Iron | 3 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 10259 | | WW | East Greenwich Ave | 6 | Asbestos Cement | 2 | UNK | 1.56 out of 5 | $442 | 1,058 |
| Distribution Main | 10266 | | WW | East Greenwich Ave | 8 | Asbestos Cement | 11 | 43 | 0.85 out of 5 | $442 | 4,961 |
| Transmission Main | 278 | P-1197 | WW | East Greenwich Ave. | 12 | Asbestos Cement | 141 | 19 | 0.85 out of 5 | N/A | $0 |
| Transmission Main | 281 | P-1411 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 274 | 50 | 1.14 out of 5 | $442 | 121,281 |
| Transmission Main | 282 | P-1411 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 16 | 50 | 1.14 out of 5 | $442 | 6,976 |
| Transmission Main | 286 | P-1411 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 227 | 50 | 1.14 out of 5 | $442 | 100,490 |
| Transmission Main | 287 | P-1435 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 87 | 50 | 1.14 out of 5 | $442 | 38,555 |
| Transmission Main | 288 | P-1197 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 485 | 19 | 0.85 out of 5 | N/A | $0 |
| Transmission Main | 390 | P-1188 | WW | East Greenwich Ave. | 12 | Unknown | 10 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 536 | | WW | East Greenwich Ave. | 8 | Ductile Iron | 34 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 537 | P-1157 | WW | East Greenwich Ave. | 12 | Ductile Iron | 793 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 538 | P-10017 | WW | East Greenwich Ave. | 8 | Ductile Iron | 23 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 539 | P-1414 | WW | East Greenwich Ave. | 12 | Ductile Iron | 266 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 540 | P-1415 | WW | East Greenwich Ave. | 12 | Ductile Iron | 248 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1105 | P-1296 | WW | East Greenwich Ave. | 12 | Ductile Iron | 468 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1106 | P-89 | WW | East Greenwich Ave. | 12 | Ductile Iron | 9 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1107 | P-116 | WW | East Greenwich Ave. | 12 | Ductile Iron | 223 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1108 | P-116 | WW | East Greenwich Ave. | 12 | Ductile Iron | 119 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1344 | P-1435 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 541 | 50 | 1.14 out of 5 | $442 | 239,058 |
| Transmission Main | 1345 | P-1428 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 375 | 50 | 1.14 out of 5 | $442 | 165,943 |
| Transmission Main | 1346 | P-1428 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 9 | 50 | 1.14 out of 5 | $442 | 3,904 |
| Transmission Main | 1347 | P-1421 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 242 | 50 | 1.14 out of 5 | $442 | 107,179 |
| Transmission Main | 1350 | P-1197 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 189 | 19 | 0.85 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 1352 | P-1197 | WW | East Greenwich Ave. | 12 | Asbestos Cement | 20 | 19 | 0.85 out of 5 | N/A | $0 |
| Transmission Main | 2161 | P-87 | WW | East Greenwich Ave. | 12 | Ductile Iron | 76 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2162 | P-81 | WW | East Greenwich Ave. | 12 | Ductile Iron | 23 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2163 | P-1436 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 336 | 50 | 1.14 out of 5 | $442 | 148,385 |
| Transmission Main | 2164 | P-1436 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 166 | 50 | 1.14 out of 5 | $442 | 73,514 |
| Transmission Main | 2165 | P-116 | WW | East Greenwich Ave. | 12 | Ductile Iron | 78 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2166 | P-1400 | WW | East Greenwich Ave. | 12 | Ductile Iron | 28 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2167 | P-1182 | WW | East Greenwich Ave. | 12 | Ductile Iron | 5 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2168 | P-1182 | WW | East Greenwich Ave. | 12 | Ductile Iron | 262 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2169 | P-1418 | WW | East Greenwich Ave. | 12 | Ductile Iron | 3 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2170 | P-116 | WW | East Greenwich Ave. | 12 | Ductile Iron | 7 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2171 | P-1418 | WW | East Greenwich Ave. | 12 | Ductile Iron | 567 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2175 | P-1418 | WW | East Greenwich Ave. | 12 | Ductile Iron | 378 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2177 | P-187 | WW | East Greenwich Ave. | 12 | Ductile Iron | 375 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2178 | P-187 | WW | East Greenwich Ave. | 12 | Ductile Iron | 570 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2254 | P-1404 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 151 | 50 | 1.14 out of 5 | $442 | 66,708 |
| Transmission Main | 2255 | P-1404 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 255 | 50 | 1.14 out of 5 | $442 | 112,538 |
| Transmission Main | 2305 | P-87 | WW | East Greenwich Ave. | 12 | Ductile Iron | 116 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2308 | P-86 | WW | East Greenwich Ave. | 12 | Ductile Iron | 170 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2309 | P-81 | WW | East Greenwich Ave. | 12 | Ductile Iron | 16 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2310 | P-1296 | WW | East Greenwich Ave. | 12 | Ductile Iron | 17 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2311 | P-89 | WW | East Greenwich Ave. | 12 | Ductile Iron | 232 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2312 | P-89 | WW | East Greenwich Ave. | 12 | Ductile Iron | 5 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2313 | P-116 | WW | East Greenwich Ave. | 12 | Ductile Iron | 8 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2315 | P-116 | WW | East Greenwich Ave. | 12 | Ductile Iron | 8 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2317 | P-1418 | WW | East Greenwich Ave. | 12 | Ductile Iron | 6 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2333 | | WW | East Greenwich Ave. | 6 | Unknown | 11 | 71 | 1.14 out of 5 | $442 | 4,825 |
| Transmission Main | 2334 | P-1295 | WW | East Greenwich Ave. | 12 | Ductile Iron | 300 | 29 | 0.14 out of 5 | $442 | 132,639 |
| Transmission Main | 2335 | P-1295 | WW | East Greenwich Ave. | 12 | Ductile Iron | 335 | 29 | 0.14 out of 5 | $442 | 148,045 |
| Transmission Main | 2336 | P-1404 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 174 | 50 | 1.14 out of 5 | $442 | 76,751 |
| Transmission Main | 2337 | P-1404 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 104 | 50 | 1.14 out of 5 | $442 | 45,914 |
| Distribution Main | 2343 | P-1158 | WW | East Greenwich Ave. | 6 | Asbestos Cement | 249 | 71 | 2 out of 5 | $442 | 110,064 |
| Distribution Main | 2344 | P-1158 | WW | East Greenwich Ave. | 6 | Asbestos Cement | 27 | 71 | 2 out of 5 | $442 | 11,944 |
| Distribution Main | 3894 | P-1139 | WW | East Greenwich Ave. | 4 | Cast Iron | 352 | 124 | 3.29 out of 5 | $442 | 155,493 |
| Distribution Main | 3895 | P-1139 | WW | East Greenwich Ave. | 4 | Cast Iron | 486 | 124 | 3.29 out of 5 | $442 | 214,999 |
| Distribution Main | 4688 | P-1140 | WW | East Greenwich Ave. | 6 | Asbestos Cement | 138 | 71 | 2 out of 5 | $442 | 61,014 |
| Transmission Main | 4696 | P-2743 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 74 | 50 | 1.14 out of 5 | $442 | 32,572 |
| Transmission Main | 4699 | P-1404 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 498 | 50 | 1.14 out of 5 | $442 | 220,080 |
| Transmission Main | 4700 | P-1404 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 580 | 50 | 1.14 out of 5 | $442 | 256,566 |
| Transmission Main | 4701 | P-1404 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 447 | 50 | 1.14 out of 5 | $442 | 197,497 |
| Distribution Main | 4781 | P-1599 | WW | East Greenwich Ave. | 6 | Asbestos Cement | 7 | 71 | 2 out of 5 | $442 | 2,932 |
| Distribution Main | 4782 | P-1599 | WW | East Greenwich Ave. | 6 | Asbestos Cement | 295 | 71 | 2 out of 5 | $442 | 130,462 |
| Transmission Main | 8512 | P-187 | WW | East Greenwich Ave. | 12 | Ductile Iron | 229 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 8513 | P-187 | WW | East Greenwich Ave. | 12 | Ductile Iron | 142 | 21 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 8514 | P-187 | WW | East Greenwich Ave. | 12 | Ductile Iron | 232 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 8515 | P-187 | WW | East Greenwich Ave. | 12 | Ductile Iron | 578 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9496 | P-89 | WW | East Greenwich Ave. | 12 | Ductile Iron | 61 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9919 | P-1294 | WW | East Greenwich Ave. | 12 | PVC | 419 | 19 | 0.28 out of 5 | N/A | $0 |
| Transmission Main | 10087 | P-1157 | WW | East Greenwich Ave. | 12 | Ductile Iron | 135 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10253 | P-1197 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 13 | 19 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 10254 | | WW | East Greenwich Ave. | 8 | Ductile Iron | 2 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 10436 | P-1197 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 6 | 19 | 0.85 out of 5 | N/A | $0 |
| Transmission Main | 10437 | P-1151 | WW | East Greenwich Ave. | 12 | Asbestos Cement | 45 | 19 | 0.85 out of 5 | N/A | $0 |
| Transmission Main | 10438 | P-1151 | WW | East Greenwich Ave. | 12 | Asbestos Cement | 93 | 19 | 0.85 out of 5 | N/A | $0 |
| Transmission Main | 11063 | P-1436 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 12 | 50 | 1.14 out of 5 | $442 | 5,188 |
| Transmission Main | 11127 | P-1197 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 16 | 19 | 0.85 out of 5 | N/A | $0 |
| Transmission Main | 11156 | P-1436 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 203 | 50 | 1.14 out of 5 | $442 | 89,923 |
| Transmission Main | 11157 | P-187 | WW | East Greenwich Ave. | 12 | Ductile Iron | 204 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11158 | P-1404 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 7 | 50 | 1.14 out of 5 | $442 | 3,061 |
| Transmission Main | 11159 | P-1404 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 6 | 50 | 1.14 out of 5 | $442 | 2,736 |
| Transmission Main | 11162 | P-1404 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 148 | 50 | 1.14 out of 5 | $442 | 65,435 |
| Transmission Main | 11473 | P-187 | WW | East Greenwich Ave. | 12 | Ductile Iron | 144 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11623 | P-1687 | WW | East Greenwich Ave. | 12 | PVC | 147 | 19 | 0.28 out of 5 | N/A | $0 |
| Transmission Main | 11624 | P-1579 | WW | East Greenwich Ave. | 12 | PVC | 3 | 19 | 0.28 out of 5 | N/A | $0 |
| Transmission Main | 12074 | P-1404 | WW | East Greenwich Ave. | 20 | Asbestos Cement | 150 | 50 | 1.14 out of 5 | $442 | 66,413 |
| Transmission Main | 12094 | P-187 | WW | East Greenwich Ave. | 12 | Ductile Iron | 45 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12095 | P-187 | WW | East Greenwich Ave. | 12 | Ductile Iron | 37 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 12155 | P-1415 | WW | East Greenwich Ave. | 12 | Ductile Iron | 2 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 325 | P-1350 | WW | East Main St. | 6 | Cast Iron | 283 | 133 | 2.57 out of 5 | $442 | 124,935 |
| Distribution Main | 326 | P-1350 | WW | East Main St. | 6 | Cast Iron | 14 | 133 | 2.57 out of 5 | $442 | 6,257 |
| Distribution Main | 435 | P-986 | WW | East Main St. | 6 | Cast Iron | 188 | 133 | 2.57 out of 5 | $442 | 83,030 |
| Distribution Main | 436 | P-1351 | WW | East Main St. | 6 | Cast Iron | 390 | 134 | 2.57 out of 5 | $442 | 172,200 |
| Distribution Main | 437 | P-1351 | WW | East Main St. | 6 | Cast Iron | 9 | 133 | 2.57 out of 5 | $442 | 4,189 |
| Distribution Main | 441 | P-995 | WW | East Main St. | 6 | Cast Iron | 214 | 133 | 2.57 out of 5 | $442 | 94,532 |
| Distribution Main | 958 | P-1350 | WW | East Main St. | 6 | Cast Iron | 26 | 133 | 2.57 out of 5 | $442 | 11,434 |
| Transmission Main | 1168 | P-1005 | WW | East Main St. | 12 | Asbestos Cement | 377 | 68 | 1.29 out of 5 | $442 | 166,691 |
| Transmission Main | 1169 | P-1005 | WW | East Main St. | 12 | Asbestos Cement | 20 | 68 | 1.29 out of 5 | $442 | 8,786 |
| Distribution Main | 1692 | P-988 | WW | East Main St. | 6 | Cast Iron | 322 | 133 | 2.57 out of 5 | $442 | 142,535 |
| Distribution Main | 2206 | P-1351 | WW | East Main St. | 6 | Cast Iron | 90 | 134 | 2.57 out of 5 | $442 | 39,934 |
| Distribution Main | 3335 | P-995 | WW | East Main St. | 6 | Cast Iron | 8 | 133 | 2.57 out of 5 | $442 | 3,556 |
| Transmission Main | 3339 | P-1004 | WW | East Main St. | 12 | Asbestos Cement | 353 | 68 | 1.29 out of 5 | $442 | 156,094 |
| Transmission Main | 3340 | P-1004 | WW | East Main St. | 12 | Asbestos Cement | 438 | 68 | 1.29 out of 5 | $442 | 193,456 |
| Distribution Main | 12001 | P-1350 | WW | East Main St. | 6 | Cast Iron | 120 | 133 | 2.57 out of 5 | $442 | 53,076 |
| Distribution Main | 12002 | P-1350 | WW | East Main St. | 6 | Cast Iron | 233 | 133 | 2.57 out of 5 | $442 | 102,887 |
| Distribution Main | 128 | P-1955 | WW | East St. | 6 | Ductile Iron | 86 | 29 | 0.85 out of 5 | $442 | 38,112 |
| Distribution Main | 129 | P-1955 | WW | East St. | 6 | Ductile Iron | 141 | 29 | 0.85 out of 5 | $442 | 62,481 |
| Distribution Main | 133 | P-699 | WW | East St. | 6 | Ductile Iron | 23 | 29 | 0.85 out of 5 | $442 | 10,358 |
| Distribution Main | 3611 | P-700 | WW | East St. | 6 | Ductile Iron | 478 | 29 | 0.85 out of 5 | $442 | 211,447 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3761 | P-699 | WW | East St. | 6 | Ductile Iron | 244 | 29 | 0.85 out of 5 | $442 | 107,644 |
| Distribution Main | 8977 | | WW | Echo Ln | 8 | Ductile Iron | 5 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2245 | P-659 | WW | Eddy St. | 6 | Cast Iron | 424 | 134 | 2.57 out of 5 | $442 | 187,460 |
| Distribution Main | 4329 | P-660 | WW | Eddy St. | 6 | Cast Iron | 33 | 134 | 2.57 out of 5 | $442 | 14,618 |
| Distribution Main | 4330 | P-660 | WW | Eddy St. | 6 | Cast Iron | 447 | 134 | 2.57 out of 5 | $442 | 197,574 |
| Distribution Main | 10654 | P-385 | WW | Edge St | 6 | Ductile Iron | 15 | 2 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10655 | P-385 | WW | Edge St | 6 | Ductile Iron | 1 | 2 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10656 | P-385 | WW | Edge St | 8 | Ductile Iron | 5 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3539 | P-385 | WW | Edge St. | 6 | Ductile Iron | 260 | 31 | 0.85 out of 5 | $442 | 114,915 |
| Distribution Main | 3540 | | WW | Edge St. | 6 | Ductile Iron | 10 | 31 | 0.85 out of 5 | $442 | 4,225 |
| Distribution Main | 10652 | P-385 | WW | Edge St. | 6 | Ductile Iron | 18 | 2 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10653 | P-385 | WW | Edge St. | 6 | Ductile Iron | 16 | UNK | 0.71 out of 5 | $442 | 7,266 |
| Distribution Main | 10657 | P-374 | WW | Edith St | 8 | Ductile Iron | 589 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3549 | P-111 | WW | Edwards Ct. | 6 | Asbestos Cement | 139 | 52 | 1.85 out of 5 | $442 | 61,408 |
| Distribution Main | 10412 | P-606 | WW | Eileen Dr | 8 | Ductile Iron | 16 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10413 | P-606 | WW | Eileen Dr | 8 | Ductile Iron | 98 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9367 | P-606 | WW | Eileen Dr. | 8 | Ductile Iron | 17 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1793 | P-1854 | WW | Elbow St | 2 | Unknown | 269 | 34 | 1.57 out of 5 | $442 | 118,737 |
| Distribution Main | 4621 | P-94 | WW | Elizabeth Ct | 8 | Asbestos Cement | 15 | 49 | 1.14 out of 5 | $442 | 6,731 |
| Distribution Main | 5184 | P-94 | WW | Elizabeth Ct | 8 | Asbestos Cement | 418 | 49 | 1.14 out of 5 | $442 | 184,851 |
| Distribution Main | 1070 | P-1025 | WW | Ellison St. | 2 | Copper | 489 | 79 | 2.43 out of 5 | $442 | 216,100 |
| Distribution Main | 440 | P-987 | WW | Elm St. | 1 | Galvanized Iron | 30 | 91 | 3.43 out of 5 | $442 | 13,281 |
| Distribution Main | 3337 | P-987 | WW | Elm St. | 1 | Galvanized Iron | 207 | 91 | 3.43 out of 5 | $442 | 91,470 |
| Distribution Main | 8083 | P-1514 | WW | Emerson Ct | 8 | Ductile Iron | 312 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8084 | P-1514 | WW | Emerson Ct | 8 | Ductile Iron | 200 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9802 | P-1966 | WW | Emile St | 8 | Ductile Iron | 195 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1326 | P-75 | WW | Energy Way | 12 | Ductile Iron | 587 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1327 | | WW | Energy Way | 6 | PVC | 80 | UNK | 0.99 out of 5 | $442 | 35,578 |
| Transmission Main | 2806 | P-75 | WW | Energy Way | 12 | Ductile Iron | 72 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8928 | P-1718 | WW | Enfield Dr | 8 | Ductile Iron | 297 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8929 | P-1718 | WW | Enfield Dr | 8 | Ductile Iron | 263 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8930 | P-1719 | WW | Enfield Dr | 8 | Ductile Iron | 169 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8931 | P-1736 | WW | Enfield Dr | 8 | Ductile Iron | 278 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9395 | P-1718 | WW | Enfield Dr | 8 | Ductile Iron | 3 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10830 | P-1719 | WW | Enfield Dr | 8 | Ductile Iron | 150 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10831 | P-1719 | WW | Enfield Dr | 8 | Ductile Iron | 119 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10832 | P-196 | WW | Enfield Dr | 8 | Ductile Iron | 168 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11002 | P-1718 | WW | Enfield Dr | 8 | Ductile Iron | 2 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4279 | P-16 | WW | Enfield Dr. | 8 | Ductile Iron | 29 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1729 | P-648 | WW | Epworth Ave. | 6 | Cast Iron | 412 | 134 | 2.57 out of 5 | $442 | 182,181 |
| Distribution Main | 1730 | P-648 | WW | Epworth Ave. | 6 | Cast Iron | 368 | 134 | 2.57 out of 5 | $442 | 162,626 |
| Distribution Main | 3976 | P-649 | WW | Epworth Ave. | 4 | Cast Iron | 257 | 134 | 3.29 out of 5 | $442 | 113,561 |
| Distribution Main | 4003 | P-649 | WW | Epworth Ave. | 4 | Cast Iron | 23 | 134 | 3.29 out of 5 | $442 | 10,093 |
| Distribution Main | 12000 | P-648 | WW | Epworth Ave. | 6 | Cast Iron | 34 | 134 | 2.57 out of 5 | $442 | 14,886 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2696 | P-8028 | WW | Ernest St. | 8 | Ductile Iron | 350 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3896 | | WW | Esmond St. | 6 | Asbestos Cement | 9 | 69 | 2 out of 5 | $442 | 3,777 |
| Distribution Main | 4689 | P-1591 | WW | Esmond St. | 6 | Asbestos Cement | 135 | 69 | 2 out of 5 | $442 | 59,660 |
| Distribution Main | 4833 | P-1165 | WW | Esmond St. | 6 | Asbestos Cement | 190 | 69 | 2 out of 5 | $442 | 84,103 |
| Distribution Main | 4834 | P-1165 | WW | Esmond St. | 6 | Asbestos Cement | 419 | 69 | 2 out of 5 | $442 | 185,161 |
| Distribution Main | 11261 | P-1591 | WW | Esmond St. | 6 | Asbestos Cement | 97 | 69 | 2 out of 5 | $442 | 42,910 |
| Distribution Main | 10621 | P-399 | WW | Ethel Av | 8 | Ductile Iron | 428 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10622 | P-399 | WW | Ethel Av | 8 | Ductile Iron | 341 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5141 | P-427 | WW | Evelyn St. | 6 | Asbestos Cement | 256 | 72 | 2 out of 5 | $442 | 113,137 |
| Distribution Main | 2540 | P-45 | WW | Exchange Rd. | 8 | Asbestos Cement | 244 | 50 | 1.14 out of 5 | $442 | 107,862 |
| Distribution Main | 2548 | P-33 | WW | Exchange Rd. | 8 | Asbestos Cement | 270 | 50 | 1.14 out of 5 | $442 | 119,144 |
| Distribution Main | 2549 | P-39 | WW | Exchange Rd. | 8 | Asbestos Cement | 441 | 50 | 1.14 out of 5 | $442 | 195,101 |
| Distribution Main | 2550 | P-39 | WW | Exchange Rd. | 8 | Asbestos Cement | 26 | 50 | 1.14 out of 5 | $442 | 11,325 |
| Distribution Main | 4644 | P-1377 | WW | Exchange Rd. | 8 | Asbestos Cement | 166 | 44 | 1.14 out of 5 | $442 | 73,322 |
| Distribution Main | 4966 | P-1377 | WW | Exchange Rd. | 8 | Asbestos Cement | 105 | 50 | 1.14 out of 5 | $442 | 46,541 |
| Distribution Main | 11259 | P-1377 | WW | Exchange Rd. | 8 | Asbestos Cement | 8 | 44 | 1.14 out of 5 | $442 | 3,533 |
| Distribution Main | 10797 | P-342 | WW | Factory St | 8 | Ductile Iron | 297 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10798 | P-340 | WW | Factory St | 8 | Ductile Iron | 259 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10875 | P-329 | WW | Factory St | 8 | Ductile Iron | 230 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10876 | P-333 | WW | Factory St | 8 | Ductile Iron | 252 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10877 | P-339 | WW | Factory St | 8 | Ductile Iron | 16 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11734 | P-340 | WW | Factory St | 8 | Ductile Iron | 187 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12039 | P-342 | WW | Factory St | 8 | Ductile Iron | 58 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12042 | P-342 | WW | Factory St | 8 | Ductile Iron | 219 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12044 | P-342 | WW | Factory St | 8 | Ductile Iron | 23 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12200 | P-342 | WW | Factory St | 8 | Ductile Iron | 170 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12202 | P-342 | WW | Factory St | 8 | Ductile Iron | 6 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12205 | P-342 | WW | Factory St | 8 | Ductile Iron | 29 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1164 | P-10070 | WW | Factory St. | 6 | Cast Iron | 197 | 134 | 2.57 out of 5 | $442 | 87,119 |
| Distribution Main | 1358 | | WW | Factory St. | 6 | Unknown | 19 | UNK | 0.71 out of 5 | $442 | 8,565 |
| Distribution Main | 1600 | P-1015 | WW | Factory St. | 6 | Cast Iron | 222 | 134 | 2.57 out of 5 | $442 | 97,941 |
| Distribution Main | 2684 | P-10070 | WW | Factory St. | 6 | Cast Iron | 161 | 134 | 2.57 out of 5 | $442 | 70,980 |
| Distribution Main | 2685 | P-1016 | WW | Factory St. | 6 | Cast Iron | 16 | 134 | 2.57 out of 5 | $442 | 7,158 |
| Distribution Main | 2686 | P-1016 | WW | Factory St. | 6 | Cast Iron | 161 | 134 | 2.57 out of 5 | $442 | 71,319 |
| Distribution Main | 2687 | | WW | Factory St. | 6 | Unknown | 142 | UNK | 0.71 out of 5 | $442 | 62,946 |
| Distribution Main | 2688 | | WW | Factory St. | 6 | Unknown | 161 | UNK | 0.71 out of 5 | $442 | 71,032 |
| Distribution Main | 3368 | P-1015 | WW | Factory St. | 6 | Cast Iron | 79 | 134 | 2.57 out of 5 | $442 | 34,750 |
| Distribution Main | 11184 | P-1016 | WW | Factory St. | 6 | Cast Iron | 10 | 134 | 2.57 out of 5 | $442 | 4,498 |
| Distribution Main | 12045 | P-10070 | WW | Factory St. | 6 | Cast Iron | 13 | 134 | 2.57 out of 5 | $442 | 5,939 |
| Distribution Main | 9975 | | WW | Factory Street | 6 | Ductile Iron | 38 | 12 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 12040 | | WW | Factory Street | 8 | Ductile Iron | 69 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 1978 | P-482 | WW | Fairgreen Dr. | 6 | Asbestos Cement | 265 | 63 | 2 out of 5 | $442 | 117,151 |
| Distribution Main | 1979 | P-482 | WW | Fairgreen Dr. | 6 | Asbestos Cement | 120 | 63 | 2 out of 5 | $442 | 53,115 |
| Distribution Main | 1981 | P-479 | WW | Fairgreen Dr. | 6 | Asbestos Cement | 27 | 63 | 2 out of 5 | $442 | 11,716 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3113 | P-479 | WW | Fairgreen Dr. | 6 | Asbestos Cement | 505 | 63 | 2 out of 5 | $442 | 223,303 |
| Distribution Main | 5073 | P-480 | WW | Fairgreen Dr. | 6 | Asbestos Cement | 238 | 63 | 2 out of 5 | $442 | 105,285 |
| Distribution Main | 5074 | P-482 | WW | Fairgreen Dr. | 6 | Asbestos Cement | 5 | 63 | 2 out of 5 | $442 | 2,126 |
| Distribution Main | 1973 | P-1096 | WW | Fairmont St. | 6 | Asbestos Cement | 198 | 57 | 1.85 out of 5 | $442 | 87,561 |
| Distribution Main | 4209 | P-1096 | WW | Fairmont St. | 6 | Asbestos Cement | 431 | 57 | 1.85 out of 5 | $442 | 190,484 |
| Distribution Main | 4210 | P-1096 | WW | Fairmont St. | 6 | Asbestos Cement | 14 | 57 | 1.85 out of 5 | $442 | 6,131 |
| Transmission Main | 8553 | P-1921 | WW | Fairview Ave | 20 | Ductile Iron | 32 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8554 | P-1258 | WW | Fairview Ave | 12 | Ductile Iron | 12 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8559 | | WW | Fairview Ave | 12 | Ductile Iron | 8 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8967 | P-1611 | WW | Fairview Ave | 16 | Ductile Iron | 249 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8968 | P-1611 | WW | Fairview Ave | 16 | Ductile Iron | 163 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8971 | | WW | Fairview Ave | 6 | Ductile Iron | 18 | 9 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8972 | P-1209 | WW | Fairview Ave | 6 | Ductile Iron | 27 | 9 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 8973 | P-1207 | WW | Fairview Ave | 16 | Ductile Iron | 173 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8974 | P-1205 | WW | Fairview Ave | 16 | Ductile Iron | 212 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8982 | P-1260 | WW | Fairview Ave | 16 | Ductile Iron | 121 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8983 | P-1260 | WW | Fairview Ave | 16 | Ductile Iron | 6 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8986 | P-1922 | WW | Fairview Ave | 12 | Ductile Iron | 15 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8987 | P-1258 | WW | Fairview Ave | 12 | Ductile Iron | 10 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8989 | P-1261 | WW | Fairview Ave | 12 | Ductile Iron | 180 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8990 | P-1261 | WW | Fairview Ave | 20 | Ductile Iron | 2 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9693 | P-1259 | WW | Fairview Ave | 16 | Ductile Iron | 87 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9694 | P-1922 | WW | Fairview Ave | 16 | Ductile Iron | 8 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11039 | P-1260 | WW | Fairview Ave | 16 | Ductile Iron | 2 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11040 | P-1258 | WW | Fairview Ave | 12 | Ductile Iron | 2 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11531 | P-1928 | WW | Fairview Ave | 16 | Ductile Iron | 67 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11533 | P-1207 | WW | Fairview Ave | 16 | Ductile Iron | 28 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11534 | P-1259 | WW | Fairview Ave | 16 | Ductile Iron | 126 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11535 | P-1923 | WW | Fairview Ave | 16 | Ductile Iron | 32 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12019 | P-1928 | WW | Fairview Ave | 16 | Ductile Iron | 59 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12100 | P-1207 | WW | Fairview Ave | 16 | Ductile Iron | 41 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3115 | P-1150 | WW | Fawn Ln. | 8 | Asbestos Cement | 634 | 42 | 1.14 out of 5 | $442 | 280,421 |
| Distribution Main | 3116 | P-1150 | WW | Fawn Ln. | 8 | Asbestos Cement | 104 | 42 | 1.14 out of 5 | $442 | 45,780 |
| Distribution Main | 10620 | P-402 | WW | Faxon St | 8 | Ductile Iron | 228 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8922 | P-155 | WW | Fernwood Dr | 8 | Ductile Iron | 466 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8923 | P-155 | WW | Fernwood Dr | 8 | Ductile Iron | 8 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9402 | P-1726 | WW | Fernwood Dr | 8 | Ductile Iron | 14 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3586 | P-1726 | WW | Fernwood Dr. | 8 | Ductile Iron | 22 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10796 | P-344 | WW | First St | 8 | Ductile Iron | 327 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10038 | P-251 | WW | Fiume St | 8 | Ductile Iron | 662 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10039 | P-252 | WW | Fiume St | 8 | Ductile Iron | 240 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1104 | P-88 | WW | Flanders Dr. | 12 | Ductile Iron | 425 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2306 | P-88 | WW | Flanders Dr. | 8 | Ductile Iron | 7 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2307 | P-88 | WW | Flanders Dr. | 8 | Ductile Iron | 20 | 19 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 2332 | P-1298 | WW | Flanders Dr. | 20 | Asbestos Cement | 450 | 50 | 1.14 out of 5 | $442 | 199,027 |
| Transmission Main | 11104 | P-88 | WW | Flanders Dr. | 12 | Ductile Iron | 10 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1691 | | WW | Flynn Ter | 4 | Unknown | 165 | UNK | 1.42 out of 5 | $442 | 72,970 |
| Distribution Main | 335 | P-817 | WW | Flynn Ter. | 6 | Asbestos Cement | 11 | 67 | 2 out of 5 | $442 | 4,922 |
| Distribution Main | 957 | P-816 | WW | Flynn Ter. | 4 | Cast Iron | 20 | 134 | 3.29 out of 5 | $442 | 8,932 |
| Distribution Main | 2208 | P-816 | WW | Flynn Ter. | 4 | Cast Iron | 199 | 134 | 3.29 out of 5 | $442 | 88,039 |
| Distribution Main | 3350 | P=817 | WW | Flynn Ter. | 6 | Asbestos Cement | 386 | 67 | 2 out of 5 | $442 | 170,586 |
| Distribution Main | 3356 | P-816 | WW | Flynn Ter. | 4 | Asbestos Cement | 92 | 67 | 2.71 out of 5 | $442 | 40,569 |
| Distribution Main | 4167 | P-83 | WW | Forest Ave. | 6 | Copper | 5 | 78 | 1.71 out of 5 | $442 | 2,288 |
| Distribution Main | 4392 | P-90 | WW | Forest Ave. | 6 | Asbestos Cement | 201 | 78 | 2 out of 5 | $442 | 88,727 |
| Distribution Main | 5297 | P-83 | WW | Forest Ave. | 6 | Copper | 9 | 78 | 1.71 out of 5 | $442 | 4,073 |
| Distribution Main | 6547 | | WW | Forest Ave. | 6 | Asbestos Cement | 3 | 78 | 2 out of 5 | $442 | 1,261 |
| Distribution Main | 6548 | P-83 | WW | Forest Ave. | 2 | Copper | 197 | 78 | 2.43 out of 5 | $442 | 86,875 |
| Distribution Main | 860 | P-292 | WW | Fornelli St. | 6 | Asbestos Cement | 209 | 78 | 2 out of 5 | $442 | 92,443 |
| Distribution Main | 861 | P-292 | WW | Fornelli St. | 6 | Asbestos Cement | 366 | 78 | 2 out of 5 | $442 | 161,567 |
| Distribution Main | 4087 | P-1087 | WW | Fountain St. | 6 | Asbestos Cement | 683 | 50 | 1.85 out of 5 | $442 | 302,043 |
| Distribution Main | 2341 | P-85 | WW | Fox Run | 6 | Ductile Iron | 27 | 29 | 0.85 out of 5 | $442 | 11,806 |
| Distribution Main | 2342 | P-85 | WW | Fox Run | 6 | Ductile Iron | 300 | 29 | 0.85 out of 5 | $442 | 132,460 |
| Distribution Main | 4676 | P-10032 | WW | Freemont St. | 6 | Unknown | 4 | 69 | 1.14 out of 5 | $442 | 1,918 |
| Distribution Main | 4677 | P-10032 | WW | Freemont St. | 6 | Unknown | 335 | 69 | 1.14 out of 5 | $442 | 147,956 |
| Distribution Main | 5127 | P-10032 | WW | Freemont St. | 6 | Unknown | 6 | 69 | 1.14 out of 5 | $442 | 2,482 |
| Distribution Main | 4629 | P-62 | WW | Friar Tuck La. | 8 | Asbestos Cement | 195 | 46 | 1.14 out of 5 | $442 | 86,241 |
| Distribution Main | 2400 | P-819 | WW | Fruit St. | 4 | Cast Iron | 15 | 134 | 3.29 out of 5 | $442 | 6,425 |
| Distribution Main | 3346 | P-819 | WW | Fruit St. | 4 | Cast Iron | 202 | 134 | 3.29 out of 5 | $442 | 89,489 |
| Distribution Main | 10018 | P-274 | WW | Gage St. | 8 | Ductile Iron | 157 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10028 | P-274 | WW | Gage St. | 8 | Ductile Iron | 201 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1699 | P-1047 | WW | Gardner Ave. | 4 | Cast Iron | 506 | 132 | 3.29 out of 5 | $442 | 223,738 |
| Distribution Main | 1700 | P-1047 | WW | Gardner Ave. | 4 | Cast Iron | 10 | 132 | 3.29 out of 5 | $442 | 4,619 |
| Distribution Main | 1882 | P-747 | WW | Gareau St. | 6 | Cast Iron | 269 | 79 | 2.28 out of 5 | $442 | 118,930 |
| Distribution Main | 9646 | P-748 | WW | Gareau St. | 8 | Ductile Iron | 239 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1534 | P-902 | WW | Garfield Ter. | 6 | Ductile Iron | 64 | 27 | 0.85 out of 5 | $442 | 28,311 |
| Distribution Main | 1535 | P-902 | WW | Garfield Ter. | 6 | Ductile Iron | 183 | 27 | 0.85 out of 5 | $442 | 81,055 |
| Distribution Main | 487 | P-965 | WW | Garnet St. | 6 | Asbestos Cement | 313 | 58 | 1.85 out of 5 | $442 | 138,267 |
| Distribution Main | 1537 | P-963 | WW | Garnet St. | 6 | Asbestos Cement | 450 | 58 | 1.85 out of 5 | $442 | 198,907 |
| Distribution Main | 8420 | P-1805 | WW | Garnet St. | 8 | Ductile Iron | 4 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8421 | P-1805 | WW | Garnet St. | 8 | Ductile Iron | 33 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3249 | P-1083 | WW | Gendron Street | 2 | Copper | 38 | 81 | 2.57 out of 5 | $442 | 16,940 |
| Distribution Main | 3250 | P-1083 | WW | Gendron Street | 2 | Copper | 240 | 81 | 2.57 out of 5 | $442 | 106,143 |
| Distribution Main | 10787 | P-10067 | WW | Gerald St | 8 | Ductile Iron | 116 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10788 | P-1508 | WW | Gerald St | 8 | Ductile Iron | 285 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 501 | P-867 | WW | Gilcrest Cir. | 8 | Ductile Iron | 57 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 502 | P-867 | WW | Gilcrest Cir. | 8 | Ductile Iron | 303 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2054 | P-870 | WW | Gilcrest Cir. | 8 | Ductile Iron | 371 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2055 | P-870 | WW | Gilcrest Cir. | 8 | Ductile Iron | 176 | 18 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2056 | P-871 | WW | Gilcrest Cir. | 8 | Ductile Iron | 29 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2057 | P-871 | WW | Gilcrest Cir. | 8 | Ductile Iron | 360 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2058 | P-869 | WW | Gilcrest Cir. | 8 | Ductile Iron | 234 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2059 | P-1560 | WW | Gilcrest Cir. | 8 | Ductile Iron | 4 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2073 | P-869 | WW | Gilcrest Cir. | 8 | Ductile Iron | 130 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2077 | P-871 | WW | Gilcrest Cir. | 8 | Ductile Iron | 26 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2079 | P-871 | WW | Gilcrest Cir. | 8 | Ductile Iron | 364 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2080 | P-871 | WW | Gilcrest Cir. | 8 | Ductile Iron | 28 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2081 | P-871 | WW | Gilcrest Cir. | 8 | Ductile Iron | 8 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2082 | P-1560 | WW | Gilcrest Cir. | 8 | Ductile Iron | 172 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2083 | P-1560 | WW | Gilcrest Cir. | 8 | Ductile Iron | 5 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2084 | | WW | Gilcrest Cir. | 8 | Ductile Iron | 13 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2085 | | WW | Gilcrest Cir. | 8 | Ductile Iron | 3 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2093 | P-871 | WW | Gilcrest Cir. | 8 | Ductile Iron | 10 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2099 | P-869 | WW | Gilcrest Cir. | 8 | Ductile Iron | 4 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8056 | | WW | Gilcrest Cir. | 8 | Ductile Iron | 4 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8057 | P-871 | WW | Gilcrest Cir. | 8 | Ductile Iron | 4 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9427 | P-871 | WW | Gilcrest Cir. | 8 | Ductile Iron | 4 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10982 | P-871 | WW | Gilcrest Cir. | 8 | Ductile Iron | 4 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10983 | P-1560 | WW | Gilcrest Cir. | 8 | Ductile Iron | 5 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12048 | P-870 | WW | Gilcrest Cir. | 8 | Ductile Iron | 27 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2078 | | WW | Gilcrest Dr. | 8 | Ductile Iron | 23 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 8995 | | WW | Giorgio Dr | 6 | Unknown | 5 | UNK | 0.71 out of 5 | $442 | 2,149 |
| Distribution Main | 811 | P-435 | WW | Glen Dr. | 6 | Asbestos Cement | 548 | 53 | 1.85 out of 5 | $442 | 242,348 |
| Distribution Main | 2968 | P-440 | WW | Glen Dr. | 6 | PVC | 286 | 32 | 1.14 out of 5 | $442 | 126,195 |
| Distribution Main | 2969 | P-440 | WW | Glen Dr. | 6 | PVC | 518 | 32 | 1.14 out of 5 | $442 | 229,021 |
| Distribution Main | 9134 | P-440 | WW | Glen Dr. | 6 | Asbestos Cement | 223 | 53 | 1.85 out of 5 | $442 | 98,715 |
| Distribution Main | 8932 | P-194 | WW | Glendale Dr | 8 | Ductile Iron | 237 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8941 | P-195 | WW | Glendale Dr | 8 | Ductile Iron | 217 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8942 | P-195 | WW | Glendale Dr | 8 | Ductile Iron | 15 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8947 | P-208 | WW | Glendale Dr | 8 | Ductile Iron | 613 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8948 | P-208 | WW | Glendale Dr | 8 | Ductile Iron | 431 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8951 | P-206 | WW | Glendale Dr | 8 | Ductile Iron | 108 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10932 | P-206 | WW | Glendale Dr | 8 | Ductile Iron | 136 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11528 | P-209 | WW | Glendale Dr | 8 | Ductile Iron | 74 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 316 | P-1077 | WW | Gough Ave. | 6 | Cast Iron | 103 | 133 | 2.57 out of 5 | $442 | 45,508 |
| Distribution Main | 380 | P-775 | WW | Gough Ave. | 6 | Cast Iron | 188 | 82 | 2.43 out of 5 | $442 | 82,963 |
| Distribution Main | 381 | P-774 | WW | Gough Ave. | 6 | Asbestos Cement | 16 | 75 | 2 out of 5 | $442 | 7,083 |
| Distribution Main | 388 | P-1883 | WW | Gough Ave. | 6 | Cast Iron | 16 | UNK | 1.85 out of 5 | $442 | 6,952 |
| Distribution Main | 444 | P-1879 | WW | Gough Ave. | 6 | Cast Iron | 731 | 133 | 2.57 out of 5 | $442 | 323,272 |
| Distribution Main | 1074 | P-1036 | WW | Gough Ave. | 6 | Cast Iron | 203 | 133 | 2.57 out of 5 | $442 | 89,819 |
| Transmission Main | 1209 | P-770 | WW | Gough Ave. | 16 | Asbestos Cement | 404 | 75 | 1.29 out of 5 | $442 | 178,555 |
| Distribution Main | 1970 | P-1076 | WW | Gough Ave. | 6 | Cast Iron | 379 | 133 | 2.57 out of 5 | $442 | 167,385 |
| Distribution Main | 2391 | | WW | Gough Ave. | 8 | Unknown | 18 | 75 | 0.43 out of 5 | $442 | 8,064 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2483 | | WW | Gough Ave. | 6 | Unknown | 223 | UNK | 0.71 out of 5 | $442 | 98,670 |
| Distribution Main | 2484 | | WW | Gough Ave. | 6 | Unknown | 149 | UNK | 0.71 out of 5 | $442 | 65,876 |
| Distribution Main | 2492 | P-784 | WW | Gough Ave. | 6 | Cast Iron | 27 | 82 | 2.43 out of 5 | $442 | 11,936 |
| Distribution Main | 2495 | P-1072 | WW | Gough Ave. | 6 | Cast Iron | 210 | 133 | 2.57 out of 5 | $442 | 92,922 |
| Distribution Main | 2862 | P-1069 | WW | Gough Ave. | 6 | Cast Iron | 366 | 82 | 2.43 out of 5 | $442 | 161,738 |
| Distribution Main | 2863 | P-777 | WW | Gough Ave. | 6 | Cast Iron | 21 | 82 | 2.43 out of 5 | $442 | 9,387 |
| Distribution Main | 2864 | P-777 | WW | Gough Ave. | 6 | Cast Iron | 215 | 82 | 2.43 out of 5 | $442 | 95,208 |
| Distribution Main | 3372 | P-1882 | WW | Gough Ave. | 6 | Cast Iron | 156 | 133 | 2.57 out of 5 | $442 | 69,173 |
| Distribution Main | 3373 | P-1882 | WW | Gough Ave. | 6 | Cast Iron | 489 | 133 | 2.57 out of 5 | $442 | 215,921 |
| Distribution Main | 3375 | P-1045 | WW | Gough Ave. | 6 | Cast Iron | 200 | 133 | 2.57 out of 5 | $442 | 88,491 |
| Distribution Main | 3377 | P-1036 | WW | Gough Ave. | 6 | Cast Iron | 26 | 133 | 2.57 out of 5 | $442 | 11,649 |
| Distribution Main | 3670 | P-1075 | WW | Gough Ave. | 6 | Cast Iron | 260 | 83 | 2.43 out of 5 | $442 | 115,071 |
| Distribution Main | 3788 | P-784 | WW | Gough Ave. | 6 | Cast Iron | 381 | 82 | 2.43 out of 5 | $442 | 168,263 |
| Transmission Main | 3789 | P-8044 | WW | Gough Ave. | 16 | Asbestos Cement | 17 | 75 | 1.29 out of 5 | $442 | 7,493 |
| Transmission Main | 3790 | P-8044 | WW | Gough Ave. | 16 | Asbestos Cement | 656 | 75 | 2 out of 5 | $442 | 289,739 |
| Transmission Main | 8047 | | WW | Gough Ave. | 16 | Asbestos Cement | 3 | 75 | 1.29 out of 5 | $442 | 1,527 |
| Distribution Main | 8809 | P-1045 | WW | Gough Ave. | 6 | Cast Iron | 36 | 133 | 2.57 out of 5 | $442 | 16,074 |
| Transmission Main | 8992 | P-8044 | WW | Gough Ave. | 16 | Asbestos Cement | 27 | 75 | 1.29 out of 5 | $442 | 12,064 |
| Distribution Main | 9538 | P-1076 | WW | Gough Ave. | 6 | Cast Iron | 99 | 133 | 2.57 out of 5 | $442 | 43,978 |
| Distribution Main | 9539 | P-1076 | WW | Gough Ave. | 6 | Cast Iron | 46 | 133 | 2.57 out of 5 | $442 | 20,421 |
| Distribution Main | 9540 | P-1074 | WW | Gough Ave. | 6 | Cast Iron | 111 | 83 | 2.43 out of 5 | $442 | 48,852 |
| Distribution Main | 9898 | P-1074 | WW | Gough Ave. | 6 | Cast Iron | 41 | 82 | 2.43 out of 5 | $442 | 18,228 |
| Transmission Main | 10880 | P-771 | WW | Gough Ave. | 16 | Asbestos Cement | 122 | 75 | 1.29 out of 5 | $442 | 53,928 |
| Distribution Main | 11054 | P-1077 | WW | Gough Ave. | 6 | Cast Iron | 14 | 133 | 2.57 out of 5 | $442 | 6,162 |
| Distribution Main | 11059 | P-1879 | WW | Gough Ave. | 6 | Cast Iron | 19 | 133 | 2.57 out of 5 | $442 | 8,323 |
| Transmission Main | 11105 | P-770 | WW | Gough Ave. | 16 | Asbestos Cement | 32 | 75 | 1.29 out of 5 | $442 | 14,244 |
| Distribution Main | 11230 | P-784 | WW | Gough Ave. | 6 | Cast Iron | 11 | 82 | 2.43 out of 5 | $442 | 4,670 |
| Transmission Main | 11231 | P-771 | WW | Gough Ave. | 16 | Asbestos Cement | 117 | 75 | 1.29 out of 5 | $442 | 51,765 |
| Distribution Main | 11622 | P-1069 | WW | Gough Ave. | 6 | Cast Iron | 29 | 82 | 2.43 out of 5 | $442 | 13,016 |
| Distribution Main | 11759 | P-1882 | WW | Gough Ave. | 6 | Cast Iron | 289 | 133 | 2.57 out of 5 | $442 | 127,615 |
| Distribution Main | 1439 | P-900 | WW | Grace Ct. | 6 | Asbestos Cement | 163 | 51 | 1.85 out of 5 | $442 | 72,263 |
| Distribution Main | 1512 | P-911 | WW | Grandview Dr. | 6 | Asbestos Cement | 17 | 61 | 2 out of 5 | $442 | 7,516 |
| Distribution Main | 1513 | P-911 | WW | Grandview Dr. | 6 | Asbestos Cement | 603 | 61 | 2 out of 5 | $442 | 266,333 |
| Distribution Main | 3733 | P-911 | WW | Grandview Dr. | 6 | Asbestos Cement | 4 | 61 | 2 out of 5 | $442 | 1,946 |
| Distribution Main | 3203 | P-731 | WW | Granite St. | 4 | Cast Iron | 255 | 133 | 3.29 out of 5 | $442 | 112,682 |
| Distribution Main | 3204 | P-731 | WW | Granite St. | 4 | Cast Iron | 4 | 133 | 3.29 out of 5 | $442 | 1,572 |
| Distribution Main | 3240 | P-731 | WW | Granite St. | 4 | Cast Iron | 307 | 133 | 3.29 out of 5 | $442 | 135,582 |
| Distribution Main | 4441 | P-1505 | WW | Grant St | 2 | Copper | 205 | 33 | 2.14 out of 5 | $442 | 90,779 |
| Distribution Main | 10343 | P-1505 | WW | Grant St | 1.5 | Copper | 126 | 33 | 2.14 out of 5 | $442 | 55,524 |
| Distribution Main | 10344 | P-1505 | WW | Grant St | 1.5 | Copper | 18 | 33 | 2.14 out of 5 | $442 | 7,843 |
| Distribution Main | 4440 | P-15303 | WW | Grant St. | 2 | Copper | 161 | 33 | 2.14 out of 5 | $442 | 71,050 |
| Distribution Main | 11144 | P-15303 | WW | Grant St. | 2 | Copper | 3 | 33 | 2.14 out of 5 | $442 | 1,522 |
| Distribution Main | 8705 | | WW | Great Lane | 2 | HDPE | 25 | 12 | 1.71 out of 5 | N/A | $0 |
| Transmission Main | 472 | P-1453 | WW | Green Bush Rd. | 12 | Ductile Iron | 354 | 22 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 473 | P-1438 | WW | Green Bush Rd. | 16 | Ductile Iron | 300 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 474 | P-1438 | WW | Green Bush Rd. | 16 | Ductile Iron | 1,229 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 980 | P-48 | WW | Green Bush Rd. | 16 | Asbestos Cement | 682 | 46 | 1.14 out of 5 | $442 | 301,471 |
| Transmission Main | 981 | P-48 | WW | Green Bush Rd. | 16 | Asbestos Cement | 219 | 46 | 1.14 out of 5 | $442 | 96,897 |
| Transmission Main | 982 | P-1448 | WW | Green Bush Rd. | 16 | Asbestos Cement | 196 | 46 | 1.14 out of 5 | $442 | 86,627 |
| Transmission Main | 989 | P-10044 | WW | Green Bush Rd. | 16 | Asbestos Cement | 293 | 46 | 1.14 out of 5 | $442 | 129,552 |
| Transmission Main | 990 | P-10044 | WW | Green Bush Rd. | 16 | Asbestos Cement | 486 | 46 | 1.14 out of 5 | $442 | 214,932 |
| Transmission Main | 991 | P-50 | WW | Green Bush Rd. | 16 | Asbestos Cement | 173 | 46 | 1.14 out of 5 | $442 | 76,503 |
| Transmission Main | 992 | P-50 | WW | Green Bush Rd. | 16 | Asbestos Cement | 442 | 46 | 1.14 out of 5 | $442 | 195,297 |
| Transmission Main | 1078 | P-1449 | WW | Green Bush Rd. | 16 | Asbestos Cement | 572 | 46 | 1.14 out of 5 | $442 | 252,675 |
| Distribution Main | 1080 | | WW | Green Bush Rd. | 10 | Ductile Iron | 28 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1353 | P-1452 | WW | Green Bush Rd. | 12 | Ductile Iron | 551 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2357 | P-1455 | WW | Green Bush Rd. | 12 | Ductile Iron | 803 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2358 | P-1455 | WW | Green Bush Rd. | 12 | Ductile Iron | 640 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 10162 | P-1448 | WW | Green Bush Rd. | 16 | Asbestos Cement | 137 | 46 | 1.14 out of 5 | $442 | 60,730 |
| Transmission Main | 10165 | P-50 | WW | Green Bush Rd. | 16 | Asbestos Cement | 143 | 46 | 1.14 out of 5 | $442 | 63,260 |
| Transmission Main | 10167 | P-1396 | WW | Green Bush Rd. | 12 | Asbestos Cement | 181 | 46 | 1.14 out of 5 | $442 | 79,854 |
| Transmission Main | 11062 | P-1438 | WW | Green Bush Rd. | 16 | Ductile Iron | 2 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11096 | P-48 | WW | Green Bush Rd. | 16 | Asbestos Cement | 268 | 46 | 1.14 out of 5 | $442 | 118,633 |
| Transmission Main | 11100 | P-1449 | WW | Green Bush Rd. | 16 | Asbestos Cement | 9 | 46 | 1.14 out of 5 | $442 | 3,792 |
| Transmission Main | 11101 | P-1452 | WW | Green Bush Rd. | 12 | Ductile Iron | 12 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11170 | P-1396 | WW | Green Bush Rd. | 12 | Asbestos Cement | 170 | 46 | 1.14 out of 5 | $442 | 75,197 |
| Transmission Main | 11171 | P-1455 | WW | Green Bush Rd. | 12 | Ductile Iron | 209 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 12050 | P-48 | WW | Green Bush Rd. | 16 | Asbestos Cement | 122 | 46 | 1.14 out of 5 | $442 | 53,922 |
| Distribution Main | 5374 | | WW | Green Ct. | 8 | Unknown | 6 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 148 | P-320 | WW | Greenbrier Rd. | 8 | Asbestos Cement | 507 | 43 | 1.14 out of 5 | $442 | 223,984 |
| Distribution Main | 149 | P-321 | WW | Greenbrier Rd. | 8 | Asbestos Cement | 402 | 43 | 1.14 out of 5 | $442 | 177,837 |
| Distribution Main | 926 | | WW | Greenbush Rd. | 8 | Ductile Iron | 33 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10163 | P-1451 | WW | Greenbush Road | 10 | PVC | 3 | 31 | 0.43 out of 5 | $442 | 1,487 |
| Distribution Main | 203 | | WW | Greene St. | 6 | Unknown | 7 | UNK | 0.71 out of 5 | $442 | 3,229 |
| Distribution Main | 207 | P-783 | WW | Greene St. | 8 | Asbestos Cement | 512 | 86 | 1.43 out of 5 | $442 | 226,155 |
| Distribution Main | 383 | P-1533 | WW | Greene St. | 8 | Ductile Iron | 337 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 1206 | P-800 | WW | Greene St. | 4 | Cast Iron | 307 | 86 | 3.14 out of 5 | $442 | 135,559 |
| Distribution Main | 1207 | P-800 | WW | Greene St. | 4 | Cast Iron | 279 | 86 | 3.14 out of 5 | $442 | 123,164 |
| Distribution Main | 1208 | P-800 | WW | Greene St. | 4 | Cast Iron | 84 | 86 | 3.14 out of 5 | $442 | 37,101 |
| Distribution Main | 2176 | P-809 | WW | Greene St. | 6 | Asbestos Cement | 107 | 67 | 2 out of 5 | $442 | 47,414 |
| Distribution Main | 2449 | P-1398 | WW | Greene St. | 8 | Asbestos Cement | 301 | 86 | 1.43 out of 5 | $442 | 133,180 |
| Distribution Main | 3465 | P-797 | WW | Greene St. | 8 | Asbestos Cement | 9 | 86 | 1.43 out of 5 | $442 | 3,989 |
| Distribution Main | 3468 | P-796 | WW | Greene St. | 8 | Asbestos Cement | 224 | 86 | 1.43 out of 5 | $442 | 98,871 |
| Distribution Main | 3718 | P-809 | WW | Greene St. | 6 | Asbestos Cement | 302 | 67 | 2 out of 5 | $442 | 133,586 |
| Distribution Main | 3746 | P-797 | WW | Greene St. | 4 | Cast Iron | 231 | 132 | 3.29 out of 5 | $442 | 102,110 |
| Distribution Main | 3747 | P-797 | WW | Greene St. | 4 | Cast Iron | 20 | 132 | 3.29 out of 5 | $442 | 8,664 |
| Distribution Main | 3748 | P-797 | WW | Greene St. | 8 | Asbestos Cement | 14 | 86 | 1.43 out of 5 | $442 | 6,118 |
| Distribution Main | 3749 | P-1397 | WW | Greene St. | 4 | Cast Iron | 25 | 86 | 3.14 out of 5 | $442 | 10,927 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3750 | P-1397 | WW | Greene St. | 4 | Cast Iron | 615 | 86 | 3.14 out of 5 | $442 | 271,734 |
| Distribution Main | 3754 | P-796 | WW | Greene St. | 4 | Cast Iron | 19 | 86 | 3.14 out of 5 | $442 | 8,310 |
| Distribution Main | 3802 | P-783 | WW | Greene St. | 8 | Asbestos Cement | 23 | 86 | 1.43 out of 5 | $442 | 10,252 |
| Distribution Main | 2937 | P-8049 | WW | Greenwood Ave. | 6 | Asbestos Cement | 315 | 56 | 1.85 out of 5 | $442 | 139,276 |
| Distribution Main | 2938 | P-8049 | WW | Greenwood Ave. | 6 | Asbestos Cement | 509 | 56 | 1.85 out of 5 | $442 | 225,115 |
| Distribution Main | 3760 | P-1976 | WW | Grove Street | 2 | Copper | 249 | 81 | 2.57 out of 5 | $442 | 110,050 |
| Distribution Main | 3617 | P-760 | WW | Guertin St. | 2 | Galvanized Iron | 163 | 69 | 3.28 out of 5 | $442 | 72,044 |
| Distribution Main | 3673 | P-760 | WW | Guertin St. | 2 | Galvanized Iron | 187 | 69 | 3.28 out of 5 | $442 | 82,734 |
| Distribution Main | 3784 | P-7610 | WW | Guertin St. | 2 | Galvanized Iron | 17 | 69 | 3.28 out of 5 | $442 | 7,310 |
| Distribution Main | 3798 | P-1068 | WW | Hall St. | 6 | PVC | 240 | 32 | 1.14 out of 5 | $442 | 105,862 |
| Distribution Main | 4668 | P-428 | WW | Hamilton St. | 6 | Asbestos Cement | 156 | 66 | 2 out of 5 | $442 | 68,927 |
| Distribution Main | 4669 | P-444 | WW | Hamilton St. | 6 | Asbestos Cement | 475 | 66 | 2 out of 5 | $442 | 209,853 |
| Distribution Main | 5142 | P-426 | WW | Hamilton St. | 6 | Asbestos Cement | 307 | 66 | 2 out of 5 | $442 | 135,782 |
| Distribution Main | 2137 | P-574 | WW | Harbour Ave. | 2 | Copper | 228 | 73 | 2.43 out of 5 | $442 | 100,685 |
| Distribution Main | 2893 | P-551 | WW | Harbour Ave. | 6 | Cast Iron | 310 | 73 | 2.28 out of 5 | $442 | 137,097 |
| Distribution Main | 2894 | P-551 | WW | Harbour Ave. | 6 | Cast Iron | 149 | 73 | 2.28 out of 5 | $442 | 65,832 |
| Distribution Main | 3098 | P-568 | WW | Harbour Ave. | 6 | Asbestos Cement | 260 | 73 | 2 out of 5 | $442 | 114,775 |
| Distribution Main | 3099 | P-568 | WW | Harbour Ave. | 6 | Asbestos Cement | 9 | 73 | 2 out of 5 | $442 | 3,852 |
| Distribution Main | 3974 | P-576 | WW | Harbour Ave. | 2 | Copper | 16 | 73 | 2.43 out of 5 | $442 | 7,241 |
| Distribution Main | 4103 | P-568 | WW | Harbour Ave. | 8 | Asbestos Cement | 16 | 73 | 1.29 out of 5 | $442 | 7,247 |
| Distribution Main | 4104 | P-568 | WW | Harbour Ave. | 6 | Asbestos Cement | 14 | 73 | 2 out of 5 | $442 | 6,290 |
| Distribution Main | 4105 | P-564 | WW | Harbour Ave. | 6 | Asbestos Cement | 234 | 73 | 2 out of 5 | $442 | 103,297 |
| Distribution Main | 4303 | P-576 | WW | Harbour Ave. | 2 | Copper | 120 | 73 | 2.43 out of 5 | $442 | 52,889 |
| Distribution Main | 8013 | P-1603 | WW | Harbour Ave. | 8 | Ductile Iron | 22 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8014 | P-1605 | WW | Harbour Ave. | 8 | Ductile Iron | 234 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8015 | P-1606 | WW | Harbour Ave. | 8 | Ductile Iron | 278 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9352 | P-1606 | WW | Harbour Ave. | 6 | Ductile Iron | 14 | 14 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11244 | P-568 | WW | Harbour Ave. | 8 | Asbestos Cement | 4 | 73 | 1.29 out of 5 | $442 | 1,984 |
| Distribution Main | 11417 | P-1603 | WW | Harbour Ave. | 8 | Ductile Iron | 7 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8432 | P-1676 | WW | Harding St | 12 | Ductile Iron | 439 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8437 | P-896 | WW | Harding St | 16 | Ductile Iron | 180 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8438 | P-896 | WW | Harding St | 16 | Ductile Iron | 805 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8439 | P-1699 | WW | Harding St | 20 | Ductile Iron | 20 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8502 | P-1790 | WW | Harding St | 12 | Ductile Iron | 188 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8504 | P-891 | WW | Harding St | 12 | Ductile Iron | 212 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8506 | P-895 | WW | Harding St | 12 | Ductile Iron | 169 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8507 | P-895 | WW | Harding St | 12 | Ductile Iron | 42 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8508 | P-1676 | WW | Harding St | 12 | Ductile Iron | 24 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8509 | P-1676 | WW | Harding St | 16 | Ductile Iron | 39 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8510 | P-1699 | WW | Harding St | 16 | Ductile Iron | 15 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2884 | P-662 | WW | Hare St. | 1 | Galvanized Iron | 398 | 134 | 3.57 out of 5 | $442 | 175,856 |
| Distribution Main | 2885 | P-662 | WW | Hare St. | 1 | Galvanized Iron | 23 | 134 | 3.57 out of 5 | $442 | 10,129 |
| Distribution Main | 3530 | P-662 | WW | Hare St. | 1 | Galvanized Iron | 27 | 134 | 3.57 out of 5 | $442 | 12,012 |
| Distribution Main | 9788 | P-631 | WW | Harley St | 8 | Ductile Iron | 308 | 8 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9789 | P-631 | WW | Harley St | 8 | Ductile Iron | 36 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9796 | P-638 | WW | Harley St | 8 | Ductile Iron | 219 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9797 | P-621 | WW | Harley St | 8 | Ductile Iron | 547 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9894 | P-629 | WW | Harley St | 8 | Ductile Iron | 22 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10409 | P-629 | WW | Harley St | 8 | Ductile Iron | 96 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10883 | P-636 | WW | Harley St | 8 | Ductile Iron | 413 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10884 | P-633 | WW | Harley St | 8 | Ductile Iron | 281 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11608 | P-638 | WW | Harley St | 8 | Ductile Iron | 24 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12109 | P-638 | WW | Harley St | 8 | Ductile Iron | 295 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12110 | P-1965 | WW | Harley St | 8 | Ductile Iron | 166 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9363 | P-621 | WW | Harley St. | 8 | Ductile Iron | 8 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9364 | P-621 | WW | Harley St. | 8 | Ductile Iron | 5 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1795 | P-918 | WW | Harmony St. | 6 | Cast Iron | 361 | 129 | 2.57 out of 5 | $442 | 159,386 |
| Distribution Main | 1796 | P-918 | WW | Harmony St. | 6 | Cast Iron | 32 | 129 | 2.57 out of 5 | $442 | 13,957 |
| Distribution Main | 3734 | P-917 | WW | Harmony St. | 4 | Cast Iron | 526 | 129 | 3.29 out of 5 | $442 | 232,374 |
| Distribution Main | 201 | P-799 | WW | Harris Ave. | 8 | Asbestos Cement | 541 | 73 | 1.29 out of 5 | $442 | 239,033 |
| Distribution Main | 202 | P-799 | WW | Harris Ave. | 8 | Asbestos Cement | 285 | 73 | 1.29 out of 5 | $442 | 126,113 |
| Distribution Main | 1604 | P-792 | WW | Harris Ave. | 6 | Cast Iron | 422 | 134 | 2.57 out of 5 | $442 | 186,713 |
| Distribution Main | 1605 | P-792 | WW | Harris Ave. | 6 | Cast Iron | 436 | 134 | 2.57 out of 5 | $442 | 192,921 |
| Distribution Main | 3383 | P-794 | WW | Harris Ave. | 6 | Cast Iron | 440 | 134 | 2.57 out of 5 | $442 | 194,274 |
| Distribution Main | 8740 | P-792 | WW | Harris Ave. | 6 | Cast Iron | 153 | 134 | 2.57 out of 5 | $442 | 67,684 |
| Distribution Main | 8741 | P-10090 | WW | Harris Ave. | 6 | Cast Iron | 71 | 134 | 2.57 out of 5 | $442 | 31,393 |
| Distribution Main | 8742 | P-10090 | WW | Harris Ave. | 6 | Cast Iron | 239 | 134 | 2.57 out of 5 | $442 | 105,512 |
| Distribution Main | 8743 | P-799 | WW | Harris Ave. | 8 | Asbestos Cement | 36 | 73 | 1.29 out of 5 | $442 | 15,706 |
| Distribution Main | 8744 | P-7074 | WW | Harris Ave. | 8 | Asbestos Cement | 309 | 69 | 1.29 out of 5 | $442 | 136,426 |
| Distribution Main | 8745 | P-7074 | WW | Harris Ave. | 8 | Asbestos Cement | 511 | 69 | 1.29 out of 5 | $442 | 225,765 |
| Distribution Main | 12012 | P-792 | WW | Harris Ave. | 6 | Cast Iron | 73 | 134 | 2.57 out of 5 | $442 | 32,374 |
| Distribution Main | 8445 | P-1628 | WW | Harris St | 6 | Ductile Iron | 22 | 10 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 8446 | P-8752 | WW | Harris St | 12 | Ductile Iron | 27 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8447 | P-1912 | WW | Harris St | 12 | Ductile Iron | 8 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 240 | P-8129 | WW | Harris St. | 6 | Cast Iron | 31 | 119 | 2.57 out of 5 | $442 | 13,830 |
| Distribution Main | 241 | P-8129 | WW | Harris St. | 6 | Cast Iron | 162 | 119 | 2.57 out of 5 | $442 | 71,702 |
| Distribution Main | 1098 | P-8124 | WW | Harris St. | 6 | Cast Iron | 219 | 119 | 2.57 out of 5 | $442 | 96,992 |
| Distribution Main | 3523 | P-8133 | WW | Harris St. | 4 | Cast Iron | 13 | 119 | 3.29 out of 5 | $442 | 5,724 |
| Distribution Main | 3602 | P-8133 | WW | Harris St. | 6 | Cast Iron | 14 | 119 | 2.57 out of 5 | $442 | 6,116 |
| Distribution Main | 3603 | P-8133 | WW | Harris St. | 6 | Cast Iron | 513 | 119 | 2.57 out of 5 | $442 | 226,923 |
| Distribution Main | 11103 | P-8124 | WW | Harris St. | 6 | Cast Iron | 3 | 119 | 2.57 out of 5 | $442 | 1,516 |
| Distribution Main | 9104 | | WW | Hartman Court | 2 | Unknown | 24 | UNK | 1.42 out of 5 | $442 | 10,699 |
| Distribution Main | 4133 | P-96 | WW | Hatheway Dr. | 8 | Asbestos Cement | 49 | 41 | 1.14 out of 5 | $442 | 21,645 |
| Distribution Main | 4135 | P-96 | WW | Hatheway Dr. | 8 | Asbestos Cement | 93 | 41 | 1.14 out of 5 | $442 | 40,978 |
| Distribution Main | 4136 | P-96 | WW | Hatheway Dr. | 8 | Asbestos Cement | 563 | 41 | 1.14 out of 5 | $442 | 249,046 |
| Distribution Main | 5159 | P-96 | WW | Hatheway Dr. | 8 | Asbestos Cement | 8 | 41 | 1.14 out of 5 | $442 | 3,717 |
| Distribution Main | 5162 | P-10016 | WW | Hatheway Dr. | 8 | Asbestos Cement | 219 | 41 | 1.14 out of 5 | $442 | 96,582 |
| Distribution Main | 11773 | P-96 | WW | Hatheway Dr. | 8 | Asbestos Cement | 368 | 41 | 1.14 out of 5 | $442 | 162,623 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10174 | | WW | Havens Ct | 1 | Copper | 273 | 72 | 2.43 out of 5 | $442 | 120,883 |
| Distribution Main | 8616 | P-1870 | WW | Hay St | 8 | Ductile Iron | 70 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9424 | | WW | Hay St | 6 | Ductile Iron | 1 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 321 | P-1345 | WW | Hay St. | 6 | PVC | 233 | 46 | 1.28 out of 5 | $442 | 103,169 |
| Distribution Main | 1876 | | WW | Hay St. | 6 | Ductile Iron | 52 | UNK | 0.71 out of 5 | $442 | 22,784 |
| Distribution Main | 3341 | P-992 | WW | Hay St. | 6 | PVC | 273 | 46 | 1.28 out of 5 | $442 | 120,811 |
| Distribution Main | 3342 | P-992 | WW | Hay St. | 6 | PVC | 243 | 46 | 1.28 out of 5 | $442 | 107,281 |
| Distribution Main | 8049 | P-1933 | WW | Hebert St | 1.5 | HDPE | 4 | 91 | 2.29 out of 5 | $442 | 1,795 |
| Distribution Main | 2489 | P-1951 | WW | Hebert St. | 2 | Galvanized Iron | 33 | 91 | 3.43 out of 5 | $442 | 14,458 |
| Distribution Main | 3616 | P-1933 | WW | Hebert St. | 2 | Galvanized Iron | 823 | 91 | 3.43 out of 5 | $442 | 363,583 |
| Distribution Main | 3792 | P-773 | WW | Hebert St. | 6 | Asbestos Cement | 281 | 53 | 1.85 out of 5 | $442 | 124,354 |
| Distribution Main | 10893 | P-716 | WW | Hebert St. | 2 | Galvanized Iron | 7 | 91 | 3.43 out of 5 | $442 | 2,875 |
| Distribution Main | 11232 | P-773 | WW | Hebert St. | 6 | Asbestos Cement | 1 | 53 | 1.85 out of 5 | $442 | 637 |
| Distribution Main | 4652 | P-149 | WW | Hemlock Ln. | 8 | Asbestos Cement | 414 | 50 | 1.14 out of 5 | $442 | 183,159 |
| Distribution Main | 922 | P-1124 | WW | Hepburn St. | 2 | PVC | 523 | 30 | 1.85 out of 5 | $442 | 231,105 |
| Distribution Main | 923 | P-1113 | WW | Hepburn St. | 6 | Cast Iron | 288 | 134 | 2.57 out of 5 | $442 | 127,153 |
| Distribution Main | 924 | P-1113 | WW | Hepburn St. | 6 | Cast Iron | 211 | 134 | 2.57 out of 5 | $442 | 93,397 |
| Distribution Main | 1908 | P-1123 | WW | Hepburn St. | 4 | Cast Iron | 342 | 134 | 3.29 out of 5 | $442 | 151,167 |
| Distribution Main | 12008 | P-1113 | WW | Hepburn St. | 6 | Cast Iron | 113 | 134 | 2.57 out of 5 | $442 | 49,738 |
| Distribution Main | 4683 | P-534 | WW | High View Dr. | 8 | Asbestos Cement | 232 | 52 | 1.14 out of 5 | $442 | 102,463 |
| Distribution Main | 5133 | P-536 | WW | High View Dr. | 8 | Asbestos Cement | 38 | 52 | 1.14 out of 5 | $442 | 16,743 |
| Distribution Main | 5134 | P-536 | WW | High View Dr. | 8 | Asbestos Cement | 885 | 52 | 1.14 out of 5 | $442 | 391,276 |
| Distribution Main | 8534 | P-1843 | WW | Highland St | 8 | Ductile Iron | 19 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8564 | P-1843 | WW | Highland St | 6 | Ductile Iron | 3 | 13 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 2942 | P-1915 | WW | Highland St. | 6 | Cast Iron | 248 | 134 | 2.57 out of 5 | $442 | 109,621 |
| Distribution Main | 2943 | P-1915 | WW | Highland St. | 6 | Cast Iron | 136 | 134 | 2.57 out of 5 | $442 | 60,136 |
| Distribution Main | 2944 | P-1253 | WW | Highland St. | 6 | Cast Iron | 132 | 134 | 2.57 out of 5 | $442 | 58,517 |
| Distribution Main | 3480 | P-981 | WW | Highland St. | 6 | Cast Iron | 300 | 134 | 2.57 out of 5 | $442 | 132,714 |
| Distribution Main | 3481 | P-981 | WW | Highland St. | 6 | Cast Iron | 258 | 134 | 2.57 out of 5 | $442 | 114,053 |
| Distribution Main | 11193 | P-1915 | WW | Highland St. | 6 | Cast Iron | 99 | 134 | 2.57 out of 5 | $442 | 43,725 |
| Distribution Main | 12006 | P-981 | WW | Highland St. | 6 | Cast Iron | 12 | 134 | 2.57 out of 5 | $442 | 5,354 |
| Distribution Main | 2382 | P-754 | WW | Hillcrest Dr. | 6 | Cast Iron | 225 | 70 | 2.28 out of 5 | $442 | 99,523 |
| Distribution Main | 2482 | P-1954 | WW | Hillcrest Dr. | 1 | Copper | 20 | UNK | 1.99 out of 5 | $442 | 8,905 |
| Distribution Main | 2855 | | WW | Hillcrest Dr. | 6 | Cast Iron | 7 | 70 | 2.28 out of 5 | $442 | 3,029 |
| Distribution Main | 3796 | P-756 | WW | Hillcrest Dr. | 6 | Cast Iron | 210 | 70 | 2.28 out of 5 | $442 | 92,908 |
| Transmission Main | 8969 | P-1212 | WW | Hillside Ave | 12 | Ductile Iron | 15 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8970 | P-1212 | WW | Hillside Ave | 12 | Ductile Iron | 16 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9213 | P-1212 | WW | Hillside Ave | 8 | Ductile Iron | 199 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11532 | P-1212 | WW | Hillside Ave | 12 | Ductile Iron | 4 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10784 | P-359 | WW | Hilltop Av | 8 | Ductile Iron | 528 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10785 | P-330 | WW | Hilltop Av | 8 | Ductile Iron | 770 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11731 | P-330 | WW | Hilltop Av | 8 | Ductile Iron | 9 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1590 | P-532 | WW | Hollow Cir. | 6 | Asbestos Cement | 5 | 51 | 1.85 out of 5 | $442 | 2,320 |
| Distribution Main | 5131 | P-532 | WW | Hollow Cir. | 6 | Asbestos Cement | 124 | 51 | 1.85 out of 5 | $442 | 54,725 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 5132 | P-532 | WW | Hollow Cir. | 6 | Asbestos Cement | 422 | 51 | 1.85 out of 5 | $442 | 186,614 |
| Distribution Main | 2848 | P-733 | WW | Home St. | 6 | Cast Iron | 183 | 79 | 2.28 out of 5 | $442 | 81,011 |
| Distribution Main | 2849 | P-733 | WW | Home St. | 6 | Cast Iron | 397 | 79 | 2.28 out of 5 | $442 | 175,499 |
| Distribution Main | 10003 | P-733 | WW | Home St. | 6 | Cast Iron | 7 | 79 | 2.28 out of 5 | $442 | 3,003 |
| Distribution Main | 1552 | P-894 | WW | Hoover St. | 6 | Ductile Iron | 489 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9428 | P-1300 | WW | Hoover St. | 6 | Ductile Iron | 389 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8937 | P-193 | WW | Hopedale Dr | 8 | Ductile Iron | 439 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9406 | P-1729 | WW | Hopedale Dr | 8 | Ductile Iron | 13 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9407 | P-169 | WW | Hopedale Dr | 8 | Ductile Iron | 8 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9408 | P-169 | WW | Hopedale Dr | 8 | Ductile Iron | 193 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9409 | P-193 | WW | Hopedale Dr | 8 | Ductile Iron | 4 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3581 | P-1730 | WW | Hopedale Dr. | 8 | Ductile Iron | 23 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3872 | P-152 | WW | Hornbeam Ln. | 8 | Asbestos Cement | 257 | 42 | 1.14 out of 5 | $442 | 113,801 |
| Distribution Main | 8433 | P-1789 | WW | Horta Dr | 8 | Ductile Iron | 27 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8503 | P-1789 | WW | Horta Dr | 6 | Ductile Iron | 19 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 1006 | P-892 | WW | Horta Dr. | 6 | Asbestos Cement | 547 | 55 | 1.85 out of 5 | $442 | 241,676 |
| Distribution Main | 1410 | P-893 | WW | Horta Dr. | 6 | Asbestos Cement | 83 | 55 | 1.85 out of 5 | $442 | 36,733 |
| Distribution Main | 1411 | P-893 | WW | Horta Dr. | 6 | Asbestos Cement | 114 | 55 | 1.85 out of 5 | $442 | 50,313 |
| Distribution Main | 8975 | P-1927 | WW | Hoxie Ct | 8 | Ductile Iron | 7 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8976 | P-1927 | WW | Hoxie Ct | 8 | Ductile Iron | 38 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1994 | P-1208 | WW | Hoxie Ct. | 8 | Ductile Iron | 355 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4660 | P-160 | WW | Huckleberry Dr. | 8 | Asbestos Cement | 423 | 42 | 1.14 out of 5 | $442 | 187,166 |
| Distribution Main | 9829 | P-830 | WW | Industrial Ln | 8 | Ductile Iron | 334 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9830 | P-830 | WW | Industrial Ln | 8 | Ductile Iron | 391 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10414 | | WW | Industrial Ln | 8 | Ductile Iron | 6 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10810 | | WW | Industrial Ln | 6 | Ductile Iron | 1 | 7 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 12020 | P-830 | WW | Industrial Ln | 8 | Ductile Iron | 520 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12021 | P-830 | WW | Industrial Ln | 8 | Ductile Iron | 23 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12111 | P-830 | WW | Industrial Ln | 8 | Ductile Iron | 131 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12112 | P-830 | WW | Industrial Ln | 8 | Ductile Iron | 351 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5643 | P-234 | WW | Intervale Rd. | 6 | Asbestos Cement | 543 | 55 | 1.85 out of 5 | $442 | 240,068 |
| Distribution Main | 5644 | P-234 | WW | Intervale Rd. | 6 | Asbestos Cement | 16 | 55 | 1.85 out of 5 | $442 | 7,121 |
| Distribution Main | 4009 | P-325 | WW | Iron Dr. | 8 | Asbestos Cement | 37 | 47 | 1.14 out of 5 | $442 | 16,329 |
| Distribution Main | 4010 | P-325 | WW | Iron Dr. | 8 | Asbestos Cement | 319 | 47 | 1.14 out of 5 | $442 | 141,064 |
| Distribution Main | 5191 | P-322 | WW | Iron Dr. | 8 | Asbestos Cement | 211 | 47 | 1.14 out of 5 | $442 | 93,045 |
| Distribution Main | 2147 | P-295 | WW | Ivy St. | 6 | Asbestos Cement | 171 | 71 | 2 out of 5 | $442 | 75,519 |
| Distribution Main | 2148 | P-295 | WW | Ivy St. | 6 | Asbestos Cement | 405 | 71 | 2 out of 5 | $442 | 179,171 |
| Distribution Main | 11155 | P-295 | WW | Ivy St. | 6 | Asbestos Cement | 8 | 71 | 2 out of 5 | $442 | 3,572 |
| Transmission Main | 46 | P-1550 | WW | J.P. Murphy Hwy | 16 | Asbestos Cement | 8 | 39 | 1 out of 5 | $442 | 3,477 |
| Transmission Main | 47 | P-1315 | WW | J.P. Murphy Hwy | 16 | Asbestos Cement | 5 | 39 | 1 out of 5 | $442 | 2,272 |
| Transmission Main | 48 | P-1315 | WW | J.P. Murphy Hwy | 16 | Asbestos Cement | 174 | 39 | 1 out of 5 | $442 | 76,794 |
| Transmission Main | 9078 | P-1550 | WW | J.P. Murphy Hwy | 16 | Asbestos Cement | 3 | 39 | 1 out of 5 | $442 | 1,510 |
| Transmission Main | 9079 | P-1550 | WW | J.P. Murphy Hwy | 16 | Asbestos Cement | 7 | 39 | 1 out of 5 | $442 | 2,997 |
| Transmission Main | 9842 | P-1550 | WW | J.P. Murphy Hwy | 16 | Asbestos Cement | 9 | 39 | 1 out of 5 | $442 | 3,833 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 11011 | P-1550 | WW | J.P. Murphy Hwy | 16 | Asbestos Cement | 6 | 39 | 1 out of 5 | $442 | 2,837 |
| Transmission Main | 11012 | P-1550 | WW | J.P. Murphy Hwy | 16 | Asbestos Cement | 3 | 39 | 1 out of 5 | $442 | 1,147 |
| Distribution Main | 655 | P-466 | WW | Jacques St. | 6 | Asbestos Cement | 444 | 64 | 2 out of 5 | $442 | 196,414 |
| Distribution Main | 9055 | | WW | James P Murphy Hwy | 4 | Ductile Iron | 2 | 22 | 1.57 out of 5 | N/A | $0 |
| Distribution Main | 42 | | WW | James P Murphy Ind Rd | 10 | Ductile Iron | 5 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 43 | | WW | James P Murphy Ind Rd | 10 | Ductile Iron | 5 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 44 | | WW | James P Murphy Ind Rd | 10 | Ductile Iron | 26 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 45 | | WW | James P Murphy Ind Rd | 10 | Ductile Iron | 7 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 49 | | WW | James P Murphy Ind Rd | 10 | Ductile Iron | 17 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 50 | | WW | James P Murphy Ind Rd | 10 | Ductile Iron | 17 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 356 | | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 195 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1322 | | WW | James P Murphy Ind Rd | 6 | Ductile Iron | 2 | 22 | 0.85 out of 5 | N/A | $0 |
| Transmission Main | 9843 | P-65 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 630 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9844 | P-65 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 59 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9845 | P-65 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 77 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9846 | P-65 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 699 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9847 | P-66 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 107 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9848 | P-66 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 787 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9849 | P-1573 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 271 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9850 | P-1573 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 611 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9851 | P-1573 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 105 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9852 | P-1573 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 792 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9853 | P-67 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 407 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9854 | P-67 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 150 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9855 | P-1549 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 234 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9856 | P-1549 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 710 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9857 | P-10007 | WW | James P Murphy Ind Rd | 12 | Ductile Iron | 25 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9858 | P-72 | WW | James P Murphy Ind Rd | 12 | Ductile Iron | 45 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9859 | P-10009 | WW | James P Murphy Ind Rd | 12 | Ductile Iron | 33 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10956 | P-66 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 326 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11617 | P-65 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 41 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11987 | P-1573 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 366 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11988 | P-66 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 166 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11989 | P-65 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 425 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11990 | P-65 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 516 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12114 | P-67 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 83 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12115 | P-67 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 185 | 7 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12116 | P-67 | WW | James P Murphy Ind Rd | 16 | Ductile Iron | 108 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8963 | P-198 | WW | Janet Dr | 8 | Ductile Iron | 17 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8964 | P-198 | WW | Janet Dr | 6 | Ductile Iron | 11 | 9 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 4169 | P-198 | WW | Janet Dr. | 6 | Asbestos Cement | 479 | 69 | 2 out of 5 | $442 | 211,545 |
| Distribution Main | 4944 | P-198 | WW | Janet Dr. | 6 | Asbestos Cement | 26 | 69 | 2 out of 5 | $442 | 11,450 |
| Distribution Main | 2546 | P-34 | WW | Jaycee Dr. | 8 | Asbestos Cement | 582 | 57 | 1.14 out of 5 | $442 | 257,098 |
| Distribution Main | 4968 | P-1390 | WW | Jaycee Dr. | 8 | Asbestos Cement | 60 | 57 | 1.14 out of 5 | $442 | 26,575 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4969 | P-1390 | WW | Jaycee Dr. | 8 | Asbestos Cement | 303 | 57 | 1.14 out of 5 | $442 | 134,099 |
| Distribution Main | 10166 | P-1391 | WW | Jaycee Dr. | 8 | Asbestos Cement | 8 | 57 | 1.14 out of 5 | $442 | 3,559 |
| Distribution Main | 11172 | P-1390 | WW | Jaycee Dr. | 8 | Asbestos Cement | 6 | 57 | 1.14 out of 5 | $442 | 2,530 |
| Distribution Main | 2160 | P-581 | WW | Jefferson St. | 6 | Asbestos Cement | 151 | 70 | 2 out of 5 | $442 | 66,938 |
| Distribution Main | 9368 | P-581 | WW | Jefferson St. | 8 | Ductile Iron | 31 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9369 | P-581 | WW | Jefferson St. | 6 | Ductile Iron | 5 | 14 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 2260 | P-460 | WW | Joaquin Ct. | 8 | Asbestos Cement | 531 | 40 | 1 out of 5 | $442 | 234,767 |
| Distribution Main | 2261 | P-460 | WW | Joaquin Ct. | 8 | Asbestos Cement | 61 | 40 | 1 out of 5 | $442 | 26,928 |
| Distribution Main | 4602 | P-459 | WW | Joaquin Ct. | 8 | Asbestos Cement | 122 | 40 | 1 out of 5 | $442 | 53,941 |
| Distribution Main | 3243 | P-750 | WW | Jodoin St. | 6 | Cast Iron | 549 | 74 | 2.28 out of 5 | $442 | 242,539 |
| Distribution Main | 3255 | P-750 | WW | Jodoin St. | 6 | Cast Iron | 15 | 74 | 2.28 out of 5 | $442 | 6,534 |
| Distribution Main | 1775 | P-1067 | WW | John St. | 1 | Copper | 122 | 74 | 2.43 out of 5 | $442 | 53,711 |
| Distribution Main | 2854 | P-1067 | WW | John St. | 1 | Copper | 34 | 74 | 2.43 out of 5 | $442 | 14,982 |
| Distribution Main | 3202 | P-1064 | WW | John St. | 6 | Cast Iron | 213 | 74 | 2.28 out of 5 | $442 | 94,167 |
| Distribution Main | 3263 | P-1067 | WW | John St. | 1 | Copper | 93 | 74 | 2.43 out of 5 | $442 | 41,291 |
| Distribution Main | 3612 | P-1065 | WW | John St. | 6 | Cast Iron | 98 | 74 | 2.28 out of 5 | $442 | 43,113 |
| Distribution Main | 3613 | P-1065 | WW | John St. | 6 | Cast Iron | 63 | 74 | 2.28 out of 5 | $442 | 27,781 |
| Distribution Main | 645 | P-470 | WW | Judy Ter. | 6 | Asbestos Cement | 190 | 54 | 1.85 out of 5 | $442 | 84,048 |
| Distribution Main | 659 | P-471 | WW | Judy Ter. | 6 | Asbestos Cement | 372 | 54 | 1.85 out of 5 | $442 | 164,405 |
| Distribution Main | 5154 | P-469 | WW | Judy Ter. | 6 | Asbestos Cement | 6 | 54 | 1.85 out of 5 | $442 | 2,833 |
| Distribution Main | 5155 | P-469 | WW | Judy Ter. | 6 | Asbestos Cement | 260 | 54 | 1.85 out of 5 | $442 | 114,833 |
| Distribution Main | 10173 | P-990 | WW | Junior St | 6 | Ductile Iron | 3 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 426 | P-991 | WW | Junior St. | 6 | Cast Iron | 192 | 97 | 2.43 out of 5 | $442 | 85,036 |
| Distribution Main | 427 | P-989 | WW | Junior St. | 6 | Cast Iron | 82 | 97 | 2.43 out of 5 | $442 | 36,025 |
| Distribution Main | 428 | P-989 | WW | Junior St. | 6 | Cast Iron | 297 | 97 | 2.43 out of 5 | $442 | 131,067 |
| Distribution Main | 3361 | P-990 | WW | Junior St. | 6 | Cast Iron | 200 | 97 | 2.43 out of 5 | $442 | 88,228 |
| Distribution Main | 3362 | P-990 | WW | Junior St. | 6 | Cast Iron | 167 | 97 | 2.43 out of 5 | $442 | 73,839 |
| Distribution Main | 8587 | P-1867 | WW | Junior St. | 6 | Cast Iron | 119 | 97 | 2.43 out of 5 | $442 | 52,808 |
| Distribution Main | 8588 | P-1343 | WW | Junior St. | 6 | Cast Iron | 102 | 97 | 2.43 out of 5 | $442 | 44,867 |
| Distribution Main | 8589 | P-991 | WW | Junior St. | 6 | Cast Iron | 84 | 97 | 2.43 out of 5 | $442 | 36,923 |
| Distribution Main | 8590 | P-1347 | WW | Junior St. | 8 | Ductile Iron | 154 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9419 | P-1868 | WW | Junior St. | 6 | Cast Iron | 5 | 97 | 2.43 out of 5 | $442 | 2,022 |
| Distribution Main | 9420 | P-991 | WW | Junior St. | 6 | Cast Iron | 6 | 97 | 2.43 out of 5 | $442 | 2,577 |
| Distribution Main | 11214 | P-990 | WW | Junior St. | 6 | Cast Iron | 62 | 97 | 2.43 out of 5 | $442 | 27,208 |
| Distribution Main | 2211 | P-10012 | WW | Juniper Dr. | 8 | Asbestos Cement | 68 | 42 | 1.14 out of 5 | $442 | 30,093 |
| Distribution Main | 2213 | P-178 | WW | Juniper Dr. | 8 | Asbestos Cement | 425 | 42 | 1.14 out of 5 | $442 | 187,907 |
| Distribution Main | 3434 | P-181 | WW | Juniper Dr. | 8 | Asbestos Cement | 241 | 42 | 1.14 out of 5 | $442 | 106,711 |
| Distribution Main | 3572 | P-1402 | WW | Juniper Dr. | 8 | Asbestos Cement | 988 | 42 | 1.14 out of 5 | $442 | 436,565 |
| Distribution Main | 3573 | P-1402 | WW | Juniper Dr. | 8 | Asbestos Cement | 140 | 42 | 1.14 out of 5 | $442 | 62,059 |
| Distribution Main | 10260 | P-1403 | WW | Juniper Dr. | 8 | Asbestos Cement | 9 | 42 | 1.14 out of 5 | $442 | 3,888 |
| Distribution Main | 10262 |  | WW | Juniper Dr. | 8 | Ductile Iron | 20 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 9653 | P-1902 | WW | Kenmore St / Hall St | 1.5 | Copper | 183 | 70 | 2.43 out of 5 | $442 | 80,748 |
| Distribution Main | 9654 | P-1904 | WW | Kenmore St / Hall St | 1 | Copper | 145 | 70 | 2.43 out of 5 | $442 | 64,222 |
| Distribution Main | 11589 | P-1903 | WW | Kenmore St / Hall St | 1.5 | Copper | 62 | 70 | 2.43 out of 5 | $442 | 27,590 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2493 | P-1901 | WW | Kenmore St. | 1 | Copper | 304 | 70 | 2.43 out of 5 | $442 | 134,550 |
| Distribution Main | 3207 | P-1066 | WW | Kenmore St. | 2 | Copper | 225 | 70 | 2.43 out of 5 | $442 | 99,320 |
| Distribution Main | 9652 | P-1066 | WW | Kenmore St. | 6 | Asbestos Cement | 87 | 70 | 2 out of 5 | $442 | 38,420 |
| Distribution Main | 12218 | P-1066 | WW | Kenmore St. | 6 | Asbestos Cement | 13 | 70 | 2 out of 5 | $442 | 5,874 |
| Distribution Main | 2135 | P-573 | WW | Kent St. | 8 | Ductile Iron | 145 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2136 | P-573 | WW | Kent St. | 8 | Ductile Iron | 79 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2892 | P-567 | WW | Kent St. | 6 | Ductile Iron | 17 | 18 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 3983 | P-567 | WW | Kent St. | 8 | Ductile Iron | 242 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3984 | P-567 | WW | Kent St. | 8 | Ductile Iron | 538 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4328 | P-573 | WW | Kent St. | 8 | Ductile Iron | 12 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11154 | P-573 | WW | Kent St. | 8 | Ductile Iron | 15 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1705 | P-789 | WW | Kenyon St. | 1.25 | Galvanized Iron | 264 | 81 | 3.43 out of 5 | $442 | 116,872 |
| Transmission Main | 1083 | P-10089 | WW | Keyes Way | 12 | Ductile Iron | 337 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1084 | P-10089 | WW | Keyes Way | 12 | Ductile Iron | 45 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1241 | | WW | Keyes Way | 8 | Ductile Iron | 1 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1242 | P-10089 | WW | Keyes Way | 12 | Ductile Iron | 94 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1243 | P-10089 | WW | Keyes Way | 12 | Ductile Iron | 105 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1247 | | WW | Keyes Way | 8 | Ductile Iron | 32 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1323 | P-69 | WW | Keyes Way | 12 | Ductile Iron | 302 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1324 | P-69 | WW | Keyes Way | 12 | Ductile Iron | 8 | 21 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 12158 | P-69 | WW | Keyes Way | 12 | Ductile Iron | 16 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 276 | P-1191 | WW | Kimberly Ln. | 8 | Asbestos Cement | 34 | 49 | 1.14 out of 5 | $442 | 14,970 |
| Distribution Main | 277 | P-1191 | WW | Kimberly Ln. | 8 | Asbestos Cement | 361 | 49 | 1.14 out of 5 | $442 | 159,366 |
| Distribution Main | 391 | | WW | Kimberly Ln. | 8 | Unknown | 8 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 3566 | P-101 | WW | Kimberly Ln. | 8 | Asbestos Cement | 184 | 44 | 1.14 out of 5 | $442 | 81,310 |
| Distribution Main | 4127 | P-100 | WW | Kimberly Ln. | 6 | Asbestos Cement | 441 | 44 | 1.85 out of 5 | $442 | 194,868 |
| Distribution Main | 4128 | P-100 | WW | Kimberly Ln. | 6 | Asbestos Cement | 143 | 44 | 1.85 out of 5 | $442 | 63,142 |
| Distribution Main | 5156 | P-99 | WW | Kimberly Ln. | 8 | Asbestos Cement | 351 | 44 | 1.14 out of 5 | $442 | 155,114 |
| Distribution Main | 5157 | P-1193 | WW | Kimberly Ln. | 8 | Asbestos Cement | 6 | 49 | 1.14 out of 5 | $442 | 2,472 |
| Distribution Main | 5158 | P-1193 | WW | Kimberly Ln. | 8 | Asbestos Cement | 353 | 49 | 1.14 out of 5 | $442 | 155,848 |
| Distribution Main | 9978 | P-1193 | WW | Kimberly Ln. | 6 | Asbestos Cement | 529 | 49 | 1.85 out of 5 | $442 | 233,996 |
| Distribution Main | 10095 | P-100 | WW | Kimberly Ln. | 8 | Ductile Iron | 147 | 27 | 0.14 out of 5 | $442 | 64,759 |
| Distribution Main | 10251 | P-1191 | WW | Kimberly Ln. | 8 | Asbestos Cement | 1 | 49 | 1.14 out of 5 | $442 | 520 |
| Distribution Main | 11048 | P-1191 | WW | Kimberly Ln. | 8 | Asbestos Cement | 16 | 49 | 1.14 out of 5 | $442 | 7,226 |
| Distribution Main | 12056 | P-1193 | WW | Kimberly Ln. | 8 | Asbestos Cement | 99 | 49 | 1.14 out of 5 | $442 | 43,810 |
| Distribution Main | 2427 | P-8 | WW | Kings Forest | 8 | Ductile Iron | 672 | 28 | 0.14 out of 5 | $442 | 296,819 |
| Distribution Main | 2428 | P-8 | WW | Kings Forest | 8 | Ductile Iron | 67 | 28 | 0.14 out of 5 | $442 | 29,525 |
| Distribution Main | 3466 | P-778 | WW | Kinne St. | 4 | Cast Iron | 284 | 70 | 3 out of 5 | $442 | 125,583 |
| Distribution Main | 3756 | P-781 | WW | Kinne St. | 6 | Asbestos Cement | 2 | 70 | 2 out of 5 | $442 | 934 |
| Distribution Main | 3757 | P-781 | WW | Kinne St. | 6 | Asbestos Cement | 326 | 70 | 2 out of 5 | $442 | 144,213 |
| Distribution Main | 3803 | P-778 | WW | Kinne St. | 4 | Cast Iron | 398 | 70 | 3 out of 5 | $442 | 175,900 |
| Distribution Main | 8747 | | WW | Kinne St. | 8 | Ductile Iron | 18 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8749 | P-779 | WW | Kinne St. | 8 | Ductile Iron | 19 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10973 | P-781 | WW | Kinne St. | 8 | Ductile Iron | 8 | 18 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4733 | P-36 | WW | Kiwanis Road | 8 | Asbestos Cement | 451 | 57 | 1.14 out of 5 | $442 | 199,410 |
| Transmission Main | 8542 | P-928 | WW | Knight St | 12 | Ductile Iron | 38 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8568 | P-1845 | WW | Knight St | 20 | Ductile Iron | 205 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8569 | P-1845 | WW | Knight St | 20 | Ductile Iron | 52 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8572 | P-926 | WW | Knight St | 20 | Ductile Iron | 400 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11479 | P-1845 | WW | Knight St | 20 | Ductile Iron | 180 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11480 | P-1845 | WW | Knight St | 20 | Ductile Iron | 14 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11481 | P-926 | WW | Knight St | 20 | Ductile Iron | 3 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9765 | P-1964 | WW | Koch St | 8 | Ductile Iron | 257 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9776 | P-632 | WW | Kowalik Dr | 8 | Ductile Iron | 119 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9777 | P-632 | WW | Kowalik Dr | 8 | Ductile Iron | 8 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9791 | P-632 | WW | Kowalik Dr | 8 | Ductile Iron | 464 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 995 | | WW | Krystal Pond Dr. | 8 | Unknown | 10 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 996 | | WW | Krystal Pond Dr. | 8 | Unknown | 3 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 997 | P-1324 | WW | Krystal Pond Dr. | 8 | Ductile Iron | 137 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8657 | | WW | Krystal Pond Dr. | 8 | Unknown | 2 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 8658 | | WW | Krystal Pond Dr. | 8 | Ductile Iron | 12 | 29 | 0.14 out of 5 | $442 | 5,157 |
| Distribution Main | 8659 | P-1324 | WW | Krystal Pond Dr. | 8 | Ductile Iron | 252 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8662 | P-1322 | WW | Krystal Pond Dr. | 8 | PVC | 24 | 29 | 0.43 out of 5 | $442 | 10,611 |
| Distribution Main | 8663 | P-1321 | WW | Krystal Pond Dr. | 8 | PVC | 250 | 29 | 0.43 out of 5 | $442 | 110,486 |
| Distribution Main | 8664 | P-1321 | WW | Krystal Pond Dr. | 8 | PVC | 59 | 29 | 0.43 out of 5 | $442 | 26,080 |
| Distribution Main | 8806 | | WW | Krystal Pond Dr. | 8 | Cast Iron | 16 | UNK | 1.14 out of 5 | $442 | 7,041 |
| Distribution Main | 11006 | P-1322 | WW | Krystal Pond Dr. | 8 | PVC | 12 | 29 | 0.43 out of 5 | $442 | 5,367 |
| Distribution Main | 11490 | P-1324 | WW | Krystal Pond Dr. | 8 | Ductile Iron | 208 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1571 | P-499 | WW | Kulas Rd. | 8 | Asbestos Cement | 6 | 49 | 1.14 out of 5 | $442 | 2,860 |
| Transmission Main | 3414 | P-138 | WW | Kulas Rd. | 12 | Asbestos Cement | 668 | 49 | 1.14 out of 5 | $442 | 295,461 |
| Transmission Main | 3415 | P-138 | WW | Kulas Rd. | 12 | Asbestos Cement | 172 | 49 | 1.14 out of 5 | $442 | 76,225 |
| Distribution Main | 3416 | P-139 | WW | Kulas Rd. | 8 | Asbestos Cement | 361 | 49 | 1.14 out of 5 | $442 | 159,409 |
| Transmission Main | 4124 | P-10014 | WW | Kulas Rd. | 12 | Asbestos Cement | 206 | 49 | 1.14 out of 5 | $442 | 90,928 |
| Distribution Main | 4125 | P-139 | WW | Kulas Rd. | 8 | Asbestos Cement | 238 | 49 | 1.14 out of 5 | $442 | 105,366 |
| Distribution Main | 4658 | P-499 | WW | Kulas Rd. | 8 | Asbestos Cement | 1,038 | 49 | 1.14 out of 5 | $442 | 458,843 |
| Distribution Main | 10151 | P-1609 | WW | Kulas Rd. | 8 | Asbestos Cement | 4 | 49 | 1.14 out of 5 | $442 | 1,915 |
| Distribution Main | 10153 | P-10013 | WW | Kulas Rd. | 8 | Asbestos Cement | 28 | 49 | 1.14 out of 5 | $442 | 12,575 |
| Distribution Main | 10154 | P-10013 | WW | Kulas Rd. | 8 | Asbestos Cement | 1 | 49 | 1.14 out of 5 | $442 | 613 |
| Distribution Main | 10453 | P-139 | WW | Kulas Rd. | 8 | Asbestos Cement | 4 | 49 | 1.14 out of 5 | $442 | 1,662 |
| Distribution Main | 2850 | P-719 | WW | Lachance St. | 6 | Cast Iron | 224 | 81 | 2.43 out of 5 | $442 | 98,881 |
| Distribution Main | 3266 | P-1365 | WW | Lachance St. | 6 | Cast Iron | 259 | 81 | 3.14 out of 5 | $442 | 114,263 |
| Transmission Main | 1244 | P-73 | WW | Lacroix Dr. | 12 | Ductile Iron | 4 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1245 | P-73 | WW | Lacroix Dr. | 12 | Ductile Iron | 25 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1328 | P-73 | WW | Lacroix Dr. | 12 | Ductile Iron | 656 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9779 | P-635 | WW | Lada Dr | 8 | Ductile Iron | 108 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9792 | P-635 | WW | Lada Dr | 8 | Ductile Iron | 117 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9793 | P-634 | WW | Lada Dr | 8 | Ductile Iron | 184 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11607 | P-635 | WW | Lada Dr | 8 | Ductile Iron | 28 | 8 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 864 | P-289 | WW | Lafayette St. | 6 | Ductile Iron | 243 | 26 | 0.85 out of 5 | $442 | 107,350 |
| Distribution Main | 2140 | P-289 | WW | Lafayette St. | 6 | Ductile Iron | 250 | 26 | 0.85 out of 5 | $442 | 110,331 |
| Distribution Main | 2141 | P-289 | WW | Lafayette St. | 6 | Ductile Iron | 246 | 26 | 0.85 out of 5 | $442 | 108,692 |
| Distribution Main | 10051 | P-263 | WW | Lancelotta St | 8 | Ductile Iron | 22 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10052 | P-263 | WW | Lancelotta St | 8 | Ductile Iron | 427 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11637 | P-263 | WW | Lancelotta St | 8 | Ductile Iron | 278 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3550 | P-1447 | WW | Lancer Ln. | 8 | Asbestos Cement | 290 | 41 | 1.14 out of 5 | $442 | 128,123 |
| Distribution Main | 3551 | P-1447 | WW | Lancer Ln. | 8 | Asbestos Cement | 422 | 41 | 1.14 out of 5 | $442 | 186,724 |
| Distribution Main | 2934 | P-1225 | WW | Lanphear St. | 6 | Cast Iron | 189 | 134 | 2.57 out of 5 | $442 | 83,585 |
| Distribution Main | 2935 | P-1225 | WW | Lanphear St. | 6 | Cast Iron | 411 | 134 | 2.57 out of 5 | $442 | 181,487 |
| Distribution Main | 3696 | P-1224 | WW | Lanphear St. | 6 | Cast Iron | 164 | 134 | 2.57 out of 5 | $442 | 72,302 |
| Distribution Main | 11192 | P-1225 | WW | Lanphear St. | 6 | Cast Iron | 2 | 134 | 2.57 out of 5 | $442 | 736 |
| Distribution Main | 4333 | P-572 | WW | Laramee Ave. | 6 | PVC | 236 | 30 | 1.14 out of 5 | $442 | 104,351 |
| Distribution Main | 4334 | P-572 | WW | Laramee Ave. | 6 | PVC | 53 | 30 | 1.14 out of 5 | $442 | 23,440 |
| Distribution Main | 4335 | P-563 | WW | Laramee Ave. | 6 | Ductile Iron | 485 | 28 | 0.85 out of 5 | $442 | 214,225 |
| Distribution Main | 4654 | P-147 | WW | Laural Ln. | 8 | Asbestos Cement | 345 | 50 | 1.14 out of 5 | $442 | 152,530 |
| Distribution Main | 4655 | P-147 | WW | Laural Ln. | 8 | Asbestos Cement | 96 | 50 | 1.14 out of 5 | $442 | 42,462 |
| Transmission Main | 392 | | WW | Lauren Ln. | 12 | Ductile Iron | 6 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2316 | | WW | Lauren Ln. | 12 | Ductile Iron | 15 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2339 | P-1426 | WW | Lauren Ln. | 12 | PVC | 15 | 32 | 0.43 out of 5 | $442 | 6,743 |
| Transmission Main | 4758 | P-1427 | WW | Lauren Ln. | 12 | PVC | 189 | 32 | 0.43 out of 5 | $442 | 83,714 |
| Transmission Main | 4759 | P-1427 | WW | Lauren Ln. | 12 | PVC | 379 | 32 | 0.43 out of 5 | $442 | 167,359 |
| Transmission Main | 10261 | P-1426 | WW | Lauren Ln. | 12 | PVC | 3 | 32 | 0.43 out of 5 | $442 | 1,418 |
| Distribution Main | 2852 | P-1978 | WW | Lavoie Street | 2 | Unknown | 185 | 51 | 1.71 out of 5 | $442 | 81,884 |
| Distribution Main | 8415 | P-1820 | WW | Lawrence St | 8 | Ductile Iron | 22 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8416 | P-1818 | WW | Lawrence St | 8 | Ductile Iron | 29 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8490 | P-1818 | WW | Lawrence St | 6 | Ductile Iron | 2 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9713 | P-1811 | WW | Lawrence St | 6 | Ductile Iron | 7 | 27 | 0.85 out of 5 | $442 | 2,989 |
| Distribution Main | 9714 | P-1811 | WW | Lawrence St | 6 | Ductile Iron | 200 | 27 | 0.85 out of 5 | $442 | 88,367 |
| Distribution Main | 3506 | P-1818 | WW | Lawrence Street | 6 | Asbestos Cement | 362 | 64 | 2 out of 5 | $442 | 159,843 |
| Distribution Main | 1787 | P-1221 | WW | Le Valley St. | 4 | Cast Iron | 24 | 134 | 3.29 out of 5 | $442 | 10,422 |
| Distribution Main | 1789 | P-1220 | WW | Le Valley St. | 4 | Cast Iron | 73 | 134 | 3.29 out of 5 | $442 | 32,050 |
| Distribution Main | 1790 | P-1220 | WW | Le Valley St. | 4 | Cast Iron | 22 | 134 | 3.29 out of 5 | $442 | 9,919 |
| Distribution Main | 1960 | P-1221 | WW | Le Valley St. | 4 | Cast Iron | 69 | 134 | 3.29 out of 5 | $442 | 30,710 |
| Distribution Main | 1961 | P-1226 | WW | Le Valley St. | 4 | Cast Iron | 130 | 134 | 3.29 out of 5 | $442 | 57,494 |
| Distribution Main | 1962 | P-1226 | WW | Le Valley St. | 4 | Cast Iron | 120 | 134 | 3.29 out of 5 | $442 | 52,843 |
| Distribution Main | 3094 | P-1502 | WW | Le Valley St. | 4 | Cast Iron | 64 | 134 | 3.29 out of 5 | $442 | 28,201 |
| Distribution Main | 3095 | P-1502 | WW | Le Valley St. | 4 | Cast Iron | 165 | 134 | 3.29 out of 5 | $442 | 73,100 |
| Distribution Main | 3524 | P-1220 | WW | Le Valley St. | 4 | Cast Iron | 29 | 134 | 3.29 out of 5 | $442 | 12,672 |
| Distribution Main | 9683 | P-1502 | WW | Le Valley St. | 4 | Cast Iron | 17 | 134 | 3.29 out of 5 | $442 | 7,557 |
| Distribution Main | 10663 | P-377 | WW | Leaf St | 8 | Ductile Iron | 309 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10664 | P-377 | WW | Leaf St | 8 | Ductile Iron | 481 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10902 | P-10034 | WW | Leaf St | 8 | Ductile Iron | 189 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11701 | P-377 | WW | Leaf St | 8 | Ductile Iron | 92 | 2 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9928 | P-10035 | WW | Leaf St. | 1 | Copper | 146 | 69 | 2.43 out of 5 | $442 | 64,468 |
| Distribution Main | 3197 | P-905 | WW | Ledge Dr. | 6 | Asbestos Cement | 358 | 64 | 2 out of 5 | $442 | 158,286 |
| Distribution Main | 10774 | P-365 | WW | Ledgemont Ct | 8 | Ductile Iron | 331 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4816 | P-517 | WW | Lee St. | 6 | Asbestos Cement | 284 | 69 | 2 out of 5 | $442 | 125,702 |
| Distribution Main | 4817 | P-517 | WW | Lee St. | 6 | Asbestos Cement | 116 | 69 | 2 out of 5 | $442 | 51,304 |
| Distribution Main | 5094 | P-527 | WW | Lee St. | 6 | Asbestos Cement | 92 | 69 | 2 out of 5 | $442 | 40,553 |
| Distribution Main | 5136 | P-514 | WW | Lee St. | 6 | Asbestos Cement | 596 | 69 | 2 out of 5 | $442 | 263,392 |
| Distribution Main | 5146 | P-513 | WW | Lee St. | 8 | Ductile Iron | 17 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2889 | P-570 | WW | Leeder St. | 2 | Galvanized Iron | 80 | 91 | 3.43 out of 5 | $442 | 35,546 |
| Distribution Main | 3968 | P-570 | WW | Leeder St. | 2 | Galvanized Iron | 265 | 91 | 3.43 out of 5 | $442 | 117,309 |
| Distribution Main | 4316 | | WW | Leeder St. | 2 | Galvanized Iron | 8 | 91 | 3.43 out of 5 | $442 | 3,678 |
| Transmission Main | 1032 | P-79 | WW | Legend Way | 16 | Ductile Iron | 212 | 28 | 0.14 out of 5 | $442 | 93,839 |
| Transmission Main | 10667 | P-1108 | WW | Legris Av | 12 | Ductile Iron | 22 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10668 | P-1108 | WW | Legris Av | 12 | Ductile Iron | 340 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10669 | P-1497 | WW | Legris Av | 12 | Ductile Iron | 443 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10670 | P-1495 | WW | Legris Av | 12 | Ductile Iron | 253 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10676 | P-1581 | WW | Legris Av | 12 | Ductile Iron | 305 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10677 | P-1581 | WW | Legris Av | 12 | Ductile Iron | 421 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10678 | P-1498 | WW | Legris Av | 12 | Ductile Iron | 46 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10679 | P-1498 | WW | Legris Av | 12 | Ductile Iron | 269 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10889 | P-1496 | WW | Legris Av | 12 | Ductile Iron | 32 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10890 | P-1496 | WW | Legris Av | 12 | Ductile Iron | 256 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10892 | P-1107 | WW | Legris Av | 12 | Ductile Iron | 25 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11702 | P-1108 | WW | Legris Av | 12 | Ductile Iron | 21 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11706 | P-1499 | WW | Legris Av | 12 | Ductile Iron | 44 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12030 | P-1108 | WW | Legris Av | 12 | Ductile Iron | 61 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12142 | P-1581 | WW | Legris Av | 12 | Ductile Iron | 31 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 881 | P-1499 | WW | Legris Ave. | 8 | Asbestos Cement | 49 | 60 | 1.14 out of 5 | $442 | 21,579 |
| Distribution Main | 882 | P-1499 | WW | Legris Ave. | 8 | Asbestos Cement | 884 | 60 | 1.14 out of 5 | $442 | 390,781 |
| Distribution Main | 1433 | | WW | Legris Ave. | 8 | Unknown | 8 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 1723 | P-641 | WW | Legris Ave. | 6 | Ductile Iron | 44 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 1724 | P-641 | WW | Legris Ave. | 6 | Ductile Iron | 35 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 2883 | P-642 | WW | Legris Ave. | 6 | Ductile Iron | 63 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 3531 | P-2775 | WW | Legris Ave. | 8 | Asbestos Cement | 95 | 60 | 1.14 out of 5 | $442 | 41,902 |
| Distribution Main | 3537 | | WW | Legris Ave. | 8 | Asbestos Cement | 21 | 60 | 1.14 out of 5 | $442 | 9,156 |
| Distribution Main | 3964 | P-2775 | WW | Legris Ave. | 8 | Asbestos Cement | 350 | 60 | 1.14 out of 5 | $442 | 154,909 |
| Distribution Main | 3965 | P-1499 | WW | Legris Ave. | 8 | Asbestos Cement | 150 | 60 | 1.14 out of 5 | $442 | 66,458 |
| Distribution Main | 3966 | P-1499 | WW | Legris Ave. | 8 | Asbestos Cement | 605 | 60 | 1.14 out of 5 | $442 | 267,434 |
| Distribution Main | 4302 | P-1107 | WW | Legris Ave. | 6 | Ductile Iron | 361 | 25 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 4324 | P-1107 | WW | Legris Ave. | 6 | Ductile Iron | 35 | UNK | 0.71 out of 5 | $442 | 15,480 |
| Distribution Main | 11935 | P-1499 | WW | Legris Ave. | 8 | Asbestos Cement | 469 | 60 | 1.14 out of 5 | $442 | 207,485 |
| Distribution Main | 8840 | P-704 | WW | Lemoine Ct. | 2 | Galvanized Iron | 269 | 130 | 3.57 out of 5 | $442 | 118,850 |
| Distribution Main | 10634 | P-391 | WW | Lenox Av | 8 | Ductile Iron | 272 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10635 | P-396 | WW | Lenox Av | 8 | Ductile Iron | 339 | 2 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10636 | P-10033 | WW | Lenox Av | 8 | Ductile Iron | 410 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10637 | P-391 | WW | Lenox Av | 8 | Ductile Iron | 197 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11695 | P-395 | WW | Lenox Av | 8 | Ductile Iron | 228 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4702 | P-388 | WW | Lenox Ave. | 6 | Ductile Iron | 90 | 26 | 0.85 out of 5 | $442 | 39,768 |
| Distribution Main | 4705 | P-388 | WW | Lenox Ave. | 8 | Ductile Iron | 298 | 26 | 0.14 out of 5 | $442 | 131,526 |
| Distribution Main | 4710 | P-388 | WW | Lenox Ave. | 6 | Ductile Iron | 104 | 26 | 0.85 out of 5 | $442 | 46,025 |
| Distribution Main | 10638 | | WW | Lexington Av | 8 | Ductile Iron | 739 | 2 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10639 | P-383 | WW | Lexington Av | 8 | Ductile Iron | 526 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10640 | P-381 | WW | Lexington Av | 8 | Ductile Iron | 169 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10641 | P-382 | WW | Lexington Av | 8 | Ductile Iron | 276 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11696 | P-386 | WW | Lexington Av | 8 | Ductile Iron | 5 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11697 | P-383 | WW | Lexington Av | 8 | Ductile Iron | 154 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11698 | P-382 | WW | Lexington Av | 8 | Ductile Iron | 6 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12139 | P-386 | WW | Lexington Av | 8 | Ductile Iron | 25 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12140 | P-383 | WW | Lexington Av | 8 | Ductile Iron | 9 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8926 | P-119 | WW | Linden Dr | 8 | Ductile Iron | 45 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8927 | P-119 | WW | Linden Dr | 8 | Ductile Iron | 446 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2962 | P-1720 | WW | Linden Dr. | 8 | Ductile Iron | 22 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1536 | | WW | Linwood St. | 6 | Asbestos Cement | 16 | 77 | 2 out of 5 | $442 | 6,928 |
| Distribution Main | 3697 | P-952 | WW | Linwood St. | 6 | Asbestos Cement | 402 | 77 | 2 out of 5 | $442 | 177,849 |
| Distribution Main | 10644 | P-380 | WW | Lionel Av | 8 | Ductile Iron | 141 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10645 | P-380 | WW | Lionel Av | 8 | Ductile Iron | 132 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2551 | P-37 | WW | Lions Dr. | 8 | Asbestos Cement | 183 | 50 | 1.14 out of 5 | $442 | 81,085 |
| Distribution Main | 4730 | P-35 | WW | Lions Dr. | 8 | Asbestos Cement | 296 | 50 | 1.14 out of 5 | $442 | 130,976 |
| Distribution Main | 4731 | P-35 | WW | Lions Dr. | 8 | Asbestos Cement | 44 | 50 | 1.14 out of 5 | $442 | 19,551 |
| Distribution Main | 4964 | P-1941 | WW | Lions Dr. | 8 | Asbestos Cement | 105 | 50 | 1.14 out of 5 | $442 | 46,401 |
| Distribution Main | 4965 | P-1942 | WW | Lions Dr. | 6 | Asbestos Cement | 67 | 50 | 1.85 out of 5 | $442 | 29,535 |
| Distribution Main | 3236 | P-5126 | WW | Lippitt Ave. | 6 | Asbestos Cement | 722 | 44 | 1.85 out of 5 | $442 | 319,172 |
| Distribution Main | 3237 | P-5126 | WW | Lippitt Ave. | 6 | Asbestos Cement | 326 | 44 | 1.85 out of 5 | $442 | 144,260 |
| Distribution Main | 9430 | P-5126 | WW | Lippitt Ave. | 6 | Asbestos Cement | 563 | 44 | 1.85 out of 5 | $442 | 248,869 |
| Distribution Main | 9431 | P-5126 | WW | Lippitt Ave. | 6 | Asbestos Cement | 44 | 44 | 1.85 out of 5 | $442 | 19,387 |
| Distribution Main | 1805 | P-2 | WW | Little John La. | 8 | Ductile Iron | 303 | 28 | 0.14 out of 5 | $442 | 133,854 |
| Distribution Main | 1806 | P-2 | WW | Little John La. | 8 | Ductile Iron | 14 | 28 | 0.14 out of 5 | $442 | 6,167 |
| Distribution Main | 2429 | P-4 | WW | Little John La. | 8 | Ductile Iron | 32 | 28 | 0.14 out of 5 | $442 | 14,182 |
| Distribution Main | 2430 | P-4 | WW | Little John La. | 8 | Ductile Iron | 464 | 28 | 0.14 out of 5 | $442 | 204,919 |
| Distribution Main | 646 | P-450 | WW | Lockwood St. | 6 | Asbestos Cement | 567 | 69 | 2 out of 5 | $442 | 250,823 |
| Distribution Main | 647 | P-450 | WW | Lockwood St. | 6 | Asbestos Cement | 982 | 69 | 2 out of 5 | $442 | 433,845 |
| Distribution Main | 648 | P-443 | WW | Lockwood St. | 6 | Asbestos Cement | 234 | 69 | 2 out of 5 | $442 | 103,471 |
| Distribution Main | 649 | P-441 | WW | Lockwood St. | 6 | PVC | 82 | 33 | 1.14 out of 5 | $442 | 36,355 |
| Distribution Main | 650 | P-441 | WW | Lockwood St. | 6 | PVC | 167 | 33 | 1.14 out of 5 | $442 | 73,950 |
| Distribution Main | 656 | P-463 | WW | Lockwood St. | 6 | Asbestos Cement | 61 | 69 | 2 out of 5 | $442 | 27,097 |
| Distribution Main | 809 | P-436 | WW | Lockwood St. | 6 | PVC | 352 | 33 | 1.14 out of 5 | $442 | 155,545 |
| Distribution Main | 810 | P-436 | WW | Lockwood St. | 6 | PVC | 216 | 33 | 1.14 out of 5 | $442 | 95,544 |
| Distribution Main | 1750 | P-438 | WW | Lockwood St. | 6 | PVC | 239 | 33 | 1.14 out of 5 | $442 | 105,747 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3884 | P-463 | WW | Lockwood St. | 6 | Asbestos Cement | 429 | 69 | 2 out of 5 | $442 | 189,641 |
| Distribution Main | 4666 | P-463 | WW | Lockwood St. | 6 | Asbestos Cement | 18 | 69 | 2 out of 5 | $442 | 7,844 |
| Distribution Main | 4674 | P-443 | WW | Lockwood St. | 6 | Asbestos Cement | 9 | 69 | 2 out of 5 | $442 | 4,143 |
| Distribution Main | 11143 | P-438 | WW | Lockwood St. | 6 | PVC | 7 | 33 | 1.14 out of 5 | $442 | 3,018 |
| Distribution Main | 12028 | P-450 | WW | Lockwood St. | 6 | Asbestos Cement | 119 | 69 | 2 out of 5 | $442 | 52,504 |
| Distribution Main | 4777 | P-1465 | WW | Locust Dr. | 8 | PVC | 444 | 33 | 0.43 out of 5 | $442 | 196,237 |
| Distribution Main | 4622 | P-131 | WW | Loggers Run | 8 | Ductile Iron | 228 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4623 | P-131 | WW | Loggers Run | 8 | Ductile Iron | 595 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4624 | P-1269 | WW | Loggers Run | 8 | Ductile Iron | 493 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4625 | P-132 | WW | Loggers Run | 8 | Ductile Iron | 288 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4626 | P-132 | WW | Loggers Run | 8 | Ductile Iron | 318 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2088 | P-875 | WW | Lombardi Ln. | 12 | PVC | 637 | 30 | 0.43 out of 5 | $442 | 281,575 |
| Distribution Main | 1807 | P-9 | WW | Longbow Dr. | 8 | Ductile Iron | 4 | 28 | 0.14 out of 5 | $442 | 1,804 |
| Distribution Main | 2425 | P-10 | WW | Longbow Dr. | 8 | Ductile Iron | 51 | 28 | 0.14 out of 5 | $442 | 22,428 |
| Distribution Main | 2426 | P-10 | WW | Longbow Dr. | 8 | Ductile Iron | 387 | 28 | 0.14 out of 5 | $442 | 170,915 |
| Distribution Main | 2433 | P-7 | WW | Longbow Dr. | 8 | Ductile Iron | 240 | 28 | 0.14 out of 5 | $442 | 105,936 |
| Distribution Main | 2439 | P-9 | WW | Longbow Dr. | 8 | Ductile Iron | 282 | 28 | 0.14 out of 5 | $442 | 124,629 |
| Distribution Main | 4451 | P-15 | WW | Longbow Dr. | 8 | Ductile Iron | 241 | 28 | 0.14 out of 5 | $442 | 106,301 |
| Distribution Main | 4742 | P-21 | WW | Longbow Dr. | 8 | Ductile Iron | 425 | 28 | 0.14 out of 5 | $442 | 187,661 |
| Transmission Main | 1591 | P-135 | WW | Lonsdale St. | 12 | Asbestos Cement | 3 | 50 | 1.14 out of 5 | $442 | 1,136 |
| Transmission Main | 2154 | P-1155 | WW | Lonsdale St. | 12 | Asbestos Cement | 216 | 50 | 1.14 out of 5 | $442 | 95,287 |
| Transmission Main | 2155 | P-1155 | WW | Lonsdale St. | 12 | Asbestos Cement | 409 | 50 | 1.14 out of 5 | $442 | 180,915 |
| Transmission Main | 3898 | P-1149 | WW | Lonsdale St. | 12 | Asbestos Cement | 558 | 50 | 1.14 out of 5 | $442 | 246,676 |
| Transmission Main | 5108 | P-135 | WW | Lonsdale St. | 12 | Asbestos Cement | 155 | 50 | 1.14 out of 5 | $442 | 68,412 |
| Transmission Main | 5109 | P-135 | WW | Lonsdale St. | 12 | Asbestos Cement | 720 | 50 | 1.14 out of 5 | $442 | 318,432 |
| Transmission Main | 5172 | P-136 | WW | Lonsdale St. | 12 | Asbestos Cement | 251 | 50 | 1.14 out of 5 | $442 | 110,821 |
| Transmission Main | 5173 | P-136 | WW | Lonsdale St. | 12 | Asbestos Cement | 741 | 50 | 1.14 out of 5 | $442 | 327,380 |
| Distribution Main | 4822 | P-1143 | WW | Lori Ct. | 8 | Asbestos Cement | 228 | 47 | 1.14 out of 5 | $442 | 100,711 |
| Distribution Main | 1530 | P-847 | WW | Louise Dr. | 6 | Asbestos Cement | 536 | 64 | 2 out of 5 | $442 | 236,915 |
| Distribution Main | 1531 | P-847 | WW | Louise Dr. | 6 | Asbestos Cement | 16 | 64 | 2 out of 5 | $442 | 7,264 |
| Distribution Main | 9753 | P-610 | WW | Loven Ct | 8 | Ductile Iron | 126 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9754 | P-1383 | WW | Loven Ct | 8 | Ductile Iron | 15 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9758 | P-610 | WW | Loven Ct | 8 | Ductile Iron | 229 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8417 | P-1812 | WW | Lowell St | 8 | Ductile Iron | 27 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9453 | P-1813 | WW | Lowell St | 1 | Copper | 237 | 10 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 488 | P-966 | WW | Lowell St. | 6 | Asbestos Cement | 297 | 57 | 1.85 out of 5 | $442 | 131,396 |
| Distribution Main | 2356 | P-1445 | WW | Maid Marian Ln. | 8 | Asbestos Cement | 290 | 41 | 1.14 out of 5 | $442 | 127,995 |
| Distribution Main | 3552 | P-1446 | WW | Maid Marian Ln. | 8 | Asbestos Cement | 292 | 41 | 1.14 out of 5 | $442 | 128,978 |
| Distribution Main | 3553 | P-1446 | WW | Maid Marian Ln. | 8 | Asbestos Cement | 270 | 41 | 1.14 out of 5 | $442 | 119,173 |
| Transmission Main | 8535 | P-941 | WW | Main St | 20 | Ductile Iron | 102 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8543 | P-925 | WW | Main St | 20 | Ductile Iron | 174 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8544 | P-925 | WW | Main St | 20 | Ductile Iron | 357 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8547 | P-1850 | WW | Main St | 8 | Ductile Iron | 26 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8560 | P-1256 | WW | Main St | 20 | Ductile Iron | 18 | 13 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 8561 | P-1256 | WW | Main St | 20 | Ductile Iron | 12 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8562 | P-1256 | WW | Main St | 20 | Ductile Iron | 362 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8563 | P-1256 | WW | Main St | 20 | Ductile Iron | 320 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8565 | P-982 | WW | Main St | 20 | Ductile Iron | 140 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8567 | P-941 | WW | Main St | 20 | Ductile Iron | 109 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8576 | P-925 | WW | Main St | 12 | Ductile Iron | 18 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8577 | P-925 | WW | Main St | 12 | Ductile Iron | 13 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8578 | P-828 | WW | Main St | 8 | Ductile Iron | 10 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8629 | P-1865 | WW | Main St | 10 | Ductile Iron | 180 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8988 | | WW | Main St | 12 | Ductile Iron | 8 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9327 | P-1009 | WW | Main St | 6 | Ductile Iron | 5 | 9 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 9695 | P-1256 | WW | Main St | 20 | Ductile Iron | 15 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10355 | | WW | Main St | | Cast Iron | 20 | UNK | 1.14 out of 5 | $442 | 8,850 |
| Transmission Main | 10964 | P-941 | WW | Main St | 20 | Ductile Iron | 75 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11476 | P-941 | WW | Main St | 20 | Ductile Iron | 9 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11483 | P-925 | WW | Main St | 12 | Ductile Iron | 20 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12004 | P-1256 | WW | Main St | 20 | Ductile Iron | 91 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12005 | P-1256 | WW | Main St | 20 | Ductile Iron | 286 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 137 | P-1975 | WW | Main St. | 6 | Cast Iron | 224 | 134 | 2.57 out of 5 | $442 | 98,927 |
| Distribution Main | 256 | P-1500 | WW | Main St. | 8 | Cast Iron | 304 | 84 | 1.72 out of 5 | $442 | 134,192 |
| Distribution Main | 293 | P-1895 | WW | Main St. | 6 | Cast Iron | 12 | 83 | 2.43 out of 5 | $442 | 5,478 |
| Distribution Main | 294 | P-1885 | WW | Main St. | 8 | Cast Iron | 14 | 83 | 1.72 out of 5 | $442 | 6,187 |
| Distribution Main | 317 | P-1037 | WW | Main St. | 6 | Cast Iron | 251 | 134 | 2.57 out of 5 | $442 | 110,824 |
| Distribution Main | 318 | P-1020 | WW | Main St. | 6 | Cast Iron | 328 | 134 | 2.57 out of 5 | $442 | 144,947 |
| Distribution Main | 320 | P-1885 | WW | Main St. | 8 | Cast Iron | 3 | 83 | 1.72 out of 5 | $442 | 1,144 |
| Distribution Main | 329 | P-1009 | WW | Main St. | 6 | Cast Iron | 132 | 134 | 2.57 out of 5 | $442 | 58,440 |
| Distribution Main | 330 | P-1009 | WW | Main St. | 6 | Cast Iron | 193 | 134 | 2.57 out of 5 | $442 | 85,400 |
| Distribution Main | 336 | P-1894 | WW | Main St. | 6 | Cast Iron | 209 | 83 | 2.43 out of 5 | $442 | 92,555 |
| Distribution Main | 434 | P-1007 | WW | Main St. | 10 | Cast Iron | 212 | 134 | 1.86 out of 5 | $442 | 93,553 |
| Distribution Main | 445 | P-790 | WW | Main St. | 6 | Cast Iron | 25 | 83 | 2.43 out of 5 | $442 | 10,877 |
| Distribution Main | 446 | P-1039 | WW | Main St. | 6 | Cast Iron | 345 | 134 | 2.57 out of 5 | $442 | 152,376 |
| Distribution Main | 605 | P-1033 | WW | Main St. | 8 | Cast Iron | 371 | 84 | 1.72 out of 5 | $442 | 163,846 |
| Distribution Main | 606 | P-1030 | WW | Main St. | 8 | Cast Iron | 171 | 84 | 1.72 out of 5 | $442 | 75,361 |
| Distribution Main | 607 | P-1030 | WW | Main St. | 8 | Cast Iron | 178 | 84 | 1.72 out of 5 | $442 | 78,459 |
| Distribution Main | 917 | P-1117 | WW | Main St. | 8 | Cast Iron | 30 | 134 | 1.86 out of 5 | $442 | 13,241 |
| Distribution Main | 918 | P-1117 | WW | Main St. | 8 | Cast Iron | 175 | 134 | 1.86 out of 5 | $442 | 77,161 |
| Distribution Main | 919 | P-1482 | WW | Main St. | 8 | Cast Iron | 262 | 134 | 1.86 out of 5 | $442 | 115,998 |
| Distribution Main | 920 | P-1115 | WW | Main St. | 8 | Cast Iron | 395 | 134 | 1.86 out of 5 | $442 | 174,798 |
| Distribution Main | 961 | P-827 | WW | Main St. | 10 | Cast Iron | 95 | 134 | 1.86 out of 5 | $442 | 42,062 |
| Distribution Main | 962 | P-827 | WW | Main St. | 10 | Cast Iron | 170 | 134 | 1.86 out of 5 | $442 | 74,987 |
| Distribution Main | 1071 | P-1026 | WW | Main St. | 6 | Cast Iron | 405 | 124 | 2.57 out of 5 | $442 | 179,075 |
| Distribution Main | 1072 | P-1026 | WW | Main St. | 6 | Cast Iron | 32 | 134 | 2.57 out of 5 | $442 | 14,311 |
| Distribution Main | 1075 | P-1037 | WW | Main St. | 6 | Cast Iron | 16 | 134 | 2.57 out of 5 | $442 | 7,255 |
| Distribution Main | 1515 | P-1501 | WW | Main St. | 8 | Cast Iron | 308 | 134 | 1.86 out of 5 | $442 | 136,105 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 1516 | P-1501 | WW | Main St. | 8 | Cast Iron | 198 | 134 | 1.86 out of 5 | $442 | 87,603 |
| Distribution Main | 1610 | P-1033 | WW | Main St. | 8 | Cast Iron | 362 | 84 | 1.72 out of 5 | $442 | 160,006 |
| Distribution Main | 1701 | P-1035 | WW | Main St. | 6 | Cast Iron | 401 | 134 | 2.57 out of 5 | $442 | 177,342 |
| Distribution Main | 1702 | P-1078 | WW | Main St. | 6 | Cast Iron | 75 | 134 | 2.57 out of 5 | $442 | 33,282 |
| Distribution Main | 1703 | P-1285 | WW | Main St. | 6 | Cast Iron | 373 | 134 | 2.57 out of 5 | $442 | 164,672 |
| Distribution Main | 1704 | P-1285 | WW | Main St. | 6 | Cast Iron | 166 | 134 | 2.57 out of 5 | $442 | 73,505 |
| Distribution Main | 1722 | | WW | Main St. | 6 | Unknown | 30 | UNK | 0.71 out of 5 | $442 | 13,144 |
| Distribution Main | 1785 | P-1251 | WW | Main St. | 8 | Cast Iron | 306 | 134 | 1.86 out of 5 | $442 | 135,427 |
| Distribution Main | 1786 | P-1251 | WW | Main St. | 8 | Cast Iron | 321 | 84 | 1.72 out of 5 | $442 | 142,093 |
| Distribution Main | 1879 | P-1027 | WW | Main St. | 8 | Cast Iron | 13 | 84 | 1.72 out of 5 | $442 | 5,823 |
| Distribution Main | 1880 | P-1027 | WW | Main St. | 8 | Cast Iron | 231 | 84 | 1.72 out of 5 | $442 | 101,945 |
| Distribution Main | 1884 | P-1116 | WW | Main St. | 8 | Cast Iron | 114 | 134 | 1.86 out of 5 | $442 | 50,540 |
| Distribution Main | 1885 | P-1130 | WW | Main St. | 8 | Cast Iron | 110 | 134 | 1.86 out of 5 | $442 | 48,505 |
| Distribution Main | 1888 | P-1125 | WW | Main St. | 8 | Cast Iron | 482 | 134 | 1.86 out of 5 | $442 | 213,083 |
| Distribution Main | 1890 | P-1116 | WW | Main St. | 8 | Cast Iron | 175 | 134 | 1.86 out of 5 | $442 | 77,278 |
| Distribution Main | 1891 | P-1116 | WW | Main St. | 8 | Cast Iron | 16 | 134 | 1.86 out of 5 | $442 | 7,199 |
| Distribution Main | 1963 | P-1500 | WW | Main St. | 8 | Cast Iron | 278 | 84 | 1.72 out of 5 | $442 | 122,833 |
| Distribution Main | 2182 | P-828 | WW | Main St. | 10 | Cast Iron | 169 | 134 | 1.86 out of 5 | $442 | 74,763 |
| Distribution Main | 2207 | P-1336 | WW | Main St. | 8 | Cast Iron | 10 | 84 | 1.72 out of 5 | $442 | 4,616 |
| Distribution Main | 2247 | P-1105 | WW | Main St. | 8 | Cast Iron | 802 | 134 | 1.86 out of 5 | $442 | 354,494 |
| Distribution Main | 2248 | P-1105 | WW | Main St. | 8 | Cast Iron | 84 | 134 | 1.86 out of 5 | $442 | 36,931 |
| Distribution Main | 2249 | P-1105 | WW | Main St. | 8 | Cast Iron | 357 | 134 | 1.86 out of 5 | $442 | 157,833 |
| Distribution Main | 2396 | P-1008 | WW | Main St. | 10 | Cast Iron | 81 | 134 | 1.86 out of 5 | $442 | 35,959 |
| Distribution Main | 2397 | P-1008 | WW | Main St. | 10 | Cast Iron | 63 | 134 | 1.86 out of 5 | $442 | 28,009 |
| Distribution Main | 2450 | P-1884 | WW | Main St. | 6 | Cast Iron | 4 | 83 | 2.43 out of 5 | $442 | 1,650 |
| Distribution Main | 2451 | P-1884 | WW | Main St. | 6 | Cast Iron | 14 | 83 | 2.43 out of 5 | $442 | 6,155 |
| Distribution Main | 2452 | P-1265 | WW | Main St. | 6 | Cast Iron | 20 | 83 | 2.43 out of 5 | $442 | 8,630 |
| Distribution Main | 2453 | P-1265 | WW | Main St. | 6 | Cast Iron | 53 | 83 | 2.43 out of 5 | $442 | 23,622 |
| Distribution Main | 2897 | P-641 | WW | Main St. | 8 | Cast Iron | 33 | 84 | 1.72 out of 5 | $442 | 14,775 |
| Distribution Main | 2898 | P-646 | WW | Main St. | 6 | Cast Iron | 154 | 134 | 2.57 out of 5 | $442 | 68,279 |
| Distribution Main | 2952 | P-1846 | WW | Main St. | 8 | Cast Iron | 88 | 134 | 1.86 out of 5 | $442 | 38,897 |
| Distribution Main | 2953 | P-1846 | WW | Main St. | 8 | Cast Iron | 126 | 134 | 1.86 out of 5 | $442 | 55,696 |
| Distribution Main | 2954 | P-930 | WW | Main St. | 8 | Cast Iron | 201 | 134 | 1.86 out of 5 | $442 | 88,665 |
| Distribution Main | 2955 | P-930 | WW | Main St. | 8 | Cast Iron | 168 | 134 | 1.86 out of 5 | $442 | 74,293 |
| Distribution Main | 3101 | | WW | Main St. | 4 | Unknown | 10 | UNK | 1.42 out of 5 | $442 | 4,369 |
| Distribution Main | 3102 | | WW | Main St. | 4 | Unknown | 10 | UNK | 1.42 out of 5 | $442 | 4,567 |
| Distribution Main | 3103 | | WW | Main St. | 4 | Unknown | 6 | UNK | 1.42 out of 5 | $442 | 2,530 |
| Distribution Main | 3104 | | WW | Main St. | 4 | Unknown | 123 | UNK | 1.42 out of 5 | $442 | 54,302 |
| Distribution Main | 3134 | P-1033 | WW | Main St. | 8 | Cast Iron | 30 | 84 | 1.72 out of 5 | $442 | 13,050 |
| Distribution Main | 3353 | P-1035 | WW | Main St. | 8 | Cast Iron | 10 | 84 | 1.72 out of 5 | $442 | 4,289 |
| Distribution Main | 3354 | P-1033 | WW | Main St. | 8 | Cast Iron | 180 | 84 | 1.72 out of 5 | $442 | 79,437 |
| Distribution Main | 3358 | P-788 | WW | Main St. | 6 | Cast Iron | 99 | 83 | 2.43 out of 5 | $442 | 43,697 |
| Distribution Main | 3359 | P-788 | WW | Main St. | 6 | Cast Iron | 28 | 83 | 2.43 out of 5 | $442 | 12,596 |
| Distribution Main | 3360 | P-1865 | WW | Main St. | 10 | Cast Iron | 12 | 134 | 1.86 out of 5 | $442 | 5,176 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3376 | P-1021 | WW | Main St. | 6 | Cast Iron | 241 | 134 | 2.57 out of 5 | $442 | 106,668 |
| Distribution Main | 3380 | P-1285 | WW | Main St. | 6 | Cast Iron | 235 | 134 | 2.57 out of 5 | $442 | 104,062 |
| Distribution Main | 3381 | P-1035 | WW | Main St. | 6 | Cast Iron | 10 | 134 | 2.57 out of 5 | $442 | 4,536 |
| Distribution Main | 3382 | P-1892 | WW | Main St. | 6 | Cast Iron | 5 | 134 | 2.57 out of 5 | $442 | 2,371 |
| Distribution Main | 3384 | P-1019 | WW | Main St. | 6 | Cast Iron | 17 | 84 | 2.43 out of 5 | $442 | 7,475 |
| Distribution Main | 3385 | P-1019 | WW | Main St. | 6 | Cast Iron | 348 | 134 | 2.57 out of 5 | $442 | 153,779 |
| Distribution Main | 3390 | P-826 | WW | Main St. | 10 | Cast Iron | 73 | 134 | 1.86 out of 5 | $442 | 32,193 |
| Distribution Main | 3470 | P-931 | WW | Main St. | 8 | Cast Iron | 233 | 134 | 1.86 out of 5 | $442 | 102,912 |
| Distribution Main | 3526 | P-1251 | WW | Main St. | 8 | Cast Iron | 839 | 84 | 1.72 out of 5 | $442 | 370,681 |
| Distribution Main | 3605 | P-1033 | WW | Main St. | 8 | Cast Iron | 196 | 84 | 1.72 out of 5 | $442 | 86,415 |
| Distribution Main | 3606 | P-1033 | WW | Main St. | 8 | Cast Iron | 155 | 84 | 1.72 out of 5 | $442 | 68,486 |
| Distribution Main | 3607 | P-1030 | WW | Main St. | 8 | Cast Iron | 11 | 84 | 1.72 out of 5 | $442 | 5,014 |
| Distribution Main | 3608 | P-1030 | WW | Main St. | 8 | Cast Iron | 41 | 84 | 1.72 out of 5 | $442 | 18,046 |
| Distribution Main | 3609 | P-1031 | WW | Main St. | 8 | Cast Iron | 275 | 84 | 1.72 out of 5 | $442 | 121,628 |
| Distribution Main | 3610 | P-1031 | WW | Main St. | 8 | Cast Iron | 51 | 84 | 1.72 out of 5 | $442 | 22,644 |
| Distribution Main | 3723 | P-1501 | WW | Main St. | 8 | Cast Iron | 341 | 134 | 1.86 out of 5 | $442 | 150,564 |
| Distribution Main | 3724 | P-1501 | WW | Main St. | 8 | Cast Iron | 7 | 134 | 1.86 out of 5 | $442 | 3,075 |
| Distribution Main | 3758 | P-667 | WW | Main St. | 6 | Cast Iron | 270 | 134 | 2.57 out of 5 | $442 | 119,561 |
| Distribution Main | 3759 | P-667 | WW | Main St. | 6 | Cast Iron | 92 | 134 | 2.57 out of 5 | $442 | 40,467 |
| Distribution Main | 3765 | P-668 | WW | Main St. | 8 | Cast Iron | 30 | 84 | 1.72 out of 5 | $442 | 13,171 |
| Distribution Main | 3957 | P-1110 | WW | Main St. | 8 | Cast Iron | 34 | 134 | 1.86 out of 5 | $442 | 15,174 |
| Distribution Main | 3967 | P-651 | WW | Main St. | 6 | Cast Iron | 10 | 134 | 2.57 out of 5 | $442 | 4,272 |
| Distribution Main | 3977 | P-641 | WW | Main St. | 8 | Ductile Iron | 169 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3978 | P-646 | WW | Main St. | 6 | Cast Iron | 91 | 134 | 2.57 out of 5 | $442 | 40,254 |
| Distribution Main | 3979 | P-646 | WW | Main St. | 6 | Cast Iron | 443 | 134 | 2.57 out of 5 | $442 | 195,946 |
| Distribution Main | 3980 | P-646 | WW | Main St. | 6 | Cast Iron | 33 | 134 | 2.57 out of 5 | $442 | 14,696 |
| Distribution Main | 3981 | | WW | Main St. | 6 | Unknown | 18 | UNK | 0.71 out of 5 | $442 | 7,806 |
| Distribution Main | 3982 | | WW | Main St. | 4 | Unknown | 42 | UNK | 1.42 out of 5 | $442 | 18,461 |
| Distribution Main | 4106 | P-661 | WW | Main St. | 6 | Cast Iron | 123 | 134 | 2.57 out of 5 | $442 | 54,291 |
| Distribution Main | 4107 | P-661 | WW | Main St. | 6 | Cast Iron | 72 | 134 | 2.57 out of 5 | $442 | 31,785 |
| Distribution Main | 4108 | P-663 | WW | Main St. | 6 | Cast Iron | 131 | 134 | 2.57 out of 5 | $442 | 57,738 |
| Distribution Main | 4109 | P-663 | WW | Main St. | 6 | Cast Iron | 14 | 134 | 2.57 out of 5 | $442 | 6,170 |
| Distribution Main | 4110 | P-651 | WW | Main St. | 6 | Cast Iron | 18 | 134 | 2.57 out of 5 | $442 | 7,898 |
| Distribution Main | 4111 | P-651 | WW | Main St. | 6 | Cast Iron | 138 | 134 | 2.57 out of 5 | $442 | 61,215 |
| Distribution Main | 4112 | P-650 | WW | Main St. | 6 | Cast Iron | 238 | 134 | 2.57 out of 5 | $442 | 105,218 |
| Distribution Main | 4113 | P-650 | WW | Main St. | 6 | Cast Iron | 340 | 134 | 2.57 out of 5 | $442 | 150,118 |
| Distribution Main | 4114 | P-1481 | WW | Main St. | 8 | Cast Iron | 24 | 134 | 1.86 out of 5 | $442 | 10,591 |
| Distribution Main | 4115 | P-1481 | WW | Main St. | 8 | Cast Iron | 10 | 134 | 1.86 out of 5 | $442 | 4,280 |
| Distribution Main | 4211 | | WW | Main St. | 8 | Cast Iron | 3 | 134 | 1.86 out of 5 | $442 | 1,452 |
| Distribution Main | 4288 | P-1337 | WW | Main St. | 8 | Cast Iron | 343 | 84 | 1.72 out of 5 | $442 | 151,444 |
| Distribution Main | 4297 | P-1481 | WW | Main St. | 8 | Cast Iron | 18 | 134 | 1.86 out of 5 | $442 | 7,879 |
| Distribution Main | 4300 | | WW | Main St. | 6 | Unknown | 128 | UNK | 0.71 out of 5 | $442 | 56,436 |
| Distribution Main | 4301 | P-646 | WW | Main St. | 6 | Unknown | 21 | UNK | 0.71 out of 5 | $442 | 9,395 |
| Distribution Main | 4325 | | WW | Main St. | 6 | Unknown | 59 | UNK | 0.71 out of 5 | $442 | 26,213 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4343 | P-1137 | WW | Main St. | 8 | Cast Iron | 304 | 134 | 1.86 out of 5 | $442 | 134,461 |
| Distribution Main | 4344 | P-1137 | WW | Main St. | 8 | Cast Iron | 422 | 134 | 1.86 out of 5 | $442 | 186,549 |
| Distribution Main | 4349 | P-1112 | WW | Main St. | 8 | Cast Iron | 409 | 134 | 1.86 out of 5 | $442 | 180,756 |
| Distribution Main | 4350 | P-1112 | WW | Main St. | 8 | Cast Iron | 23 | 134 | 1.86 out of 5 | $442 | 10,307 |
| Distribution Main | 4351 | P-1119 | WW | Main St. | 8 | Cast Iron | 156 | 134 | 1.86 out of 5 | $442 | 68,891 |
| Distribution Main | 4352 | P-1119 | WW | Main St. | 8 | Cast Iron | 283 | 134 | 1.86 out of 5 | $442 | 125,086 |
| Distribution Main | 4353 | P-1119 | WW | Main St. | 8 | Cast Iron | 141 | 134 | 1.86 out of 5 | $442 | 62,224 |
| Distribution Main | 4354 | P-1481 | WW | Main St. | 8 | Cast Iron | 344 | 134 | 1.86 out of 5 | $442 | 152,039 |
| Distribution Main | 4711 | P-1137 | WW | Main St. | 8 | Cast Iron | 12 | 84 | 1.72 out of 5 | $442 | 5,362 |
| Distribution Main | 4712 | P-1125 | WW | Main St. | 8 | Cast Iron | 35 | 134 | 1.86 out of 5 | $442 | 15,311 |
| Distribution Main | 5086 | P-1119 | WW | Main St. | 8 | Cast Iron | 6 | 134 | 1.86 out of 5 | $442 | 2,549 |
| Distribution Main | 5087 | P-1137 | WW | Main St. | 8 | Cast Iron | 138 | 134 | 1.86 out of 5 | $442 | 60,855 |
| Distribution Main | 5119 | P-1137 | WW | Main St. | 8 | Cast Iron | 167 | 134 | 1.86 out of 5 | $442 | 73,600 |
| Distribution Main | 8137 | P-1125 | WW | Main St. | 8 | Cast Iron | 117 | 134 | 1.86 out of 5 | $442 | 51,572 |
| Distribution Main | 8138 | P-1116 | WW | Main St. | 8 | Cast Iron | 101 | 134 | 1.86 out of 5 | $442 | 44,747 |
| Distribution Main | 8139 | P-1130 | WW | Main St. | 8 | Cast Iron | 75 | 134 | 1.86 out of 5 | $442 | 33,226 |
| Distribution Main | 8140 | P-1130 | WW | Main St. | 8 | Cast Iron | 20 | 134 | 1.86 out of 5 | $442 | 9,024 |
| Distribution Main | 9354 | P-1116 | WW | Main St. | 8 | Ductile Iron | 3 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9355 | P-1116 | WW | Main St. | 12 | Ductile Iron | 5 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9356 | P-1116 | WW | Main St. | 12 | Ductile Iron | 7 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9357 | P-1116 | WW | Main St. | 8 | Ductile Iron | 4 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9533 | P-1892 | WW | Main St. | 6 | Cast Iron | 30 | 134 | 2.57 out of 5 | $442 | 13,182 |
| Distribution Main | 9534 | P-1895 | WW | Main St. | 6 | Cast Iron | 28 | 83 | 2.43 out of 5 | $442 | 12,484 |
| Distribution Main | 9535 | P-1886 | WW | Main St. | 6 | Cast Iron | 67 | 134 | 2.57 out of 5 | $442 | 29,693 |
| Distribution Main | 9536 | P-1886 | WW | Main St. | 6 | Cast Iron | 30 | 134 | 2.57 out of 5 | $442 | 13,361 |
| Distribution Main | 9588 | | WW | Main St. | 8 | Cast Iron | 69 | 84 | 1.72 out of 5 | $442 | 30,282 |
| Distribution Main | 10356 | | WW | Main St. | 6 | Cast Iron | 6 | 84 | 2.43 out of 5 | $442 | 2,573 |
| Distribution Main | 11055 | P-1009 | WW | Main St. | 6 | Cast Iron | 35 | 134 | 2.57 out of 5 | $442 | 15,570 |
| Distribution Main | 11058 | P-1007 | WW | Main St. | 10 | Cast Iron | 8 | 134 | 1.86 out of 5 | $442 | 3,681 |
| Distribution Main | 11245 | P-1481 | WW | Main St. | 8 | Cast Iron | 2 | 134 | 1.86 out of 5 | $442 | 1,059 |
| Distribution Main | 11584 | P-1039 | WW | Main St. | 6 | Cast Iron | 26 | 134 | 2.57 out of 5 | $442 | 11,579 |
| Distribution Main | 11585 | P-1888 | WW | Main St. | 6 | Cast Iron | 14 | 134 | 2.57 out of 5 | $442 | 6,230 |
| Distribution Main | 12009 | P-646 | WW | Main St. | 6 | Cast Iron | 100 | 134 | 2.57 out of 5 | $442 | 44,414 |
| Distribution Main | 12013 | P-1030 | WW | Main St. | 8 | Cast Iron | 18 | 84 | 1.72 out of 5 | $442 | 8,151 |
| Distribution Main | 12016 | P-1112 | WW | Main St. | 8 | Cast Iron | 163 | 134 | 1.86 out of 5 | $442 | 72,025 |
| Distribution Main | 12189 | | WW | Main St. | 6 | Cast Iron | 68 | 134 | 2.57 out of 5 | $442 | 30,145 |
| Distribution Main | 12220 | P-641 | WW | Main St. | 8 | Cast Iron | 65 | 84 | 1.72 out of 5 | $442 | 28,612 |
| Distribution Main | 12237 | P-641 | WW | Main St. | 8 | Cast Iron | 49 | 84 | 1.72 out of 5 | $442 | 21,846 |
| Distribution Main | 3121 | P-1168 | WW | Main Street | 8 | Cast Iron | 25 | 91 | 1.72 out of 5 | $442 | 10,885 |
| Distribution Main | 3891 | P-1137 | WW | Main Street | 4 | Cast Iron | 7 | 132 | 3.29 out of 5 | $442 | 3,140 |
| Transmission Main | 4684 | P-1170 | WW | Main Street | 12 | Asbestos Cement | 479 | 54 | 1.14 out of 5 | $442 | 211,874 |
| Transmission Main | 4685 | P-1170 | WW | Main Street | 12 | Asbestos Cement | 522 | 54 | 1.14 out of 5 | $442 | 230,607 |
| Transmission Main | 4691 | P-1170 | WW | Main Street | 12 | Asbestos Cement | 322 | 54 | 1.14 out of 5 | $442 | 142,126 |
| Transmission Main | 4692 | P-1170 | WW | Main Street | 12 | Asbestos Cement | 68 | 54 | 1.14 out of 5 | $442 | 30,011 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4830 | P-1166 | WW | Main Street | 8 | Cast Iron | 1,073 | 91 | 1.72 out of 5 | $442 | 474,396 |
| Distribution Main | 4831 | P-1166 | WW | Main Street | 8 | Cast Iron | 379 | 91 | 1.72 out of 5 | $442 | 167,389 |
| Transmission Main | 4962 | P-1170 | WW | Main Street | 12 | Asbestos Cement | 37 | 54 | 1.14 out of 5 | $442 | 16,217 |
| Distribution Main | 5116 | P-1168 | WW | Main Street | 4 | Cast Iron | 500 | 132 | 3.29 out of 5 | $442 | 220,906 |
| Distribution Main | 5117 | P-1168 | WW | Main Street | 4 | Cast Iron | 887 | 132 | 3.29 out of 5 | $442 | 391,853 |
| Distribution Main | 5118 | | WW | Main Street | 4 | Cast Iron | 83 | 132 | 3.29 out of 5 | $442 | 36,648 |
| Distribution Main | 5120 | P-1166 | WW | Main Street | 8 | Cast Iron | 36 | 91 | 1.72 out of 5 | $442 | 16,021 |
| Transmission Main | 11278 | P-1170 | WW | Main Street | 12 | Asbestos Cement | 36 | 54 | 1.14 out of 5 | $442 | 15,731 |
| Distribution Main | 9252 | P-1132 | WW | Manchester St | 8 | Ductile Iron | 161 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9253 | P-1132 | WW | Manchester St | 8 | Ductile Iron | 10 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 163 | | WW | Manchester St. | 6 | Asbestos Cement | 24 | 134 | 2.29 out of 5 | $442 | 10,644 |
| Transmission Main | 166 | P-1136 | WW | Manchester St. | 12 | PVC | 179 | 32 | 0.43 out of 5 | $442 | 79,258 |
| Transmission Main | 167 | P-1136 | WW | Manchester St. | 12 | PVC | 249 | 32 | 0.43 out of 5 | $442 | 110,057 |
| Distribution Main | 1992 | | WW | Manchester St. | 8 | Ductile Iron | 7 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1993 | P-1122 | WW | Manchester St. | 4 | Cast Iron | 237 | 134 | 3.29 out of 5 | $442 | 104,937 |
| Distribution Main | 4090 | P-1121 | WW | Manchester St. | 4 | Cast Iron | 491 | 134 | 3.29 out of 5 | $442 | 216,915 |
| Distribution Main | 4091 | P-1120 | WW | Manchester St. | 4 | Cast Iron | 242 | 134 | 3.29 out of 5 | $442 | 107,127 |
| Distribution Main | 4570 | | WW | Manchester St. | 8 | Cast Iron | 249 | 134 | 1.86 out of 5 | $442 | 110,006 |
| Distribution Main | 9249 | | WW | Manchester St. | 8 | Cast Iron | 78 | 134 | 1.86 out of 5 | $442 | 34,601 |
| Distribution Main | 9324 | | WW | Manchester St. | 10 | PVC | 59 | 32 | 0.43 out of 5 | $442 | 26,283 |
| Distribution Main | 9359 | P-1992 | WW | Manchester St. | 4 | Ductile Iron | 14 | 14 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 9360 | P-1992 | WW | Manchester St. | 8 | Ductile Iron | 5 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9361 | | WW | Manchester St. | 6 | Ductile Iron | 12 | 14 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11242 | P-1121 | WW | Manchester St. | 4 | Cast Iron | 4 | 134 | 3.29 out of 5 | $442 | 1,653 |
| Transmission Main | 12055 | P-1136 | WW | Manchester St. | 12 | PVC | 20 | 32 | 0.43 out of 5 | $442 | 8,939 |
| Distribution Main | 10271 | P-1200 | WW | Maple Av | | Unknown | 8 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 8979 | P-1925 | WW | Maple Ave | 12 | Ductile Iron | 26 | 9 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8980 | P-1925 | WW | Maple Ave | 16 | Ductile Iron | 4 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8981 | P-1926 | WW | Maple Ave | 6 | Ductile Iron | 20 | 9 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10341 | P-1200 | WW | Maple Ave | 1.5 | Copper | 20 | UNK | 1.99 out of 5 | $442 | 9,044 |
| Distribution Main | 2398 | P-822 | WW | Maple Ave. | 6 | Cast Iron | 19 | 134 | 2.57 out of 5 | $442 | 8,415 |
| Distribution Main | 2399 | P-822 | WW | Maple Ave. | 6 | Cast Iron | 205 | 134 | 2.57 out of 5 | $442 | 90,558 |
| Distribution Main | 2947 | P-1200 | WW | Maple Ave. | 6 | Cast Iron | 479 | 134 | 2.57 out of 5 | $442 | 211,587 |
| Distribution Main | 2948 | P-823 | WW | Maple Ave. | 6 | Cast Iron | 371 | 134 | 2.57 out of 5 | $442 | 164,145 |
| Distribution Main | 2949 | P-823 | WW | Maple Ave. | 6 | Cast Iron | 10 | 134 | 2.57 out of 5 | $442 | 4,552 |
| Distribution Main | 3345 | P-822 | WW | Maple Ave. | 6 | Cast Iron | 44 | 134 | 2.57 out of 5 | $442 | 19,321 |
| Distribution Main | 3472 | P-1200 | WW | Maple Ave. | 6 | Cast Iron | 136 | 134 | 2.57 out of 5 | $442 | 60,304 |
| Distribution Main | 3473 | P-1200 | WW | Maple Ave. | 6 | Cast Iron | 114 | 134 | 2.57 out of 5 | $442 | 50,202 |
| Distribution Main | 11194 | P-1200 | WW | Maple Ave. | 6 | Cast Iron | 4 | 134 | 2.57 out of 5 | $442 | 1,722 |
| Distribution Main | 11195 | P-823 | WW | Maple Ave. | 6 | Cast Iron | 3 | 134 | 2.57 out of 5 | $442 | 1,286 |
| Distribution Main | 11220 | P-1200 | WW | Maple Ave. | 6 | Cast Iron | 108 | 134 | 2.57 out of 5 | $442 | 47,631 |
| Distribution Main | 12014 | P-823 | WW | Maple Ave. | 6 | Cast Iron | 245 | 134 | 2.57 out of 5 | $442 | 108,417 |
| Distribution Main | 12017 | P-1200 | WW | Maple Ave. | 6 | Cast Iron | 109 | 134 | 2.57 out of 5 | $442 | 48,220 |
| Distribution Main | 1511 | P-1204 | WW | Maple St. | 6 | Cast Iron | 202 | 89 | 2.43 out of 5 | $442 | 89,286 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2945 | P-1202 | WW | Maple St. | 6 | Cast Iron | 395 | 134 | 2.57 out of 5 | $442 | 174,744 |
| Distribution Main | 2946 | P-1202 | WW | Maple St. | 6 | Cast Iron | 43 | 134 | 2.57 out of 5 | $442 | 19,174 |
| Distribution Main | 3744 | P-1204 | WW | Maple St. | 6 | Cast Iron | 397 | 89 | 2.43 out of 5 | $442 | 175,518 |
| Distribution Main | 3745 | P-1204 | WW | Maple St. | 6 | Cast Iron | 52 | 89 | 2.43 out of 5 | $442 | 22,856 |
| Distribution Main | 12018 | P-1202 | WW | Maple St. | 6 | Cast Iron | 277 | 134 | 2.57 out of 5 | $442 | 122,434 |
| Distribution Main | 3438 | P-163 | WW | Marco Dr. | 8 | Asbestos Cement | 246 | 42 | 1.14 out of 5 | $442 | 108,900 |
| Distribution Main | 3869 | P-174 | WW | Marco Dr. | 8 | Asbestos Cement | 190 | 42 | 1.14 out of 5 | $442 | 84,071 |
| Distribution Main | 5163 | P-173 | WW | Marco Dr. | 8 | Asbestos Cement | 248 | 42 | 1.14 out of 5 | $442 | 109,782 |
| Distribution Main | 5164 | P-168 | WW | Marco Dr. | 8 | Asbestos Cement | 136 | 42 | 1.14 out of 5 | $442 | 59,930 |
| Distribution Main | 5165 | P-168 | WW | Marco Dr. | 8 | Asbestos Cement | 111 | 42 | 1.14 out of 5 | $442 | 49,264 |
| Distribution Main | 5166 | P-158 | WW | Marco Dr. | 8 | Asbestos Cement | 148 | 42 | 1.14 out of 5 | $442 | 65,604 |
| Distribution Main | 5167 | P-158 | WW | Marco Dr. | 8 | Asbestos Cement | 95 | 42 | 1.14 out of 5 | $442 | 41,912 |
| Distribution Main | 146 | P-319 | WW | Mark Fore Dr. | 8 | Asbestos Cement | 834 | 39 | 1 out of 5 | $442 | 368,753 |
| Distribution Main | 147 | P-319 | WW | Mark Fore Dr. | 8 | Asbestos Cement | 35 | 39 | 1 out of 5 | $442 | 15,441 |
| Distribution Main | 10298 | P-240 | WW | Market St | 8 | Ductile Iron | 225 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10299 | P-240 | WW | Market St | 8 | Ductile Iron | 339 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11996 | P-240 | WW | Market St | 8 | Ductile Iron | 313 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10618 | P-10026 | WW | Mary Av | 8 | Ductile Iron | 212 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10619 | P-401 | WW | Mary Av | 8 | Ductile Iron | 404 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11691 | P-403 | WW | Mary Av | 8 | Ductile Iron | 171 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8924 | P-140 | WW | Maryland Dr | 8 | Ductile Iron | 26 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8925 | P-140 | WW | Maryland Dr | 8 | Ductile Iron | 464 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3587 | P-1723 | WW | Maryland Dr. | 8 | Ductile Iron | 20 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3588 | P-1723 | WW | Maryland Dr. | 8 | Ductile Iron | 4 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10623 | P-398 | WW | Mason St | 8 | Ductile Iron | 248 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10885 | P-404 | WW | Mason St | 8 | Ductile Iron | 248 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10886 | P-406 | WW | Mason St | 8 | Ductile Iron | 186 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10887 | P-400 | WW | Mason St | 8 | Ductile Iron | 18 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10888 | P-400 | WW | Mason St | 8 | Ductile Iron | 213 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12147 | P-400 | WW | Mason St | 8 | Ductile Iron | 10 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8010 | P-554 | WW | Matteson Ave. | 8 | Cast Iron | 203 | 119 | 1.86 out of 5 | $442 | 89,903 |
| Distribution Main | 8011 | P-574 | WW | Matteson Ave. | 8 | Ductile Iron | 41 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8016 | P-1604 | WW | Matteson Ave. | 8 | Cast Iron | 435 | 119 | 1.86 out of 5 | $442 | 192,268 |
| Distribution Main | 8017 | P-1604 | WW | Matteson Ave. | 8 | Ductile Iron | 18 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8018 | P-553 | WW | Matteson Ave. | 8 | Ductile Iron | 21 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8019 | P-553 | WW | Matteson Ave. | 8 | Ductile Iron | 3 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8020 | P-553 | WW | Matteson Ave. | 8 | Cast Iron | 240 | 119 | 1.86 out of 5 | $442 | 105,951 |
| Distribution Main | 8152 | P-1604 | WW | Matteson Ave. | 8 | Cast Iron | 43 | 119 | 1.86 out of 5 | $442 | 19,169 |
| Distribution Main | 8169 | P-553 | WW | Matteson Ave. | 8 | Cast Iron | 76 | 119 | 1.86 out of 5 | $442 | 33,378 |
| Distribution Main | 8920 | P-1727 | WW | Maywood Dr. | 8 | Ductile Iron | 14 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9209 | P-1053 | WW | Mcelroy St | 8 | Ductile Iron | 31 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9210 | P-1053 | WW | Mcelroy St | 8 | Ductile Iron | 331 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3238 | P-740 | WW | Mcglynn St. | 1.5 | Copper | 461 | 78 | 3.14 out of 5 | $442 | 203,695 |
| Distribution Main | 1776 | P-749 | WW | Mcniff St. | 6 | Cast Iron | 132 | 79 | 2.28 out of 5 | $442 | 58,432 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3239 | P-742 | WW | Mcniff St. | 4 | Cast Iron | 61 | 79 | 3 out of 5 | $442 | 27,076 |
| Distribution Main | 3247 | P-743 | WW | Mcniff St. | 6 | Cast Iron | 313 | 79 | 2.28 out of 5 | $442 | 138,554 |
| Distribution Main | 3248 | P-743 | WW | Mcniff St. | 6 | Cast Iron | 24 | 79 | 2.28 out of 5 | $442 | 10,799 |
| Distribution Main | 3256 | P-751 | WW | Mcniff St. | 6 | Cast Iron | 154 | 79 | 3 out of 5 | $442 | 68,240 |
| Distribution Main | 3799 | P-742 | WW | Mcniff St. | 4 | Cast Iron | 15 | 79 | 3 out of 5 | $442 | 6,713 |
| Distribution Main | 10035 | P-247 | WW | Mcteers Ct | 8 | Ductile Iron | 372 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4214 | P-481 | WW | Meadow Dr. | 6 | Asbestos Cement | 655 | 63 | 2 out of 5 | $442 | 289,399 |
| Distribution Main | 1773 | P-845 | WW | Meadowchase Ln. | 8 | PVC | 330 | 31 | 0.43 out of 5 | $442 | 145,892 |
| Distribution Main | 2424 | P-6 | WW | Medeival Way | 8 | Ductile Iron | 241 | 28 | 0.14 out of 5 | $442 | 106,395 |
| Distribution Main | 2431 | P-13 | WW | Medeival Way | 8 | Ductile Iron | 323 | 28 | 0.14 out of 5 | $442 | 142,938 |
| Distribution Main | 2432 | P-13 | WW | Medeival Way | 8 | Ductile Iron | 212 | 28 | 0.14 out of 5 | $442 | 93,897 |
| Distribution Main | 2443 | P-5 | WW | Medeival Way | 8 | Ductile Iron | 442 | 28 | 0.14 out of 5 | $442 | 195,439 |
| Distribution Main | 4449 | P-20 | WW | Medeival Way | 8 | Ductile Iron | 259 | 28 | 0.14 out of 5 | $442 | 114,566 |
| Distribution Main | 4450 | P-20 | WW | Medeival Way | 8 | Ductile Iron | 33 | 28 | 0.14 out of 5 | $442 | 14,384 |
| Distribution Main | 4554 | P-14 | WW | Medeival Way | 8 | Ductile Iron | 248 | 28 | 0.14 out of 5 | $442 | 109,671 |
| Distribution Main | 4555 | P-14 | WW | Medeival Way | 8 | Ductile Iron | 403 | 28 | 0.14 out of 5 | $442 | 178,111 |
| Distribution Main | 1779 | P-838 | WW | Medinah Dr. | 8 | Ductile Iron | 214 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1780 | P-838 | WW | Medinah Dr. | 8 | Ductile Iron | 240 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9417 | P-838 | WW | Medinah Dr. | 8 | Ductile Iron | 4 | 18 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2318 | | WW | Meggan Ct. | 12 | Ductile Iron | 23 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2338 | P-1419 | WW | Meggan Ct. | 12 | PVC | 13 | 32 | 0.43 out of 5 | $442 | 5,739 |
| Transmission Main | 4755 | P-1187 | WW | Meggan Ct. | 12 | PVC | 308 | 32 | 0.43 out of 5 | $442 | 136,190 |
| Transmission Main | 4756 | P-1420 | WW | Meggan Ct. | 12 | PVC | 308 | 32 | 0.43 out of 5 | $442 | 136,019 |
| Transmission Main | 4757 | P-1420 | WW | Meggan Ct. | 12 | PVC | 25 | 32 | 0.43 out of 5 | $442 | 10,949 |
| Transmission Main | 10263 | P-1419 | WW | Meggan Ct. | 12 | PVC | 3 | 32 | 0.43 out of 5 | $442 | 1,134 |
| Transmission Main | 11167 | P-1419 | WW | Meggan Ct. | 12 | PVC | 8 | 32 | 0.43 out of 5 | $442 | 3,378 |
| Distribution Main | 8418 | P-1807 | WW | Mello St | 8 | Ductile Iron | 9 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8419 | P-1807 | WW | Mello St | 8 | Ductile Iron | 9 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1526 | P-943 | WW | Mello St. | 6 | Asbestos Cement | 66 | 68 | 2 out of 5 | $442 | 29,250 |
| Distribution Main | 1555 | P-942 | WW | Mello St. | 6 | Asbestos Cement | 164 | 68 | 2 out of 5 | $442 | 72,509 |
| Distribution Main | 1556 | P-944 | WW | Mello St. | 6 | Asbestos Cement | 325 | 68 | 2 out of 5 | $442 | 143,504 |
| Distribution Main | 1557 | P-944 | WW | Mello St. | 6 | Asbestos Cement | 192 | 68 | 2 out of 5 | $442 | 84,931 |
| Distribution Main | 3518 | P-1808 | WW | Mello Street | 6 | Unknown | 37 | 68 | 1.14 out of 5 | $442 | 16,406 |
| Distribution Main | 9423 | P-1808 | WW | Mello Street | 6 | Unknown | 10 | 68 | 1.14 out of 5 | $442 | 4,606 |
| Distribution Main | 9454 | P-1814 | WW | Mello Street | 1 | Unknown | 249 | 68 | 1.86 out of 5 | $442 | 110,277 |
| Distribution Main | 8497 | P-1800 | WW | Melrose St | 6 | Ductile Iron | 8 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9710 | P-1801 | WW | Melrose St | 8 | Ductile Iron | 6 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9711 | P-1801 | WW | Melrose St | 8 | Ductile Iron | 20 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 483 | P-1799 | WW | Melrose St. | 6 | Cast Iron | 12 | 81 | 2.43 out of 5 | $442 | 5,270 |
| Distribution Main | 1538 | P-959 | WW | Melrose St. | 6 | Cast Iron | 270 | 81 | 2.43 out of 5 | $442 | 119,172 |
| Distribution Main | 1539 | P-959 | WW | Melrose St. | 6 | Cast Iron | 472 | 81 | 2.43 out of 5 | $442 | 208,723 |
| Distribution Main | 1558 | P-958 | WW | Melrose St. | 6 | Cast Iron | 54 | 81 | 2.43 out of 5 | $442 | 24,006 |
| Distribution Main | 10605 | | WW | Miami St | 8 | Ductile Iron | 143 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10606 | P-410 | WW | Miami St | 8 | Ductile Iron | 247 | 2 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3567 | P-107 | WW | Michael St. | 6 | Asbestos Cement | 240 | 48 | 1.85 out of 5 | $442 | 106,064 |
| Distribution Main | 3570 | P-108 | WW | Michael St. | 6 | Asbestos Cement | 232 | 48 | 1.85 out of 5 | $442 | 102,325 |
| Distribution Main | 3271 | P-752 | WW | Middle St. | 2 | Galvanized Iron | 299 | 86 | 3.43 out of 5 | $442 | 132,349 |
| Distribution Main | 4653 | P-165 | WW | Midlands Dr. | 8 | Asbestos Cement | 423 | 42 | 1.14 out of 5 | $442 | 186,814 |
| Distribution Main | 8933 | P-1738 | WW | Midway Dr | 8 | Ductile Iron | 15 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8940 | P-1738 | WW | Midway Dr | 6 | Ductile Iron | 4 | 9 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8944 | P-191 | WW | Midway Dr | 8 | Ductile Iron | 4 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8945 | P-191 | WW | Midway Dr | 6 | Ductile Iron | 7 | 9 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9396 | P-1738 | WW | Midway Dr | 8 | Ductile Iron | 17 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4523 | P-1738 | WW | Midway Dr. | 6 | Asbestos Cement | 358 | 67 | 2 out of 5 | $442 | 158,035 |
| Distribution Main | 127 | P-677 | WW | Mill St. | 4 | Cast Iron | 265 | 134 | 3.29 out of 5 | $442 | 117,070 |
| Distribution Main | 1280 | P-8130 | WW | Mill St. | 6 | Cast Iron | 295 | 119 | 2.57 out of 5 | $442 | 130,184 |
| Distribution Main | 1281 | P-8130 | WW | Mill St. | 6 | Cast Iron | 226 | 119 | 2.57 out of 5 | $442 | 99,990 |
| Distribution Main | 4283 | P-676 | WW | Mill St. | 4 | Cast Iron | 438 | 134 | 3.29 out of 5 | $442 | 193,719 |
| Distribution Main | 4284 | P-676 | WW | Mill St. | 4 | Cast Iron | 27 | 134 | 3.29 out of 5 | $442 | 11,783 |
| Distribution Main | 8412 | P-1826 | WW | Miller Dr | 8 | Ductile Iron | 16 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8482 | P-1827 | WW | Miller Dr | 6 | Ductile Iron | 10 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 3691 | P-969 | WW | Miller Dr. | 6 | Asbestos Cement | 348 | 64 | 2 out of 5 | $442 | 153,715 |
| Distribution Main | 3692 | P-969 | WW | Miller Dr. | 6 | Asbestos Cement | 385 | 64 | 2 out of 5 | $442 | 170,276 |
| Distribution Main | 4447 | P-1380 | WW | Misty Oak Ct. | 6 | Ductile Iron | 137 | 28 | 0.85 out of 5 | $442 | 60,740 |
| Distribution Main | 1824 | P-509 | WW | Monterey Dr. | 8 | Asbestos Cement | 403 | 56 | 1.14 out of 5 | $442 | 177,990 |
| Distribution Main | 1825 | P-509 | WW | Monterey Dr. | 8 | Asbestos Cement | 940 | 56 | 1.14 out of 5 | $442 | 415,435 |
| Distribution Main | 3436 | P-505 | WW | Monterey Dr. | 8 | Asbestos Cement | 66 | 56 | 1.14 out of 5 | $442 | 29,358 |
| Distribution Main | 3437 | P-505 | WW | Monterey Dr. | 8 | Asbestos Cement | 202 | 56 | 1.14 out of 5 | $442 | 89,480 |
| Distribution Main | 3867 | P-503 | WW | Monterey Dr. | 8 | Asbestos Cement | 236 | 56 | 1.14 out of 5 | $442 | 104,230 |
| Distribution Main | 3868 | P-508 | WW | Monterey Dr. | 8 | Asbestos Cement | 234 | 56 | 1.14 out of 5 | $442 | 103,598 |
| Distribution Main | 4120 | P-506 | WW | Monterey Dr. | 8 | Asbestos Cement | 86 | 56 | 1.14 out of 5 | $442 | 37,816 |
| Distribution Main | 4121 | P-506 | WW | Monterey Dr. | 8 | Asbestos Cement | 155 | 56 | 1.14 out of 5 | $442 | 68,415 |
| Distribution Main | 4126 | P-500 | WW | Monterey Dr. | 8 | Asbestos Cement | 5 | 56 | 1.14 out of 5 | $442 | 2,075 |
| Distribution Main | 4603 | P-500 | WW | Monterey Dr. | 8 | Asbestos Cement | 563 | 56 | 1.14 out of 5 | $442 | 248,747 |
| Distribution Main | 4604 | P-500 | WW | Monterey Dr. | 8 | Asbestos Cement | 73 | 56 | 1.14 out of 5 | $442 | 32,321 |
| Distribution Main | 1155 | P-302 | WW | Moran St. | 8 | Asbestos Cement | 20 | 52 | 1.14 out of 5 | $442 | 9,057 |
| Distribution Main | 1156 | P-302 | WW | Moran St. | 8 | Asbestos Cement | 224 | 52 | 1.14 out of 5 | $442 | 98,881 |
| Distribution Main | 1583 | P-586 | WW | Moretti Dr. | 8 | Ductile Iron | 90 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8150 | P-586 | WW | Moretti Dr. | 8 | Ductile Iron | 225 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2503 | P-318 | WW | Morningside Dr. | 8 | Asbestos Cement | 25 | 41 | 1.14 out of 5 | $442 | 11,038 |
| Distribution Main | 2504 | P-318 | WW | Morningside Dr. | 8 | Asbestos Cement | 773 | 41 | 1.85 out of 5 | $442 | 341,566 |
| Distribution Main | 4014 | P-323 | WW | Morningside Dr. | 8 | Asbestos Cement | 296 | 41 | 1.14 out of 5 | $442 | 130,856 |
| Distribution Main | 5188 | P-308 | WW | Morningside Dr. | 8 | Asbestos Cement | 16 | 41 | 1.14 out of 5 | $442 | 7,245 |
| Distribution Main | 5198 | P-308 | WW | Morningside Dr. | 8 | Asbestos Cement | 11 | 41 | 1.14 out of 5 | $442 | 4,990 |
| Distribution Main | 5199 | P-308 | WW | Morningside Dr. | 8 | Asbestos Cement | 293 | 41 | 1.14 out of 5 | $442 | 129,321 |
| Distribution Main | 8005 | P-583 | WW | Morris St. | 6 | Ductile Iron | 19 | 14 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8006 | P-583 | WW | Morris St. | 6 | Asbestos Cement | 601 | 71 | 2 out of 5 | $442 | 265,747 |
| Distribution Main | 9622 | P-1382 | WW | Morris St. | 8 | Ductile Iron | 225 | 13 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 9623 | P-1382 | WW | Morris St. | 6 | Ductile Iron | 2 | 13 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10115 | P-585 | WW | Morris St. | 8 | Ductile Iron | 6 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3124 | P-10030 | WW | Mosalyk Street | 1 | Copper | 223 | 47 | 2.28 out of 5 | $442 | 98,716 |
| Distribution Main | 145 | P-314 | WW | Musket Rd. | 8 | Asbestos Cement | 703 | 39 | 1 out of 5 | $442 | 310,579 |
| Distribution Main | 2501 | P-310 | WW | Musket Rd. | 8 | Asbestos Cement | 38 | 39 | 1 out of 5 | $442 | 16,622 |
| Distribution Main | 2502 | P-310 | WW | Musket Rd. | 8 | Asbestos Cement | 220 | 39 | 1 out of 5 | $442 | 97,399 |
| Distribution Main | 806 | P-417 | WW | Myron St. | 6 | Asbestos Cement | 253 | 43 | 1.85 out of 5 | $442 | 111,960 |
| Distribution Main | 807 | P-417 | WW | Myron St. | 6 | Asbestos Cement | 338 | 43 | 1.85 out of 5 | $442 | 149,180 |
| Distribution Main | 4444 | P-417 | WW | Myron St. | 6 | Asbestos Cement | 6 | 43 | 1.85 out of 5 | $442 | 2,543 |
| Distribution Main | 1157 | P-299 | WW | Napolean St. | 6 | Asbestos Cement | 292 | 52 | 1.85 out of 5 | $442 | 129,100 |
| Distribution Main | 1158 | P-299 | WW | Napolean St. | 6 | Asbestos Cement | 62 | 52 | 1.85 out of 5 | $442 | 27,421 |
| Distribution Main | 643 | P-512 | WW | Narragansett Ave. | 8 | Ductile Iron | 97 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4663 | P-513 | WW | Narragansett Ave. | 8 | Ductile Iron | 322 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4664 | P-513 | WW | Narragansett Ave. | 8 | Ductile Iron | 99 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4673 | P-512 | WW | Narragansett Ave. | 8 | Ductile Iron | 843 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3502 | P-1837 | WW | Navarre St | 6 | Cast Iron | 173 | 84 | 2.43 out of 5 | $442 | 76,642 |
| Distribution Main | 3503 | P-1837 | WW | Navarre St | 6 | Cast Iron | 214 | 84 | 2.43 out of 5 | $442 | 94,515 |
| Distribution Main | 8405 | P-1835 | WW | Navarre St | 8 | Ductile Iron | 19 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8473 | P-1836 | WW | Navarre St | 6 | Ductile Iron | 17 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9429 | P-1837 | WW | Navarre St | 6 | Asbestos Cement | 290 | 84 | 2.14 out of 5 | $442 | 128,227 |
| Distribution Main | 915 | P-1082 | WW | Nestor St. | 6 | Cast Iron | 11 | 134 | 2.57 out of 5 | $442 | 4,988 |
| Distribution Main | 916 | | WW | Nestor St. | 2 | Galvanized Iron | 143 | 134 | 3.57 out of 5 | $442 | 63,413 |
| Distribution Main | 4714 | P-1083 | WW | Nestor St. | 6 | Cast Iron | 282 | 134 | 2.57 out of 5 | $442 | 124,747 |
| Distribution Main | 4715 | P-1083 | WW | Nestor St. | 6 | Cast Iron | 20 | 134 | 2.57 out of 5 | $442 | 8,811 |
| Distribution Main | 4717 | P-1083 | WW | Nestor St. | 6 | Cast Iron | 150 | 134 | 2.57 out of 5 | $442 | 66,081 |
| Distribution Main | 4718 | | WW | Nestor St. | 2 | Galvanized Iron | 145 | UNK | 2.85 out of 5 | $442 | 64,057 |
| Distribution Main | 5088 | | WW | Nestor St. | 2 | Galvanized Iron | 10 | 134 | 3.57 out of 5 | $442 | 4,370 |
| Distribution Main | 11262 | P-1083 | WW | Nestor St. | 6 | Cast Iron | 135 | 134 | 2.57 out of 5 | $442 | 59,450 |
| Distribution Main | 10357 | | WW | New London Av | 8 | PVC | 60 | UNK | 0.28 out of 5 | $442 | 26,475 |
| Transmission Main | 10671 | P-371 | WW | New London Av | 12 | Ductile Iron | 459 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10672 | P-1104 | WW | New London Av | 12 | Ductile Iron | 396 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10673 | P-1110 | WW | New London Av | 12 | Ductile Iron | 16 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10674 | P-370 | WW | New London Av | 12 | Ductile Iron | 65 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10765 | P-10060 | WW | New London Av | 12 | Ductile Iron | 355 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10766 | P-370 | WW | New London Av | 12 | Ductile Iron | 11 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10767 | P-370 | WW | New London Av | 12 | Ductile Iron | 338 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10770 | P-1308 | WW | New London Av | 12 | Ductile Iron | 433 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10771 | P-332 | WW | New London Av | 12 | Ductile Iron | 566 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10891 | P-645 | WW | New London Av | 12 | Ductile Iron | 10 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11700 | P-372 | WW | New London Av | 12 | Ductile Iron | 64 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11703 | P-372 | WW | New London Av | 12 | Ductile Iron | 254 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11704 | P-1105 | WW | New London Av | 12 | Ductile Iron | 221 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11705 | P-1103 | WW | New London Av | 12 | Ductile Iron | 29 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11720 | P-10060 | WW | New London Av | 12 | Ductile Iron | 423 | 0 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 11721 | P-10062 | WW | New London Av | 12 | Ductile Iron | 133 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11722 | P-10062 | WW | New London Av | 12 | Ductile Iron | 527 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11723 | P-1312 | WW | New London Av | 12 | Ductile Iron | 226 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11749 | P-332 | WW | New London Av | 12 | Ductile Iron | 170 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11913 | P-10062 | WW | New London Av | 12 | Ductile Iron | 38 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11919 | P-332 | WW | New London Av | 12 | Ductile Iron | 48 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12025 | P-1105 | WW | New London Av | 12 | Ductile Iron | 12 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12145 | P-332 | WW | New London Av | 12 | Ductile Iron | 410 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12157 | P-1312 | WW | New London Av | 12 | Ductile Iron | 26 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12166 | P-370 | WW | New London Av | 12 | Ductile Iron | 37 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12169 | P-1308 | WW | New London Av | 12 | Ductile Iron | 13 | 20 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12178 | P-332 | WW | New London Av | 12 | Ductile Iron | 55 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12190 | P-332 | WW | New London Av | 12 | Ductile Iron | 9 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 395 | P-10055 | WW | New London Ave. | 8 | Unknown | 12 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 955 | P-10054 | WW | New London Ave. | 8 | Asbestos Cement | 373 | 47 | 1.14 out of 5 | $442 | 164,656 |
| Distribution Main | 1043 | P-10057 | WW | New London Ave. | 8 | Asbestos Cement | 355 | UNK | 0.85 out of 5 | $442 | 156,836 |
| Distribution Main | 1044 | P-10054 | WW | New London Ave. | 8 | Asbestos Cement | 23 | 47 | 1.14 out of 5 | $442 | 10,017 |
| Distribution Main | 1145 | | WW | New London Ave. | 6 | Ductile Iron | 38 | UNK | 0.71 out of 5 | $442 | 16,695 |
| Distribution Main | 1413 | | WW | New London Ave. | 6 | Unknown | 449 | UNK | 0.71 out of 5 | $442 | 198,365 |
| Distribution Main | 1414 | P-10058 | WW | New London Ave. | 8 | Unknown | 48 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 1737 | P-326 | WW | New London Ave. | 8 | Asbestos Cement | 651 | 47 | 1.14 out of 5 | $442 | 287,778 |
| Distribution Main | 4011 | P-326 | WW | New London Ave. | 8 | Asbestos Cement | 43 | 47 | 1.14 out of 5 | $442 | 18,888 |
| Distribution Main | 4012 | P-324 | WW | New London Ave. | 8 | Asbestos Cement | 835 | 47 | 1.14 out of 5 | $442 | 369,204 |
| Distribution Main | 4013 | P-324 | WW | New London Ave. | 8 | Asbestos Cement | 244 | 47 | 1.14 out of 5 | $442 | 108,013 |
| Distribution Main | 4016 | P-328 | WW | New London Ave. | 8 | Asbestos Cement | 68 | 47 | 1.14 out of 5 | $442 | 30,025 |
| Distribution Main | 4017 | P-324 | WW | New London Ave. | 8 | Asbestos Cement | 25 | 47 | 1.14 out of 5 | $442 | 11,248 |
| Distribution Main | 4018 | P-328 | WW | New London Ave. | 8 | Asbestos Cement | 406 | 47 | 1.14 out of 5 | $442 | 179,254 |
| Distribution Main | 4341 | | WW | New London Ave. | 4 | Unknown | 65 | UNK | 1.42 out of 5 | $442 | 28,594 |
| Distribution Main | 4342 | | WW | New London Ave. | 6 | Unknown | 55 | UNK | 0.71 out of 5 | $442 | 24,210 |
| Distribution Main | 5194 | | WW | New London Ave. | 8 | Asbestos Cement | 10 | 47 | 1.14 out of 5 | $442 | 4,345 |
| Distribution Main | 5195 | P-324 | WW | New London Ave. | 8 | Asbestos Cement | 11 | 47 | 1.14 out of 5 | $442 | 4,791 |
| Transmission Main | 628 | P-1163 | WW | New London Tpk. | 12 | Asbestos Cement | 183 | 60 | 1.14 out of 5 | $442 | 80,875 |
| Transmission Main | 927 | P-26 | WW | New London Tpk. | 12 | Ductile Iron | 17 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1135 | P-1171 | WW | New London Tpk. | 12 | Asbestos Cement | 610 | 41 | 1.14 out of 5 | $442 | 269,783 |
| Transmission Main | 2353 | P-113 | WW | New London Tpk. | 12 | Asbestos Cement | 8 | 60 | 1.14 out of 5 | $442 | 3,693 |
| Transmission Main | 3087 | P-112 | WW | New London Tpk. | 12 | Asbestos Cement | 672 | 60 | 1.14 out of 5 | $442 | 296,819 |
| Transmission Main | 3088 | P-112 | WW | New London Tpk. | 12 | Asbestos Cement | 85 | 60 | 1.14 out of 5 | $442 | 37,626 |
| Transmission Main | 3089 | P-1171 | WW | New London Tpk. | 12 | Asbestos Cement | 174 | 41 | 1.14 out of 5 | $442 | 76,959 |
| Transmission Main | 3276 | P-1995 | WW | New London Tpk. | 12 | Asbestos Cement | 309 | 60 | 1.14 out of 5 | $442 | 136,491 |
| Transmission Main | 3277 | P-1995 | WW | New London Tpk. | 12 | Asbestos Cement | 310 | 60 | 1.14 out of 5 | $442 | 136,917 |
| Distribution Main | 3897 | | WW | New London Tpk. | 8 | Unknown | 12 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 4719 | P-1993 | WW | New London Tpk. | 12 | Asbestos Cement | 239 | 60 | 1.14 out of 5 | $442 | 105,483 |
| Transmission Main | 4720 | P-1993 | WW | New London Tpk. | 12 | Asbestos Cement | 474 | 60 | 1.14 out of 5 | $442 | 209,350 |
| Transmission Main | 4722 | P-1510 | WW | New London Tpk. | 12 | Asbestos Cement | 117 | 60 | 1.14 out of 5 | $442 | 51,680 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 4729 | P-26 | WW | New London Tpk. | 12 | Asbestos Cement | 307 | 59 | 1.14 out of 5 | $442 | 135,511 |
| Distribution Main | 4832 | | WW | New London Tpk. | 8 | Unknown | 9 | UNK | 0 out of 5 | N/A | $0 |
| Transmission Main | 4958 | P-114 | WW | New London Tpk. | 12 | Asbestos Cement | 576 | 60 | 1.14 out of 5 | $442 | 254,755 |
| Distribution Main | 5121 | P-1164 | WW | New London Tpk. | 8 | Cast Iron | 34 | 91 | 1.72 out of 5 | $442 | 14,839 |
| Distribution Main | 5122 | P-1164 | WW | New London Tpk. | 8 | Cast Iron | 505 | 91 | 1.72 out of 5 | $442 | 223,231 |
| Transmission Main | 5123 | P-1162 | WW | New London Tpk. | 12 | Asbestos Cement | 65 | 41 | 1.14 out of 5 | $442 | 28,543 |
| Transmission Main | 11081 | P-1163 | WW | New London Tpk. | 12 | Asbestos Cement | 13 | 60 | 1.14 out of 5 | $442 | 5,736 |
| Transmission Main | 11095 | P-26 | WW | New London Tpk. | 12 | Ductile Iron | 5 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11169 | P-113 | WW | New London Tpk. | 12 | Asbestos Cement | 4 | 60 | 1.14 out of 5 | $442 | 1,603 |
| Distribution Main | 12207 | P-1164 | WW | New London Tpk. | 8 | Cast Iron | 34 | 91 | 1.72 out of 5 | $442 | 15,092 |
| Distribution Main | 859 | P-301 | WW | Newell St. | 6 | Asbestos Cement | 774 | 39 | 1.71 out of 5 | $442 | 341,926 |
| Distribution Main | 862 | P-291 | WW | Newell St. | 6 | Ductile Iron | 247 | 26 | 0.85 out of 5 | $442 | 109,011 |
| Distribution Main | 2151 | P-286 | WW | Newell St. | 6 | Ductile Iron | 195 | 26 | 0.85 out of 5 | $442 | 86,261 |
| Distribution Main | 9903 | P-303 | WW | Newell St. | 8 | Asbestos Cement | 193 | 52 | 1.14 out of 5 | $442 | 85,440 |
| Distribution Main | 10924 | P-294 | WW | Newell St. | 6 | Ductile Iron | 207 | 26 | 0.85 out of 5 | $442 | 91,351 |
| Distribution Main | 10925 | P-290 | WW | Newell St. | 6 | Ductile Iron | 193 | 26 | 0.85 out of 5 | $442 | 85,328 |
| Distribution Main | 10926 | P-290 | WW | Newell St. | 6 | Ductile Iron | 22 | 26 | 0.85 out of 5 | $442 | 9,618 |
| Distribution Main | 8414 | P-1321 | WW | Newlight St | 8 | Ductile Iron | 23 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8422 | P-1824 | WW | Newlight St | 8 | Ductile Iron | 10 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8423 | P-1824 | WW | Newlight St | 8 | Ductile Iron | 3 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8488 | P-1822 | WW | Newlight St | 6 | Ductile Iron | 10 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 3693 | P-1362 | WW | Newlight St. | 6 | Asbestos Cement | 618 | 53 | 1.85 out of 5 | $442 | 273,019 |
| Distribution Main | 3330 | P-1878 | WW | Nichols Ct | 1 | Copper | 277 | 65 | 2.43 out of 5 | $442 | 122,475 |
| Distribution Main | 813 | P-1180 | WW | Nicole Dr. | 8 | Asbestos Cement | 237 | 39 | 1 out of 5 | $442 | 104,832 |
| Distribution Main | 4760 | P-1181 | WW | Nicole Dr. | 8 | Asbestos Cement | 751 | 39 | 1 out of 5 | $442 | 332,137 |
| Distribution Main | 4761 | P-1181 | WW | Nicole Dr. | 8 | Asbestos Cement | 148 | 39 | 1 out of 5 | $442 | 65,573 |
| Transmission Main | 7496 | P-266 | WW | Nobile St. | 12 | Ductile Iron | 362 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 7497 | P-266 | WW | Nobile St. | 12 | Ductile Iron | 6 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11380 | P-266 | WW | Nobile St. | 12 | Ductile Iron | 6 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4286 | P-685 | WW | Nolan St. | 2 | PVC | 408 | 41 | 2 out of 5 | $442 | 180,258 |
| Distribution Main | 4671 | P-446 | WW | North Gate Dr. | 6 | Asbestos Cement | 759 | 44 | 1.85 out of 5 | $442 | 335,279 |
| Transmission Main | 8385 | P-1242 | WW | North Pleasant St | 12 | Ductile Iron | 243 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8392 | P-1242 | WW | North Pleasant St | 12 | Ductile Iron | 111 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8393 | P-1242 | WW | North Pleasant St | 12 | Ductile Iron | 225 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8448 | P-1628 | WW | North Pleasant St | 6 | Ductile Iron | 17 | 10 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 8449 | P-1245 | WW | North Pleasant St | 12 | Ductile Iron | 391 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8451 | P-1658 | WW | North Pleasant St | 12 | Ductile Iron | 16 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8452 | P-1658 | WW | North Pleasant St | 12 | Ductile Iron | 82 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8453 | P-1658 | WW | North Pleasant St | 12 | Ductile Iron | 173 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8454 | P-1911 | WW | North Pleasant St | 12 | Ductile Iron | 84 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8455 | P-1911 | WW | North Pleasant St | 12 | Ductile Iron | 31 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11468 | P-1658 | WW | North Pleasant St | 12 | Ductile Iron | 69 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11469 | P-1242 | WW | North Pleasant St | 12 | Ductile Iron | 3 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1203 | P-1246 | WW | North Pleasant St. | 6 | Asbestos Cement | 610 | 44 | 1.85 out of 5 | $442 | 269,701 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 1204 | P-1246 | WW | North Pleasant St. | 6 | Asbestos Cement | 21 | 44 | 1.85 out of 5 | $442 | 9,074 |
| Distribution Main | 8380 | P-1628 | WW | North Pleasant St. | 6 | Asbestos Cement | 37 | 44 | 1.85 out of 5 | $442 | 16,559 |
| Transmission Main | 470 | P-1277 | WW | Nottingham Dr. | 16 | Ductile Iron | 572 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 475 | P-1441 | WW | Nottingham Dr. | 8 | Asbestos Cement | 424 | 46 | 1.14 out of 5 | $442 | 187,395 |
| Transmission Main | 985 | P-1277 | WW | Nottingham Dr. | 16 | Ductile Iron | 4 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1079 | | WW | Nottingham Dr. | 8 | Ductile Iron | 7 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1831 | P-10004 | WW | Nottingham Dr. | 8 | Asbestos Cement | 167 | 46 | 1.14 out of 5 | $442 | 73,961 |
| Distribution Main | 2354 | P-63 | WW | Nottingham Dr. | 8 | Asbestos Cement | 513 | 46 | 1.14 out of 5 | $442 | 226,953 |
| Distribution Main | 2355 | P-63 | WW | Nottingham Dr. | 8 | Asbestos Cement | 27 | 46 | 1.14 out of 5 | $442 | 11,926 |
| Distribution Main | 3556 | P-10001 | WW | Nottingham Dr. | 8 | Asbestos Cement | 159 | 46 | 1.14 out of 5 | $442 | 70,415 |
| Distribution Main | 3557 | P-10002 | WW | Nottingham Dr. | 6 | Asbestos Cement | 97 | 46 | 1.85 out of 5 | $442 | 42,657 |
| Distribution Main | 3563 | P-10003 | WW | Nottingham Dr. | 8 | Asbestos Cement | 6 | 46 | 1.14 out of 5 | $442 | 2,451 |
| Distribution Main | 4630 | P-64 | WW | Nottingham Dr. | 8 | Asbestos Cement | 355 | 46 | 1.14 out of 5 | $442 | 156,871 |
| Distribution Main | 4637 | P-10003 | WW | Nottingham Dr. | 8 | Asbestos Cement | 435 | 46 | 1.14 out of 5 | $442 | 192,419 |
| Distribution Main | 4638 | P-10003 | WW | Nottingham Dr. | 8 | Asbestos Cement | 120 | 46 | 1.14 out of 5 | $442 | 53,092 |
| Distribution Main | 4639 | P-10001 | WW | Nottingham Dr. | 8 | Asbestos Cement | 94 | 46 | 1.14 out of 5 | $442 | 41,351 |
| Distribution Main | 4640 | P-10001 | WW | Nottingham Dr. | 8 | Asbestos Cement | 139 | 46 | 1.14 out of 5 | $442 | 61,654 |
| Distribution Main | 10161 | P-10000 | WW | Nottingham Dr. | 8 | Asbestos Cement | 2 | 46 | 1.14 out of 5 | $442 | 837 |
| Distribution Main | 11097 | P-10000 | WW | Nottingham Dr. | 8 | Asbestos Cement | 16 | 46 | 1.14 out of 5 | $442 | 7,087 |
| Distribution Main | 12052 | P-63 | WW | Nottingham Dr. | 8 | Asbestos Cement | 27 | 46 | 1.14 out of 5 | $442 | 11,924 |
| Distribution Main | 10615 | | WW | Noxon St | 8 | Ductile Iron | 269 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12203 | | WW | Noxon St | 8 | Ductile Iron | 190 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 802 | P-415 | WW | Noxon St. | 6 | Asbestos Cement | 23 | 46 | 1.85 out of 5 | $442 | 10,086 |
| Distribution Main | 808 | P-416 | WW | Noxon St. | 6 | Asbestos Cement | 290 | 46 | 1.85 out of 5 | $442 | 128,245 |
| Distribution Main | 4442 | P-415 | WW | Noxon St. | 6 | Asbestos Cement | 236 | 46 | 1.85 out of 5 | $442 | 104,400 |
| Distribution Main | 4443 | P-415 | WW | Noxon St. | 6 | Asbestos Cement | 30 | 46 | 1.85 out of 5 | $442 | 13,458 |
| Distribution Main | 3492 | P-914 | WW | Oak St. | 6 | Cast Iron | 76 | 134 | 2.57 out of 5 | $442 | 33,469 |
| Distribution Main | 3493 | P-914 | WW | Oak St. | 6 | Cast Iron | 102 | 129 | 2.57 out of 5 | $442 | 45,250 |
| Distribution Main | 3735 | P-1851 | WW | Oak St. | 6 | Cast Iron | 122 | 134 | 2.57 out of 5 | $442 | 54,121 |
| Distribution Main | 9731 | P-915 | WW | Oak St. | 6 | Cast Iron | 115 | 134 | 2.57 out of 5 | $442 | 50,921 |
| Distribution Main | 8906 | | WW | Oakland Dr | 8 | Ductile Iron | 27 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8954 | P-1744 | WW | Oakland Dr | 8 | Ductile Iron | 310 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8956 | P-1746 | WW | Oakland Dr | 6 | Ductile Iron | 2 | 9 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10928 | P-212 | WW | Oakland Dr | 8 | Ductile Iron | 11 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11530 | P-1746 | WW | Oakland Dr | 8 | Ductile Iron | 23 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12099 | P-1744 | WW | Oakland Dr | 8 | Ductile Iron | 17 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3578 | P-222 | WW | Oakland Dr. | 8 | Ductile Iron | 32 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3584 | P-222 | WW | Oakland Dr. | 6 | Asbestos Cement | 367 | 72 | 2 out of 5 | $442 | 162,428 |
| Distribution Main | 6537 | P-211 | WW | Oakland Dr. | 6 | Asbestos Cement | 127 | 69 | 2 out of 5 | $442 | 56,161 |
| Distribution Main | 6538 | P-211 | WW | Oakland Dr. | 6 | Asbestos Cement | 119 | 69 | 2 out of 5 | $442 | 52,566 |
| Distribution Main | 8157 | P-222 | WW | Oakland Dr. | 6 | Ductile Iron | 29 | 15 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8903 | P-211 | WW | Oakland Dr. | 6 | Asbestos Cement | 96 | 69 | 2 out of 5 | $442 | 42,379 |
| Distribution Main | 8904 | P-212 | WW | Oakland Dr. | 6 | Asbestos Cement | 200 | 69 | 2 out of 5 | $442 | 88,373 |
| Distribution Main | 8905 | P-212 | WW | Oakland Dr. | 6 | Asbestos Cement | 20 | 69 | 2 out of 5 | $442 | 9,014 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 109 | P-1154 | WW | Oakridge Dr | 8 | PVC | 253 | 33 | 0.43 out of 5 | $442 | 112,030 |
| Distribution Main | 110 | P-1154 | WW | Oakridge Dr | 8 | PVC | 374 | 33 | 0.43 out of 5 | $442 | 165,471 |
| Distribution Main | 2153 | P-10020 | WW | Oakridge Dr. | 8 | PVC | 166 | 33 | 0.43 out of 5 | $442 | 73,415 |
| Distribution Main | 4775 | P-1152 | WW | Oakridge Dr. | 8 | PVC | 145 | 33 | 0.43 out of 5 | $442 | 64,090 |
| Distribution Main | 4776 | P-1152 | WW | Oakridge Dr. | 8 | PVC | 15 | 33 | 0.43 out of 5 | $442 | 6,433 |
| Distribution Main | 5067 | P-488 | WW | Old Carriage Rd. | 8 | Asbestos Cement | 455 | 43 | 1.14 out of 5 | $442 | 201,141 |
| Distribution Main | 5068 | P-488 | WW | Old Carriage Rd. | 8 | Asbestos Cement | 230 | 43 | 1.14 out of 5 | $442 | 101,788 |
| Distribution Main | 5069 | P-488 | WW | Old Carriage Rd. | 8 | Asbestos Cement | 450 | 43 | 1.14 out of 5 | $442 | 198,798 |
| Distribution Main | 5070 | P-488 | WW | Old Carriage Rd. | 8 | Asbestos Cement | 55 | 43 | 1.14 out of 5 | $442 | 24,271 |
| Distribution Main | 8997 | | WW | Old Quaker Ln | 10 | Ductile Iron | 14 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8998 | | WW | Old Quaker Ln | 10 | Ductile Iron | 9 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9001 | P-4708 | WW | Old Quaker Ln | 8 | Ductile Iron | 193 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9059 | | WW | Old Quaker Ln | 8 | Ductile Iron | 8 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11537 | | WW | Old Quaker Ln | 10 | Ductile Iron | 13 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5145 | P-1507 | WW | Ontario St. | 2 | Galvanized Iron | 235 | 56 | 3.14 out of 5 | $442 | 103,978 |
| Distribution Main | 5148 | P-1506 | WW | Ontario St. | 6 | PVC | 243 | 56 | 1.28 out of 5 | $442 | 107,499 |
| Distribution Main | 1974 | P-10038 | WW | Orchard St. | 2 | Copper | 103 | 48 | 2.28 out of 5 | $442 | 45,624 |
| Distribution Main | 4346 | P-1098 | WW | Orchard St. | 6 | Asbestos Cement | 200 | 48 | 1.85 out of 5 | $442 | 88,541 |
| Distribution Main | 4348 | P-1099 | WW | Orchard St. | 6 | Asbestos Cement | 120 | 48 | 1.85 out of 5 | $442 | 53,054 |
| Distribution Main | 9621 | P-584 | WW | Orrin St | 8 | Ductile Iron | 5 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10999 | | WW | Orrin St | 8 | Ductile Iron | 4 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 173 | P-584 | WW | Orrin St. | 8 | Ductile Iron | 40 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1886 | P-584 | WW | Orrin St. | 6 | Ductile Iron | 7 | 14 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8027 | P-584 | WW | Orrin St. | 6 | Asbestos Cement | 165 | 70 | 2.71 out of 5 | $442 | 72,869 |
| Distribution Main | 9353 | P-584 | WW | Orrin St. | 6 | Asbestos Cement | 38 | 70 | 2 out of 5 | $442 | 16,863 |
| Distribution Main | 10116 | P-584 | WW | Orrin St. | 6 | Ductile Iron | 8 | 13 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9833 | P-1973 | WW | Ottawa St | 8 | Ductile Iron | 263 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9834 | P-1973 | WW | Ottawa St | 8 | Ductile Iron | 15 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9837 | P-675 | WW | Ottawa St | 8 | Ductile Iron | 22 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9838 | P-675 | WW | Ottawa St | 8 | Ductile Iron | 222 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9839 | P-676 | WW | Ottawa St | 4 | Ductile Iron | 4 | 7 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 9916 | | WW | Ottawa St | 8 | Ductile Iron | 11 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11616 | P-1973 | WW | Ottawa St | 8 | Ductile Iron | 3 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12113 | P-675 | WW | Ottawa St | 8 | Ductile Iron | 21 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 125 | P-727 | WW | Ottawa St. | 6 | Cast Iron | 101 | 134 | 2.57 out of 5 | $442 | 44,551 |
| Distribution Main | 126 | P-727 | WW | Ottawa St. | 6 | Cast Iron | 128 | 134 | 2.57 out of 5 | $442 | 56,360 |
| Distribution Main | 138 | P-727 | WW | Ottawa St. | 6 | Cast Iron | 6 | 134 | 2.57 out of 5 | $442 | 2,721 |
| Distribution Main | 139 | P-727 | WW | Ottawa St. | 6 | Cast Iron | 10 | 134 | 2.57 out of 5 | $442 | 4,601 |
| Distribution Main | 869 | P-725 | WW | Ottawa St. | 6 | Cast Iron | 238 | 134 | 2.57 out of 5 | $442 | 105,204 |
| Distribution Main | 3265 | P-728 | WW | Ottawa St. | 6 | Cast Iron | 102 | 133 | 2.57 out of 5 | $442 | 45,241 |
| Distribution Main | 3763 | P-725 | WW | Ottawa St. | 6 | Cast Iron | 12 | 134 | 2.57 out of 5 | $442 | 5,124 |
| Distribution Main | 12064 | P-725 | WW | Ottawa St. | 6 | Cast Iron | 3 | 134 | 2.57 out of 5 | $442 | 1,188 |
| Distribution Main | 8909 | P-217 | WW | Overhill Dr | 8 | Ductile Iron | 210 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8910 | P-216 | WW | Overhill Dr | 8 | Ductile Iron | 6 | 9 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 8911 | P-216 | WW | Overhill Dr | 8 | Ductile Iron | 454 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8955 | P-1745 | WW | Overhill Dr | 8 | Ductile Iron | 319 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9399 | P-1734 | WW | Overhill Dr | 8 | Ductile Iron | 25 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5377 | P-1734 | WW | Overhill Dr. | 8 | Ductile Iron | 22 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8571 | P-933 | WW | Packard St | 8 | Ductile Iron | 29 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8573 | P-933 | WW | Packard St | 6 | Ductile Iron | 10 | 13 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 3736 | P-933 | WW | Packard St. | 6 | Cast Iron | 283 | 134 | 2.57 out of 5 | $442 | 125,168 |
| Distribution Main | 8038 | | WW | Park | 6 | Unknown | 18 | UNK | 0.71 out of 5 | $442 | 7,998 |
| Distribution Main | 8039 | | WW | Park | 6 | Unknown | 50 | UNK | 0.71 out of 5 | $442 | 22,003 |
| Distribution Main | 9467 | | WW | Park Ave | 1.5 | Copper | 381 | UNK | 1.99 out of 5 | $442 | 168,397 |
| Distribution Main | 10789 | P-331 | WW | Park Ave. | 8 | Ductile Iron | 253 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10790 | P-339 | WW | Park Blvd | 8 | Ductile Iron | 252 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12162 | P-339 | WW | Park Blvd | 8 | Ductile Iron | 315 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12198 | P-339 | WW | Park Blvd | 8 | Ductile Iron | 249 | 0 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8466 | P-979 | WW | Parker St | 12 | Ductile Iron | 144 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8467 | P-980 | WW | Parker St | 4 | Ductile Iron | 22 | 10 | 1.42 out of 5 | N/A | $0 |
| Transmission Main | 8468 | P-980 | WW | Parker St | 12 | Ductile Iron | 8 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11000 | P-979 | WW | Parker St | 12 | Ductile Iron | 3 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1521 | P-980 | WW | Parker St. | 6 | Cast Iron | 9 | 134 | 2.57 out of 5 | $442 | 4,152 |
| Distribution Main | 1522 | P-980 | WW | Parker St. | 6 | Cast Iron | 441 | 134 | 2.57 out of 5 | $442 | 194,863 |
| Distribution Main | 2481 | P-980 | WW | Parker St. | 6 | Cast Iron | 413 | 134 | 2.57 out of 5 | $442 | 182,470 |
| Distribution Main | 3698 | P-980 | WW | Parker St. | 6 | Cast Iron | 50 | 134 | 2.57 out of 5 | $442 | 22,288 |
| Distribution Main | 12029 | P-980 | WW | Parker St. | 6 | Cast Iron | 367 | 134 | 2.57 out of 5 | $442 | 162,089 |
| Distribution Main | 8737 | P-806 | WW | Patrick Quinn Drive | 6 | Asbestos Cement | 55 | 41 | 1.85 out of 5 | $442 | 24,417 |
| Distribution Main | 8738 | P-806 | WW | Patrick Quinn Drive | 6 | Asbestos Cement | 234 | 41 | 1.85 out of 5 | $442 | 103,461 |
| Distribution Main | 1438 | P-810 | WW | Patrick Rd. | 6 | Asbestos Cement | 251 | 41 | 1.85 out of 5 | $442 | 110,959 |
| Distribution Main | 3717 | P-807 | WW | Patrick Rd. | 6 | Asbestos Cement | 214 | 41 | 1.85 out of 5 | $442 | 94,595 |
| Distribution Main | 3719 | P-810 | WW | Patrick Rd. | 6 | Asbestos Cement | 7 | 41 | 1.85 out of 5 | $442 | 3,089 |
| Distribution Main | 10660 | | WW | Pauline St | 8 | Ductile Iron | 128 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10661 | | WW | Pauline St | 8 | Ductile Iron | 35 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10662 | | WW | Pauline St | 8 | Ductile Iron | 194 | 2 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1577 | P-580 | WW | Pawtuxet Ter. | 12 | Ductile Iron | 252 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1578 | P-580 | WW | Pawtuxet Ter. | 12 | Ductile Iron | 22 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1579 | P-582 | WW | Pawtuxet Ter. | 12 | Ductile Iron | 306 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1580 | P-585 | WW | Pawtuxet Ter. | 12 | Ductile Iron | 67 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1581 | P-585 | WW | Pawtuxet Ter. | 12 | Ductile Iron | 215 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1582 | P-592 | WW | Pawtuxet Ter. | 12 | Ductile Iron | 470 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4308 | P-556 | WW | Pawtuxet Ter. | 12 | Ductile Iron | 492 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8007 | P-580 | WW | Pawtuxet Ter. | 12 | Ductile Iron | 186 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8008 | P-580 | WW | Pawtuxet Ter. | 12 | Ductile Iron | 41 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8009 | P-577 | WW | Pawtuxet Ter. | 12 | Ductile Iron | 134 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8012 | P-1367 | WW | Pawtuxet Ter. | 12 | Ductile Iron | 337 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8141 | P-592 | WW | Pawtuxet Ter. | 12 | Ductile Iron | 379 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8151 | P-580 | WW | Pawtuxet Ter. | 12 | Ductile Iron | 112 | 14 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10060 | | WW | Payan St | 4 | Ductile Iron | 1 | 26 | 1.57 out of 5 | $442 | 525 |
| Distribution Main | 2388 | P-1063 | WW | Payan St. | 6 | Cast Iron | 147 | 83 | 2.43 out of 5 | $442 | 64,767 |
| Distribution Main | 2490 | P-1056 | WW | Payan St. | 6 | Cast Iron | 134 | 83 | 2.43 out of 5 | $442 | 59,138 |
| Distribution Main | 3241 | P-1062 | WW | Payan St. | 6 | Cast Iron | 230 | 83 | 2.43 out of 5 | $442 | 101,543 |
| Distribution Main | 3253 | P-1982 | WW | Payan St. | 6 | Cast Iron | 248 | 83 | 2.43 out of 5 | $442 | 109,570 |
| Distribution Main | 3257 | P-1062 | WW | Payan St. | 6 | Cast Iron | 27 | 83 | 2.43 out of 5 | $442 | 11,714 |
| Distribution Main | 3374 | P-1071 | WW | Payan St. | 6 | Cast Iron | 314 | 83 | 2.43 out of 5 | $442 | 138,921 |
| Distribution Main | 3797 | P-1059 | WW | Payan St. | 6 | Cast Iron | 160 | 83 | 2.43 out of 5 | $442 | 70,692 |
| Distribution Main | 3807 | P-1056 | WW | Payan St. | 6 | Cast Iron | 21 | 83 | 2.43 out of 5 | $442 | 9,132 |
| Distribution Main | 3808 | P-1057 | WW | Payan St. | 6 | Cast Iron | 77 | 83 | 2.43 out of 5 | $442 | 34,107 |
| Distribution Main | 12076 | P-1063 | WW | Payan St. | 6 | Cast Iron | 90 | 83 | 2.43 out of 5 | $442 | 39,582 |
| Distribution Main | 9679 | | WW | Pearce St | 8 | Ductile Iron | 26 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3865 | P-1484 | WW | Pearson St. | 2 | Cast Iron | 11 | 134 | 3.29 out of 5 | $442 | 4,975 |
| Distribution Main | 3866 | P-1484 | WW | Pearson St. | 2 | Cast Iron | 290 | 134 | 4 out of 5 | $442 | 128,155 |
| Distribution Main | 11237 | P-1484 | WW | Pearson St. | 2 | Cast Iron | 10 | 134 | 3.29 out of 5 | $442 | 4,213 |
| Distribution Main | 10613 | P-421 | WW | Penel Dr | 8 | Ductile Iron | 28 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10614 | P-421 | WW | Penel Dr | 6 | Ductile Iron | 3 | 2 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 3136 | P-421 | WW | Penel Dr. | 6 | Asbestos Cement | 459 | 56 | 1.85 out of 5 | $442 | 202,840 |
| Distribution Main | 9644 | P-10041 | WW | Pennsylvania Ave | 1 | Copper | 11 | 35 | 2.14 out of 5 | $442 | 4,739 |
| Distribution Main | 9645 | P-10041 | WW | Pennsylvania Ave | 1 | Copper | 91 | 35 | 2.14 out of 5 | $442 | 40,070 |
| Distribution Main | 4345 | P-1090 | WW | Pennsylvania Ave. | 6 | Cast Iron | 223 | 134 | 2.57 out of 5 | $442 | 98,551 |
| Distribution Main | 9642 | P-1478 | WW | Pennsylvania Ave. | 6 | PVC | 106 | 35 | 1.14 out of 5 | $442 | 46,983 |
| Distribution Main | 9643 | P-1478 | WW | Pennsylvania Ave. | 6 | PVC | 5 | 35 | 1.14 out of 5 | $442 | 2,158 |
| Distribution Main | 11588 | P-10041 | WW | Pennsylvania Ave. | 6 | PVC | 9 | 35 | 1.14 out of 5 | $442 | 4,046 |
| Transmission Main | 10306 | P-264 | WW | Penta St | 12 | Ductile Iron | 31 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 7377 | P-264 | WW | Penta St. | 12 | Ductile Iron | 297 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 7378 | P-264 | WW | Penta St. | 12 | Ductile Iron | 31 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 10320 | P-267 | WW | Penta St. | 12 | Ductile Iron | 1 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1975 | P-487 | WW | Pepin St. | 8 | Asbestos Cement | 28 | 55 | 1.14 out of 5 | $442 | 12,578 |
| Distribution Main | 1982 | P-486 | WW | Pepin St. | 8 | Asbestos Cement | 369 | 55 | 1.14 out of 5 | $442 | 163,285 |
| Distribution Main | 1983 | P-486 | WW | Pepin St. | 8 | Asbestos Cement | 317 | 55 | 1.14 out of 5 | $442 | 140,286 |
| Distribution Main | 5064 | P-487 | WW | Pepin St. | 8 | Asbestos Cement | 296 | 55 | 1.14 out of 5 | $442 | 130,805 |
| Distribution Main | 5065 | P-487 | WW | Pepin St. | 8 | Asbestos Cement | 525 | 55 | 1.14 out of 5 | $442 | 232,260 |
| Distribution Main | 5066 | | WW | Pepin St. | 8 | Asbestos Cement | 92 | 55 | 1.14 out of 5 | $442 | 40,598 |
| Distribution Main | 11875 | P-486 | WW | Pepin St. | 8 | Asbestos Cement | 221 | 55 | 1.14 out of 5 | $442 | 97,494 |
| Distribution Main | 10646 | P-378 | WW | Perkins St | 8 | Ductile Iron | 252 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10647 | P-378 | WW | Perkins St | 8 | Ductile Iron | 335 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10901 | P-378 | WW | Perkins St | 8 | Ductile Iron | 193 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12141 | P-379 | WW | Perkins St | 8 | Ductile Iron | 159 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1435 | P-1931 | WW | Peters Ln. | 8 | Asbestos Cement | 390 | 59 | 1.14 out of 5 | $442 | 172,188 |
| Distribution Main | 1563 | P-801 | WW | Peters Ln. | 8 | Asbestos Cement | 462 | 59 | 1.14 out of 5 | $442 | 204,154 |
| Distribution Main | 500 | P-293 | WW | Petti Dr. | 6 | Ductile Iron | 419 | 26 | 0.85 out of 5 | $442 | 185,147 |
| Distribution Main | 8815 | P-288 | WW | Petti Dr. | 6 | Ductile Iron | 204 | 26 | 0.85 out of 5 | $442 | 90,278 |
| Distribution Main | 8816 | P-288 | WW | Petti Dr. | 6 | Ductile Iron | 12 | 26 | 0.85 out of 5 | $442 | 5,414 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 11513 | P-288 | WW | Petti Dr. | 6 | Ductile Iron | 8 | 26 | 0.85 out of 5 | $442 | 3,608 |
| Distribution Main | 106 | P-951 | WW | Phenix Ave | 6 | Cast Iron | 66 | 134 | 2.57 out of 5 | $442 | 29,335 |
| Distribution Main | 107 | P-1825 | WW | Phenix Ave | 8 | Cast Iron | 463 | 87 | 1.72 out of 5 | $442 | 204,767 |
| Distribution Main | 108 | P-1825 | WW | Phenix Ave | 8 | Cast Iron | 285 | 87 | 1.72 out of 5 | $442 | 126,023 |
| Transmission Main | 8413 | P-1806 | WW | Phenix Ave | 12 | Ductile Iron | 163 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8425 | P-956 | WW | Phenix Ave | 12 | Ductile Iron | 59 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8426 | P-956 | WW | Phenix Ave | 12 | Ductile Iron | 408 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8430 | P-1798 | WW | Phenix Ave | 8 | Ductile Iron | 111 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8431 | P-1798 | WW | Phenix Ave | 8 | Ductile Iron | 6 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8483 | P-952 | WW | Phenix Ave | 8 | Ductile Iron | 15 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8484 | P-952 | WW | Phenix Ave | 12 | Ductile Iron | 8 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8485 | P-1360 | WW | Phenix Ave | 12 | Ductile Iron | 49 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8486 | P-1360 | WW | Phenix Ave | 12 | Ductile Iron | 23 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8487 | P-1824 | WW | Phenix Ave | 12 | Ductile Iron | 17 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8489 | P-1361 | WW | Phenix Ave | 12 | Ductile Iron | 202 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8491 | P-1815 | WW | Phenix Ave | 12 | Ductile Iron | 195 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8492 | P-1363 | WW | Phenix Ave | 12 | Ductile Iron | 16 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8493 | P-1363 | WW | Phenix Ave | 12 | Ductile Iron | 15 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8494 | P-1802 | WW | Phenix Ave | 12 | Ductile Iron | 94 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8495 | P-955 | WW | Phenix Ave | 12 | Ductile Iron | 122 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8496 | P-955 | WW | Phenix Ave | 12 | Ductile Iron | 102 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8498 | P-957 | WW | Phenix Ave | 12 | Ductile Iron | 185 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8500 | P-1797 | WW | Phenix Ave | 12 | Ductile Iron | 126 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8501 | P-1798 | WW | Phenix Ave | 12 | Ductile Iron | 13 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9712 | P-1802 | WW | Phenix Ave | 12 | Ductile Iron | 64 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11470 | P-1361 | WW | Phenix Ave | 12 | Ductile Iron | 7 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11471 | P-957 | WW | Phenix Ave | 12 | Ductile Iron | 63 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11590 | P-1804 | WW | Phenix Ave | 12 | Ductile Iron | 31 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 482 | P-961 | WW | Phenix Ave. | 8 | Asbestos Cement | 591 | 54 | 1.14 out of 5 | $442 | 261,160 |
| Distribution Main | 1523 | P-1842 | WW | Phenix Ave. | 6 | Cast Iron | 156 | 134 | 2.57 out of 5 | $442 | 69,153 |
| Distribution Main | 1801 | P-939 | WW | Phenix Ave. | 6 | Cast Iron | 242 | 134 | 2.57 out of 5 | $442 | 107,019 |
| Distribution Main | 3701 | P-949 | WW | Phenix Ave. | 6 | Cast Iron | 22 | 134 | 2.57 out of 5 | $442 | 9,686 |
| Distribution Main | 3702 | P-949 | WW | Phenix Ave. | 6 | Cast Iron | 164 | 134 | 2.57 out of 5 | $442 | 72,706 |
| Distribution Main | 3703 | P-950 | WW | Phenix Ave. | 8 | Cast Iron | 214 | 87 | 1.72 out of 5 | $442 | 94,417 |
| Distribution Main | 3731 | P-940 | WW | Phenix Ave. | 6 | Cast Iron | 130 | 134 | 2.57 out of 5 | $442 | 57,494 |
| Distribution Main | 3732 | P-940 | WW | Phenix Ave. | 6 | Cast Iron | 296 | 134 | 2.57 out of 5 | $442 | 130,642 |
| Distribution Main | 8552 | P-1841 | WW | Phenix Ave. | 8 | Ductile Iron | 23 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8566 | P-1842 | WW | Phenix Ave. | 4 | Ductile Iron | 11 | 13 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 11146 | P-939 | WW | Phenix Ave. | 6 | Cast Iron | 3 | 134 | 2.57 out of 5 | $442 | 1,260 |
| Distribution Main | 11147 | P-940 | WW | Phenix Ave. | 6 | Cast Iron | 2 | 134 | 2.57 out of 5 | $442 | 968 |
| Distribution Main | 327 | P-1352 | WW | Pike St. | 4 | Cast Iron | 320 | 134 | 3.29 out of 5 | $442 | 141,516 |
| Distribution Main | 328 | P-1352 | WW | Pike St. | 4 | Cast Iron | 299 | 134 | 3.29 out of 5 | $442 | 132,043 |
| Distribution Main | 3343 | P-1352 | WW | Pike St. | 4 | Cast Iron | 10 | 134 | 3.29 out of 5 | $442 | 4,573 |
| Transmission Main | 432 | P-1348 | WW | Pike Street | 12 | Asbestos Cement | 185 | 68 | 1.29 out of 5 | $442 | 81,828 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 433 | P-1348 | WW | Pike Street | 12 | Asbestos Cement | 317 | 68 | 1.29 out of 5 | $442 | 140,057 |
| Transmission Main | 3365 | P-1005 | WW | Pike Street | 12 | Asbestos Cement | 133 | 68 | 1.29 out of 5 | $442 | 58,767 |
| Transmission Main | 10243 | P-1005 | WW | Pike Street | 12 | Asbestos Cement | 39 | 68 | 1.29 out of 5 | $442 | 17,039 |
| Distribution Main | 8994 | P-1994 | WW | Pine Hollow Rd | 8 | Ductile Iron | 348 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12057 | P-1994 | WW | Pine Hollow Rd | 8 | Ductile Iron | 302 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1834 | P-125 | WW | Pine Orchard Rd. | 8 | Asbestos Cement | 497 | 42 | 1.14 out of 5 | $442 | 219,657 |
| Distribution Main | 1835 | P-125 | WW | Pine Orchard Rd. | 8 | Asbestos Cement | 24 | 42 | 1.14 out of 5 | $442 | 10,810 |
| Distribution Main | 4605 | P-134 | WW | Pine Orchard Rd. | 8 | Asbestos Cement | 14 | 42 | 1.14 out of 5 | $442 | 6,182 |
| Transmission Main | 4606 | P-134 | WW | Pine Orchard Rd. | 12 | Asbestos Cement | 515 | 42 | 1.14 out of 5 | $442 | 227,518 |
| Distribution Main | 4607 | P-124 | WW | Pine Orchard Rd. | 8 | Asbestos Cement | 524 | 42 | 1.14 out of 5 | $442 | 231,648 |
| Distribution Main | 4620 | P-123 | WW | Pine Orchard Rd. | 8 | Asbestos Cement | 544 | 44 | 1.14 out of 5 | $442 | 240,658 |
| Distribution Main | 5185 | P-124 | WW | Pine Orchard Rd. | 8 | Asbestos Cement | 57 | 42 | 1.14 out of 5 | $442 | 25,104 |
| Distribution Main | 12054 | P-125 | WW | Pine Orchard Rd. | 8 | Asbestos Cement | 48 | 42 | 1.14 out of 5 | $442 | 21,056 |
| Distribution Main | 3740 | P-825 | WW | Pine St. | 6 | Ductile Iron | 504 | 14 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 1818 | P-156 | WW | Pinewood Dr. | 8 | Asbestos Cement | 95 | 42 | 1.14 out of 5 | $442 | 42,112 |
| Distribution Main | 1819 | P-176 | WW | Pinewood Dr. | 8 | Asbestos Cement | 99 | 42 | 1.14 out of 5 | $442 | 43,952 |
| Distribution Main | 1820 | P-176 | WW | Pinewood Dr. | 8 | Asbestos Cement | 49 | 42 | 1.14 out of 5 | $442 | 21,492 |
| Distribution Main | 3870 | P-172 | WW | Pinewood Dr. | 8 | Asbestos Cement | 118 | 42 | 1.14 out of 5 | $442 | 52,196 |
| Distribution Main | 4659 | P-177 | WW | Pinewood Dr. | 8 | Asbestos Cement | 126 | 42 | 1.14 out of 5 | $442 | 55,642 |
| Distribution Main | 5168 | P-171 | WW | Pinewood Dr. | 8 | Asbestos Cement | 143 | 42 | 1.14 out of 5 | $442 | 63,057 |
| Distribution Main | 5169 | P-171 | WW | Pinewood Dr. | 8 | Asbestos Cement | 104 | 42 | 1.14 out of 5 | $442 | 45,961 |
| Distribution Main | 5170 | P-166 | WW | Pinewood Dr. | 8 | Asbestos Cement | 247 | 42 | 1.14 out of 5 | $442 | 109,231 |
| Distribution Main | 5171 | P-161 | WW | Pinewood Dr. | 8 | Asbestos Cement | 246 | 42 | 1.14 out of 5 | $442 | 108,712 |
| Distribution Main | 1774 | P-714 | WW | Plante St. | 2 | PVC | 320 | 38 | 1.85 out of 5 | $442 | 141,350 |
| Distribution Main | 8395 | P-1236 | WW | Pleasant St | 8 | Ductile Iron | 22 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8463 | P-1236 | WW | Pleasant St | 6 | Ductile Iron | 13 | 10 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 8555 | P-1920 | WW | Pleasant St | 12 | Ductile Iron | 36 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8556 | P-1918 | WW | Pleasant St | 12 | Ductile Iron | 11 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8557 | P-1917 | WW | Pleasant St | 12 | Ductile Iron | 14 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8558 | P-1918 | WW | Pleasant St | 8 | Ductile Iron | 32 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9704 | P-1919 | WW | Pleasant St | 12 | Ductile Iron | 11 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1788 | P-1908 | WW | Pleasant St. | 4 | Cast Iron | 19 | 134 | 3.29 out of 5 | $442 | 8,521 |
| Distribution Main | 2479 | P-1908 | WW | Pleasant St. | 6 | Cast Iron | 432 | 134 | 2.57 out of 5 | $442 | 190,900 |
| Distribution Main | 3520 | P-1229 | WW | Pleasant St. | 6 | Cast Iron | 153 | 134 | 2.57 out of 5 | $442 | 67,831 |
| Distribution Main | 3521 | P-1229 | WW | Pleasant St. | 6 | Cast Iron | 61 | 134 | 2.57 out of 5 | $442 | 26,781 |
| Distribution Main | 3706 | P-1254 | WW | Pleasant St. | 6 | Cast Iron | 8 | 134 | 2.57 out of 5 | $442 | 3,444 |
| Distribution Main | 3707 | P-1254 | WW | Pleasant St. | 6 | Cast Iron | 339 | 134 | 2.57 out of 5 | $442 | 149,631 |
| Distribution Main | 3708 | P-1254 | WW | Pleasant St. | 6 | Cast Iron | 218 | 134 | 2.57 out of 5 | $442 | 96,566 |
| Distribution Main | 8530 | P-1257 | WW | Pleasant St. | 8 | Cast Iron | 109 | 134 | 1.86 out of 5 | $442 | 48,047 |
| Distribution Main | 8531 | P-1254 | WW | Pleasant St. | 6 | Cast Iron | 25 | 134 | 2.57 out of 5 | $442 | 11,233 |
| Distribution Main | 8532 | P-1254 | WW | Pleasant St. | 6 | Cast Iron | 3 | 134 | 2.57 out of 5 | $442 | 1,414 |
| Transmission Main | 8533 | P-1255 | WW | Pleasant St. | 12 | Cast Iron | 114 | 134 | 1.86 out of 5 | $442 | 50,208 |
| Distribution Main | 9705 | P-1916 | WW | Pleasant St. | 8 | Cast Iron | 11 | 134 | 1.86 out of 5 | $442 | 4,819 |
| Distribution Main | 11474 | P-1257 | WW | Pleasant St. | 8 | Cast Iron | 17 | 134 | 1.86 out of 5 | $442 | 7,340 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 11475 | P-1255 | WW | Pleasant St. | 12 | Cast Iron | 46 | 134 | 1.86 out of 5 | $442 | 20,334 |
| Distribution Main | 9049 | P-1957 | WW | Podgurski St | 6 | Ductile Iron | 46 | 15 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 1136 | P-589 | WW | Podgurski St. | 8 | Ductile Iron | 40 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5386 | P-589 | WW | Podgurski St. | 6 | Asbestos Cement | 297 | 65 | 2 out of 5 | $442 | 131,336 |
| Distribution Main | 8026 | P-589 | WW | Podgurski St. | 6 | Ductile Iron | 4 | 14 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 610 | P-722 | WW | Pond St. | 12 | Cast Iron | 149 | 134 | 1.86 out of 5 | $442 | 65,650 |
| Transmission Main | 611 | P-722 | WW | Pond St. | 12 | Cast Iron | 249 | 134 | 1.86 out of 5 | $442 | 109,947 |
| Transmission Main | 1968 | P-721 | WW | Pond St. | 12 | Cast Iron | 273 | 134 | 1.86 out of 5 | $442 | 120,743 |
| Transmission Main | 2158 | P-723 | WW | Pond St. | 12 | Cast Iron | 187 | 134 | 1.86 out of 5 | $442 | 82,581 |
| Transmission Main | 3267 | P-718 | WW | Pond St. | 12 | Cast Iron | 507 | 89 | 1.72 out of 5 | $442 | 223,981 |
| Transmission Main | 3268 | P-718 | WW | Pond St. | 12 | Cast Iron | 28 | 89 | 1.72 out of 5 | $442 | 12,284 |
| Transmission Main | 3804 | P-720 | WW | Pond St. | 12 | Cast Iron | 283 | 89 | 1.72 out of 5 | $442 | 125,045 |
| Distribution Main | 1588 | P-1475 | WW | Pond View Dr. | 8 | Ductile Iron | 26 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1589 | P-1475 | WW | Pond View Dr. | 8 | Ductile Iron | 317 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3881 | P-457 | WW | Pond View Dr. | 8 | Ductile Iron | 303 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 4118 | P-507 | WW | Ponderosa Dr. | 6 | Asbestos Cement | 200 | 50 | 1.85 out of 5 | $442 | 88,322 |
| Distribution Main | 4119 | P-507 | WW | Ponderosa Dr. | 6 | Asbestos Cement | 561 | 50 | 1.85 out of 5 | $442 | 247,993 |
| Distribution Main | 2218 | P-1749 | WW | Pontiac Av | 10 | Ductile Iron | 707 | 29 | 0.14 out of 5 | $442 | 312,434 |
| Distribution Main | 5359 | P-1749 | WW | Pontiac Av | 10 | Ductile Iron | 77 | 29 | 0.14 out of 5 | $442 | 34,085 |
| Distribution Main | 8155 | P-1749 | WW | Pontiac Av | 10 | Ductile Iron | 8 | 29 | 0.14 out of 5 | $442 | 3,363 |
| Distribution Main | 8156 | P-1749 | WW | Pontiac Av | 10 | Ductile Iron | 125 | 29 | 0.14 out of 5 | $442 | 55,423 |
| Distribution Main | 10386 | P-1749 | WW | Pontiac Av | 10 | Ductile Iron | 29 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3331 | P-1044 | WW | Potter Ave. | 8 | Ductile Iron | 289 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3332 | P-1044 | WW | Potter Ave. | 8 | Ductile Iron | 4 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3333 | P-1043 | WW | Potter Ave. | 6 | Cast Iron | 31 | 134 | 2.57 out of 5 | $442 | 13,765 |
| Distribution Main | 3334 | P-1043 | WW | Potter Ave. | 6 | Cast Iron | 474 | 134 | 2.57 out of 5 | $442 | 209,394 |
| Distribution Main | 3344 | P-1043 | WW | Potter Ave. | 6 | Cast Iron | 17 | 134 | 2.57 out of 5 | $442 | 7,660 |
| Distribution Main | 8848 | P-1043 | WW | Potter Ave. | 6 | Cast Iron | 160 | 134 | 2.57 out of 5 | $442 | 70,783 |
| Distribution Main | 8849 | P-1043 | WW | Potter Ave. | 6 | Cast Iron | 282 | 134 | 2.57 out of 5 | $442 | 124,861 |
| Distribution Main | 8850 | P-1043 | WW | Potter Ave. | 6 | Cast Iron | 20 | 134 | 2.57 out of 5 | $442 | 8,654 |
| Distribution Main | 8851 | P-1043 | WW | Potter Ave. | 6 | Cast Iron | 80 | 134 | 2.57 out of 5 | $442 | 35,219 |
| Distribution Main | 10378 | P-1044 | WW | Potter Ave. | 6 | Cast Iron | 68 | 18 | 1.85 out of 5 | N/A | $0 |
| Transmission Main | 10032 | P-248 | WW | Prospect Hill Ave | 12 | Ductile Iron | 24 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10033 | P-248 | WW | Prospect Hill Ave | 12 | Ductile Iron | 264 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10036 | P-249 | WW | Prospect Hill Ave | 12 | Ductile Iron | 45 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10037 | P-254 | WW | Prospect Hill Ave | 12 | Ductile Iron | 525 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10040 | P-255 | WW | Prospect Hill Ave | 12 | Ductile Iron | 91 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10041 | P-257 | WW | Prospect Hill Ave | 12 | Ductile Iron | 254 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10043 | P-1768 | WW | Prospect Hill Ave | 8 | Ductile Iron | 67 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10050 | P-1520 | WW | Prospect Hill Ave | 8 | Ductile Iron | 423 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10301 | P-244 | WW | Prospect Hill Ave | 12 | Ductile Iron | 253 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10307 | P-246 | WW | Prospect Hill Ave | 12 | Ductile Iron | 305 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10308 | P-246 | WW | Prospect Hill Ave | 12 | Ductile Iron | 178 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11631 | P-254 | WW | Prospect Hill Ave | 12 | Ductile Iron | 3 | 6 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 11632 | P-254 | WW | Prospect Hill Ave | 12 | Ductile Iron | 35 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11633 | P-255 | WW | Prospect Hill Ave | 12 | Ductile Iron | 47 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11634 | P-258 | WW | Prospect Hill Ave | 8 | Ductile Iron | 8 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11997 | P-246 | WW | Prospect Hill Ave | 12 | Ductile Iron | 19 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12122 | P-248 | WW | Prospect Hill Ave | 12 | Ductile Iron | 7 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12123 | P-257 | WW | Prospect Hill Ave | 12 | Ductile Iron | 16 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9342 | P-245 | WW | Prospect St | 8 | Ductile Iron | 216 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9343 | P-245 | WW | Prospect St | 8 | Ductile Iron | 307 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10309 | P-245 | WW | Prospect St | 8 | Ductile Iron | 29 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8607 | P-1873 | WW | Providence St | 12 | Ductile Iron | 47 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8608 | P-1873 | WW | Providence St | 12 | Ductile Iron | 9 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8610 | P-1340 | WW | Providence St | 12 | Ductile Iron | 18 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8611 | P-1340 | WW | Providence St | 12 | Ductile Iron | 313 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8614 | P-1344 | WW | Providence St | 8 | Ductile Iron | 5 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8615 | P-1344 | WW | Providence St | 8 | Ductile Iron | 23 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8622 | P-1871 | WW | Providence St | 12 | Ductile Iron | 100 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8623 | P-1868 | WW | Providence St | 6 | Ductile Iron | 5 | 12 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 8624 | P-1869 | WW | Providence St | 12 | Ductile Iron | 5 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8625 | P-1869 | WW | Providence St | 12 | Ductile Iron | 85 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8626 | P-1872 | WW | Providence St | 6 | Ductile Iron | 3 | 12 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9414 | P-1714 | WW | Providence St | 8 | Ductile Iron | 33 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10013 | P-1318 | WW | Providence St | 8 | Ductile Iron | 275 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10014 | P-1307 | WW | Providence St | 8 | Ductile Iron | 323 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10054 | P-2563 | WW | Providence St | 8 | Ductile Iron | 5 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10296 | P-269 | WW | Providence St | 12 | Ductile Iron | 72 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10297 | P-242 | WW | Providence St | 12 | Ductile Iron | 275 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10305 | P-271 | WW | Providence St | 8 | Ductile Iron | 46 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10310 | P-238 | WW | Providence St | 12 | Ductile Iron | 258 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10311 | P-238 | WW | Providence St | 12 | Ductile Iron | 282 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10314 | P-232 | WW | Providence St | 12 | Ductile Iron | 384 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10318 | P-232 | WW | Providence St | 16 | Ductile Iron | 27 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10609 |  | WW | Providence St | 6 | Ductile Iron | 3 | UNK | 0.71 out of 5 | $442 | 1,316 |
| Distribution Main | 10814 | P-1317 | WW | Providence St | 8 | Ductile Iron | 68 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10815 | P-1317 | WW | Providence St | 8 | Ductile Iron | 99 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10816 | P-1758 | WW | Providence St | 8 | Ductile Iron | 135 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10817 | P-238 | WW | Providence St | 12 | Ductile Iron | 211 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10818 | P-238 | WW | Providence St | 12 | Ductile Iron | 43 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10819 | P-232 | WW | Providence St | 12 | Ductile Iron | 36 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10820 | P-232 | WW | Providence St | 12 | Ductile Iron | 389 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11485 | P-1873 | WW | Providence St | 12 | Ductile Iron | 7 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11628 | P-1307 | WW | Providence St | 8 | Ductile Iron | 19 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11629 | P-1318 | WW | Providence St | 8 | Ductile Iron | 44 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11649 | P-269 | WW | Providence St | 12 | Ductile Iron | 118 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11650 | P-232 | WW | Providence St | 12 | Ductile Iron | 14 | 5 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 11651 | P-223 | WW | Providence St | 16 | Ductile Iron | 6 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11991 | P-232 | WW | Providence St | 12 | Ductile Iron | 136 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11994 | P-239 | WW | Providence St | 12 | Ductile Iron | 46 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11995 | P-242 | WW | Providence St | 12 | Ductile Iron | 162 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11999 | P-1307 | WW | Providence St | 8 | Ductile Iron | 138 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12119 | P-1307 | WW | Providence St | 8 | Ductile Iron | 76 | 23 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 12120 | P-1307 | WW | Providence St | 8 | Ductile Iron | 28 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12121 | P-1307 | WW | Providence St | 8 | Ductile Iron | 31 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12126 | P-270 | WW | Providence St | 12 | Ductile Iron | 27 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 12127 | P-269 | WW | Providence St | 12 | Ductile Iron | 7 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12128 | P-242 | WW | Providence St | 12 | Ductile Iron | 10 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12129 | P-232 | WW | Providence St | 16 | Ductile Iron | 16 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12153 | P-269 | WW | Providence St | 12 | Ductile Iron | 11 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 324 | P-1686 | WW | Providence St. | 6 | Ductile Iron | 54 | 30 | 0.85 out of 5 | $442 | 23,898 |
| Distribution Main | 863 | P-1227 | WW | Providence St. | 8 | Ductile Iron | 394 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 956 | P-1870 | WW | Providence St. | 6 | Ductile Iron | 43 | 30 | 0.85 out of 5 | $442 | 18,947 |
| Distribution Main | 1067 | P-994 | WW | Providence St. | 10 | Cast Iron | 919 | 91 | 1.72 out of 5 | $442 | 406,187 |
| Distribution Main | 1073 | P-1032 | WW | Providence St. | 6 | Cast Iron | 81 | 134 | 2.57 out of 5 | $442 | 35,849 |
| Distribution Main | 1150 | P-1227 | WW | Providence St. | 8 | Ductile Iron | 149 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1693 | P-1018 | WW | Providence St. | 6 | Cast Iron | 189 | 134 | 2.57 out of 5 | $442 | 83,560 |
| Distribution Main | 1694 | P-1018 | WW | Providence St. | 6 | Cast Iron | 620 | 134 | 2.57 out of 5 | $442 | 274,075 |
| Distribution Main | 1695 | P-1877 | WW | Providence St. | 6 | Cast Iron | 154 | 84 | 2.43 out of 5 | $442 | 67,976 |
| Distribution Main | 1697 | P-1012 | WW | Providence St. | 6 | Cast Iron | 47 | 134 | 2.57 out of 5 | $442 | 20,745 |
| Distribution Main | 1698 | P-1012 | WW | Providence St. | 6 | Cast Iron | 755 | 134 | 2.57 out of 5 | $442 | 333,675 |
| Distribution Main | 2142 | P-304 | WW | Providence St. | 6 | Cast Iron | 14 | 91 | 2.43 out of 5 | $442 | 6,007 |
| Distribution Main | 2143 | P-304 | WW | Providence St. | 6 | Cast Iron | 250 | 91 | 2.43 out of 5 | $442 | 110,574 |
| Distribution Main | 2144 | P-1701 | WW | Providence St. | 10 | Cast Iron | 873 | 91 | 1.72 out of 5 | $442 | 385,951 |
| Distribution Main | 2145 | P-1701 | WW | Providence St. | 10 | Cast Iron | 325 | 91 | 1.72 out of 5 | $442 | 143,624 |
| Transmission Main | 2219 | P-154 | WW | Providence St. | 12 | Ductile Iron | 219 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2220 | P-162 | WW | Providence St. | 12 | Ductile Iron | 237 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2676 | P-1023 | WW | Providence St. | 6 | Cast Iron | 199 | 134 | 2.57 out of 5 | $442 | 87,761 |
| Transmission Main | 2964 | P-117 | WW | Providence St. | 12 | Ductile Iron | 3 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2966 | P-154 | WW | Providence St. | 12 | Ductile Iron | 5 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3347 | P-998 | WW | Providence St. | 6 | Cast Iron | 417 | 134 | 2.57 out of 5 | $442 | 184,139 |
| Distribution Main | 3348 | P-998 | WW | Providence St. | 6 | Cast Iron | 162 | 134 | 2.57 out of 5 | $442 | 71,814 |
| Distribution Main | 3355 | P-994 | WW | Providence St. | 10 | Cast Iron | 11 | 91 | 1.72 out of 5 | $442 | 5,058 |
| Distribution Main | 3366 | P-1014 | WW | Providence St. | 6 | Cast Iron | 102 | 134 | 2.57 out of 5 | $442 | 45,207 |
| Distribution Main | 3367 | P-1014 | WW | Providence St. | 6 | Cast Iron | 136 | 134 | 2.57 out of 5 | $442 | 60,008 |
| Distribution Main | 3369 | P-1022 | WW | Providence St. | 6 | Cast Iron | 126 | 134 | 2.57 out of 5 | $442 | 55,586 |
| Distribution Main | 3370 |  | WW | Providence St. | 6 | Unknown | 16 | UNK | 0.71 out of 5 | $442 | 7,057 |
| Distribution Main | 3371 | P-1022 | WW | Providence St. | 6 | Cast Iron | 191 | 134 | 2.57 out of 5 | $442 | 84,462 |
| Distribution Main | 3403 | P-1227 | WW | Providence St. | 8 | Ductile Iron | 80 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3404 | P-1227 | WW | Providence St. | 8 | Ductile Iron | 70 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 3405 | P-1316 | WW | Providence St. | 8 | Ductile Iron | 402 | 25 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 3406 | P-1316 | WW | Providence St. | 8 | Ductile Iron | 276 | 25 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 3575 | P-154 | WW | Providence St. | 12 | Ductile Iron | 4 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3576 | P-153 | WW | Providence St. | 12 | Ductile Iron | 251 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3577 | P-215 | WW | Providence St. | 12 | Ductile Iron | 209 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3579 | P-221 | WW | Providence St. | 12 | Ductile Iron | 241 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3580 | P-1748 | WW | Providence St. | 12 | Ductile Iron | 3 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3582 | P-1750 | WW | Providence St. | 12 | Ductile Iron | 347 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3583 | P-1750 | WW | Providence St. | 10 | Cast Iron | 18 | UNK | 1.14 out of 5 | $442 | 8,045 |
| Distribution Main | 4019 | P-994 | WW | Providence St. | 10 | Cast Iron | 150 | 91 | 1.72 out of 5 | $442 | 66,334 |
| Transmission Main | 4278 | P-1713 | WW | Providence St. | 12 | Ductile Iron | 233 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4280 | P-70 | WW | Providence St. | 12 | Cast Iron | 57 | 51 | 1.43 out of 5 | $442 | 25,054 |
| Transmission Main | 4386 | P-1763 | WW | Providence St. | 12 | Ductile Iron | 152 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 4387 | P-270 | WW | Providence St. | 12 | Ductile Iron | 203 | 23 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 5376 | P-221 | WW | Providence St. | 12 | Ductile Iron | 3 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5378 | P-223 | WW | Providence St. | 10 | Cast Iron | 36 | UNK | 1.14 out of 5 | $442 | 15,742 |
| Distribution Main | 5379 | P-223 | WW | Providence St. | 10 | Cast Iron | 51 | UNK | 1.14 out of 5 | $442 | 22,528 |
| Transmission Main | 5460 | P-213 | WW | Providence St. | 12 | Ductile Iron | 259 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8028 | P-1748 | WW | Providence St. | 12 | Ductile Iron | 73 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8029 | P-1748 | WW | Providence St. | 12 | Ductile Iron | 220 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8030 | P-117 | WW | Providence St. | 12 | Ductile Iron | 21 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8031 | P-46 | WW | Providence St. | 12 | Ductile Iron | 3 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8583 | P-994 | WW | Providence St. | 10 | Cast Iron | 102 | 91 | 1.72 out of 5 | $442 | 45,018 |
| Distribution Main | 8584 | P-994 | WW | Providence St. | 10 | Cast Iron | 136 | 91 | 1.72 out of 5 | $442 | 60,077 |
| Distribution Main | 8585 | P-994 | WW | Providence St. | 10 | Cast Iron | 79 | 91 | 1.72 out of 5 | $442 | 34,867 |
| Distribution Main | 8586 | P-994 | WW | Providence St. | 10 | Cast Iron | 298 | 91 | 1.72 out of 5 | $442 | 131,881 |
| Distribution Main | 8591 | P-1685 | WW | Providence St. | 6 | Cast Iron | 342 | 134 | 2.57 out of 5 | $442 | 151,288 |
| Distribution Main | 8592 | P-994 | WW | Providence St. | 10 | Cast Iron | 12 | 91 | 1.72 out of 5 | $442 | 5,395 |
| Distribution Main | 8593 | P-994 | WW | Providence St. | 10 | Cast Iron | 69 | 91 | 1.72 out of 5 | $442 | 30,310 |
| Distribution Main | 8594 | P-994 | WW | Providence St. | 10 | Cast Iron | 105 | 91 | 1.72 out of 5 | $442 | 46,272 |
| Distribution Main | 9057 | | WW | Providence St. | 8 | Ductile Iron | 1 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9088 | | WW | Providence St. | 8 | Ductile Iron | 3 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9393 | P-153 | WW | Providence St. | 12 | Ductile Iron | 4 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9398 | P-215 | WW | Providence St. | 12 | Ductile Iron | 18 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9410 | P-70 | WW | Providence St. | 10 | Cast Iron | 397 | UNK | 1.14 out of 5 | $442 | 175,536 |
| Distribution Main | 9418 | P-998 | WW | Providence St. | 6 | Cast Iron | 11 | 134 | 2.57 out of 5 | $442 | 4,851 |
| Distribution Main | 9523 | P-305 | WW | Providence St. | 10 | Cast Iron | 116 | 91 | 1.72 out of 5 | $442 | 51,251 |
| Distribution Main | 9524 | P-305 | WW | Providence St. | 10 | Cast Iron | 470 | 91 | 1.72 out of 5 | $442 | 207,897 |
| Distribution Main | 9525 | P-1227 | WW | Providence St. | 8 | Ductile Iron | 70 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9526 | P-1227 | WW | Providence St. | 8 | Ductile Iron | 74 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 9527 | P-1685 | WW | Providence St. | 6 | Cast Iron | 91 | 134 | 2.57 out of 5 | $442 | 40,300 |
| Distribution Main | 9528 | P-1685 | WW | Providence St. | 6 | Cast Iron | 59 | 134 | 2.57 out of 5 | $442 | 25,859 |
| Distribution Main | 9867 | P-1764 | WW | Providence St. | 8 | Cast Iron | 32 | 15 | 1.14 out of 5 | N/A | $0 |
| Distribution Main | 9868 | P-1762 | WW | Providence St. | 8 | Cast Iron | 54 | 91 | 1.72 out of 5 | $442 | 23,698 |
| Distribution Main | 9869 | P-1762 | WW | Providence St. | 8 | Ductile Iron | 24 | 15 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10417 | P-1764 | WW | Providence St. | 8 | Ductile Iron | 21 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10419 | P-223 | WW | Providence St. | 10 | Ductile Iron | 28 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10970 | P-117 | WW | Providence St. | 12 | Ductile Iron | 234 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10971 | P-46 | WW | Providence St. | 12 | Ductile Iron | 200 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11010 | P-117 | WW | Providence St. | 12 | Ductile Iron | 3 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11180 | P-1023 | WW | Providence St. | 6 | Cast Iron | 81 | 134 | 2.57 out of 5 | $442 | 35,797 |
| Distribution Main | 11181 | P-1023 | WW | Providence St. | 6 | Cast Iron | 36 | 134 | 2.57 out of 5 | $442 | 15,727 |
| Distribution Main | 11182 | P-1023 | WW | Providence St. | 6 | Cast Iron | 11 | 134 | 2.57 out of 5 | $442 | 4,979 |
| Distribution Main | 11215 | P-1316 | WW | Providence St. | 8 | Ductile Iron | 32 | 25 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11580 | P-1714 | WW | Providence St. | 10 | Cast Iron | 41 | UNK | 1.14 out of 5 | $442 | 18,148 |
| Distribution Main | 11581 | P-70 | WW | Providence St. | 10 | Cast Iron | 32 | UNK | 1.14 out of 5 | $442 | 14,330 |
| Distribution Main | 11751 | P-1701 | WW | Providence St. | 10 | Cast Iron | 264 | 91 | 1.72 out of 5 | $442 | 116,897 |
| Distribution Main | 11752 | P-1701 | WW | Providence St. | 10 | Cast Iron | 248 | 91 | 1.72 out of 5 | $442 | 109,783 |
| Distribution Main | 12003 | P-1018 | WW | Providence St. | 6 | Cast Iron | 373 | 134 | 2.57 out of 5 | $442 | 164,758 |
| Distribution Main | 12061 | P-1686 | WW | Providence St. | 6 | Ductile Iron | 48 | 30 | 0.85 out of 5 | $442 | 21,008 |
| Distribution Main | 9362 | | WW | Pulaski St | 6 | Ductile Iron | 16 | 14 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 170 | P-1127 | WW | Pulaski St. | 12 | Ductile Iron | 126 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 171 | P-1127 | WW | Pulaski St. | 12 | Ductile Iron | 168 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 172 | P-1602 | WW | Pulaski St. | 12 | Ductile Iron | 127 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 928 | P-596 | WW | Pulaski St. | 12 | Ductile Iron | 220 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 929 | P-594 | WW | Pulaski St. | 12 | Ductile Iron | 220 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 930 | P-1126 | WW | Pulaski St. | 12 | Ductile Iron | 167 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 931 | P-1126 | WW | Pulaski St. | 12 | Ductile Iron | 346 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 933 | P-593 | WW | Pulaski St. | 12 | Ductile Iron | 141 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 934 | P-602 | WW | Pulaski St. | 12 | Ductile Iron | 143 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 935 | P-602 | WW | Pulaski St. | 12 | Ductile Iron | 45 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1573 | P-601 | WW | Pulaski St. | 12 | Ductile Iron | 146 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1574 | P-605 | WW | Pulaski St. | 12 | Ductile Iron | 396 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1575 | P-605 | WW | Pulaski St. | 12 | Ductile Iron | 221 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1576 | P-609 | WW | Pulaski St. | 12 | Ductile Iron | 243 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1887 | P-1990 | WW | Pulaski St. | 12 | Ductile Iron | 26 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1889 | P-1990 | WW | Pulaski St. | 12 | Ductile Iron | 384 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 1892 | P-1990 | WW | Pulaski St. | 12 | Ductile Iron | 25 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5383 | | WW | Pulaski St. | 8 | Ductile Iron | 30 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5384 | P-599 | WW | Pulaski St. | 12 | Ductile Iron | 42 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 5385 | P-599 | WW | Pulaski St. | 12 | Ductile Iron | 198 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8143 | P-601 | WW | Pulaski St. | 12 | Ductile Iron | 108 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8144 | P-609 | WW | Pulaski St. | 12 | Ductile Iron | 41 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9358 | | WW | Pulaski St. | 8 | Ductile Iron | 27 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9375 | | WW | Pulaski St. | 8 | Ductile Iron | 3 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9895 | P-8012 | WW | Pulaski St. | 6 | Cast Iron | 10 | UNK | 1.85 out of 5 | $442 | 4,494 |
| Transmission Main | 11044 | P-1127 | WW | Pulaski St. | 12 | Ductile Iron | 46 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11149 | P-1990 | WW | Pulaski St. | 12 | Ductile Iron | 8 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11150 | P-1990 | WW | Pulaski St. | 12 | Ductile Iron | 15 | 14 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 11301 | P-599 | WW | Pulaski St. | 12 | Ductile Iron | 11 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11563 | P-1126 | WW | Pulaski St. | 12 | Ductile Iron | 6 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11747 | P-1127 | WW | Pulaski St. | 12 | Ductile Iron | 71 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11750 | P-1990 | WW | Pulaski St. | 12 | Ductile Iron | 8 | 14 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12007 | P-1126 | WW | Pulaski St. | 12 | Ductile Iron | 103 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1830 | P-491 | WW | Quaker Dr. | 8 | Asbestos Cement | 245 | 54 | 1.14 out of 5 | $442 | 108,342 |
| Distribution Main | 3428 | P-494 | WW | Quaker Dr. | 8 | Asbestos Cement | 238 | 54 | 1.14 out of 5 | $442 | 105,002 |
| Distribution Main | 3429 | P-494 | WW | Quaker Dr. | 8 | Asbestos Cement | 437 | 54 | 1.14 out of 5 | $442 | 193,181 |
| Distribution Main | 3545 | P-492 | WW | Quaker Dr. | 8 | Asbestos Cement | 434 | 54 | 1.14 out of 5 | $442 | 192,044 |
| Distribution Main | 4647 | P-491 | WW | Quaker Dr. | 8 | Asbestos Cement | 364 | 54 | 1.14 out of 5 | $442 | 161,050 |
| Distribution Main | 10152 | P-491 | WW | Quaker Dr. | 8 | Asbestos Cement | 42 | 54 | 1.14 out of 5 | $442 | 18,516 |
| Distribution Main | 8517 | P-2895 | WW | Quaker Lane | 6 | Ductile Iron | 383 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8518 | P-2895 | WW | Quaker Lane | 6 | Ductile Iron | 20 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8519 | P-2894 | WW | Quaker Lane | 6 | Ductile Iron | 54 | 20 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8520 | P-2894 | WW | Quaker Lane | 6 | Ductile Iron | 37 | 20 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 66 | P-10006 | WW | Quaker Ln | 12 | Ductile Iron | 180 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 67 | P-10006 | WW | Quaker Ln | 12 | Ductile Iron | 75 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9069 | P-10006 | WW | Quaker Ln | 12 | Ductile Iron | 197 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9070 | | WW | Quaker Ln | 6 | Ductile Iron | 24 | 15 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9698 | | WW | Quaker Ln | 6 | Ductile Iron | 64 | UNK | 0.71 out of 5 | $442 | 28,269 |
| Distribution Main | 9699 | | WW | Quaker Ln | 6 | Ductile Iron | 12 | 16 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9700 | | WW | Quaker Ln | 6 | Ductile Iron | 57 | UNK | 0.71 out of 5 | $442 | 25,220 |
| Transmission Main | 9860 | P-10006 | WW | Quaker Ln | 12 | Ductile Iron | 338 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9861 | P-10006 | WW | Quaker Ln | 16 | Ductile Iron | 23 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10141 | P-2892 | WW | Quaker Ln | 16 | Ductile Iron | 303 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10142 | P-2892 | WW | Quaker Ln | 16 | Ductile Iron | 795 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10143 | P-2970 | WW | Quaker Ln | 12 | Ductile Iron | 21 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10145 | | WW | Quaker Ln | 6 | Ductile Iron | 6 | 5 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10146 | | WW | Quaker Ln | 6 | Ductile Iron | 16 | 5 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 11014 | P-10006 | WW | Quaker Ln | 12 | Ductile Iron | 33 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11022 | P-10006 | WW | Quaker Ln | 12 | Ductile Iron | 26 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11216 | P-2892 | WW | Quaker Ln | 16 | Ductile Iron | 211 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11618 | P-10006 | WW | Quaker Ln | 16 | Ductile Iron | 6 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1875 | P-485 | WW | Quaker Ln. | 8 | PVC | 86 | 38 | 0.43 out of 5 | $442 | 38,122 |
| Distribution Main | 1984 | | WW | Quaker Ln. | 8 | Asbestos Cement | 8 | 39 | 1 out of 5 | $442 | 3,539 |
| Distribution Main | 3394 | P-485 | WW | Quaker Ln. | 8 | PVC | 385 | 38 | 0.43 out of 5 | $442 | 170,276 |
| Distribution Main | 3395 | P-485 | WW | Quaker Ln. | 8 | PVC | 351 | 38 | 0.43 out of 5 | $442 | 155,164 |
| Distribution Main | 3535 | P-10084 | WW | Quaker Ln. | 8 | Asbestos Cement | 271 | 45 | 1.14 out of 5 | $442 | 120,000 |
| Distribution Main | 3536 | P-10084 | WW | Quaker Ln. | 8 | Asbestos Cement | 1,090 | 45 | 1.14 out of 5 | $442 | 481,637 |
| Distribution Main | 3958 | P-485 | WW | Quaker Ln. | 8 | PVC | 38 | 38 | 0.43 out of 5 | $442 | 16,771 |
| Distribution Main | 3959 | P-485 | WW | Quaker Ln. | 8 | PVC | 104 | 38 | 0.43 out of 5 | $442 | 46,051 |
| Distribution Main | 5063 | P-484 | WW | Quaker Ln. | 8 | PVC | 355 | 38 | 0.43 out of 5 | $442 | 157,085 |
| Distribution Main | 5081 | | WW | Quaker Ln. | 8 | Asbestos Cement | 15 | 39 | 1 out of 5 | $442 | 6,546 |
| Distribution Main | 9071 | | WW | Quaker Ln. | 6 | Ductile Iron | 16 | 15 | 0.71 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 11285 | P-484 | WW | Quaker Ln. | 8 | PVC | 31 | 38 | 0.43 out of 5 | $442 | 13,681 |
| Distribution Main | 11286 | P-484 | WW | Quaker Ln. | 8 | PVC | 17 | 38 | 0.43 out of 5 | $442 | 7,412 |
| Distribution Main | 11763 | P-485 | WW | Quaker Ln. | 8 | PVC | 42 | 38 | 0.43 out of 5 | $442 | 18,461 |
| Distribution Main | 8660 | P-879 | WW | Queen Ann Ct. | 8 | Ductile Iron | 16 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8661 | P-879 | WW | Queen Ann Ct. | 8 | Ductile Iron | 255 | 16 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10786 | P-338 | WW | Queen Av | 8 | Ductile Iron | 435 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10878 | P-334 | WW | Queen Av | 8 | Ductile Iron | 13 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11744 | P-338 | WW | Queen Av | 8 | Ductile Iron | 224 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12154 | P-338 | WW | Queen Av | 8 | Ductile Iron | 299 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12197 | P-338 | WW | Queen Av | 8 | Ductile Iron | 367 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1802 | P-1389 | WW | Quill Dr. | 8 | Ductile Iron | 226 | 28 | 0.14 out of 5 | $442 | 99,757 |
| Distribution Main | 4452 | P-41 | WW | Quill Dr. | 8 | Ductile Iron | 5 | 28 | 0.14 out of 5 | $442 | 2,037 |
| Distribution Main | 4453 | P-41 | WW | Quill Dr. | 8 | Ductile Iron | 44 | 28 | 0.14 out of 5 | $442 | 19,616 |
| Distribution Main | 4556 | P-41 | WW | Quill Dr. | 6 | Ductile Iron | 412 | 28 | 0.85 out of 5 | $442 | 182,017 |
| Distribution Main | 10642 | | WW | Quinlan St | 8 | Ductile Iron | 150 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10643 | | WW | Quinlan St | 8 | Ductile Iron | 170 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9499 | | WW | Quiver Dr | 8 | Asbestos Cement | 85 | 46 | 1.14 out of 5 | $442 | 37,451 |
| Distribution Main | 1126 | P-43 | WW | Quiver Dr. | 8 | Ductile Iron | 338 | 28 | 0.14 out of 5 | $442 | 149,539 |
| Distribution Main | 1127 | P-43 | WW | Quiver Dr. | 8 | Ductile Iron | 212 | 28 | 0.14 out of 5 | $442 | 93,533 |
| Distribution Main | 8847 | P-692 | WW | Rathburn St. | 6 | Asbestos Cement | 542 | 63 | 2 out of 5 | $442 | 239,744 |
| Distribution Main | 9907 | P-1946 | WW | Red Brook Ln | 8 | Ductile Iron | 90 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9908 | | WW | Red Brook Ln | 8 | Ductile Iron | 37 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9909 | P-1946 | WW | Red Brook Ln | 8 | Ductile Iron | 58 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8048 | P-776 | WW | Regnaiere Ct | 6 | PVC | 206 | UNK | 0.99 out of 5 | $442 | 90,951 |
| Distribution Main | 4828 | P-518 | WW | Rei St. | 6 | Asbestos Cement | 134 | 72 | 2 out of 5 | $442 | 59,185 |
| Distribution Main | 9250 | P-1131 | WW | Remington St | 8 | Ductile Iron | 8 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9251 | P-1131 | WW | Remington St | 8 | Ductile Iron | 24 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9254 | | WW | Remington St | 8 | Ductile Iron | 8 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9255 | | WW | Remington St | 6 | Ductile Iron | 12 | 13 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11562 | P-1131 | WW | Remington St | 8 | Ductile Iron | 8 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 925 | | WW | Remington St. | 6 | Cast Iron | 248 | 124 | 3.29 out of 5 | $442 | 109,683 |
| Distribution Main | 3501 | P-1906 | WW | Renaudet St | 0.75 | Unknown | 416 | UNK | 1.42 out of 5 | $442 | 183,831 |
| Distribution Main | 8400 | P-1906 | WW | Renaudet St | 8 | Ductile Iron | 30 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8401 | P-1906 | WW | Renaudet St | 8 | Ductile Iron | 11 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9675 | P-1906 | WW | Renaudet St | 0.75 | Unknown | 2 | 10 | 1.42 out of 5 | N/A | $0 |
| Distribution Main | 322 | | WW | Renehan Ct | 2 | Unknown | 163 | UNK | 1.42 out of 5 | $442 | 71,957 |
| Distribution Main | 3118 | P-526 | WW | Revere Av | 6 | Asbestos Cement | 39 | 78 | 2 out of 5 | $442 | 17,084 |
| Distribution Main | 3119 | P-526 | WW | Revere Av | 6 | Asbestos Cement | 206 | 78 | 2 out of 5 | $442 | 91,043 |
| Distribution Main | 9492 | P-526 | WW | Revere Av | 6 | Asbestos Cement | 188 | 78 | 2 out of 5 | $442 | 83,309 |
| Distribution Main | 10624 | P-397 | WW | Revere Av | 8 | Ductile Iron | 350 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10625 | P-397 | WW | Revere Av | 8 | Ductile Iron | 402 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10626 | P-392 | WW | Revere Av | 8 | Ductile Iron | 156 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10627 | P-390 | WW | Revere Av | 8 | Ductile Iron | 172 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10628 | P-390 | WW | Revere Av | 8 | Ductile Iron | 272 | 2 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10898 | P-392 | WW | Revere Av | 8 | Ductile Iron | 287 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11692 | P-10028 | WW | Revere Av | 8 | Ductile Iron | 185 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11693 | P-393 | WW | Revere Av | 8 | Ductile Iron | 56 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 213 | P-335 | WW | Rex St. | 8 | Ductile Iron | 34 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4337 | P-336 | WW | Rex St. | 8 | Ductile Iron | 205 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4338 | P-336 | WW | Rex St. | 8 | Ductile Iron | 253 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10879 | P-335 | WW | Rex St. | 8 | Ductile Iron | 264 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8398 | P-1232 | WW | Richard St | 8 | Ductile Iron | 17 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8399 | P-1232 | WW | Richard St | 8 | Ductile Iron | 3 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8465 | P-1232 | WW | Richard St | 6 | Ductile Iron | 4 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 3527 | P-1232 | WW | Richard St. | 6 | Asbestos Cement | 505 | 64 | 2 out of 5 | $442 | 223,322 |
| Distribution Main | 10629 | P-389 | WW | Ridge St | 8 | Ductile Iron | 220 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10630 | P-387 | WW | Ridge St | 8 | Ductile Iron | 178 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11694 | P-387 | WW | Ridge St | 8 | Ductile Iron | 66 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 12177 | P-389 | WW | Ridge St | 8 | Ductile Iron | 7 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3269 | P-738 | WW | Rita St. | 8 | Ductile Iron | 492 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 35 | P-1953 | WW | Ritchotte Court | 6 | Asbestos Cement | 33 | 39 | 1.71 out of 5 | $442 | 14,462 |
| Distribution Main | 8841 | P-1953 | WW | Ritchotte Court | 6 | Asbestos Cement | 184 | 39 | 1.71 out of 5 | $442 | 81,184 |
| Distribution Main | 8842 | P-1953 | WW | Ritchotte Court | 6 | Asbestos Cement | 177 | 39 | 1.71 out of 5 | $442 | 78,416 |
| Distribution Main | 2138 | P-287 | WW | River Ave. | 6 | Ductile Iron | 304 | 26 | 0.85 out of 5 | $442 | 134,236 |
| Distribution Main | 2139 | P-287 | WW | River Ave. | 6 | Ductile Iron | 508 | 26 | 0.85 out of 5 | $442 | 224,475 |
| Distribution Main | 524 | | WW | River Farm Lane | 6 | PVC | 324 | UNK | 0.99 out of 5 | $442 | 143,148 |
| Transmission Main | 525 | P-1776 | WW | River Farms Dr. | 12 | PVC | 254 | 30 | 0.43 out of 5 | $442 | 112,133 |
| Transmission Main | 993 | P-1778 | WW | River Farms Dr. | 12 | PVC | 247 | 30 | 0.43 out of 5 | $442 | 109,329 |
| Transmission Main | 994 | P-1780 | WW | River Farms Dr. | 12 | PVC | 413 | 30 | 0.43 out of 5 | $442 | 182,466 |
| Distribution Main | 2089 | P-884 | WW | River Farms Dr. | 8 | PVC | 278 | 29 | 0.43 out of 5 | $442 | 123,047 |
| Distribution Main | 2090 | P-884 | WW | River Farms Dr. | 8 | PVC | 135 | 29 | 0.43 out of 5 | $442 | 59,491 |
| Transmission Main | 2091 | P-881 | WW | River Farms Dr. | 12 | PVC | 153 | 30 | 0.43 out of 5 | $442 | 67,840 |
| Transmission Main | 2092 | P-1773 | WW | River Farms Dr. | 12 | PVC | 191 | 30 | 0.43 out of 5 | $442 | 84,609 |
| Transmission Main | 8646 | P-1325 | WW | River Farms Dr. | 12 | PVC | 75 | 30 | 0.43 out of 5 | $442 | 33,163 |
| Transmission Main | 8647 | P-1325 | WW | River Farms Dr. | 12 | PVC | 160 | 30 | 0.43 out of 5 | $442 | 70,704 |
| Transmission Main | 8649 | P-1325 | WW | River Farms Dr. | 12 | PVC | 244 | 30 | 0.43 out of 5 | $442 | 107,954 |
| Transmission Main | 8650 | P-1326 | WW | River Farms Dr. | 12 | PVC | 353 | 30 | 0.43 out of 5 | $442 | 156,136 |
| Transmission Main | 8651 | P-1326 | WW | River Farms Dr. | 12 | PVC | 175 | 30 | 0.43 out of 5 | $442 | 77,197 |
| Transmission Main | 8654 | P-878 | WW | River Farms Dr. | 12 | PVC | 151 | 30 | 0.43 out of 5 | $442 | 66,589 |
| Transmission Main | 8655 | P-878 | WW | River Farms Dr. | 12 | PVC | 119 | 30 | 0.43 out of 5 | $442 | 52,459 |
| Transmission Main | 8656 | P-1780 | WW | River Farms Dr. | 12 | PVC | 149 | 30 | 0.43 out of 5 | $442 | 65,993 |
| Transmission Main | 8665 | P-1325 | WW | River Farms Dr. | 12 | PVC | 121 | 30 | 0.43 out of 5 | $442 | 53,389 |
| Transmission Main | 8666 | P-885 | WW | River Farms Dr. | 12 | PVC | 113 | 30 | 0.43 out of 5 | $442 | 49,860 |
| Transmission Main | 8671 | P-1320 | WW | River Farms Dr. | 12 | PVC | 39 | 30 | 0.43 out of 5 | $442 | 17,309 |
| Transmission Main | 8672 | P-1320 | WW | River Farms Dr. | 12 | PVC | 481 | 30 | 0.43 out of 5 | $442 | 212,607 |
| Transmission Main | 8807 | P-1778 | WW | River Farms Dr. | 12 | PVC | 188 | 30 | 0.43 out of 5 | $442 | 83,221 |
| Transmission Main | 8808 | P-881 | WW | River Farms Dr. | 12 | PVC | 194 | 30 | 0.43 out of 5 | $442 | 85,886 |
| Transmission Main | 8810 | P-1319 | WW | River Farms Dr. | 12 | PVC | 295 | 30 | 0.43 out of 5 | $442 | 130,321 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 8817 | P-886 | WW | River Farms Dr. | 12 | PVC | 345 | 30 | 0.43 out of 5 | $442 | 152,499 |
| Transmission Main | 8818 | P-1709 | WW | River Farms Dr. | 12 | PVC | 403 | 30 | 0.43 out of 5 | $442 | 177,972 |
| Transmission Main | 10840 | P-1772 | WW | River Farms Dr. | 12 | PVC | 7 | 30 | 0.43 out of 5 | $442 | 2,950 |
| Transmission Main | 10841 | P-1772 | WW | River Farms Dr. | 12 | PVC | 145 | 30 | 0.43 out of 5 | $442 | 63,909 |
| Transmission Main | 11153 | P-1773 | WW | River Farms Dr. | 12 | PVC | 59 | 30 | 0.43 out of 5 | $442 | 26,083 |
| Transmission Main | 11489 | P-1326 | WW | River Farms Dr. | 12 | PVC | 12 | 30 | 0.43 out of 5 | $442 | 5,226 |
| Transmission Main | 1997 | P-1264 | WW | River Farms Dr. Easement | 12 | PVC | 894 | 30 | 0.43 out of 5 | $442 | 395,224 |
| Transmission Main | 10694 | | WW | River Rd. | 42 | Asbestos Cement | 273 | UNK | 0.85 out of 5 | $442 | 120,622 |
| Distribution Main | 10312 | P-231 | WW | River St | 8 | Ductile Iron | 65 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10319 | | WW | River St | 16 | Ductile Iron | 34 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10418 | P-224 | WW | River St | 10 | Ductile Iron | 19 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10724 | | WW | River St | 16 | Ductile Iron | 297 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10725 | | WW | River St | 16 | Ductile Iron | 235 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10726 | P-231 | WW | River St | 8 | Ductile Iron | 286 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10727 | P-231 | WW | River St | 8 | Ductile Iron | 337 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11712 | | WW | River St | 16 | Ductile Iron | 166 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12144 | | WW | River St | 16 | Ductile Iron | 10 | 1 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1731 | P-657 | WW | Riverdale Ave. | 2 | Cast Iron | 149 | 134 | 3.29 out of 5 | $442 | 65,712 |
| Distribution Main | 4318 | P-658 | WW | Riverdale Ave. | 4 | Cast Iron | 235 | 134 | 3.29 out of 5 | $442 | 103,879 |
| Distribution Main | 4319 | P-658 | WW | Riverdale Ave. | 4 | Cast Iron | 386 | 134 | 3.29 out of 5 | $442 | 170,827 |
| Distribution Main | 4002 | P-1970 | WW | Riverside Terrace | 1 | Copper | 198 | 69 | 2.43 out of 5 | $442 | 87,633 |
| Distribution Main | 181 | P-665 | WW | Robert St | 6 | Ductile Iron | 12 | 15 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9835 | P-1971 | WW | Robert St | 8 | Ductile Iron | 13 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9836 | P-1971 | WW | Robert St | 8 | Ductile Iron | 21 | 7 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9840 | P-678 | WW | Robert St | 6 | Ductile Iron | 4 | 7 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9841 | P-1972 | WW | Robert St | 6 | Ductile Iron | 11 | 7 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9999 | | WW | Robert St | 6 | Ductile Iron | 28 | 15 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10006 | P-666 | WW | Robert St | 6 | Ductile Iron | 9 | 15 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 135 | P-678 | WW | Robert St. | 6 | Cast Iron | 444 | 90 | 2.43 out of 5 | $442 | 196,409 |
| Distribution Main | 136 | P-678 | WW | Robert St. | 6 | Cast Iron | 34 | 90 | 2.43 out of 5 | $442 | 14,850 |
| Distribution Main | 179 | P-666 | WW | Robert St. | 4 | Cast Iron | 229 | 90 | 3.14 out of 5 | $442 | 101,371 |
| Distribution Main | 344 | P-673 | WW | Robert St. | 6 | Cast Iron | 402 | 90 | 2.43 out of 5 | $442 | 177,716 |
| Distribution Main | 345 | P-665 | WW | Robert St. | 4 | Cast Iron | 40 | 90 | 3.14 out of 5 | $442 | 17,495 |
| Distribution Main | 688 | P-665 | WW | Robert St. | 4 | Cast Iron | 232 | 90 | 3.14 out of 5 | $442 | 102,430 |
| Distribution Main | 4281 | P-678 | WW | Robert St. | 6 | Cast Iron | 59 | 90 | 2.43 out of 5 | $442 | 26,186 |
| Distribution Main | 1822 | P-143 | WW | Robin Ln. | 8 | Asbestos Cement | 111 | 50 | 1.14 out of 5 | $442 | 49,142 |
| Distribution Main | 1823 | P-143 | WW | Robin Ln. | 8 | Asbestos Cement | 51 | 50 | 1.14 out of 5 | $442 | 22,423 |
| Distribution Main | 2209 | P-144 | WW | Robin Ln. | 8 | Asbestos Cement | 331 | 50 | 1.14 out of 5 | $442 | 146,224 |
| Distribution Main | 2214 | P-146 | WW | Robin Ln. | 8 | Asbestos Cement | 93 | 50 | 1.14 out of 5 | $442 | 40,953 |
| Distribution Main | 2215 | P-146 | WW | Robin Ln. | 8 | Asbestos Cement | 340 | 50 | 1.14 out of 5 | $442 | 150,411 |
| Distribution Main | 2217 | P-497 | WW | Robin Ln. | 8 | Asbestos Cement | 56 | 51 | 1.14 out of 5 | $442 | 24,722 |
| Distribution Main | 3871 | | WW | Robin Ln. | 8 | Asbestos Cement | 10 | 51 | 1.14 out of 5 | $442 | 4,415 |
| Distribution Main | 4138 | P-148 | WW | Robin Ln. | 8 | Asbestos Cement | 547 | 50 | 1.14 out of 5 | $442 | 241,655 |
| Distribution Main | 627 | P-1700 | WW | Robinson Way | 8 | Ductile Iron | 155 | 14 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 932 | P-595 | WW | Robinson Way | 8 | Ductile Iron | 513 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4706 | P-588 | WW | Robinson Way | 8 | Ductile Iron | 257 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4707 | P-590 | WW | Robinson Way | 8 | Ductile Iron | 153 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4709 | P-587 | WW | Robinson Way | 8 | Ductile Iron | 223 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8142 | P-595 | WW | Robinson Way | 8 | Ductile Iron | 165 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8145 | P-590 | WW | Robinson Way | 8 | Ductile Iron | 19 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8146 | P-590 | WW | Robinson Way | 8 | Ductile Iron | 37 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8147 | P-587 | WW | Robinson Way | 8 | Ductile Iron | 38 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8148 | P-587 | WW | Robinson Way | 8 | Ductile Iron | 3 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8167 | P-1700 | WW | Robinson Way | 8 | Ductile Iron | 130 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9365 | P-595 | WW | Robinson Way | 8 | Ductile Iron | 39 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9366 | P-595 | WW | Robinson Way | 8 | Ductile Iron | 33 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10385 | P-1700 | WW | Robinson Way | 8 | Ductile Iron | 12 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5190 | P-312 | WW | Rolling Green Ln. | 8 | Asbestos Cement | 660 | 47 | 1.14 out of 5 | $442 | 291,764 |
| Distribution Main | 5264 | P-312 | WW | Rolling Green Ln. | 8 | Asbestos Cement | 9 | 47 | 1.14 out of 5 | $442 | 3,913 |
| Distribution Main | 348 | P-674 | WW | Roosevelt St. | 1 | PVC | 170 | 19 | 1.71 out of 5 | N/A | $0 |
| Distribution Main | 2541 | P-31 | WW | Rotary Dr. | 8 | Asbestos Cement | 89 | 57 | 1.14 out of 5 | $442 | 39,508 |
| Distribution Main | 2542 | P-1943 | WW | Rotary Dr. | 8 | Asbestos Cement | 36 | 57 | 1.14 out of 5 | $442 | 15,979 |
| Distribution Main | 2543 | P-1943 | WW | Rotary Dr. | 8 | Asbestos Cement | 384 | 57 | 1.14 out of 5 | $442 | 169,646 |
| Distribution Main | 2544 | P-1944 | WW | Rotary Dr. | 6 | Asbestos Cement | 71 | 57 | 1.85 out of 5 | $442 | 31,298 |
| Distribution Main | 2547 | P-29 | WW | Rotary Dr. | 8 | Asbestos Cement | 244 | 57 | 1.14 out of 5 | $442 | 107,855 |
| Distribution Main | 4560 | P-32 | WW | Rotary Dr. | 8 | Asbestos Cement | 324 | 57 | 1.14 out of 5 | $442 | 143,383 |
| Distribution Main | 4561 | P-31 | WW | Rotary Dr. | 8 | Asbestos Cement | 137 | 57 | 1.14 out of 5 | $442 | 60,766 |
| Distribution Main | 4347 | P-1097 | WW | Rowland St. | 6 | Asbestos Cement | 196 | 57 | 1.85 out of 5 | $442 | 86,444 |
| Distribution Main | 2345 | P-95 | WW | Royal Dr. | 8 | Asbestos Cement | 594 | 42 | 1.14 out of 5 | $442 | 262,740 |
| Distribution Main | 2346 | P-95 | WW | Royal Dr. | 8 | Asbestos Cement | 258 | 42 | 1.14 out of 5 | $442 | 114,153 |
| Distribution Main | 11168 | P-95 | WW | Royal Dr. | 8 | Asbestos Cement | 19 | 42 | 1.14 out of 5 | $442 | 8,490 |
| Distribution Main | 1770 | P-842 | WW | Saddlebrook Dr. | 8 | PVC | 365 | 31 | 0.43 out of 5 | $442 | 161,445 |
| Distribution Main | 3509 | P-840 | WW | Saddlebrook Dr. | 8 | PVC | 315 | 31 | 0.43 out of 5 | $442 | 139,222 |
| Distribution Main | 3510 | P-840 | WW | Saddlebrook Dr. | 8 | PVC | 83 | 31 | 0.43 out of 5 | $442 | 36,611 |
| Distribution Main | 11761 | P-840 | WW | Saddlebrook Dr. | 8 | PVC | 251 | 31 | 0.43 out of 5 | $442 | 111,009 |
| Transmission Main | 2086 | P-1779 | WW | Sandpiper Drive | 12 | Ductile Iron | 578 | 15 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2087 | P-1779 | WW | Sandpiper Drive | 12 | Ductile Iron | 14 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8429 | P-1796 | WW | Schofield St | 8 | Ductile Iron | 36 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 484 | P-964 | WW | Schofield St. | 6 | Asbestos Cement | 177 | 58 | 1.85 out of 5 | $442 | 78,108 |
| Distribution Main | 485 | P-964 | WW | Schofield St. | 6 | Asbestos Cement | 27 | 58 | 1.85 out of 5 | $442 | 11,909 |
| Distribution Main | 10120 | | WW | School St | 1 | Copper | 11 | 89 | 2.57 out of 5 | $442 | 4,722 |
| Distribution Main | 3400 | | WW | School St. | 2 | Galvanized Iron | 79 | 92 | 3.43 out of 5 | $442 | 35,077 |
| Distribution Main | 4078 | P-1089 | WW | School St. | 6 | Cast Iron | 73 | 134 | 2.57 out of 5 | $442 | 32,361 |
| Distribution Main | 4079 | P-1091 | WW | School St. | 6 | Cast Iron | 25 | 134 | 2.57 out of 5 | $442 | 10,853 |
| Distribution Main | 4080 | P-1091 | WW | School St. | 6 | Cast Iron | 281 | 134 | 2.57 out of 5 | $442 | 124,081 |
| Distribution Main | 4086 | P-1088 | WW | School St. | 6 | Cast Iron | 177 | 134 | 2.57 out of 5 | $442 | 78,068 |
| Distribution Main | 4716 | | WW | School St. | 4 | Cast Iron | 282 | 89 | 3.14 out of 5 | $442 | 124,480 |
| Distribution Main | 5089 | P-1091 | WW | School St. | 4 | Cast Iron | 80 | 89 | 3.14 out of 5 | $442 | 35,578 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 11240 | P-1091 | WW | School St. | 6 | Cast Iron | 54 | 134 | 2.57 out of 5 | $442 | 23,812 |
| Distribution Main | 10795 | P-1989 | WW | Second St | 8 | Ductile Iron | 326 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2545 | P-38 | WW | Service Rd. | 6 | Asbestos Cement | 14 | 50 | 1.85 out of 5 | $442 | 6,394 |
| Distribution Main | 4454 | P-40 | WW | Service Rd. | 8 | Ductile Iron | 225 | 28 | 0.14 out of 5 | $442 | 99,332 |
| Distribution Main | 4557 | P-38 | WW | Service Rd. | 6 | Asbestos Cement | 476 | 50 | 1.85 out of 5 | $442 | 210,172 |
| Distribution Main | 4558 | P-38 | WW | Service Rd. | 6 | Asbestos Cement | 8 | 50 | 1.85 out of 5 | $442 | 3,469 |
| Distribution Main | 4732 | P-44 | WW | Service Rd. | 8 | Ductile Iron | 156 | 28 | 0.14 out of 5 | $442 | 69,099 |
| Distribution Main | 4747 | P-42 | WW | Service Rd. | 8 | Ductile Iron | 3 | 28 | 0.14 out of 5 | $442 | 1,494 |
| Distribution Main | 4748 | P-42 | WW | Service Rd. | 8 | Ductile Iron | 321 | 28 | 0.14 out of 5 | $442 | 141,863 |
| Distribution Main | 4749 | P-1940 | WW | Service Rd. | 8 | Ductile Iron | 92 | 28 | 0.14 out of 5 | $442 | 40,599 |
| Distribution Main | 4750 | P-1940 | WW | Service Rd. | 8 | Ductile Iron | 38 | 28 | 0.14 out of 5 | $442 | 17,007 |
| Distribution Main | 4432 | P-362 | WW | Seth Dr. | 6 | PVC | 128 | 32 | 1.14 out of 5 | $442 | 56,750 |
| Distribution Main | 4434 | P-361 | WW | Seth Dr. | 6 | PVC | 121 | 32 | 1.14 out of 5 | $442 | 53,543 |
| Distribution Main | 4435 | P-361 | WW | Seth Dr. | 6 | PVC | 139 | 32 | 1.14 out of 5 | $442 | 61,507 |
| Transmission Main | 283 | P-92 | WW | Setian Ln. | 20 | Asbestos Cement | 120 | 50 | 1.14 out of 5 | $442 | 53,025 |
| Transmission Main | 284 | P-92 | WW | Setian Ln. | 12 | Asbestos Cement | 398 | 50 | 1.14 out of 5 | $442 | 176,072 |
| Transmission Main | 285 | P-92 | WW | Setian Ln. | 12 | Asbestos Cement | 9 | 50 | 1.14 out of 5 | $442 | 3,950 |
| Distribution Main | 1348 | P-121 | WW | Setian Ln. | 8 | Asbestos Cement | 11 | 43 | 1.14 out of 5 | $442 | 4,940 |
| Transmission Main | 1349 | P-92 | WW | Setian Ln. | 12 | Asbestos Cement | 10 | 50 | 1.14 out of 5 | $442 | 4,494 |
| Transmission Main | 2324 | P-1548 | WW | Setian Ln. | 12 | Ductile Iron | 172 | 19 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2347 | P-121 | WW | Setian Ln. | 20 | Asbestos Cement | 8 | 43 | 1.14 out of 5 | $442 | 3,561 |
| Transmission Main | 2348 | P-92 | WW | Setian Ln. | 20 | Asbestos Cement | 19 | 50 | 1.14 out of 5 | $442 | 8,523 |
| Transmission Main | 2349 | P-92 | WW | Setian Ln. | 20 | Asbestos Cement | 18 | 50 | 1.14 out of 5 | $442 | 7,903 |
| Distribution Main | 2350 | P-121 | WW | Setian Ln. | 8 | Asbestos Cement | 86 | 43 | 1.14 out of 5 | $442 | 38,068 |
| Transmission Main | 5175 | P-1468 | WW | Setian Ln. | 12 | Asbestos Cement | 371 | 50 | 1.14 out of 5 | $442 | 163,911 |
| Transmission Main | 5176 | P-1468 | WW | Setian Ln. | 12 | Asbestos Cement | 581 | 50 | 1.14 out of 5 | $442 | 256,800 |
| Transmission Main | 5186 | P-1467 | WW | Setian Ln. | 12 | Asbestos Cement | 513 | 50 | 1.14 out of 5 | $442 | 226,638 |
| Distribution Main | 10252 | P-121 | WW | Setian Ln. | 8 | Asbestos Cement | 6 | 43 | 1.14 out of 5 | $442 | 2,467 |
| Transmission Main | 11020 | P-92 | WW | Setian Ln. | 20 | Asbestos Cement | 7 | 50 | 1.14 out of 5 | $442 | 3,121 |
| Distribution Main | 389 | P-496 | WW | Shady Hill Dr. | 8 | Asbestos Cement | 276 | 54 | 1.14 out of 5 | $442 | 122,201 |
| Distribution Main | 3541 | P-493 | WW | Shady Hill Dr. | 8 | Asbestos Cement | 17 | 54 | 1.14 out of 5 | $442 | 7,303 |
| Distribution Main | 3542 | P-493 | WW | Shady Hill Dr. | 8 | Asbestos Cement | 268 | 54 | 1.14 out of 5 | $442 | 118,458 |
| Distribution Main | 4648 | P-493 | WW | Shady Hill Dr. | 8 | Asbestos Cement | 235 | 54 | 1.14 out of 5 | $442 | 103,819 |
| Distribution Main | 4649 | P-493 | WW | Shady Hill Dr. | 8 | Asbestos Cement | 593 | 54 | 1.14 out of 5 | $442 | 262,090 |
| Distribution Main | 12046 | P-493 | WW | Shady Hill Dr. | 8 | Asbestos Cement | 470 | 54 | 1.14 out of 5 | $442 | 207,528 |
| Distribution Main | 4433 | P-363 | WW | Shane Dr. | 6 | PVC | 260 | 32 | 1.14 out of 5 | $442 | 114,735 |
| Distribution Main | 2075 | P-866 | WW | Shannon Ln. | 8 | Ductile Iron | 20 | 26 | 0.14 out of 5 | $442 | 8,633 |
| Distribution Main | 2096 | P-866 | WW | Shannon Ln. | 8 | Ductile Iron | 422 | 26 | 0.14 out of 5 | $442 | 186,495 |
| Distribution Main | 9771 | P-614 | WW | Sheffield Ave | 8 | Ductile Iron | 199 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9772 | P-614 | WW | Sheffield Ave | 8 | Ductile Iron | 33 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9781 | P-630 | WW | Sheffield Ave | 8 | Ductile Iron | 93 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9790 | P-630 | WW | Sheffield Ave | 8 | Ductile Iron | 581 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11604 | P-615 | WW | Sheffield Ave | 8 | Ductile Iron | 19 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11605 | P-1385 | WW | Sheffield Ave | 8 | Ductile Iron | 29 | 8 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10313 | P-243 | WW | Sheldon St | 8 | Ductile Iron | 580 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9761 | P-613 | WW | Sherwood Ave | 8 | Ductile Iron | 295 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9773 | P-613 | WW | Sherwood Ave | 8 | Ductile Iron | 27 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9774 | P-613 | WW | Sherwood Ave | 8 | Ductile Iron | 425 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 572 | P-8040 | WW | Shippee Ave. | 8 | Cast Iron | 291 | 130 | 1.86 out of 5 | $442 | 128,409 |
| Distribution Main | 1972 | P-741 | WW | Shippee Ave. | 6 | Cast Iron | 297 | 80 | 2.28 out of 5 | $442 | 131,288 |
| Distribution Main | 2494 | P-737 | WW | Shippee Ave. | 8 | Cast Iron | 7 | 80 | 1.57 out of 5 | $442 | 2,882 |
| Distribution Main | 2865 | P-737 | WW | Shippee Ave. | 8 | Cast Iron | 6 | 80 | 1.57 out of 5 | $442 | 2,525 |
| Distribution Main | 2866 | P-736 | WW | Shippee Ave. | 6 | Cast Iron | 25 | 80 | 2.28 out of 5 | $442 | 10,843 |
| Transmission Main | 2867 | P-717 | WW | Shippee Ave. | 12 | Cast Iron | 199 | 89 | 1.72 out of 5 | $442 | 88,069 |
| Transmission Main | 2868 | P-717 | WW | Shippee Ave. | 12 | Cast Iron | 83 | 89 | 1.72 out of 5 | $442 | 36,758 |
| Distribution Main | 2869 | P-709 | WW | Shippee Ave. | 8 | Cast Iron | 4 | 130 | 1.86 out of 5 | $442 | 1,655 |
| Distribution Main | 2870 | P-709 | WW | Shippee Ave. | 8 | Cast Iron | 184 | 130 | 1.86 out of 5 | $442 | 81,323 |
| Distribution Main | 2871 | P-711 | WW | Shippee Ave. | 8 | Cast Iron | 187 | 130 | 1.86 out of 5 | $442 | 82,679 |
| Distribution Main | 2872 | P-713 | WW | Shippee Ave. | 8 | Cast Iron | 257 | 130 | 1.86 out of 5 | $442 | 113,422 |
| Distribution Main | 3201 | P-737 | WW | Shippee Ave. | 6 | Cast Iron | 174 | 80 | 2.28 out of 5 | $442 | 77,008 |
| Distribution Main | 3260 | P-712 | WW | Shippee Ave. | 8 | Cast Iron | 229 | 130 | 2.57 out of 5 | $442 | 101,190 |
| Distribution Main | 3270 | P-737 | WW | Shippee Ave. | 8 | Cast Iron | 7 | 80 | 1.57 out of 5 | $442 | 2,930 |
| Distribution Main | 8824 | P-739 | WW | Shippee Ave. | 6 | Cast Iron | 132 | 80 | 2.28 out of 5 | $442 | 58,391 |
| Distribution Main | 8825 | P-739 | WW | Shippee Ave. | 6 | Cast Iron | 34 | 80 | 2.28 out of 5 | $442 | 15,233 |
| Distribution Main | 8826 | P-739 | WW | Shippee Ave. | 8 | Cast Iron | 5 | 80 | 1.57 out of 5 | $442 | 2,245 |
| Distribution Main | 8827 | P-736 | WW | Shippee Ave. | 6 | Cast Iron | 60 | 80 | 2.28 out of 5 | $442 | 26,587 |
| Distribution Main | 8828 | P-709 | WW | Shippee Ave. | 8 | Cast Iron | 12 | 130 | 1.86 out of 5 | $442 | 5,431 |
| Transmission Main | 8829 | P-717 | WW | Shippee Ave. | 12 | Cast Iron | 20 | 89 | 1.72 out of 5 | $442 | 8,950 |
| Distribution Main | 8936 | P-192 | WW | Shortway Dr | 8 | Ductile Iron | 234 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8943 | P-197 | WW | Shortway Dr | 6 | Ductile Iron | 6 | 9 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8962 | P-200 | WW | Shortway Dr | 8 | Ductile Iron | 26 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8965 | P-200 | WW | Shortway Dr | 6 | Ductile Iron | 8 | 9 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11526 | P-1739 | WW | Shortway Dr | 8 | Ductile Iron | 28 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11527 | P-197 | WW | Shortway Dr | 8 | Ductile Iron | 17 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3090 | P-190 | WW | Shortway Dr. | 6 | Asbestos Cement | 185 | 69 | 2 out of 5 | $442 | 81,649 |
| Distribution Main | 5293 | P-200 | WW | Shortway Dr. | 6 | Asbestos Cement | 214 | 62 | 2 out of 5 | $442 | 94,574 |
| Distribution Main | 5479 | P-197 | WW | Shortway Dr. | 6 | Asbestos Cement | 222 | 69 | 2 out of 5 | $442 | 97,911 |
| Distribution Main | 9782 | P-626 | WW | Sidney St | 8 | Ductile Iron | 63 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9783 | P-625 | WW | Sidney St | 8 | Ductile Iron | 241 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9799 | P-1963 | WW | Sidney St | 8 | Ductile Iron | 295 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9800 | P-1963 | WW | Sidney St | 8 | Ductile Iron | 15 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10411 | P-627 | WW | Sidney St | 8 | Ductile Iron | 61 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10881 | P-623 | WW | Sidney St | 8 | Ductile Iron | 148 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10882 | P-623 | WW | Sidney St | 8 | Ductile Iron | 192 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11606 | P-626 | WW | Sidney St | 8 | Ductile Iron | 158 | 8 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8178 | P-1710 | WW | Silvercup Cir | 12 | Ductile Iron | 530 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10056 | P-1522 | WW | Silvercup Cir | 12 | Ductile Iron | 210 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10057 | P-1522 | WW | Silvercup Cir | 12 | Ductile Iron | 294 | 12 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 10704 | P-1521 | WW | Silvercup Cir | 12 | Ductile Iron | 14 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10836 | P-1521 | WW | Silvercup Cir | 12 | Ductile Iron | 11 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10837 | P-1521 | WW | Silvercup Cir | 12 | Ductile Iron | 363 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10838 | P-1523 | WW | Silvercup Cir | 12 | Ductile Iron | 222 | 12 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10839 | P-1523 | WW | Silvercup Cir | 12 | Ductile Iron | 160 | 12 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4615 | P-1469 | WW | Silverwood Lane | 8 | Asbestos Cement | 51 | 42 | 1.14 out of 5 | $442 | 22,518 |
| Distribution Main | 4616 | P-1469 | WW | Silverwood Lane | 8 | Asbestos Cement | 791 | 42 | 1.14 out of 5 | $442 | 349,726 |
| Distribution Main | 4617 | P-1469 | WW | Silverwood Lane | 8 | Asbestos Cement | 333 | 42 | 1.14 out of 5 | $442 | 147,348 |
| Distribution Main | 4618 | P-126 | WW | Silverwood Lane | 8 | Asbestos Cement | 192 | 42 | 1.14 out of 5 | $442 | 84,887 |
| Distribution Main | 4619 | P-126 | WW | Silverwood Lane | 8 | Asbestos Cement | 795 | 42 | 1.14 out of 5 | $442 | 351,209 |
| Distribution Main | 5177 | P-1469 | WW | Silverwood Lane | 8 | Asbestos Cement | 10 | 42 | 1.14 out of 5 | $442 | 4,431 |
| Distribution Main | 12051 | P-126 | WW | Silverwood Lane | 8 | Asbestos Cement | 328 | 42 | 1.14 out of 5 | $442 | 145,177 |
| Distribution Main | 9462 | P-1857 | WW | Simon Street | 1.5 | Unknown | 135 | UNK | 1.42 out of 5 | $442 | 59,472 |
| Distribution Main | 105 | P-1218 | WW | Sisson St | 1 | Galvanized Iron | 154 | 78 | 3.28 out of 5 | $442 | 68,244 |
| Distribution Main | 1517 | P-919 | WW | Smith St. | 6 | Cast Iron | 130 | 134 | 2.57 out of 5 | $442 | 57,466 |
| Distribution Main | 1799 | P-916 | WW | Smith St. | 6 | Cast Iron | 93 | 134 | 2.57 out of 5 | $442 | 41,118 |
| Distribution Main | 1800 | P-916 | WW | Smith St. | 6 | Cast Iron | 428 | 134 | 2.57 out of 5 | $442 | 189,123 |
| Distribution Main | 9048 | P-1957 | WW | Solty'S Ct | 6 | Ductile Iron | 87 | 15 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11541 | | WW | Solty'S Ct | 6 | Ductile Iron | 4 | 15 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 3351 | P-793 | WW | South St. | 6 | Asbestos Cement | 180 | 65 | 2 out of 5 | $442 | 79,358 |
| Distribution Main | 3352 | P-793 | WW | South St. | 6 | Asbestos Cement | 100 | 65 | 2 out of 5 | $442 | 44,328 |
| Distribution Main | 4276 | P-5104 | WW | Southview Ter. | 8 | Asbestos Cement | 208 | 39 | 1 out of 5 | $442 | 92,110 |
| Distribution Main | 4277 | P-5104 | WW | Southview Ter. | 8 | Asbestos Cement | 101 | 39 | 1 out of 5 | $442 | 44,644 |
| Distribution Main | 8159 | P-5104 | WW | Southview Ter. | 8 | Ductile Iron | 66 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8652 | P-877 | WW | Sparrow Cir | 8 | PVC | 147 | 29 | 0.43 out of 5 | $442 | 65,145 |
| Distribution Main | 8653 | P-877 | WW | Sparrow Cir | 8 | PVC | 2 | 29 | 0.43 out of 5 | $442 | 926 |
| Distribution Main | 2936 | P-811 | WW | Spencer St. | 6 | Asbestos Cement | 515 | 69 | 2 out of 5 | $442 | 227,838 |
| Distribution Main | 3716 | P-812 | WW | Spencer St. | 6 | Asbestos Cement | 365 | 69 | 2 out of 5 | $442 | 161,463 |
| Distribution Main | 3720 | P-812 | WW | Spencer St. | 6 | Asbestos Cement | 129 | 69 | 2 out of 5 | $442 | 56,874 |
| Distribution Main | 8811 | P-811 | WW | Spencer St. | 6 | Asbestos Cement | 19 | 69 | 2 out of 5 | $442 | 8,304 |
| Distribution Main | 8812 | P-811 | WW | Spencer St. | 6 | Asbestos Cement | 7 | 69 | 2 out of 5 | $442 | 2,982 |
| Distribution Main | 3880 | P-456 | WW | Spring Meadow Circle | 8 | Ductile Iron | 201 | 21 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 914 | | WW | Spring St. | 2 | Galvanized Iron | 314 | 91 | 3.43 out of 5 | $442 | 138,633 |
| Distribution Main | 4081 | P-1094 | WW | Spring St. | 2 | Galvanized Iron | 169 | 134 | 3.57 out of 5 | $442 | 74,728 |
| Distribution Main | 4084 | P-1092 | WW | Spring St. | 6 | Cast Iron | 15 | 134 | 2.57 out of 5 | $442 | 6,608 |
| Distribution Main | 4085 | P-1092 | WW | Spring St. | 6 | Cast Iron | 254 | 134 | 2.57 out of 5 | $442 | 112,072 |
| Distribution Main | 4713 | P-1092 | WW | Spring St. | 6 | Cast Iron | 18 | 134 | 2.57 out of 5 | $442 | 7,877 |
| Distribution Main | 11772 | P-1092 | WW | Spring St. | 6 | Cast Iron | 4 | 134 | 2.57 out of 5 | $442 | 1,706 |
| Distribution Main | 3571 | P-104 | WW | Spruce Ct | 6 | Asbestos Cement | 13 | 41 | 1.85 out of 5 | $442 | 5,881 |
| Distribution Main | 4131 | P-104 | WW | Spruce Ct | 6 | Asbestos Cement | 160 | 41 | 1.85 out of 5 | $442 | 70,574 |
| Distribution Main | 10400 | P-1980 | WW | St James St | 8 | Ductile Iron | 206 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9207 | P-1034 | WW | St Mary | 8 | Ductile Iron | 136 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9208 | P-1034 | WW | St Mary | 8 | Ductile Iron | 230 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10780 | P-10065 | WW | St. George St | 8 | Ductile Iron | 140 | 0 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10781 | P-10063 | WW | St. George St | 8 | Ductile Iron | 37 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10782 | P-10063 | WW | St. George St | 8 | Ductile Iron | 9 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10783 | P-357 | WW | St. George St | 8 | Ductile Iron | 239 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10921 | P-10065 | WW | St. George St | 8 | Ductile Iron | 37 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10922 | P-10065 | WW | St. George St | 8 | Ductile Iron | 84 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11730 | P-358 | WW | St. George St | 8 | Ductile Iron | 234 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 177 | P-670 | WW | St. John St. | 6 | Cast Iron | 182 | 129 | 2.57 out of 5 | $442 | 80,598 |
| Distribution Main | 178 | P-670 | WW | St. John St. | 6 | Cast Iron | 22 | 129 | 2.57 out of 5 | $442 | 9,746 |
| Distribution Main | 180 | P-670 | WW | St. John St. | 6 | Ductile Iron | 11 | 15 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 3766 | P-670 | WW | St. John St. | 6 | Cast Iron | 284 | 129 | 2.57 out of 5 | $442 | 125,458 |
| Distribution Main | 3767 | P-670 | WW | St. John St. | 6 | Cast Iron | 112 | 129 | 2.57 out of 5 | $442 | 49,439 |
| Distribution Main | 12188 | | WW | St. Mary St. | 6 | Cast Iron | 87 | 129 | 2.57 out of 5 | $442 | 38,360 |
| Distribution Main | 393 | P-1437 | WW | St. Onge Dr. | 8 | Ductile Iron | 44 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2314 | P-1437 | WW | St. Onge Dr. | 8 | Ductile Iron | 5 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 2340 | P-1433 | WW | St. Onge Dr. | 8 | Asbestos Cement | 23 | 39 | 1 out of 5 | $442 | 9,985 |
| Distribution Main | 4762 | P-1434 | WW | St. Onge Dr. | 8 | Asbestos Cement | 402 | 39 | 1 out of 5 | $442 | 177,670 |
| Distribution Main | 4763 | P-1434 | WW | St. Onge Dr. | 8 | Asbestos Cement | 112 | 39 | 1 out of 5 | $442 | 49,703 |
| Distribution Main | 4961 | P-1179 | WW | St. Onge Dr. | 8 | Asbestos Cement | 342 | 39 | 1 out of 5 | $442 | 150,982 |
| Distribution Main | 3110 | P-546 | WW | Standard Ave. | 2 | Galvanized Iron | 11 | 109 | 3.57 out of 5 | $442 | 4,936 |
| Distribution Main | 3970 | P-546 | WW | Standard Ave. | 2 | Galvanized Iron | 324 | 109 | 3.57 out of 5 | $442 | 143,177 |
| Distribution Main | 4311 | P-547 | WW | Standard Ave. | 6 | Cast Iron | 21 | 109 | 2.57 out of 5 | $442 | 9,148 |
| Distribution Main | 4312 | P-547 | WW | Standard Ave. | 6 | Cast Iron | 668 | 109 | 2.57 out of 5 | $442 | 295,071 |
| Distribution Main | 8669 | P-1777 | WW | Starling Way | 8 | Ductile Iron | 4 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8670 | P-1777 | WW | Starling Way | 8 | Ductile Iron | 399 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9067 | P-10015 | WW | Starlite Ct | 8 | Ductile Iron | 6 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9068 | P-10015 | WW | Starlite Ct | 8 | Ductile Iron | 186 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10023 | P-1757 | WW | State St | 8 | Ductile Iron | 325 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4390 | P-204 | WW | Steven Dr. | 8 | Asbestos Cement | 301 | 42 | 1.14 out of 5 | $442 | 133,024 |
| Distribution Main | 4391 | P-204 | WW | Steven Dr. | 8 | Asbestos Cement | 632 | 42 | 1.14 out of 5 | $442 | 279,308 |
| Distribution Main | 3439 | P-170 | WW | Stoney Creek Dr. | 8 | Asbestos Cement | 422 | 42 | 1.14 out of 5 | $442 | 186,308 |
| Transmission Main | 8396 | P-1231 | WW | Summit Ave | 12 | Ductile Iron | 312 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8397 | P-1231 | WW | Summit Ave | 12 | Ductile Iron | 28 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8404 | P-1838 | WW | Summit Ave | 8 | Ductile Iron | 9 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8440 | P-1235 | WW | Summit Ave | 12 | Ductile Iron | 164 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8464 | P-1235 | WW | Summit Ave | 12 | Ductile Iron | 69 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8469 | P-978 | WW | Summit Ave | 12 | Ductile Iron | 255 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8470 | P-978 | WW | Summit Ave | 12 | Ductile Iron | 26 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8471 | P-1838 | WW | Summit Ave | 6 | Ductile Iron | 10 | 10 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 9673 | P-1235 | WW | Summit Ave | 12 | Ductile Iron | 21 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8462 | P-1233 | WW | Summit Ave / N Pleasant | 6 | Ductile Iron | 26 | 10 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 9674 | P-1233 | WW | Summit Ave / N Pleasant | 12 | Ductile Iron | 5 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8394 | P-1907 | WW | Summit Ave / Pleasant St | 12 | Ductile Iron | 142 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1524 | P-976 | WW | Summit Ave. | 6 | Cast Iron | 110 | 134 | 2.57 out of 5 | $442 | 48,785 |
| Distribution Main | 1525 | P-976 | WW | Summit Ave. | 6 | Cast Iron | 274 | 134 | 2.57 out of 5 | $442 | 121,083 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 2480 | P-1223 | WW | Summit Ave. | 6 | Cast Iron | 243 | 134 | 2.57 out of 5 | $442 | 107,200 |
| Distribution Main | 3477 | P-977 | WW | Summit Ave. | 6 | Cast Iron | 258 | 134 | 2.57 out of 5 | $442 | 114,135 |
| Distribution Main | 3528 | P-1223 | WW | Summit Ave. | 6 | Cast Iron | 62 | 134 | 2.57 out of 5 | $442 | 27,363 |
| Distribution Main | 3529 | P-1223 | WW | Summit Ave. | 6 | Cast Iron | 199 | 134 | 2.57 out of 5 | $442 | 87,968 |
| Distribution Main | 3704 | P-975 | WW | Summit Ave. | 6 | Cast Iron | 584 | 134 | 2.57 out of 5 | $442 | 258,118 |
| Distribution Main | 9671 | P-977 | WW | Summit Ave. | 6 | Cast Iron | 18 | 134 | 2.57 out of 5 | $442 | 7,928 |
| Distribution Main | 8949 | P-210 | WW | Suncrest Dr | 8 | Ductile Iron | 36 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8957 | | WW | Suncrest Dr | 6 | Ductile Iron | 3 | 9 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 8958 | P-210 | WW | Suncrest Dr. | 6 | Asbestos Cement | 244 | 69 | 2 out of 5 | $442 | 107,632 |
| Distribution Main | 378 | P-813 | WW | Sunrise Ave. | 6 | Asbestos Cement | 206 | 54 | 1.85 out of 5 | $442 | 91,112 |
| Distribution Main | 379 | P-813 | WW | Sunrise Ave. | 6 | Asbestos Cement | 125 | 54 | 1.85 out of 5 | $442 | 55,471 |
| Distribution Main | 384 | P-1513 | WW | Sunrise Ave. | 8 | Ductile Iron | 60 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 385 | P-1513 | WW | Sunrise Ave. | 8 | Ductile Iron | 202 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 1798 | P-7914 | WW | Sunrise Ave. | 6 | Asbestos Cement | 11 | 66 | 2 out of 5 | $442 | 4,798 |
| Distribution Main | 3471 | P-824 | WW | Sunrise Ave. | 4 | Cast Iron | 499 | 134 | 3.29 out of 5 | $442 | 220,717 |
| Distribution Main | 3479 | P-1516 | WW | Sunrise Ave. | 6 | Asbestos Cement | 201 | 54 | 1.85 out of 5 | $442 | 88,850 |
| Distribution Main | 3721 | P-813 | WW | Sunrise Ave. | 6 | Asbestos Cement | 454 | 54 | 1.85 out of 5 | $442 | 200,512 |
| Distribution Main | 3741 | | WW | Sunrise Ave. | 4 | Cast Iron | 26 | 134 | 3.29 out of 5 | $442 | 11,603 |
| Distribution Main | 11056 | P-1513 | WW | Sunrise Ave. | 8 | Ductile Iron | 30 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 331 | P-820 | WW | Sunset Ave. | 6 | Cast Iron | 189 | 134 | 2.57 out of 5 | $442 | 83,457 |
| Distribution Main | 332 | P-820 | WW | Sunset Ave. | 6 | Cast Iron | 226 | 134 | 2.57 out of 5 | $442 | 100,032 |
| Distribution Main | 959 | P-821 | WW | Sunset Ave. | 6 | Cast Iron | 332 | 134 | 2.57 out of 5 | $442 | 146,790 |
| Distribution Main | 960 | P-821 | WW | Sunset Ave. | 6 | Cast Iron | 218 | 134 | 2.57 out of 5 | $442 | 96,300 |
| Distribution Main | 8835 | P-821 | WW | Sunset Ave. | 6 | Cast Iron | 37 | 134 | 2.57 out of 5 | $442 | 16,570 |
| Distribution Main | 9433 | P-1607 | WW | Sunset Ave. | 6 | Cast Iron | 101 | 134 | 2.57 out of 5 | $442 | 44,451 |
| Distribution Main | 5174 | P-1409 | WW | Surrey La | 8 | Asbestos Cement | 208 | 44 | 1.14 out of 5 | $442 | 92,156 |
| Distribution Main | 5178 | P-1410 | WW | Surrey La | 8 | Asbestos Cement | 217 | 44 | 1.14 out of 5 | $442 | 95,724 |
| Distribution Main | 5179 | P-1410 | WW | Surrey La | 8 | Asbestos Cement | 44 | 44 | 1.14 out of 5 | $442 | 19,590 |
| Distribution Main | 5180 | | WW | Surrey La | 8 | Asbestos Cement | 65 | 44 | 1.14 out of 5 | $442 | 28,664 |
| Distribution Main | 5181 | | WW | Surrey La | 8 | Asbestos Cement | 13 | 44 | 1.14 out of 5 | $442 | 5,682 |
| Distribution Main | 10265 | P-1409 | WW | Surrey La | 8 | Asbestos Cement | 15 | 44 | 1.14 out of 5 | $442 | 6,714 |
| Distribution Main | 5182 | P-122 | WW | Surrey Ln. | 8 | Asbestos Cement | 911 | 44 | 1.14 out of 5 | $442 | 402,556 |
| Distribution Main | 5183 | P-122 | WW | Surrey Ln. | 8 | Asbestos Cement | 640 | 44 | 1.14 out of 5 | $442 | 282,683 |
| Distribution Main | 10264 | | WW | Surrey Ln. | 8 | Ductile Iron | 33 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 1827 | P-497 | WW | Sycamore Dr. | 8 | Asbestos Cement | 873 | 51 | 1.14 out of 5 | $442 | 385,884 |
| Distribution Main | 1828 | P-495 | WW | Sycamore Dr. | 8 | Asbestos Cement | 848 | 51 | 1.14 out of 5 | $442 | 374,844 |
| Distribution Main | 1829 | P-495 | WW | Sycamore Dr. | 8 | Asbestos Cement | 157 | 54 | 1.14 out of 5 | $442 | 69,568 |
| Transmission Main | 1082 | P-72 | WW | Szydlo Dr. | 12 | Ductile Iron | 591 | 19 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10610 | P-411 | WW | Tampa St | 8 | Ductile Iron | 269 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10611 | P-411 | WW | Tampa St | 8 | Ductile Iron | 343 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10612 | | WW | Tampa St | 8 | Ductile Iron | 330 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11686 | P-414 | WW | Tampa St | 8 | Ductile Iron | 208 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11687 | P-407 | WW | Tampa St | 8 | Ductile Iron | 193 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11688 | P-409 | WW | Tampa St | 8 | Ductile Iron | 210 | 2 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 11689 | P-411 | WW | Tampa St | 8 | Ductile Iron | 5 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11690 | | WW | Tampa St | 8 | Ductile Iron | 19 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 5138 | P-424 | WW | Tampa St. | 6 | Asbestos Cement | 170 | 58 | 1.85 out of 5 | $442 | 74,975 |
| Distribution Main | 5139 | P-424 | WW | Tampa St. | 6 | Asbestos Cement | 237 | 58 | 1.85 out of 5 | $442 | 104,944 |
| Distribution Main | 5140 | P-425 | WW | Tampa St. | 6 | Asbestos Cement | 295 | 58 | 1.85 out of 5 | $442 | 130,515 |
| Distribution Main | 151 | P-317 | WW | Tanglewood Dr. | 8 | Asbestos Cement | 700 | 41 | 1.14 out of 5 | $442 | 309,439 |
| Distribution Main | 1734 | P-307 | WW | Tanglewood Dr. | 8 | Asbestos Cement | 56 | 41 | 1.14 out of 5 | $442 | 24,744 |
| Distribution Main | 1735 | P-327 | WW | Tanglewood Dr. | 8 | Asbestos Cement | 310 | 41 | 1.14 out of 5 | $442 | 137,105 |
| Distribution Main | 1736 | P-327 | WW | Tanglewood Dr. | 8 | Asbestos Cement | 42 | 41 | 1.14 out of 5 | $442 | 18,488 |
| Distribution Main | 4015 | P-306 | WW | Tanglewood Dr. | 8 | Asbestos Cement | 26 | 41 | 1.14 out of 5 | $442 | 11,430 |
| Distribution Main | 5187 | P-306 | WW | Tanglewood Dr. | 8 | Asbestos Cement | 363 | 41 | 1.14 out of 5 | $442 | 160,392 |
| Distribution Main | 5192 | P-307 | WW | Tanglewood Dr. | 8 | Asbestos Cement | 354 | 41 | 1.14 out of 5 | $442 | 156,433 |
| Distribution Main | 5193 | P-307 | WW | Tanglewood Dr. | 8 | Asbestos Cement | 14 | 41 | 1.14 out of 5 | $442 | 6,083 |
| Distribution Main | 5196 | P-316 | WW | Tanglewood Dr. | 8 | Asbestos Cement | 55 | 41 | 1.14 out of 5 | $442 | 24,466 |
| Distribution Main | 5197 | P-316 | WW | Tanglewood Dr. | 8 | Asbestos Cement | 436 | 41 | 1.14 out of 5 | $442 | 192,887 |
| Distribution Main | 5200 | P-306 | WW | Tanglewood Dr. | 8 | Asbestos Cement | 352 | 41 | 1.14 out of 5 | $442 | 155,632 |
| Distribution Main | 5201 | P-306 | WW | Tanglewood Dr. | 8 | Asbestos Cement | 107 | 41 | 1.14 out of 5 | $442 | 47,265 |
| Distribution Main | 9718 | P-10022 | WW | Teddy Ct | 8 | Ductile Iron | 24 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9719 | P-10022 | WW | Teddy Ct | 8 | Ductile Iron | 237 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9678 | P-1244 | WW | Terrace Ave | 8 | Ductile Iron | 33 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3378 | P-1880 | WW | Terrance Court | 2 | Unknown | 288 | 77 | 1.86 out of 5 | $442 | 127,250 |
| Distribution Main | 12077 | P-1880 | WW | Terrance Court | 2 | Unknown | 1 | 77 | 1.86 out of 5 | $442 | 601 |
| Distribution Main | 4721 | P-115 | WW | Terre Mar Dr. | 8 | Asbestos Cement | 467 | 44 | 1.14 out of 5 | $442 | 206,242 |
| Distribution Main | 10793 | P-348 | WW | Third St | 8 | Ductile Iron | 254 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10794 | P-348 | WW | Third St | 8 | Ductile Iron | 72 | 0 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1570 | P-525 | WW | Tiffany Ave. | 6 | Asbestos Cement | 151 | 51 | 1.85 out of 5 | $442 | 66,959 |
| Distribution Main | 5129 | P-524 | WW | Tiffany Ave. | 6 | Asbestos Cement | 92 | 51 | 1.85 out of 5 | $442 | 40,729 |
| Distribution Main | 5130 | P-524 | WW | Tiffany Ave. | 6 | Asbestos Cement | 34 | 51 | 1.85 out of 5 | $442 | 14,927 |
| Distribution Main | 921 | P-1100 | WW | Tilton St. | 6 | Asbestos Cement | 484 | 48 | 1.85 out of 5 | $442 | 213,735 |
| Distribution Main | 2330 | P-1416 | WW | Timber Walk | 8 | Ductile Iron | 58 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2331 | P-1416 | WW | Timber Walk | 8 | Ductile Iron | 485 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8516 | P-188 | WW | Timber Walk | 6 | Ductile Iron | 23 | 21 | 0.85 out of 5 | N/A | $0 |
| Distribution Main | 9899 | P-1900 | WW | Tobin St | 6 | Ductile Iron | 30 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9900 | P-1899 | WW | Tobin St | 8 | Ductile Iron | 158 | 11 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9901 | P-1898 | WW | Tobin St | 6 | Ductile Iron | 17 | 11 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 206 | P-786 | WW | Tobin St. | 6 | Cast Iron | 263 | 74 | 2.28 out of 5 | $442 | 116,212 |
| Distribution Main | 9902 | P-786 | WW | Tobin St. | 6 | Cast Iron | 140 | 74 | 2.28 out of 5 | $442 | 61,964 |
| Distribution Main | 150 | P-315 | WW | Tower Rd. | 8 | Asbestos Cement | 361 | 43 | 1.14 out of 5 | $442 | 159,682 |
| Distribution Main | 2499 | P-311 | WW | Tower Rd. | 8 | Asbestos Cement | 277 | 43 | 1.14 out of 5 | $442 | 122,486 |
| Distribution Main | 2500 | P-311 | WW | Tower Rd. | 8 | Asbestos Cement | 640 | 43 | 1.14 out of 5 | $442 | 282,838 |
| Distribution Main | 5189 | P-309 | WW | Tower Rd. | 8 | Asbestos Cement | 321 | 43 | 1.14 out of 5 | $442 | 141,867 |
| Distribution Main | 5265 | P-313 | WW | Tower Rd. | 8 | Asbestos Cement | 58 | 43 | 1.14 out of 5 | $442 | 25,733 |
| Distribution Main | 5266 | P-313 | WW | Tower Rd. | 8 | Asbestos Cement | 599 | 43 | 1.14 out of 5 | $442 | 264,586 |
| Distribution Main | 12049 | P-313 | WW | Tower Rd. | 8 | Asbestos Cement | 7 | 43 | 1.14 out of 5 | $442 | 3,080 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10042 | P-259 | WW | Tripoli St | 8 | Ductile Iron | 183 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10834 | P-1768 | WW | Tripoli St | 8 | Ductile Iron | 97 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10835 | P-1768 | WW | Tripoli St | 8 | Ductile Iron | 58 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2846 | P-1905 | WW | Tuckerman Street | 2 | Unknown | 124 | 75 | 1.86 out of 5 | $442 | 54,880 |
| Distribution Main | 3568 | P-105 | WW | Turner Dr. | 8 | Asbestos Cement | 121 | 44 | 1.14 out of 5 | $442 | 53,410 |
| Distribution Main | 3569 | P-106 | WW | Turner Dr. | 8 | Asbestos Cement | 215 | 44 | 1.14 out of 5 | $442 | 95,072 |
| Distribution Main | 4129 | P-103 | WW | Turner Dr. | 8 | Asbestos Cement | 775 | 44 | 1.14 out of 5 | $442 | 342,331 |
| Distribution Main | 4130 | P-103 | WW | Turner Dr. | 8 | Asbestos Cement | 42 | 44 | 1.14 out of 5 | $442 | 18,420 |
| Distribution Main | 4132 | P-105 | WW | Turner Dr. | 8 | Asbestos Cement | 130 | 44 | 1.14 out of 5 | $442 | 57,243 |
| Distribution Main | 9458 | P-1914 | WW | Urquhart St | | Unknown | 46 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 9459 | P-1914 | WW | Urquhart St | | Unknown | 314 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 9460 | P-1913 | WW | Urquhart St | | Unknown | 317 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 9461 | P-1913 | WW | Urquhart St | | Unknown | 21 | UNK | 0 out of 5 | N/A | $0 |
| Distribution Main | 2853 | P-755 | WW | Valley View Dr. | 1 | Copper | 206 | 69 | 2.43 out of 5 | $442 | 91,093 |
| Distribution Main | 8541 | P-934 | WW | Ventura St | 8 | Ductile Iron | 13 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8570 | P-934 | WW | Ventura St | 6 | Ductile Iron | 7 | 13 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 3486 | P-1848 | WW | Ventura St. | 6 | Cast Iron | 356 | 134 | 2.57 out of 5 | $442 | 157,475 |
| Distribution Main | 8667 | P-1781 | WW | Victoria Way | 8 | Ductile Iron | 19 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8668 | P-1781 | WW | Victoria Way | 8 | Ductile Iron | 107 | 15 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4166 | P-91 | WW | Victory Ave. | 6 | Asbestos Cement | 302 | 78 | 2 out of 5 | $442 | 133,332 |
| Distribution Main | 8434 | P-890 | WW | Vincenzo Dr | 8 | Ductile Iron | 36 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8505 | P-890 | WW | Vincenzo Dr | 6 | Ductile Iron | 14 | 10 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 1005 | P-889 | WW | Vincenzo Dr. | 6 | PVC | 289 | 38 | 1.14 out of 5 | $442 | 127,564 |
| Distribution Main | 1412 | P-1791 | WW | Vincenzo Dr. | 6 | Asbestos Cement | 517 | 55 | 1.85 out of 5 | $442 | 228,636 |
| Distribution Main | 2950 | P-1359 | WW | Vine St. | 4 | Cast Iron | 4 | 133 | 3.29 out of 5 | $442 | 1,829 |
| Distribution Main | 2951 | P-1359 | WW | Vine St. | 4 | Cast Iron | 480 | 133 | 3.29 out of 5 | $442 | 212,075 |
| Distribution Main | 1969 | | WW | Virginia Ave. | 6 | Asbestos Cement | 7 | 52 | 1.85 out of 5 | $442 | 3,238 |
| Distribution Main | 3791 | P-762 | WW | Virginia Ave. | 6 | Asbestos Cement | 233 | 52 | 1.85 out of 5 | $442 | 103,095 |
| Distribution Main | 8640 | P-1783 | WW | W.W. Elementary School | 8 | Ductile Iron | 161 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8641 | | WW | W.W. Elementary School | 12 | Ductile Iron | 2 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8642 | P-133Y | WW | W.W. Elementary School | 12 | Ductile Iron | 403 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8643 | P-1328 | WW | W.W. Elementary School | 12 | Ductile Iron | 42 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8644 | P-1329 | WW | W.W. Elementary School | 12 | Ductile Iron | 236 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8645 | P-1329 | WW | W.W. Elementary School | 12 | Ductile Iron | 105 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9053 | | WW | W.W. Elementary School | 6 | Ductile Iron | 3 | 17 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9054 | | WW | W.W. Elementary School | 4 | Ductile Iron | 2 | 17 | 1.42 out of 5 | N/A | $0 |
| Transmission Main | 11487 | P-1329 | WW | W.W. Elementary School | 12 | Ductile Iron | 9 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11488 | P-1329 | WW | W.W. Elementary School | 12 | Ductile Iron | 2 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 12096 | P-1329 | WW | W.W. Elementary School | 12 | Ductile Iron | 75 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8539 | P-1847 | WW | Wakefield St | 20 | Ductile Iron | 296 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8540 | P-1847 | WW | Wakefield St | 20 | Ductile Iron | 136 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10049 | P-1751 | WW | Wakefield St | 16 | Ductile Iron | 214 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10315 | | WW | Wakefield St | 16 | Ductile Iron | 6 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10316 | | WW | Wakefield St | 16 | Ductile Iron | 4 | 5 | 0 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 10317 | P-233 | WW | Wakefield St | 8 | Ductile Iron | 6 | 5 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10693 | | WW | Wakefield St | 42 | Asbestos Cement | 1,061 | UNK | 0.85 out of 5 | $442 | 469,096 |
| Transmission Main | 10702 | | WW | Wakefield St | 16 | Ductile Iron | 2,022 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10713 | P-874 | WW | Wakefield St | 12 | Ductile Iron | 7 | 1 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11636 | P-1752 | WW | Wakefield St | 16 | Ductile Iron | 47 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 503 | P-1330 | WW | Wakefield St. | 12 | Asbestos Cement | 227 | 39 | 1 out of 5 | $442 | 100,379 |
| Transmission Main | 1197 | P-909 | WW | Wakefield St. | 12 | Ductile Iron | 430 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1198 | P-909 | WW | Wakefield St. | 12 | Ductile Iron | 10 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1199 | P-908 | WW | Wakefield St. | 12 | Ductile Iron | 437 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1200 | P-908 | WW | Wakefield St. | 12 | Ductile Iron | 487 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1202 | P-1333 | WW | Wakefield St. | 12 | Ductile Iron | 292 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1518 | P-929 | WW | Wakefield St. | 12 | Ductile Iron | 14 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1543 | P-854 | WW | Wakefield St. | 12 | Ductile Iron | 7 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1544 | P-852 | WW | Wakefield St. | 12 | Ductile Iron | 142 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1545 | P-852 | WW | Wakefield St. | 12 | Ductile Iron | 211 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1546 | P-887 | WW | Wakefield St. | 12 | Ductile Iron | 75 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1547 | P-851 | WW | Wakefield St. | 12 | Ductile Iron | 179 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1548 | P-850 | WW | Wakefield St. | 12 | Ductile Iron | 335 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1549 | P-850 | WW | Wakefield St. | 12 | Ductile Iron | 33 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1782 | P-855 | WW | Wakefield St. | 12 | Ductile Iron | 570 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1783 | P-855 | WW | Wakefield St. | 12 | Ductile Iron | 140 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1784 | P-907 | WW | Wakefield St. | 12 | Ductile Iron | 236 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 1998 | P-1330 | WW | Wakefield St. | 12 | Asbestos Cement | 7 | 39 | 1 out of 5 | $442 | 2,964 |
| Transmission Main | 2094 | P-1305 | WW | Wakefield St. | 12 | Asbestos Cement | 58 | 39 | 1 out of 5 | $442 | 25,513 |
| Transmission Main | 2097 | P-10049 | WW | Wakefield St. | 12 | Asbestos Cement | 844 | 39 | 1 out of 5 | $442 | 373,115 |
| Transmission Main | 2102 | P-855 | WW | Wakefield St. | 12 | Asbestos Cement | 690 | 39 | 1 out of 5 | $442 | 304,998 |
| Transmission Main | 2103 | P-855 | WW | Wakefield St. | 12 | Asbestos Cement | 857 | 39 | 1 out of 5 | $442 | 378,651 |
| Transmission Main | 2959 | P-920 | WW | Wakefield St. | 12 | Ductile Iron | 57 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 2960 | P-920 | WW | Wakefield St. | 12 | Ductile Iron | 88 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 3498 | P-854 | WW | Wakefield St. | 12 | Ductile Iron | 135 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5631 | P-233 | WW | Wakefield St. | 8 | Ductile Iron | 450 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5632 | P-237 | WW | Wakefield St. | 8 | Ductile Iron | 15 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5633 | P-237 | WW | Wakefield St. | 8 | Ductile Iron | 399 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 5645 | P-233 | WW | Wakefield St. | 8 | Ductile Iron | 93 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7134 | P-237 | WW | Wakefield St. | 8 | Ductile Iron | 190 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7135 | P-237 | WW | Wakefield St. | 8 | Ductile Iron | 92 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 7495 | P-236 | WW | Wakefield St. | 8 | Ductile Iron | 222 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 8123 | | WW | Wakefield St. | 8 | Ductile Iron | 3 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 8511 | P-850 | WW | Wakefield St. | 16 | Ductile Iron | 4 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 8536 | P-929 | WW | Wakefield St. | 12 | Ductile Iron | 116 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 8537 | P-935 | WW | Wakefield St. | 12 | Ductile Iron | 298 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 8538 | P-935 | WW | Wakefield St. | 12 | Ductile Iron | 141 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 9132 | P-874 | WW | Wakefield St. | 12 | PVC | 158 | 30 | 0.43 out of 5 | $442 | 70,019 |
| Transmission Main | 9422 | P-850 | WW | Wakefield St. | 12 | Ductile Iron | 2 | 22 | 0.14 out of 5 | N/A | $0 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 11133 | P-850 | WW | Wakefield St. | 12 | Ductile Iron | 18 | 22 | 0.14 out of 5 | N/A | $0 |
| Distribution Main | 11310 | P-233 | WW | Wakefield St. | 8 | Ductile Iron | 31 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11472 | P-850 | WW | Wakefield St. | 16 | Ductile Iron | 2 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11477 | P-935 | WW | Wakefield St. | 12 | Ductile Iron | 96 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 11478 | P-935 | WW | Wakefield St. | 12 | Ductile Iron | 14 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 12026 | P-907 | WW | Wakefield St. | 12 | Ductile Iron | 20 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 12027 | P-855 | WW | Wakefield St. | 12 | Ductile Iron | 179 | 22 | 0.14 out of 5 | N/A | $0 |
| Transmission Main | 254 | P-1267 | WW | Wakefield St. Tank | 12 | Ductile Iron | 11 | 29 | 0.14 out of 5 | $442 | 4,852 |
| Transmission Main | 255 | P-1267 | WW | Wakefield St. Tank | 12 | Ductile Iron | 106 | 29 | 0.14 out of 5 | $442 | 46,952 |
| Transmission Main | 8054 | P-1267 | WW | Wakefield St. Tank | 12 | Ductile Iron | 9 | 29 | 0.14 out of 5 | $442 | 3,847 |
| Distribution Main | 9530 | P-1891 | WW | Walker St | 0.75 | Copper | 19 | 18 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 9531 | P-1893 | WW | Walker St | 2 | Copper | 38 | 18 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 10379 | P-1891 | WW | Walker St | 0.75 | Copper | 16 | 18 | 1.99 out of 5 | N/A | $0 |
| Distribution Main | 319 | P-1897 | WW | Walker St. | 4 | Cast Iron | 29 | 18 | 2.56 out of 5 | N/A | $0 |
| Distribution Main | 3326 | P-1402 | WW | Walker St. | 8 | Ductile Iron | 434 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3327 | P-1040 | WW | Walker St. | 8 | Ductile Iron | 350 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3357 | P-1890 | WW | Walker St. | 8 | Ductile Iron | 4 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9532 | P-1897 | WW | Walker St. | 8 | Ductile Iron | 24 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9537 | P-1890 | WW | Walker St. | 8 | Ductile Iron | 46 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11583 | P-1897 | WW | Walker St. | 8 | Ductile Iron | 12 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 609 | P-683 | WW | Walnut St. | 6 | Asbestos Cement | 401 | 47 | 1.85 out of 5 | $442 | 177,255 |
| Distribution Main | 4285 | P-683 | WW | Walnut St. | 1 | Unknown | 22 | 47 | 1.71 out of 5 | $442 | 9,612 |
| Distribution Main | 123 | P-729 | WW | Washington St. | 8 | Cast Iron | 89 | 134 | 1.86 out of 5 | $442 | 39,363 |
| Distribution Main | 124 | P-729 | WW | Washington St. | 8 | Cast Iron | 105 | 134 | 1.86 out of 5 | $442 | 46,515 |
| Transmission Main | 867 | P-689 | WW | Washington St. | 12 | Cast Iron | 359 | 134 | 1.86 out of 5 | $442 | 158,458 |
| Transmission Main | 2967 | P-687 | WW | Washington St. | 12 | Cast Iron | 44 | 134 | 1.86 out of 5 | $442 | 19,240 |
| Distribution Main | 3675 | P-1681 | WW | Washington St. | 8 | Cast Iron | 14 | 134 | 1.86 out of 5 | $442 | 6,399 |
| Distribution Main | 3676 | P-1681 | WW | Washington St. | 8 | Cast Iron | 289 | 134 | 1.86 out of 5 | $442 | 127,941 |
| Distribution Main | 3764 | P-1974 | WW | Washington St. | 8 | Cast Iron | 111 | 88 | 1.72 out of 5 | $442 | 48,997 |
| Distribution Main | 3770 | P-724 | WW | Washington St. | 8 | Cast Iron | 470 | 134 | 1.86 out of 5 | $442 | 207,737 |
| Distribution Main | 3771 | P-668 | WW | Washington St. | 8 | Cast Iron | 38 | 134 | 1.86 out of 5 | $442 | 16,658 |
| Transmission Main | 3779 | P-687 | WW | Washington St. | 12 | Cast Iron | 74 | 134 | 1.86 out of 5 | $442 | 32,514 |
| Transmission Main | 3780 | P-687 | WW | Washington St. | 12 | Cast Iron | 211 | 134 | 1.86 out of 5 | $442 | 93,415 |
| Distribution Main | 3945 | P-669 | WW | Washington St. | 8 | Cast Iron | 83 | 88 | 1.72 out of 5 | $442 | 36,835 |
| Distribution Main | 3946 | P-669 | WW | Washington St. | 8 | Cast Iron | 116 | 88 | 1.72 out of 5 | $442 | 51,323 |
| Distribution Main | 3947 | P-671 | WW | Washington St. | 8 | Cast Iron | 157 | 88 | 1.72 out of 5 | $442 | 69,177 |
| Distribution Main | 3948 | P-671 | WW | Washington St. | 8 | Cast Iron | 150 | 88 | 1.72 out of 5 | $442 | 66,287 |
| Transmission Main | 3949 | P-680 | WW | Washington St. | 12 | Cast Iron | 80 | 134 | 1.86 out of 5 | $442 | 35,557 |
| Transmission Main | 3950 | P-682 | WW | Washington St. | 12 | Cast Iron | 266 | 133 | 1.86 out of 5 | $442 | 117,719 |
| Transmission Main | 3951 | P-682 | WW | Washington St. | 12 | Cast Iron | 66 | 133 | 1.86 out of 5 | $442 | 29,122 |
| Transmission Main | 3952 | P-684 | WW | Washington St. | 12 | Cast Iron | 177 | 133 | 1.86 out of 5 | $442 | 78,343 |
| Transmission Main | 3953 | P-1381 | WW | Washington St. | 12 | Cast Iron | 57 | 133 | 1.86 out of 5 | $442 | 25,336 |
| Transmission Main | 3954 | P-1381 | WW | Washington St. | 12 | Cast Iron | 116 | 133 | 1.86 out of 5 | $442 | 51,207 |
| Transmission Main | 3955 | P-686 | WW | Washington St. | 12 | Cast Iron | 249 | 133 | 1.86 out of 5 | $442 | 110,026 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 3956 | P-686 | WW | Washington St. | 12 | Cast Iron | 727 | 133 | 1.86 out of 5 | $442 | 321,191 |
| Distribution Main | 10000 | P-1974 | WW | Washington St. | 8 | Cast Iron | 15 | 88 | 1.72 out of 5 | $442 | 6,643 |
| Distribution Main | 10117 | P-729 | WW | Washington St. | 6 | Ductile Iron | 10 | UNK | 0.71 out of 5 | $442 | 4,530 |
| Distribution Main | 11093 | P-1681 | WW | Washington St. | 8 | Cast Iron | 14 | 134 | 1.86 out of 5 | $442 | 6,255 |
| Distribution Main | 11224 | P-1681 | WW | Washington St. | 8 | Cast Iron | 22 | 134 | 1.86 out of 5 | $442 | 9,833 |
| Distribution Main | 11228 | P-724 | WW | Washington St. | 8 | Cast Iron | 29 | 134 | 1.86 out of 5 | $442 | 12,610 |
| Distribution Main | 11229 | P-668 | WW | Washington St. | 8 | Cast Iron | 22 | 88 | 1.72 out of 5 | $442 | 9,935 |
| Distribution Main | 10001 | P-729 | WW | Washington Street | 6 | Ductile Iron | 6 | 12 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 10300 | P-268 | WW | Water St | 8 | Ductile Iron | 12 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10302 | P-268 | WW | Water St | 8 | Ductile Iron | 502 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10303 | P-268 | WW | Water St | 8 | Ductile Iron | 178 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10416 | P-267 | WW | Water St | 8 | Ductile Iron | 172 | 5 | 0 out of 5 | N/A | $0 |
| Distribution Main | 4122 | P-183 | WW | Watervalley Rd. | 8 | PVC | 430 | 35 | 0.43 out of 5 | $442 | 190,011 |
| Distribution Main | 4123 | P-183 | WW | Watervalley Rd. | 8 | PVC | 4 | 35 | 0.43 out of 5 | $442 | 1,618 |
| Distribution Main | 10294 | P-184 | WW | Watervalley Rd. | 8 | PVC | 39 | 35 | 0.43 out of 5 | $442 | 17,453 |
| Distribution Main | 486 | P-960 | WW | Waverly St. | 8 | Asbestos Cement | 417 | 54 | 1.14 out of 5 | $442 | 184,440 |
| Distribution Main | 1008 | P-960 | WW | Waverly St. | 8 | Asbestos Cement | 115 | 54 | 1.14 out of 5 | $442 | 51,001 |
| Distribution Main | 9995 | P-1053 | WW | Weaver St | 8 | Ductile Iron | 13 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9996 | P-1053 | WW | Weaver St | 8 | Ductile Iron | 49 | 8 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2847 | P-1060 | WW | Weaver St. | 6 | Cast Iron | 225 | 129 | 2.57 out of 5 | $442 | 99,546 |
| Distribution Main | 3132 | P-1048 | WW | Weaver St. | 6 | Cast Iron | 251 | 129 | 2.57 out of 5 | $442 | 111,136 |
| Distribution Main | 3133 | P-1061 | WW | Weaver St. | 4 | Cast Iron | 241 | 129 | 3.29 out of 5 | $442 | 106,350 |
| Distribution Main | 3205 | P-1339 | WW | Weaver St. | 4 | Cast Iron | 161 | 129 | 3.29 out of 5 | $442 | 71,380 |
| Distribution Main | 3206 | P-1339 | WW | Weaver St. | 4 | Cast Iron | 92 | 129 | 3.29 out of 5 | $442 | 40,739 |
| Distribution Main | 214 | P-341 | WW | Webster Knight Dr. | 6 | Asbestos Cement | 521 | 48 | 1.85 out of 5 | $442 | 230,432 |
| Distribution Main | 215 | P-341 | WW | Webster Knight Dr. | 6 | Asbestos Cement | 36 | 48 | 1.85 out of 5 | $442 | 15,950 |
| Distribution Main | 4339 | | WW | Webster Knight Dr. | 6 | Asbestos Cement | 476 | 48 | 1.85 out of 5 | $442 | 210,229 |
| Distribution Main | 4340 | | WW | Webster Knight Dr. | 6 | Asbestos Cement | 69 | 48 | 1.85 out of 5 | $442 | 30,535 |
| Distribution Main | 3107 | P-1366 | WW | Webster St. | 4 | Cast Iron | 296 | 109 | 3.29 out of 5 | $442 | 130,751 |
| Distribution Main | 10648 | | WW | Wells St | 8 | Ductile Iron | 112 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10649 | P-384 | WW | Wells St | 8 | Ductile Iron | 183 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10650 | P-376 | WW | Wells St. | 8 | Ductile Iron | 42 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10651 | P-375 | WW | Wells St. | 8 | Ductile Iron | 263 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 11699 | P-376 | WW | Wells St. | 8 | Ductile Iron | 220 | 2 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3117 | P-1147 | WW | Wendy Way | 6 | Asbestos Cement | 899 | 48 | 1.85 out of 5 | $442 | 397,230 |
| Distribution Main | 4820 | P-1147 | WW | Wendy Way | 6 | Asbestos Cement | 18 | 48 | 1.85 out of 5 | $442 | 7,900 |
| Distribution Main | 9985 | P-1583 | WW | West Glen Lane | 8 | Ductile Iron | 618 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9986 | P-1583 | WW | West Glen Lane | 8 | Ductile Iron | 228 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 130 | P-697 | WW | West St. | 6 | Cast Iron | 232 | 131 | 2.57 out of 5 | $442 | 102,569 |
| Transmission Main | 2856 | P-769 | WW | West St. | 12 | Asbestos Cement | 7 | 75 | 1.29 out of 5 | $442 | 3,249 |
| Transmission Main | 2857 | P-765 | WW | West St. | 12 | Cast Iron | 296 | 89 | 1.72 out of 5 | $442 | 130,645 |
| Transmission Main | 2858 | P-761 | WW | West St. | 12 | Cast Iron | 71 | 89 | 1.72 out of 5 | $442 | 31,493 |
| Transmission Main | 2859 | P-761 | WW | West St. | 12 | Cast Iron | 308 | 89 | 1.72 out of 5 | $442 | 136,345 |
| Transmission Main | 2860 | P-759 | WW | West St. | 12 | Cast Iron | 168 | 89 | 1.72 out of 5 | $442 | 74,101 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Transmission Main | 2861 | P-1289 | WW | West St. | 12 | Cast Iron | 282 | 89 | 1.72 out of 5 | $442 | 124,796 |
| Transmission Main | 3209 | P-769 | WW | West St. | 16 | Asbestos Cement | 335 | 75 | 1.29 out of 5 | $442 | 148,144 |
| Distribution Main | 3212 | P-708 | WW | West St. | 2 | Galvanized Iron | 797 | 79 | 3.28 out of 5 | $442 | 352,183 |
| Distribution Main | 3261 | P-703 | WW | West St. | 4 | Cast Iron | 297 | 130 | 3.29 out of 5 | $442 | 131,452 |
| Distribution Main | 3262 | P-706 | WW | West St. | 6 | Cast Iron | 133 | 79 | 2.28 out of 5 | $442 | 58,576 |
| Distribution Main | 3762 | P-697 | WW | West St. | 6 | Cast Iron | 3 | 131 | 2.57 out of 5 | $442 | 1,442 |
| Distribution Main | 3777 | P-1952 | WW | West St. | 6 | Cast Iron | 471 | 131 | 2.57 out of 5 | $442 | 208,087 |
| Distribution Main | 3778 | P-1952 | WW | West St. | 6 | Cast Iron | 168 | 131 | 2.57 out of 5 | $442 | 74,374 |
| Distribution Main | 8836 | P-696 | WW | West St. | 6 | Cast Iron | 56 | 130 | 2.57 out of 5 | $442 | 24,563 |
| Distribution Main | 8837 | P-705 | WW | West St. | 4 | Cast Iron | 269 | 130 | 3.29 out of 5 | $442 | 118,708 |
| Distribution Main | 8838 | P-705 | WW | West St. | 4 | Cast Iron | 13 | 130 | 3.29 out of 5 | $442 | 5,657 |
| Distribution Main | 10687 | P-708 | WW | West St. | 6 | Cast Iron | 151 | 79 | 2.28 out of 5 | $442 | 66,561 |
| Distribution Main | 10688 | P-708 | WW | West St. | 1 | Copper | 18 | 1 | 1.99 out of 5 | N/A | $0 |
| Transmission Main | 11205 | P-769 | WW | West St. | 16 | Asbestos Cement | 6 | 75 | 1.29 out of 5 | $442 | 2,559 |
| Distribution Main | 11518 | P-705 | WW | West St. | 4 | Cast Iron | 4 | 130 | 3.29 out of 5 | $442 | 1,574 |
| Distribution Main | 11707 | P-708 | WW | West St. | 6 | Cast Iron | 3 | 79 | 2.28 out of 5 | $442 | 1,349 |
| Transmission Main | 2390 | | WW | West St. Tank | 12 | Cast Iron | 9 | 89 | 1.72 out of 5 | $442 | 3,954 |
| Transmission Main | 2485 | | WW | West St. Tank | 12 | Ductile Iron | 11 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 2486 | | WW | West St. Tank | 12 | Cast Iron | 14 | 89 | 1.72 out of 5 | $442 | 6,051 |
| Transmission Main | 2496 | | WW | West St. Tank | 12 | Cast Iron | 5 | 89 | 1.72 out of 5 | $442 | 2,220 |
| Transmission Main | 3208 | | WW | West St. Tank | 16 | Ductile Iron | 4 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3210 | | WW | West St. Tank | 8 | Cast Iron | 40 | 89 | 1.72 out of 5 | $442 | 17,476 |
| Transmission Main | 3211 | | WW | West St. Tank | 12 | Ductile Iron | 2 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3213 | P-769 | WW | West St. Tank | 12 | Ductile Iron | 4 | 17 | 0 out of 5 | N/A | $0 |
| Transmission Main | 3604 | | WW | West St. Tank | 12 | Cast Iron | 4 | 89 | 1.72 out of 5 | $442 | 1,781 |
| Transmission Main | 3671 | | WW | West St. Tank | 12 | Ductile Iron | 10 | 17 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9709 | P-1846 | WW | West Warwick | 10 | Ductile Iron | 29 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 140 | P-550 | WW | West Warwick Ave. | 6 | Cast Iron | 90 | 134 | 2.57 out of 5 | $442 | 39,592 |
| Distribution Main | 141 | P-550 | WW | West Warwick Ave. | 6 | Cast Iron | 129 | 134 | 2.57 out of 5 | $442 | 56,929 |
| Distribution Main | 1720 | P-1949 | WW | West Warwick Ave. | 6 | Cast Iron | 158 | 134 | 2.57 out of 5 | $442 | 69,989 |
| Distribution Main | 1728 | P-690 | WW | West Warwick Ave. | 6 | Cast Iron | 257 | 129 | 2.57 out of 5 | $442 | 113,793 |
| Distribution Main | 2890 | P-639 | WW | West Warwick Ave. | 6 | Cast Iron | 415 | 134 | 2.57 out of 5 | $442 | 183,503 |
| Distribution Main | 2891 | P-639 | WW | West Warwick Ave. | 6 | Cast Iron | 9 | 134 | 2.57 out of 5 | $442 | 4,108 |
| Distribution Main | 2895 | P-550 | WW | West Warwick Ave. | 6 | Cast Iron | 3 | 134 | 2.57 out of 5 | $442 | 1,520 |
| Distribution Main | 3990 | P-1969 | WW | West Warwick Ave. | 6 | Cast Iron | 203 | 134 | 2.57 out of 5 | $442 | 89,587 |
| Distribution Main | 3991 | P-569 | WW | West Warwick Ave. | 6 | Cast Iron | 163 | 134 | 2.57 out of 5 | $442 | 71,860 |
| Distribution Main | 3992 | P-566 | WW | West Warwick Ave. | 6 | Cast Iron | 119 | 134 | 2.57 out of 5 | $442 | 52,566 |
| Distribution Main | 3993 | P-565 | WW | West Warwick Ave. | 6 | Cast Iron | 180 | 134 | 2.57 out of 5 | $442 | 79,625 |
| Distribution Main | 3994 | P-565 | WW | West Warwick Ave. | 6 | Cast Iron | 22 | 134 | 2.57 out of 5 | $442 | 9,783 |
| Distribution Main | 3995 | P-560 | WW | West Warwick Ave. | 6 | Cast Iron | 244 | 134 | 2.57 out of 5 | $442 | 107,654 |
| Distribution Main | 3996 | P-559 | WW | West Warwick Ave. | 6 | Cast Iron | 204 | 134 | 2.57 out of 5 | $442 | 90,355 |
| Distribution Main | 3997 | P-552 | WW | West Warwick Ave. | 6 | Cast Iron | 97 | 134 | 2.57 out of 5 | $442 | 42,983 |
| Distribution Main | 4004 | P-639 | WW | West Warwick Ave. | 6 | Cast Iron | 33 | 134 | 2.57 out of 5 | $442 | 14,619 |
| Distribution Main | 4005 | P-639 | WW | West Warwick Ave. | 6 | Cast Iron | 145 | 134 | 2.57 out of 5 | $442 | 64,217 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4317 | P-640 | WW | West Warwick Ave. | 6 | Cast Iron | 111 | 134 | 2.57 out of 5 | $442 | 49,012 |
| Distribution Main | 4320 | P-639 | WW | West Warwick Ave. | 6 | Cast Iron | 12 | 134 | 2.57 out of 5 | $442 | 5,249 |
| Transmission Main | 8021 | P-557 | WW | West Warwick Ave. | 12 | Ductile Iron | 5 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8022 | P-557 | WW | West Warwick Ave. | 6 | Cast Iron | 6 | 134 | 2.57 out of 5 | $442 | 2,563 |
| Distribution Main | 8023 | P-557 | WW | West Warwick Ave. | 6 | Cast Iron | 20 | 134 | 2.57 out of 5 | $442 | 8,793 |
| Distribution Main | 8024 | P-555 | WW | West Warwick Ave. | 6 | Cast Iron | 234 | 134 | 2.57 out of 5 | $442 | 103,570 |
| Transmission Main | 8025 | P-557 | WW | West Warwick Ave. | 12 | Ductile Iron | 6 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9371 | P-557 | WW | West Warwick Ave. | 6 | Ductile Iron | 2 | 14 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 9372 | P-557 | WW | West Warwick Ave. | 6 | Ductile Iron | 2 | 14 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 11238 | P-560 | WW | West Warwick Ave. | 6 | Cast Iron | 28 | 134 | 2.57 out of 5 | $442 | 12,361 |
| Distribution Main | 8548 | P-923 | WW | Westly St | 8 | Ductile Iron | 25 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8574 | P-923 | WW | Westly St | 6 | Ductile Iron | 2 | 13 | 0.71 out of 5 | N/A | $0 |
| Transmission Main | 8575 | P-924 | WW | Westly St | 20 | Ductile Iron | 179 | 13 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11482 | P-924 | WW | Westly St | 20 | Ductile Iron | 3 | 13 | 0 out of 5 | N/A | $0 |
| Distribution Main | 1519 | P-923 | WW | Westly St. | 6 | Cast Iron | 57 | 134 | 2.57 out of 5 | $442 | 24,983 |
| Distribution Main | 1520 | P-923 | WW | Westly St. | 6 | Cast Iron | 269 | 134 | 2.57 out of 5 | $442 | 119,106 |
| Distribution Main | 3739 | P-922 | WW | Westly St. | 6 | Cast Iron | 182 | 134 | 2.57 out of 5 | $442 | 80,660 |
| Transmission Main | 9328 | P-1689 | WW | Whisper Ct | 12 | Ductile Iron | 448 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9329 | P-1689 | WW | Whisper Ct | 12 | Ductile Iron | 143 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9330 | P-1691 | WW | Whisper Ct | 12 | Ductile Iron | 139 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 9331 | P-1692 | WW | Whisper Ct | 12 | Ductile Iron | 448 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11576 | | WW | Whisper Ct | 12 | Ductile Iron | 1 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 2440 | P-3 | WW | Whispering Pines Ct. | 8 | Ductile Iron | 236 | 28 | 0.14 out of 5 | $442 | 104,135 |
| Distribution Main | 4661 | P-175 | WW | Whitebirch Ln. | 8 | Asbestos Cement | 379 | 42 | 1.14 out of 5 | $442 | 167,387 |
| Distribution Main | 4662 | P-175 | WW | Whitebirch Ln. | 8 | Asbestos Cement | 38 | 42 | 1.14 out of 5 | $442 | 16,745 |
| Transmission Main | 2277 | P-1356 | WW | Wightman St. | 12 | PVC | 10 | 31 | 0.43 out of 5 | $442 | 4,512 |
| Transmission Main | 3512 | P-1356 | WW | Wightman St. | 12 | PVC | 433 | 31 | 0.43 out of 5 | $442 | 191,519 |
| Transmission Main | 3513 | P-1357 | WW | Wightman St. | 12 | PVC | 335 | 31 | 0.43 out of 5 | $442 | 147,962 |
| Transmission Main | 3514 | P-1357 | WW | Wightman St. | 12 | PVC | 296 | 31 | 1.14 out of 5 | $442 | 130,907 |
| Transmission Main | 3515 | P-835 | WW | Wightman St. | 12 | PVC | 363 | 31 | 1.14 out of 5 | $442 | 160,525 |
| Distribution Main | 8843 | P-8033 | WW | Willow St. | 6 | Cast Iron | 342 | 124 | 2.57 out of 5 | $442 | 151,365 |
| Distribution Main | 8844 | P-694 | WW | Willow St. | 6 | Cast Iron | 177 | 129 | 2.57 out of 5 | $442 | 78,253 |
| Distribution Main | 8845 | P-694 | WW | Willow St. | 6 | Cast Iron | 36 | 129 | 2.57 out of 5 | $442 | 15,716 |
| Distribution Main | 8846 | P-695 | WW | Willow St. | 6 | Cast Iron | 407 | 129 | 2.57 out of 5 | $442 | 180,032 |
| Transmission Main | 10045 | P-1704 | WW | Wilson St | 12 | Ductile Iron | 384 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10046 | P-256 | WW | Wilson St | 12 | Ductile Iron | 237 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10047 | P-1767 | WW | Wilson St | 12 | Ductile Iron | 138 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 10048 | P-1767 | WW | Wilson St | 12 | Ductile Iron | 809 | 6 | 0 out of 5 | N/A | $0 |
| Transmission Main | 11635 | P-1704 | WW | Wilson St | 12 | Ductile Iron | 79 | 6 | 0 out of 5 | N/A | $0 |
| Distribution Main | 10410 | P-603 | WW | Windsor Park Dr | 8 | Ductile Iron | 145 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 9732 | P-603 | WW | Windsor Park Dr. | 8 | Ductile Iron | 11 | 14 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3109 | P-544 | WW | Winthrop Ave. | 2 | Galvanized Iron | 380 | 109 | 4.28 out of 5 | $442 | 168,031 |
| Distribution Main | 3969 | P-544 | WW | Winthrop Ave. | 2 | Galvanized Iron | 37 | 109 | 3.57 out of 5 | $442 | 16,332 |
| Distribution Main | 4314 | P-545 | WW | Winthrop Ave. | 4 | Cast Iron | 50 | 109 | 3.29 out of 5 | $442 | 22,153 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 4315 | P-545 | WW | Winthrop Ave. | 4 | Cast Iron | 643 | 109 | 3.29 out of 5 | $442 | 284,221 |
| Distribution Main | 8839 | P-707 | WW | Wood St. | 6 | Asbestos Cement | 252 | 69 | 2 out of 5 | $442 | 111,171 |
| Transmission Main | 8409 | P-1679 | WW | Woodbine St | 12 | Ductile Iron | 17 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8410 | P-1679 | WW | Woodbine St | 12 | Ductile Iron | 79 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8411 | P-967 | WW | Woodbine St | 12 | Ductile Iron | 435 | 10 | 0 out of 5 | N/A | $0 |
| Transmission Main | 8481 | P-1679 | WW | Woodbine St | 12 | Ductile Iron | 242 | 10 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8935 | | WW | Woodland Dr | 8 | Ductile Iron | 35 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8938 | P-180 | WW | Woodland Dr | 8 | Ductile Iron | 14 | 9 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8946 | P-180 | WW | Woodland Dr | 6 | Ductile Iron | 2 | 9 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 4524 | P-180 | WW | Woodland Dr. | 6 | Asbestos Cement | 223 | 69 | 2 out of 5 | $442 | 98,638 |
| Distribution Main | 5299 | P-189 | WW | Woodland Dr. | 6 | Asbestos Cement | 506 | 69 | 2 out of 5 | $442 | 223,857 |
| Distribution Main | 5300 | P-189 | WW | Woodland Dr. | 6 | Asbestos Cement | 19 | 69 | 2 out of 5 | $442 | 8,530 |
| Distribution Main | 6549 | P-189 | WW | Woodland Dr. | 6 | Asbestos Cement | 2 | 69 | 2 out of 5 | $442 | 833 |
| Distribution Main | 333 | P-818 | WW | Woodside Ave. | 6 | Cast Iron | 180 | 134 | 2.57 out of 5 | $442 | 79,724 |
| Distribution Main | 334 | P-818 | WW | Woodside Ave. | 6 | Cast Iron | 347 | 134 | 2.57 out of 5 | $442 | 153,544 |
| Distribution Main | 1508 | P-803 | WW | Woodside Ave. | 6 | Cast Iron | 575 | 81 | 2.43 out of 5 | $442 | 254,334 |
| Distribution Main | 3386 | P-815 | WW | Woodside Ave. | 6 | Cast Iron | 48 | 134 | 2.57 out of 5 | $442 | 21,079 |
| Distribution Main | 3387 | P-815 | WW | Woodside Ave. | 6 | Cast Iron | 154 | 134 | 2.57 out of 5 | $442 | 68,036 |
| Distribution Main | 3388 | P-814 | WW | Woodside Ave. | 6 | Cast Iron | 718 | 134 | 2.57 out of 5 | $442 | 317,285 |
| Distribution Main | 3389 | P-814 | WW | Woodside Ave. | 6 | Cast Iron | 327 | 134 | 2.57 out of 5 | $442 | 144,644 |
| Distribution Main | 3699 | P-808 | WW | Woodside Ave. | 6 | Cast Iron | 607 | 81 | 2.43 out of 5 | $442 | 268,120 |
| Distribution Main | 3700 | P-808 | WW | Woodside Ave. | 6 | Cast Iron | 12 | 81 | 2.43 out of 5 | $442 | 5,301 |
| Distribution Main | 8739 | P-805 | WW | Woodside Ave. | 6 | Cast Iron | 177 | 81 | 2.43 out of 5 | $442 | 78,068 |
| Distribution Main | 3864 | P-1483 | WW | Wyman St. | 6 | Cast Iron | 240 | 134 | 2.57 out of 5 | $442 | 106,255 |
| Distribution Main | 4212 | P-1483 | WW | Wyman St. | 6 | Cast Iron | 11 | 134 | 2.57 out of 5 | $442 | 4,748 |
| Distribution Main | 5090 | P-1485 | WW | Wyman St. | 6 | Ductile Iron | 50 | 14 | 0.71 out of 5 | N/A | $0 |
| Distribution Main | 204 | P-782 | WW | Youngs Ave. | 8 | Ductile Iron | 49 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 205 | P-782 | WW | Youngs Ave. | 8 | Ductile Iron | 151 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 291 | P-787 | WW | Youngs Ave. | 6 | Cast Iron | 514 | 134 | 2.57 out of 5 | $442 | 227,252 |
| Distribution Main | 292 | P-787 | WW | Youngs Ave. | 6 | Cast Iron | 213 | 134 | 2.57 out of 5 | $442 | 94,159 |
| Distribution Main | 1565 | P-780 | WW | Youngs Ave. | 6 | Asbestos Cement | 246 | 63 | 2 out of 5 | $442 | 108,696 |
| Distribution Main | 1602 | P-1038 | WW | Youngs Ave. | 2 | Galvanized Iron | 14 | 134 | 3.57 out of 5 | $442 | 6,400 |
| Distribution Main | 1603 | P-1038 | WW | Youngs Ave. | 2 | Galvanized Iron | 909 | 134 | 3.57 out of 5 | $442 | 401,711 |
| Distribution Main | 2940 | P-8050 | WW | Youngs Ave. | 8 | Asbestos Cement | 289 | 63 | 1.29 out of 5 | $442 | 127,717 |
| Distribution Main | 2941 | P-8050 | WW | Youngs Ave. | 8 | Asbestos Cement | 333 | 63 | 1.29 out of 5 | $442 | 146,988 |
| Distribution Main | 3464 | P-797 | WW | Youngs Ave. | 8 | Ductile Iron | 304 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3467 | P-782 | WW | Youngs Ave. | 8 | Ductile Iron | 297 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 3751 | P-787 | WW | Youngs Ave. | 6 | Cast Iron | 62 | 134 | 2.57 out of 5 | $442 | 27,510 |
| Distribution Main | 3752 | P-787 | WW | Youngs Ave. | 6 | Cast Iron | 137 | 134 | 2.57 out of 5 | $442 | 60,679 |
| Distribution Main | 3753 | P-785 | WW | Youngs Ave. | 6 | Cast Iron | 337 | 134 | 2.57 out of 5 | $442 | 149,116 |
| Distribution Main | 8746 | P-785 | WW | Youngs Ave. | 6 | Cast Iron | 35 | 134 | 2.57 out of 5 | $442 | 15,602 |
| Distribution Main | 8748 | P-780 | WW | Youngs Ave. | 8 | Ductile Iron | 12 | 18 | 0 out of 5 | N/A | $0 |
| Distribution Main | 8750 | | WW | Youngs Ave. | 6 | Asbestos Cement | 12 | 63 | 2 out of 5 | $442 | 5,224 |
| Distribution Main | 8751 | P-8050 | WW | Youngs Ave. | 8 | Asbestos Cement | 10 | 63 | 1.29 out of 5 | $442 | 4,570 |

| Infrastructure Subtype | Pipe ID (NEW) | Pipe ID (OLD) | Town | Street Name | Pipe Diameter | Pipe Material | Length (Linear Feet) | Age (in years) | Condition Assessment (Need for Rehabilitation) | Replacement Cost Per LF (+ 15% for Engineering/Construction Services) | Replacement Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Distribution Main | 11049 | P-787 | WW | Youngs Ave. | 6 | Cast Iron | 18 | 134 | 2.57 out of 5 | $442 | 7,794 |
| Distribution Main | 12010 | P-787 | WW | Youngs Ave. | 6 | Cast Iron | 348 | 134 | 2.57 out of 5 | $442 | 154,002 |
| Distribution Main | 12011 | P-787 | WW | Youngs Ave. | 6 | Cast Iron | 277 | 134 | 2.57 out of 5 | $442 | 122,340 |

| Total Infrastructure Rehabilitation and Replacement Costs<br>Kent County Water Authority | | |
|---|---|---|
| **Infrastructure Type** | **5-year Costs** | **Total Costs Over 20 Years** |
| **Source** | $1,000,000 | $1,000,000 |
| **Treatment** | $1,500,000 | $1,500,000 |
| **Disinfection** | $0 | $0 |
| **Transmission_Distribution**** | $32,450,000 | $135,550,000 |
| **Storage** | $0 | $1,800,000 |
| **Other** | $50,000 | $150,000 |
| **TOTAL*** | **$35,000,000** | **$140,000,000** |

*Totals are based on proposed annual restricted replacement fund of $7,000,000.

**Remaining cost to replace transmission and distribution infrastructure is estimated at $744,838,860

| Financial Component | Questions | Brief Description |
|---|---|---|
| Infrastructure Replacement Fund | Does the water system have an Infrastructure Replacement Fund? | Yes, the system is approved by the RIPUC to collect rates to finance an annual restricted replacement fund of $7,000,000. |
| Planning for Replacements (Impact on Rate Structure) | Did the plan incorporate proposed rate structure impacts, a schedule of proposed rate changes, and schedule for fully funding the replacement projects based on the schedule included in the plan? | Determined by RIPUC |